



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V26568

In Date: 09/30/2009
Close Date: 10/26/2009

Meter Reading: 1,260.00

Problem?

B INSPECTION SET UP NEW VEHICLE R15

Task performed:

- B-Inspection
- R/R frnt pass seat, mod brkts.
- Set up new veh.
- B-Inspection
- R/R L/R aux brkt light; reprogram light asy to be on steady with bvrake application.
- Adj rear air suspension leveling valves to level out veh; leans to left.
- Tighten grnd cables at chassis.
- Cln chassis grease frm inside L/R brake drum with ___ then cln w/brakleen.
- Mnt eqmpt, finish up after striper; mnt etc.; adj air pack seats. j

Parts

Quantity

101-124-000CRASH RESTRAINT STRAPS	1
14-7014HGR-1 HELMET HOOK	7
1878042C91FUEL FILTER 2008 HORTON	1
5269LPVM-5 SM MOUNT	6
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
KD-UN-5-SFUSE 6-SF BRACKET	1
LPVM-7LG MOUNT	1
UMVS162511STRAP	3
UMVS254411STRAP 46 IN	1

Workorder: V27210

In Date: 10/27/2009
Close Date: 10/30/2009

Meter Reading: 1,242.00

Problem?

install new air pack brackets

Task performed:

- Assemble & instill (3) walk-away SCBA brackets into veh.
- Rep compt open alarm going off; rep damaged wiring. j

Parts

Quantity

NO PARTS USED

Workorder: V26881

In Date: 10/14/2009
Close Date: 11/02/2009

Meter Reading: 1,242.00

Problem?

install # plates and remove scba brakets

Task performed:

- Chk over trucks; mnt striker; adj cot, mnt stop & hook.
- makeup & install # plages & 002 sign. j

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V27487

In Date: 11/07/2009
Close Date: 11/30/2009

Meter Reading: 1,242.00

Problem?

Rear tailboard compartment door continues to pop open while vehicle is in motion.r15

Task performed:

Parts

Quantity

1. Went to Stn15; fnd rear compt door not fully latching; adj latch; ck ok.
2. Fnd stretcher catch not working; rem hook; drilled/remnted hook; sealed hook; ck opn; ck ok. j

NO PARTS USED

Workorder: V28273

In Date: 12/11/2009
Close Date: 12/21/2009

Meter Reading: 1,688.00

Problem?

wont start on call R15

Task performed:

Parts

Quantity

- Travel to R15; fnd starter solenoid bad; bypassed solenoid to get started; travel to shop. j

NO PARTS USED

Workorder: V28345

In Date: 12/14/2009
Close Date: 01/05/2010

Meter Reading: 151.00

Problem?

Emergency Strobe Lights in front grille still activate intermittently. readout shows: Module 11 pin 2-7 problem. LED Rear Dome li in pt comp is out. Rear outside hatch(Comp. #7) latch does not close. r15

Task performed:

Parts

Quantity

1. Chk dia; fnd multiple codes; unplug moduals & reconnect; run dia again - ok; Halmark to come out & chk veh.
2. Drill/rethread rear compt latch bolt to 5/16 thread; mov locknut & drill out latch hole bigger. j

NO PARTS USED

Workorder: V29420

In Date: 01/25/2010
Close Date: 02/11/2010

Meter Reading:

Problem?

Rain water leaking into cab, dripping onto electrical switches / mobile radio on console.

Task performed:

Parts

Quantity

- Contacted Hallmark for warranty repair. j

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V29936

In Date: 02/12/2010
Close Date: 03/18/2010

Meter Reading: 3,542.00

Problem?

Right rear turn signal not working.R15

Task performed:

Went to Stn15; all t-signals work but R/rear; rem t-signal light; no power; t-shoot & fnd relay (Micra)bad; did not have one; did not have relay in parts of on svc trks; rem relay frm another trk; returned to Stn15; replc relay; ck ok. j

Parts

3600330C1RELAY

Quantity

1

Workorder: V30875

In Date: 03/19/2010
Close Date: 03/19/2010

Meter Reading: 5,780.00

Problem?

siren not working right mechanic said it is fine to use from steeringwheel only but it has no yelp and not the way it was when we got the new truck rumbler but not the same either.

Task performed:

cONTACTED HALLMARK FOR WARRANTY REPAIR 03/19

Parts

NO PARTS USED

Quantity

Workorder: V30282

In Date: 02/26/2010
Close Date: 03/24/2010

Meter Reading: 3,542.00

Problem?

Whelen siren not working properly.T1 and T2 on dial not working(need to use Manual push botton over ride bottom left corner). Rambler siren not working R15

Task performed:

Went to Stn15; ran/ck siren/rumbler; fnd master needs to be on w/siren/horn button; ran/ck ok. j

Parts

3600330C1RELAY

Quantity

2

Workorder: V30957

In Date: 03/22/2010
Close Date: 04/07/2010

Meter Reading: 5,780.00

Problem?

STRETCHER ON R15 LOCKING DEVICE NOT LOCKING IN.

Task performed:

Readj stretcher lock. j

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V31342

In Date: 04/07/2010
Close Date: 04/27/2010

Meter Reading: 5,780.00

Problem?

R side door to patient compartment stays locked. Unable to unlock with outside button, key or inside the door (Kind of like a Stephen King movie.) Rescue is a second generation Horton. Thanks, Lt. Denison R15

Task performed:

Ck side pat door; lube latches; ck opn-ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V31449

In Date: 04/12/2010
Close Date: 04/27/2010

Meter Reading: 5,780.00

Problem?

need defibrillator mount R15

Task performed:

Get w/Mark G. on ordering mnt for truck 4-12-10; order cancelled; going w/diff mnt. j

Parts

Quantity

NO PARTS USED

Workorder: V31515

In Date: 04/14/2010
Close Date: 04/30/2010

Meter Reading: 5,780.00

Problem?

Install moulding around screen R15

Task performed:

installed moldinig on mnt. j

Parts

Quantity

NO PARTS USED

Workorder: V31788

In Date: 04/26/2010
Close Date: 05/17/2010

Meter Reading: 5,782.70

Problem?

rubber boot between cab and patient area, the rubber boot has about 4inch tear and leaking rain water onto the rear ac unit in the cab. R15

Task performed:

Contacted Hallmark for repair - warranty j

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V31928

In Date: 05/03/2010

Meter Reading: 8,249.00

Close Date: 05/17/2010

Problem?

light out in ceiling/ back of rescue. R15

Task performed:

Parts

Quantity

Chk R15; fnd grnd wire on light loose; tighten it up; light ok. j

NO PARTS USED

Workorder: V31929

In Date: 05/03/2010

Meter Reading: 8,249.00

Close Date: 05/17/2010

Problem?

PASSENGER SIDE HEADLIGHT OUT/LOW BEAM. R15

Task performed:

Parts

Quantity

Went to Stn15 for Stn19; R/R headlight bulb. j

H4656USE CV TYPE HEAD LIGHT

1



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V31997

In Date: 05/04/2010
Close Date: 06/14/2010

Meter Reading: 8,249.00

Problem?

Perfor "C" service R15.

Task performed:

- C-Inspection; add coolant; fill all tires to proper pressure.
- 2. Svc btrys.
- 3. Replcd R/frnt grd lite brckt & wire connector; cut new brkt to fit; drill new holes & secure; protect wires & secure wire loom.
- 4. Replcd wiper blades.
- 5. Pat compt door wont stay latched; grind down striker for latch to catch-ok.
- 6. Rem brkn O2 wrench cable & secure wrench to wall.
- 7. Replcd msng door panel screws R-3 & drill/tap new screw for bad nutzert; tighten all door skin screws on other compt doors; tighten loose screw pat compt stepanel.
- 8. R/F tire monitor not reading PSI; rem sensor & fnd rubber gskt out of position; repos gskt & program monitor - ok.
- 9. Fab tray for 15K medical eqmpt.
- 10. Finish making tray for 15K med.
- 11. Dia no rear load lites; chk wiring/ckt diagragms; chk for power 6A-40A & B-ok; rem lite fixtures & chk power/grnd-ok; fnd all bulbs bad; rem fixtures & replc all bulbs.
- 12. Rem L-2 door open brkt; rem (2) halves of brkt & straightened; reversed ball stud & reinstall; replcd stripped fastener w/sheet metal screw.
- 13. Torque u-bolts.
- 14. Rem masking tape frm side pat compt steps & installed non-skid strips. j

Parts

Quantity

1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	30
16302RETAINER CLIP	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
H35SN12BULB	2
MFG01876GROUND LT BRACKET	1
UMFS-0311UTILITY STRAP	1
UMVS162511STRAP	2

Workorder: V32851

In Date: 06/12/2010
Close Date: 06/21/2010

Meter Reading: 9,955.00

Problem?

We have a Second Generation Horton. On start up, or while driving, we get a "Module 2A Pin 3 Fail" notice and alarm sounding. Each start-up seems to trigger a different Module # and Pin # Fail notice with alarm. R15

Task performed:

went to Stn15; ck alarms going off; operated, started/ran rescue w/officer; cld not get alarm to go off; need to have Horton ck unit. j

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V32894

In Date: 06/14/2010
Close Date: 06/21/2010

Meter Reading: 9,955.00

Problem?

module 11 A pin 1,2,3 and 5 went off again Sta15 R15

Task performed:

Contacted Hallmark for repair. j

Parts

Quantity

NO PARTS USED

Workorder: V32993

In Date: 06/18/2010
Close Date: 06/25/2010

Meter Reading: 9,955.00

Problem?

A/C Blower fan, front of cab is not working. R15 It's HOT in there!!! Thanks, Lt G. Denison

Task performed:

Went to 15; Ck all relays/breakers; ck ok; fnd rear cab A/C unit fine to run over weekend. j

Parts

Quantity

NO PARTS USED

Sent to Intl for warranty. j

Workorder: V34053

In Date: 08/05/2010
Close Date: 09/09/2010

Meter Reading: 11,650.00

Problem?

R-15 Cab Front A/C not working, Fan also not working. The Jump - seat A/C (back of cab) works. Patient compartment A/C works

Task performed:

Went to 15; had to rep north end computer to link to truck; retrieved codes; cld not find codes for rep; must go to International for repairs. j

Parts

Quantity

NO PARTS USED

Workorder: V35177

In Date: 09/25/2010
Close Date: 10/07/2010

Meter Reading: 13,184.00

Problem?

support bracket on front right fuel tank is disconnected and hardware is missing. (nuts and screws) R15

Task performed:

1. travel to station 15; check and found right fuel tank step assy loose, replaced missing bolts and nuts; remounted steps, check ok. jab

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V35702

In Date: 10/17/2010
Close Date: 10/28/2010

Meter Reading: 13,783.00

Problem?

Drivers rear inside tire, tire pressure sensor not transmitting. R15

Task performed:

L/R/I tire press snsr inop; valve core loose; tightened sensor. j

Parts

NO PARTS USED

Quantity

Contacted Hallmark for Warranty repair. j

Workorder: V35695

In Date: 10/16/2010
Close Date: 10/29/2010

Meter Reading: 13,783.00

Problem?

Privacy glass will not turn off. Privacy glass is on all the time, making backing of the vehicle difficult. R15

Task performed:

Privacy glass inop; inverter bad; replc power inverter. j

Parts

10006527WINDOW INVERTOR

Quantity

1

Workorder: V36335

In Date: 11/09/2010
Close Date: 11/15/2010

Meter Reading: 15,008.00

Problem?

B INSPECTION AND REPAIR AS NEEDED R15

Task performed:

- (1) "B" INSPECTION.
 - (2) "B" INSPECTION COMPLETE.
 - (3) RESET TIRE MONITOR.
 - (4) QAQC CHECK.
 - (5) R&R ENGINE CAB, & REPLACED REAR A/C FILTER.
 - (6) R&R LEFT SIDE REVERSE LIGHT.
 - (7) COVER HOLE IN PATIENT COMP CEILING.
- J.W.

Parts

- 15W40BSYN OIL BULK QTS
- 1878042C91FUEL FILTER 2008 HORTON
- 2506656C124316 WIX CAB A/C FILTER
- 46870AIR FILTER
- 4DA2545W LAMP
- 5774457744XD OIL FILTER
- 78R539018-2699 A/C FILTER

Quantity

- 30
- 1
- 1
- 1
- 1
- 1
- 1



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V37233

In Date: 12/17/2010
Close Date: 01/06/2011

Meter Reading: 16,040.00

Problem?

R15 electrical gauge issues. Upon responding to a call and initiating the master switch for the lights the low coolant alarm sounds and flashes. The console screen also displayed shut off engine. coolant levels WNL R15

Task performed:

(1) TRAVELED TO ST-15 TO REPAIR R15 LOW COOLANT ALARM SOUNDING WHEN MASTER SWITCH FOR THE LIGHTS IS TURNED ON. CHECKED LOW COOLANT ALARM AND FLUID LEVEL. ALL WORKING OK NOW. J.W.

Parts

Quantity

2587324C1LEVEL SENSOR

1

2602872C91SURGE TANK

1

Workorder: V36530

In Date: 11/17/2010
Close Date: 01/11/2011

Meter Reading: 15,008.00

Problem?

Flat front passenger tire TCI r15

Task performed:

Flat front pass tire R15 - TCI j

Parts

Quantity

NO PARTS USED

Vendor? TCI

Workorder: V37913

In Date: 01/20/2011
Close Date: 01/24/2011

Meter Reading: 17,842.00

Problem?

Strong smell of exhaust fumes in cab after truck has run idle. Takes several miles with windows down to clear cab of smell. Possible exhaust leak under cab? Thanx for looking into this!! R15

Task performed:

Travel to stn; poss exh leak - clamp @ turbo loose; tightened clamp. j

Parts

Quantity

NO PARTS USED

Workorder: V38331

In Date: 02/07/2011
Close Date: 02/15/2011

Meter Reading: 18,359.00

Problem?

R-15 B- shift reports fuel gauge does not read below 3/4. A/C front of cab not cold. Rear (LED) dome light in pt compartment is out

Task performed:

1. Chk A/C not cold; add freon; chk for leaks; didnt find leaks; travel to Stn15.
 2. Chk dome light; fnd loose wire; reinstall light.
 3. C/O fuel gauge; transfer pump; refill the outer tank.
- j

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V39568

In Date: 03/30/2011
Close Date: 04/05/2011

Meter Reading: 21,230.00

Problem?

a/c units in front and rear of cab not making cold air (fan works). Rear dome light in pt compartment not working. R15

Task performed:

1. Travel to 15; chkd A/C sys 10-7; sent to shop.
2. Chkd dome lights - NPF. j

Parts

NO PARTS USED

Quantity

Workorder: V39474

In Date: 03/27/2011
Close Date: 04/13/2011

Meter Reading: 21,089.00

Problem?

Strobe lense and frame cracked on passenger side pt compartment R15

Task performed:

1. Travel to 15; light bezel cracked & lens ; none on trck, will get parts & return.
2. Charged cab A/C - sys was low.
3. Replc strobe lens. j

Parts

6811813493LENS CLEAR 68-1181349-3
9EFLANGEFLANGE CHROME

Quantity

1
1

Workorder: V39605

In Date: 04/01/2011
Close Date: 04/13/2011

Meter Reading: 21,405.00

Problem?

Front a/c blowing hot.

Task performed:

Compressor starting to fail lo-side needle on gauge bouncing; R/R compress, dryer & expansion valve; charge 2.25 lbs.; run to chk performance. j4/13/11

Travel to 15; replcd low coolant sensor. j4/14/11

Parts

2587324C1LEVEL SENSOR
3611894C9103-0805 A/C COMPRESSOR 4347
3660853C22512331C1 EXP VALVE NAV
3670134C1ACCUMULATOR ASSY INT.

Quantity

1
1
1
1

Workorder: V39771

In Date: 04/07/2011
Close Date: 04/18/2011

Meter Reading: 21,742.00

Problem?

Right front scene light has a severe crack. Please replace whenever you have a chance. Thank you R15

Task performed:

Completed, see rep order V39474. j

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V39870

In Date: 04/12/2011

Meter Reading: 22,212.00

Close Date: 04/27/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED R15

Task performed:

- C-Inspection
- 2. Tires over inflated; bring tire PSI to 110 as per mfr specs.
- 3. Inspect frnt axle bearing grease - add grease to left frnt axle.
- 4. Cab A/C warm; recycle freon; chk/leak - none fnd; recharge to 2.3 lbs; operate unit; cooling to 36 degrees within mfr specs.
- 5. L-3 hold open support loose; secure loose screws our holdopen brkt.
- 6. Cab to med partition booth torn; secured torn section w/silicone & weatherstrip adhesive.
- 7. Mid rear lower warning light cycles when brakes applied; rem LEDS to reprogram to stay on solid when brakes are applied.
- 8. O2 wrench msgng; install replacement O2 wrench.
- 9. Cab rear A/C filter; rem/install new A/C filter.
- 10. Pat compt dome light 10-7; fnd grnd cable brake loose at term splice; reconnect loose grnd connection.
- 11. Windshield wiper blade worn; rem/isntall new wiper blades & add washer solvent/water.
- 12. Driver door panel loose; diss door panel; fnd screw msgng & plastic clips worn out; install new clips & screws; reassm panel.
- 13. Retorque frnt/rear u-bolts.
- 14. Air dryer svc.
- 15. R/side air bag not inflated; adj leveling rod to activate air leveling valve.
- 16. A/C belt svc; rem/install new belts.
- 17. Eng belt svc; rem/isntall new belt.
- 18. P/S filter & fluid svc.
- 19. Pat compt (2) A/C filters; rem/isntall new filters.
- 20. Pat compt A/C UV bulb inop; rem blown UV bulb & install new UV bulb.
- 21. Fnd no audible alarm in overhead or center console; buzzer laying center console; no clip wire fnd; relocate to overhead; splice into warning light line. j

Parts

Quantity

065624AD-IP DRIER	1
1501450007750USE 0775145	1
1647221C2FAN SCHROUD	1
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
3805943C1DOOR RETAINER	5
5774457744XD OIL FILTER	1
78R536078R5360M 2PK FILTER AIR COND	1
91-22WIPER BLADE	2
AS75807OXM1757-01 OXYGEN WRENCH	1
GPX13ULTRA VIOLET LIGHT SHORT	1
K060695BELT	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V40046

In Date: 04/22/2011
Close Date: 05/09/2011

Meter Reading: 22,103.00

Problem?

Replace 6 tires R15

Task performed:

Parts

Quantity

Replc (6) tires R15 - Boulevard j

NO PARTS USED

Vendor? BOULEVARD

Workorder: V40764

In Date: 05/20/2011
Close Date: 05/25/2011

Meter Reading: 22,657.00

Problem?

Rescue -15 Cab A/C blowing hot air. Rear A/C not cold, either.

Task performed:

Parts

Quantity

Rep on W.O. 40800 j

NO PARTS USED

Workorder: V40791

In Date: 05/23/2011
Close Date: 05/25/2011

Meter Reading: 23,434.00

Problem?

ON CALL A/C 10-7 R15

Task performed:

Parts

Quantity

Travel to Stn15; chk A/C - no freon; started to add huge cut in A/C hose near R/S inner fender; cannot fix. j

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V40800

In Date: 05/23/2011
Close Date: 05/27/2011

Meter Reading: 23,434.00

Problem?

REPAIR A/C HOSE R 15

Task performed:

WARRANTY

1. Chk A/C blowing warm air; fnd lo-side hose that goes to rear cab A/C unit rubbed thru on R/frnt fender/fender well support brkt; rem R/frt fender well & right frt qtr fender; rem lo-side line; installed new w/new o-rings; replcd dryer; vac sys & recharged; leak tested sys; reinstalled fender parts.
2. Road tested truck; cln shop bay after repair. j

Parts

Quantity

3670134C1ACCUMULATOR ASSY INT.

1

383365HOSE ASSY

1

Workorder: V40446

In Date: 05/06/2011
Close Date: 06/14/2011

Meter Reading: 22,657.00

Problem?

Hub covers for R-15 Front and Rear wheels on driver's side are missing. The lug nut caps are all installed. Sta 15.

Task performed:

1. Travel to training - ordered hub caps.
2. Installed hub caps. j

Parts

Quantity

Q2010AXLE COVER REAR HORTONS

2

Workorder: V43590

In Date: 09/12/2011
Close Date: 09/12/2011

Meter Reading: 27,782.00

Problem?

drive to 15 get vehicle drive to shop get parts back to 15 finish repair. r-15

Task performed:

DRIVE TO ST 15 GET DOOR OPEN DRIVE TO SHOP
GET PARTS BACK TO 15 FINISH REPAIR

Parts

Quantity

NO PARTS USED

Workorder: V43580

In Date: 09/11/2011
Close Date: 09/19/2011

Meter Reading: 27,782.00

Problem?

Rear A/C in the patient compartment is not cooling when plugged into shore powerSta 15.

Task performed:

Rep rear A/C; replc con densor fans. j

Parts

Quantity

50-1500USE FAN KIT PANCAKE MOTOR DANHARD

2



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44176

In Date: 10/05/2011
Close Date: 10/06/2011

Meter Reading: 28,215.00

Problem?

Re-program rectangle shaped lowest Left rear emer. light to burn solid red, when brakes are applied so both lights are solid red.
Mechanic Re-programmed on 10/5/11. Sta 15.

Task performed:

repaired lr brake light

Parts

NO PARTS USED

Quantity

Workorder: V44620

In Date: 10/24/2011
Close Date: 11/14/2011

Meter Reading: 29,157.00

Problem?

B INSPECTION R 15

Task performed:

- 1. B-Inspection
- 2. Replc btry; R/R (3) btry; clnd cables.
- 3. Fnd pat door catches loose; tightened all catches - ck ok; tightened cab grab handles.
- 4. Rep body grnds; rem/clnd grns at frame; rep & clnd; ck ok.
- 5. Drained exh rad; installed heater shutoff valves; R/R drain valve for rad; filled rad; test drove; ck for leaks; R/R rear A/C filter,.
- 6. Fnd exh pipe leak; reposition clamp; tightened clamps; ck ok.
- 7. Quality check - J. George. j

Parts

1878042C91FUEL FILTER 2008 HORTON 1
 2506656C124316 WIX CAB A/C FILTER 1
 388863HOSE KIT 2
 5774457744XD OIL FILTER 1
 78R539018-2699 A/C FILTER 1
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER 3
 HP-31DBATTERY 950CCA HP-31D 3

Quantity

Workorder: V44915

In Date: 11/02/2011
Close Date: 11/30/2011

Meter Reading: 29,288.00

Problem?

replace body mounts r 15

Task performed:

replace body mts - removed rear comp. door and comp., removed all mts, r&r rubber bushings, reinstalled all mts, ck ok

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V43565

In Date: 09/10/2011
Close Date: 01/11/2012

Meter Reading: 27,782.00

Problem?

Rear patient compartment door want open. Can't get stretcher out if need be. R15

Task performed:

Parts

Quantity

DRIVE TO STA-15 CHECK VCH. CAN'T OPEN REAR ENTRY DOOR. REMOVE INNER DOOR PANEL, LOWER LATCH, BAD HAD TO DESTROY LATCH. TRAVEL TO CENTRAL STATION GET NEW LATCH. TRAVEL BACK TO 15, INSTALL AND ADJUST.

NO PARTS USED

Workorder: V46728

In Date: 01/20/2012
Close Date: 01/23/2012

Meter Reading: 32,531.00

Problem?

left rear tires low at 80psi, unable to fill. need to check, Sta 15

Task performed:

Parts

Quantity

TRAVEL TO 15 CHECKED TIRES FOUND PSI FLAT CALLED TIRE COMPANY.

NO PARTS USED

Workorder: V46776

In Date: 01/23/2012
Close Date: 01/27/2012

Meter Reading: 32,531.00

Problem?

repair flat

Task performed:

Parts

Quantity

REPAIR FLAT.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V47202

In Date: 02/09/2012
Close Date: 02/10/2012

Meter Reading: 33,606.00

Problem?

FLAT TIRE R 15

Task performed:

Parts

Quantity

FLAT TIRE R 15.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V47091

In Date: 02/05/2012 Meter Reading: 33,486.00
Close Date: 02/29/2012

Problem?
spotlight on R 15 is out, Sta 15

Task performed:	<u>Parts</u>	<u>Quantity</u>
FOUND WIRE BURNT AT CONNECTOR IN CENTER CONSOLE AND BAD BULB.	H9SPOT LIGHT BULB	1

Workorder: V47338

In Date: 02/15/2012 Meter Reading: 34,087.00
Close Date: 02/29/2012

Problem?
passanger window dosent open

Task performed:	<u>Parts</u>	<u>Quantity</u>
TRAVEL TO STATION FOUND WINDOW WOULD NOT WORK FROM EITHER DOOR CHECKED WIRING FOUND BAD CONNECTION AT CONTROL PANEL ON PASSENGER SIDE DOOR. CORRECTED CHECKED OK.	NO PARTS USED	

Workorder: V47713

In Date: 03/02/2012 Meter Reading: 34,684.00
Close Date: 03/15/2012

Problem?
dewalt stretcher battery 10-7

Task performed:	<u>Parts</u>	<u>Quantity</u>
TRAVEL TO ST 15 CHECK OUT STRETCHER BATTERY AND CHARGER INSTALL NEW BATTERY.	NO PARTS USED	

Workorder: V48010

In Date: 03/16/2012 Meter Reading: 3,855.90
Close Date: 03/20/2012

Problem?
truck is having trouble starting.

Task performed:	<u>Parts</u>	<u>Quantity</u>
WENT TO 15 - DRIVER SAID CRANKS AND HARD START WHEN COLD - CODE 2335 -164-1 ICP LOW DURING CRANK - CHECK STARTING AND CHECK OK - OIL LEVEL CHECK OK.	NO PARTS USED	



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V48429

In Date: 04/04/2012

Meter Reading: 36,356.00

Close Date: 04/13/2012

Problem?

C INSPECTION R15

Task performed:

1. C-INSPECTION.
2. C-INSPECTION.
3. C-INSPECTION.
4. REMOVE REAR BENCH SEAT.
5. R&R RIGHT REAR UPPER ENTRY LIGHT.
6. R&R AIR CLEANER.
7. START R&R AIR DRYER, HAD TO AIR CHIESEL BOLT OUT, REMOVE HOUSING FULL OF WATER DUE TO FAULTY AUTO DRAIN ELEON REINSTALL, REMOVE AUTO DRAIN.
8. CLEAN DRYER HOUSING, REINSTALL.
9. TIGHTEN ALL DOOR HOLD OPEN BRACKETS.
10. REMOVE OLD TIRE MONITOR SYSTEM, INFLATE ALL TIRES TO LL0 PSI. INSTALL LED MONITOR ON VALVE STEMS. INSTALL BRACKETS ON REAR WHEELS, REMOVE CENTER CAPS.
11. QUALITY INSPECTION.
12. RESECURE RIGHT SIDE STEP, BOLTS MISSING INSTALLED NEW NUTS 1/2 BOLTS.
13. DRIVE TO STA 15 ADJUST STRETCHER MOUNTS TO FIT FERNO STRETCHER.

Parts

Quantity

065624AD-IP DRIER	1
103385NDRAIN COCK	1
109498BOLT KIT CARTRIDGE ADIP	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
440-33-11/16 VALVE EXT	2
46870AIR FILTER	1
5774457744XD OIL FILTER	1
92541677TEST PRESSURE GAUGE	1
AMH-1AMH-1 VALVE EXTENSION	1
H35SN12BULB	1
K022105PURGE VALVE AD-IP-IS	1
L PLACARDLARGE SIDE PLACARD	4
L PLACARD INSERTLARGE PLACARD INSERT CARD	4
RWTG1234LED PRESSURE CAP	6
S PLACARDFRONT AND BACK PLACARD	1
S PLACARD INSERTFRONT AND BACK INSERT CARD	1

Workorder: V49170

In Date: 05/08/2012

Meter Reading: 37,528.00

Close Date: 05/10/2012

Problem?

stretcher locking mechanism not locking properly. needs adjustment

Task performed:

- TRAVEL TO 15 REPLACED STRETCHER LATCH AND ADJUSTED.

Parts

Quantity

0567042LONG STRECHER BAR	1
090-0278STRECHER BAR NEW	1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V49436

In Date: 05/17/2012
Close Date: 05/29/2012

Meter Reading: 37,748.00

Problem?

A INSPECTION / MAKE NUMBER PLATES SET UP FOR STRYKER R 48

Task performed:

1. ADJUSTED STRETCHER LOCK AND MOUNTED HOOK ON FLOOR FOR STYKER STRETCHER.
2. MADE AND MOUNT NEW STATION NUMBER PLACKARDS.
3. PERFORMED "A" SERVICE.

Parts	Quantity
6092036018J HOOK STRYKER	1
L PLACARD INSERTLARGE PLACARD INSERT CARD	2
S PLACARD INSERTFRONT AND BACK INSERT CARD	1

Workorder: V49463

In Date: 05/18/2012
Close Date: 05/29/2012

Meter Reading: 37,748.00

Problem?

redo number plates to R47

Task performed:

1. MADE NEW STATION NUMBER PLACKARDS AGAIN. (WRONG NUMBER)

Parts	Quantity
L PLACARD INSERTLARGE PLACARD INSERT CARD	2
S PLACARD INSERTFRONT AND BACK INSERT CARD	1

Workorder: V49673

In Date: 05/28/2012
Close Date: 06/01/2012

Meter Reading: 38,684.00

Problem?

clunking sound from the rear. mainly happens when rpm come back down, slight vibration noted. R47

Task performed:

ROAD TESTED AND FOUND NO NOISE.

Parts	Quantity
NO PARTS USED	

Workorder: V49786

In Date: 06/01/2012
Close Date: 06/08/2012

Meter Reading: 39,032.00

Problem?

REPLACE MIRROR R 47

Task performed:

1. REPLACED BROKEN MIRROR ON RIGHT SIDE.
2. READJUSTED AIR PACK BRACKETS.

Parts	Quantity
2505818C2MIRROR GLASS LONG	1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V50391

In Date: 06/26/2012

Meter Reading:

Close Date: 06/26/2012

Problem?

AC in cab not working blowing hot air R47

Task performed:

1. check cab a/c blows cool air, check blend doors, all ok, check pressures, found pow side high and high side low, evecaute system, remove air filter, remove a/c belt and a/c compressor, drier, and expansion valve. order parts..
2. check new compressor for correct amount of oil, turn comp. 15 times to run oil through system. install compressor and new O rings and gaskets, install new expansion valve and drier, install new O rings and gaskets on both, install a/c belt and air filter, replace cab a/c filter, evecaute system for 1 hr and charge with 2lbs 4oz of freon run system. road test.. ok

Parts

Quantity

2506656C124316 WIX CAB A/C FILTER	1
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1

Workorder: V50422

In Date: 06/26/2012

Meter Reading: 41,315.00

Close Date: 06/28/2012

Problem?

BASE RADIO DOES NOT ALWAYS TURN ON WHEN THE BATTERY AND TRUCK IS RUNNING, SOME TIMES IT TAKES 2-3 TIMES DO GET IT TO COME ON r 47

Task performed:

CONTACTED RADIO SHOP FOR REPAIR.

Parts

Quantity

NO PARTS USED

Workorder: V50921

In Date: 07/17/2012

Meter Reading: 43,034.00

Close Date: 07/18/2012

Problem?

MDT keeps shutting off everytime the rescue is started. MDT asst. # 10180613. This seems to be some kind of electrical problem Thank you!

Task performed:

MDT KEEP SHUTTING OFF EVERYTIME THE RESCUE IS TARTED. MDT ASST.#10180613. THIS SEEMS TO BE SOME KIND OF ELECTRICAL PROBLEM. THANK YOU.

Parts

Quantity

NO PARTS USED

REPORTED RADIO SHOP.



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V51228

In Date: 07/30/2012
Close Date: 08/03/2012

Meter Reading: 43,799.00

Problem?
repair flat

Task performed:	Parts	Quantity
REPAIR FLAT.	NO PARTS USED	

Vendor? BOULEVARD TIRE CENTE

Workorder: V50952

In Date: 07/18/2012
Close Date: 08/06/2012

Meter Reading: 43,034.00

Problem?
ST47-Rescue shoreline not working properly,not popping out from unit. R47

Task performed:	Parts	Quantity
REPAIRED SHORELINE AND TESTED.	NO PARTS USED	

Workorder: V52279

In Date: 09/10/2012
Close Date: 09/10/2012

Meter Reading: 46,104.00

Problem?
will not start, R-47

Task performed:	Parts	Quantity
1. travel to sta-47 check for no start condition, found starter inop, will have towed to s/shop for repair, travel back to s/shop	82000056808 38MT 12T STARTER	1
2. remove starter, found water in starter, install new starter and test ok		

Workorder: V51816

In Date: 08/22/2012
Close Date: 09/13/2012

Meter Reading: 44,239.00

Problem?
REPLACE TIRES

Task performed:	Parts	Quantity
REPLACE TIRES	NO PARTS USED	

Vendor? BOULEVARD TIRE



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V52040

In Date: 08/30/2012
Close Date: 09/13/2012

Meter Reading: 45,137.00

Problem?

R47 SOUNDS LIKE IT IS HAVING TROUBLE TURNING OVER. WILL START BUT DOESNT SOUND RITE. VOLT GUAGE REA
14. POSSIBLE ALTERNATOR PROBLEM?

Task performed:

Parts

Quantity

1. CHK CHARGING SYST AND BATT ALL TESTED OK

NO PARTS USED

Workorder: V51163

In Date: 07/27/2012
Close Date: 09/14/2012

Meter Reading: 43,799.00

Problem?

REAR A/C NOT WORKING. R47

Task performed:

Parts

Quantity

RECHARGER SYST AND CHKD FOR LEAKS.

NO PARTS USED

Workorder: V51368

In Date: 08/05/2012
Close Date: 09/17/2012

Meter Reading:

Problem?

hanging hooks needed behind driver, both need to be replaced R47

Task performed:

Parts

Quantity

INSTALLED KOOKS IN CAB.

NO PARTS USED

Workorder: V52093

In Date: 09/02/2012
Close Date: 09/17/2012

Meter Reading: 45,137.00

Problem?

ON CALL BATTERY DEAD

Task performed:

Parts

Quantity

TRVL TO 47 TEST BATTERIES STARTER AND
SHARELINE REPLACE BATTERIES.

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTEF
HP-31D BATTERY 950CCA HP-31D

3
3



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V52276

In Date: 09/10/2012

Meter Reading: 46,104.00

Close Date: 09/19/2012

Problem?

ON CALL STERTER 10-7 R 47

Task performed:

NO START/ STARTER DEFECTIVE/ TROUBLESHOOT
NO START NEEDS A STARTER PICK UP SPARE
RESCUE AT SHOP AND SWAP OUT.

Parts

NO PARTS USED

Quantity

Workorder: V51443

In Date: 08/07/2012

Meter Reading: 44,239.00

Close Date: 09/20/2012

Problem?

B INSPECTION R 47

Task performed:

1. B INSP
2. B INSP
3. R/S MIRROR ABOVE DOOR/LOOSE/ADJ AND TIGHTENED TOP CONVEX MIRROR ALSO TIGHTENED CAB GRAB HANDLES.
4. FUEL LEAK/ INTAKE MANIFOLD GASKET/CLEANED ENGINE AND LOCATE LEAK.
5. FUEL RETURN LINE FITTINGS AT FILTER HEADER BROKEN/ REPAIRED LINE INSTALLED NEW FITTING
6. RESEAL REAR COMPT DOOR W/ WEATHER STAY.

Parts

- 1842033C1GASKET
- 1845023C1GASKET
- 1870742C92MANIFOLD INTAKE
- 1873906C1SEAL FUEL FILTER HSG
- 1873910C91FUEL STRAINER HORTON
- 1875808C1GASKET EGR COOLER
- 1878042C91FUEL FILTER 2008 HORTON
- 2506656C124316 WIX CAB A/C FILTER
- 3533426C3FUEL FITTING
- 3591094C1FUEL FITTING
- 5774457744XD OIL FILTER
- 78R539018-2699 A/C FILTER
- 91-22WIPER BLADE

Quantity

- 1
- 1
- 1
- 1
- 1
- 2
- 1
- 1
- 1
- 1
- 1
- 1
- 2



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V51476

In Date: 08/08/2012

Meter Reading:

Close Date: 09/20/2012

Problem?

-You cannot exit the pt area from the inside on the passenger side. -The AC is not blowing cold in the passenger area. -MDC shut off when its active and you turn the truck. -The truck is on its way to the shop for P R47

Task performed:

- 1.SIDE DOOR INOP- REMOVE DOOR PANEL-ADJ DOOR LATCH PULL NOB-REASSEM AND OPERATE LOCKING MECHANISM-REASSEMBLE DOOR PANNEL.
2. CAB A/C NOT COOLING- CHK PSI FOUND LOW ON FREON VACCUM SYST CHK FOR LEAK WITH NITROGEN NO LEAK FOUND VACCUM AND CHANGE UNIT.
3. INSTALL STRETCHER BUMP RAILS REMOVE LOCKING DEVICE CLEAN TUM SCREW AND APPLY NEVER SCAZE, LOCK UNIT IN PLACE.
4. TORQUE BAR BOLT AT FRAME LOOSE- TORQUE ALL ASSOCIATED NUT AND BOLTS.
5. MISSING BOLTS ON PACENT A/C COMPRESSOR SUPORT BRACKET INSTALL REPLACEMENT BOLT AND RECHARGE ALL NUT AND BOLT ON COMPRESSOR AND SUPPORT BRACKET.
6. TRANSMISSION FILL TUBE LOOSE. CHK FOR LEAK AND SECURE FILL TUBE TO SUPPORT BRACKET.

Parts

Quantity

10005596GRABRAIL

2

Workorder: V52572

In Date: 09/23/2012

Meter Reading:

Close Date: 09/24/2012

Problem?

Exterior door to the oxygen compartment will not open / Rear flood light is not coming on. R47

Task performed:

1. check o2 compt door, will not open. remove strobe lite and drill hole in door to unlock latch, found rod fell off of latch, install cotter pin reassemble door.

Parts

Quantity

6811813493LENS CLEAR 68-1181349-3

1

Workorder: V52424

In Date: 09/17/2012

Meter Reading: 46,547.00

Close Date: 09/25/2012

Problem?

CAB A/C 10-7 R 47

Task performed:

RECHARGED SYSTEM AND CHKD FOR LEAKS.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V52001

In Date: 08/30/2012
Close Date: 10/01/2012

Meter Reading: 45,137.00

Problem?

ROOF LEAKING R 47

Task performed:

RESEALED TOP OFF ROOF DUE TO WATER COMING IN CAB.

Parts

NO PARTS USED

Quantity

Workorder: V52734

In Date: 10/01/2012
Close Date: 10/02/2012

Meter Reading: 48,033.00

Problem?

SLOW STARTING

Task performed:

LOAD TESTED BATTERIES FOUND ALL GOOD - FOUND CREW NOT PLUGING TRUCK IN AND LEAVING DOOR LIGHTS ON AND DRAINING DOWN BATTERIES.

Parts

NO PARTS USED

Quantity

Workorder: V52985

In Date: 10/10/2012
Close Date: 10/12/2012

Meter Reading: 48,648.00

Problem?

REPAIR A/C R 47

Task performed:

1. CHK OUT A/C NOT CODING. REMOVED SYST FOUND LOW FILLED WITH NITROGEN AND LEAK TESTED FOUND LEAK AT HIGH SIDE.
2. A/C REPAIR NOTICED HIGH NEEDLE ON GAUGE FLICKERING OUT OF CONTRL .
3. REPLACED RECIEVE DOOR MOTOR (CRACKED/BROKEN) ALSO RECALIBRATED.
4. CHK RGHT OUT TIRE MONITOR BLINKING FOUND TIRE LOW. FAULTY SCHRADER VALVE.
5. DRAINED AND FILLED NEW A/C COMPRESSOR TO CORRECT LEVEL-REPAIR PAT. DRAWERS REMOVED 2 DRAWERS.

Parts

3542606C12611234C1 VENT ACTUATOR
3611894C9103-0805 A/C COMPRESSOR 4347

Quantity

1
1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V53365

In Date: 10/29/2012
Close Date: 11/16/2012

Meter Reading: 50,383.00

Problem?

FUEL LEAK R 47

Task performed:

1. REMOVE INTAKE MANIFOLD GASKET FUEL LEAK REMOVED MANIFOLD.
2. INSTALL INTAKE MANIFOLD GASKET.
3. INSTALL INTAKE.
4. INSTALL INTAKE.
5. FINISH INTAKE INSTALLATION AND ROAD TEST CHECK OK.

Parts

Quantity

NO PARTS USED

Workorder: V53823

In Date: 11/16/2012
Close Date: 11/20/2012

Meter Reading: 52,224.00

Problem?

AIR BAG LEAKING R 47

Task performed:

CHECK AIR LEAK REPLACE BOTH AIR BAGS.

Parts

Quantity

GUI1R11216GY1R11216 AIR BAG INT.

2

Workorder: V53573

In Date: 11/06/2012
Close Date: 11/28/2012

Meter Reading: 50,809.00

Problem?

Air break has a slow leak. R47

Task performed:

CHECKED FOR AIR LEAKS FOUND REAR AIR BAGS HAS HOLE SENT TO SHOP.

Parts

Quantity

NO PARTS USED

Workorder: V53946

In Date: 11/21/2012
Close Date: 11/28/2012

Meter Reading:

Problem?

SIRENS WILL NOT TURN ON.. R47

Task performed:

NO SIRENS FOUND RELAY CONNECTION LOOSE SECURE LOOSE CONNECTION TEST AFTER REPAIR OPERATING NORMAL.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V53995

In Date: 11/26/2012

Meter Reading: 52,430.00

Close Date: 12/06/2012

Problem?

C INSPECTION R 47

Task performed:

1. C INSP
2. ADJUST ALL TIRE PRESSURES TO PROPER LEVELS, REPLACE 2 EXTENSION; 1 VALVE CORE AND 5 TIRE PRESSURE MONITORS.
3. REPLACE 5 ZERX FITTING ON FRONT AXLE IN ORDER LUBE CHANGE FROM STRAIGHT TO GO 90 TO 40 ZERK.
4. SERVICE TRANSMISSION.
5. TIGHTEN ALL DOOR PANEL SCREWS.
6. REPLACE BOTH SIDE REVERSE LIGHTS.
7. TIGHTEN ALL STRETCHER MOUNTS.
8. REPLACE GROUND LIGHT AND WIPER BLADES.
9. TROUBLESHOOT REAR LIGHTS INOP FOUND WIRE LOOSE IN CONNECTOR AT OUTPUT MODULE
10. RESECURE SHARPIES DRAW SLIDES.
11. TROUBLESHOOT 110V SHORTLINE A/C INOP FOUND BAD CONNECTION FOR BATTERIES IN THERMOSTATE CONTROL.
12. CHECK FOR AIR LEAKS REPLACE GOVERNOR QURCH CONNECT FITTINGS.
13. CHECK FOR AIR LEAKS, REPLACE FITTING FOR FAN CLURCH.
14. QC VEH.
15. REPLACE ALL A/C FILTERS.
16. R & R UV LIGHTS.

Parts

Quantity

1501450007750USE 0775145	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
29526898 29548988 TRANS FILTER ALLISON	1
440-33-11/16 VALVE EXT	1
4DA2545W LAMP	2
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
GPX13ULTRA VIOLET LIGHT SHORT	1
H35SN12BULB	2
HLD3999GSS1715UV 30LB STRUT GAS	2
RWTG1234LED PRESSURE CAP	5

Workorder: V53806

In Date: 11/15/2012

Meter Reading:

Close Date: 12/14/2012

Problem?

THERE IS A LEAK IN THE REDIATOR SYSTEM. ABOUT A PINT OF FLUID HAS LEAKED IN A 24 HOUR PERIOD. R47

Task performed:

FOUND NO KEAK AT THIS TIME. DROPPED OFF OIL AT STATION.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V54282

In Date: 12/07/2012

Close Date: 12/17/2012

Meter Reading: 52,430.00

Problem?

replace headlight

Task performed:

REPLACED BULB.

Parts

9007H9007 BULB ASSY

Quantity

1

Workorder: V56280

In Date: 03/09/2013

Close Date: 03/18/2013

Meter Reading: 61,019.00

Problem?

stretcher lock mounted to the pt compartment is broken. the stretcher will lock in place if the lock is manually controlled.

Task performed:

1. R-2 HOLD OPEN LOOSE - HOLD OPEN MOUNTING SCREW STRIP - REMOVE AND REPLACE WITH NEW SUPPORT SIREN AND PIVOT BALL.
2. AIR HORN NEED TURNING - TUNE RIGHT SIDE HORN.
3. Q & A.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V56240

In Date: 03/07/2013

Meter Reading: 60,646.00

Close Date: 03/19/2013

Problem?

B inspection R47

Task performed:

1. B-INSPECTION; ADJUST TIRE AIR PRESSURE; INSTALL NEW PRESSURE SENSOR WARNING DEVICE L/R INNER TIRE.
2. REMOVE TORN SEAT CUSHION - OUTSIDE REPAIR. INSTALL REPAIRED SEAT.
3. REMOVE DIRTY PATIENT COMPARTMENT A/C FILTER AND INSTALL NEW FILTER.
4. WINDSHIELD WIPER BLADE, FLUID RESEVIOR AND BUG SOLVENT - SERVICE CLEAN SPRAY NOZZLES.
5. L/REAR INNER TIRE PRESSURE SENSOR INOP - REMOVE AND INSTALL NEW SENSOR - INSURE TIRE PRESSURE IS 110 PSI AND LED ACTIVATED.
6. L-1 02 GAUGE BROKEN - REMOVE GAUGE - CLEAN CONNECTOR - NEW GAUGE WRAP THREADS WITH TEFLON TAPE AND INSTALL.
7. REAR TIRES NEED REPLACING - ACQUIRE 4 TIRES FROM BLDG. #3; REMOVE BAD TIRES AND INSTALL, ADJUST TIRE PRESSURES TO 110 PSI. TIRE VIBRATION - REMOVE TIRE INSTALL NEW TIRE AND ROAD TEST NO FURTHER VIBRATION DETECTED.
8. HARD START IN THE MORNING - CHECK NO CODES, CHECK BATTERY ALL GOOD, CHECK CHARGING SYSTEM NO FAULT FOUND.
9. DRIVER DOOR FOOT PANNEL LOOSE; L-2 TOOL HOLDERS LOOSE; REAR PATIENT DOOR PANEL LOOSE; CAB HEAD SET HOOK LOOSE - SECURE ALL LOOSE; ITEMS BY RETAP AND REPLACE MISSING SCREWS.
10. PATIENT COMP OPEN NEEDLE ON FLOOR - NOT PROPERLY.
11. CAB TO PATIENT COMP BOOTH DAMAGE - REMOVE BOOTH FOUND HOLD DOWN SUPPORT LOOSE - REASSEMBLE AND SILICONE JOINTS - BOOTH NOT DAMAGE.
12. CAB OFFICERS DOOR LIGHT INOP - REMOVE BLOWN BULB, REPLACE NEW BULB AND REPAIR PINCHED WIRE AT DOOR JAM ACCESS HOLE.

Parts

Quantity

1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
366555GTL6 13 X 19 FILTER	1
5774457744XD OIL FILTER	1
5ZP78WELDING PRESSURE GAUGE 4000 PSI	1
91-22WIPER BLADE	2
MG-C23SPMGC23 GAUGE	1
RWTG1234LED PRESSURE CAP	1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V56515

In Date: 03/19/2013
Close Date: 03/19/2013

Meter Reading: 61,019.00

Problem?

shut down engine alarm going off, R-47

Task performed:

Parts

Quantity

1. hook up laptop, check for codes found low coolant code, found coolant below switch, add 1 gallon of coolant check for leaks. none found at this time

NO PARTS USED

Workorder: V52719

In Date: 09/29/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

A/C BLOWING WARM IN PASSENGER COMPARTMENT. STILL COLD IN PATIENT COMPARTMENT

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V53552

In Date: 11/05/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

could we have the cab windows tinted? q47

Task performed:

Parts

Quantity

15W40QSYN OIL QT

5

Workorder: V56566

In Date: 03/21/2013
Close Date: 04/08/2013

Meter Reading: 61,450.00

Problem?

Coolant leak

Task performed:

Parts

Quantity

1. CHECK VEHICLE FOR ANY COOLANT LEAKS.
2. CHECK VEHICLE FOR COOLANT LEAKS.

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V56647

In Date: 03/26/2013
Close Date: 04/09/2013

Meter Reading: 61,450.00

Problem?

Stretcher bar bracket loose

Task performed:

1. FOUND PAT - HEATER CONTROL VALVE LEAKING ORDERED PARTM.
2. STRETCHER LOCK BROKEN - R&R LOCK - CHECK OK.
3. FOUND R& REAR OUTSIDE TIRE MONITOR BLINKING - AIRED TIRE TO SPECS - FOUND VALVE HOSE LEAKING - REPAIRED HOSE - AIRED TIRES - CHECK OK.
4. REPLACE HEATER CONTROL VALVE - R&R VALVE TOPPED OFF TANK - TEST DROVE - CHECK FOR LEAKS - CHECK OK.
5. FOUND TRUCK PULLING TO RIGHT - CHECK TIRE PRESSURE - CHECKED O-BOLTS - CHECKED AND ADJUST TOE.
6. TEST DROVE - TIRES WORN ABNORMAL - TIRES WILL BE REPLACED NEXT P.M. AND CHECK OK.

Parts

Quantity

090-0278STRECHER BAR NEW

1

746148211237 HEATER VALVE

1

Workorder: V56574

In Date: 03/21/2013
Close Date: 04/22/2013

Meter Reading: 61,450.00

Problem?

coolent level was low and stop engine light came on. coolant put in at station. truck just came back from shop 4 days ago E-47

Task performed:

LOW ON COOLANT, WILL MONITOR.

Parts

Quantity

NO PARTS USED

Workorder: V52890

In Date: 10/05/2012
Close Date: 04/23/2013

Meter Reading: 48,648.00

Problem?

MDC bracket is broken. The bolt that connects the computer to the stand broke in half inside the female threaded end. Q 47

Task performed:

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V57172

In Date: 04/21/2013

Meter Reading:

Close Date: 04/29/2013

Problem?

Driver side headlight is out. Needs to be replaced R47

Task performed:

REPLACED HEADLIGHT.

Parts

9007H9007 BULB ASSY

Quantity

1

Workorder: V57627

In Date: 05/09/2013

Meter Reading:

Close Date: 05/17/2013

Problem?

Side rear compartment door hinge is broken off and will no open door, R47

Task performed:

REMOVED SIDE ENTRE DOOR PANEL INSTALLED NEW HANDLE.

Parts

10008146HND5948 HANDLE RH HORTON

Quantity

1

Workorder: V57483

In Date: 05/05/2013

Meter Reading:

Close Date: 05/20/2013

Problem?

left front tire tread low...tire needs replacement. R47

Task performed:

LEFT FRONT TIRE THREAD LOW... TIRE NEEDS REPLACEMENT. R47

Vendor? BOULEVARD TIRE

Parts

216568BRIDGESTONE 255/70R22.5

Quantity

2

Workorder: V57754

In Date: 05/15/2013

Meter Reading: 64,326.00

Close Date: 05/24/2013

Problem?

Rear a/c inop

Task performed:

1. RECHARGED A/C AND REPAIRED LEAK.
2. READJUSTED AIR BAGS AND ROAD TESTED.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V57976

In Date: 05/26/2013

Meter Reading:

Close Date: 05/31/2013

Problem?

the lights are blinking on two valve stems. both driver side.

Task performed:

REFILLED TIRES AND REPLACED SENSORS.

Parts

RWTG1234LED PRESSURE CAP

Quantity

6

Workorder: V58973

In Date: 07/09/2013

Meter Reading: 67,356.00

Close Date: 07/09/2013

Problem?

no power to pat. compt, R-47

Task performed:

1. check for no power to pat. box, found "turn on battery switch" lite on center console but battery switch was turned on, check battery switch connections, all tight, when i went back in the driver seat there was power to the box and all lights worked, per Steve R check all battery cables on frame rail for tightness, which they all were. only thing i could figure was when checking battery switch terminals i moved the switch, so i replaced the batt. switch.

Parts

51-30219-1045 MASTER SWITCH 175 AMP

Quantity

1

Workorder: V59063

In Date: 07/13/2013

Meter Reading: 67,864.00

Close Date: 07/19/2013

Problem?

the dustcap on the shoreline plug broke off R 47

Task performed:

TRACED OUT AIR LEAK FOUND AND REPAIRED.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V59167

In Date: 07/17/2013
Close Date: 07/30/2013

Meter Reading: 67,864.00

Problem?

C inspectioin R47

Task performed:

1. C insp.
2. o2 slide out tray tracks broken, will not open, cut out tracks on wall, new tracks in stock all had locks, per. Steve R cut off locks on all 3 tracks and install, tracks new tracks did not line up with holes for o2 holder had to drill and tap all new holes
3. shole line cover broken for batt charger, replace cover
4. remove rear wheels and replace rear brake shoes, brake hardware and drums, install wheels and adjust brakes road test and readjust brakes
5. service air dryer
6. replace wiper blades
7. replace cab a/c filer (red dot)
8. replace pat. a/c filters
9. replace 2 compt. door struts in pat. compt.
10. replace 10 ground lites
11. update international chassis software
12. 11o v a/c inop, low on freon, check for leaks, found lines on compressor leaking, evecaute system and install new clamps on hoses, charge system and recheck for leaks, non found

Parts

Quantity

065624AD-IP DRIER	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
15-40B15W40 MOTOR OIL NON SYN	30
1501450007750USE 0775145	2
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
283255 SLIDE 18IN 500 LBS	3
3757REAR DRUMS 3757X 3647X	2
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	10
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
HLD3999GSS1715UV 30LB STRUT GAS	2
K022105PURGE VALVE AD-IP-IS	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2

Workorder: V59555

In Date: 08/05/2013
Close Date: 08/19/2013

Meter Reading: 67,864.00

Problem?

there is a leak in the main o2. we have used soapy water and checked the connections that are accessable and could not find the leak. we are going through a bottle in about a week with very little usage

Task performed:

TRACED OUT O2 LEAK FOUND FITTING BEHIND WALL LEAKING.

Parts

Quantity

NO PARTS USED

Workorder: V60511

In Date: 09/15/2013
Close Date: 09/16/2013

Meter Reading:

Problem?

r47 stretcher asset #10175538 has lost hydrolic pressure. when the stretcher is fully extended when taking it out of the rescue the stretcher will start to collapse before the hydrolics can catch up with the button

Task performed:

spoke with crew about operation of stretcher npf

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V60853

In Date: 09/28/2013
Close Date: 10/10/2013

Meter Reading:

Problem?

map light broken, requesting it be fixed. Need the light at night

Task performed:

1. INSTALLED NEW MAP LIGHT AND TESTED.
2. STETCHER LATCH INOP-REMOVED LATCH AND REPAIRED AND REINSTALLED.

Parts

Quantity

LF18TS-LEDMAP LIGHT LED 18 IN

1

Workorder: V56582

In Date: 04/04/2013
Close Date: 12/13/2013

Meter Reading: 61,450.00

Problem?

Check for possible multiple coolant leaks ang leaking egr coolers

Task performed:

REPAIRED ON WO 56574.

Parts

Quantity

1844447C1ORING

4

1876262C96EGR COOLER INT SIDE USE 4307362R91

1

1878918C2EGR VALVE

1

7090595C91COOLER EGR KIT 330MM EXH SIDE OLD 1876

1

CORECORE CHARGE

1

Workorder: V62334

In Date: 11/28/2013
Close Date: 12/17/2013

Meter Reading:

Problem?

back tires worn to tread bump R47

Task performed:

REPAIRED LEFT REAR DOOR THAT WAS HARD TO OPEN.

Parts

Quantity

NO PARTS USED

Workorder: V62817

In Date: 12/18/2013
Close Date: 12/23/2013

Meter Reading: 76,678.00

Problem?

REPLACE FRONT TIRES

Task performed:

REPLACE FRONT TIRES.

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V62239

In Date: 11/24/2013

Meter Reading:

Close Date: 12/31/2013

Problem?

spot light on top of cab will not move up/down or side/side R47

Task performed:

Parts

Quantity

REPAIRED SPOT LIGHT ON CAB.

NO PARTS USED

Workorder: V62464

In Date: 12/04/2013

Meter Reading: 76,273.00

Close Date: 12/31/2013

Problem?

A/c inop

Task performed:

Parts

Quantity

RECHARGED A/C AND REPAIRED LEAK.

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V62614

In Date: 12/10/2013

Meter Reading: 76,678.00

Close Date: 01/02/2014

Problem?

B INSPECTION R47

Task performed:

1. b insp.
2. spotlight inop. replace control and wiring
3. cab a/c inop. low on freon, add freon check for leaks, found leaks at expansion valve and cond. replace o rings and recharge recheck for leaks
4. replace 2 broken a/c vents
5. coolant leak, pressure test system, found leaks at egr hose clamps and hose clamps under turbo, pressure test again for leaks, none found
6. l/side front brake chamber hose fitting loose, remove hose and tighten fitting on chamber, reinstall brake hose
7. replace wiper blades
8. struts an compt. cabinet above bench seat inop, replace struts
9. side entry door will not open from inside, remove window and door panel, adjust latch rods, reinstall window and door panel
10. service p/s
11. defrosters inop, hook up laptop, found vent actuator inop, remove found actuator cam cracked, install new one and recheck, now work
12. air system leaks down overnight, use soap and water to check for leaks, found multiple leaks, replace fittings, recheck for leaks, held overnight now
13. hook up laptop and update international software

Parts

Quantity

15-40B15W40 MOTOR OIL NON SYN	30
1878042C91FUEL FILTER 2008 HORTON	1
21481SEARCHLIGHT CONTROL	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
3542606C12611234C1 VENT ACTUATOR	2
3598042C1LOUVER DASH INT.	4
3598043C2LOUVER DASH INT.	4
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
FREIGHTSHIPPING CHARGES	1
HLD3999GSS1715UV 30LB STRUT GAS	2
VML/T1808D2503221C1 FILTER POWER STEERING	1

Workorder: V57640

In Date: 05/10/2013

Meter Reading: 76,273.00

Close Date: 01/24/2014

Problem?

Install front bumper light poles on R47

Task performed:

VERIFIED COMPLAINT. WORK COMPLETED ON ANOTHER WORK ORDER.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V63188

In Date: 01/07/2014

Meter Reading: 78,140.00

Close Date: 01/24/2014

Problem?

REPAIR COOLANT LEAK Q47

Task performed:

1. TRACED OUT COOLANT LEAK AND REPAIRED LOWER COOLANT HOSE.
2. REMOUNTED TOOLS IN L-1 COMPARTMENT.

Parts

ALA00350-50 EXTENDED LIFE COOLANT GAL

Quantity

6

Workorder: V63514

In Date: 01/18/2014

Meter Reading:

Close Date: 02/06/2014

Problem?

right front tire making popping sound while braking. Tire shaking while driving on the highway going over 45 MPH R47

Task performed:

- ROAD TESETD TRUCK AND DID NOT FEEL OR HEAR POPING NOISE.

Parts

NO PARTS USED

Quantity

Workorder: V64214

In Date: 02/13/2014

Meter Reading: 79,670.00

Close Date: 02/18/2014

Problem?

QC vehicle - cam shaft replaced by dealer

Task performed:

1. Q.C VEHICLE.
2. REPLACED FRONT BRAKE SHOES AND DRUMS- WAS AND BLOW OFF ALL COMPONENTS.
3. ASSIST NORRIS WITH ABOVE BRAKE REPAIR.
4. COMPLETE LEFT SIDE OF ENGINE BLOCK COVERED IN OIL- LAYED OIL ABSORBENT PADS AND CLEANED OFF ENGINE BLOCK, ALSO FOUND OIL PAN BOLTS LOOSE TIGHTEN ALL BELTS TAKE VEHICLE ON LONG ROAD TEST- RECHECK FOR OIL LEAKAGE ALL CHECKED OUT OK.
5. ASSIST NORRIS WITH OIL DEBRIS OF BLOCK AND CLEANING.
6. DRIVERS SEAT BOTTOM SEAT CUSHION ABOUT TO FALL OFF SEAT FRAME- REMOVE THE ONLY REMAINING BOLT- MATCH UP BOLT, AND INSTALL MISSING BOLTS.
7. REMOVE AND REPLACE CITY HORN FOUND BOTH HORNS BROKEN.
8. PRESSURE TEST COOLANT SYSTEM AND FOUND COOLANT LEAK BEHIND TURBO.

Parts

3523179C92ELECTRIC HORN LOW

3558466C92ELECTRIC HORN HI

3753BRAKE DRUM RUMPER FRONT

KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE

Quantity

1

1

2

2



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V64420

In Date: 02/20/2014
Close Date: 02/21/2014

Meter Reading: 80,245.00

Problem?

camshaft failure

Task performed:

CAMSHAFT FAILURE. WARRANTY.

Parts

NO PARTS USED

Quantity

Workorder: V63724

In Date: 01/26/2014
Close Date: 02/25/2014

Meter Reading:

Problem?

Piece that catches and holds left rear door is loose and not holding door in place.

Task performed:

ALTERNATOR BELT, REPLACED BELT THAT WAS WORN.

Parts

BHC207ZS LATCH
K080570BELT

Quantity

3
1

Workorder: V63929

In Date: 02/03/2014
Close Date: 03/05/2014

Meter Reading: 79,670.00

Problem?

running rough

Task performed:

CHECKED ENGINE CODES AND ROAD TESTED SWAPED OUT TRUCK.

Parts

59-0867DASH VENTS

Quantity

1

Workorder: V64712

In Date: 03/05/2014
Close Date: 03/05/2014

Meter Reading:

Problem?

the truck has a hard time starting after only setting for 4 hours or so. even when plugged in. this is an ongoing issue. the starter has been replaced in the last several month

Task performed:

REPLACED ENGINE OIL AND CHECK FOR CODES NO CODES ACTIVE AT THIS TIME. STARTS FINE NOW.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V64713

In Date: 03/05/2014
Close Date: 03/10/2014

Meter Reading:

Problem?

r47 needs a new docking station. MDC keeps undocking and no one has been able to fix it.

Task performed:

REPAIRED BY RADIO SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V64929

In Date: 03/14/2014
Close Date: 03/17/2014

Meter Reading: 81,679.00

Problem?

cab a/c inop

Task performed:

CHECK A/C FOR OPERATION FOUND NEED NEW COMPRESSOR AIR DRIER AND EXPANSION BAND. REPLACE AIR PARTS REFILL AND TEST FOR OPERATION IS GOOD NOW.

Parts

3611894C9103-0805 A/C COMPRESSOR 4347
3660853C22512331C1 EXP VALVE NAV
3670134C1ACCUMULATOR ASSY INT.

Quantity

1
1
1

Workorder: V62759

In Date: 12/17/2013
Close Date: 03/19/2014

Meter Reading: 76,678.00

Problem?

Ordered new a/c vent deflectors Removed from new rescue, need to re-install on asset#10194778

Task performed:

PARTS ONLY NO LABOR.

Parts

NO PARTS USED

Quantity

Workorder: V64372

In Date: 02/19/2014
Close Date: 03/19/2014

Meter Reading:

Problem?

Noise from siren inside cab is excessive R47

Task performed:

FOUND SIREN SPEAKERS ON BACKWARDS FROM INTERNATIONAL, REMOVED AND REPAIRED.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V62771

In Date: 12/17/2013
Close Date: 03/26/2014

Meter Reading:

Problem?

front left tire has a cut in the sidewall, Ed at ST-42 is advised.

Task performed:

REPAIRED BY ELPEX ON WORK ORDER #62779.

Parts

NO PARTS USED

Quantity

Workorder: V65206

In Date: 11/28/2013
Close Date: 03/26/2014

Meter Reading:

Problem?

back tires worn to tread bump R47

Task performed:

BACK TIRES WORN TO TREAD BUMP R47.

Parts

NO PARTS USED

Quantity

Vendor? BOULEVARD TIRE

Workorder: V64904

In Date: 03/12/2014
Close Date: 03/28/2014

Meter Reading:

Problem?

FRONT AC NOT WORKING

Task performed:

TRACED OUT PROBLEM FOUND A/C COMPRESSOR
NEEDDS TO BE REPLACED.

Parts

NO PARTS USED

Quantity

Workorder: V65452

In Date: 04/04/2014
Close Date: 04/25/2014

Meter Reading: 83,106.00

Problem?

coolant leak

Task performed:

1. REPAIRED COOLANT LEAK ON LOWER HOSE.
2. REPAIRED HOOD LATCH THAT WAS OFF.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V65545

In Date: 04/08/2014
Close Date: 04/25/2014

Meter Reading: 83,106.00

Problem?
A/C inop

Task performed:

RECHARGED A/C AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V65902

In Date: 04/23/2014
Close Date: 04/30/2014

Meter Reading: 84,195.00

Problem?
C insp. and repairs as needed

Task performed:

1. C insp.
2. cab a/c inop, check system, found high pressure switch inop, replace switch a/c now cools down to 29deg.
3. engine temp will not go to operating temp. check system, found fan clutch stays on all the time and has a wobble, remove fan and fan clutch, install new fan clutch and replace fan, drain cooling system and replace thermostat, refill system, road test system, temp. now normal
4. repalce wiper blades
5. replace fan belt and a/c belt
6. battery's failed test, battery tray har to open, clean and lube tracks, install new battery's
7. cab spot light inop, remove center console, found control head inop, replace control head
8. replace cab a/c filter (red dot)
9. rear lite bar inop. in park, reprogram horton system
10. r/rear door red reflector missing, replace
11. lite on EMT work bench inop. replace bulbs
12. replace pat. compt. a/c filters
13. 110v a/c inop, found thermostat bad, install and wire up new thermostat
14. repalce non skid tape on rear and side entry door's
15. road test vehicle

Parts

0775145PANEL FILTER	1
15-40B15W40 MOTOR OIL NON SYN	30
1842130C11842130C3 THERMOSTAT DT466	1
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2020-DDASH MOUNT REMOTE CONTROL	1
2506656C124316 WIX CAB A/C FILTER	1
3546241C1SWITCH A/C PRESSURE INT.	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
ANTICOOLANT ANTIFREEZE GAL	7
B484RB484R REFLECT-RED	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
HOR994972FAN CLUTCH INT. 3611885C93	1
HP-31DBATTERY 950CCA HP-31D	3
K060695BELT	1
TH5220D1003WALL THERMOSTATE HORTON	1

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V65810

In Date: 04/18/2014

Meter Reading:

Close Date: 05/22/2014

Problem?

rear passenger door bumper stopper fell off, needs new screws. Bumper is in OIC quarters @ st 47 A/c inop

Task performed:

Parts

Quantity

1. REPLACED DOOR HOLD OPEN BRACKET ON LEFT SIDE AND REPAIRED DOOR HINGE.
2. REPAIRED A/C THAT WAS OUT, FOUND LOW ON R-134.

DRC401202840048 DOOR GRABBER

1

Workorder: V63789

In Date: 01/28/2014

Meter Reading: 79,670.00

Close Date: 06/10/2014

Problem?

no start

Task performed:

Parts

Quantity

REPAIRED ON W.O #63935 BY TOM TORCHIA.

82000056808 38MT 12T STARTER

1

Workorder: V66550

In Date: 05/17/2014

Meter Reading:

Close Date: 06/11/2014

Problem?

Leak in the radiator. Approx half full R47

Task performed:

Parts

Quantity

Repaired small leak at bottom hoses.

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V66984

In Date: 06/05/2014

Meter Reading: 212,328.00

Close Date: 06/18/2014

Problem?

running rough

Task performed:

1. CHK ENGINE FOR MISS- RAN ENGINE, NO MISS. CHK CODES DPF NEEDS SERVICED AND REMOVED AIR DRIER AND TUBES- CHK CROSS OVER EGR PIPE- COOLERS CHK OK- REASSEMBLED-CHK EGR VALVE.
2. CHK COOLANK LEAKS- FILLED SYSTEM- PRESSURE TEST SYSTEM- REPAIRED RAD HOSE AND WATER PIPE LEAKS- CHK OK.
3. CHK ENG FOR MISS- REMOVED D.P.F PRESS TUBES.
4. ENG MISS CONT REMOVED TEMP SENSORS, CLAMPS, CUT WELDS AND REMOVED PREFILTER PIPE- CLEANED PIPE.
5. ENG MISS CONT SMOTHERED OUT CUT WELDS- REMOVED AND REPAIRED PRESS TUBE FITTING- REPLACED D.P.F- INSTALLED PREFILTER AND PIPE
6. ENG MISS CONT: REINSTALLED TEMP, SENSORS AND PRESS. TUBE TIED UP ALL WIRES- CHK OK.
7. FOUND STAR WASHERS ON PAT BOX GROUNDS- REMOVED GROUND AND STAR WASHERS- CLEANED FRAME AND CABLES.
8. REPAIR GROUNDS CONT- REINSTALLED ALL GROUNDS- CHK OK.
9. CHK OIL LEAK ON DRIVER SIDE- CLEANED AREA- RAN ENGINE- FOUND OIL PRESSURE SENDING UNIT LEAKING- REMOVED WASHER BOTTLE AND BRKT- R&R SENDING UNIT- CHK OK REASSEMBLED.
10. CHK ENG MISS CONT- RAN KEYON ENG OFF TESTS-CHK OK- NEED TO REPLACE OIL RAIL SEALS AND INJECTORS.
11. CHK ENG MISS CONT: REMOVED AIR CLEANER, TUBES AND BREATHER TUBE VALVE COVER.
12. CHK FOR AIR LEAKS- SPRAYED LINES AND FITTINGS- FOUND AIR LINE TO FAN CLUTCH LEAKING- REPAIRED LEAK AND CHK OK.
13. CHK ENG MISS- REMOVED INJ- HARNESS, VALVE COVER/HARNESS OIL RAIL AND INJECTORS- R&R INJ TUBE SEALS- R&R INJECTORS- R&R ICP SENSOR- INSTALLED OIL RAIL.
14. CHK ENG MISS CONT AND RAN TEST DROVE TO GET TO OPERATING TEMP- RAN ENG RUN TESTS AND CHK OK CLEANED BAY.

Parts

Quantity

1839415C91OIL PRESSURE SENSOR	1
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
1875784C921875784C93 ICP SENSOR	1
2593986C1DPF GASKET	1
2593998C1DPF GASKET	1
5010561R925010561R93 INJECTOR	6
DPFCLEANED UNIT	1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V67572

In Date: 06/30/2014

Meter Reading:

Close Date: 07/09/2014

Problem?

R47 coolant hose broken, leaking coolant

Task performed:

Parts

Quantity

Removed and replaced broken hoses

NO PARTS USED

Workorder: V68473

In Date: 08/07/2014

Meter Reading:

Close Date: 08/08/2014

Problem?

Air Dump system has a leak

Task performed:

Parts

Quantity

Check dump system. Found level valve leaking. Adjusted valve. Recheck system. Check ok. Return to shop.

NO PARTS USED

Workorder: V69145

In Date: 09/03/2014

Meter Reading: 91,164.00

Close Date: 09/05/2014

Problem?

cab a/c inop

Task performed:

Parts

Quantity

repaired bad connection on blower motor and tested ok.

NO PARTS USED

Workorder: V69007

In Date: 08/27/2014

Meter Reading:

Close Date: 09/08/2014

Problem?

Squealing of front brakes.

Task performed:

Parts

Quantity

ROARTESTED TRUCK DID NOT HEAR SQUEAKING FROM BRAKES CK, BRAKES CK, OK. TRACED OUT AIR LEAKS.

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V69136

In Date: 09/03/2014
Close Date: 09/08/2014

Meter Reading: 91,164.00

Problem?
air leak

Task performed:

TRACED OUT AIR LEAKS AND REPAIRED.

Parts

NO PARTS USED

Quantity

Workorder: V69415

In Date: 09/16/2014
Close Date: 09/29/2014

Meter Reading: 91,713.60

Problem?
R47 coolant leak

Task performed:

replaced leveling valve for cab air bag.
repaired coolant leak from hose clamp.

Parts

NO PARTS USED

Quantity

Workorder: V69456

In Date: 09/17/2014
Close Date: 10/10/2014

Meter Reading: 91,713.60

Problem?
CAB LEVELING VALVE LEAKS R47

Task performed:

work is already complete on w/o 69415 on leveling
value...

Parts

2507385C1CAB AIR LEVEL VALVE INT

1

Quantity

Workorder: V69556

In Date: 09/21/2014
Close Date: 10/10/2014

Meter Reading: 92,206.00

Problem?
Stryker charger for stretcherbatteries stopped working R47

Task performed:

batteries delivered

Parts

NO PARTS USED

Quantity

Will have new charger sent to station.



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V69703

In Date: 09/25/2014

Meter Reading: 92,446.00

Close Date: 10/15/2014

Problem?

B inspection R47 by OCS

Task performed:

B inspection

Parts

Quantity

1878042C91FUEL FILTER 2008 HORTON

1

2506656C124316 WIX CAB A/C FILTER

1

5774457744XD OIL FILTER

1

Vendor? OCS

Workorder: V70196

In Date: 10/16/2014

Meter Reading:

Close Date: 10/28/2014

Problem?

2 front tires are bald, need to be changed out ASAP.

Task performed:

WORK REPAIRS REQUESTED

Parts

Quantity

NO PARTS USED

Vendor? BLVD. TIRE CENTER

Workorder: V70448

In Date: 10/26/2014

Meter Reading:

Close Date: 10/29/2014

Problem?

R47 needs 3 new rear tires due to being bald as well as being unlevel with the new rear left tire replaced, per the shop, requesting replace the remainin 3 tires.

Task performed:

WORK REPAIR REQUESTED.

Parts

Quantity

NO PARTS USED

Vendor? BLVD. TIRE CENTER

Workorder: V69990

In Date: 10/07/2014

Meter Reading: 92,710.00

Close Date: 10/31/2014

Problem?

siren inop

Task performed:

Siren inop-Removed and replaced siren head and tester

Parts

Quantity

SD-210RXSIREN DRIVER SMALL

1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V70197

In Date: 10/16/2014
Close Date: 10/31/2014

Meter Reading: 93,601.00

Problem?

Ground lights on both sides are broken, wires dangling on the floor. Light is intact, but the wires are exposed.

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---|--------------------------------------|-----------------|
| 1. Auto eject inoperable. Removed and replaced. | 0915520120AUTO EJECT 20 AERO OTL3925 | 1 |

Workorder: V70236

In Date: 10/17/2014
Close Date: 10/31/2014

Meter Reading: 93,994.00

Problem?

Ground lights: one on drivers side is out and one on passenger side is missing q47

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---|---------------|-----------------|
| 1. Repaired rear ground lights that were out. | NO PARTS USED | |
| 2. Repaired A/C blower motor that had bad connection on fuse. | | |

Workorder: V70237

In Date: 10/17/2014
Close Date: 10/31/2014

Meter Reading: 93,994.00

Problem?

Charger is not auto ejecting. q47

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---|---------------|-----------------|
| 1. Repaired coolant leak at top hose. | NO PARTS USED | |
| 2. Repaired tic charger that was not working. | | |

Workorder: V70709

In Date: 11/04/2014
Close Date: 11/07/2014

Meter Reading: 94,905.00

Problem?

replace 3 tires on rear

Task performed:

WORK REPAIRS REQUESTED.

Vendor? BLVD TIRE CENTER



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V70937

In Date: 11/14/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

a/c isn't cold; ;just warm air blowing

Task performed:

Test system 100 PSI both sides with comp running-R/R compressor, drier, all seals and o-rings. Adjust oil in comp., recharge system and read test 40 degrees from dash ducts. Rear cab aux needs work.

Parts

Quantity

3611894C9103-0805 A/C COMPRESSOR 4347

1

3670134C1ACCUMULATOR ASSY INT.

1

Workorder: V71406

In Date: 12/04/2014

Meter Reading: 96,992.00

Close Date: 12/04/2014

Problem?

r/r amber lite inop, R-47

Task performed:

install amber lite on r/rear of truck, only half lite up need to order another one, only had one in stock

Parts

Quantity

QL97SFCAAAMBER QUAD LIGHT

1

Workorder: V71344

In Date: 12/02/2014

Meter Reading: 96,992.00

Close Date: 12/05/2014

Problem?

Stuck in sand

Task performed:

Boynton Beach Blvd - 4 South 441. Pull out of sand. Stuck

Parts

Quantity

NO PARTS USED

Workorder: V72146

In Date: 01/09/2015

Meter Reading:

Close Date: 01/28/2015

Problem?

Coolant leak in rescue

Task performed:

1. Repaired coolant leak at fill tank.
2. Readjusted rear door linkage.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V72166

In Date: 01/09/2015
Close Date: 01/28/2015

Meter Reading: 99,393.00

Problem?

R47 Coolant Leak

Task performed:

1. Repaired coolant leak at all hose clamps.
2. Readjusted air bags and road tested.

Parts

NO PARTS USED

Quantity

Workorder: V72751

In Date: 01/30/2015
Close Date: 02/05/2015

Meter Reading: 100,476.00

Problem?

Air leak

Task performed:

1. Diagnose air leak. Found air bags leaking. Remove and install new air bags.
2. Assist M. McIntosh with repair.

Parts

GUI1R11216GY1R11216 AIR BAG INT.

2

Quantity

Workorder: V72734

In Date: 01/30/2015
Close Date: 02/18/2015

Meter Reading:

Problem?

R47 is leaking coolant daily, has to be refilled due to the engine light coming on, and instructions to shut the engine off come up. Also there is an air leak in either the breaks or the airbags that lower the truck

Task performed:

1. Will need to go to shop for repair or dealer at this time
2. Air bags have hole. Will send to shop.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V72879

In Date: 02/04/2015

Meter Reading: 101,057.00

Close Date: 03/11/2015

Problem?

C- INSPECTION

Task performed:

1. Perform "C" Service.
2. Troubel shoot rear emergency light amber. one only work half way. CK power gournd, connection, output mod, found that wrong light in unit, also wrong light order for replacement, order wright one.
3. Replace # 3 ground light on left side, and bracket also replace # 3 ground light on right side and bracket also. Also replace plug on one light. Drill and mount both brackets.
4. R&R dryer, remove clean and replace back on truck very dirty inside of unit.
5. CK battery found 2 bad batteries. Replaced all batteries in unity. Clean all terminal recheck charging system & shore changer. OK.
6. Replace both wiper blades. Repair sprayer. Replace step light.
7. CK. connection and power and ground, all good. Found bulb out replace and recheck ok.
8. CK out A/C fans under truck one not working, ck power and ground and connection. Found fan bad, replace set with updated one retest ok.
9. Charged all A/C filter in cab and rear, patient compartment ok.
10. Start on R&R both EGR cooler. Continue on cooler work.
11. R&R oil spinner filter on side of motor clean and reseal unit.
12. CK, UV light, ck power ground connection all ok, bad light, replace and rechecked ok.
13. R&R water pump after test drive, found leaking coolant.
14. Repalce air governor on compressor wood not build air after start up.
15. Start to troubleshoot A/C cab intermittently on and off.
16. Continue troubleshooting A/C system. Found bad wire in ECU, repalce and repair wiring also replace pressure switch, demisster both pump down and recharge system. Repair wire end and connection to A/C complete. R&R rear brakes complete.
17. Replace all coolant hoses to motor, bypass hose to EGR cooler hoses behind turbo, etc...
18. INstall all new eng, drive belts.
19. Q&A

Parts

Quantity

065624AD-IP DRIER	2
0775145PANEL FILTER	1
1842665C93WATER PUMP DT570	1
1847727C1BELT	1
1875880C2SEAL	1
1876922C91SEAL KIT	1
1878042C91FUEL FILTER 2008 HORTON	1
1878918C2EGR VALVE	1
211-2BULB	3
2506656C124316 WIX CAB A/C FILTER	1
284358GOVERNOR D-2	1
3546241C1SWITCH A/C PRESSURE INT.	1
3622764C32606229C92 THERMISTER	1
3757REAR DRUMS 3757X 3647X	2
4070091740 GROMMET T/L 4 IN	2
4307362R91KIT EGR COOLER COLD SIDE OLD 1876262C	1
46870AIR FILTER	1
50-2204FAN KIT DANHARD CONDENSER	1
5774457744XD OIL FILTER	1
61H01LED GROUND LITE CLEAR	2
7090595C91COOLER EGR KIT 330MM EXH SIDE OLD 1876	1
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	3
FRT 66562FREIGHT CHARGE	1
GPX13ULTRA VIOLET LIGHT SHORT	1
HP-31DBATTERY 950CCA HP-31D	3
K022105PURGE VALVE AD-IP-IS	1
K060695BELT	1
MFG01876GROUND LT BRACKET	1
QL97SFCAAAMBER QUAD LIGHT	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10188445

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V74668

In Date: 04/15/2015
Close Date: 04/17/2015

Meter Reading: 105,163.00

Problem?

AW coolant leak

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V74254

In Date: 03/28/2015
Close Date: 04/22/2015

Meter Reading:

Problem?

Emergency light broken on the driver side, above rear tire. Light, and light housing are both broken. R47

Task performed:

Parts

Quantity

1. Installed new light.

50R03ZCRLIGHT LED RED TIR 6

2

5FLANGEC5FLANGEC FLANGE CHROME

1

5TSMACMOUNT 500 TIR SER CHROME

1



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10188445) 2009 - HORTON 4400 Advanced Life Support Vehicle R47

10188445

CSHOP-2015-1011

Comments: **R47 BROKE DOWN**

Date Opened 6-5-2015

Date Finished

6-9-2015

Meter 1 Reading:

105,992

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

1 SENSOR; LEVEL SENSOR

CSHOP-2015-1175

Comments: **R47 BOX LIGHT CHARGER NOT WORKING**

Date Opened 6-15-2015

Date Finished

6-22-2015

Meter 1 Reading:

106,000

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

CSHOP-2015-122

Comments: **COOLANT LEAK R47**

Date Opened 4-17-2015

Date Finished

5-4-2015

Meter 1 Reading:

105,792

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR LATCH
COOLING SYSTEM
ENGINE AND ACCESSORIES
AUTO-EJECT

6 FLUID; 50-50 EXTENDED LIFE COOLANT GAL

CSHOP-2015-1954

Comments: **SCENE LT LENS BROKEN R 47**

Date Opened 7-27-2015

Date Finished

8-2-2015

Meter 1 Reading:

106,000

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

1 LENS; LENS CLEAR 68-1181349-3

CSHOP-2015-2030

Comments: **B SERVICE.**

Date Opened 7-30-2015

Date Finished

8-4-2015

Meter 1 Reading:

110,635

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; FUEL FILTER 2008 HORTON
1 FILTER; 57744XD OIL FILTER
1 FILTER; 24316 WIX CAB A/C FILTER

Asset Work Order History 10188445

CSHOP-2015-2128

Comments: **REPAIR FROM B SERVICE**

Date Opened 8-4-2015 Date Finished 8-6-2015 Meter 1 Reading: 110,635

INSTALLED NEW SEAT BELT AND TIGHTENED SEAT BASE

TASKS PERFORMED

Q PARTS

COOLING SYSTEM	2	WIPER; WIPER BLADE
SPOT LIGHTS	2	LIGHT; HEADLITE KIT WITH SEALER
LIGHTING SYSTEM	1	LIGHT; AMBER QUAD LIGHT
STROBE LIGHTS	1	BELT; SEAT BELT
SEAT BELTS	1	BELT; RECIEVER SEAT BELT BUCKLE WITH TETHER

CSHOP-2015-2549

Comments: **FRONT AND REAR DRIVER SIDE TIRE DOWN TO WEAR BAR R47**

Date Opened 8-26-2015 Date Finished 9-2-2015 Meter 1 Reading: 110,635

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE
TIRES ALL
AIR CONDITIONING

CSHOP-2015-266

Comments: **R47 HEAVY WHITE SMOKE WHEN ACCELERATING COOLANT HOSE LEAKING CHECK EGR COOLERS**

Date Opened 4-24-2015 Date Finished 5-21-2015 Meter 1 Reading: 105,792

REPAIRED ON ANOTHER TICKEY

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES	1	CLAMP; CLAMP T-BOLT AIR INTAKE
	1	VALVE; EGR VALVE
	1	FITTING; FUEL FITTING
	1	FITTING; FUEL FITTING
	1	FITTING; FUEL LINE FITTING INT.
	1	SENSOR; SENSOR EBP
	1	COOLER; KIT EGR COOLER COLD SIDE OLD 1876262C96
	1	SENSOR; SENSOR MAP
	1	CLAMP; CLAMP T-BOLT AIR INTAKE COLD SIDE
	2	SLEEVE; FUEL LINE SLEEVE INT
	1	COOLER; COOLER EGR KIT 330MM EXH SIDE OLD 1876261C98
	1	TUBE; TUBE AIR INTAKE COLD SIDE
	1	FITTING; FITTING FUEL

Asset Work Order History 10188445

CSHOP-2015-2719

Comments: **R47 CHECK ENGINE LIGHT**

Date Opened 9-3-2015 Date Finished 9-23-2015 Meter 1 Reading: 114,194

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
DIAGNOSE ELECTRICAL
AIR SYSTEM
AIR CONDITIONING

CSHOP-2015-2784

Comments: **R47 STOP ENGINE LIGHT**

Date Opened 9-8-2015 Date Finished 9-8-2015 Meter 1 Reading: 112,972

TASKS PERFORMED

NO PARTS USED

ALARM-BUZZER-WARNING LIGHT

CSHOP-2015-3235

Comments: **R47 PAT A/C INOP**

Date Opened 10-5-2015 Date Finished 10-22-2015 Meter 1 Reading: 116,390

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
AIR CONDITIONING

CSHOP-2015-3359

Comments: **R47 LIGHT BOX CHARGER INOP**

Date Opened 10-13-2015 Date Finished 10-28-2015 Meter 1 Reading: 116,390

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES
AIR CONDITIONING

Service Requests:

10/16/2015 A/C / 19: LOOSE / REPAIR
CREW CAB A/C IS MALFUNCTIONING... WHILE BEING OPERATED THE A/C SEEMS TO GO FROM A HIGH SETTING TO A LOW SETTING CONTINUOUSLY.

10/16/2015 A/C / 15: FOREIGN MATERIAL / REPAIR
THE CREW CAB A/C IS MALFUNCTIONING. IT STILL WORKS. HOWEVER, IT SEEMS TO GO FROM A HIGH SETTING TO A LOW SETTING CONTINUOUSLY WHILE BEING OPERATED.

10/20/2015 LIGHTS / 19: LOOSE / REPAIR
REAR FLOOD LIGHT NOT WORKING ON OFFICERS SIDE

Asset Work Order History 10188445

CSHOP-2015-3670

Comments: **R47 TALK - TO NORRIS**

Date Opened 10-29-2015 Date Finished 11-13-2015 Meter 1 Reading: 117,986

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Service Requests:

10/29/2015 SERVICE REQUEST / 19: LOOSE / REPAIR
THE STAIR CHAIR COMPARTMENT ALARM IS UNABLE TO SHUT OFF, A SHOP MECHANIC CAME TO ST 47 OF WHICH REMOVED THE SENSOR, AND REQUESTED A SECONDARY WORK ORDER TO REPLACE THE SENSOR.

CSHOP-2015-3944

Comments: **R47 COOLANT LEAKS**

Date Opened 11-13-2015 Date Finished 11-13-2015 Meter 1 Reading: 117,986

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

11/13/2015 ENGINE / 18: LEAKING / EXCHANGE - USED
COOLENT LEVEL KEEPS GOING DOWN AND NEEDING TO BE FILLED ONCE A SHIFT. WE EITHER NEED MORE COOLENT OR HAVE THE SENSOR FIXED AGAIN.

CSHOP-2015-4047

Comments: **R47**

Date Opened 11-19-2015 Date Finished 12-8-2015 Meter 1 Reading: 119,574

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM 1 BULB; H9007 BULB ASSY
AIR CONDITIONING

Service Requests:

11/19/2015 LIGHTS / 16: GLAZED / REPAIR
DRIVER SIDE HEAD LIGHT IS OUT.

CSHOP-2015-4415

Comments: **BROKE DOWN AT BETHESDA WEST R47**

Date Opened 12-10-2015 Date Finished 12-10-2015 Meter 1 Reading: 119,574

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Asset Work Order History 10188445

CSHOP-2015-4615

Comments: **R47 REPAIRS FROM PM**

Date Opened 12-23-2015 Date Finished 1-27-2016 Meter 1 Reading: 122,106

TASKS PERFORMED

Q PARTS

WIPER BLADES	2	WIPER; WIPER BLADE
WIPERS-WASHER	-1	PULLEY; IDLER PULLEY
FUEL SYSTEM	1	PULLEY; IDLER PULLEY
SERPENTINE BELT TENSIONER	1	BELT; BELT TENSIONER
ENGINE AND ACCESSORIES	1	FILTER; AIR FILTER
LIGHTING SYSTEM	1	BULB; BULB
CROSS MEMBER	1	LIGHT; 700 SERIES SCENE
AIR DRIER	1	LIGHT; DOME LIGHT ASSY
DOOR	1	VALVE; PURGE VALVE AD-IP-IS
DOOR HANDLES INSIDE-OUTSIDE	1	DRYER; AD-IP DRIER
	1	INTERNATIONAL; CONTAINER

CSHOP-2015-4622

Comments: **R47 C INSPECTION**

Date Opened 12-23-2015 Date Finished 1-5-2016 Meter 1 Reading: 120,352

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE	1	FILTER; FUEL FILTER 2008 HORTON
	1	FILTER; 24316 WIX CAB A/C FILTER
	1	FILTER; 57744XD OIL FILTER

CSHOP-2015-4625

Comments: **NO POWER R47**

Date Opened 12-23-2015 Date Finished 12-23-2015 Meter 1 Reading: 119,910

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2015-839

Comments: **R47 COOLANT LEAK**

Date Opened 5-27-2015 Date Finished 5-28-2015 Meter 1 Reading: 105,892

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
AIR CONDITIONING

CSHOP-2016-107

Date Opened 1-8-2016 Date Finished 1-25-2016 Meter 1 Reading: 121,970

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
AIR CONDITIONING

Asset Work Order History 10188445

CSHOP-2016-1323

Date Opened 3-21-2016 Date Finished 3-23-2016 Meter 1 Reading: 125,865

TASKS PERFORMED

Q PARTS

AIR HORN
CAB-INTERIOR ACCESSORIES

1	BRACKET; 244770R1 HORN SUPPORT BRKT
2	SLIDE; 12 IN PAIR DRAWER SLIDES

Service Requests:

03/18/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
R47 PATIENT COMPARTMENT IV DRAWER (LOWER DRAWER ON PASSENGERS SIDE) NEEDS NEW SLIDING TRACKS.

03/19/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
BRACKET HOLDING DOWN LEFT HORN ON R47 (ABOVE DRIVER SIDE WHEEL WELL) IS CRACKED AND LOOSE

CSHOP-2016-1343

Comments: **R-47 REAR DOOR NOT WORKING.**

Date Opened 3-21-2016 Date Finished 3-25-2016 Meter 1 Reading: 125,865

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR

CSHOP-2016-1483

Comments: **R47**

Date Opened 3-29-2016 Date Finished 4-4-2016 Meter 1 Reading: 126,718

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TOWING HITCH
COOLING SYSTEM

Service Requests:

03/29/2016 ENGINE / 18: LEAKING / REPAIR
LOW COOLANT LEVEL ON ENGINE STARTUP FOR R47

03/29/2016 LIGHTS / 19: LOOSE / REPAIR
RIGHT HEADLIGHT OUT. GROUND LIGHT BELOW MAIN O2 COMPARTMENT OUT

03/31/2016 LIGHTS / 19: LOOSE / REPAIR
FRONT PASSENGER HEADLIGHT IS NOT WORKING.

CSHOP-2016-1750

Comments: **R47**

Date Opened 4-13-2016 Date Finished 4-20-2016 Meter 1 Reading: 127,833

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

1	A/C; FREON LB
---	---------------

Asset Work Order History 10188445

CSHOP-2016-1803

Comments: **R47 HEADLIGHT OUT**

Date Opened 4-18-2016 Date Finished 4-20-2016 Meter 1 Reading: 127,833

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR CONDITIONING

1 BULB; H9007 BULB ASSY

Service Requests:

04/17/2016 LIGHTS / 19: LOOSE / D
FRONT HEADLIGHT IS OUT ON R47

CSHOP-2016-2051

Date Opened 4-29-2016 Date Finished 5-9-2016 Meter 1 Reading: 129,009

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
AIR CONDITIONING

CSHOP-2016-2494

Comments: **ON-CALL R47 NO SIREN**

Date Opened 5-24-2016 Date Finished 5-24-2016 Meter 1 Reading: 130,223

SIREN INOP.

TASKS PERFORMED

Q PARTS

SIREN

1 SIREN; SIREN

CSHOP-2016-26

Comments: **ON-CALL R47 NO SIREN**

Date Opened 1-4-2016 Date Finished 1-12-2016 Meter 1 Reading: 120,911

TASKS PERFORMED

NO PARTS USED

SIREN

CSHOP-2016-2759

Date Opened 6-9-2016 Date Finished 6-9-2016 Meter 1 Reading: 131,246

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

Asset Work Order History 10188445

CSHOP-2016-2849

Date Opened 6-14-2016 Date Finished 7-17-2016 Meter 1 Reading: 133,563

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

06/14/2016 TIRES / 44: WORN / EXCHANGE - NEW
BOTH OUTSIDE REAR TIRES NEED REPLACED. INSIDE REAR TIRES MAY NEED REPLACED AT THE SAME TIME.
WOULD BE MECHANICS DISCRETION.

06/17/2016 TIRES / 44: WORN / EXCHANGE - NEW
FRONT DRIVER SIDE TIRE IS WORN DOWN TO WEAR BAR. BOTH REAR TIRES ARE ALSO WORN DOWN

CSHOP-2016-3016

Comments: **R47 REAR DOOR INOP**

Date Opened 6-22-2016 Date Finished 6-22-2016 Meter 1 Reading: 132,124

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
REAR DOOR
DOOR LATCH

CSHOP-2016-3050

Comments: **R47**

Date Opened 6-24-2016 Date Finished 6-24-2016 Meter 1 Reading: 132,437

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

1 HOSE; RADIATOR HOSE
8 FLUID; COOLANT ANTIFREEZE GAL

Service Requests:

06/24/2016 ENGINE / 18: LEAKING / UPPER RADIATOR HOSE BURST. REPLACED FAILED HOSE, FILLED SYS`
RADIATOR HOSE BUSTED.

CSHOP-2016-3320

Comments: **R47 PAT A/C INOP**

Date Opened 7-8-2016 Date Finished 7-11-2016 Meter 1 Reading: 133,204

AC IN REAR OF TRUCK INOP.

TASKS PERFORMED

Q PARTS

AIR CONDITIONING

2 A/C; FREON LB

Asset Work Order History 10188445

CSHOP-2016-3611

Date Opened 7-28-2016 Date Finished 7-30-2016 Meter 1 Reading: 134,488

TASKS PERFORMED

Q PARTS

AIR FILTER
REPAIR FROM PM - BRAKES
AIR HORN

1 FILTER; AIR FILTER
2 BRAKE; BRAKE DRUM RUMPER FRONT
2 BRAKE; FRONTBRAKE KIT RUMPER AND 4DR RESCUE
2 NEWPART; BRAKE SHOES
2 BRAKE; REAR DRUMS 3757X 3647X

CSHOP-2016-3615

Comments: **B INSPECTION R47**

Date Opened 7-28-2016 Date Finished 7-30-2016 Meter 1 Reading: 134,249

TASKS PERFORMED

Q PARTS

PM SERVICE B

30 MOTOR; 15W40 MOTOR OIL NON SYN
1 FILTER; FUEL FILTER 2008 HORTON
1 FILTER; 57744XD OIL FILTER
1 FILTER; 24316 WIX CAB A/C FILTER

CSHOP-2016-4358

Date Opened 9-6-2016 Date Finished 9-6-2016 Meter 1 Reading: 136,931

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

CSHOP-2016-4400

Date Opened 9-8-2016 Date Finished 9-9-2016 Meter 1 Reading: 137,138

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
HEADLIGHTS LOW BEAM

2 LIGHT; LOCK RING HEADLITE

CSHOP-2016-4418

Date Opened 9-10-2016 Date Finished 10-12-2016 Meter 1 Reading: 138,311

TASKS PERFORMED

Q PARTS

CAB-INTERIOR ACCESSORIES

1 LENS; LENS CLEAR 68-1181349-3

Service Requests:

09/10/2016 LIGHTS / 19: LOOSE / REPAIR
MISSING LIGHT COVER . OFFICER SIDE MID-UPER LIGHT. LIGHT STILL WORKS COVER JUST FELL OFF.

Asset Work Order History 10188445

CSHOP-2016-5356

Comments: **R47 C INSPECTION BY H2**

Date Opened 11-15-2016 Date Finished 11-17-2016 Meter 1 Reading: 138,311

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

30 FLUID; SYN OIL BULK QTS
1 FILTER; FUEL FILTER 2008 HORTON
1 FILTER; 57744XD OIL FILTER
1 FILTER; 24316 WIX CAB A/C FILTER

VENDOR? H2 FIRE SERVICES

CSHOP-2016-5445

Comments: **REPAIRS FROM PM R47**

Date Opened 11-21-2016 Date Finished 11-22-2016 Meter 1 Reading: 138,448

TASKS PERFORMED

Q PARTS

LENS
LIGHTING SYSTEM
BATTERY
BRAKES
FAULT CODE

1 BULB; BULB
1 LENS; LENS CLEAR 68-1181349-3
3 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
3 BATTERY; BATTERY 950CCA HP-31D

CSHOP-2016-5471

Date Opened 11-23-2016 Date Finished 11-23-2016 Meter 1 Reading: 138,448

TASKS PERFORMED

NO PARTS USED

TRANSMISSION

CSHOP-2016-5805

Date Opened 12-12-2016 Date Finished 12-16-2016 Meter 1 Reading: 140,067

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

12/10/2016 MISCELLANEOUS / 18: LEAKING / REPAIR
THE SCREW FOR THE BRACKET ON THE DRIVER COMPARTMENT SIDE WHAT HOLDS THE SCBA PACK IS STRIPPED
AND NOW THE SCBA HAS TO BE HELD IN THE CAB. ALL WE NEED IS SOMEONE TO DRILL THE DRIVER SIDE DOOR TO
PLACE BRACKET.

Asset Work Order History 10188445

CSHOP-2016-727

Comments: **ON CALL R47**

Date Opened 2-16-2016 Date Finished 2-19-2016 Meter 1 Reading: 123,684

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

02/15/2016 ALARMS / 18: LEAKING / REPAIR
FREQUENT ALARM FOR WATER TEMP GAUGE OVER 230, OIL DIP STICK SHOWS HIGH OIL LEVEL (WAY OVER HASH MARKINGS)

CSHOP-2016-821

Comments: **UNIT OVERHEATING**

Date Opened 2-19-2016 Date Finished 2-24-2016 Meter 1 Reading: 123,735

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
OIL

1 THERMOSTAT; 1842130C3 THERMOSTAT DT466
1 NEWPART; KIT SEAL OIL COOLER
1 SEAL; SEAL KIT OIL COOLER
1 FILTER; 57744XD OIL FILTER

CSHOP-2017-1413

Date Opened 3-7-2017 Date Finished 5-2-2017 Meter 1 Reading: 151,832

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
INSTRUMENTS-GAUGES-WARNING &

CSHOP-2017-1942

Comments: **R47**

Date Opened 4-3-2017 Date Finished 4-12-2017 Meter 1 Reading: 150,525

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
INSTRUMENTS-GAUGES-WARNING &

Service Requests:

04/02/2017 LIGHTS / 19: LOOSE / REPAIR
VEHICLE LIGHTS NOT WORKING

Asset Work Order History 10188445

CSHOP-2017-2246

Date Opened 4-17-2017 Date Finished 5-5-2017 Meter 1 Reading: 152,065

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
LIGHTING SYSTEM
DIAGNOSE ELECTRICAL
INSTRUMENTS-GAUGES-WARNING &

1 9IP; BULB

Service Requests:

04/17/2017 LIGHTS / 18: LEAKING / REPAIR
R47 VEHICLE LIGHTS NOT WORKING, DRIVER SIDE GROUND LIGHT NOT WORKING.

04/17/2017 LIGHTS / 18: LEAKING / REPAIR
R47 VEHICLE LIGHTS NOT WORKING, REAR FLOOD LIGHT OUT.

CSHOP-2017-275

Comments: **R-47 REAR A/C MAKING NOISE**

Date Opened 1-13-2017 Date Finished 1-26-2017 Meter 1 Reading: 143,605

TASKS PERFORMED

NO PARTS USED

ELECTRICAL
AIR SYSTEM
AIR CONDITIONING

Service Requests:

01/13/2017 A/C / 19: LOOSE / REPAIR
A/C ISSUE. A/C IS MAKING A HIGH TONED WHISTLING SOUND. STILL RUNNING AND COOLING REAR PATIENT
COMPARTMENT WELL BUT WHISTLING.

CSHOP-2017-2792

Comments: **INSTALL NEW TIC CHARGER AND TIC GET PARTS FROM WAYNE**

Date Opened 5-11-2017 Date Finished 5-12-2017 Meter 1 Reading: 152,551

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

CSHOP-2017-2944

Date Opened 5-18-2017 Date Finished 5-24-2017 Meter 1 Reading: 152,662

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

18 90C; BULK TRANS SYN
30 90C; SYN 15W40
1 FIL; NAPAGOLD OIL FILTER
1 TWD; REP/CART
1 FIL; NAPA GOLD FUEL FILTER
1 FIL; NAPA TRANS FILTER
2 1AN; WIPERS
1 TWD; AD-IP AD-IS PURGE VLV

Asset Work Order History 10188445

CSHOP-2017-2953

Comments: **P.M. REPAIR**

Date Opened 5-18-2017

Date Finished

5-25-2017

Meter 1 Reading:

152,662

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS

2

MAC; NON-CHLOR BRAKE CLNR

FUEL SYSTEM

1

9AP; LIGHT

OIL FILTER

2

2IH; LIGHT

LIGHTING SYSTEM

1

2IH; HOSE AIR COMP

REPAIR FROM PM - AIR SYSTEM

4

MAC; NON-CHLOR BRAKE CLNR

REPAIR FROM PM - REAR SUSPENSION

-1

TWD; BENDIX

REPAIR FROM PM - BELTS

1

TWD; BENDIX

REPAIR FROM PM - ENGINE

1

TWD; BENDIX

REPAIR FROM PM - TRANSMISSION

1

2IH; GASKET

REPAIR FROM PM - STEERING

1

2IH; COMPRESSOR

1

2IH; GASKET

1

2IH; DRAIN

2

2IH; POWER STEERING FLUID 32OZ

1

2IH; AIR COMP BREATHER GASKET

2

2IH; SPRING AIR

1

NBH; SERPENTINE BELT

1

2IH; SEAL

1

2IH; SEAL KIT

1

NBH; V-RIBBED BELT

1

9IP; PS RESV GASKET

1

FIL; POWER STEERING FILTER

CSHOP-2017-3149

Date Opened 5-30-2017

Date Finished

5-30-2017

Meter 1 Reading:

152,997

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

05/29/2017

SERVICE REQUEST / 19: LOOSE / REPAIR

SERVICE REQUEST PLEXIE GLASS ON INTERIOR DOOR NEEDS SMALL SCREWS TO MOUNT BACK IN PATIENT COMPARTMENT DOOR

CSHOP-2017-3228

Comments: **R47**

Date Opened 6-2-2017

Date Finished

6-6-2017

Meter 1 Reading:

153,562

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

BODY EXTERIOR

AIR CONDITIONING

Service Requests:

06/01/2017

DOOR / 18: LEAKING / REPAIR

VEHICLE DOORS- DRIVER COMPARTMENT DOOR, THE BRACKET HOLDING THE PICK HEAD AXE IS MISSING A SCREW AND IS ONLY HELD ON THE DOOR BY ONE OTHER SCREW.

Asset Work Order History 10188445

CSHOP-2017-331

Comments: **R47 CHECK OIL LEVEL AND SEE IF IT NEEDS TO COME TO SHOP FOR OIL CHANGE.**

Date Opened 1-17-2017 Date Finished 1-20-2017 Meter 1 Reading: 142,997

TASKS PERFORMED

Q PARTS

HOSE UPPER
OIL

1 NBH; CURVED RADIATOR HOSE
1 2IH; 2IH
24 9IP; 15W40 MOTOR OIL NON SYN

Service Requests:

01/17/2017 SERVICE REQUEST / 15: FOREIGN MATERIAL / LUBRICATE
OIL LEVEL IS ABOVE THE NORMAL RANGE. YESTERDAY THEY NOTICED WHITE PUFFS OF SMOKE COMING FROM MUFFLER WHILE DRIVING.

CSHOP-2017-3334

Date Opened 6-6-2017 Date Finished 6-6-2017 Meter 1 Reading: 153,562

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SUSPENSION
INSTRUMENTS-GAUGES-WARNING &

CSHOP-2017-3397

Date Opened 6-8-2017 Date Finished 6-9-2017 Meter 1 Reading: 153,967

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL
AIR CONDITIONING

Service Requests:

06/08/2017 LIGHTS / 18: LEAKING / REPAIR
LIGHT BOX (YELLOW) UNABLE TO CHARGE OR TURN ON

CSHOP-2017-3436

Date Opened 6-9-2017 Date Finished 6-13-2017 Meter 1 Reading: 154,262

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
AIR CONDITIONING

Service Requests:

06/09/2017 LIGHTS / 18: LEAKING / REPAIR
LED FLASHING LIGHTS IN GRILL AND RUNNING BOARD OF R-47 CAB TURN ON AS SOON AS YOU GO TO START THE TRUCK UP (TRUCK BATTERY IS ON), BUT THEY DO NOT FLASH WHEN THE MASTER WARNING LIGHT BUTTON IS TURNED ON (IN PRIMARY WARNING MODE AND IN SECONDARY WARNING MODE). POSSIBLE GROUND/WIRING ISSUE?

Asset Work Order History 10188445

CSHOP-2017-3522

Date Opened 6-14-2017 Date Finished 6-14-2017 Meter 1 Reading: 154,371

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
INSTRUMENTS-GAUGES-WARNING &

CSHOP-2017-3746

Date Opened 6-26-2017 Date Finished 6-26-2017 Meter 1 Reading: 155,261

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

06/25/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
R47'S HOWLER (LOW FREQUENCY SIREN) DOES NOT SOUND LIKE IT IS WORKING PROPERLY. IT IS BARELY NOTICEABLE WHEN ACTIVATED

CSHOP-2017-3794

Date Opened 6-27-2017 Date Finished 6-27-2017 Meter 1 Reading: 155,386

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR
INSTRUMENTS-GAUGES-WARNING &

CSHOP-2017-3829

Date Opened 6-28-2017 Date Finished 7-14-2017 Meter 1 Reading: 156,561

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES

Service Requests:

06/28/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE: AC IN PATIENT COMPARTMENT LEAKS WHEN HOOKED UP TO THE STATION SHORELINE. UNABLE TO LEAVE RESCUE PLUGGED IN WITHOUT HAVING BIG PUDDLES IN THE BACK OF THE RESCUE

CSHOP-2017-3852

Comments: **COOLANT LEAK**

Date Opened 6-29-2017 Date Finished 6-30-2017 Meter 1 Reading: 155,563

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

06/29/2017 ENGINE / 18: LEAKING / REPAIR
COOLANT LINE RUPTURED AND LEAKING

Asset Work Order History 10188445

CSHOP-2017-3954

Comments: SENT CALLAGHAN SATURDAY 7-8-17 WITH 4 MOUNTED TIRES FROM OUR STOCK. THEY WILL MOUNT NEW TIRES MONDAY AND WE WILL PICK THEM UP.

Date Opened 7-5-2017 Date Finished 7-19-2017 Meter 1 Reading: 156,864

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

07/05/2017 TIRES / 18: LEAKING / REPAIR
R47'S REAR OUTER TIRES APPEAR TO BE CLOSE TO BALD/CLOSE TO THE DEPTH INDICATOR AND NEED TO BE REPLACED.

CSHOP-2017-4131

Date Opened 7-17-2017 Date Finished 7-18-2017 Meter 1 Reading: 156,864

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COMMERCIAL WORK - OUTSIDE AGENCY
DIAGNOSE ELECTRICAL
BODY EXTERIOR
AIR CONDITIONING

1 5EF; HANDLE LH
1 5EF; HANDLE

Service Requests:

07/16/2017 BODY / 18: LEAKING / REPAIR
R47'S DOOR HANDLE (PATIENT COMPARTMENT SIDE DOOR) IS CRACKED. IT CURRENTLY WORKS BUT APPEARS THAT IT WILL NEED TO BE REPLACED SOON.

CSHOP-2017-4336

Date Opened 7-26-2017 Date Finished 7-26-2017 Meter 1 Reading: 157,271

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
AIR SYSTEM

CSHOP-2017-4344

Date Opened 7-26-2017 Date Finished 7-26-2017 Meter 1 Reading: 157,271

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SUSPENSION

Service Requests:

07/26/2017 STEERING / 18: LEAKING / REPAIR
STEERING/ALIGNMENT VEHICLE PULLS TO THE RIGHT BAD AND MAKES A NOISE WHEN TURNING.

Asset Work Order History 10188445

CSHOP-2017-4648

Date Opened 8-10-2017 Date Finished 8-10-2017 Meter 1 Reading: 158,313

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM
AIR CONDITIONING

CSHOP-2017-4880

Date Opened 8-21-2017 Date Finished 8-25-2017 Meter 1 Reading: 159,451

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

08/20/2017 ALARMS / 18: LEAKING / REPAIR
ALARM SIGNALS-ENGINE COOLANT- HOSE POSSIBLY

CSHOP-2017-5033

Date Opened 8-26-2017 Date Finished 9-19-2017 Meter 1 Reading: 161,276

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
TRANSMISSION
STEERING
WINDSHIELD
BODY EXTERIOR
AIR CONDITIONING

4 9ME; ZICO RATCHET STRAPS
10 9IP; LUG NUT COVER PK10
2 1AN; 22`` WIPER BLADE
1 NFR; 30LB 134A REFRIGERANT

Service Requests:

08/26/2017 STEERING / 19: LOOSE / REPAIR
STEERING/ALIGNMENT

CSHOP-2017-5113

Date Opened 8-30-2017 Date Finished 9-15-2017 Meter 1 Reading: 161,064

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FIL; NAPA CABIN AIR FILTER
1 FIL; NAPA GOLD FUEL FILTER
2 2IH; POWER STEERING FLUID 32OZ
1 FIL; POWER STEERING FILTER
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD AIR FILTER
1 2IH; GASKET

Asset Work Order History 10188445

CSHOP-2017-5189

Date Opened 9-5-2017 Date Finished 9-9-2017 Meter 1 Reading: 160,147

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

3 MAC; CARB-CHOKE CLNR 13OZ
3 SF; MOTOR TUNE-UP 16OZ

CSHOP-2017-5304

Date Opened 9-12-2017 Date Finished 9-14-2017 Meter 1 Reading: 160,964

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-540

Comments: **R47 SCENE LIGHT NOT WORKING.**

Date Opened 1-24-2017 Date Finished 1-25-2017 Meter 1 Reading: 143,426

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

01/24/2017 LIGHTS / 19: LOOSE / REPAIR
THE LEFT REAR SCENE LIGHT IS NOT COMING ON.

CSHOP-2017-5418

Comments: **PLEASE CHECK OIL SERVICE WAS JUST DONE 129 MILES AGO MAYBE JUST OVERFILLED.**

Date Opened 9-18-2017 Date Finished 9-19-2017 Meter 1 Reading: 161,276

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

09/18/2017 OIL / 18: LEAKING / LUBRICATE
ENGINE OIL ABOVE MAX LEVEL ON R 47

CSHOP-2017-5509

Date Opened 9-22-2017 Date Finished 9-24-2017 Meter 1 Reading: 161,593

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL

3 1AD; BATTERY 31 SERIES

Service Requests:

09/22/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST

Asset Work Order History 10188445

CSHOP-2017-5532

Date Opened 9-24-2017 Date Finished 9-24-2017 Meter 1 Reading: 161,593

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

09/23/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
MULTIPLEX SYSTEM ERROR. THE CENTER CONSOLE IS DISPLAYING HORTON ERROR MESSAGES FOR THE MULTIPLEX SYSTEM ADVISING SEVERAL "MOD 10 PIN FAILS": "MOD 10 PIN 1 FAIL," "MOD 10 PIN 2 FAIL," "MOD 10 PIN 3 FAIL," "MOD 10 PIN 4 FAIL," "MOD 10 PIN 5 FAIL." VEHICLE APPEARS TO BE WORKING NORMALLY, BUT WE'D APPRECIATE IT IF ONE OF THE APPARATUS TECHS CAN TAKE A LOOK AT TO MAKE SURE IT'S NOTHING SERIOUS.

CSHOP-2017-5899

Date Opened 10-12-2017 Date Finished 10-13-2017 Meter 1 Reading: 163,131

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

2 BK; RADIATOR CAP

Service Requests:

10/12/2017 ENGINE / 12: BROKEN / REPAIR
LOW OIL AND LOW COOLANT

CSHOP-2017-5941

Comments: R47

Date Opened 10-16-2017 Date Finished 10-17-2017 Meter 1 Reading: 163,488

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TIRES & WHEELS
SUSPENSION

Service Requests:

10/14/2017 TIRES / 18: LEAKING / REPAIR
DRIVER'S SIDE REAR TIRE IS LOOKING LIKE IT WILL NEED TO BE REPLACED (IT IS NOT BALD YET, BUT TREAD IS GETTING THIN)

CSHOP-2017-604

Date Opened 1-27-2017 Date Finished 2-1-2017 Meter 1 Reading: 144,150

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
BODY EXTERIOR

Service Requests:

01/25/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST. THE DRIVER'S BUNKER GEAR COMPARTMENT NEEDS A NEW SCBA BRACKET FOR THE SCBA. THE SCBA DOES NOT CURRENTLY HAVE A STORAGE BRACKET AND IS JUST HANGING LOOSE IN THE COMPARTMENT BY A HOOK.

Asset Work Order History 10188445

CSHOP-2017-6169

Date Opened 10-26-2017 Date Finished 11-16-2017 Meter 1 Reading: 166,085

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL

Service Requests:

10/25/2017 TIRES / 18: LEAKING / REPAIR
BAD TIRES - 255/70-R 22.5 16PR PER TOMMY, DRIVERS OUTSIDE REAR TIRE NEEDS TO BE REPLACED

CSHOP-2017-626

Comments: **R47**
Date Opened 1-30-2017 Date Finished 2-6-2017 Meter 1 Reading: 144,581

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES 1 6KU; AUTO EJECT 20A
LIGHTING SYSTEM 1 9IP; OVAL AUTO EJECT COVER
HOOD HINGE
BODY EXTERIOR

Service Requests:

01/28/2017 LIGHTS / 19: LOOSE / REPAIR
VEHICLE LIGHTS NOT WORKING. 1 OF THE HALOGEN REAR LOADING LIGHTS ON R-47 IS BURNT OUT AND NEEDS TO BE REPLACED. THE HALOGEN SCENE LIGHT IS PART OF THE WHELEN 4500 PLUS SERIES LIGHT BAR.

01/29/2017 ENGINE / 19: LOOSE / REPAIR
ENGINE. THE OIL READING ON THE DIPSTICK ON R-47 IS HIGHER THAN THE RECOMMENDED RANGE

01/29/2017 BODY / 19: LOOSE / REPAIR
BODY ISSUE. THE BOTTOM LATCH ON THE EXTERIOR COMPARTMENT DOOR (WHERE THE DRIVER HANGS HIS SCBA PACK) IS HAVING PROBLEMS LATCHING ONTO THE NADER PIN.

CSHOP-2017-7317

Date Opened 12-22-2017 Date Finished 12-22-2017 Meter 1 Reading: 168,061

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-768

Date Opened 2-6-2017 Date Finished 2-10-2017 Meter 1 Reading: 144,581

TASKS PERFORMED

Q PARTS

PM SERVICE B 1 9IP; FUEL FILTER 2008 HORTON
1 FIL; NAPAGOLD OIL FILTER

Service Requests:

02/06/2017 ENGINE / 18: LEAKING / REPAIR
ENGINE OIL. ENGINE OIL IS STILL HIGH (ABOUT 1/2 INCH ABOVE THE MAX. RANGE ON THE DIPSTICK). HAS PREVIOUSLY BEEN WRITTEN UP MULTIPLE TIMES

Asset Work Order History 10188445

CSHOP-2017-90

Comments: **R-47 12 VOLT OUTLETS NOT WORKING**

Date Opened 1-4-2017

Date Finished

1-4-2017

Meter 1 Reading:

141,624

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
CAB-INTERIOR ACCESSORIES

Service Requests:

01/04/2017

SERVICE REQUEST / 19: LOOSE / REPAIR

CIGARETTE LIGHTER / 12 VOLT OUTLET, NOT WORKING IN BOTH FRONT AND REAR COMPARTMENT, UNABLE TO CHARGE SAFETY PAD

RADIO-2016-233

Comments: **ADJUSTED TENSION NUTS ON ARTICULATED MDC MOUNT.**

Date Opened 4-22-2016

Date Finished

4-22-2016

Meter 1 Reading:

127,918

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
RADIO

Service Requests:

04/21/2016

SERVICE REQUEST / /

RADIO SHOP. R47 DOCK SWINGS FREELY DURING TURNS ON TO DRIVER'S SIDE. MDC INTERMITTENTLY UNDOCKS WHILE DRIVING.
