



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1003984      **Meter:** 9504      **In Date:** 04/19/2010      **Closed:** 04/27/2010  
**Problem:** P. M. SERVICE

- P. M.	<b>Parts List</b>	<b>Qty</b>
- Fill all tires with nitrogen, rotate, reset tpms sensor system.	Shop Supplies	1.00
- Shop Supplies	Ch9018 Oil Filter Acd Pf457g Wix 57082	1.00
	5w30 Oil	5.00
Hours 3.50	Labor: 210.00	Parts: 24.22
:		Total: 234.22

**Workorder:** 1009773      **Meter:** 12902      **In Date:** 09/07/2010      **Closed:** 09/15/2010  
**Problem:** P. M., Lights on for Svc hybrid engine & Svc gas engine, Check R/F tire sensor (light intermittent)

- P. M. Service.	<b>Parts List</b>	<b>Qty</b>
- Install "how's my driving" decal.	Shop Supplies	1.00
- C/s: Check engine light is on. Verify, scan for codes & found code # P1a59, P1a19. Send to dealer for recall.	Ch9018 Oil Filter Acd Pf457g Wix 57082	1.00
	5w30 Oil	5.00
- Transport & pick up vehicle at dealer.		
- Dealer replace vehicle battery ! Recall hybrid battery pack !		
- Shop Supplies		
Hours 5.00	Labor: 300.00	Parts: 20.68
:		Total: 320.68

**Workorder:** 1010886      **Meter:** 13909      **In Date:** 10/04/2010      **Closed:** 10/04/2010  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1104048      **Meter:** 15068      **In Date:** 04/13/2011      **Closed:** 04/20/2011  
**Problem:** P.M. service and canceiver.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Install two new tires to the front wheels.nitrogen fill and balance all four.	Shop Supplies	1.00
	Ch9018 Oil Filter Acd Pf457g Wix 57082	1.00
- Perform wheel alignment complete.	Ca10115 Air Filter Wix 49102	1.00
- Shop Supplies	5w30 Oil	5.00
	31-24 Wiper Blades 24" Blade	1.00
	31-16 Wiper Blades 16" Wiper Blade	1.00
	738168571 225/60r17 Assurance Fuel Max 98t	2.00
	Tire Disposal Fee	2.00
Hours 6.50	Labor: 390.00	Parts: 296.82
:		Total: 686.82

**Workorder:** 1104255      **Meter:** 15072      **In Date:** 04/19/2011      **Closed:** 04/22/2011  
**Problem:** reflash canceiver spot 174

- Reflash Canceiver	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1108172      **Meter:** 15985      **In Date:** 08/04/2011      **Closed:** 08/05/2011  
**Problem:** Check left rear tire, low

- C/c: Check left rear tire. Verify nail in L/r tire. Dismount, patch, mount, balance, & add N2 to all tires. Clear Tpms.      **Parts List**      **Qty**  
Shop Supplies      1.00

- Shop Supplies

Hours 1.00      Labor: 60.00      Parts: 2.00      Total: 62.00  
:

---

**Workorder:** 1111041      **Meter:** 16380      **In Date:** 10/17/2011      **Closed:** 10/27/2011  
**Problem:** Pm service

- P.m. Service.      **Parts List**      **Qty**  
- Rotate and balance all tires.      Shop Supplies      1.00  
- Shop Supplies      Ch9018 Oil Filter Acd Pf457g Wix 57082      1.00  
5w30 Oil      5.00  
31-24 Wiper Blades 24" Blade      1.00  
31-16 Wiper Blades 16" Wiper Blade      1.00  
96624648 Rear Wiper Blade      1.00

Hours 3.00      Labor: 180.00      Parts: 42.39      Total: 222.39  
:

---

**Workorder:** 1204450      **Meter:** 17282      **In Date:** 05/10/2012      **Closed:** 05/17/2012  
**Problem:** P.M. service.

- P.m. Service.      **Parts List**      **Qty**  
- Replace right front signal light bulb.      Shop Supplies      1.00  
- Rotate and balance all tires.      Ch9018 Oil Filter Acd Pf457g Wix 57082      1.00  
- Shop Supplies      5w30 Oil      5.00

Hours 3.25      Labor: 195.00      Parts: 20.70      Total: 215.70  
:

---

**Workorder:** 1208156      **Meter:** 20017      **In Date:** 08/29/2012      **Closed:** 09/26/2012  
**Problem:** Pm service and check engine light on.

- Recharge battery and test battery and charging system.diagnose and replace negative battery cable to correct intermittent no charge.      **Parts List**      **Qty**  
Battery Tax      1.00  
Shop Supplies      1.00  
- Diagnose check engine light.c0045.perform pinpoint test and replace defective left rear wheel speed sensor.clear code and test drive.      Battery      1.00  
Negative Battery Cable      1.00  
- Shop Supplies      L/rear Wheel Speed Sensor      1.00

Hours 5.00      Labor: 300.00      Parts: 276.56      Total: 576.56  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1400605	<b>Meter:</b> 33132	<b>In Date:</b> 01/17/2014	<b>Closed:</b> 02/19/2014
<b>Problem:</b> pm ck lr tire , send out for detailing			
- pm	<b>Parts List</b>		<b>Qty</b>
- replace 4 tires	Napa Quart 5w30		5.00
- fill all tires with nitrogen	Napagold Oil Filter		1.00
- Shop Supplies	31-24 Wiper Blades 2		1.00
	Wiper Blade		1.00
	738168571 225-60r17		4.00
	Shop Supplies		1.00
	Tire Disposal Fee		4.00
Hours 4.50	Labor: 270.00	Parts: 746.97	Total: 1,016.97
:			
<b>Workorder:</b> 1408213	<b>Meter:</b> 38241	<b>In Date:</b> 08/19/2014	<b>Closed:</b> 08/29/2014
<b>Problem:</b> pm			
- pm	<b>Parts List</b>		<b>Qty</b>
- verify nail lr tire dismount patch mount balance add n2 rotate to fl	Napagold Oil Filter		1.00
- Shop Supplies	Napa Quart 5w30		5.00
	31-24 Wiper Blades 2		1.00
	Wiper Blade		1.00
	Washer Fl		1.00
	Shop Supplies		1.00
Hours 3.00	Labor: 180.00	Parts: 36.73	Total: 216.73
:			
<b>Workorder:</b> 1501728	<b>Meter:</b> 40841	<b>In Date:</b> 02/18/2015	<b>Closed:</b> 03/09/2015
<b>Problem:</b> Pm service.Has to jump start .Flat tire.			
- Pm service.	<b>Parts List</b>		<b>Qty</b>
- Test starting and charging system.battery failed loadtest after recharge.replace defective battery.	Dexos 5w30 Oil		5.00
- Inspect and replace defective dome lamp assembly.	Napagold Oil Filter		1.00
- Rotate and balance all four tires.	31-24 Wiper Blades 2		1.00
- Shop Supplies	Wiper Blade		1.00
	Wiper Blade		1.00
	Battery		1.00
	Lamp		1.00
	Shop Supplies		1.00
Hours 4.75	Labor: 285.00	Parts: 266.87	Total: 551.87
:			
<b>Workorder:</b> 1506615	<b>Meter:</b> 43683	<b>In Date:</b> 07/01/2015	<b>Closed:</b> 07/31/2015
<b>Problem:</b> Check engine light on.Right front door lock inop.Unable to fuel vehicle.			
- Diagnose check engine light.p0a9c,c1221.replace left front wheel speed sensor.clear codes and test drive.	<b>Parts List</b>		<b>Qty</b>
- Diagnose inop right front door lock.replace defective lock asemble.	Abs Sensor		1.00
- Transport vehicle to dealer for hydribd battery temp.sensor warranty.	Front Door Acculator		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 6.50	Labor: 390.00	Parts: 240.43	Total: 630.43
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1509113      **Meter:** 44113      **In Date:** 09/11/2015      **Closed:** 09/30/2015  
**Problem:** Pm service.Check for water in vehicle cabin.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Perform water leak test for windows and weatherstrips.leaking at rear door.remove seat and carpet.dry water from floor and carpet jute.replace rear weather strip and fabricate mounting.	Retainer	1.00
	Panel	1.00
	Handle	1.00
- Chrome peeling off driver door handle.r&r driver door panel and replace door handle.replace broken door sill trim.	Napa Quart 5w30	5.00
	Napagold Oil Filter	1.00
- Rotate and balance all tires.	Wiper Blade	1.00
- Shop Supplies	Wiper Blade	1.00
	Wiper Blade	1.00
	Washer Fluid Concentr	1.00
	Clr Rtv Silcn Sealant	1.00
	Weatherst	1.00
	Air Freshener	1.00
	Shop Supplies	1.00
Hours 10.50	Labor: 630.00	Parts: 303.55
:		Total: 933.55

**Workorder:** 1602893      **Meter:** 48041      **In Date:** 03/17/2016      **Closed:** 04/06/2016  
**Problem:** P.M. Service.TPSM light on.A/C not cold.

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Ac performance and leak test.bad compressor clutch.evacuate system.replace defective ac compressor,condenser/reciever drier assy and expansion valve.vacume and recharge system to specs.	Dexos 5w30	5.00
	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
- Service rear brakes.replace brake pads,machine rotors and service calipers.	Pag Oil	1.00
	Rear Brake Pad A/c Delco	1.00
- Diagnose and replace defective hood latch assembly and switch causing hood open indicator lamp to stay on.	Brake Cleaner	1.00
	R134a Lv Shop 2	2.00
- Rotate and balance all four tires.	Hood Latch Assembly	1.00
- Shop Supplies	Wiper Blades 24"	1.00
	Wiper	1.00
	A/c Compressor Assy	1.00
	A/c Condenser	1.00
	Expansion Valve	1.00
	Napa Cabin Air Filter	1.00
	Shop Supplies	1.00
Hours 14.00	Labor: 840.00	Parts: 1,134.31
:		Total: 1,974.31

**Workorder:** 1603495      **Meter:** 48041      **In Date:** 02/29/2016      **Closed:** 04/04/2016  
**Problem:** damage to hood & grille

- damage to hood & grille		
Hours 0.00	Labor: 0.00	Parts: 0.00
:		Total: 0.00

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1606951	<b>Meter:</b> 48274	<b>In Date:</b> 07/11/2016	<b>Closed:</b> 07/25/2016
<b>Problem:</b> Check engine light on and check right front tire.			
- Diagnose check engine ;light and Abs light.c1222 &c1224.test and replace right front and right rear speed sensors.clear codes.	<b>Parts List</b>		<b>Qty</b>
	Sensor		1.00
	Abs Sensor		1.00
- Repair and balance right rear tire.	Shop Supplies		1.00
- Shop Supplies			
Hours 4.50	Labor: 270.00	Parts: 136.06	Total: 406.06
:			

---

<b>Workorder:</b> 1612195	<b>Meter:</b> 48341	<b>In Date:</b> 11/29/2016	<b>Closed:</b> 12/27/2016
<b>Problem:</b> P.M. service and towed for no start.			
- P.m. Service.	<b>Parts List</b>		<b>Qty</b>
- Rotate and balance tires.	Napagold Oil Filter		1.00
- Test battery and charging system.replace bad battery.	Napa Syn 5w30 Qt		5.00
- Resurface front brakes rotors,replace front pads.service and lube calipers.flush and bleed system.	Wiper		1.00
	Wiper Blades 24"		1.00
- Replace right brake lamp bulb.	Wiper Blade		1.00
- Diagnose hybrid system fault.p0acb.perform pin point test.replace defective battery temp sensors.clear codes.	Washer Fluid Concentr		1.00
	Battery		1.00
- Shop Supplies	Front Brake Pad Ac Delco		1.00
	Non-chlor Brake Clnr		1.00
	Bulb		1.00
	Hybrid Battery Sensor		1.00
	Shop Supplies		1.00
Hours 11.50	Labor: 690.00	Parts: 398.65	Total: 1,088.65
:			

---

<b>Workorder:</b> 1612243	<b>Meter:</b> 48274	<b>In Date:</b> 11/29/2016	<b>Closed:</b> 11/30/2016
<b>Problem:</b> No start/PM			
- Tow From: 8100 Forest Hill Blvd in rear To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1700933	<b>Meter:</b> 48341	<b>In Date:</b> 01/30/2017	<b>Closed:</b> 01/30/2017
<b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1700981	<b>Meter:</b> 48503	<b>In Date:</b> 01/31/2017	<b>Closed:</b> 02/09/2017
<b>Problem:</b> needs 2 spare keys			
- Make and Program 2 keys	<b>Parts List</b>		<b>Qty</b>
- Test and remove canceiver issue fuel card	Key For Saturn Precut		2.00
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 66.17	Total: 186.17
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1701941	<b>Meter:</b> 49546	<b>In Date:</b> 02/24/2017	<b>Closed:</b> 03/28/2017
<b>Problem:</b> Towed in for no start.			
- Recharge battery and test charging system.check for draw,okay.		<b>Parts List</b>	<b>Qty</b>
		Battery Module A/c Delco	1.00
- Diagnose hybrid charging system.p0af8.perform pin point test.r&r hybrid battery and replace control module.clear codes.		Shop Supplies	1.00
- Shop Supplies			
Hours 5.50	Labor: 330.00	Parts: 787.90	Total: 1,117.90
:			
<b>Workorder:</b> 1701947	<b>Meter:</b> 49153	<b>In Date:</b> 02/24/2017	<b>Closed:</b> 02/27/2017
<b>Problem:</b> No start			
- Tow From: 4808 Brandywine dr, Boca Raton To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1702358	<b>Meter:</b> 49213	<b>In Date:</b> 03/08/2017	<b>Closed:</b> 03/08/2017
<b>Problem:</b> Vehicle No start			
- Tow From: 1381 Stonehaven Estates Dr To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1705410	<b>Meter:</b> 50973	<b>In Date:</b> 05/31/2017	<b>Closed:</b> 05/31/2017
<b>Problem:</b> 5 - Wash ticket(s) issued			
- 5 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1705780	<b>Meter:</b> 51294	<b>In Date:</b> 06/09/2017	<b>Closed:</b> 06/19/2017
<b>Problem:</b> PM service Check cracks on tires.			
- Pm service.		<b>Parts List</b>	<b>Qty</b>
- Repair left front marker light.		Napagold Oil Filter	1.00
- Replace all four tires		Napa Syn 5w30 Qt	5.00
- Fill all tires with nitrogen.		Washer Fluid Concentr	1.00
- Shop Supplies		Wiper Blades 24"	1.00
		Wiper	1.00
		Clr Rtv Silcn Sealant	1.00
		Bulb	1.00
		738168571 225-60r17	4.00
		Shop Supplies	1.00
		Tire Disposal Fee	4.00
Hours 5.50	Labor: 330.00	Parts: 729.54	Total: 1,059.54
:			
<b>Workorder:</b> 1708876	<b>Meter:</b> 53681	<b>In Date:</b> 09/15/2017	<b>Closed:</b> 09/15/2017
<b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1709843	<b>Meter:</b> 53873	<b>In Date:</b> 10/06/2017	<b>Closed:</b> 10/27/2017
<b>Problem:</b> water leaking in back seat floor on both sides			
- R&r rear carpet and seats to dry out ck for water leak-reseal tail lamp housing and rear hatch	<b>Parts List</b>		<b>Qty</b>
	Brake Control Module		1.00
- Scan for codes had "u3000" abs control module not communicating-perform diag test and replace Abs control module and reprogram	Program Abs		1.00
	Shop Supplies		1.00
- Shop Supplies			
Hours 7.00	Labor: 420.00	Parts: 1,018.73	Total: 1,438.73
:			
<b>Workorder:</b> 1712426	<b>Meter:</b> 55737	<b>In Date:</b> 12/18/2017	<b>Closed:</b> 12/28/2017
<b>Problem:</b> PM Service			
- Pm Service.	<b>Parts List</b>		<b>Qty</b>
- Rotate and balance four tires.	Napagold Oil Filter		1.00
- Vacume debris from crawl and engine bay.	Napa Syn 5w30 Qt		5.00
- Shop Supplies	Washer Fluid Concentr		1.00
	Wiper Blades 24"		1.00
	Wiper		1.00
	Shop Supplies		1.00
Hours 3.50	Labor: 210.00	Parts: 41.30	Total: 251.30
:			
<b>Workorder:</b> 1802892	<b>Meter:</b> 58421	<b>In Date:</b> 03/16/2018	<b>Closed:</b> 03/29/2018
<b>Problem:</b> Left rear tire flat.side wall damage			
- Replace and balance left rear tire.nitrogen fill all.reset Tpm.	<b>Parts List</b>		<b>Qty</b>
	738168571 225-60r17		1.00
- Shop Supplies	Shop Supplies		1.00
	Tire Disposal Fee		1.00
Hours 1.00	Labor: 60.00	Parts: 173.68	Total: 233.68
:			
<b>Workorder:</b> 1804575	<b>Meter:</b> 60177	<b>In Date:</b> 05/02/2018	<b>Closed:</b> 05/14/2018
<b>Problem:</b> Right rear tire flat.Front of lab building.			
- Repair right rear tire.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1805166	<b>Meter:</b> 60441	<b>In Date:</b> 05/18/2018	<b>Closed:</b> 05/24/2018
<b>Problem:</b> carpet gets wet when raining			
- test for water leaks, remove rear bumper, replace louver and retest	<b>Parts List</b>		<b>Qty</b>
	Valve		1.00
- pm service	Napagold Oil Filter		1.00
- Shop Supplies	Napa Quart 5w30		5.00
	Wiper Blades 24"		1.00
	Wiper		1.00
	Shop Supplies		1.00
Hours 5.00	Labor: 300.00	Parts: 105.05	Total: 405.05
:			



**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1805375      **Meter:** 60483      **In Date:** 05/29/2018      **Closed:** 05/29/2018  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1807898      **Meter:** 62263      **In Date:** 08/01/2018      **Closed:** 08/20/2018  
**Problem:** FAILS TO START

- Charge and test battery(failed)replace battery,and repair eire harness loom to keep from shorting out. wiring.	<b>Parts List</b>	<b>Qty</b>
	Battery	1.00
- Drive to Nw corner of military and atlantic ave to jump start vehicle in Md now parking lot.	Shop Supplies	1.00

- Shop Supplies

Hours 3.50      Labor: 210.00      Parts: 125.33      Total: 335.33  
:

---

**Workorder:** 1808466      **Meter:** 62201      **In Date:** 08/16/2018      **Closed:** 08/16/2018  
**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00  
: