

**Palm Beach County Fleet Management  
Asset Maintenance History**

**K11241      2003 GMC 1500 Pickup, 1/2 Ton, W/8 Ft. Body**

---

**Workorder:** 336012      **Meter:** 0      **In Date:** 03/10/2003      **Closed:** 03/10/2003  
**Problem:** WASH VEHICLE

- Wash Vehicle
- Pre-delivery Inspection
- Make Duplicate Keys For New Vehicle

Hours 3.10      Labor: 155.00      Parts: 0.00      Total: 155.00  
 :

---

**Workorder:** 337917      **Meter:** 600      **In Date:** 04/04/2003      **Closed:** 04/04/2003  
**Problem:** VEHICLE TAG CHARGE

- Tag Charge

**Parts List**      **Qty**  
 Vehicle Tag Charge      1.00

Hours 0.00      Labor: 0.00      Parts: 51.85      Total: 51.85  
 :

---

**Workorder:** 338842      **Meter:** 0      **In Date:** 04/18/2003      **Closed:** 04/30/2003  
**Problem:** FAB LIGHT POLE

- Fab Light Pole
- Welding Supplies

**Parts List**      **Qty**  
 Shop Supplies      1.00  
 1/4x3x20 Alum Flat Bar 6063      1.00  
 2x2x1/4x20 Alum Angle Architectual      1.00  
 1" X 20 Alum Pipe Sch 80      3.00  
 1-1/2x20 Alum Pipe Sch 80      3.00  
 18410 Pintle Pin      1.00

Hours 2.50      Labor: 125.00      Parts: 21.21      Total: 146.21  
 :

---

**Workorder:** 338893      **Meter:** 834      **In Date:** 04/21/2003      **Closed:** 04/23/2003  
**Problem:** INSTALL STROBE LIGHT.

- Fabricate & Install Strobe Light Assy.
- Shop Supplies

**Parts List**      **Qty**  
 Shop Supplies      1.00  
 Ds-167 Toggle Switch (standard)      1.00  
 S-12-30 30 Amp Breaker      1.00

Hours 3.00      Labor: 150.00      Parts: 13.11      Total: 163.11  
 :

---

**Workorder:** 349889      **Meter:** 3174      **In Date:** 10/15/2003      **Closed:** 10/16/2003  
**Problem:** P.M.SERVICE

- Pm Service
- Shop Supplies

**Parts List**      **Qty**  
 Shop Supplies      1.00  
 L/#ph51a Oil Filter Wix 51036 Fram Ph3980      1.00  
 10w30 Motor Oil      5.00

Hours 2.00      Labor: 100.00      Parts: 9.44      Total: 109.44  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 449231	<b>Meter:</b> 7210	<b>In Date:</b> 06/28/2004	<b>Closed:</b> 06/29/2004
<b>Problem:</b> P.M.SERVICE			
- Pm Service	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
	Af1519 Air Filter Use Laf1520 Frm Ca8755a	1.00	
	1036 Oil Filter Frm Ph3980 Wix 51036	1.00	
	10w30 Motor Oil	5.00	
Hours 2.00	Labor: 100.00	Parts: 17.16	Total: 117.16
:			
<b>Workorder:</b> 455456	<b>Meter:</b> 8056	<b>In Date:</b> 08/27/2004	<b>Closed:</b> 08/30/2004
<b>Problem:</b> BROKEN TAIL GATE CABLES			
- Transport & Pickup Vehicle At Dealer.(broken Tail Gate Cable)	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 50.00	Parts: 2.00	Total: 52.00
:			
<b>Workorder:</b> 532191	<b>Meter:</b> 9858	<b>In Date:</b> 01/03/2005	<b>Closed:</b> 01/05/2005
<b>Problem:</b> P.M.SERVICE,SEE NOTE			
- Pm Service	<b>Parts List</b>	<b>Qty</b>	
- Check Gauges.unable To Verify Driver Concern At This Time.	Shop Supplies	1.00	
- Jump Start,recharge Battery.check Charging Sys.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00	
- Shop Supplies	3481 Fuel Filter Frm G3727 Wix 33481	1.00	
	10w30 Motor Oil	5.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
Hours 3.00	Labor: 150.00	Parts: 27.88	Total: 177.88
:			
<b>Workorder:</b> 534888	<b>Meter:</b> 10309	<b>In Date:</b> 01/31/2005	<b>Closed:</b> 01/31/2005
<b>Problem:</b> KNOCKING SOUND FROM STEERING WHILE TURNING.			
- Transport & Pickup Vehicle At Dealer.(steering Noise)	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 50.00	Parts: 2.00	Total: 52.00
:			
<b>Workorder:</b> 538504	<b>Meter:</b> 11025	<b>In Date:</b> 03/09/2005	<b>Closed:</b> 03/09/2005
<b>Problem:</b> LEFT FRT FLAT			
- Repair Left Frt & Rt Frt Tire	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 50.00	Parts: 2.00	Total: 52.00
:			
<b>Workorder:</b> 540845	<b>Meter:</b> 11414	<b>In Date:</b> 04/04/2005	<b>Closed:</b> 04/05/2005
<b>Problem:</b> STALLS			
- Ignition System Diagnosis (mis-fire)	<b>Parts List</b>	<b>Qty</b>	
- Transport & Pickup Vehicle At Dealer(defective Dist. Cap Androtor)	Shop Supplies	1.00	
- Shop Supplies			
Hours 1.75	Labor: 87.50	Parts: 2.00	Total: 89.50
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 541042	<b>Meter:</b> 11481	<b>In Date:</b> 04/05/2005	<b>Closed:</b> 04/07/2005
<b>Problem:</b> FLAT TIRE.			
- R&r 4 Tires	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
	773430430 235/75r16 Wrangler St SI		4.00
Hours 2.00	Labor: 100.00	Parts: 293.60	Total: 393.60
:			
<b>Workorder:</b> 548905	<b>Meter:</b> 13171	<b>In Date:</b> 06/28/2005	<b>Closed:</b> 06/29/2005
<b>Problem:</b> P.M.SERVICE/RECALL			
- Pm Service	<b>Parts List</b>		<b>Qty</b>
- Transport & Pickup Vehicle At Dealer.(recall#05500)	Shop Supplies		1.00
- Shop Supplies	Af1519 Air Filter Use Laf1520 Frm Ca8755a		1.00
	Ph3387a Oil Filter Lbf Ph47 Wix 51040		1.00
	10w30 Motor Oil		5.00
	31-22 Wiper Blades 22" Wiper Blade		2.00
Hours 3.00	Labor: 150.00	Parts: 32.16	Total: 182.16
:			
<b>Workorder:</b> 549498	<b>Meter:</b> 13236	<b>In Date:</b> 07/06/2005	<b>Closed:</b> 07/15/2005
<b>Problem:</b> INSTALL ARROW BOARD			
- Install Arrow Board-rewire Strobe Light.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
	82-5602 Trailer Wire 4 Wire 14 Gauge (grote)		28.00
Hours 6.00	Labor: 300.00	Parts: 44.42	Total: 344.42
:			
<b>Workorder:</b> 549562	<b>Meter:</b> 13236	<b>In Date:</b> 07/07/2005	<b>Closed:</b> 07/25/2005
<b>Problem:</b> FAB ARROW BOARD MOUNT			
- Fab Arrow Board Mount.	<b>Parts List</b>		<b>Qty</b>
- Welding Supplies	Shop Supplies		1.00
	1/2"x2"x20' Alum Flat Bar		4.00
	1/4x2x4x20 Alum Angle 6063		6.00
	3"x3"x20' Alum Angle Architectual 1/4" Thick		5.00
	1/4x2x24 Sq. Alum Tube		4.00
	Pal Arrow Board(used W/controller		1.00
Hours 13.50	Labor: 675.00	Parts: 341.45	Total: 1,016.45
:			
<b>Workorder:</b> 551014	<b>Meter:</b> 13431	<b>In Date:</b> 07/22/2005	<b>Closed:</b> 07/25/2005
<b>Problem:</b> GAUGES INOP.			
- Transport And Pickup Vehicle At Dealer.(gauges Inop)	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 50.00	Parts: 2.00	Total: 52.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 553098	<b>Meter:</b> 13662	<b>In Date:</b> 08/15/2005	<b>Closed:</b> 08/16/2005
<b>Problem:</b> REPAIR AIR DAMPNER ON FRONT BUMPER.			
- Service Front Air Deflector With Nuts And Bolts. Repair Bumper Bracket	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.50	Labor: 75.00	Parts: 2.00	Total: 77.00
:			
<b>Workorder:</b> 559565	<b>Meter:</b> 15292	<b>In Date:</b> 12/13/2005	<b>Closed:</b> 12/14/2005
<b>Problem:</b> BROKEN STROBE LIGHT SWITCH/TAIL LIGHT INOP.			
- R&r Strobe Light Toggle Switch.repair R/front Head Light Connection.found No Tail Light Problem At This Time.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
	Ds-167 Toggle Switch (standard)		1.00
Hours 1.00	Labor: 50.00	Parts: 6.65	Total: 56.65
:			
<b>Workorder:</b> 632854	<b>Meter:</b> 15773	<b>In Date:</b> 01/17/2006	<b>Closed:</b> 01/18/2006
<b>Problem:</b> P.M.SERVICE			
- Pm Service	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
	Ph3387a Oil Filter Lbf Ph47 Wix 51040		1.00
	3481 Fuel Filter Frm G3727 Wix 33481		1.00
	10w30 Motor Oil		5.00
Hours 2.00	Labor: 100.00	Parts: 19.85	Total: 119.85
:			
<b>Workorder:</b> 633572	<b>Meter:</b> 15954	<b>In Date:</b> 01/31/2006	<b>Closed:</b> 01/31/2006
<b>Problem:</b> L/F TIRE LEAKING.			
- Repair L/f Tire And Balance.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 50.00	Parts: 2.00	Total: 52.00
:			
<b>Workorder:</b> 635051	<b>Meter:</b> 16437	<b>In Date:</b> 03/01/2006	<b>Closed:</b> 03/06/2006
<b>Problem:</b> SPEEDOMETER INOP.			
- C/s Speedometer Inop.verified Concern.found Speedo Stops Working Intermittently.	<b>Parts List</b>		<b>Qty</b>
- Transport & Pickup Vehicle At Dealer.(speedometer & Steeringshaft)	Shop Supplies		1.00
- Shop Supplies			
Hours 1.50	Labor: 75.00	Parts: 2.00	Total: 77.00
:			
<b>Workorder:</b> 637032	<b>Meter:</b> 17106	<b>In Date:</b> 04/10/2006	<b>Closed:</b> 04/11/2006
<b>Problem:</b> R/HEAD LIGHT INOP/NAIL IN L/FRONT TIRE			
- Repair R/head Light	<b>Parts List</b>		<b>Qty</b>
- Repair Nail In L/front Tire.	Shop Supplies		1.00
- Shop Supplies	9006 Bulb Assy		1.00
Hours 1.50	Labor: 75.00	Parts: 8.32	Total: 83.32
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 637768	<b>Meter:</b> 17321	<b>In Date:</b> 04/20/2006	<b>Closed:</b> 04/24/2006
<b>Problem:</b> STALL,NO START.			
- Check Charging Sys. R&r Battery.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
	78-72 Battery Group 78		1.00
Hours 0.75	Labor: 37.50	Parts: 61.25	Total: 98.75
:			
<b>Workorder:</b> 637781	<b>Meter:</b> 0	<b>In Date:</b> 04/20/2006	<b>Closed:</b> 04/20/2006
<b>Problem:</b> SISTERS TOWING & TRANSPORTATON TOW FROM AIRPORT TE			
- Sisters Towing & Transportaton Tow From Airport Terminal			
- Tow To 3700 Belvedere Blvd			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 642062	<b>Meter:</b> 18375	<b>In Date:</b> 07/10/2006	<b>Closed:</b> 07/10/2006
<b>Problem:</b> R/REAR TIRE FLAT			
- Repair Nail In R/rear Tire.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 50.00	Parts: 2.00	Total: 52.00
:			
<b>Workorder:</b> 643847	<b>Meter:</b> 18673	<b>In Date:</b> 08/10/2006	<b>Closed:</b> 08/14/2006
<b>Problem:</b> P.M.SERVICE			
- Pm Service	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
	6678 Air Filter Frm Ca8755a Wix 46678		1.00
	Ph3387a Oil Filter Lbf Ph47 Wix 51040		1.00
	10w30 Motor Oil		5.00
	31-22 Wiper Blades 22" Wiper Blade		2.00
Hours 2.00	Labor: 100.00	Parts: 38.45	Total: 138.45
:			
<b>Workorder:</b> 649111	<b>Meter:</b> 0	<b>In Date:</b> 11/13/2006	<b>Closed:</b> 11/28/2006
<b>Problem:</b> TUFF-COAT PAINT & BODY			
- Tuff-coat Paint & Body			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 732276	<b>Meter:</b> 20301	<b>In Date:</b> 01/03/2007	<b>Closed:</b> 01/05/2007
<b>Problem:</b> STROBE LIGHT BROKEN OFF			
- Replace Roof Strobe Lamp.re-thread Mounting Pipe.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 55.00	Parts: 2.00	Total: 57.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 734292	<b>Meter:</b> 20960	<b>In Date:</b> 02/14/2007	<b>Closed:</b> 02/20/2007
<b>Problem:</b> P.M SERVICE			
- Pm Service	<b>Parts List</b>	<b>Qty</b>	
- Transmission Flush W/cleaner And Additive.	Shop Supplies	1.00	
- Rf Low Beam Headlight Bulb	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00	
- Replace Arrow Board Lights (2)	3481 Fuel Filter Frm G3727 Wix 33481	1.00	
- Nitrogen Fill Tires.	Syn/atf Trans Fluid Synthetic	10.00	
- Shop Supplies	10w30 Motor Oil	5.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	9006 Bulb Assy	1.00	
	7414y Amber Light Arrow Board	2.00	
	L4300 Trans Flush	1.00	
Hours 5.60	Labor: 308.00	Parts: 126.14	Total: 434.14
:			
<b>Workorder:</b> 734737	<b>Meter:</b> 21036	<b>In Date:</b> 02/26/2007	<b>Closed:</b> 02/27/2007
<b>Problem:</b> FLAT TIRE			
- Repair L/r Tire.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 55.00	Parts: 2.00	Total: 57.00
:			
<b>Workorder:</b> 735436	<b>Meter:</b> 21182	<b>In Date:</b> 03/12/2007	<b>Closed:</b> 03/13/2007
<b>Problem:</b> R/R HAS NAIL.			
- Repair And Balance Right Rear Tire.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 55.00	Parts: 2.00	Total: 57.00
:			
<b>Workorder:</b> 737115	<b>Meter:</b> 21640	<b>In Date:</b> 04/12/2007	<b>Closed:</b> 04/16/2007
<b>Problem:</b> BOLT IN R/F TIRE			
- Rf Tire Replacement (unrepairable - 1/2 Inch Hole)	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
	Tire Disposal Fee	1.00	
	773430430 235/75r16 Wrangler St SI	1.00	
Hours 1.00	Labor: 55.00	Parts: 111.15	Total: 166.15
:			
<b>Workorder:</b> 742201	<b>Meter:</b> 22925	<b>In Date:</b> 07/30/2007	<b>Closed:</b> 08/03/2007
<b>Problem:</b> CHECK FRONT END.STROBE LIGHT SWITCH BROKE.			
- Replace Broken Strobe Light Switch	<b>Parts List</b>	<b>Qty</b>	
- Diagnose Frt End Noise Ck Ball Joints & Tierods.inner	Shop Supplies	1.00	
Tierodworn & Rack Leaking Repl Rack & Pinion Flush Power	61a P/steering Fluid	1.00	
Steering Fluid Sys.renew FI	Ds-167 Toggle Switch (standard)	1.00	
- Front End Alignment.	Rp6532 Rack And Pinion	1.00	
- Shop Supplies			
Hours 5.50	Labor: 302.50	Parts: 365.24	Total: 667.74
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 743866	<b>Meter:</b> 23580	<b>In Date:</b> 09/10/2007	<b>Closed:</b> 09/19/2007
<b>Problem:</b> P.M. SERVICE.			
- Performed Complete Pm Service,also Replaced Wiper Blades,air Filter,fuel Additive.	<b>Parts List</b>	<b>Qty</b>	
	Shop Supplies	1.00	
- Inspected Doors,found Bushings On Drivers Door Worn Out.removed Drivers Side Kick Panel,wiring That Goes To Door,unbolted Door & Removed.	6678 Air Filter Frm Ca8755a Wix 46678	1.00	
	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00	
- Inspected Tires-left Front Tire Had Bad Edge	10020 Injector Cleaner Don't Reorder	1.00	
Wear.replaced Left Fornt With A Good Spare Tire.also	10w30 Motor Oil	5.00	
Swaped Right Front With Veh. Spare Tire.	31-22 Wiper Blades 22" Wiper Blade	2.00	
- Shop Supplies	38437 Hinge Pin Kit	1.00	
Hours 6.00	Labor: 330.00	Parts: 71.87	Total: 401.87
:			
<b>Workorder:</b> 746548	<b>Meter:</b> 24236	<b>In Date:</b> 10/31/2007	<b>Closed:</b> 10/31/2007
<b>Problem:</b> ARROW BOARD NOT WORKING,CHANGE OIL LIGHT ON			
- Repair Wiring To Main Control Box And Replace Fuse. (shorted To Dash Panel)	<b>Parts List</b>	<b>Qty</b>	
	Shop Supplies	1.00	
- Shop Supplies			
Hours 1.50	Labor: 90.00	Parts: 2.00	Total: 92.00
:			
<b>Workorder:</b> 748314	<b>Meter:</b> 24625	<b>In Date:</b> 12/07/2007	<b>Closed:</b> 12/10/2007
<b>Problem:</b> ARROW BOARD BLOWS FUSES			
- Diag Lights Run Power Wire Fr Pos Battery Terminal To Controler.retest.	<b>Parts List</b>	<b>Qty</b>	
	Shop Supplies	1.00	
- Shop Supplies			
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 835914	<b>Meter:</b> 26209	<b>In Date:</b> 03/21/2008	<b>Closed:</b> 03/27/2008
<b>Problem:</b> P.M SERVICE,SEE NOTE			
- Pm Service	<b>Parts List</b>	<b>Qty</b>	
- Replaced Rear Liftgate Handle Bezel.	L17301a Engine Fog Kit Hard Carbon (smart Blend)	1.00	
- Inspect & Test.reverse Lamps,repl Fuse & R.side Bulb.insp. &test Dome Lamp,repl.test Daytime Running Lamps,repl Burnt Up Sockets & Bulbs.	L17040 Inject Cleaner One Part (smart Blend)	1.00	
	Shop Supplies	1.00	
- Pressure Test & Inspect Cooling System.flush And Refill System.	6678 Air Filter Frm Ca8755a Wix 46678	1.00	
	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00	
- Induction System Cleaning.flush Injectors.	3481 Fuel Filter Frm G3727 Wix 33481	1.00	
- Rotate & High Speed Balance All 4 Tires.nitro Fill All Tires	10w30 Motor Oil	6.00	
- Shop Supplies	31-22 Wiper Blades 22" Wiper Blade	2.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	Tailgate Handle Bezel	1.00	
	3157 Tail Light Bulbs	1.00	
	4114k Bulb (acd)	2.00	
	Ls94 Bulb Socket Drive Light (acd)	2.00	
	Antifreeze Ext/life All Makes (peak 407)	2.00	
Hours 10.30	Labor: 618.00	Parts: 241.36	Total: 859.36
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 838469	<b>Meter:</b> 26990	<b>In Date:</b> 05/14/2008	<b>Closed:</b> 05/19/2008
<b>Problem:</b> CHECK ENGINE LIGHT ON			
- Scan For Codes-p0430 Perform Pin Point Test.send To Dealer For Warranty Catalyst Converter.	<b>Parts List</b>		<b>Qty</b>
- To/from Dealer For Warranty Cat-converter.	Shop Supplies		1.00
- Shop Supplies			
Hours 2.40	Labor: 144.00	Parts: 2.00	Total: 146.00
:			
<b>Workorder:</b> 845051	<b>Meter:</b> 29066	<b>In Date:</b> 10/02/2008	<b>Closed:</b> 10/14/2008
<b>Problem:</b> P.M SERVICE,SEE NOTE			
- Pm Service	<b>Parts List</b>		<b>Qty</b>
- Mount 3 New Tires.balance All Four Nitro Fill	Shop Supplies		1.00
- Diag. Ac Sys.replace Blower Resister And Blower Motor.repairwiring Harness.	Ph3387a Oil Filter Lbf Ph47 Wix 51040		1.00
- Test Charging Sys. Replace Battery.	3481 Fuel Filter Frm G3727 Wix 33481		1.00
- Replace Driver's Door Hinge Pins.adjust And Lubricate Door.	10w30 Motor Oil		5.00
- Complete Front End Alignment.test Drive.	31-22 Wiper Blades 22" Wiper Blade		2.00
- Shop Supplies	Driver Door Hinge Pin Kit		2.00
	Group 78 Battery (acd 78ps)		1.00
	22807123 Resistor Blower Motor (acd)		1.00
	15-81683 Blower Motor (acd)		1.00
	Tire Disposal Fee		3.00
	773430430 235/75r16 Wrangler St SI		3.00
Hours 13.00	Labor: 780.00	Parts: 745.21	Total: 1,525.21
:			
<b>Workorder:</b> 935110	<b>Meter:</b> 31529	<b>In Date:</b> 03/13/2009	<b>Closed:</b> 03/16/2009
<b>Problem:</b> CHECK LIGHTS			
- Ck All Lights & Replace L/f Head Light Bulb.	<b>Parts List</b>		<b>Qty</b>
	9006 Bulb Assy		1.00
Hours 0.50	Labor: 30.00	Parts: 6.32	Total: 36.32
:			
<b>Workorder:</b> 937156	<b>Meter:</b> 32276	<b>In Date:</b> 04/28/2009	<b>Closed:</b> 04/30/2009
<b>Problem:</b> P.M SERVICE			
- Pm Service	<b>Parts List</b>		<b>Qty</b>
- Service Rear Differential.	82194 Gray Silicone (permatex)		1.00
- Rotate & High Speed Balance And Nitro Fill All 4 Tires.	Shop Supplies		1.00
- R&r Burned Out Tag Lamp Bulb.	Ph3387a Oil Filter Lbf Ph47 Wix 51040		1.00
- Diagnose Washer System.remove Battery To Access & Repair Washer Hose.	12345841 Gear Oil Synthetic 75w-90		3.00
- Shop Supplies	10w30 Motor Oil		5.00
	Used Firex Refurbed Fire Extingshers		1.00
Hours 5.10	Labor: 306.00	Parts: 100.09	Total: 406.09
:			



**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 938776	<b>Meter:</b> 32771	<b>In Date:</b> 06/09/2009	<b>Closed:</b> 06/15/2009
<b>Problem:</b> A/C WORKS INTERMITTENTLY.CHECK DRIVER SIDE WINDOW.			
- Inspect L/f Window,r&r Panel To Access And Replace Defectivewindow Regulator Assy.	<b>Parts List</b>	<b>Qty</b>	
	05074 Silicone Spray	1.00	
- Performed Ac Performance Test.recover, Leak Test,vacuum Sys.r&r Defective Orifice Tube.recharge And Retest.	Shop Supplies	1.00	
	1066 White Lithium (crc 05037)	1.00	
- Shop Supplies	Driver Door Window Regulator	1.00	
	R134a Refrigerant	2.00	
	E8 A/c Oil R134a A/c Oil (tsi)	1.00	
	Orifice Tube	1.00	
Hours 4.00	Labor: 240.00	Parts: 118.70	Total: 358.70
:			
<b>Workorder:</b> 944810	<b>Meter:</b> 34199	<b>In Date:</b> 10/20/2009	<b>Closed:</b> 11/04/2009
<b>Problem:</b> P.M service, check engine light on.			
- P.m service.	<b>Parts List</b>	<b>Qty</b>	
- Test starting & charging system, test & replace battery.	Shop Supplies	1.00	
- Replace tail gate hinges & straps, secure bedliner.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00	
- Diagnose A/c blower system, replace blower motor, resistor & wire in new pigtail conector.	3481 Fuel Filter Frm G3727 Wix 33481	1.00	
- Swap spare tire with L/r tire, rotate & balance all four tires.	6678 Air Filter Frm Ca8755a Wix 46678	1.00	
- Repair "a" pillar trim panel on right side.	10w30 Motor Oil	5.00	
- Perform computer diagnostics, run Evap bay test, clean out mulch between cab & bed, replace & relocate Evap vent solinoid, clear codes.	31-22 Wiper Blades 22" Wiper Blade	2.00	
- Replace tag light bulb.	Group 78 Battery (acd 78ps)	1.00	
- Shop Supplies	15-81683 Blower Motor (acd)	1.00	
	22807123 Resistor Blower Motor (acd)	1.00	
	Pt2195 Pigtail Blower Motor (acd)	1.00	
	Evap Vent Solenoid 214-2081	1.00	
	Tailgate Cable	1.00	
	Tailgate Cable	1.00	
	Hinge	1.00	
	Hinge	1.00	
	Hinge	1.00	
	Hinge	1.00	
Hours 12.30	Labor: 738.00	Parts: 638.78	Total: 1,376.78
:			
<b>Workorder:</b> 1000752	<b>Meter:</b> 35475	<b>In Date:</b> 01/20/2010	<b>Closed:</b> 01/22/2010
<b>Problem:</b> Screw in R/R tire, arrow board inop			
- Test power to arrow board, replace melted fuse holder & circuit breaker.	<b>Parts List</b>	<b>Qty</b>	
- Repair R/r tire.	Shop Supplies	1.00	
- Shop Supplies	30055-20 Ckt Breaker 20 Amp	1.00	
	80865 Fuseholder Imperial 80865	1.00	
Hours 2.00	Labor: 120.00	Parts: 13.31	Total: 133.31
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1004503	<b>Meter:</b> 37547	<b>In Date:</b> 05/03/2010	<b>Closed:</b> 05/06/2010
<b>Problem:</b> P.M service, check A/C.			
- P.m service.	<b>Parts List</b>	<b>Qty</b>	
- Mount two new tires, rotate & balance all four tires.	Shop Supplies	1.00	
- Inspect inop A/c system, trace concern to burnt fuse block, replace fuse block on driver side.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00	
- Diagnose & repair windshield washer system.	10w30 Motor Oil	5.00	
- Alignment.	31-22 Wiper Blades 22" Wiper Blade	2.00	
- Replace worn intermediate steering shaft.	Fuse Box	1.00	
- Shop Supplies	19153614 Steer Shaft Intermediate (gmc)	1.00	
	183680418 P235/75r16 Wrangler Sr-a 109s	2.00	
	Tire Disposal Fee	2.00	
Hours 12.00	Labor: 720.00	Parts: 601.29	Total: 1,321.29
:			
<b>Workorder:</b> 1005019	<b>Meter:</b> 37679	<b>In Date:</b> 05/13/2010	<b>Closed:</b> 05/13/2010
<b>Problem:</b> Nail in L/F tire			
- Repair L/f tire.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1007197	<b>Meter:</b> 38505	<b>In Date:</b> 07/08/2010	<b>Closed:</b> 07/12/2010
<b>Problem:</b> Left front tire flat.			
- Repair and balance left front tire.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1010590	<b>Meter:</b> 39676	<b>In Date:</b> 09/27/2010	<b>Closed:</b> 09/29/2010
<b>Problem:</b> Check engine light on,also see notes on arrow board inop.			
- Computer diagnose for check engine light on.test and replace failed gas cap with new.clear codes and road test.	<b>Parts List</b>	<b>Qty</b>	
- Clean and re- glued falling rear view mirror and secure same.	Shop Supplies	1.00	
- Test and repair open wiring for power circuit to arrow board.	81844/loctite Mirror Glue	1.00	
- Shop Supplies	Fuel Cap	1.00	
Hours 3.50	Labor: 210.00	Parts: 21.40	Total: 231.40
:			
<b>Workorder:</b> 1011090	<b>Meter:</b> 39711	<b>In Date:</b> 10/07/2010	<b>Closed:</b> 10/07/2010
<b>Problem:</b> no start			
- From: airport bldg B To: lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1011125	<b>Meter:</b> 39790	<b>In Date:</b> 10/08/2010	<b>Closed:</b> 10/12/2010
<b>Problem:</b> Towed in no start.			
- Diagnose no start.recharge and test battery.test and replace Failed starter motor assembly with new.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
	Starter	1.00	
Hours 2.00	Labor: 120.00	Parts: 319.84	Total: 439.84
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1012024      **Meter:** 39985      **In Date:** 10/27/2010      **Closed:** 11/15/2010  
**Problem:** Pm service,also see notes on trim falling off.

<ul style="list-style-type: none"> <li>- Perform pm service.</li> <li>- Fabricate and replace failed driver door hinge bushings with new then adjust and align same.</li> <li>- Rotate and balance all four tires.</li> <li>- Shop Supplies</li> </ul>	<table border="0" style="width: 100%;"> <tr> <th style="text-align: left;"><b>Parts List</b></th> <th style="text-align: right;"><b>Qty</b></th> </tr> <tr> <td>Shop Supplies</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>Ph3387a Oil Filter Lbf Ph47 Wix 51040</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>3481 Fuel Filter Frm G3727 Wix 33481</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>10w30 Motor Oil</td> <td style="text-align: right;">5.00</td> </tr> <tr> <td>Rh A-pillar Molding</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>Hinge Bushing Kit</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>Used Firex Refurbed Fire Extingshers</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>89025539 Door Hinge Bushing Kit (gmc)</td> <td style="text-align: right;">1.00</td> </tr> </table>	<b>Parts List</b>	<b>Qty</b>	Shop Supplies	1.00	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00	3481 Fuel Filter Frm G3727 Wix 33481	1.00	10w30 Motor Oil	5.00	Rh A-pillar Molding	1.00	Hinge Bushing Kit	1.00	Used Firex Refurbed Fire Extingshers	1.00	89025539 Door Hinge Bushing Kit (gmc)	1.00
<b>Parts List</b>	<b>Qty</b>																		
Shop Supplies	1.00																		
Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00																		
3481 Fuel Filter Frm G3727 Wix 33481	1.00																		
10w30 Motor Oil	5.00																		
Rh A-pillar Molding	1.00																		
Hinge Bushing Kit	1.00																		
Used Firex Refurbed Fire Extingshers	1.00																		
89025539 Door Hinge Bushing Kit (gmc)	1.00																		
Hours 5.50 :	Labor: 330.00      Parts: 208.29      Total: 538.29																		

**Workorder:** 1100308      **Meter:** 41439      **In Date:** 01/07/2011      **Closed:** 01/13/2011  
**Problem:** Rear view mirror fell off.

<ul style="list-style-type: none"> <li>- Clean and install falling rear view mirror with new glue to windshield</li> </ul>	<table border="0" style="width: 100%;"> <tr> <th style="text-align: left;"><b>Parts List</b></th> <th style="text-align: right;"><b>Qty</b></th> </tr> <tr> <td>81844/loctite Mirror Glue</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>81844/loctite Mirror Glue</td> <td style="text-align: right;">1.00</td> </tr> </table>	<b>Parts List</b>	<b>Qty</b>	81844/loctite Mirror Glue	1.00	81844/loctite Mirror Glue	1.00
<b>Parts List</b>	<b>Qty</b>						
81844/loctite Mirror Glue	1.00						
81844/loctite Mirror Glue	1.00						
Hours 0.50 :	Labor: 30.00      Parts: 9.03      Total: 39.03						

**Workorder:** 1100547      **Meter:** 41271      **In Date:** 01/13/2011      **Closed:** 01/13/2011  
**Problem:** No Brakes

- From: 3700 Belverdere rd west side of Bldg E      To: Lv shop

Hours 0.00 :	Labor: 0.00      Parts: 0.00      Total: 0.00
-----------------	---

**Workorder:** 1100560      **Meter:** 41479      **In Date:** 01/13/2011      **Closed:** 01/28/2011  
**Problem:** Brake hydralic line leaking above fuel tank.

<ul style="list-style-type: none"> <li>- Check brake fluid leak.r&amp;r fuel tank and remove rust brake line.fabricate and install new line. Bleed system and test drive vehicle.</li> <li>- Replace both broken tag lamps.</li> <li>- Shop Supplies</li> </ul>	<table border="0" style="width: 100%;"> <tr> <th style="text-align: left;"><b>Parts List</b></th> <th style="text-align: right;"><b>Qty</b></th> </tr> <tr> <td>Shop Supplies</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>Brake Line Abs/rear Hoses</td> <td style="text-align: right;">1.00</td> </tr> <tr> <td>09997 Brake Clean</td> <td style="text-align: right;">2.00</td> </tr> <tr> <td>1401 Brake Fluid Brake Fluid</td> <td style="text-align: right;">2.00</td> </tr> <tr> <td>15082619 Tag Light (gmc)</td> <td style="text-align: right;">2.00</td> </tr> </table>	<b>Parts List</b>	<b>Qty</b>	Shop Supplies	1.00	Brake Line Abs/rear Hoses	1.00	09997 Brake Clean	2.00	1401 Brake Fluid Brake Fluid	2.00	15082619 Tag Light (gmc)	2.00
<b>Parts List</b>	<b>Qty</b>												
Shop Supplies	1.00												
Brake Line Abs/rear Hoses	1.00												
09997 Brake Clean	2.00												
1401 Brake Fluid Brake Fluid	2.00												
15082619 Tag Light (gmc)	2.00												
Hours 6.00 :	Labor: 360.00      Parts: 112.84      Total: 472.84												

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1105374      **Meter:** 43486      **In Date:** 05/20/2011      **Closed:** 06/08/2011

**Problem:** Pm service also check and repair tail gate falling off.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Fabricate and replace rusted out tailgate hinge.	Shop Supplies	1.00
- Replace two tires,rotate and balance all.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Complete wheel alignment.	6678 Air Filter Frm Ca8755a Wix 46678	1.00
- Shop Supplies	10w30 Motor Oil	5.00
	Rh Tailgate Hinge (tailgate Part)	1.00
	Hinge	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	183680418 P235/75r16 Wrangler Sr-a 109s	2.00
	Tire Disposal Fee	2.00
Hours 7.50	Labor: 450.00	Parts: 356.06
:		Total: 806.06

**Workorder:** 1109050      **Meter:** 44502      **In Date:** 08/26/2011      **Closed:** 09/07/2011

**Problem:** Service brake booster light on and battery light on .

- Computer diagnose for brake booster warning light on.test and replace failed power brake vacume booster with new and bleed hydraulic system.clear codes with scan tool and road test.	<b>Parts List</b>	<b>Qty</b>
- Fully recharge battery and test starting and charging system.test and replace failed alternator with new.	Shop Supplies	1.00
- Inspect and replace failed noisy serpentine belt with new.	K060950 Serp Belt	1.00
- Shop Supplies	Brake Booster	1.00
	Alternator	1.00
Hours 5.25	Labor: 315.00	Parts: 676.78
:		Total: 991.78

**Workorder:** 1111107      **Meter:** 44904      **In Date:** 10/19/2011      **Closed:** 11/09/2011

**Problem:** Repair left front seat and left front window hard to roll up and makes noise.

- Replace left window regulator.	<b>Parts List</b>	<b>Qty</b>
- Remove seat and transport and pick up from upholstery shop.	Shop Supplies	1.00
- Shop Supplies	Left Hand Window Regulator	1.00
Hours 3.00	Labor: 180.00	Parts: 88.37
:		Total: 268.37

**Workorder:** 1112577      **Meter:** 45197      **In Date:** 11/29/2011      **Closed:** 12/07/2011

**Problem:** Pm service

- P.m. Service	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all tires.	Shop Supplies	1.00
- Shop Supplies	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
	22514722 O-ring Seal Fuel Filter (acd 217-452)	2.00
	3481 Fuel Filter Frm G3727 Wix 33481	1.00
	10w30 Motor Oil	5.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 3.00	Labor: 180.00	Parts: 48.18
:		Total: 228.18

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1210803	<b>Meter:</b> 49149	<b>In Date:</b> 11/05/2012	<b>Closed:</b> 11/30/2012
<b>Problem:</b> P.M. Service.Tailgate handle broke.			
- Perform pm service.	<b>Parts List</b>	<b>Qty</b>	
- Install new rear brake rotors,new calipers and new brake pads.flush brake fluid and automated bleed hydraulic system.	10w30 Motor Oil	5.00	
- Inspect and replace failed tailgate handle bezel with new.	Ph3387a Oil Filter Lb	1.00	
- Install two new tires to the front wheels.nitrogen fill and balance all four.	31-22 Wiper Blades 22	2.00	
- Perform wheel alignment complete.	1401 Brake Fluid Bra	1.00	
- Shop Supplies	183680418 P235-75r16	2.00	
	Tail Gate Handle Bezel	1.00	
	Rod Clip (green)	1.00	
	Rod Clip (red)	1.00	
	Brake Rotor Only	2.00	
	Reman Brake Caliper	1.00	
	Reman Brake Caliper	1.00	
	Disc Brake Pads	1.00	
	Shop Supplies	1.00	
Hours 11.50	Labor: 690.00	Parts: 649.73	Total: 1,339.73
:			
<b>Workorder:</b> 1302165	<b>Meter:</b> 50339	<b>In Date:</b> 03/04/2013	<b>Closed:</b> 03/07/2013
<b>Problem:</b> Left front window inop.			
- Remove left door panel and replace window regulator.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Regulator	1.00	
	Shop Supplies	1.00	
Hours 1.50	Labor: 90.00	Parts: 125.24	Total: 215.24
:			
<b>Workorder:</b> 1303390	<b>Meter:</b> 50746	<b>In Date:</b> 04/08/2013	<b>Closed:</b> 04/09/2013
<b>Problem:</b> Right front tire going flat.			
- Repair flat right front tire.nitrogen fill and balance same.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1303831      **Meter:** 50974      **In Date:** 04/18/2013      **Closed:** 05/06/2013  
**Problem:** Pm service and ABS light on.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Presure test and inspect cooling system.remove upper and lower intake manifolds and replace failed intake manifold gaskets with new.install new thermostat.reverse flush and renew engine coolant.	Thermostat	1.00
	10w30 Motor Oil	5.00
	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	31-22 Wiper Blades 22	2.00
- Computer diagnose Abs warning light on.test and replace failed Abs module,brake pressure modulator and combination valve with new.flush brake fluid and automated bleed hydraulic system.	Napagold Fuel Filter	1.00
	Washer FI	1.00
	Peak Global	1.00
- Shop Supplies	Manifold Set	1.00
	Brake Module	1.00
	Brake Valve	1.00
	1401 Brake Fluid Bra	1.00
	Brake Cleaner	1.00
	Valve	1.00
	Shop Supplies	1.00
Hours 15.50	Labor: 930.00	Parts: 1,030.24
:		Total: 1,960.24

**Workorder:** 1309433      **Meter:** 52569      **In Date:** 09/17/2013      **Closed:** 09/30/2013  
**Problem:** Pm service and has to jump start.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Test battery and charging system.replace bad battery.	10w30 Motor Oil	5.00
- R&r left and right doors and replace upper and lower hinge pins and bushings.	Napagold Oil Filter	1.00
	Wiper Blade	2.00
- Replace arrow board bulb.	Engine Seal 12oz	1.00
- Rotate and balance all tires.	Group 78 Battery	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Pin Kit	4.00
	Shop Supplies	1.00
Hours 9.50	Labor: 570.00	Parts: 457.01
:		Total: 1,027.01

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1404665      **Meter:** 55742      **In Date:** 05/13/2014      **Closed:** 05/21/2014  
**Problem:** P.M. service.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Install two new tires to the front wheels.nitrogen fill and balance all four.	10w30 Motor Oil	5.00
	Napagold Oil Filter	1.00
- Install new front brake pads and resurface rotors.install two new calipers and flush brake fluid.automated bleed hydraulic system with scan tool and road test.	Wiper Blade	2.00
	Napagold Fuel Filter	1.00
- Inspect and replace both failed rear axle bump stops with new.	Used Fire X Refurbished	1.00
	183680418 P235-75r16	2.00
- Shop Supplies	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	2232 Brake Fluid Quar	1.00
	Brake Cleaner	1.00
	Engine Seal 12oz	1.00
	Bump Stoppers	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.75	Labor: 525.00	Parts: 664.67
:	Total: 1,189.67	

**Workorder:** 1405349      **Meter:** 55802      **In Date:** 06/02/2014      **Closed:** 06/06/2014  
**Problem:** Check engine light on .

- Diagnose check engine light.p0455.perform evap. system bay test.replace defective fuel cap.clear code and test drive.	<b>Parts List</b>	<b>Qty</b>
	cap	1.00
- Shop Supplies	Stg Wheel Cov - Chevy	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 37.69
:	Total: 97.69	

**Workorder:** 1409512      **Meter:** 57009      **In Date:** 09/23/2014      **Closed:** 09/26/2014  
**Problem:** Screw in right rear tire.

- Repair and balance right rear tire.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:	Total: 62.00	

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1502567      **Meter:** 59779      **In Date:** 03/11/2015      **Closed:** 03/20/2015  
**Problem:** Towed in for brake concern.Pm service.Toggle switch broken for becon lamp.

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Check battery and charging system.battery failed loadtest after recharge.replace defective battery.	10w30 Motor Oil	5.00
- Diagnose for brake concern.drain and remove fuel tank to acess and replace defectiive brake line from pressure modulation valve to rear axle due to corrosion.flush brake fluid and bleed hydraulic system.	Napagold Oil Filter	1.00
	Engine Seal 12oz	1.00
	Brake Cleaner	1.00
	Group 78 Battery	1.00
- Replace defective strobe lights toggle switch and left front turnsignal lamp bulb.	1401 Brake Fluid Bra	4.00
	Wiper Blade	2.00
- Repair one flat tire.rotate and balance all four.	Washer Fluid Concentr	1.00
- Shop Supplies	Bulb	1.00
	Battery Cable Bolt	1.00
	Brake Line	1.00
	Rubberized Undercoat	1.00
	Toggle Switch	1.00
	Shop Supplies	1.00
Hours 12.00	Labor: 720.00	Parts: 224.66
:		Total: 944.66

---

**Workorder:** 1502610      **Meter:** 59767      **In Date:** 03/11/2015      **Closed:** 03/12/2015  
**Problem:** Brake issue

- Tow From: Airport Maint next to Bldg E To: Lv

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

**Workorder:** 1503661      **Meter:** 60000      **In Date:** 04/09/2015      **Closed:** 04/14/2015  
**Problem:** Rear view mirror fell off.

- Inspect,clean and reglue rear view mirror.	<b>Parts List</b>	<b>Qty</b>
	Ptex Rview Mir Adh Cd	1.00
Hours 0.50	Labor: 30.00	Parts: 3.86
:		Total: 33.86



**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1510331	<b>Meter:</b> 63647	<b>In Date:</b> 10/13/2015	<b>Closed:</b> 11/03/2015
<b>Problem:</b> Pm service.Passenger seat adjuster broken.Poor air flow through AC vents.			
- Pm service.	<b>Parts List</b>	<b>Qty</b>	
- Replace broken passenger seat adjuster.	Seat Handel	1.00	
- Replace and balance all four tires.	Evaporato A/c	1.00	
- Ac performance and leak test.replace defective ac	Accumulat	1.00	
evaporator,heater core,accumulator,orifice tube and fresh air	A/c Control	1.00	
door actuator.replace broken climate control head.vacume	Air Door Actuator	1.00	
and recharge system to specs.	Dyestercool Oil	1.00	
- Complete front end alignment.test drive.	Oring Kit A /c	1.00	
- Shop Supplies	Heat Core A/c	1.00	
	10w30 Motor Oil	5.00	
	Napagold Oil Filter	1.00	
	Engine Seal 12oz	1.00	
	Used Fire X Refurbished	1.00	
	Napagold Fuel Filter	1.00	
	Wiper Blade	2.00	
	183680418 P235-75r16	4.00	
	R134a Lv Shop 1	2.00	
	Orifice Tube	1.00	
	Accumulator	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 17.00	Labor: 1,020.0	Parts: 1,734.39	Total: 2,754.39
:	0		
<b>Workorder:</b> 1511882	<b>Meter:</b> 63916	<b>In Date:</b> 11/20/2015	<b>Closed:</b> 12/09/2015
<b>Problem:</b> Check brake pulsates and power steering fluid			
- Check over power steering system.replace defective power	<b>Parts List</b>	<b>Qty</b>	
steering pump.flush and refill power steering fluid.	Psf Qt	1.00	
- Ckeck brake pulsation.resurface both rear brake	Reman Ps Pump	1.00	
rotors.service calipers and lube slide pins.	Shop Supplies	1.00	
- Shop Supplies			
Hours 5.00	Labor: 300.00	Parts: 72.68	Total: 372.68
:			
<b>Workorder:</b> 1600054	<b>Meter:</b> 64066	<b>In Date:</b> 01/04/2016	<b>Closed:</b> 01/19/2016
<b>Problem:</b> Power steering leak.			
- Check and replace defective power steering pressure	<b>Parts List</b>	<b>Qty</b>	
hose,bleed system and test drive.	Pressure Hose	1.00	
- Shop Supplies	Psf Qt	2.00	
	Shop Supplies	1.00	
Hours 1.50	Labor: 90.00	Parts: 59.50	Total: 149.50
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1604783	<b>Meter:</b> 65685	<b>In Date:</b> 05/06/2016	<b>Closed:</b> 05/17/2016
<b>Problem:</b> P.M. service.			
- P.m. Service.	<b>Parts List</b>		<b>Qty</b>
- Shift indicatorbin instrument cluster inop.replace and reprogram defective cluster.	10w30 Motor Oil		5.00
- Diagnose and replace bad shift lock actuator.	Napagold Oil Filter		1.00
- Rotate and balance all tires.	Washer Fluid Concentr		1.00
- Service and adjust rear brakes.	Used Fire X Refurbished		1.00
- Shop Supplies	22" Wiper Blade		2.00
	Napagold Air Filter		1.00
	Instrument Cluster		1.00
	Actuator		1.00
	Shop Supplies		1.00
Hours 7.50	Labor: 450.00	Parts: 568.69	Total: 1,018.69
:			
<b>Workorder:</b> 1609859	<b>Meter:</b> 67352	<b>In Date:</b> 09/21/2016	<b>Closed:</b>
<b>Problem:</b> Check tailgate operation.			
-			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1610909	<b>Meter:</b> 67352	<b>In Date:</b> 09/23/2016	<b>Closed:</b> 10/24/2016
<b>Problem:</b> tail gate hinge damaged			
- tail gate hinge damaged			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1611527	<b>Meter:</b> 67816	<b>In Date:</b> 11/08/2016	<b>Closed:</b> 11/29/2016
<b>Problem:</b> P.M. Service.			
- P.m. Service.	<b>Parts List</b>		<b>Qty</b>
- Rotate and balance tires.	Napagold Oil Filter		1.00
- Inspect and service rear differential.	Napa Quart 5w30		5.00
- Service transmission.flush and refillsystem.	Washer Fluid Concentr		1.00
- Pressure test and inspect cooling system.flush and refill system.	22" Wiper Blade		2.00
- R&r driver and passenger doors and replace worn out hinge pins and bushings.	Engine Seal 12oz		1.00
- Shop Supplies	Non-chlor Brake Clnr		1.00
	Ptex Ultra Grey 3oz		1.00
	1qt Syngear Oil 75-90		3.00
	Filter Kit		1.00
	Syn-atf Trans Fluid S		16.00
	Dex Coolant Engine		2.00
	Pin Kit		2.00
	Pin Kit Door		2.00
	Shop Supplies		1.00
Hours 12.50	Labor: 750.00	Parts: 877.70	Total: 1,627.70
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1612692	<b>Meter:</b> 68070	<b>In Date:</b> 12/12/2016	<b>Closed:</b> 12/30/2016
<b>Problem:</b> Power steering leak.			
- Replace leaking rack and pinion assemble,power steering pressure and return hoses.replace leaking pump.bleed system.	<b>Parts List</b>	<b>Qty</b>	
	Reman Rack And Pinion	1.00	
	cooler	1.00	
- Complete wheel alignment.test drive.	Pawer Stirring Hose	1.00	
- Shop Supplies	Pawer Hose Connector	1.00	
	Non-chlor Brake Clnr	1.00	
	Psf Qt	2.00	
	Pawer Steering Pump A/c Delco	1.00	
	Shop Supplies	1.00	
Hours 8.70	Labor: 522.00	Parts: 619.22	Total: 1,141.22
:			
<b>Workorder:</b> 1701317	<b>Meter:</b> 68502	<b>In Date:</b> 02/08/2017	<b>Closed:</b> 02/28/2017
<b>Problem:</b> P.M. service.			
- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Test battery and charging system.replace bad battery.	10w30 Motor Oil	5.00	
- Major tune up.replace plugs,cap, rotor and wires	Napagold Oil Filter	1.00	
- Service and clean throttle body and induction system.flush injectors.	22" Wiper Blade	2.00	
	Washer Fluid Concentr	1.00	
- Shop Supplies	Battery	1.00	
	Spark Plug Asm	6.00	
	Distributor Cap	1.00	
	Rotor	1.00	
	Set Ignition Wires	1.00	
	Throttle Body Cleaner	1.00	
	Injector Cleaner	1.00	
	Napagold Fuel Filter	1.00	
	Shop Supplies	1.00	
Hours 9.00	Labor: 540.00	Parts: 326.62	Total: 866.62
:			
<b>Workorder:</b> 1703710	<b>Meter:</b> 68999	<b>In Date:</b> 04/12/2017	<b>Closed:</b> 04/28/2017
<b>Problem:</b> Arrowboard inop.Check battery.			
- Diagnose arrowboard. Disasseble control box to replace middle switch .retest.	<b>Parts List</b>	<b>Qty</b>	
	Switch	1.00	
- Test battery and charging system .preform draw test .003 amps after ten mins.no problem found at this time.	Shop Supplies	1.00	
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 8.78	Total: 128.78
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1708316	<b>Meter:</b> 70485	<b>In Date:</b> 08/23/2017	<b>Closed:</b> 09/07/2017
<b>Problem:</b> P.M. service and check power steering.			
- P.m. service.	<b>Parts List</b>	<b>Qty</b>	
- Repair nail in tire right front.rotate and high speed balance all four .nitro fill all .	10w30 Motor Oil	5.00	
	Napagold Oil Filter	1.00	
- Inspect power steering for leaks.none. Check for excessive play,ok.no fault found at this time.road test.	22" Wiper Blade	2.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Used Fire X Refurbished	1.00	
	Drain Plug	1.00	
	Shop Supplies	1.00	
Hours 4.50	Labor: 270.00	Parts: 39.29	Total: 309.29
:			
<b>Workorder:</b> 1709829	<b>Meter:</b> 70859	<b>In Date:</b> 10/06/2017	<b>Closed:</b> 10/17/2017
<b>Problem:</b> Engine belt squeaks when first started, Check brake noise.			
- Replace noisy serpentine belt.retest.	<b>Parts List</b>	<b>Qty</b>	
- Service front and rear brake pads and calipers.remove debris from calipers.flush and bleed brake system .test drive.	Engine Belt	1.00	
- Shop Supplies	B Fluid Dot 3-32oz	1.00	
	Shop Supplies	1.00	
Hours 4.30	Labor: 258.00	Parts: 70.06	Total: 328.06
:			
<b>Workorder:</b> 1711903	<b>Meter:</b> 71587	<b>In Date:</b> 12/05/2017	<b>Closed:</b> 12/07/2017
<b>Problem:</b> Right side tire going flat.			
- Repair right rear tire and balance .nitrogen fill tires.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1803431      **Meter:** 72897      **In Date:** 04/02/2018      **Closed:** 04/10/2018  
**Problem:** P.M. service and had to jump start.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Replace broken pintle pin with new.	Battery	1.00
- Pressure test cooling system .r&r both inlet and outlet heater hoses.replace leaking water pump and thermostat .reverse flush cooling system and refill.	10w30 Motor Oil	5.00
	Napagold Oil Filter	1.00
- Replace two worn tires.rotate and balance all four tires .	Washer Fluid Concentr	1.00
	20" Wiper Blade	2.00
- Load test battery and recharge .replace failed battery .check charging system ,okay.check for draw , .009 amps from Gps .okay at this time.	Napagold Fuel Filter	1.00
	Floor Mat-2pc Rub Bk	1.00
- Test high hat beacon strobe .replace defective beacon strobe light with customer supplied beacon .rewire.	Pintle Pin W/clip	1.00
	Peak Global Antifrz	2.00
- Shop Supplies	Hose Clamp	1.00
	Hose Clamp	3.00
	Heater Hose Assembly	1.00
	Hose	1.00
	Water Pump Kit	1.00
	Thermostat	1.00
	183680418 P235-75r16	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.90	Labor: 654.00	Parts: 982.97
:		Total: 1,636.97

**Workorder:** 1804548      **Meter:** 73412      **In Date:** 05/01/2018      **Closed:** 06/26/2018  
**Problem:** Towed in will not stay running.

- Diagnose no start.check fuel pressure.perform pin point test.r&r fuel tank and replace defective fuel pump module.refill fuel tank.	<b>Parts List</b>	<b>Qty</b>
	Fuel Pump	1.00
- Diagnose inop check engine light.perform pin point test.replace P.c.m. Transport vehicle to dealer to program new P.c.m	Fmx-30 Fuse	1.00
	Pcm Assy	1.00
	Program	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 1,354.43
:		Total: 1,774.43

**Workorder:** 1804598      **Meter:** 72897      **In Date:** 05/01/2018      **Closed:** 05/02/2018  
**Problem:** wont stay running

- Tow From: 3700 Belvedere Rd next to Bldg E

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			