

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Total Hours: 124.25 Labor: 8,870.25 Parts: 8,630.04 Comm: 13,931.38 Charged: 31431.67

Work Order: 1703889 **Meter:** 315 **In Date:** 04/18/2017 **Closed:** 04/18/2017
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1705299 **Meter:** 1321 **In Date:** 05/30/2017 **Closed:** 05/30/2017
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1711263 **Meter:** 9118 **In Date:** 11/15/2017 **Closed:** 11/21/2017
Problem: P.M. service.Inspect for exhaust fumes.

Work Completed

- P.m. service.

- Rotate and balance four tires.

- Inspect all rear seams and plugs for gaps or leaks.recalibrate Hvac system with scan tool.per Tsb 17-0044.

- Shop Supplies

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 20.23 Total: 260.23

Work Order: 1801313 **Meter:** 9118 **In Date:** 01/19/2018 **Closed:** 02/02/2018
Problem: damag to rear bumper

Work Completed

- damag to rear bumper

Hours: 0.00 Comm: 1,271.70 Labor: 0.00 Parts: 0.00 Total: 1,271.70

Parts Issued	Quantity
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Work Order: 1807106 **Meter:** 18804 **In Date:** 07/12/2018 **Closed:** 07/18/2018
Problem: P.M. service and recall17N03 .

Work Completed

- P.m. service.
- Balance and rotate all four tires. Nitrofill.
- Transport to and from dealer for recall 17n03 .
- Shop Supplies

Parts Issued

Quantity

Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 59.81 Total: 359.81

Work Order: 1807367 **Meter:** 18804 **In Date:** 07/19/2018 **Closed:** 07/19/2018
Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00 Comm: 83.40 Labor: 0.00 Parts: 0.00 Total: 83.40

Work Order: 1810535 **Meter:** 18804 **In Date:** 09/27/2018 **Closed:** 10/12/2018
Problem: Accident Damage

Work Completed

- Tow From: I-95 in Broward County To: Accident Line @ Vista Parkway

Hours: 0.00 Comm: 230.40 Labor: 0.00 Parts: 0.00 Total: 230.40

Work Order: 1811547 **Meter:** 21565 **In Date:** 11/09/2018 **Closed:** 11/19/2018
Problem: check battery

Work Completed

- replace battery & check charging system
- Shop Supplies

Parts Issued

Quantity

Battery 65	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 172.77 Total: 239.77

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Work Order: 1909866 **Meter:** 28350 **In Date:** 09/25/2019 **Closed:** 09/25/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1910234 **Meter:** 28350 **In Date:** 10/03/2019 **Closed:** 10/03/2019
Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00 Comm: 95.40 Labor: 0.00 Parts: 0.00 Total: 95.40

Work Order: 2000013 **Meter:** 35100 **In Date:** 01/02/2020 **Closed:** 01/13/2020
Problem: P.M. service.

Work Completed

- P.m. service.

- Mount and balance all four tires . Nitrofill all.

- Perform complete front front alignment and road test .

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Washer Fluid Concentr 1.00

Napa Cabin Air Filter 1.00

245/60/18 Tire Mic 4.00

Shop Supplies 1.00

Tire Disposal Fee 4.00

Hours: 6.50 Comm: 0.00 Labor: 474.50 Parts: 1,008.81 Total: 1,483.31

Work Order: 2000330 **Meter:** 28350 **In Date:** 01/10/2020 **Closed:** 01/10/2020
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Work Order: 2105732 **Meter:** 51053 **In Date:** 05/24/2021 **Closed:** 06/28/2021
Problem: PM Service . and buzzing noise from light bar while driving

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Dismount And Patch Front Left Tire Balance And Rotate All Tires With Nitro Fill
- Service transmission . Drain & Fill Transmission Test Drive And Recheck
- Test Drive for noise .r&r Inside And Outside Pillar weather strip and front cowl panel . Road test .
- Shop Supplies

22in Exactfit-beam	1.00
11in Exactfit-rear	1.00
26in Exactfit-beam	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
oil auto	8.00
Moulding	1.00
Grille Wiper Motor	1.00
Shop Supplies	1.00

Hours: 7.00 Comm: 0.00 Labor: 511.00 Parts: 843.69 Total: 1,354.69

Work Order: 2105884 **Meter:** 51046 **In Date:** 05/27/2021 **Closed:** 06/01/2021
Problem: replace cracked windshield

Work Completed

Parts Issued

Quantity

- set up repairs
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 647.89 Labor: 73.00 Parts: 4.00 Total: 724.89

Work Order: 2109303 **Meter:** 51053 **In Date:** 08/18/2021 **Closed:** 08/26/2021
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 44.92 Labor: 0.00 Parts: 0.00 Total: 44.92

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Work Order: 2113419 **Meter:** 56060 **In Date:** 12/20/2021 **Closed:** 12/23/2021
Problem: PM Service. and recall 21S22

Work Completed

- Preventive Maint. Service
- Check all tires, R & I four new tires, speed balance , nitro fill
- Perform complete front alignment, road test
- Check and replace cabin filter
- Transport to and from dealer for recall 21s22 .
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
26in Exactfit-beam	1.00
Oil Filter	1.00
5w20 Engine Oil	6.00
Napagold Air Filter	1.00
245/60/18 Tire Mic	4.00
Napa Cabin Air Filter	1.00
22in Exactfitblade	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 8.00

Comm: 0.00

Labor: 584.00

Parts: 851.71

Total: 1,435.71

Work Order: 2200446 **Meter:** 56456 **In Date:** 01/13/2022 **Closed:** 01/18/2022
Problem: Key battery needs replacing

Work Completed

- replace key Fob batteries.

Parts Issued

Quantity

Battery	2.00
---------	------

Hours: 0.30

Comm: 0.00

Labor: 21.90

Parts: 7.94

Total: 29.84

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Work Order: 2203952 **Meter:** 56458 **In Date:** 04/12/2022 **Closed:** 04/19/2022
Problem: PM Service . Right outside b-pillar molding fell off

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- rotate and balance all 4 tire nitro fill all
- passenger side outer b pillar molding remove adhesive and replace with new molding
- steering wheel making noises from side to side remove and replace front struts
- perform front end alignment after replacing struts
- Shop Supplies

11in Exactfit-rear	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Oil Filter	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Bracket	2.00
moulding	1.00
Strut	1.00
Strut	1.00
Shop Supplies	1.00

Hours: 9.10

Comm: 0.00

Labor: 664.30 Parts: 534.72 Total: 1,199.02

Work Order: 2209892 **Meter:** 64510 **In Date:** 09/22/2022 **Closed:** 10/03/2022
Problem: PM Service nail in rear tire and scratch left rear Quarter panel .

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Inspect Brakes, Rear Brake Pads At Mimimum Deapth And Rotors Out Of Spec, R&r Rear Brake Pads, Rotors, Service And Bleed Brakes Test Drive
- Balance And Rotate Tires With Nitro Fill
- Passanger Side Mirror Turn Signal Out R&r Lights And Retest
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Brake Rotor	2.00
Mirror Lamp Assy	1.00
Brake Pads	1.00
Mirror Glass	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50 Parts: 458.91 Total: 1,006.41

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Work Order: 2312707 **Meter:** 72785 **In Date:** 12/28/2023 **Closed:** 01/08/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Blade	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00 Parts: 71.44 Total: 290.44

Work Order: 2404126 **Meter:** 83575 **In Date:** 04/25/2024 **Closed:** 05/01/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Diagnose engine misfire .r&i six sparkplugs, coil boots, and upper intake gaskets due normal wear and tear. Power balance test cylinders with scan tool and road test to verify repair.
- Service fuel injection, decarb upper intake system, and clean throttle body.
- Repair left rear tire flat, rotate and balance four. Relearn tire sensors.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Spark Plug	6.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Boot Ing	6.00
Plenum Gskt Set	1.00
Shop Supplies	1.00

Hours: 10.50

Comm: 0.00

Labor: 766.50 Parts: 193.35 Total: 959.85

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Work Order: 2407931 **Meter:** 88264 **In Date:** 08/16/2024 **Closed:** 09/19/2024
Problem: PM Service. Safety recall # 24S02/24V031

Work Completed

- Preventive Maint. Service
- Recall: Safety recall # 24s02/24v031 A-pillar trim loose (improper assembly) parts ordered for recall back ordered .
- mount 2 tires rotate and balance all 4 tires nitro fill all
- Engine side mount was observed to be leaking vehicle was power break and excessive movement was seen. Remove and replace engine side and transmission mount.
- Shop Supplies

Hours: 7.80

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
21in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Engine Bracket	1.00
Insulator Tram	1.00
245/60/18 Tire Mic	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Labor: 569.40

Parts: 695.34

Total: 1,264.74

Work Order: 2501614 **Meter:** 91792 **In Date:** 02/18/2025 **Closed:** 02/27/2025
Problem: P.M. Service. Tire sensor light on

Work Completed

- perform Preventive Maint. Service
- mount 2 tires, balance rotate all, nitro fill, scanned sensors, 3 low batt 1 dead. R&r dead tpms sensors and low batt sensors. rattling caused by tire imbalance.
- Shop Supplies

Hours: 4.00

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Tpms Sens Kit	4.00
245/60/18 Tire Mic	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Labor: 292.00

Parts: 729.04

Total: 1,021.04

1/28/2026
2:01:07 PM

Palm Beach County Fleet Management Asset Maintenance History
10203425 2017 FORD EXPLORER Suv, Lg Mid Size, Black

Work Order: 2507483 **Meter:** 100621 **In Date:** 08/11/2025 **Closed:** 09/03/2025
Problem: PM Service. Had to jump start vehicle

Work Completed

- Preventive Maint. Service
- Recall: Safety recall # 24s02/24v031 A-pillar trim loose (improper assembly) parts ordered and on back order
- Rotated and balanced all 4 tires. Nitrogen filled al tires
- Charged battery fully. Tested starting and charging system and battery tested bad. Replaced bad battery and use scan tool to reset Bms.
- Replaced cabin filter and clean debris from fresh air intake.
- Replaced cowl panel and pass side b pillar cover. Clean glue and tape residue and damaged wiper transmission assembly
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Napagold Air Filter	1.00
Kseal Head Gsket Repr	1.00
Battery	1.00
Cabin Filter	1.00
Grille	1.00
moulding	1.00
Arm Wiper Assy	1.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 584.00

Parts: 751.72

Total: 1,335.72

Work Order: 2509976 **Meter:** 100621 **In Date:** 10/23/2025 **Closed:** 10/27/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 124.25

Total Labor: 8,870.25

Total Comm: 13,931.38

Total Parts: 8,630.04