

1/28/2026
2:29:12 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2017 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Total Hours: 206.00 Labor: 14,820.25 Parts: 15,019.80 Comm: 5,068.58 Charged: 34908.63

Work Order: 1711848 **Meter:** 312 **In Date:** 12/04/2017 **Closed:** 12/22/2017
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
- Shop Supplies

Hours: 2.00 Comm: 0.00

Parts Issued

Shop Supplies 1.00

Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1800358 **Meter:** 314 **In Date:** 01/10/2018 **Closed:** 01/18/2018
Problem: install brush guards

Work Completed

- Brush guard installed
- Jump, charge, load test. battery test good
- Shop Supplies

Hours: 1.50 Comm: 0.00

Parts Issued

Shop Supplies 1.00

Labor: 90.00 Parts: 2.00 Total: 92.00

Work Order: 1804009 **Meter:** 3371 **In Date:** 04/18/2018 **Closed:** 04/19/2018
Problem: Left rear tire going flat.

Work Completed

- Swap spare tire onto left rear wheel and mount new tire on spare .balance both wheel assemblies and nitrogen fill tires.
- Shop Supplies

Hours: 1.00 Comm: 0.00

Parts Issued

Lt265/70r17 Gdy Silent Armor 1.00
Shop Supplies 1.00
Tire Disposal Fee 1.00

Labor: 60.00 Parts: 288.18 Total: 348.18

Work Order: 1805270 **Meter:** 4450 **In Date:** 05/23/2018 **Closed:** 05/24/2018
Problem: Left rear tire leaking.

Work Completed

- Repair left rear tire and balance .nitrogen fill tires.
- Shop Supplies

Hours: 1.00 Comm: 0.00

Parts Issued

Shop Supplies 1.00

Labor: 60.00 Parts: 2.00 Total: 62.00

1/28/2026
2:29:12 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2017 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 1806939 **Meter:** 6086 **In Date:** 07/09/2018 **Closed:** 07/18/2018
Problem: P.M. Service.Install A/T tires.Mount box in bed of truck.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Replace all four tires with A/t tires .nitrofill and high speed balance all four tires.
- Drill and secure tool box In bed of truck .
- Shop Supplies

Ford Triton Pvc Swc	1.00
Floor Mat-2pc Rub Bk	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Lt265 70r17 Mt Tire	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 5.25 Comm: 0.00 Labor: 315.00 Parts: 1,286.34 Total: 1,601.34

Work Order: 1807891 **Meter:** 6197 **In Date:** 07/17/2018 **Closed:** 08/01/2018
Problem: damage to rear bumper

Work Completed

- damage to rear bumper

Hours: 0.00 Comm: 891.00 Labor: 0.00 Parts: 0.00 Total: 891.00

Work Order: 1811650 **Meter:** 12019 **In Date:** 11/14/2018 **Closed:** 11/19/2018
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Inspect and service winch .
- Rotate and balance all four tires . Nitrofill all tires . Reset Tpms.
- Shop Supplies

Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Shop Supplies	1.00

Hours: 4.75 Comm: 0.00 Labor: 318.25 Parts: 49.31 Total: 367.56

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 1811945 **Meter:** 12022 **In Date:** 11/26/2018 **Closed:** 11/28/2018
Problem: repair loose spoiler

Work Completed

- repair loose spoiler
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

Work Order: 1900245 **Meter:** 14371 **In Date:** 01/07/2019 **Closed:** 01/10/2019
Problem: Jump start at traffic lot .

Work Completed

- Service call to traffic lot to jump start . Charge battery fully . Battery failed load test . R&r defective battery and retest.
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Battery 65	1.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 100.50 Parts: 179.69 Total: 280.19

Work Order: 1904215 **Meter:** 18478 **In Date:** 04/18/2019 **Closed:** 04/25/2019
Problem: P.M. service and right tail lamp broken .

Work Completed

- P.m. service.
- Inspect and service winch .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 4.75 Comm: 0.00 Labor: 318.25 Parts: 47.54 Total: 365.79

Work Order: 1904944 **Meter:** 18478 **In Date:** 04/23/2019 **Closed:** 05/07/2019
Problem: Damage to right rear tail light & tailgate.

Work Completed

- Damage to right rear tail light & tailgate.

Hours: 0.00 Comm: 420.00 Labor: 0.00 Parts: 0.00 Total: 420.00

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2004811 **Meter:** 31836 **In Date:** 05/13/2020 **Closed:** 05/27/2020
Problem: P.M Service.

Work Completed

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Diagnose emergency brake not holding . R&r leaking right rear axle seal and replace saturated parking brake shoes and adjust and clean oil . Refill rear differential and retest .
- Replace and balance all four tires . Nitrofill all.
- Diagnose engine missfire . Perform tune up . Replace all sixteen spark plugs and wire set and coil two ,four and five . Clear codes and retest .
- Perform complete air intake decarb and cleaning . Flush injectors .
- Inspect and service winch .
- Complete front end alignment and road test .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Cabin Air Filter	1.00
Air Fltr	1.00
Brake Shoes Park	1.00
Axle O Ring	1.00
Seal	1.00
Lt265/70r17	4.00
Coil	2.00
Coil	1.00
Spark Plug Wire	8.00
Spark Plug	16.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 21.45

Comm: 0.00

Labor: 1,565.85

Parts: 2,196.72

Total: 3,762.57

Work Order: 2005428 **Meter:** 31969 **In Date:** 06/01/2020 **Closed:** 06/02/2020
Problem: Jump start at traffic lot .

Work Completed

- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery .
- Shop Supplies

Parts Issued

Quantity

Battery 65	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 180.69

Total: 253.69

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2008479 **Meter:** 35113 **In Date:** 08/25/2020 **Closed:** 08/31/2020
Problem: Traction control light on, Stability warning on.

Work Completed

Parts Issued

Quantity

- Computer diagnose traction control codes , C0051 ,p193c and U0415 . Perform pinpoint test . Clear codes and reset parameters . Road test and inspect undercarrige for damage .
- Test and replace corroded trailer plug connector and rewire as needed .
- Shop Supplies

trailer plug	1.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 15.10 Total: 161.10

Work Order: 2008718 **Meter:** 35151 **In Date:** 08/31/2020 **Closed:** 09/02/2020
Problem: Check engine light on.

Work Completed

Parts Issued

Quantity

- Computer diagnose check engine light , code P0307and P0300 . Perform pinpoint test , power balance test . R&r defective number seven coil and spark plug . Clear codes and retest .
- Shop Supplies

Coil	1.00
Spark Plug	1.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 143.25 Total: 289.25

Work Order: 2009476 **Meter:** 35583 **In Date:** 09/21/2020 **Closed:** 09/22/2020
Problem: Left rear tire has screw.

Work Completed

Parts Issued

Quantity

- Repair left rear tire and balance . Nitrofill all.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2010372 **Meter:** 36390 **In Date:** 10/15/2020 **Closed:** 10/21/2020
Problem: P.M. Service.Check engine light on.

Work Completed

- P.m. service.
- Computer diagnose check engine light , code P0300 P0316 . Perform power balance test . Replace four coils and four spark plugs due to water intrusion . Clear codes and retest .
- Test and replace defective washer pump . Refill tank and retest .
- Resurface both front brake rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test .
- Inspect and service transfer case
- Inspect and service winch .
- Balance all four tires . Nitrofill all.
- Shop Supplies

Hours: 13.55

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Spark Plug	4.00
Coil	2.00
Coil	2.00
Washer Pump	1.00
Brake Pad	1.00
oil auto	3.00
Shop Supplies	1.00

Labor: 989.15

Parts: 803.53

Total: 1,792.68

Work Order: 2100624 **Meter:** 38670 **In Date:** 01/19/2021 **Closed:** 01/20/2021
Problem: Right rear tire going flat .

Work Completed

- Diagnose tire going flat . Replace damage valve stem and retest . Balance and nitro fill .
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Quantity

Tire Pressure Monitoring System Sensor (1.00
Shop Supplies	1.00

Labor: 73.00

Parts: 7.62

Total: 80.62

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2101726 **Meter:** 39562 **In Date:** 02/16/2021 **Closed:** 03/03/2021
Problem: P.M. service , A/C not cold , winch inop and repair bumper

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Performed Service And Inspection On Winch, Replaced Damaged Controller, Also Removed And Replaced Frayed And Separated Winch Cable & Hook.
- Strokes Inop, Check Power & Ground To Switch. Power & Ground Was Ok, Found Switch Defective, Removed And Replaced Then Check. Working As Design.
- Check Customer Concern, Performed A/c Cooling System Performance Test, Recover A/c System, Found A/c Compressor Defective Removed And Replaced, A/c Compressor, Condensor, Expansion Valve, Cabin Filter Clean And Flush A/c System, Vacuum And Charge.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Clevis Slip Hook-bulk	1.00
Rep/rope	1.00
Remote Ctrl Ser. Part	1.00
Universal Switch	1.00
Cabin Filter	1.00
Freon Lv Shop 2	2.00
Oil Compressor	1.00
Flush Solvent	1.00
O Ring Kit A/c	1.00
A/cseal	1.00
Seal	1.00
A/c Valve	1.00
A/c Condensor	1.00
A/c Compressor	1.00
Shop Supplies	1.00

Hours: 16.05

Comm: 0.00

Labor: 1,171.65

Parts: 1,312.23

Total: 2,483.88

Work Order: 2103276 **Meter:** 39511 **In Date:** 02/26/2021 **Closed:** 03/23/2021
Problem: damage to front & rear bumpers

Work Completed

- damage to front & rear bumpers

Hours: 0.00

Comm: 3,178.34

Labor: 0.00

Parts: 0.00

Total: 3,178.34

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2202434 **Meter:** 51002 **In Date:** 03/03/2022 **Closed:** 03/14/2022

Problem: PM Service. Strobe light loose.

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Performed Service & Inspection On Winch.
- Removed And Replaced Cabin Air Filter, Clean A/c Vents & Check.
- Straighten Mount Plate And Resecure Loose Driver Side Beacon Strobe Light.
- Removed And Replaced Broken Passenger Side Rear Tail Light Assembly, Modify For Strobe.
- Removed And Replaced Both Front Leaking Hood Shock Strut.
- Remove Lower Dash Panel And Wiper Cowl Panel To Removed And Replaced Damaged Antenna Base & Mass..
- Removed & Replaced Rear Brake Pads, Resurface Rear Brake Rotors, Then Bleed & Flush Entire Brake System, Test Drove Vehicle And Burnish Brakes.
- Check Engine Light On & Vehicle Runs Rough, Plug In Scan Tool And Check For Faults, Found Fault Code P0307 & Po303, Performed Test Plan, Found Ignition Coil Cylinder 3 & 7 Defective Removed And Replaced.
- Shop Supplies

Hours: 15.45

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Cabin Air Filter	1.00
Tail Lamp Asy Rh	1.00
Antena Radio	1.00
Lift Support	1.00
Lift Support	1.00
Aerial Assy	1.00
Non-chlor Brake Clnr	2.00
Brake Pads	1.00
Coil	1.00
Coil	1.00
Brake Master Cap	1.00
Brk Fluid Dot 4-32oz	1.00
Shop Supplies	1.00

Labor: 1,127.85

Parts: 579.26

Total: 1,707.11

Work Order: 2202514 **Meter:** 51001 **In Date:** 02/17/2022 **Closed:** 03/07/2022

Problem: winch out, stuck about 30" from asphalt

Work Completed

- Tow From: Beeline/indiantown rd, west side of beeline To:

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2301605

Meter: 61437

In Date: 02/16/2023 **Closed:** 03/07/2023

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Inspect Power Winch And Found Gears Seized Due To Water Causing Rust Inside. Removed, Cleaned And Lubricate Gears. Fabricate Winch Cable Too Long And Getting Stuck. Retest Winch And Verified Repair Complete.
- Mount Two New Tires, Rotate And Balance Four. Relearn Tire Sensors.
- Inspect And Found Contaminated Front Differential Oil. Removed Cover To Clean And Resealed. Replace With New Gear Oil.
- Inspect And Service Transmission Oil, Removed Pan To Replace Filter, And Complete Automatic Transmission Service Flush. Road Test To Verify Repair Complete.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Wd40 Spr	1.00
Non-chlor Brake Clnr	1.00
Px Grey Rtv Silicone	1.00
Oil Gear	3.00
Trams Filter	1.00
oil auto	16.00
Lt265/70r17	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.25

Comm: 0.00

Labor: 821.25

Parts: 779.81

Total: 1,601.06

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2309702 **Meter:** 68621 **In Date:** 09/25/2023 **Closed:** 10/02/2023

Problem: PM Service tire light and had to jump start Remount strobes on rack outside

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill Check and replace faulty left front wheel sensor
- Inspect and service winches
- Perform battery analyzing load & Charging system test, battery failed, R & i new batt
- Running board/nerf board step, Damage both side R & i , install new running board
- Repair both side Roof strobe light Fabricate bracket and mount on roof Rack, rewire circuit to lamp , Repair front bumper valance detach
- Check all, R & i new front brakes, Resurface both rotors, R & i both front Calipers, service both caliper slide pins Bleed brake system, Burnish rotors, road test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Air Fltr	1.00
Used Fire X Refurbished	1.00
Big G Degreaser 1 Gal	1.00
Gear Oil	1.00
Battery	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	2.00
Brake Pads	1.00
Bracketed Caliper	1.00
Bracketed Caliper	1.00
Tpms Sensor	1.00
Step Assy	1.00
Shop Supplies	1.00

Hours: 16.75

Comm: 0.00

Labor: 1,222.75

Parts: 1,065.55

Total: 2,288.30

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2402676

Meter: 75155

In Date: 03/14/2024 **Closed:** 04/30/2024

Problem: PM Service

Work Completed

- Preventive Maint. Service
- mount 2 tires replace 2 tpms sensors rotate and balance all 4 tires nitro fill all
- perform fuel injector kit clean throttle body
- replace all sparkplug and wires
- customer states camper lock won't unlock. lock was frozen Replace camper lock drum
- customer states back wig-wags won't work. Pinpoint test found faulty front strobe lights itself. Remove and replace.
- Right Rear brake light assembly has a hole Remove and replace light assembly and install strobe light
- inspect winch and lube all moving
- Driveshaft slip joint boot is torn Remove and replace
- Front Diff vent hose broke off Replace hose vent
- Customer states vehicle has a hard time start. Using Ids found purge valve stuck open causing a hard start Remove and replace Purge valve
- Vehicle would not until key was cycle when it sat for long period of time. Pcm relay was found to have heat marks and be extremely hot after vehicle was turned off
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Air Fltr	1.00
Quality Htr Hose	4.00
Valve Asm	1.00
Tpms Sensor	2.00
Lt265/70r17 Bfg All-terrain	2.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Spark Plug Wire	8.00
Spark Plug	16.00
Mnt Conc Led Clear	2.00
Boot	1.00
Tail Lamp Asy Rh	1.00
Lock Cylinder	1.00
Relay	1.00
Coil	1.00
Coil	2.00
Relay	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 20.15

Comm: 0.00

Labor: 1,470.95

Parts: 1,967.24

Total: 3,438.19

1/28/2026
2:29:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10204208 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4

Work Order: 2504267 **Meter:** 87556 **In Date:** 05/07/2025 **Closed:** 05/08/2025
Problem: fix flat tire

Work Completed

- Repair left rear tire and balance . Nitro fill all and reset Tpms
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Shop Supplies

Quantity

1.00

Labor: 73.00

Parts: 2.65

Total: 75.65

Work Order: 2507288 **Meter:** 90009 **In Date:** 08/06/2025 **Closed:** 08/20/2025
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Right Side Beacon Mounting Bracket Broken Replace And Mount, Right Rear Reverse Bulb Burnt Test Power And Ground To Bllb Replace Bulb And Retest, Tested Power And Ground To Alley Light Bar Found Switch Shorted Internally Replace Switch Board
- Front Right Strobe Lights Burnt Test Power And Ground Repalce And Retest
- Rear Camper Door Strut Bracket Broken Drill Out Old Rivets And Install New Rivets And Strut Retest
- Replace 2 Tires Balance With Nitro Fill
- Test And Service Winche
- Test Drive And Perform Front End Alignment Retest
- Shop Supplies

Hours: 13.25

Comm: 0.00

Parts Issued

Napagold Oil Filter

Napa Quart 5w30

Used Fire X Refurbished

Wiper Blade

Vtx609c Led Strobe Cl

Lighted Switchbox

Warning Beacon

Support

Boxed Miniatures

Lt265/70r17 Bfg All-terrain

Shop Supplies

Tire Disposal Fee

Quantity

1.00

7.00

1.00

2.00

1.00

1.00

1.00

2.00

1.00

2.00

1.00

2.00

Labor: 967.25

Parts: 1,080.35

Total: 2,047.60

Work Order: 2511384 **Meter:** 93326 **In Date:** 12/08/2025 **Closed:** 12/09/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 206.00

Total Labor: 14,820.25

Total Comm: 5,068.58

Total Parts: 15,019.80