

1/28/2026
2:53:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10201354 2017 MACK CHU613 Truck Tractor, Tandem Axle

Total Hours: 225.10 Labor: 15,242.50 Parts: 20,359.66 Comm: 678.38 Charged: 36280.54

Work Order: 1607653 **Meter:** 209 **In Date:** 07/27/2016 **Closed:** 08/19/2016
Problem: check in

Work Completed

- New vehicle check in
- Build and install hyd.lines and pogo stick
- Install fire exstingusher
- Def
- Install (over load) sign and fab pole holders
- To Mako
- Road test
- Shop Supplies

Parts Issued

Quantity

W W Vacuum Tubing	10.00
hose made	1.00
Cable Tie	2.00
u bolt	1.00
hose made	1.00
Used Fire X Refurbished	1.00
Custom Bracket Fire Ex	1.00
Def Quart	5.00
18x18 red flag	4.00
Pogo Stick	1.00
Shop Supplies	1.00

Hours: 20.50

Comm: 0.00

Labor: 1,230.00

Parts: 727.70

Total: 1,957.70

Work Order: 1608284 **Meter:** 209 **In Date:** 08/11/2016 **Closed:** 08/11/2016
Problem: 1062 - Make & Apply Decals. Check Fluids, Belts and Operation

Work Completed

- Make & Apply Decals. Check Fluids, Belts and Operation

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 0.00

Total: 60.00

Work Order: 1608310 **Meter:** 209 **In Date:** 08/11/2016 **Closed:** 08/19/2016
Problem: order spare keys M087

Work Completed

- Parts only

Hours: 0.00

Comm: 0.00

Parts Issued

Quantity

Ign Key	2.00
---------	------

Labor: 0.00

Parts: 9.75

Total: 9.75

1/28/2026
2:53:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10201354 2017 MACK CHU613 Truck Tractor, Tandem Axle

Work Order: 1903251 **Meter:** 17436 **In Date:** 03/26/2019 **Closed:** 03/27/2019
Problem: Abs light on trailer

Work Completed

Parts Issued

Quantity

- Inspect Abs system on trailer. Found rear axle harness unplugged. Reconnected harness.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.50 Comm: 0.00 Labor: 100.50 Parts: 3.00 Total: 103.50

Work Order: 1907824 **Meter:** 19722 **In Date:** 07/29/2019 **Closed:** 08/06/2019
Problem: Pm service.

Work Completed

Parts Issued

Quantity

- Pm service.
- Add Def.
- Shop Supplies

Filter Kit For Mack	1.00
15w40 Bulk Tank Pahokee	38.00
20" Wiper Blade	2.00
Def Fluid 2.5	1.00
Shop Supplies	1.00

Hours: 7.50 Comm: 0.00 Labor: 502.50 Parts: 266.36 Total: 768.86

Work Order: 1912198 **Meter:** 22143 **In Date:** 11/26/2019 **Closed:** 11/26/2019
Problem: Air leak

Work Completed

Parts Issued

Quantity

- Repair leaking airline at air tank.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 4.00 Total: 113.50

1/28/2026
2:53:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10201354 2017 MACK CHU613 Truck Tractor, Tandem Axle

Work Order: 2002401 **Meter:** 23843 **In Date:** 03/09/2020 **Closed:** 03/10/2020
Problem: Pm service.

Work Completed

- Pm service.
- Add Def.
- Test drive. Hook to trailer.
- Shop Supplies

Parts Issued

Quantity

Filter Kit For Mack	1.00
15w40 Bulk Tank Pahokee	38.00
20" Wiper Blade	2.00
Napagold Air Filter	1.00
Blue Df	4.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00 Parts: 359.74 Total: 1,016.74

Work Order: 2009736 **Meter:** 26530 **In Date:** 09/28/2020 **Closed:** 10/08/2020
Problem: Pm service.

Work Completed

- Pm service.
- Add Def.
- Replace damaged pto hyd hoses to trailer.
- Fuel not pulling from Lh fuel tank. Tank breather filter clogged. Replaced fuel tank vent filters.
- Clean a/c filter.
- Fm to Hyd. Supply.
- Shop Supplies

Parts Issued

Quantity

15w40 Bulk Tank Pahokee	38.00
Filter Kit For Mack	1.00
Washer Fluid Concentr	1.00
20" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Blue Df	4.00
Aw68 Hyd Fluid Tank Pahokee	8.00
Vent Filter	2.00
Hose Assembly	1.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50 Parts: 1,051.50 Total: 1,891.00

Work Order: 2012806 **Meter:** 27562 **In Date:** 12/23/2020 **Closed:** 01/07/2021
Problem: mud flap

Work Completed

- mud flap and bracket damaged replaced both factory mud flap brackets and mud flap on right side
- Shop Supplies

Parts Issued

Quantity

Brkt Guard	1.00
Mack Mud Flap	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 615.09 Total: 688.09

1/28/2026
2:53:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10201354 2017 MACK CHU613 Truck Tractor, Tandem Axle

Work Order: 2101777 **Meter:** 29318 **In Date:** 02/17/2021 **Closed:** 02/24/2021
Problem: right air supply line to trailer has break in it.

Work Completed

Parts Issued

Quantity

- replaced trailer air lines from truck to trailer and found air fitting leaking on tank
- Shop Supplies

Nipple	1.00
Hose Coiled/trailer	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50 Parts: 121.57 Total: 304.07

Work Order: 2103964 **Meter:** 30341 **In Date:** 04/08/2021 **Closed:** 04/20/2021
Problem: lights bar bracket broken/ lights on light bar not flashing, pm service

Work Completed

Parts Issued

Quantity

- Preventive Maintenance Service
- Repair light bar wiring and install new mounting brackets
- Add Def
- Shop Supplies

15w40 Bulk Tank Pahokee	38.00
Filter Kit For Mack	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
20" Wiper Blade	2.00
Napagold Air Filter	1.00
Blue Df	4.00
Roof Mount Kit	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00 Parts: 500.38 Total: 1,157.38

Work Order: 2109250 **Meter:** 31900 **In Date:** 08/25/2021 **Closed:** 08/30/2021
Problem: truck will not start

Work Completed

Parts Issued

Quantity

- Batteries failed test, install new batteries.
- Shop Supplies

Group 31 Stud Delco	3.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00 Parts: 373.14 Total: 519.14

1/28/2026
2:53:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10201354 2017 MACK CHU613 Truck Tractor, Tandem Axle

Work Order: 2207727 **Meter:** 36052 **In Date:** 07/25/2022 **Closed:** 08/02/2022
Problem: driver side window up/down button not working

Work Completed

- checked all connections verified switch was bad replaced driver side window switch
- Shop Supplies

Hours: 1.00 Comm: 0.00

Parts Issued

	Quantity
Window Switch	1.00
Shop Supplies	1.00

Labor: 73.00 Parts: 49.92 Total: 122.92

Work Order: 2301061 **Meter:** 38835 **In Date:** 02/01/2023 **Closed:** 02/09/2023
Problem: air leaking from tank on right front side, pm service

Work Completed

- Preventive Maintenance Service
- R/r 4 Parking brake tank fitting and reseal. Replaced 2 of the fittings. Trimmed worn hose ends and adjust hose routing.
- Top off Def
- Shop Supplies

Hours: 8.50 Comm: 0.00

Parts Issued

	Quantity
15w40 Bulk Tank Pahokee	38.00
Filter Kit	1.00
Washer Fluid Concentr	1.00
20" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	1.00
Aw68 Hyd Fluid Tank Pahokee	3.00
Blue Df	3.00
Elbow Nipple	1.00
Elbow Nipple	1.00
Shop Supplies	1.00

Labor: 620.50 Parts: 456.76 Total: 1,077.26

1/28/2026
2:53:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10201354 2017 MACK CHU613 Truck Tractor, Tandem Axle

Work Order: 2500002 **Meter:** 49461 **In Date:** 01/02/2025 **Closed:** 01/07/2025
Problem: 2 - cab running lights are out

Work Completed

Parts Issued

Quantity

- Outer cab clearance lights shorted. Installed new aftermarket lights swapping wiring pigtails to new lights and drilling mounting holes in lights.
- Shop Supplies

Aerodynamic Cab Lamp	2.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 57.96 Total: 203.96

Work Order: 2501096 **Meter:** 49775 **In Date:** 02/04/2025 **Closed:** 02/11/2025
Problem: right rear airbag leaking

Work Completed

Parts Issued

Quantity

- rear airbags leaking replaced both rear bags
- Shop Supplies

Air Spring	2.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 434.07 Total: 726.07

Work Order: 2504703 **Meter:** 51945 **In Date:** 05/20/2025 **Closed:** 07/09/2025
Problem: PM Service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- added def
- a/c not cold found low on freon found high side Shrader valve leaking replaced valve and recharged system found recirculate blend door actuator bad replaced actuator
- test drive x2
- disconnected trailer from truck reconnected when done with service
- Shop Supplies

Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Fuel Filter	1.00
Napagold Fuel Filter	1.00
15w40 Bulk Tank Pahokee	38.00
Napagold Oil Filter	2.00
Napa Oil Filter	1.00
Napagold Air Filter	1.00
Blue Df	2.00
Freon Pahokee Shop	4.00
Actuator	1.00
Shop Supplies	1.00

Hours: 14.00 Comm: 0.00 Labor: 1,022.00 Parts: 350.34 Total: 1,372.34

1/28/2026
2:53:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10201354 2017 MACK CHU613 Truck Tractor, Tandem Axle

Work Order: 2509499 **Meter:** 52611 **In Date:** 10/07/2025 **Closed:** 10/09/2025
Problem: HYDRAULIC HOSE BURST

Work Completed

Parts Issued

Quantity

- from pa shop to hydraulic supply back to pa shop
- hydraulic line burst replaced both lines from tractor to lowboy trailer
- Shop Supplies

Hyd Hose 10201354	1.00
Shop Supplies	1.00

Hours: 3.50 Comm: 0.00 Labor: 255.50 Parts: 838.00 Total: 1,093.50

Work Order: 2510671 **Meter:** 52611 **In Date:** 11/12/2025 **Closed:** 11/20/2025
Problem: remove oversize sign from front bumper

Work Completed

Parts Issued

Quantity

- removed oversized load sign from front of truck to use on new truck
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2511236 **Meter:** 53074 **In Date:** 12/03/2025 **Closed:**
Problem: Glades Mario, need to swap out fitting on pigtail from this truck to CA2000037666 it is in our yard by our Low-boy

Work Completed

-

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2511242 **Meter:** 53074 **In Date:** 12/03/2025 **Closed:** 12/03/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 225.10 Total Labor: 15,242.50 Total Comm: 678.38 Total Parts: 20,359.66