


EAST OPERATION



CAUTION: Pilots are cautioned not to mistake Taxiway Lima for Runway 10L/28R or Runway 10R/28L

WEST OPERATION



CAUTION: Pilots are cautioned not to mistake Taxiway Lima for Runway 10L/28R or Runway 10R/28L