

**Palm Beach County Fleet Management
Asset Maintenance History**

10175093 2009 FORD F350 Utility Body, 1 Ton

Workorder: 937084 **Meter:** 0 **In Date:** 04/27/2009 **Closed:** 04/27/2009
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 4.00 Labor: 240.00 Parts: 0.00 Total: 240.00
:

Workorder: 946552 **Meter:** 4328 **In Date:** 12/01/2009 **Closed:** 01/07/2010
Problem: P.M service, install grab handles on rear utility bed

- P.m service.

Parts List

Qty

- Fabricate & install grab handles on rear of utility box.

Freight

1.00

- Rotate & balance all six tires, perform nitro service on all six tires.

Shop Supplies

1.00

7312 Oil Filterfrm Ch9549 Wix 57312

1.00

- Shop Supplies

Cs10263 Fuel Filter (use Cs10263a)

1.00

15/40 Oil

15.00

Grab Handles B239920c

2.00

Hours 7.50 Labor: 450.00 Parts: 120.43 Total: 570.43
:

Workorder: 1000987 **Meter:** 4775 **In Date:** 01/27/2010 **Closed:** 02/23/2010
Problem: Install tool boxes on utility bed.

- Fabricate & install two tool boxes on top of utility bed.

Parts List

Qty

- Shop Supplies

Shop Supplies

1.00

3"x3"x20' Alum Angle Architectual 1/4" Thick

6.00

1/2x4x12 Alum Flat Bar

2.00

Tool Box / 365-0-01

2.00

Hours 4.00 Labor: 240.00 Parts: 2,430.23 Total: 2,670.23
:

Workorder: 1007043 **Meter:** 7910 **In Date:** 07/06/2010 **Closed:** 07/13/2010
Problem: Pm service.

- P.m. Service.

Parts List

Qty

- Rotate and balance six tires.

Shop Supplies

1.00

- Shop Supplies

7312 Oil Filterfrm Ch9549 Wix 57312

1.00

Cs10263 Fuel Filter (use Cs10263a)

1.00

Ca10270 Air Filter Mtc Fa1886 Wix 49886

1.00

15/40 Oil

15.00

Used Firex Refurbed Fire Extingshers

1.00

Hours 5.50 Labor: 330.00 Parts: 135.61 Total: 465.61
:

Workorder: 1007348 **Meter:** 7910 **In Date:** 07/13/2010 **Closed:** 07/15/2010
Problem: reflash canceiver / spot #212

- Reflash Canceiver and reprogram

Parts List

Qty

- Shop Supplies

Shop Supplies

1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1100664 **Meter:** 11523 **In Date:** 01/18/2011 **Closed:** 01/25/2011
Problem: P.M. Service.

- P.m. Service.	Parts List	Qty
- Replace two tires,repair one.rotate and balance all.	Shop Supplies	1.00
- Complete wheel alignment.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Shop Supplies	Cs10263 Fuel Filter (use Cs10263a)	1.00
	09997 Brake Clean	1.00
	15/40 Oil	15.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	179636492 Lt245/75r17 Wrangler Sr-a E	2.00
	Tire Disposal Fee	2.00
Hours 9.50	Labor: 570.00	Parts: 473.44
:		Total: 1,043.44

Workorder: 1107352 **Meter:** 14954 **In Date:** 07/13/2011 **Closed:** 07/28/2011
Problem: P.M. service and trailer connector inop. and right rear tire flat.

- Perform pm service.	Parts List	Qty
- Test starting and charging system.both batteries failed load test after recharge.replace both failed batteries with new.	Shop Supplies	1.00
- Install four new tires.nitrogen fill and balance all six.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Test and repair shorted trailer harness and install new fuse.also repair ground circuit for tag lamp.	Cs10263 Fuel Filter (use Cs10263a)	1.00
- Transport vehicle to and from dealer for replacing failed upper radiator hose with new and reprogram pcm as per recall #11b23	15/40 Oil	15.00
- Shop Supplies	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	Group 65 Battery (mtc Bxt-65-850)	2.00
	179636492 Lt245/75r17 Wrangler Sr-a E	4.00
	Tire Disposal Fee	4.00
Hours 11.50	Labor: 690.00	Parts: 1,124.96
:		Total: 1,814.96

Workorder: 1111103 **Meter:** 16728 **In Date:** 10/19/2011 **Closed:** 10/24/2011
Problem: Wipers no clearing windsheild due to overspray.

- Clean off paint over spray from windshield and replace both damage wiper blades with new.	Parts List	Qty
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 0.50	Labor: 30.00	Parts: 9.99
:		Total: 39.99

Workorder: 1200467 **Meter:** 18415 **In Date:** 01/13/2012 **Closed:** 01/25/2012
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Repair right raer tire,rotate and balance all six.	Shop Supplies	1.00
- Shop Supplies	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00
	15/40 Oil	15.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 6.50	Labor: 390.00	Parts: 105.38
:		Total: 495.38

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1212010	Meter: 24460	In Date: 12/12/2012	Closed: 01/11/2013
Problem: Pm service.			
- P.m. Service.	Parts List	Qty	
- Replace three failed led lights in light bar.	15-40 Oil	15.00	
- Replace two tires,rotate and balance all four.	Oil Filter	1.00	
- Test and replace failed blower resistor.	Napagold Fuel Filter	1.00	
- Pressure test and inspect coling system.replace leaking lower radiator hoses.flush and refill cooling system.	31-22 Wiper Blades 22	2.00	
	Used Firex Refurbed F	1.00	
- Complete wheel alignment.test drive.	Pm-22-a Additive Dies	1.00	
- Shop Supplies	179636492 Lt245-75r17	2.00	
	Blower Resistor	1.00	
	lower hose	1.00	
	Radiator Hose	1.00	
	Antifreeze Ext-life	2.00	
	Caster-camber Bushing	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 14.00	Labor: 840.00	Parts: 875.12	Total: 1,715.12
:			
Workorder: 1307169	Meter: 28721	In Date: 07/18/2013	Closed: 07/25/2013
Problem: Right front tire flat.			
- Repair and balance right rear tire.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1307923	Meter: 29183	In Date: 08/08/2013	Closed: 08/27/2013
Problem: P.M. service.			
- P.m. Service.	Parts List	Qty	
- Test batteries and charging system.replace both batteries.	15-40 Oil	15.00	
- Pressure test and inspect cooling system.replace leaking radiator.flush and refill cooling system.	Napagold Oil Filter	1.00	
	Napagold Fuel Filter	1.00	
- Replace missing pintle pin.test and repair ground circuit for rear marker light bar.	31-20 Wiper Blades 20	2.00	
	Battery 65	2.00	
- Rotate and balance all six tires.	Peak Global	3.00	
- Shop Supplies	Pintle Pin W/chain	1.00	
	Radiator	1.00	
	Shop Supplies	1.00	
Hours 13.50	Labor: 810.00	Parts: 1,296.04	Total: 2,106.04
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1405538	Meter: 36760	In Date: 06/05/2014	Closed: 06/17/2014
Problem: P.M. Service.			
- Perform pm service.	Parts List	Qty	
- Install six new tires.nitrogen fill and balance all six.	Stg Wheel Cov - Ford	1.00	
- Perform wheel alignment complete.	15-40 Oil	15.00	
- Test and replace failed third brake lamp bulbs with new.	Napagold Oil Filter	1.00	
- Shop Supplies	Napagold Air Filter	1.00	
	Wiper Blade	2.00	
	Used Fire X Refurbished	1.00	
	Pedal Pad	1.00	
	Fuel Filter Ford Only	1.00	
	Wd40 16oz	1.00	
	Pm-22-a Additive Dies	1.00	
	Tr416 Valve Stem	6.00	
	Lt245 75r17 Hankook Dyn	6.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	6.00	
Hours 9.50	Labor: 570.00	Parts: 1,910.05	Total: 2,480.05
:			
Workorder: 1409030	Meter: 39577	In Date: 09/08/2014	Closed: 09/18/2014
Problem: RPM will not get above 2000rpm.Belt squealing.			
- Computer diagnose check engine light on.codes P1408 and P2263.pinpoint test and replace defective exhaust pressure sensor and Egr valve.clear codes.reprogram Pcm with latest calibration.induction and injectors flush.test drive.	Parts List	Qty	
- Diagnose belt noise.replace defective belt tensioner pulley,both idler pulleys and serpentine belt.	Serpentine Belt	1.00	
- Pm service.	Tensioner-heavy Duty	1.00	
- Rotate and balance all six tires,	Drivealign Pulley	1.00	
- Shop Supplies	B S Pulley	1.00	
	Sensor	1.00	
	Napagold Oil Filter	1.00	
	15-40 Oil	15.00	
	Fuel Filter Ford Only	1.00	
	Bigg Degreaser	1.00	
	Exhaust Valve	1.00	
	Gasket	1.00	
	Shop Supplies	1.00	
Hours 14.50	Labor: 870.00	Parts: 753.61	Total: 1,623.61
:			
Workorder: 1411939	Meter: 41138	In Date: 11/26/2014	Closed: 12/09/2014
Problem: Ac belt and windshield washer failure.			
- Replace defective ac compressor belt and tensioner.replace both broken windshield washer nozzles .	Parts List	Qty	
- Shop Supplies	Serpentine Belt	1.00	
	Tensioner-heavy Duty	1.00	
	Washer Nozzle	2.00	
	Shop Supplies	1.00	
Hours 4.25	Labor: 255.00	Parts: 126.55	Total: 381.55
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1500051	Meter: 41139	In Date: 01/05/2015	Closed: 02/02/2015
Problem: go light install			
- install go light and wiring	Parts List	Qty	
- Shop Supplies	Fuse Holder	1.00	
	U-bolt	2.00	
	Hitch Mount Light Pole	1.00	
	Power Supply Cord	1.00	
	Led Golight	1.00	
	Shop Supplies	1.00	
	Freight Charge	1.00	
Hours 8.50	Labor: 510.00	Parts: 1,159.94	Total: 1,669.94
:			
Workorder: 1504799	Meter: 45424	In Date: 05/12/2015	Closed: 05/20/2015
Problem: P.M. Service.Right front tire leaking.Check turbo operation.			
- Pm service	Parts List	Qty	
- Inspect and replace both defective lower control arm bump stops.	15-40 Oil	15.00	
	Napagold Oil Filter	1.00	
- Inspect and replace both defective front frame rail to radiator support body mounts/insulators.	Wiper Blade	2.00	
	Fuel Filter Ford Only	1.00	
- Replace both defective headlamp sealbeams due to condensation.replace one clearance lamp bulb and one left side reverse Led lamp.	Used Fire X Refurbished	1.00	
	Stg Wheel Cov - Ford	1.00	
- Perform transmission flush and refill with transmission fluid.	Halogen Lamp	2.00	
- Repair one flat right front tire.rotate and balance all six.	Led Back-up Lamp Sys	1.00	
- Shop Supplies	Bulb	1.00	
	Syn-atf Trans Fluid S	20.00	
	bumper	2.00	
	Insulator	2.00	
	Insualtor	2.00	
	Shop Supplies	1.00	
Hours 12.50	Labor: 750.00	Parts: 640.78	Total: 1,390.78
:			
Workorder: 1507196	Meter: 47270	In Date: 07/20/2015	Closed: 09/03/2015
Problem: Check engine light on.No power .Runs ok after shuts down and restart.			
- Diagnose check engine light,no power.p0088.send to dealer for defective high pressure fuel pump.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1512277	Meter: 47975	In Date: 12/04/2015	Closed: 12/21/2015
Problem: Pm service.Has to jump start.			
- Pm service.	Parts List	Qty	
- Test batteries and charging system.both batteries failed loadtest after recharge.replace both defective batteries.	15-40 Oil	15.00	
- Rotate and balance all six tires.	Napagold Oil Filter	1.00	
- Shop Supplies	Fuel Filter Ford Only	1.00	
	Washer Fluid Concentr	1.00	
	Wiper Blade	2.00	
	Battery	2.00	
	Shop Supplies	1.00	
Hours 7.50	Labor: 450.00	Parts: 386.93	Total: 836.93
:			
Workorder: 1512667	Meter: 47838	In Date: 12/15/2015	Closed: 12/17/2015
Problem: Weld door lock			
- weld flat stock to bed and adjust locking pin	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1604247	Meter: 51937	In Date: 04/22/2016	Closed: 05/05/2016
Problem: Lightbar inop,a/c not cold and brakes squeal.			
- A/c system performance test.recover freon,vacuum and recharge system to specs.diagnose and replace defective blower motor and resistor	Parts List	Qty	
- Check light bar,inop.replace shorted fusible link, and repair ground circuit.	Blower Resistor	1.00	
- Resurface rear brake rotors,replace rear pads and calipers.flush and bleed system.test drive.	Fuse Holder	1.00	
- Replace worn out bump stops.	Reman Brake Caliper	1.00	
- Shop Supplies	Reman Brake Caliper	1.00	
	B Fluid Dot 3-32oz	1.00	
	Brake Cleaner	1.00	
	Bumper	2.00	
	Brake Pad	1.00	
	Blwer Mtr Assy Flan	1.00	
	Shop Supplies	1.00	
Hours 11.00	Labor: 660.00	Parts: 446.93	Total: 1,106.93
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1607586	Meter: 54418	In Date: 07/25/2016	Closed: 08/10/2016
Problem: P.M. service and left front tire going flat.			
- P.m. Service.	Parts List	Qty	
- Replace and balance six new tires.	15-40 Oil	14.00	
- Replace right brake lamp.	Napagold Oil Filter	1.00	
- Service and clean induction system and Egr cooler	Fuel Filter Ford Only	1.00	
ports.flush injectors.r&r Dpf and pressure clean.clear	20" Wiper Blade	2.00	
codes.perfor forced regen.	Washer Fluid Concentr	1.00	
- Shop Supplies	Used Fire X Refurbished	1.00	
	179636492 Lt245-75r17	6.00	
	Diesel Egr Induction Service Kit	1.00	
	Kq22932df Diesel Inje	1.00	
	Napagold Air Filter	1.00	
	Led Sup Mdl 44 42 Dio	1.00	
	Exha	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	6.00	
Hours 15.50	Labor: 930.00	Parts: 2,242.85	Total: 3,172.85
:			
Workorder: 1702254	Meter: 60212	In Date: 03/06/2017	Closed: 03/21/2017
Problem: P.M. service.			
- P.m. Service.	Parts List	Qty	
- Replace front brake rotors,calipers and pads.flush and	15-40 Oil	15.00	
bleed system.	Napagold Oil Filter	1.00	
- Replace left side rear marker lamp.	Fuel Filter Ford Only	1.00	
- Replace missing pintle pin.	Seal Kit	1.00	
- Replace and rewire corroded trailer plug.	Used Fire X Refurbished	1.00	
- Rotate and balance tires.	20" Wiper Blade	2.00	
- Shop Supplies	Brake Caliper	1.00	
	Brake Caliper	1.00	
	brake fluid	2.00	
	Led Sup Mdl 44 42 Dio	1.00	
	Pintle Pin W/clip	1.00	
	trailer plug	1.00	
	Brake Pads	1.00	
	Battery	1.00	
	Caliper Washer	4.00	
	Hub Asy	2.00	
	Seal	2.00	
	Shop Supplies	1.00	
Hours 12.50	Labor: 750.00	Parts: 1,179.91	Total: 1,929.91
:			
Workorder: 1702371	Meter: 59988	In Date: 03/08/2017	Closed: 03/08/2017
Problem: 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706124	Meter: 63578	In Date: 06/21/2017	Closed: 06/30/2017
Problem: Blown fuse			
- Check and replace trailer connector fuses.	Parts List		Qty
	Fmx-30 Fuse		1.00
Hours 0.50	Labor: 30.00	Parts: 4.71	Total: 34.71
:			
Workorder: 1707772	Meter: 64665	In Date: 08/09/2017	Closed: 08/09/2017
Problem: 2 - Key(s) issued			
- 2 - Key(s) issued	Parts List		Qty
	Duplicate Vehicle Keys		2.00
Hours 0.60	Labor: 36.00	Parts: 6.00	Total: 42.00
:			
Workorder: 1710633	Meter: 67014	In Date: 10/27/2017	Closed: 11/09/2017
Problem: PM Service			
- P.m. service.	Parts List		Qty
- Check starting and charging system.batteries failed load	15-40 Oil		15.00
test .replace both batteries with new.	Napagold Oil Filter		1.00
- Replace both failed headlamps.	20" Wiper Blade		2.00
- Rotate and high speed balance all six tires.	Fuel Filter Ford Only		1.00
- Shop Supplies	Used Fire X Refurbished		1.00
	Stg Wheel Cov - Ford		1.00
	Mac Wite Lithium Gres		1.00
	Wd40 Spr		1.00
	Battery		2.00
	Halogen Lamp		2.00
	Shop Supplies		1.00
Hours 8.50	Labor: 510.00	Parts: 472.22	Total: 982.22
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1804585 **Meter:** 71342 **In Date:** 05/02/2018 **Closed:** 05/24/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Check all tires .replace two front tires .rotate and high speed balance all six tires. Nitro fill all.	Washer Fluid Concentr	1.00
- Check front suspension .r&r both front upper and lower ball joints on both sides.	Front Grease Cap	1.00
- Repack both front wheel bearings and replace seals.	Wheel Seal - Front Wheel	2.00
- Inspect and replace worn utility door latch right front .transfer lock cylinder .	15-40 Oil	15.00
- Perform complete front end alignment .install caster /camber adjuster on left front.	Napagold Oil Filter	1.00
- Shop Supplies	Fuel Filter Ford Only	1.00
	20" Wiper Blade	2.00
	Napagold Air Filter	1.00
	179636492 Lt245-75r17	2.00
	Upper Ball Joint	2.00
	Lower Ball Joint	2.00
	Caster-camber Bushing	1.00
	Non-chlor Brake Clnr	1.00
	Cap	1.00
	7940ss Rtry Logo Lkg	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
Hours 18.50	Labor: 1,110.0	Parts: 1,024.70
:	0	Total: 2,134.70

Workorder: 1812787 **Meter:** 74635 **In Date:** 12/17/2018 **Closed:** 12/17/2018
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00	Labor: 134.00	Parts: 0.00	Total: 134.00
:			