

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

**Workorder:** 234667

**Problem:** WASH VEHICLE

Meter Reading: 0	Labor	Parts		
In Date: 02/12/2002	Hours	Description	Quantity	
- Wash Vehicle	2.90			
- Pre-Delivery Inspection				
- Make Duplicate Keys For New Vehicle				
Parts Charge:	0.00	Labor Charge:	145.00	

**Workorder:** 234723

**Problem:** 001 WASH TICKET ISSUED OUT 02/11/02

Meter Reading: 0	Labor	Parts		
In Date: 02/11/2002	Hours	Description	Quantity	
- 001 Wash Ticket Issued Out 02/11/02				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 7.14

**Workorder:** 238026

**Problem:** FLAT TIRE @ TRAFFIC

Meter Reading: 354	Labor	Parts		
In Date: 04/08/2002	Hours	Description	Quantity	
- Travel To And From Vehicle-To Inflate For Return To Tire	1.80	SHOP SUPPLIES	1.00	
- Sho				
- Repair Left Rear Tire				
- R/R, Custom Center Cap				
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	90.00	

**Workorder:** 434990

**Problem:** P.M. SERVICE.

Meter Reading: 5456	Labor	Parts		
In Date: 02/12/2004	Hours	Description	Quantity	
- Pm Service	2.50	51522 WIX / PH59 L/F OIL FILTER	1.00	
- Remove & Secure Bed Liner Tie Downs.		10W30 MOTOR OIL	5.00	
- Shop Supplies		SHOP SUPPLIES	1.00	
Parts Charge:	8.91	Labor Charge:	125.00	

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

<b>Workorder:</b> 457465		<b>Problem:</b> 002 KEYS ISSUED OUT		09/24/04	
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/24/2004		<b>Close Date:</b> 09/24/2004			
		<b>Hours</b>		<b>Description</b>	
				<b>Quantity</b>	
-	002 Keys Issued Out	09/24/04	0.40	DUPLICATE VEHICLE KEYS	2.00
<b>Parts Charge:</b>		6.00	<b>Labor Charge:</b>	20.00	

<b>Workorder:</b> 457561		<b>Problem:</b> WINDSHIELD/MIRROR BROKEN-HURRICANE JEANNE			
<b>Meter Reading:</b> 6309		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/29/2004		<b>Close Date:</b> 09/30/2004			
		<b>Hours</b>		<b>Description</b>	
				<b>Quantity</b>	
-	Set Up Windshield Replace-Hurricane Jean Damage	2.00	L/S MIRR 15106007		1.00
-	Clean Glass And Debre From Vehicle		SHOP SUPPLIES		1.00
-	Shop Supplies				
<b>Parts Charge:</b>		102.81	<b>Labor Charge:</b>	100.00	<b>Commercial Charge:</b> 202.73

<b>Workorder:</b> 459239		<b>Problem:</b> QUALITY CAR REPAIR INC 2972			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/30/2004		<b>Close Date:</b> 10/18/2004			
		<b>Hours</b>		<b>Description</b>	
				<b>Quantity</b>	
-	Quality Car Repair Inc 2972				
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 1,051.68

<b>Workorder:</b> 459380		<b>Problem:</b> P.M.SERVICE,RECALL			
<b>Meter Reading:</b> 7423		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/19/2004		<b>Close Date:</b> 10/20/2004			
		<b>Hours</b>		<b>Description</b>	
				<b>Quantity</b>	
-	Pm Service	3.00	10W30 MOTOR OIL		5.00
-	Transport & Pickup Vehicle At Dealer.(Recall#04007)		SHOP SUPPLIES		1.00
-	Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
<b>Parts Charge:</b>		27.57	<b>Labor Charge:</b>	150.00	

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

Workorder: 535679

Problem: 001 WASH TICKET ISSUED OUT 02/07/05

Meter Reading: 0		Labor	Parts	
In Date: 02/07/2005	Close Date: 02/08/2005	Hours	Description	Quantity
- 001 Wash Ticket Issued Out 02/07/05				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 7.14

Workorder: 558281

Problem: P.M.SERVICE

Meter Reading: 10044		Labor	Parts	
In Date: 11/17/2005	Close Date: 11/23/2005	Hours	Description	Quantity
- Pm Service				
		2.00	10W30 MOTOR OIL	5.00
- Shop Supplies				
			1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
			6678 AIR FILTER FRM CA8755A WIX 46678	1.00
			3481 FUEL FILTER FRM G3727 WIX 33481	1.00
			SHOP SUPPLIES	1.00
Parts Charge: 29.32		Labor Charge: 100.00		

Workorder: 734655

Problem: P.M SERVICE

Meter Reading: 12619		Labor	Parts	
In Date: 02/23/2007	Close Date: 02/27/2007	Hours	Description	Quantity
- Performed Pm Service Complete And Also Replace Fuel				
		4.00	10W30 MOTOR OIL	6.00
			GROUP 78 BATTERY (ACD 78PS)	1.00
Filter And Wiper Blades.				
			SHOP SUPPLIES	1.00
- Tested Charging Sys And Replaced Battery With New.				
			3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Performed Bitrogen Fill On All 4 Tires.				
			31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies				
			1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
Parts Charge: 124.36		Labor Charge: 55.00		

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

Workorder: 832646

Problem: P.M SERVICE

Meter Reading: 14340	Labor	Parts	
In Date: 01/10/2008	Hours	Description	Quantity
- Pm Service	4.00	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Battery Failed Load Test.Replace & Retest Ok		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Rotate Tires & Balance 4 Tires.		GROUP 78 BATTERY (ACD 78PS)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
		10W30 MOTOR OIL	6.00
		10020 INJECTOR CLEANER DON'T REORDER	1.00
Parts Charge:	170.30	Labor Charge:	60.00

Workorder: 844192

Problem: P.M. SERVICE.CLUNK IN STEERING.

Meter Reading: 15416	Labor	Parts	
In Date: 09/15/2008	Hours	Description	Quantity
- Pm Service	9.80	ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	2.00
- Pressure Test & Inspect Coolant System.Flush & Refill		MIDDLE STEERING SHAFT	1.00
- Coolant System.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Test & Inspect Steering System For Noise.Noise Coming		FT1217 TRANS FILTER ATP B-165 WIX DON'T USE	1.00
- From Steering Shaft Assembly.R&R Mid Steering		SYN/ATF TRANS FLUID SYNTHETIC	16.00
- Shaft.Retest, Ok.		SHOP SUPPLIES	1.00
- Service Trans,Flush & Refill And Replaced Trans Filter.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- R&R Front & Rear Faded Asset Numbers.		10W30 MOTOR OIL	5.00
- Rotate & High Speed Balance 4 Tires.Nitro Fill All Tires To		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Spec.		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Shop Supplies			
Parts Charge:	254.54	Labor Charge:	48.00

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

Workorder: 936907

Problem: P.M SERVICE

Meter Reading: 17444		Labor	Parts	
In Date: 04/23/2009	Close Date: 04/27/2009	Hours	Description	Quantity
- Pm Service		7.50	10W30 MOTOR OIL	6.00
- Battery Failed Load Test.Ck Electrical Sys. Charge Rate			1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- At Spec.No Excessive Draw.Replace Defective Battery.			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Tires Dry Rotted.Repl 4 Tires.Hi Speed Bal.Measure Rd			GROUP 78 BATTERY (ACD 78PS)	1.00
- Force.Match Mount 2 Tires To Reduce Vibration.Fill			TIRE DISPOSAL FEE	4.00
- W/Nitrogen.			183680418 P235/75R16 WRANGLER SR-A 109S	4.00
- Perform Complete Wheel Alignment.Test Drive.			SHOP SUPPLIES	1.00
- Shop Supplies				
Parts Charge: 674.13		Labor Charge: 450.00		

Workorder: 947121

Problem: PM SERVICE

Meter Reading: 21218		Labor	Parts	
In Date: 12/16/2009	Close Date: 01/06/2010	Hours	Description	Quantity
- P.M Service.		7.00	REAR BRAKE PAD SET	1.00
- Machine Both Rear Brake Rotors, Install New Pads &			SHOP SUPPLIES	1.00
- Caliper Assemblies, Flush & Bleed System, Test Drive.			REAR BRAKE CALIPER	1.00
- Rotate & Balance All Four Tires.			09997 BRAKE CLEAN	1.00
- Shop Supplies			31-22 WIPER BLADES 22" WIPER BLADE	2.00
			3481 FUEL FILTER FRM G3727 WIX 33481	1.00
			10W30 MOTOR OIL	6.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
			1401 BRAKE FLUID BRAKE FLUID	1.00
			6678 AIR FILTER FRM CA8755A WIX 46678	1.00
			REAR BRAKE CALIPER	1.00
Parts Charge: 510.08		Labor Charge: 840.00		

Workorder: 1006491

Problem: Right rear tire flat.

Meter Reading: 23164		Labor	Parts	
In Date: 06/21/2010	Close Date: 06/22/2010	Hours	Description	Quantity
- Repair And Balance Right Rear Tire.		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00		

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

**Workorder:** 1008229

**Problem:** P.M. service

<b>Meter Reading: 23930</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/03/2010	<b>Close Date:</b> 08/12/2010	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Perform Pm Service.	<b>3.00</b>	USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Rotate And Balance All Four Tires.		10W30 MOTOR OIL		6.00
-	Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		44.47	<b>Labor Charge:</b>	180.00	

**Workorder:** 1103480

**Problem:** Pm service.

<b>Meter Reading: 26013</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/31/2011	<b>Close Date:</b> 04/07/2011	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Perform Pm Service.	<b>3.00</b>	SHOP SUPPLIES		1.00
-	Rotate And Balance All Four Tires.		10W30 MOTOR OIL		6.00
-	Shop Supplies		31-22 WIPER BLADES 22" WIPER BLADE		2.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
<b>Parts Charge:</b>		26.00	<b>Labor Charge:</b>	180.00	

**Workorder:** 1111843

**Problem:** Pm service

<b>Meter Reading: 28209</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 11/03/2011	<b>Close Date:</b> 11/14/2011	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	P.M. Service.	<b>3.00</b>	USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Rotate And Balance All Tires.		SHOP SUPPLIES		1.00
-	Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			10W30 MOTOR OIL		6.00
<b>Parts Charge:</b>		42.91	<b>Labor Charge:</b>	180.00	

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

**Workorder:** 1206927

**Problem:** P.M. Service.

<b>Meter Reading: 30354</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/25/2012</b>	<b>Close Date: 08/15/2012</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	P.M. Service.	<b>5.50</b>	10W30 MOTOR OIL		6.00
-	Test Battery And Charging System.Replace Bad Battery.		1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
-	Replace Left Front Strobe Bulb.		SHOP SUPPLIES		1.00
-	Replace Leaking Washer Reservoir.		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Rotate And Balance All Tires.		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Shop Supplies		GROUP 78 BATTERY (ACD 78PS)		1.00
			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
			S30HACP STROBE BULB FOR KIT S660CCCC		1.00
			W/WASHER FLUID RESERVOIR		1.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
<b>Parts Charge:</b>		256.81	<b>Labor Charge:</b>	330.00	

**Workorder:** 1303746

**Problem:** Pm service.

<b>Meter Reading: 34383</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 04/16/2013</b>	<b>Close Date: 04/23/2013</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Perform Pm Service.	<b>3.00</b>	USED FIREX REFURBED F		1.00
-	Rotate And Balance All Four Tires.		NAPAGOLD OIL FILTER		1.00
-	Shop Supplies		WASHER FLUID CONCENTR		1.00
			10W30 MOTOR OIL		6.00
			31-22 WIPER BLADES 22		2.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		48.98	<b>Labor Charge:</b>	180.00	

**Workorder:** 1307003

**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

<b>Meter Reading: 89419</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/12/2013</b>	<b>Close Date: 07/12/2013</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	1 - Detail Vehicle Wash Ticket(S) Issued				
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 97.92

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

Workorder: 1402514

Problem: P.M.SERVICE

Meter Reading: 42020		Labor	Parts	
In Date: 03/14/2014	Close Date: 03/24/2014	Hours	Description	Quantity
- Pm		2.00	NAPAGOLD OIL FILTER	1.00
			10W30 BULK SR	6.00
			WASHER FL	1.00
			NAPAGOLD FUEL FILTER	1.00
Parts Charge: 30.78		Labor Charge: 120.00		

Workorder: 1409110

Problem: pm, broken tail light

Meter Reading: 44429		Labor	Parts	
In Date: 09/10/2014	Close Date: 09/22/2014	Hours	Description	Quantity
- Pm		7.50	183680418 P235-75R16	4.00
- Verify Needs Tires Mount Balance Add N2 4 New Tires			DISC BRAKE PADS	1.00
- Verify Needs Front Brakes And Rotors Out Of Spec Rr			REPLACEMENT LAMP	1.00
Front Pads Rotors Svc Calipers			BRAKE ROTOR	2.00
- Ck Tail Light Rr Right Rear Tail Light Assm			NAPAGOLD OIL FILTER	1.00
			10W30 BULK SR	6.00
			WIPER BLADE	2.00
			TIRE DISPOSAL FEE	4.00
Parts Charge: 1,074.33		Labor Charge: 450.00		

Workorder: 1505044

Problem: PM

Meter Reading: 48629		Labor	Parts	
In Date: 05/19/2015	Close Date: 05/26/2015	Hours	Description	Quantity
- Pm		3.00	NAPAGOLD OIL FILTER	1.00
- Install Right Rear Strobe Light			HIDE AWAY STROB	1.00
			10W30 BULK SR	6.00
			WASHER FL	1.00
			NAPAGOLD FUEL FILTER	1.00
			WIPER BLADE	2.00
			NAPAGOLD AIR FILTER	1.00
			USED FIRE X REFURBISHED	1.00
Parts Charge: 116.67		Labor Charge: 180.00		



1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

<b>Workorder:</b> 1507932		<b>Problem:</b> TOW IN, DEAD BATTERY			
<b>Meter Reading:</b> 49791		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/07/2015	<b>Close Date:</b> 08/11/2015	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Replace Bad Battery		<b>0.75</b>	BATTERY		1.00
<b>Parts Charge:</b> 103.65		<b>Labor Charge:</b> 45.00			

<b>Workorder:</b> 1508015		<b>Problem:</b> dead battery sr our loaner			
<b>Meter Reading:</b> 49791		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/07/2015	<b>Close Date:</b> 08/11/2015	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Tow From: 21258 Via Eden Boca Rio To: Sr Delray					
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 104.15		

<b>Workorder:</b> 1512333		<b>Problem:</b> pm			
<b>Meter Reading:</b> 52096		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/07/2015	<b>Close Date:</b> 12/17/2015	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm		<b>2.00</b>	10W30 BULK SR		6.00
			NAPAGOLD OIL FILTER		1.00
			WASHER FLUID CONCENTR		1.00
			WIPER BLADE		2.00
<b>Parts Charge:</b> 33.31		<b>Labor Charge:</b> 120.00			

<b>Workorder:</b> 1606544		<b>Problem:</b> Pm service			
<b>Meter Reading:</b> 55583		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/28/2016	<b>Close Date:</b> 06/29/2016	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm Service.		<b>3.25</b>	NAPAGOLD OIL FILTER		1.00
- Replace Right Rear Brake Light Bulb.			10W30 BULK SR		6.00
- Rotate And Balance All Four Tires.			BULB		1.00
			22" WIPER BLADE		2.00
			NAPAGOLD FUEL FILTER		1.00
<b>Parts Charge:</b> 36.45		<b>Labor Charge:</b> 195.00			

1/3/2017  
12:14:31PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139350 2002 GMC 1500 Pickup, 1/2 Ton, W/Strobe System

Workorder: 1611514

Problem: Transition Prep Charge

Meter Reading: 57344

Labor

Parts

In Date: 11/08/2016

Close Date: 11/08/2016

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: 3,726.38

Total Labor Charges: 4,403.00

Total Comm. Charges: 1,470.76