

**Palm Beach County Fleet Management
Asset Maintenance History**

10201376 2016 POLARIS SPORTSMAN 450 Atv, 4X4

Workorder: 1603811 **Meter:** 1 **In Date:** 04/12/2016 **Closed:** 04/20/2016
Problem: undercoat frame

- Under coat frame	Parts List	Qty
- Shop Supplies	Rubberized Undercoat	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 9.59
:		Total: 69.59

Workorder: 1603849 **Meter:** 1 **In Date:** 04/12/2016 **Closed:** 04/12/2016
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection	Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
	:			

Workorder: 1613195 **Meter:** 48 **In Date:** 12/29/2016 **Closed:** 01/12/2017
Problem: pm service

- Pm	Parts List	Qty
- Frt differential service	Napagold Oil Filter	1.00
- Wash and undercoat frame	Qt 5w50 Edge W Syn	2.00
- Shop Supplies	Demand Hub Drive Fluid	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 47.96
:		Total: 407.96

Workorder: 1706162 **Meter:** 71 **In Date:** 06/21/2017 **Closed:** 06/29/2017
Problem: pm/ starting issues/ see notes

- Pm	Parts List	Qty
- Service frt Diff	Napagold Oil Filter	1.00
- Ck for intermittent no start-r&r front facial to gain access to wiring and clean cable connections at front of Atv, battery and ign. switch and replaced starter solenoid	Qt 5w50 Edge W Syn	2.00
	Spark Plug Mr7f	1.00
- Shop Supplies	Demand Hub Drive Fluid	1.00
	Starter Solenoid	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 131.62
:		Total: 611.62

Workorder: 1706636 **Meter:** 73 **In Date:** 07/06/2017 **Closed:** 07/24/2017
Problem: intermitent no start

- trace problem to corroded ignition and brake switch. replace both and test run	Parts List	Qty
- Shop Supplies	Key Switch	1.00
	Brake Light Switch	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 183.08
:		Total: 363.08

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1710059	Meter: 73	In Date: 10/13/2017	Closed: 10/27/2017
Problem: no start/ battery wont hold a charge/ see notes			
- Check charging sys replae battery and clean battery terminals	Parts List		Qty
	Cb14aa2 Battery		1.00
- Repair intake hose leak	Shop Supplies		1.00
- Make and apply new asset numbers decals to front of Atv			
- Shop Supplies			
Hours 2.50	Labor: 150.00	Parts: 71.09	Total: 221.09
:			
Workorder: 1711138	Meter: 86	In Date: 11/09/2017	Closed: 11/20/2017
Problem: will not start			
- diagnose will not start found code 10210 Map sensor below normal or shorted to low sourche replace map sensor	Parts List		Qty
	Spark Plug Mr7f		1.00
- Check fuel pump pressure pressure below spc remov plastics and replace fuel pump assembly	Qd Electronic Cleaner		1.00
	Tmap Sensor		1.00
- Shop Supplies	Fuel Pump Kit		1.00
	Fuel Pump Kit		1.00
	Shop Supplies		1.00
Hours 4.50	Labor: 270.00	Parts: 1,278.08	Total: 1,548.08
:			
Workorder: 1800559	Meter: 91	In Date: 01/17/2018	Closed: 02/21/2018
Problem: pm service			
- Pm	Parts List		Qty
- Service frt diff	Napagold Oil Filter		1.00
- Replace l/outer Cv Boot	Qt 5w50 Edge W Syn		2.00
- Shop Supplies	Spark Plug Mr7f		1.00
	Demand Hub Drive Fluid		1.00
	Outer Boot Kit		1.00
	Shop Supplies		1.00
Hours 6.50	Labor: 390.00	Parts: 114.19	Total: 504.19
:			
Workorder: 1802329	Meter: 97	In Date: 03/01/2018	Closed: 03/08/2018
Problem: cranks but wont start			
- clean contaminated fuel from system	Parts List		Qty
- charge and test battery. replace battery	Startron 8oz Fuel Trt		1.00
- Shop Supplies	Battery M C Specialty		1.00
	Shop Supplies		1.00
Hours 3.00	Labor: 180.00	Parts: 77.42	Total: 257.42
:			
Workorder: 1805114	Meter: 101	In Date: 05/17/2018	Closed: 05/25/2018
Problem: wont start/ stuck in gear			
- check charging system and replace defective battery	Parts List		Qty
- lube and adjust shifter	Battery M C Specialty		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 1.50	Labor: 90.00	Parts: 67.99	Total: 157.99
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808713 **Meter:** 112 **In Date:** 08/23/2018 **Closed:** 08/29/2018
Problem: pm service

- pm service	Parts List	Qty
- clean and apply under coating	Napagold Oil Filter	1.00
- replace exhaust springs, fab and weld exhaust hanger	Qt 5w50 Edge W Syn	2.00
- Shop Supplies	Non-chlor Brake Clnr	2.00
	Rubberized Undercoat	1.00
	Spring	2.00
	Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 48.74
:		Total: 438.74

Workorder: 1810731 **Meter:** 133 **In Date:** 10/18/2018 **Closed:** 11/13/2018
Problem: someone filled with diesel fuel

- replace front calipers, pads, resurface rotors, bleed system	Parts List	Qty
- test and replace battery	Rh Brake Calipers W/pads	1.00
- drain diesel from tank, add fresh gas. diagnose no start,	Lh Brake Caliper W/pads	1.00
clean fuse relay panel	Brk Fluid Dot 4-12oz	1.00
- Shop Supplies	Battery M C Specialty	1.00
	Spark Plug Mr7f	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 469.00	Parts: 769.25
:		Total: 1,238.25

Workorder: 1900705 **Meter:** 133 **In Date:** 01/17/2019 **Closed:** 01/17/2019
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 134.00	Parts: 0.00
:		Total: 134.00