

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10195225    2014 FORD ESCAPE Suv, Mid Size**

**Workorder:** 1403550    **Meter:** 189    **In Date:** 04/11/2014    **Closed:** 04/11/2014  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00                      Labor: 120.00              Parts: 0.00              Total: 120.00  
 :

**Workorder:** 1407016    **Meter:** 3426    **In Date:** 07/16/2014    **Closed:** 07/16/2014  
**Problem:** 2 - Wash ticket(s) issued

- 2 - Wash ticket(s) issued

Hours 0.00                      Labor: 0.00              Parts: 0.00              Total: 0.00  
 :

**Workorder:** 1407647    **Meter:** 4446    **In Date:** 08/04/2014    **Closed:** 08/11/2014  
**Problem:** Left front tire flat,bent rim.

- Install new tire and replace bent wheel and tire pressure sensor.retrain all tire pressure sensors.  
 - Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Wheel Assembly	1.00
P235/55r17 Cont. Tire	1.00
Tpms12 Sensor Tire Pr	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours 1.25                      Labor: 75.00              Parts: 550.05              Total: 625.05  
 :

**Workorder:** 1407865    **Meter:** 4446    **In Date:** 08/04/2014    **Closed:** 08/11/2014  
**Problem:** flat tire service

- Tire Service Vista - flat tire service

Hours 0.00                      Labor: 0.00              Parts: 0.00              Total: 0.00  
 :

**Workorder:** 1408501    **Meter:** 5496    **In Date:** 08/26/2014    **Closed:** 09/08/2014  
**Problem:** Pm service.

- Pm service.  
 - Rotate and balance all four tires.  
 - Perform complete wheel alignment.adjust angles due to prior bent wheel..test drive.  
 - Shop Supplies

<b>Parts List</b>	<b>Qty</b>
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer FI	1.00
Shop Supplies	1.00

Hours 5.50                      Labor: 330.00              Parts: 23.09              Total: 353.09  
 :

**Workorder:** 1409140    **Meter:** 5769    **In Date:** 09/11/2014    **Closed:** 09/15/2014  
**Problem:** Left front tire flat.

- Repair and balance left front tire.  
 - Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00

Hours 1.00                      Labor: 60.00              Parts: 2.00              Total: 62.00  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1409921      **Meter:** 6500      **In Date:** 10/02/2014      **Closed:** 10/03/2014  
**Problem:** Left rear tire flat,

- Repair and balance flat left rear tire.      **Parts List**      **Qty**  
- Shop Supplies      Shop Supplies      1.00

Hours 1.00      Labor: 60.00      Parts: 2.00      Total: 62.00  
:

---

**Workorder:** 1411262      **Meter:** 8471      **In Date:** 11/12/2014      **Closed:** 11/18/2014  
**Problem:** Right rear tire giong flat.

- Replace and balance all four tires      **Parts List**      **Qty**  
- Complete alignment to prevent tire wear.test drive.      P235 55r17 Fuel Max      4.00  
- Shop Supplies      Shop Supplies      1.00  
Tire Disposal Fee      4.00

Hours 4.50      Labor: 270.00      Parts: 826.00      Total: 1,096.00  
:

---

**Workorder:** 1412876      **Meter:** 10573      **In Date:** 12/30/2014      **Closed:** 01/13/2015  
**Problem:** Pm service.

- Pm service.      **Parts List**      **Qty**  
- Rotate and balance all four tires.      Napagold Oil Filter      1.00  
- Shop Supplies      5w20 Engine Oil      6.00  
Mac Wite Lithium Gres      1.00  
Shop Supplies      1.00

Hours 3.00      Labor: 180.00      Parts: 26.14      Total: 206.14  
:

---

**Workorder:** 1500036      **Meter:** 10329      **In Date:** 01/02/2015      **Closed:** 01/02/2015  
**Problem:** 2 - Wash ticket(s) issued

- 2 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1501500      **Meter:** 12015      **In Date:** 02/10/2015      **Closed:** 02/27/2015  
**Problem:** Right front tire flat.

- Repair and balance one flat tire.      **Parts List**      **Qty**  
- Test starting and charging system.battery faild loadtest after recharge.replace defective battery.      Sensor      1.00  
Bxt96r 59      1.00  
- Computer diagnose for outside ambient temperature reading -40 degrees fahrenheit..code P0073.test and replace defective ambient temperature sensor.      Shop Supplies      1.00

- Transport vehicle to and from dealer for safety recall #14s03 and defective climate control head.  
- Shop Supplies

Hours 6.00      Labor: 360.00      Parts: 156.38      Total: 516.38  
:

---

**Workorder:** 1502288      **Meter:** 12367      **In Date:** 03/03/2015      **Closed:** 03/09/2015  
**Problem:** Right front tire flat.

- Repair and balance right front tire.      **Parts List**      **Qty**  
- Shop Supplies      Shop Supplies      1.00

Hours 1.00      Labor: 60.00      Parts: 2.00      Total: 62.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1502585      **Meter:** 12689      **In Date:** 03/12/2015      **Closed:** 03/16/2015  
**Problem:** Left front tire flat.

- Replace and balance one tire.      **Parts List**      **Qty**  
- Shop Supplies      P235 55r17 Fuel Max      1.00  
Shop Supplies      1.00  
Tire Disposal Fee      1.00

Hours 0.50      Labor: 30.00      Parts: 208.00      Total: 238.00  
:

---

**Workorder:** 1504201      **Meter:** 14625      **In Date:** 04/23/2015      **Closed:** 05/07/2015  
**Problem:** Pm service.Left ac vent air flow inop.

- Pm service.      **Parts List**      **Qty**  
- Replace three tires.rotate and balance all four.      5w20 Engine Oil      6.00  
- Transport vehicle to and from dealer for replacing defective left side ac vent.      Napagold Oil Filter      1.00  
Bulb      2.00  
- Shop Supplies      P235 55r17 Fuel Max      2.00  
P235 55r17 Fuel Max      1.00  
Shop Supplies      1.00  
Tire Disposal Fee      3.00

Hours 6.00      Labor: 360.00      Parts: 639.62      Total: 999.62  
:

---

**Workorder:** 1506041      **Meter:** 16449      **In Date:** 06/17/2015      **Closed:** 06/18/2015  
**Problem:** Both rear tires going flat.

- Repair and balance both rear tires.      **Parts List**      **Qty**  
- Shop Supplies      Shop Supplies      1.00

Hours 2.00      Labor: 120.00      Parts: 2.00      Total: 122.00  
:

---

**Workorder:** 1506728      **Meter:** 17578      **In Date:** 07/07/2015      **Closed:** 07/09/2015  
**Problem:** Right headlamp inop.

- Test and replace defective right headlamp bulb.      **Parts List**      **Qty**  
- Shop Supplies      Low Bulb      1.00  
Shop Supplies      1.00

Hours 0.50      Labor: 30.00      Parts: 34.96      Total: 64.96  
:

---

**Workorder:** 1507274      **Meter:** 18307      **In Date:** 07/22/2015      **Closed:** 07/27/2015  
**Problem:** Left headlight inop and right tag light inop.

- Test and replace defective left headlamp bulb and right tag lamp bulb      **Parts List**      **Qty**  
Low Bulb      1.00  
- Shop Supplies      Bulb      1.00  
Shop Supplies      1.00

Hours 0.75      Labor: 45.00      Parts: 35.33      Total: 80.33  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1508407	<b>Meter:</b> 19978	<b>In Date:</b> 08/21/2015	<b>Closed:</b> 08/31/2015
<b>Problem:</b> Pm service.Check tires.			
- Pm service.	<b>Parts List</b>		<b>Qty</b>
- Replace two tires.rotate and balance all four.	Napagold Oil Filter		1.00
- Complete alignment.test drive.	5w20 Engine Oil		6.00
- Shop Supplies	Accufit Beam		2.00
	235/55r17 Assurance		2.00
	Blade		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 6.50	Labor: 390.00	Parts: 360.39	Total: 750.39
:			
<b>Workorder:</b> 1509319	<b>Meter:</b> 21522	<b>In Date:</b> 09/16/2015	<b>Closed:</b> 09/28/2015
<b>Problem:</b> Right front tire flat.			
- Repair and balance right front and right rear tires.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
<b>Workorder:</b> 1509840	<b>Meter:</b> 21618	<b>In Date:</b> 09/29/2015	<b>Closed:</b> 09/30/2015
<b>Problem:</b> Right front tire flat.			
- Replace and balance damage right front tire.tire pressure sensor and bent wheel	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	235/55r17 Assurance		1.00
	Wheel Assembly		1.00
	Tpms Kit		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		1.00
Hours 1.00	Labor: 60.00	Parts: 507.84	Total: 567.84
:			
<b>Workorder:</b> 1511512	<b>Meter:</b> 24209	<b>In Date:</b> 11/10/2015	<b>Closed:</b> 11/12/2015
<b>Problem:</b> Left front and right rear tires flat.			
- Replace and balance all four tires.	<b>Parts List</b>		<b>Qty</b>
- Complete alignment .	235/55r17 Assurance		4.00
- Shop Supplies	Shop Supplies		1.00
	Tire Disposal Fee		4.00
Hours 4.50	Labor: 270.00	Parts: 579.58	Total: 849.58
:			
<b>Workorder:</b> 1511862	<b>Meter:</b> 25071	<b>In Date:</b> 11/20/2015	<b>Closed:</b> 12/09/2015
<b>Problem:</b> P.M. service.			
- Pm service.	<b>Parts List</b>		<b>Qty</b>
- Rotate and balance all four tires.	5w20 Engine Oil		6.00
- Shop Supplies	Napagold Oil Filter		1.00
	Shop Supplies		1.00
Hours 3.00	Labor: 180.00	Parts: 20.87	Total: 200.87
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1600363      **Meter:** 27582      **In Date:** 01/12/2016      **Closed:** 01/20/2016  
**Problem:** Left rear tire flat.

- Repair and balance left rear tire.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Workorder:** 1600656      **Meter:** 28008      **In Date:** 01/21/2016      **Closed:** 01/27/2016  
**Problem:** Tire pressure light on .right rear tire going flat.

- Repair and balance right rear tire.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Workorder:** 1600657      **Meter:** 28525      **In Date:** 01/21/2016      **Closed:**  
**Problem:** Tire pressure light on .right rear tire going flat.

-			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1601210      **Meter:** 28794      **In Date:** 02/04/2016      **Closed:** 02/11/2016  
**Problem:** Right front tire flat.

- Repair and balance right front tire.		<b>Parts List</b>	<b>Qty</b>
- Recharge and test battery,failed load test.replace defective battery.		Bxt96r 59	1.00
- Shop Supplies		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 148.34	Total: 268.34
:			

**Workorder:** 1601409      **Meter:** 28720      **In Date:** 02/06/2016      **Closed:** 02/10/2016  
**Problem:** on site move

- Tow From: fleet yard To: fleet shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1601817      **Meter:** 29439      **In Date:** 02/22/2016      **Closed:** 02/22/2016  
**Problem:** 4 - Wash ticket(s) issued

- 4 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1601958	<b>Meter:</b> 29641	<b>In Date:</b> 02/25/2016	<b>Closed:</b> 03/17/2016
<b>Problem:</b> Pm service.Driver seat fabric need repair.			
- Pm service.	<b>Parts List</b>		<b>Qty</b>
- Replace two front tires.replace bent left front wheel.rotate and balance all four.	Seat R And R		1.00
- Inspect and R&i driver seat for repairs.fabric worn out.	5w20 Engine Oil		12.00
- Perform complete front end alignment.	Napagold Oil Filter		2.00
- Shop Supplies	Accufit Beam		4.00
	Blade		2.00
	Washer Fluid Concentr		2.00
	Silicone Spray 10oz		2.00
	235/55r17 Assurance		4.00
	Wheel Assembly		2.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 7.50	Labor: 450.00	Parts: 1,572.99	Total: 2,022.99
:			
<b>Workorder:</b> 1603588	<b>Meter:</b> 29967	<b>In Date:</b> 03/11/2016	<b>Closed:</b> 04/05/2016
<b>Problem:</b> damage to lft frt fender & bumper			
- damage to lft frt fender & bumper			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1604578	<b>Meter:</b> 31383	<b>In Date:</b> 05/02/2016	<b>Closed:</b> 05/05/2016
<b>Problem:</b> Right headlight inop and left front tire going flat.			
- Replace right headlamp bulb.replace marker lamp bulbs.	<b>Parts List</b>		<b>Qty</b>
- Repair and balance left front tire.	Low Bulb		1.00
- Shop Supplies	Bulb		2.00
	Shop Supplies		1.00
Hours 2.50	Labor: 150.00	Parts: 35.77	Total: 185.77
:			
<b>Workorder:</b> 1605666	<b>Meter:</b> 33092	<b>In Date:</b> 06/02/2016	<b>Closed:</b> 06/15/2016
<b>Problem:</b> Tire pressure light on and clicking when backing or turning and tag light out.			
- Replace and balance two rear tires.	<b>Parts List</b>		<b>Qty</b>
- Replace tag lamp.	Bulb		1.00
- Transport vehicle to dealer for noisy left axle when turning.	235/55r17 Assurance		2.00
- Shop Supplies	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 3.25	Labor: 195.00	Parts: 291.20	Total: 486.20
:			
<b>Workorder:</b> 1606383	<b>Meter:</b> 34447	<b>In Date:</b> 06/23/2016	<b>Closed:</b> 07/07/2016
<b>Problem:</b> Screw in left front tire.			
- Repair and balance left front tire.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1607485      **Meter:** 37769      **In Date:** 07/22/2016      **Closed:** 09/29/2016  
**Problem:** P.M. service and tire pressure light on and check lights.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Replace two tires,rotate and balance all four.	5w20 Engine Oil	6.00
- Replace left tail light bulb.	Napagold Oil Filter	1.00
- Replace left headlight bulb.	Accufit Beam	2.00
- Transport vehicle to dealer for oil leak.(front cover)	Wpr/blde	1.00
- Replace right front tire.reopair left front.	Washer Fluid Concentr	1.00
- Shop Supplies	Bulb	2.00
	235/55r17 Assurance	2.00
	Low Bulb	1.00
	235/55r17 Assurance	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	3.00
Hours 8.50	Labor: 510.00	Parts: 529.51
:		Total: 1,039.51

**Workorder:** 1609548      **Meter:** 37652      **In Date:** 09/14/2016      **Closed:** 09/27/2016  
**Problem:** Right rear tire going flat.

- Repair and balance right rear tire.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Workorder:** 1610253      **Meter:** 38472      **In Date:** 09/30/2016      **Closed:** 10/12/2016  
**Problem:** Right brake light inop.

- Replace right brake lamp bulb.	<b>Parts List</b>	<b>Qty</b>
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.78
:		Total: 30.78

**Workorder:** 1610654      **Meter:** 39240      **In Date:** 10/17/2016      **Closed:** 10/31/2016  
**Problem:** Left front tire flat.

- Repair and balance left front and right rear tires.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

**Workorder:** 1612426      **Meter:** 41679      **In Date:** 12/05/2016      **Closed:** 01/03/2017  
**Problem:** Left rear tire flat and left front falling in.

- Replace and balance four new tires.	<b>Parts List</b>	<b>Qty</b>
- Complete wheel alignment.test drive.	235/55r17 Assurance	4.00
- Diassemble left front seat and replace boken seat frame.install floor mats.	Tire Pressure Monitoring System Sensor (	4.00
	Trackasy	1.00
- Repair and balance right front tire.	Floor Mat-2pc Rub Bk	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.50	Labor: 510.00	Parts: 1,445.44
:		Total: 1,955.44

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1701148      **Meter:** 44068      **In Date:** 02/02/2017      **Closed:** 03/06/2017  
**Problem:** P.M. service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.	Rad Cap	1.00
- Pressure test and inspect cooling system.replace leaking heater hose and recovery tank.flush and refill system.	Tank Asy	1.00
- Repair right rear tire,rotate and balance all four.	Lug Nut	1.00
- Shop Supplies	5w20 Engine Oil	6.00
	Napagold Oil Filter	1.00
	Napa Cabin Air Filter	1.00
	Washer Fluid Concentr	1.00
	Wiper Blade	1.00
	Wiper Blade	1.00
	Wpr/blde	1.00
	Mac Wite Lithium Gres	1.00
	Stg Wheel Cov - Ford	1.00
	Battery	1.00
	Anti Freeze Motorcraft	2.00
	Hose	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 431.02
:		Total: 911.02

**Workorder:** 1702278      **Meter:** 44723      **In Date:** 03/07/2017      **Closed:** 03/20/2017  
**Problem:** Left front tire flat spare on vehicle.

- Repair and balance left front tire.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Workorder:** 1702356      **Meter:** 44171      **In Date:** 03/08/2017      **Closed:** 03/08/2017  
**Problem:** Flat tire

- Tow From: Vista			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1703924      **Meter:** 46893      **In Date:** 04/19/2017      **Closed:** 04/28/2017  
**Problem:** Check tires for nails.

- Replace two front tires.repair left rear tire .road force balance all tires and reinstall on vehicle.	<b>Parts List</b>	<b>Qty</b>
- Repair one tire and balance .mount on left front .nitrogen fill tires.	235/55r17 Assurance	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 3.00	Labor: 180.00	Parts: 321.78
:		Total: 501.78



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1704801      **Meter:** 47896      **In Date:** 05/15/2017      **Closed:** 05/22/2017  
**Problem:** Headlight inop.P.M. service.

- Test and replace right side low beam bulb and retest.	<b>Parts List</b>	<b>Qty</b>
- P.m. service.	Shaft Assy Motorcraft	1.00
- Check ,resurface two front rotors and replace pads.service calipers and bleed the brakes.	Housing	1.00
	Housing	1.00
- Replace two tires on front.balance and rotate all four tires.	Halogen Bulb	1.00
- Road test for noise from drive axle when turning.found noise noticable from right side.replace defective right front axle assembly .test drive.	5w20 Engine Oil	6.00
	Napagold Oil Filter	1.00
- Replace one defective lower engine mount and defective transmission mount.replace air tube from air box due to missing strap.	Accufit Beam	2.00
	Brake Pad	1.00
- Complete alignment and road test.	235/55r17 Assurance	2.00
- Shop Supplies	Tube Air	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 15.50	Labor: 930.00	Parts: 920.64
:		Total: 1,850.64

**Workorder:** 1705799      **Meter:** 49018      **In Date:** 06/12/2017      **Closed:** 06/15/2017  
**Problem:** Install fire extinguisher.

- Fabricate and install fire extinguisher and bracket.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Used Fire X Refurbished	1.00
	Custom Bracket Fire Ex	1.00
	Shop Supplies	1.00
Hours 0.50	Labor: 30.00	Parts: 36.70
:		Total: 66.70

**Workorder:** 1706848      **Meter:** 50599      **In Date:** 07/13/2017      **Closed:** 07/17/2017  
**Problem:** Right brake light inop.

- Diagnose right brake light.r&r right tail lamp assembly.due to melted socket mount.retest.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Right Real Lamp. Asy	1.00
	Shop Supplies	1.00
Hours 0.50	Labor: 30.00	Parts: 225.50
:		Total: 255.50

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1707233      **Meter:** 51091      **In Date:** 07/24/2017      **Closed:** 08/03/2017  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Found coolant leak at recovery tank.replaced overflow hose from radiator and thermostat housing to coolant tank.post inspection shows signs of leaks.	Napagold Oil Filter	1.00
	5w20 Engine Oil	6.00
	Accufit Beam	2.00
- Inspected transmission fluid.fluashed and replaced transmission fluid.	Wpr/blde	1.00
	Washer Fluid Concentr	1.00
- Replaced two tires and high speed balanced all four tires.nitro filled.	Syn-atf Trans Fluid S	9.00
	Non-chlor Brake Clnr	1.00
- Replaced front and rear asset numbers.	235/55r17 Assurance	2.00
	Hose	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.30	Labor: 498.00	Parts: 459.39
:		Total: 957.39

---

**Workorder:** 1708158      **Meter:** 52702      **In Date:** 08/18/2017      **Closed:** 08/31/2017  
**Problem:** Rear, driver side bulb not working.Left front tire going flat.

- Replace drivers side tail lamp assembly.due to melted housing.	<b>Parts List</b>	<b>Qty</b>
	Lamp Asy	1.00
- Check and repair left front tire .nail in .repair and rebalance .adjust all pressures.	Shop Supplies	1.00
- Shop Supplies		
Hours 1.50	Labor: 90.00	Parts: 175.10
:		Total: 265.10

---

**Workorder:** 1708861      **Meter:** 53768      **In Date:** 09/14/2017      **Closed:** 09/18/2017  
**Problem:** Head light out.

- Replace left low beam headlamp bulb.	<b>Parts List</b>	<b>Qty</b>
	Halogen Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 12.42
:		Total: 42.42

---

**Workorder:** 1709372      **Meter:** 54139      **In Date:** 09/26/2017      **Closed:** 09/28/2017  
**Problem:** Left rear tire going flat.

- Replace both rear tires and balance .nitrogen fill tires.	<b>Parts List</b>	<b>Qty</b>
	235/55r17 Assurance	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.00	Labor: 60.00	Parts: 321.78
:		Total: 381.78

---

**Workorder:** 1709855      **Meter:** 54941      **In Date:** 10/10/2017      **Closed:** 10/11/2017  
**Problem:** Left rear tire going flat.

- Repair left rea tire and balance .nitrogen fill tires.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1710158      **Meter:** 55350      **In Date:** 10/17/2017      **Closed:** 10/31/2017  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Rear shocks failed .r&r failed rear shocks with new.	Adjuster Handle	1.00
- Left front seat torn .r&r seat for repair.	5w20 Engine Oil	6.00
- Replace two front tires.nitrogen fill and high speed balance all four.	Napagold Oil Filter	1.00
	235/55r17 Assurance	2.00
- Shop Supplies	Real Shock Motorcraft	2.00
	Seat Repair	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.10	Labor: 366.00	Parts: 793.19
:		Total: 1,159.19

**Workorder:** 1711545      **Meter:** 57195      **In Date:** 11/27/2017      **Closed:** 11/29/2017  
**Problem:** Low tire pressure

- Repair left front tire and balance .nitrogen fill tires.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Workorder:** 1800234      **Meter:** 59725      **In Date:** 01/08/2018      **Closed:** 01/19/2018  
**Problem:** TPMS light on.

- Repair left front tire and balance .nitrofill.	<b>Parts List</b>	<b>Qty</b>
- P.m. service.	Napagold Oil Filter	1.00
- Mount two tires and balance all four wheels and rotate .nitrofill. Replaced damaged lug nuts.	5w20 Engine Oil	6.00
	Wiper Blade	1.00
- Removed and replaced front engine mount and recheck.	Wiper Blade	1.00
- Performed cooling system flush.	Blade	1.00
- Performed four wheel alignment.	235/55r17 Assurance	2.00
- Shop Supplies	Whl/nut	10.00
	Anti Freeze Motorcraft	2.00
	Engine Mount	1.00
	Lug Nut	10.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.80	Labor: 648.00	Parts: 683.24
:		Total: 1,331.24

**Workorder:** 1800421      **Meter:** 59725      **In Date:** 01/11/2018      **Closed:** 01/11/2018  
**Problem:** Tire Change

- Tow From: 2601 vista			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1802349      **Meter:** 61202      **In Date:** 03/02/2018      **Closed:** 03/06/2018  
**Problem:** Battery went dead.

- Perform starting and charging system analysis.battery failed load test .replace battery ,retest system ,ok.no draw.  
- Shop Supplies

	<b>Parts List</b>	<b>Qty</b>
	Battery	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 149.99
:		Total: 209.99

---

**Workorder:** 1804928      **Meter:** 64459      **In Date:** 05/11/2018      **Closed:** 05/17/2018  
**Problem:** PM Service, Tire going flat.

- P.m. service.  
- Replace all four tires .nitrogen fill and balance all four tires.  
- Shop Supplies

	<b>Parts List</b>	<b>Qty</b>
	5w20 Engine Oil	6.00
	Napagold Oil Filter	1.00
	Wiper Blade	1.00
	Wiper Blade	1.00
	Blade	1.00
	235/55r17 Assurance	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 4.00	Labor: 240.00	Parts: 713.91
:		Total: 953.91

---

**Workorder:** 1805340      **Meter:** 65126      **In Date:** 05/25/2018      **Closed:** 05/30/2018  
**Problem:** Right high beam headlight inop.

- Test and replace right side high beam headlight bulb. Test and replace right side low beam bulb .  
- Shop Supplies

	<b>Parts List</b>	<b>Qty</b>
	Blister Pack Capsules	1.00
	Halogen Capsule	1.00
	Shop Supplies	1.00
Hours 0.80	Labor: 48.00	Parts: 24.97
:		Total: 72.97

---

**Workorder:** 1805923      **Meter:** 65667      **In Date:** 06/11/2018      **Closed:** 06/11/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

**Workorder:** 1806247      **Meter:** 66288      **In Date:** 06/19/2018      **Closed:** 06/27/2018  
**Problem:** Low tire pressure.

- Repair left rear tire . Nitro service.  
- Replace right front tire and balance .nitrogen fill tires.  
- Shop Supplies

	<b>Parts List</b>	<b>Qty</b>
	235/55r17 Assurance	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 1.50	Labor: 90.00	Parts: 161.89
:		Total: 251.89

---

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1806871	<b>Meter:</b> 66834	<b>In Date:</b> 07/05/2018	<b>Closed:</b> 07/05/2018
<b>Problem:</b> Low tire pressure light on .			
- Repair right rear tire and balance . Nitro service.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1807019	<b>Meter:</b> 67172	<b>In Date:</b> 07/10/2018	<b>Closed:</b> 07/18/2018
<b>Problem:</b> Stalled out.			
- Diagnose stalling issue . Over temp ,power reduction .		<b>Parts List</b>	<b>Qty</b>
Pressure test cooling Replace all heater hoses . Flush cooling system and refill .		Anti Freeze Motorcraft	2.00
- Shop Supplies		Hose Assy	1.00
		Hose Heater	1.00
		Hose	1.00
		Hose Heater	1.00
		Shop Supplies	1.00
Hours 3.50	Labor: 210.00	Parts: 249.86	Total: 459.86
:			
<b>Workorder:</b> 1807020	<b>Meter:</b> 67096	<b>In Date:</b> 07/10/2018	<b>Closed:</b> 07/10/2018
<b>Problem:</b> Stalled Out			
- Tow From: 810 Datura ave To: Lv Shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1807359	<b>Meter:</b> 67273	<b>In Date:</b> 07/19/2018	<b>Closed:</b> 07/19/2018
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1807882	<b>Meter:</b> 68340	<b>In Date:</b> 08/01/2018	<b>Closed:</b> 08/01/2018
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1808180	<b>Meter:</b> 69056	<b>In Date:</b> 08/09/2018	<b>Closed:</b> 08/09/2018
<b>Problem:</b> Tire pressure light on .			
- Repair right front tire and balance . Nitrofill all tires.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1808334      **Meter:** 69798      **In Date:** 08/14/2018      **Closed:** 08/28/2018  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Replace two tire . Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Test drive ,noise left side of vehicle on turns . R&r defective left front axle and worn out left front lowwer control arm . Test drive.	5w20 Engine Oil	6.00
	Blade	1.00
	Wiper Blade	1.00
- Check batteryu and charging system . Fully charge battery . No draw found . battery failed load test . R&r defective battery and negative battery terminal.	Wiper Blade	1.00
	235/55r17 Assurance	2.00
- Complete four wheel alignment. Road test.	Control Arm Assy	1.00
- Shop Supplies	Axle Nut	1.00
	Left Front Axle	1.00
	Used Fire X Refurbished	1.00
	Battery	1.00
	Bat Cable	1.00
	Napa Cabin Air Filter	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.70	Labor: 702.00	Parts: 957.74
:		Total: 1,659.74

**Workorder:** 1808347      **Meter:** 69501      **In Date:** 08/14/2018      **Closed:** 08/14/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1808351      **Meter:** 69501      **In Date:** 08/14/2018      **Closed:** 08/14/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1809046      **Meter:** 70352      **In Date:** 09/04/2018      **Closed:** 09/06/2018  
**Problem:** Right front tire going flat.

- Repair right front tire and replace defective Tpms sensor . Balance and nitrogen fill tire.	<b>Parts List</b>	<b>Qty</b>
	Tpms12 Sensor Tire Pr	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 80.17
:		Total: 140.17

**Workorder:** 1810119      **Meter:** 72209      **In Date:** 09/28/2018      **Closed:** 09/28/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1810379      **Meter:** 72962      **In Date:** 10/09/2018      **Closed:** 10/22/2018  
**Problem:** Right front tire flat , A/C not cold and noise from engine area .

- Mount and balance two new tires . Nitrogen fill tires .	<b>Parts List</b>	<b>Qty</b>
- A/c performance test . Recover freon and replace defective compressor ,expansion valve and accumulator and flush system . Vacuum and complete refill of system to factory specs. Retest A/c performance .	P235 55r17 Fuel Max	2.00
	A/c Accumulato	1.00
	V Belt	1.00
- Diagnose noise from engine . Replace defective belt and belt tensioner. Retest.	Valva Asy A/c	1.00
	A/c Compressor	1.00
- Remove left front seat to replace seat track assembly and cushion .	Flush Solvent	1.00
	A/c V Belt	1.00
- Pressure test and diagnose coolant leak . Replace leaking water pump . Flush and refill coolant . retest .	Pulley	1.00
	Pad Seadt	1.00
- Shop Supplies	Track Asy	1.00
	Anti Freeze Motorcraft	1.00
	Water Pump	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 13.80	Labor: 924.60	Parts: 2,292.42
:		Total: 3,217.02

**Workorder:** 1810957      **Meter:** 73068      **In Date:** 10/24/2018      **Closed:** 10/24/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1811168      **Meter:** 73376      **In Date:** 10/30/2018      **Closed:** 10/30/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1811518      **Meter:** 73820      **In Date:** 11/08/2018      **Closed:** 11/08/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1811810      **Meter:** 74297      **In Date:** 11/16/2018      **Closed:** 11/16/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1812074      **Meter:** 75048      **In Date:** 11/27/2018      **Closed:** 12/10/2018  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Replace leaking oil pressure switch .	Napagold Oil Filter	1.00
- Replace two tires . Rotate and balance all four tires .	Napa Quart 5w20	6.00
Nitrofill all.	Washer Fluid Concentr	1.00
- Shop Supplies	Oil Switch	1.00
	Tire Pressure Monitoring System Sensor (	2.00
	Tire235/55/17 Mic	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 4.50	Labor: 301.50	Parts: 429.28
:		Total: 730.78

**Workorder:** 1812183      **Meter:** 74815      **In Date:** 11/29/2018      **Closed:** 11/29/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1812809      **Meter:** 75568      **In Date:** 12/18/2018      **Closed:** 12/20/2018  
**Problem:** Left side head light inop.

- Test and replace left side low beam headlight bulb.	<b>Parts List</b>	<b>Qty</b>
	Blister Pack Capsules	1.00
Hours 0.50	Labor: 33.50	Parts: 12.59
:		Total: 46.09

**Workorder:** 1812832      **Meter:** 75464      **In Date:** 12/18/2018      **Closed:** 12/18/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1812839      **Meter:** 75464      **In Date:** 12/18/2018      **Closed:** 12/18/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1813134      **Meter:** 76126      **In Date:** 12/31/2018      **Closed:** 12/31/2018  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1900218      **Meter:** 76379      **In Date:** 01/04/2019      **Closed:** 01/04/2019  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			



**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1900272	<b>Meter:</b> 76475	<b>In Date:</b> 01/07/2019	<b>Closed:</b> 01/10/2019
<b>Problem:</b> Vehicle in front of FDO . will not go into park .			
- Service call to Fdo to bring vehicle to shop . Diagnose no start and will not go into park . R&r broken shifter cable and adjust . Charge battery and retest.	<b>Parts List</b>		<b>Qty</b>
	Cable Asy		1.00
	Shop Supplies		1.00
- Shop Supplies			
Hours 5.20	Labor: 348.40	Parts: 44.51	Total: 392.91
:			
<b>Workorder:</b> 1900548	<b>Meter:</b> 76760	<b>In Date:</b> 01/15/2019	<b>Closed:</b> 01/15/2019
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1900757	<b>Meter:</b> 76912	<b>In Date:</b> 01/18/2019	<b>Closed:</b> 01/18/2019
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1901074	<b>Meter:</b> 77484	<b>In Date:</b> 01/29/2019	<b>Closed:</b> 01/29/2019
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1901454	<b>Meter:</b> 78258	<b>In Date:</b> 02/07/2019	<b>Closed:</b> 02/13/2019
<b>Problem:</b> Right side low beam inop.			
- Test and replace right low beam headlight bulb.	<b>Parts List</b>		<b>Qty</b>
	Blister Pack Capsules		1.00
Hours 0.50	Labor: 33.50	Parts: 12.59	Total: 46.09
:			
<b>Workorder:</b> 1901624	<b>Meter:</b> 78204	<b>In Date:</b> 02/12/2019	<b>Closed:</b> 02/12/2019
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1901822	<b>Meter:</b> 78421	<b>In Date:</b> 02/19/2019	<b>Closed:</b> 02/22/2019
<b>Problem:</b> Battery light on and noise from belt area .			
- Perform battery and charging test . Charge battery fully . Perform alternator circuit test . R&r defective alternator and retest . Clear codes .	<b>Parts List</b>		<b>Qty</b>
	Alternator		1.00
	Shop Supplies		1.00
- Shop Supplies			
Hours 2.60	Labor: 174.20	Parts: 592.22	Total: 766.42
:			
<b>Workorder:</b> 1901890	<b>Meter:</b> 78363	<b>In Date:</b> 02/19/2019	<b>Closed:</b> 02/19/2019
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1902086      **Meter:** 78587      **In Date:** 02/25/2019      **Closed:** 02/25/2019  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1902100      **Meter:** 78643      **In Date:** 02/26/2019      **Closed:** 02/27/2019  
**Problem:** Tires has nails.

- Replace both front tires and balance . Nitrogen fill tires.  
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Tire235/55/17 Mic	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 1.00      Labor: 67.00      Parts: 383.92      Total: 450.92  
:

---

**Workorder:** 1902446      **Meter:** 78985      **In Date:** 03/05/2019      **Closed:** 03/05/2019  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1902576      **Meter:** 79034      **In Date:** 03/07/2019      **Closed:** 03/07/2019  
**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00      Labor: 134.00      Parts: 0.00      Total: 134.00  
: