

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10180786      2010 FORD ESCAPE Suv, Mid Size, Hybrid**

**Workorder:** 1003315      **Meter:** 0      **In Date:** 04/01/2010      **Closed:** 04/01/2010  
**Problem:** Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00  
:

**Workorder:** 1007544      **Meter:** 1915      **In Date:** 07/16/2010      **Closed:** 07/26/2010  
**Problem:** Driver door belt moulding seperating and brake lamp condensation.

- Remove left tail lamp and repair for water intrusion and condensation.

**Parts List**  
Shop Supplies      Qty 1.00

- Drive vehicle to and from dealer for warranty repair and replace driver door belt moulding with new

- Shop Supplies

Hours 3.00      Labor: 180.00      Parts: 2.00      Total: 182.00  
:

**Workorder:** 1009956      **Meter:** 2738      **In Date:** 09/10/2010      **Closed:** 09/20/2010  
**Problem:** P.M. service.

- Perform pm service.

**Parts List**      Qty

- Perform rear drum brakes service and adjust brake shoes.

Shop Supplies      1.00

- Shop Supplies

Ph9566 Oil Filter Use Fram Ph3614      1.00

5w20 Engine Oil      5.00

Hours 3.00      Labor: 180.00      Parts: 14.91      Total: 194.91  
:

**Workorder:** 1010164      **Meter:** 2738      **In Date:** 09/16/2010      **Closed:** 09/17/2010  
**Problem:** flash canceiver-spot# 220

- Reflash Canceiver and reprogram

**Parts List**      Qty

- Shop Supplies

Shop Supplies      1.00

Hours 1.00      Labor: 60.00      Parts: 2.00      Total: 62.00  
:

**Workorder:** 1101832      **Meter:** 6540      **In Date:** 02/16/2011      **Closed:** 03/10/2011  
**Problem:** Install emergency lights.

- Transport vehicle for emergency light installation.

**Parts List**      Qty

- Shop Supplies

Shop Supplies      1.00

Hours 1.00      Labor: 60.00      Parts: 2.00      Total: 62.00  
:

**Workorder:** 1103529      **Meter:** 7070      **In Date:** 04/01/2011      **Closed:** 04/07/2011  
**Problem:** P.M. Service

- Perform pm service.

**Parts List**      Qty

- Perform rear drum brakes service and adjust brake shoes.

Shop Supplies      1.00

- Rotate and balance all four tires.

Ph9566 Oil Filter Use Fram Ph3614      1.00

- Shop Supplies

5w20 Engine Oil      5.00

Ww-2046 Wiper Blade (motorcraft)      2.00

Ww-1202 Wiper Blade (motorcraft)      1.00

Hours 4.00      Labor: 240.00      Parts: 69.77      Total: 309.77  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1104466      **Meter:** 7070      **In Date:** 04/26/2011      **Closed:** 04/26/2011  
**Problem:** 2 - Wash ticket(s) issued

- 2 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
 :

**Workorder:** 1110824      **Meter:** 9253      **In Date:** 10/11/2011      **Closed:** 10/24/2011  
**Problem:** P.M. service and right rear tire has slow leak.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Perform rear drum brake service and adjust brake shoes.	Shop Supplies	1.00
- Repair flat left rear tire.nitrogen fill,rotate and balance all four.	1348 Oil Filter Frm Ph3614 Wix 51348	1.00
- Shop Supplies	5w20 Engine Oil	5.00

Hours 5.00      Labor: 300.00      Parts: 16.89      Total: 316.89  
 :

**Workorder:** 1204326      **Meter:** 11150      **In Date:** 05/07/2012      **Closed:** 05/17/2012  
**Problem:** P.M. service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all tires.	Shop Supplies	1.00
- Service and adjust rear bakes.	1348 Oil Filter Frm Ph3614 Wix 51348	1.00
- Shop Supplies	5w20 Engine Oil	5.00
	Ww-2046 Wiper Blade (motorcraft)	2.00
	Ww-1202 Wiper Blade (motorcraft)	1.00

Hours 4.00      Labor: 240.00      Parts: 74.15      Total: 314.15  
 :

**Workorder:** 1211402      **Meter:** 13669      **In Date:** 11/27/2012      **Closed:** 12/11/2012  
**Problem:** Pm service and has to jump start.See notes.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Recharge battery and test,failed load test.replace defective battery and test charging system.	Filter	1.00
- Rotate and balance all tires.	5w20 Engine Oil	5.00
- Shop Supplies	Ca10170 Air Filter Lb	1.00
	Wd40 Spray Lube Stock	1.00
	Bxt96r 59	1.00
	Shop Supplies	1.00

Hours 4.00      Labor: 240.00      Parts: 221.90      Total: 461.90  
 :

**Workorder:** 1305761      **Meter:** 18898      **In Date:** 06/10/2013      **Closed:** 06/24/2013  
**Problem:** Pm service.Repair key marks on two front fenders asper request.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Replace center brake light bulb.	5w20 Engine Oil	5.00
- Service and adjust rear brakes.	Napagold Oil Filter	1.00
- Rotate and balance all tires.	Shop Supplies	1.00
- Shop Supplies		

Hours 4.50      Labor: 270.00      Parts: 20.23      Total: 290.23  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1306954      **Meter:** 19378      **In Date:** 06/18/2013      **Closed:** 07/12/2013  
**Problem:** damage to both frt fenders

- damage to both frt fenders

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
 :

**Workorder:** 1311771      **Meter:** 23768      **In Date:** 11/21/2013      **Closed:** 12/05/2013  
**Problem:** P.M. service.

- P.m. Service.

- Service and adjust rear brakes.

- Rotate and balance all tires.

- Shop Supplies

**Parts List**

5w20 Engine Oil

Napagold Oil Filter

Shop Supplies

**Qty**

5.00

1.00

1.00

Hours 4.00      Labor: 240.00      Parts: 18.28      Total: 258.28  
 :

**Workorder:** 1312616      **Meter:** 24283      **In Date:** 12/18/2013      **Closed:** 12/19/2013  
**Problem:** Left rear tire flat.

- Repair right rear tire flat.nitrogen fill and balance same.

- Shop Supplies

**Parts List**

Shop Supplies

**Qty**

1.00

Hours 1.00      Labor: 60.00      Parts: 2.00      Total: 62.00  
 :

**Workorder:** 1405374      **Meter:** 29401      **In Date:** 06/02/2014      **Closed:** 06/17/2014  
**Problem:** P.M. service and request wiper blades.

- P.m. Service.

- Service and adjust rear brakes.

- Replace and balance four new tires.

- Shop Supplies

**Parts List**

5w20 Engine Oil

Napagold Oil Filter

Wiper Blade

Ww-1202 Wiper Blade M

Washer FI

183407418 P235-70r16

Shop Supplies

Tire Disposal Fee

**Qty**

5.00

1.00

2.00

1.00

1.00

4.00

1.00

4.00

Hours 5.00      Labor: 300.00      Parts: 841.08      Total: 1,141.08  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1500508      **Meter:** 35957      **In Date:** 01/14/2015      **Closed:** 02/26/2015  
**Problem:** Pm service and wiper blades.Safety recall#14S05.Ac blows warm air.

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Replace four defective lug nuts and balance all four tires.	5w20 Engine Oil	5.00
- Inspect and service rear rear drum brakes.	Napagold Oil Filter	1.00
- Transport vehicle to and from dealer for safety recall #14s05.	Napagold Air Filter	1.00
- Ac performance and leak test for ac blows warm air.evacuate system.r&r dash and replace defective/leaking Ac evaporator with housing.replace accumulator.vacume and recharge system to specs.	Wd40 16oz	1.00
- Shop Supplies	Wheel Nut	4.00
	Wiper Blade	2.00
	Ww-1202 Wiper Blade M	1.00
	dehydrator	1.00
	Expantion Valve	1.00
	Evaporator	1.00
	Oil	1.00
	Seal Kit	1.00
	Shop Supplies	1.00
Hours 15.50	Labor: 930.00	Parts: 1,161.65
:		Total: 2,091.65

**Workorder:** 1506975      **Meter:** 40860      **In Date:** 07/14/2015      **Closed:** 07/28/2015  
**Problem:** Pm service.Wiper blades.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service rear brakes.	5w20 Engine Oil	5.00
- Repair right rear tire,rotate and balance all four.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Ww-1202 Wiper Blade M	1.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 70.27
:		Total: 370.27

**Workorder:** 1509352      **Meter:** 43070      **In Date:** 09/16/2015      **Closed:** 09/29/2015  
**Problem:** Left brake and turnsignal lights inop.

- Test and replace defective left brake lamp bulb.	<b>Parts List</b>	<b>Qty</b>
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.75
:		Total: 30.75

**Workorder:** 1600564      **Meter:** 46358      **In Date:** 01/19/2016      **Closed:** 01/27/2016  
**Problem:** P.M. Service.

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all four tires.	5w20 Engine Oil	5.00
- Inspect and service rear brakes.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Ww-1202 Wiper Blade M	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 65.51
:		Total: 305.51

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1606803	<b>Meter:</b> 51490	<b>In Date:</b> 07/06/2016	<b>Closed:</b> 07/12/2016
<b>Problem:</b> P.M. service.			
- P.m. Service.	<b>Parts List</b>		<b>Qty</b>
- Flush and refill transmission.	5w20 Engine Oil		5.00
- Pressure test and inspect cooling system.flush and refill system.	Napagold Oil Filter		1.00
	Wiper Blade		2.00
- Rotate and balance all tires.	Syn-atf Trans Fluid S		6.00
- Service and adjust rear brakes.	Coolant Ford Gold		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 7.50	Labor: 450.00	Parts: 92.48	Total: 542.48
:			
<b>Workorder:</b> 1607970	<b>Meter:</b> 52898	<b>In Date:</b> 08/03/2016	<b>Closed:</b> 08/18/2016
<b>Problem:</b> Left rear turn signal inop.			
- Replace left rear signal light bulb.	<b>Parts List</b>		<b>Qty</b>
	Bulb		1.00
Hours 0.50	Labor: 30.00	Parts: 0.78	Total: 30.78
:			
<b>Workorder:</b> 1612642	<b>Meter:</b> 56674	<b>In Date:</b> 12/09/2016	<b>Closed:</b> 01/03/2017
<b>Problem:</b> P.M. service and had to jump start.			
- P.m. Service.	<b>Parts List</b>		<b>Qty</b>
- Test battery and charging system.replace bad battery.	5w20 Engine Oil		5.00
- Replace leaking rear shocks.	Napagold Oil Filter		1.00
- Rotate and balance tires.	Wiper Blade		2.00
- Service and adjust rear brakes.	Accufit Rear		1.00
- Shop Supplies	Battery		1.00
	Rear Shocks Absorber		2.00
	Shop Supplies		1.00
Hours 6.00	Labor: 360.00	Parts: 284.92	Total: 644.92
:			
<b>Workorder:</b> 1704370	<b>Meter:</b> 61631	<b>In Date:</b> 05/01/2017	<b>Closed:</b> 05/11/2017
<b>Problem:</b> P.M. service.			
- P.m. Service.	<b>Parts List</b>		<b>Qty</b>
- R&r driver door and replace worn out hinges.adjust door.	Napagold Oil Filter		1.00
- Service and adjust rear brakes.	5w20 Engine Oil		6.00
- Rotate and balance tires.	Wiper Blade		2.00
- Shop Supplies	Accufit Rear		1.00
	Washer Fluid Concentr		1.00
	Hinge Asy		1.00
	Hinge Asy		1.00
	Shop Supplies		1.00
Hours 7.00	Labor: 420.00	Parts: 118.76	Total: 538.76
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1709566      **Meter:** 66681      **In Date:** 10/02/2017      **Closed:** 10/04/2017  
**Problem:** P.M. Service.

- P.m. service and replace damaged lug nuts.	<b>Parts List</b>	<b>Qty</b>
- Perform rear brake service.	5w20 Engine Oil	5.00
- Rotate and balance four tires.nitrofill.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Lug Nut	8.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 88.72
:		Total: 328.72

**Workorder:** 1801721      **Meter:** 71461      **In Date:** 02/13/2018      **Closed:** 02/21/2018  
**Problem:** PM Service

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Rotated and balanced all four tires.nitrogen filled all tires.	5w20 Engine Oil	5.00
- Clean and adjusted rear brakes.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	12in Exactfit-rear	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 49.76
:		Total: 289.76

**Workorder:** 1805696      **Meter:** 75395      **In Date:** 06/05/2018      **Closed:** 07/03/2018  
**Problem:** Check engine light on.

- Computer diagnose check engine light .r&r defective H2o sensor , sensor one bank one . Clear code and retest.	<b>Parts List</b>	<b>Qty</b>
- Computer diagnose Abs brake light . Code C1015. Check booster and lines for leaks . Perform pinpoint test . Replace vacuum pump and vacuum line . Clear codes and retest.	Sensor	1.00
- Shop Supplies	Tube Asy	1.00
	Pump Asy	1.00
	Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 711.28
:		Total: 1,041.28

**Workorder:** 1807794      **Meter:** 76226      **In Date:** 07/31/2018      **Closed:** 08/06/2018  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all four tires. Nitrogen fill tires.	Napagold Oil Filter	1.00
- Inspect and service rear brakes .	5w20 Engine Oil	5.00
- Shop Supplies	12in Exactfit-rear	1.00
	20in Exactfit-beam	2.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 49.81
:		Total: 289.81

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1809365      **Meter:** 77892      **In Date:** 09/12/2018      **Closed:** 09/13/2018

**Problem:** Towed in right rear tire flat.

- Replace both rear tires .due to damaged side wall. Balance and nitrogen all.	<b>Parts List</b>	<b>Qty</b>
	183407418 P235-70r16	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.00	Labor: 60.00	Parts: 373.53
:		Total: 433.53

---

**Workorder:** 1809500      **Meter:** 77892      **In Date:** 09/12/2018      **Closed:** 09/14/2018

**Problem:** Blown Tire

- Tow From: I95 Nb near Lantana Exit To: vista

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

**Workorder:** 1900354      **Meter:** 80590      **In Date:** 01/09/2019      **Closed:** 01/31/2019

**Problem:** PM Service, Center console display not working.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>	
- Replace two tires . Rotate and balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00	
	Napa Quart 5w20	5.00	
- Pinpoint test center console display inop . Replace faulty display module and retest .	Washer Fluid Concentr	1.00	
	12in Exactfit-rear	1.00	
- Inspect and service rear brakes .	20in Exactfit-beam	2.00	
- Shop Supplies	235/70/16 Tire Cont	2.00	
	Display	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 7.00	Labor: 469.00	Parts: 817.86	Total: 1,286.86
:			

---

**Workorder:** 1905024      **Meter:** 83581      **In Date:** 05/09/2019      **Closed:** 05/09/2019

**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00	Labor: 134.00	Parts: 0.00	Total: 134.00
:			