

1/3/2017  
3:39:35PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10105565 1996 UDUMP TRAILER,INC. ?? Trailer, Dump

**Workorder:** 34157

**Problem:** ELPEX, INC. T-023665

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/03/2000	Hours	Description	
- Elpex, Inc. T-023665			
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 154.32	

**Workorder:** 37752

**Problem:** NO TRAILER LIGHTS (AT FACILITIES)

Meter Reading: 0	Labor	Parts	Quantity
In Date: 04/10/2000	Hours	Description	
- Travel From Sr Shop To Facilities For Repairs	3.50	SHOP SUPPLIES	1.00
- Checked All Lights. Repaired Ground Wire For Side Marker Light. Repaired Wiring And Replaced Bad Bulbs For Rear Lights			
- Shop Supplies			
<b>Parts Charge:</b> 2.00	<b>Labor Charge:</b> 157.50		

**Workorder:** 146504

**Problem:** PM SERVICE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 09/07/2001	Hours	Description	
- P.M. Service	4.50	SHOP SUPPLIES	1.00
- Repair Lights. Repair Wire Harness Short.			1.00
- Dump Battery Dead. R/R Battery			
- Shop Supplies			
<b>Parts Charge:</b> 107.29	<b>Labor Charge:</b> 202.50		

**Workorder:** 246010

**Problem:** CHECK LIGHTS

Meter Reading: 0	Labor	Parts	Quantity
In Date: 08/14/2002	Hours	Description	
- Ck All Lights Repair Wiring For L/R Tail Lamp	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00	<b>Labor Charge:</b> 50.00		

1/3/2017  
3:39:35PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10105565 1996 UDUMP TRAILER,INC. ?? Trailer, Dump

**Workorder:** 249236

**Problem:** PM SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 10/04/2002	Hours	Description	Quantity
- Pm Svc	4.50	SHOP SUPPLIES	1.00
- Mount One New Tire		225/75D15 TIRE 3905194120	1.00
- Shop Supplies			
<b>Parts Charge:</b>	117.01	<b>Labor Charge:</b>	225.00

**Workorder:** 348666

**Problem:** P.M SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 09/25/2003	Hours	Description	Quantity
- Pm	4.20	4086 SWITCH CABLE	1.00
- Repoace Emergency Brake Switch Cable		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	4.78	<b>Labor Charge:</b>	210.00

**Workorder:** 547010

**Problem:** P.M SERVICE.DEAD BATTERY

Meter Reading: 0	Labor	Parts	
In Date: 06/08/2005	Hours	Description	Quantity
- Replace Key Switch, Replace Battery, And Clean	8.80	84-9286 BATTERY J-BOLT 10" (GROTE)	1.00
Contacts		27-60 BATTERY 27T105	1.00
- Repair Both Tail Lights, Remove Old Lamps, Rewire		528,529 LIGHTS	2.00
- Pm Service		101010 SEAL	4.00
- Brake Service		84-9288 GROTE BATTERY HOLD DOWN	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		SW33 SWITCH	1.00
<b>Parts Charge:</b>	225.48	<b>Labor Charge:</b>	440.00

1/3/2017  
3:39:35PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10105565 1996 UDUMP TRAILER,INC. ?? Trailer, Dump

**Workorder:** 647151

**Problem:** P.M SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 10/13/2006	Hours	Description	Quantity
- Pm Service	4.75	SHOP SUPPLIES	1.00
- Fill Tires W/Nitrogen			
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	41.25

**Workorder:** 745100

**Problem:** P.M.SERVICE/SEE NOTE

Meter Reading: 0	Labor	Parts	
In Date: 10/03/2007	Hours	Description	Quantity
- Pm Service	6.00	05023 BATTERY CLEANER	1.00
- Replace Battery		SHOP SUPPLIES	1.00
- Install Trailer Battery Charging Wire, Wire Loom & Plug		HP31D BATTERY GROUP 31 STUD	1.00
- Replace 3 Bulbs - Tag Light & 2 Side Marker Lts		05046 BATTERY PROTECTOR (CRC)	1.00
- Shop Supplies			
<b>Parts Charge:</b>	88.50	<b>Labor Charge:</b>	45.00

**Workorder:** 748407

**Problem:** NEW BATTERY NOT CHARGING; REPLACE BRAKE LOCK CABLE

Meter Reading: 0	Labor	Parts	
In Date: 12/10/2007	Hours	Description	Quantity
- Replace Breakaway Cable Jack-Up Unit; Ck Emergency Brake Forproper Operation	4.00	WASTE FEE	1.00
		SHOP SUPPLIES	1.00
- Replace L/R Tire		4086 SWITCH CABLE	1.00
- Ck Battery & Charging Sys; Battery Ok; Ck Wiring		TIRE 225/75R15 394573600	1.00
Harness & Found Corrosion On Pump Wires; Clean & Test Pump Operation		TIRE DISPOSAL FEE	1.00
- Shop Supplies			
<b>Parts Charge:</b>	144.64	<b>Labor Charge:</b>	90.00

1/3/2017  
3:39:35PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10105565 1996 UDUMP TRAILER,INC. ?? Trailer, Dump

**Workorder:** 844565

**Problem:** P.M.SERVICE,SEE NOTE

Meter Reading: 0	Labor	Parts
In Date: 09/22/2008	Hours	Quantity
- Pm Service	8.00	1066 WHITE LITHIUM (CRC 05037) 1.00
- Repack Whl Brgs; Service Brake Drums & Adjust; R&R 4 Inner Axle Grease Seals		SHOP SUPPLIES 1.00 AXLE SEALS 4.00
- C/S Left Tailight Out; Unable To Verify Complaint; Verify Pass Side Running Lt Out; R&R Bulb; Repair Wiring		09997 BRAKE CLEAN 1.00
- Shop Supplies		
<b>Parts Charge:</b>	27.38	<b>Labor Charge:</b> 105.00

**Workorder:** 943420

**Problem:** P.M.SERVICE

Meter Reading: 0	Labor	Parts
In Date: 09/18/2009	Hours	Quantity
- P.M.Service	4.50	SHOP SUPPLIES 1.00
- Install New Instruction Lable		
- Shop Supplies		
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b> 270.00

**Workorder:** 944113

**Problem:** repair rusted flooring

Meter Reading: 0	Labor	Parts
In Date: 10/02/2009	Hours	Quantity
- Replate Trailer Bed R&R Fenders	28.00	1/4 4X8 SHEET STEEL 94.00
- Shop Supplies		SHOP SUPPLIES 1.00 FENDERS 2653 2.00 1/2X4X20 STEEL FLAT BAR 8.00
<b>Parts Charge:</b>	879.62	<b>Labor Charge:</b> 1,680.00

1/3/2017  
3:39:35PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10105565 1996 UDUMP TRAILER,INC. ?? Trailer, Dump

**Workorder:** 1009204

**Problem:** P. M. Service, Leaking hydraulic fluid from hoses, & Check battery.

Meter Reading: 0	Labor	Parts	
In Date: 08/25/2010	Hours	Description	Quantity
- P. M.	10.75	1066 WHITE LITHIUM (CRC 05037)	1.00
- Clean & Adjust Front & Rear Brakes.		GROUP 31 STUD BATTERY (ACD 31-900CT)	1.00
- Check Charging System & Replace Bad Battery.		SHOP SUPPLIES	1.00
- Remove Both Hydraulic Cylinders, Send Out For Repair, Reinstall, & Flush Hydraulic System.		09997 BRAKE CLEAN	1.00
- Shop Supplies		AW68 HYDRO FLUID HYDRAULIC OIL 68	20.00
<b>Parts Charge:</b> 178.92		<b>Labor Charge:</b> 645.00	<b>Commercial Charge:</b> 397.32

**Workorder:** 1110803

**Problem:** P. M. SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 10/11/2011	Hours	Description	Quantity
- P. M. Service.	6.50	SHOP SUPPLIES	1.00
- Service Front & Rear Brake Drum Assys.			
- Verify, Battery Weak. Recharge. Test Battery, Verify Charging.			
- Verify Tail Lights Out. R&R Bulbs. Clean Up Connections.			
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 390.00	

**Workorder:** 1210417

**Problem:** pm

Meter Reading: 0	Labor	Parts	
In Date: 10/30/2012	Hours	Description	Quantity
- Pm	6.00	SHOP SUPPLIES	1.00
- Clean And Adjust Front Brakes Clean And Adj Rear Brakes			
- Replace Wire And Replace Light Bulb For Left Front Marker Light			
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 360.00	

1/3/2017  
3:39:35PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10105565 1996 UDUMP TRAILER,INC. ?? Trailer, Dump

**Workorder:** 1400414

**Problem:** pm

Meter Reading: 0	Labor	Parts	
In Date: 01/14/2014	Hours	Description	Quantity
- Pm	6.75	SHOP SUPPLIES	1.00
- Verify Dead Battery Test Battery Bad Replace Battery		GROUP 31 STUD DELCO	1.00
- Svc Front And Rear Drum Brakes And Adj Replace Emergency Break Away Switch		BREAKAWAY SWITCH	1.00
- Shop Supplies			
<b>Parts Charge:</b>	143.63	<b>Labor Charge:</b>	405.00

**Workorder:** 1501941

**Problem:** PM, NEEDS NEW ASSET NUMBER STICKER

Meter Reading: 0	Labor	Parts	
In Date: 02/24/2015	Hours	Description	Quantity
- Pm	9.50	BRAKE CLEANER	2.00
- Clean And Adj. Front And Rear Brakes Replace Broken Adj. Spring		SPRING	2.00
		TANG LOCKING WASHER	4.00
- Replace All Grease Seal Clean And Repack Wheel Bearings Replace Tounge And Flat Washer		double lip dexter seal	4.00
		762173406 225-75R15	4.00
- Replace 4 Tires		TIRE DISPOSAL FEE	4.00
- Fill All Tires With Nitrogen		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	733.47	<b>Labor Charge:</b>	570.00

**Workorder:** 1601540

**Problem:** DEAD BATTERY

Meter Reading: 0	Labor	Parts	
In Date: 02/12/2016	Hours	Description	Quantity
- Ck Battery And Charging System Rr Battery	0.75	SHOP SUPPLIES	1.00
- Shop Supplies		GROUP 31 STUD DELCO	1.00
<b>Parts Charge:</b>	136.83	<b>Labor Charge:</b>	45.00

1/3/2017  
3:39:35PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10105565 1996 UDUMP TRAILER,INC. ?? Trailer, Dump

**Workorder:** 1602993                      **Problem:** pm, break away cable for break system needs reeds replacement

Meter Reading: 0	Labor	Parts	
In Date: 03/22/2016	Hours	Description	Quantity
- Pm Service.	8.50	BRAKE CLEANER	2.00
- Clean And Adjust Front Brakes.Clean And Adjust Rear Brakes.Trailer Have Two Axles And Four Drums		TANG LOCKING WASHER	2.00
		CLEVIS SLIP HOOK-BULK	2.00
- Replace Break Away Cable.		4086 CABLE SWITCH	1.00
- Replace Safety Hooks.		SHOP SUPPLIES	1.00
- Replace Leaking Grease Seals And Clean Grease From Brake Drums.		DOUBLE LIP SEAL	2.00
- Shop Supplies			
<b>Parts Charge:</b>	49.24	<b>Labor Charge:</b>	510.00

**Workorder:** 1612528                      **Problem:** Transition Prep Charge

Meter Reading: 0	Labor	Parts	
In Date: 12/07/2016	Hours	Description	Quantity
- Transition Prep Charge	2.00		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00

Total Parts Charges:                      **2,848.79**                      Total Labor Charges:                      **6,441.25**                      Total Comm. Charges:                      **551.64**