

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1504250 **Meter:** 36693 **In Date:** 04/24/2015 **Closed:** 04/30/2015
Problem: pm, wiper blades front and rear

- pm	Parts List	Qty
- rear brake drum svc	Napagold Air Filter	1.00
- Shop Supplies	Napagold Oil Filter	1.00
	Napa Quart 5w20	5.00
	Wiper Blade	2.00
	Ww-1202 Wiper Blade M	1.00
	Washer FI	1.00
	Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 78.73
:		Total: 303.73

Workorder: 1506759 **Meter:** 38616 **In Date:** 07/07/2015 **Closed:** 07/14/2015
Problem: RR TIRE SCREW SIDE WALL

- replace both rear tires	Parts List	Qty
- Shop Supplies	183407418 P235-70r16	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.50	Labor: 90.00	Parts: 395.88
:		Total: 485.88

Workorder: 1506768 **Meter:** 38143 **In Date:** 07/06/2015 **Closed:** 07/07/2015
Problem: Flat tire on P/R (spare tire mounted)

- Tire Service 8100 Forest Hill Blvd - Flat tire on P/r (spare tire mounted)			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1511504 **Meter:** 41345 **In Date:** 11/09/2015 **Closed:** 12/03/2015
Problem: PM, HARD TO START TOWED IN

- pm	Parts List	Qty	
- clean and adj rear brakes	Napagold Oil Filter	1.00	
- ck and replace bad battery	Napa Quart 5w20	5.00	
- remove interior panel and replace both rear shocks	Washer Fluid Concentr	1.00	
- replace both rear tires	Mac Wite Lithium Gres	1.00	
- Shop Supplies	Brake Cleaner	1.00	
	Mac Battery Protect	1.00	
	Macs Battery Cleaner	1.00	
	183407418 P235-70r16	2.00	
	Battery	1.00	
	Sensa-trac Trk Shock	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 8.00	Labor: 480.00	Parts: 627.21	Total: 1,107.21
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1511575 **Meter:** 41258 **In Date:** 11/09/2015 **Closed:** 11/12/2015
Problem: no start , need pm svc

- Tow From: 8100 forest hill blvd wpb To: sr delray

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1607460 **Meter:** 46127 **In Date:** 07/21/2016 **Closed:** 07/28/2016
Problem: Pm service

- Pm service.
- Rear drum brake service.
- Repair F/I tire.mount,rotate and balance all.correct N2 levels
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napa Quart 5w20	5.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Wd40 16oz	1.00
Shop Supplies	1.00

Hours 5.50 Labor: 330.00 Parts: 63.20 Total: 393.20
:

Workorder: 1704042 **Meter:** 51110 **In Date:** 04/21/2017 **Closed:** 04/28/2017
Problem: PM Service

- Pm Service
- Replace right rear strobe lamp.
- Rear brake service.
- Rotate and balance 4 tires.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napa Quart 5w20	5.00
Napagold Air Filter	1.00
Wiper Blade	2.00
Accufit Rear	1.00
Vtx609c Led Strobe Cl	1.00
Shop Supplies	1.00

Hours 5.50 Labor: 330.00 Parts: 181.40 Total: 511.40
:

Workorder: 1706416 **Meter:** 51110 **In Date:** 06/27/2017 **Closed:** 06/28/2017
Problem: No start

- Tow From: 8100 Forest Hill Blvd To: Lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1706425 **Meter:** 51163 **In Date:** 06/28/2017 **Closed:** 07/07/2017
Problem: Tow in,no start.

- Charge battery. Would not except charge.replace and recheck starting and charging system.no paracitic draw found.service cable ends.
- Shop Supplies

Parts List	Qty
Battery	1.00
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 122.12 Total: 182.12
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1711773 **Meter:** 52277 **In Date:** 11/30/2017 **Closed:** 12/11/2017
Problem: PM Service

- Pm Service.	Parts List	Qty
- Clean and adjust rear brakes.	Napagold Oil Filter	1.00
- Rotate and balance tires.	Napa Quart 5w20	5.00
- Shop Supplies	20in Exactfit-beam	2.00
	Washer Fluid Concentr	1.00
	Non-chlor Brake Clnr	1.00
	Shop Supplies	1.00
Hours 4.50	Labor: 270.00	Parts: 54.46
:		Total: 324.46

Workorder: 1803941 **Meter:** 55394 **In Date:** 04/16/2018 **Closed:** 04/23/2018
Problem: PM Service.Dead battery.TPMS light on.

- Pm Service.	Parts List	Qty
- Service rear brakes.service front calipers.replace front rotors and pads.	Napagold Oil Filter	1.00
- Replace tire pressure sensor and reset Tpms.	Napa Quart 5w20	5.00
- Check battery and charging system.replace bad battery under napa warranty.	Washer Fluid Concentr	1.00
- Shop Supplies	Non-chlor Brake Clnr	1.00
	Disc Brake Pads	1.00
	Brake Rotor	2.00
	Tpms12 Sensor Tire Pr	1.00
	Battery	1.00
	Shop Supplies	1.00
Hours 9.50	Labor: 570.00	Parts: 411.68
:		Total: 981.68

Workorder: 1901307 **Meter:** 57349 **In Date:** 02/04/2019 **Closed:** 02/13/2019
Problem: P.M. service and towed in for no start.

- P.m. service.	Parts List	Qty
- Charge battery fully . Test starting and charging system . and draw test . All test passed . Needs to be driven more often.	Napagold Oil Filter	1.00
- Rotate and balance all four tires . Nitrogen fill tires .	5w20 Engine Oil	5.00
- Service and inspect rear brakes .	12in Exactfit-rear	1.00
- Shop Supplies	20in Exactfit-beam	2.00
	Shop Supplies	1.00
Hours 5.25	Labor: 351.75	Parts: 53.25
:		Total: 405.00

Workorder: 1901327 **Meter:** 57276 **In Date:** 02/01/2019 **Closed:** 02/04/2019
Problem: No start

- Tow From: 8100 Forest Hill Blvd (west side of parking lot) To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1901685 **Meter:** 57276 **In Date:** 02/13/2019 **Closed:** 02/22/2019
Problem: replace chipped windsheild

- set up repairs & inspect		Parts List		Qty
- Shop Supplies		Shop Supplies		1.00
	Hours 1.00	Labor: 67.00	Parts: 3.00	Total: 70.00
	:			

Workorder: 1901873 **Meter:** 57349 **In Date:** 02/19/2019 **Closed:** 02/19/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued				
	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1907098 **Meter:** 57349 **In Date:** 07/09/2019 **Closed:** 07/09/2019
Problem: Transition Prep Charge

- Transition Prep Charge				
	Hours 2.00	Labor: 134.00	Parts: 0.00	Total: 134.00
	:			