

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10156412    2005 FORD F450 Cab & Chassis, 15,000 Gvwr, 4X4, W/Dump Body**

**Workorder:** 549025    **Meter:** 12    **In Date:** 06/29/2005    **Closed:** 09/07/2005  
**Problem:** FAB TRUCK BODY

- Fab Truck Body
- Wireup Body Lites
- Ck Oil
- Welding Supplies

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00
T-1 Black Paint Gloss	2.00
1/2"x2"x20' Alum Flat Bar	9.00
1/2x4x12 Alum Flat Bar	8.00
1/4x4x12 Alum Plate 5052	3.00
3/16x4x10 Dia Plate Aluminum Non Bright	96.00
3/4#.125 4x8 Alm Flt Metl Alum Flaten Expand Metal	21.00
1/4x2x20 Angle Steel	20.00
3"x3"x20' Alum Angle Architectual 1/4" Thick	1.00
3/16x1-1/2x20 Alum Angle Architectual	15.00
1-1/2x1/4x18 Sq Alum Tube Sq Alum Tube W/radius	14.00
1/2x4x20 Steel Flat Bar	3.00
1/4x2x20 Alum Flat Bar 6063	7.00
1/8x1-1/4x24 Sq. Alum Tub	6.00
1/2x3x20 Steel Flat Bar	2.00
3/8"x6"x20' St Flat Bar	2.00
4" X 20 Channel Stock 7.25 Thick	5.00
5"x20 Steel Channel 9.0 Thick	3.00
2660 Marker Light Red Oblong Led	4.00
2660a Marker Light Yellow Oblong Led	2.00
Light Bar 15050r	1.00
Mudflap Mfr2424	2.00
Sprig Latch B2596	4.00
66060 Lock Pin 3/8"x2-1/2"	3.00
66060 Lock Pin 3/8"x2-1/2"	1.00
Latch 4859ss-10	4.00
3/8lp Lynch Pin	3.00
12cal Alum Tail-gate Hing	3.00
5" Channel Aluminum Structural (assc 2.75)	25.00
4'x10' 3/16" Dia Plate Aluminum Not Bright	120.00
4" Channel Aluminum Structural (assc 2.25)	50.00
Tool Box Tbts96	1.00
Tool Box Tbts72	1.00

Hours 174.00  
:

Labor: 8,700.0    Parts: 5,152.42    Total: 13,852.42  
0

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 549165      **Meter:** 11      **In Date:** 06/30/2005      **Closed:** 09/22/2005  
**Problem:** CHECK IN

	<b>Parts List</b>	<b>Qty</b>
- Ck In		
- Drove To Advanced And Back	Shop Supplies	1.00
- Move Circuit Breaker From Hanging On Brake Limp To Mounted On Fire Wall.rewire Brake And Batt And Trailer Plug.	1/4x3x20 Alum Flat Bar 6063	17.00
	06133 3m Electric Tape Stock #832260101	1.00
- Shop Supplies		
Hours 12.00	Labor: 600.00	Parts: 42.61
:		Total: 642.61

**Workorder:** 554595      **Meter:** 12      **In Date:** 09/07/2005      **Closed:** 09/22/2005  
**Problem:** FABRICATE QUICK CONNECT 50AMP FOR CET UNIT

	<b>Parts List</b>	<b>Qty</b>
- Fab Wire Harness And Quick Disconnect For Cut Unit		
- Shop Supplies	Shop Supplies	1.00
	Sst312 Conductor	2.00
	Bp34 Cover	2.00
	Circuit Breaker	1.00
	Cs4rv Red Cable #4	15.00
	Cs4l Cable #4	10.00
	Cs4rv Red Cable #4	5.00
Hours 5.00	Labor: 250.00	Parts: 152.98
:		Total: 402.98

**Workorder:** 555117      **Meter:** 0      **In Date:** 09/15/2005      **Closed:** 09/15/2005  
**Problem:** MAKE & APPLY DECALS. CHECK FLUIDS, BELTS, AND OPER

- Make & Apply Decals. Check Fluids, Belts, And Operation As Applicable.

Hours 1.00      Labor: 50.00      Parts: 0.00      Total: 50.00  
:

**Workorder:** 642210      **Meter:** 3779      **In Date:** 07/11/2006      **Closed:** 07/20/2006  
**Problem:** PM SERVICE

	<b>Parts List</b>	<b>Qty</b>
- Performed Service		
- R&r Bulb	Shop Supplies	1.00
- Test Run	Ca9516 Air Filter Lbf Laf1646 Wix 42731	1.00
- Shop Supplies	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
	15/40 Oil	15.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 5.50	Labor: 275.00	Parts: 152.17
:		Total: 427.17

**Workorder:** 733174      **Meter:** 5802      **In Date:** 01/24/2007      **Closed:** 01/25/2007  
**Problem:** P.M SERVICE.VOID.VOID SEND TO HE SHOP

-

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 733183      **Meter:** 5802      **In Date:** 01/24/2007      **Closed:** 02/22/2007  
**Problem:** PM SERVICE

- Pm Service. Replaced Broken Oil Filler Cap	<b>Parts List</b>	<b>Qty</b>
- Take To Ford For Recall	Shop Supplies	1.00
- Test Run	F3az6766b Filler Cap	1.00
- Shop Supplies	Ca9516 Air Filter Lbf Laf1646 Wix 42731	1.00
	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
	15/40 Oil	15.00
	Used Firex Refurbed Fire Extingshers	1.00
	05046 Battery Protector (crc)	1.00
Hours 6.00	Labor: 330.00	Parts: 137.54
:		Total: 467.54

**Workorder:** 743364      **Meter:** 9429      **In Date:** 08/29/2007      **Closed:** 09/05/2007  
**Problem:** WATER IN FUEL LIGHT IS ON AND PM SERVICE

- Perform Pm	<b>Parts List</b>	<b>Qty</b>
- Repair Connection To Strobe	Shop Supplies	1.00
- Shop Supplies	Ca9516 Air Filter Lbf Laf1646 Wix 42731	1.00
	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
	05018 Lectra-motive Clean For Electrical Parts Only	1.00
	15/40 Oil	15.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 5.00	Labor: 275.00	Parts: 162.34
:		Total: 437.34

**Workorder:** 747946      **Meter:** 0      **In Date:** 09/04/2007      **Closed:** 11/30/2007  
**Problem:** CEI GROUP

- Cei Group	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 836564      **Meter:** 11286      **In Date:** 04/04/2008      **Closed:** 04/18/2008  
**Problem:** PM SERVICE

- Pm	<b>Parts List</b>	<b>Qty</b>	
- Deflate & Refill Tires W/nitrogen	Shop Supplies	1.00	
- Replace Grease Fitting	Ca9516 Air Filter Lbf Laf1646 Wix 42731	1.00	
- Test Run	7312 Oil Filterfrm Ch9549 Wix 57312	1.00	
- Shop Supplies	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00	
	05018 Lectra-motive Clean For Electrical Parts Only	1.00	
	15/40 Oil	15.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	Air Freshener	1.00	
Hours 7.50	Labor: 450.00	Parts: 134.07	Total: 584.07
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 840899      **Meter:** 12894      **In Date:** 07/03/2008      **Closed:** 07/30/2008  
**Problem:** STALLING

- Diagnosis No Codes Runs Fine At This Time.koeo Tested Ok. Koer Tested Ok	<b>Parts List</b>	<b>Qty</b>
	Shop Supplies	1.00
- Road Test W.p.f.		
- Fm-alpacker		
- Fm Al Packer.		
- Shop Supplies		
Hours 6.00	Labor: 360.00	Parts: 2.00
:		Total: 362.00

**Workorder:** 847307      **Meter:** 14807      **In Date:** 11/20/2008      **Closed:** 12/02/2008  
**Problem:** PM SERVICE

- Pm	<b>Parts List</b>	<b>Qty</b>
- Nitro All Tires.	Shop Supplies	1.00
- Shop Supplies	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
	15/40 Oil	15.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	Air Freshener	1.00
Hours 5.50	Labor: 330.00	Parts: 119.71
:		Total: 449.71

**Workorder:** 938832      **Meter:** 20834      **In Date:** 06/10/2009      **Closed:** 06/17/2009  
**Problem:** PM SERVICE

- Pm	<b>Parts List</b>	<b>Qty</b>
- R&r Front Tires.	Shop Supplies	1.00
- Nitro All Tires.	Ca9516 Air Filter Lbf Laf1646 Wix 42731	1.00
- Shop Supplies	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
	15/40 Oil	15.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	Air Freshener	1.00
	225/70r195 Tire/wheel Built Up	2.00
Hours 7.50	Labor: 450.00	Parts: 890.43
:		Total: 1,340.43

**Workorder:** 945941      **Meter:** 24976      **In Date:** 11/12/2009      **Closed:** 11/16/2009  
**Problem:** battery

- R&r batteries and connections	<b>Parts List</b>	<b>Qty</b>
- Test charging system	Shop Supplies	1.00
- Shop Supplies	Group 65 Battery (mtc Bxt-65-850)	2.00
Hours 2.50	Labor: 150.00	Parts: 256.85
:		Total: 406.85

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1000032      **Meter:** 26300      **In Date:** 01/04/2010      **Closed:** 01/29/2010  
**Problem:** P.M.

- pm service	<b>Parts List</b>	<b>Qty</b>
- replace marker lights	Shop Supplies	1.00
- add nitrogen to all tires	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- road test	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
- Shop Supplies	15/40 Oil	15.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Air Freshener	1.00
	2660a Marker Light Yellow Oblong Led	2.00
	2660 Marker Light Red Oblong Led	3.00
Hours 7.50	Labor: 450.00	Parts: 129.25
:		Total: 579.25

**Workorder:** 1007149      **Meter:** 30343      **In Date:** 06/23/2010      **Closed:** 07/08/2010  
**Problem:** right rear outside tire flat

- 441 N. of hypoloxo heading s.	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1009899      **Meter:** 33142      **In Date:** 09/09/2010      **Closed:** 09/17/2010  
**Problem:** pm service

- pm service	<b>Parts List</b>	<b>Qty</b>	
- replace 3 recaps on the rear	Shop Supplies	1.00	
- test and clean batteries	7312 Oil Filterfrm Ch9549 Wix 57312	1.00	
- service trans	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00	
- test drive	Ft145 Trans Filter In-line Frm None Wix None	1.00	
- Shop Supplies	Ft144 Trans Filter Screen Frm None Wix None	1.00	
	15/40 Oil	15.00	
	Syn/atf Trans Fluid Synthetic	2.00	
	Syn/atf Trans Fluid Synthetic	8.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	225/70r195rc Tire Recapped	3.00	
Hours 7.30	Labor: 438.00	Parts: 676.92	Total: 1,114.92
:			

**Workorder:** 1103929      **Meter:** 38592      **In Date:** 04/12/2011      **Closed:**  
**Problem:** P.M. service.

-	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1103931      **Meter:** 38592      **In Date:** 04/12/2011      **Closed:** 04/27/2011

**Problem:** pm service

- pm service	<b>Parts List</b>	<b>Qty</b>
- replace battery terminal end	Shop Supplies	1.00
- repair marker lights and repair wiring	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- fm to callaghan	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
- vehicle alignment callaghan	15/40 Oil	15.00
- Shop Supplies	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	2660 Marker Light Red Oblong Led	1.00
Hours 10.80	Labor: 648.00	Parts: 122.26
:		Total: 770.26

---

**Workorder:** 1105714      **Meter:** 38849      **In Date:** 06/01/2011      **Closed:** 06/02/2011

**Problem:** Fire ext.

- R&r Fire Ext.	<b>Parts List</b>	<b>Qty</b>
	Used Firex Refurbed Fire Extingshers	1.00
Hours 0.50	Labor: 30.00	Parts: 13.93
:		Total: 43.93

---

**Workorder:** 1111369      **Meter:** 42899      **In Date:** 10/26/2011      **Closed:** 11/02/2011

**Problem:** P.M.

- pm service	<b>Parts List</b>	<b>Qty</b>
- repair marker light and wiring	Shop Supplies	1.00
- replace front tires boulevard	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Shop Supplies	Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
	15/40 Oil	15.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	2660 Marker Light Red Oblong Led	1.00
Hours 5.00	Labor: 300.00	Parts: 106.88
:		Total: 406.88

---

**Workorder:** 1112349      **Meter:** 43288      **In Date:** 11/18/2011      **Closed:** 11/18/2011

**Problem:** Radiator problem---Fluid leaking from Radiator

- From: Entrance of Okeeheelee South			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

**Workorder:** 1112430      **Meter:** 43288      **In Date:** 11/22/2011      **Closed:** 12/01/2011

**Problem:** radiator leak

- replace radiator and coolant	<b>Parts List</b>	<b>Qty</b>
- road test	Shop Supplies	1.00
- Shop Supplies	Radiator Assy	1.00
	Antifreeze Ext/life All Makes (peak 407)	2.00
	3634621 Seal Tablets Coolant (gmc)	1.00
Hours 5.50	Labor: 330.00	Parts: 417.93
:		Total: 747.93

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1202121	<b>Meter:</b> 45250	<b>In Date:</b> 03/01/2012	<b>Closed:</b> 03/15/2012
<b>Problem:</b> brakes, abs light and drive shaft			
- scan for abs codes replace abs sensor		<b>Parts List</b>	<b>Qty</b>
- road test		Shop Supplies	1.00
- inspect drive shaft npf		09997 Brake Clean	1.00
- Shop Supplies		L/front Abs Sensor	1.00
Hours 6.50	Labor: 390.00	Parts: 64.76	Total: 454.76
:			

---

<b>Workorder:</b> 1202138	<b>Meter:</b> 45072	<b>In Date:</b> 03/01/2012	<b>Closed:</b> 03/01/2012
<b>Problem:</b> brakes to floor/ abs light on/ rattle in drive shaft			
- Tow From: riverbend 9060 indiantown rd To: he shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1203966	<b>Meter:</b> 46950	<b>In Date:</b> 04/26/2012	<b>Closed:</b> 05/14/2012
<b>Problem:</b> pm service and coolant leak			
- P.m.		<b>Parts List</b>	<b>Qty</b>
- R&r Batteries and test charging system		Shop Supplies	1.00
- Presure test cooling system, replace cooling resevoir and flush system		7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Replaced and wired in new marker lamp		Cs9667a Fuel Filter Lbf L4604f Wix 33899	1.00
- Test drive		Ca9516 Air Filter Lbf Laf1646 Wix 42731	1.00
- Service A/c evaporator		15/40 Oil	15.00
- Shop Supplies		6984 Evapor Cleaner Evaporator Cleaner	1.00
		Coolant Bottle	1.00
		Cap	1.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
		Used Firex Refurbed Fire Extingshers	1.00
		Group 65 Battery (mtc Bxt-65-850)	2.00
		2660 Marker Light Red Oblong Led	1.00
		Antifreeze Ext/life All Makes (peak 407)	2.00
Hours 12.50	Labor: 750.00	Parts: 545.80	Total: 1,295.80
:			

---

<b>Workorder:</b> 1203972	<b>Meter:</b> 46770	<b>In Date:</b> 04/20/2012	<b>Closed:</b> 04/26/2012
<b>Problem:</b> R/R blowout			
- Tire Service Northbound 95 north of Blue Herron - R/r blowout			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1203973	<b>Meter:</b> 46770	<b>In Date:</b> 04/20/2012	<b>Closed:</b> 04/26/2012
<b>Problem:</b> service			
- Tire Service i95 nb north of Blue Heron Blvd - service			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1205356	<b>Meter:</b> 47541	<b>In Date:</b> 06/07/2012	<b>Closed:</b> 06/18/2012
<b>Problem:</b> sway bar bushings			
- Install sway bar bushings		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
		Sway Bar Bushing	2.00
Hours 1.00	Labor: 60.00	Parts: 29.72	Total: 89.72
:			
<b>Workorder:</b> 1205953	<b>Meter:</b> 47541	<b>In Date:</b> 06/25/2012	<b>Closed:</b> 06/29/2012
<b>Problem:</b> Shifter			
- replace shift lever		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 2.50	Labor: 150.00	Parts: 2.00	Total: 152.00
:			
<b>Workorder:</b> 1301695	<b>Meter:</b> 52122	<b>In Date:</b> 02/19/2013	<b>Closed:</b> 03/04/2013
<b>Problem:</b> pm service			
- pm service		<b>Parts List</b>	<b>Qty</b>
- replace hitch safety pin and tighten bolts		15-40 Oil	15.00
- service winch		Oil Filter	1.00
- r&r left marker light and repair ground		Napagold Fuel Filter	1.00
- replace missing bolts for front splash shield		18410 Pintle Pin	1.00
- road test		L0135-063 Lubriplate	1.00
- Shop Supplies		31-22 Wiper Blades 22	2.00
		Shop Supplies	1.00
Hours 8.50	Labor: 510.00	Parts: 133.07	Total: 643.07
:			
<b>Workorder:</b> 1302205	<b>Meter:</b> 52122	<b>In Date:</b> 03/05/2013	<b>Closed:</b> 03/08/2013
<b>Problem:</b> adjust hitch to fit stumper hitch			
- Adjust hitch height on truck			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			
<b>Workorder:</b> 1307296	<b>Meter:</b> 55626	<b>In Date:</b> 07/22/2013	<b>Closed:</b> 08/06/2013
<b>Problem:</b> Won't go over 30			
- scan for codes replace fuel filters and fuel pump		<b>Parts List</b>	<b>Qty</b>
- replace fuel injectors 2,4,6,8		Napagold Fuel Filter	1.00
- replace oil and filter		Pm-22-a Additive Dies	1.00
- test drives		Injector Nozzle	4.00
- Shop Supplies		Injector Tube	1.00
		Pum Asy	1.00
		Napagold Air Filter	1.00
		15-40 Oil	15.00
		Napagold Oil Filter	1.00
		Shop Supplies	1.00
Hours 19.00	Labor: 1,140.00	Parts: 2,086.30	Total: 3,226.30
:	0		



**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1307300      **Meter:** 55548      **In Date:** 07/22/2013      **Closed:** 07/22/2013  
**Problem:** Only drives up to 30 MPH and won't shift

- Tow From: Nw corner Lantana/congress To: He Shop

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1310623      **Meter:** 58063      **In Date:** 10/23/2013      **Closed:** 11/25/2013  
**Problem:** pm service

- pm service	<b>Parts List</b>	<b>Qty</b>
- clean evap and box	15-40 Oil	15.00
- test charging system replace batteries	Napagold Oil Filter	1.00
- trans pm	Napagold Fuel Filter	1.00
- service transfer case	Wiper Blade	2.00
- fab/weld rear tool boxes and decking	Air Freshener	1.00
- Shop Supplies	Battery	2.00
	Evap Odor Elinitator	1.00
	Ft145 Trans Filter In	1.00
	Ft144 Trans Filter Sc	1.00
	Syn-atf Trans Fluid S	9.00
	Syn-atf Trans Fluid S	3.00
	Napa Gal 15w40	3.00
	Napa Qt 15w40	3.00
	Fuel Filter	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00

Hours 15.00      Labor: 900.00      Parts: 641.83      Total: 1,541.83  
:

---

**Workorder:** 1311395      **Meter:** 57864      **In Date:** 11/12/2013      **Closed:** 11/14/2013  
**Problem:** Replace 1 RF And LRO RRIO

- Replace Rf Lro Rrio Tires	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	3.00
	225/70r195rc Tire Recapped	3.00

Hours 0.00      Labor: 0.00      Parts: 465.47      Total: 465.47  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1406111      **Meter:** 64611      **In Date:** 06/20/2014      **Closed:** 07/10/2014  
**Problem:** P.M.

- P.m.	<b>Parts List</b>	<b>Qty</b>
- Tested and replaced both batteries	Brcf119 Brake Caliper	2.00
- Complete brake job	Brcf120 Brake Caliper	2.00
- R&r Winch cable, and replaced two failed solinodes	Brrf65 Front Rotor Mo	2.00
- R&r failed clock spring & harness	Brrf3 Rear Rotor Moto	2.00
- Replaced Lf tire	Napa Oil Seal	2.00
- Shop Supplies	Ford Original Brake Pads	2.00
	1401 Brake Fluid Bra	3.00
	F81z1001ba Seal Ring	2.00
	Caliper Washer	8.00
	Caliper Bolt Kit	4.00
	75w140 Ford Axle Lube	1.00
	Brake Cleaner	2.00
	Clock Spring	1.00
	Repl Solenoid Term Up	2.00
	Ptex Superbond Sm	1.00
	Crane Cable Fabrication	1.00
	Wd40 16oz	1.00
	15-40 Oil	15.00
	Napagold Oil Filter	1.00
	Fuel Filter	1.00
	Wiper Blade	2.00
	Washer Fl	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
	Mnt153028 Mounted 225/70r195 (153028)	1.00
Hours 24.50	Labor: 1,470.0	Parts: 3,216.06
:	0	Total: 4,686.06

**Workorder:** 1407636      **Meter:** 65425      **In Date:** 08/01/2014      **Closed:** 08/20/2014  
**Problem:** Fuel Leak

- reseal fuel filter housing	<b>Parts List</b>	<b>Qty</b>
- replace Ficm and relay. use laptop for diagnostics	Injector Module	1.00
- test run	Peak Global	1.00
- Shop Supplies	Bigg Degreaser	1.00
	Relay	1.00
	Filter O Ring Kit	1.00
	Shop Supplies	1.00
	Shop Supplies	1.00
Hours 10.50	Labor: 630.00	Parts: 905.95
:		Total: 1,535.95

**Workorder:** 1407877      **Meter:** 65281      **In Date:** 08/01/2014      **Closed:** 08/11/2014  
**Problem:** Leaking fuel

- Tow From: Jpp Maint-nursery To: He			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1411726	<b>Meter:</b> 68586	<b>In Date:</b> 11/19/2014	<b>Closed:</b> 12/03/2014
<b>Problem:</b> Transmission			
- check engine light. found Dtc p0713. remove tras pan and replace Tft sensor and clear codes	<b>Parts List</b>		<b>Qty</b>
	Sensor		1.00
- road test	Transmission Harness		1.00
- coolant leak test. replace degas bottle and fill coolant	Expansion Tank		1.00
- Shop Supplies	Peak Global		1.00
	Coolant Cap		1.00
	Syn-atf Trans Fluid S		9.00
	Ptex Thrd Lck Blue Lg		1.00
	Shop Supplies		1.00
Hours 7.00	Labor: 420.00	Parts: 417.82	Total: 837.82
:			

---

<b>Workorder:</b> 1412716	<b>Meter:</b> 68728	<b>In Date:</b> 12/18/2013	<b>Closed:</b> 12/19/2014
<b>Problem:</b> Transmission issue			
- Tow From: Jpp Admin off 6th ave entrance To: He Shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1412722	<b>Meter:</b> 68764	<b>In Date:</b> 12/19/2014	<b>Closed:</b> 01/02/2015
<b>Problem:</b> Not Running/ PM			
- Pm	<b>Parts List</b>		<b>Qty</b>
- Test Drive	15-40 Oil		15.00
- Shop Supplies	Napagold Oil Filter		1.00
	Fuel Filter		1.00
	Napagold Air Filter		1.00
	Wiper Blade		2.00
	Used Fire X Refurbished		1.00
	Shop Supplies		1.00
Hours 4.50	Labor: 270.00	Parts: 195.71	Total: 465.71
:			

---

<b>Workorder:</b> 1504655	<b>Meter:</b> 71968	<b>In Date:</b> 05/07/2015	<b>Closed:</b> 05/11/2015
<b>Problem:</b> install pumper 10139650 from turn in truck			
- Remove pumper from turn-in truck and install in 10156412	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 4.00	Labor: 240.00	Parts: 2.00	Total: 242.00
:			

---

<b>Workorder:</b> 1504738	<b>Meter:</b> 71986	<b>In Date:</b> 05/11/2015	<b>Closed:</b> 05/13/2015
<b>Problem:</b> fuel cap			
- fuel cap	<b>Parts List</b>		<b>Qty</b>
	Gt195 Gas Cap Stant 1		1.00
Hours 0.50	Labor: 30.00	Parts: 12.77	Total: 42.77
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1506277      **Meter:** 72988      **In Date:** 06/23/2015      **Closed:** 07/22/2015  
**Problem:** PM

	<b>Parts List</b>	<b>Qty</b>
- pm	15-40 Oil	15.00
- pm winch	Napagold Oil Filter	1.00
- replace winch cable. replace control switch with harness	Fuel Filter	1.00
- step board	Napagold Air Filter	1.00
- tighten up loose hitch ball	Wiper Blade	2.00
- rear diff service	Washer FI	1.00
- transfer case service	Brake Cleaner	2.00
- replace cab mounts	Winch Remote Control	1.00
- test run	step assy	1.00
- Shop Supplies	75w140 Ford Axle Lube	6.00
	Ford Transfer Case Fluid	3.00
	Crane Cable Fabrication	1.00
	Insulator	4.00
	Cable Tie	1.00
	Remote Control Socket	1.00
	Insulator	4.00
	Clevis Slip Hook	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 20.00	Labor: 1,200.0	Parts: 1,838.86
:	0	Total: 3,038.86

**Workorder:** 1507152      **Meter:** 72987      **In Date:** 07/17/2015      **Closed:** 07/21/2015  
**Problem:** RF Tire

- Rf flat	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1508595      **Meter:** 73996      **In Date:** 08/27/2015      **Closed:** 08/27/2015  
**Problem:** Tire

	<b>Parts List</b>	<b>Qty</b>
- Replace tire	Shop Supplies	1.00
- Shop Supplies	225/70/9.5 Tire Wheel Assy	1.00
Hours 0.50	Labor: 30.00	Parts: 225.50
:		Total: 255.50

**Workorder:** 1508624      **Meter:** 74094      **In Date:** 08/28/2015      **Closed:** 09/01/2015  
**Problem:** fuel cap

	<b>Parts List</b>	<b>Qty</b>
- fuel cap	Gas Cap Non-locking	1.00
Hours 0.50	Labor: 30.00	Parts: 8.25
:		Total: 38.25

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1511972      **Meter:** 77230      **In Date:** 11/24/2015      **Closed:** 12/18/2015  
**Problem:** Smokes

- scan codes with Ids	<b>Parts List</b>	<b>Qty</b>
- found leaking egr cooler. replace egr valve, decoke intake and rebuild turbo vanes and unison ring., replace oil cooler, and fuel pressure regulator	Cooler	1.00
	Egr Valve	1.00
- cooling system service and replace fan clutch	Kit Oil Cooler	1.00
- replace Rf turn signal	Filter O Ring Kit	1.00
- test run	Intake Manifold Kit	1.00
- Shop Supplies	Gasket	2.00
	Gasket Kit	1.00
	15-40 Oil	15.00
	Napagold Oil Filter	1.00
	Coolant Ford Gold	3.00
	Distilled Water 1gal	3.00
	Brake Cleaner	3.00
	Fuel Pressure Regulator Kit	1.00
	Turbo Drain Tube	1.00
	Clutch Asy	1.00
	Signal Stop Lamp	1.00
	Shop Supplies	1.00
Hours 35.00	Labor: 2,100.00	Parts: 2,606.90
:	0	Total: 4,706.90

**Workorder:** 1512670      **Meter:** 77217      **In Date:** 12/15/2015      **Closed:** 12/16/2015  
**Problem:** 2 Tires

- 2 tires	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1600232      **Meter:** 77242      **In Date:** 01/07/2016      **Closed:** 01/19/2016  
**Problem:** PM

- Pm	<b>Parts List</b>	<b>Qty</b>
- Test drive	22" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Mac Wite Lithium Gres	1.00
	Shop Supplies	1.00
Hours 4.50	Labor: 270.00	Parts: 33.58
:		Total: 303.58

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1602214	<b>Meter:</b> 78587	<b>In Date:</b> 03/02/2016	<b>Closed:</b> 03/18/2016
<b>Problem:</b> No Start			
- no start. check charging system		<b>Parts List</b>	<b>Qty</b>
- replace 2 batteries		Battery	2.00
- replace alternator		Alternator	1.00
- Shop Supplies		Alternator Connector	1.00
		Indicator	1.00
		Napa Qt 15w40	3.00
		Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 635.39	Total: 965.39
:			
<b>Workorder:</b> 1602326	<b>Meter:</b> 78489	<b>In Date:</b> 03/02/2016	<b>Closed:</b> 03/04/2016
<b>Problem:</b> No Starr			
- Tow From: Cty Pines Recl Complex at Samuel Friedland Park To: He shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1603843	<b>Meter:</b> 78744	<b>In Date:</b> 04/12/2016	<b>Closed:</b> 04/27/2016
<b>Problem:</b> Died			
- lcp, lpr remove ldm & exast mount		<b>Parts List</b>	<b>Qty</b>
- Replace coolant res. and hose		Sensor	1.00
- Rs head light		Injector Pressure Reg	1.00
- Connect scan tool to diagnost		Expansion Tank	1.00
- Road Test		Coolant Tank Hose	1.00
- Reinstall winch cable		Distilled Water 1gal	3.00
- Shop Supplies		Peak Global	3.00
		Hook Strap	1.00
		Shop Supplies	1.00
Hours 9.50	Labor: 570.00	Parts: 710.48	Total: 1,280.48
:			
<b>Workorder:</b> 1603968	<b>Meter:</b> 78675	<b>In Date:</b> 04/15/2016	<b>Closed:</b> 04/15/2016
<b>Problem:</b> Transport for repair			
- Tow From: Sr 710 west of Jupiter To: Fleet He			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1604107	<b>Meter:</b> 78675	<b>In Date:</b> 04/19/2016	<b>Closed:</b> 04/19/2016
<b>Problem:</b> wont start			
- Tow From: on site move			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1604626      **Meter:** 78919      **In Date:** 05/02/2016      **Closed:** 05/13/2016  
**Problem:** Brake pedal leak

- Replace booster and master cyl.	<b>Parts List</b>	<b>Qty</b>
- Service coolant	Brake Booster	1.00
- Test Dr	master cylinder	1.00
- Shop Supplies	B Fluid Dot 3-32oz	1.00
	brake fluid	1.00
	Peak Global	2.00
	Shop Supplies	1.00

Hours 8.50      Labor: 510.00      Parts: 701.21      Total: 1,211.21  
:

**Workorder:** 1604628      **Meter:** 78854      **In Date:** 05/02/2016      **Closed:** 05/02/2016  
**Problem:** Accident Damage to door @ the BIWA Pavillion

- Tow From: Morikami Park  
Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1609555      **Meter:** 82210      **In Date:** 09/14/2016      **Closed:** 10/12/2016  
**Problem:** Fuel Cap

	<b>Parts List</b>	<b>Qty</b>
- Fuel cap	Gas Cap Non-locking	1.00
- Pm	oring gasket intake	1.00
- Replace high presure oil pump	Distilled Water 1gal	1.00
- Replace engine oil cooler	Peak Global Antifrz	3.00
- Coolent service	Hose Made	1.00
- Perform high side and low side oil test. Scan codes	15-40 Oil	15.00
- To Mako	Napagold Oil Filter	1.00
- Tow vehicle to shop	Fuel Filter	1.00
- Tighten hitch	Napagold Air Filter	1.00
- Pm winch	Wiper Blade	2.00
- Replace front shocks. Had to cut off old shocks	Washer Fluid Concentr	1.00
- R&r steering shock	Non-chlor Brake Clnr	4.00
- Replace front bumper stops	Pump Assembly	1.00
- Service trans	Kit Oil Cooler	1.00
- Road test	Gasket	2.00
- R&r Lri tire	Turbo Hose Connector	1.00
- Shop Supplies	Gasket Kit	1.00
	Pump Fitting Kit	1.00
	Kit Gasket	1.00
	Ptex Ultra Grey 3oz	1.00
	Turbo Clamp	1.00
	front shock	2.00
	Dampner	1.00
	Bumper Stop	2.00
	Screen Asy	1.00
	Trans Pan Gasket	1.00
	Syn-atf Trans Fluid S	10.00
	Filter	1.00
	Seal	1.00
	225/70 R19.5 New He Only	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00

Hours 50.00      Labor: 3,000.0      Parts: 2,777.20      Total: 5,777.20  
:

**Workorder:** 1609759      **Meter:** 82043      **In Date:** 09/16/2016      **Closed:** 09/19/2016  
**Problem:** stop running

- Tow From: 6th and congress

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1610507      **Meter:** 82242      **In Date:** 10/07/2016      **Closed:** 10/12/2016  
**Problem:** no start

- Tow From: congress and donnelly dr, lake worth To: lv shop

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 1610545      **Meter:** 82309      **In Date:** 10/12/2016      **Closed:** 10/27/2016  
**Problem:** No Start

- replace lpr valve and connector
- road test
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Injector Pressure Reg	1.00
Wiring Harness	1.00
Shop Supplies	1.00

Hours 4.00      Labor: 240.00      Parts: 290.86      Total: 530.86  
:

**Workorder:** 1702584      **Meter:** 86264      **In Date:** 03/14/2017      **Closed:** 04/07/2017  
**Problem:** PM

- Pm
- Pm Winch
- Test run
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
15-40 Oil	15.00
Napagold Oil Filter	1.00
Fuel Filter	1.00
Napagold Air Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	3.00
Shop Supplies	1.00

Hours 6.00      Labor: 360.00      Parts: 193.82      Total: 553.82  
:

**Workorder:** 1704899      **Meter:** 86370      **In Date:** 04/06/2017      **Closed:** 05/17/2017  
**Problem:** Damage to right front door, fender & fender flare

- Damage to right front door, fender & fender flare

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1709814      **Meter:** 89878      **In Date:** 10/06/2017      **Closed:** 10/20/2017  
**Problem:** pm/list

	<b>Parts List</b>	<b>Qty</b>
- pm		
- pm winch	15-40 Oil	15.00
- free broken starter assembly and remove bolts. R&r starter	Napagold Oil Filter	1.00
- replace failed steering dampner	Fuel Filter	1.00
- road test	Napagold Air Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Non-chlor Brake Clnr	3.00
	Starter Motor	1.00
	Dampner	1.00
	Used Fire X Refurbished	1.00
	Bolt	4.00
	Bolt	4.00
	Shop Supplies	1.00
Hours 16.00	Labor: 960.00	Parts: 780.31
:		Total: 1,740.31

**Workorder:** 1709849      **Meter:** 89767      **In Date:** 10/05/2017      **Closed:** 10/06/2017  
**Problem:** Cranks but want start

- Tow From: Jpp Nursery To: He Shop

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1710391      **Meter:** 89899      **In Date:** 10/23/2017      **Closed:** 10/25/2017  
**Problem:** tire

- Tire

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1711140      **Meter:** 90412      **In Date:** 11/09/2017      **Closed:** 01/04/2018  
**Problem:** Overheating

- R&r turbo and cleaned, replaced Egr cooler, cleaned carbon from intake. Replaced Egr valve, updated turbo feed line,and Flush cooling system
- Replace Batteries
- Road test
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Distilled Water 1gal	3.00
Cooler	1.00
Egr Valve	1.00
Gasket Kit	1.00
Gasket	4.00
Kit Oil Cooler	1.00
Hose Clamp	1.00
Air Duct	1.00
elem kit filter	1.00
Turbo Drain Tube	1.00
Turbo Connection	2.00
Turbo Actuator	1.00
Big G Degreaser 1 Gal	1.00
Masking Tape 388n48mm	1.00
Napagold Oil Filter	1.00
fuel kit	1.00
Sensor	1.00
Regulator	1.00
Bolt	1.00
Turbo Ring	1.00
Tube Assembly	1.00
connection	1.00
Ptex Superbond Sm	1.00
Battery	2.00
Coolant Ford Gold	2.00
Bushing	1.00
Shop Supplies	1.00

Hours 41.50      Labor: 2,490.0      Parts: 3,457.28      Total: 5,947.28  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1801914      **Meter:** 92295      **In Date:** 02/20/2018      **Closed:** 04/20/2018  
**Problem:** Coolent leak

<ul style="list-style-type: none"> <li>- Replace radiator,hoses, Water pump and fan</li> <li>- Ac evacuate and recharge</li> <li>- R&amp;r turbo and replace lower exast pipes</li> <li>- Pm</li> <li>- Test run</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Radiator</li> <li>Radiator Hose</li> <li>Hose</li> <li>1gal Rtu Antifreeze</li> <li>Hose Clamp</li> <li>Clutch Asy</li> <li>Water Pump</li> <li>16.5 Oz Aero Kroil</li> <li>Drive Belt</li> <li>Coolant Ford Gold</li> <li>gasket</li> <li>adaptor pipe</li> <li>151.26</li> <li>bolt</li> <li>lock nut</li> <li>High Pressure Oil Pump Tube</li> <li>tube asy</li> <li>Napagold Oil Filter</li> <li>Napagold Air Filter</li> <li>Fuel Filter</li> <li>Wiper Blade</li> <li>Washer Fluid Concentr</li> <li>15-40 Oil</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>5.00</li> <li>4.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>3.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>12.00</li> <li>12.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>15.00</li> <li>1.00</li> </ul>	
Hours 22.50 :	Labor: 1,350.00 0	Parts: 2,745.35	Total: 4,095.35

**Workorder:** 1801932      **Meter:** 92007      **In Date:** 02/16/2018      **Closed:** 02/22/2018  
**Problem:** coolant leak

- Tow From: Karen marcus pk-a1a north of ocan bluff blvd  
 To: 2601 vista

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 1805243      **Meter:** 93998      **In Date:** 05/22/2018      **Closed:** 06/05/2018  
**Problem:** AC/ Rear end bounce

<ul style="list-style-type: none"> <li>- Tested and replaced blower motor</li> <li>- Test drive and look for shimmy. Did'nt find anything</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>blower wheel</li> <li>Blower Motor</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 3.50 :	Labor: 210.00	Parts: 164.17	Total: 374.17

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1807401      **Meter:** 95362      **In Date:** 07/20/2018      **Closed:** 08/07/2018  
**Problem:** Horn, Tail lights

	<b>Parts List</b>	<b>Qty</b>
- R&r left front turn signal	Signal Stop Lamp	1.00
- test horn. replace bad horn switch in steering wheel	horn pad	1.00
- trans shifter loose. replace bushings in column	F3tz71278a Bushing Sh	2.00
- Shop Supplies	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 516.22
:		Total: 756.22

**Workorder:** 1808213      **Meter:** 95445      **In Date:** 08/09/2018      **Closed:** 08/29/2018  
**Problem:** Turbo

	<b>Parts List</b>	<b>Qty</b>
- Diagnost no boost from turbo, ck all hoses and plumbing, found bad turbo and removed. Unison ring for Vgt vanes was stuck. Tested actuator and replaced turbo.	Spark Plug	8.00
- Replaced Map, Ebp sensor and tube. Baro sensor reading 7.3psi not matching pump Dtc P0069. Boro reading is 15.5 found damaged harness.	Sensor	2.00
- Replaced engine wire harness	Key	1.00
- Replace coolent degas bottle and flushed cooling system	Coolant Tank Hose	1.00
- Pm	Air Duct	1.00
- Winch Pm	Gasket Kit	1.00
- Drver side headlight	Pcv Tube Kit	1.00
- Tested and replaced batteries	Valve Cover Gasket	2.00
- Road test	clamp	2.00
- Replaced Pcm and reprogram. Bad wirring damaged Pcm	Torbu Assy	1.00
- Shop Supplies	Turbo Clamp	2.00
	Expansion Tank	1.00
	Oil Temp Sensor	1.00
	Barometric Pressure Sensor	1.00
	Sensor	1.00
	Injector Harness	1.00
	Engine Wire Harness	1.00
	Indicator	1.00
	Halogen Sealed Beams	1.00
	Battery 65	2.00
	Grime Away	1.00
	Brush	1.00
	Prussian Blue	1.00
	Super Glue	1.00
	15-40 Oil	15.00
	Fuel Filter	1.00
	Napagold Air Filter	1.00
	Napagold Oil Filter	1.00
	Washer Fluid Concentr	1.00
	Wiper Blade	2.00
	Module	1.00
	Shop Supplies	1.00
Hours 56.00	Labor: 3,360.0	Parts: 5,831.05
:	0	Total: 9,191.05

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1909117      **Meter:** 103282      **In Date:** 08/30/2019      **Closed:** 08/30/2019

**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00  
:

Labor: 134.00

Parts: 0.00

Total: 134.00