

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 446007

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts		
In Date: 05/27/2004	Hours	Description	Quantity	
- Pre-Delivery Inspection	2.00			
Parts Charge:	0.00	Labor Charge:	100.00	

Workorder: 533102

Problem: 1 800 AUTO TOW FLORIDA INC 50111023

Meter Reading: 0	Labor	Parts		
In Date: 01/11/2005	Hours	Description	Quantity	
- 1 800 Auto Tow Florida Inc 50111023 Tow From Vetrens Park-9400 W.Palmetto Pk Rd - Tow To Se/Tire Shop				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 78.00

Workorder: 533104

Problem: 1 800 AUTO TOW FLORIDA INC 50111023

Meter Reading: 0	Labor	Parts		
In Date: 01/11/2005	Hours	Description	Quantity	
- 1 800 Auto Tow Florida Inc 50111023 Tow From 9400 W Palmetto Park Rd - Tow To Se Shop				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 78.00

Workorder: 533130

Problem: L/R TIRE BLOWN

Meter Reading: 1	Labor	Parts		
In Date: 01/12/2005	Hours	Description	Quantity	
- Tire Repair	1.00	SHOP SUPPLIES		1.00
- Shop Supplies				
Parts Charge:	4.00	Labor Charge:	50.00	

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 536711

Problem: FUEL CAP/CLUCTH NOT DISENGAGING PROPERLY/NEW BLADETEETH

Meter Reading: 86	Labor	Parts	
In Date: 02/18/2005	Hours	Description	Quantity
- R/R Teeth And Bolts	5.30	TEETH 92939-001	20.00
- Replace Fuel Cap		TEETH 92939-003	2.00
- Shop Supplies		POCKET 92940-003	21.00
		SHOP SUPPLIES	1.00
			1.00
		POCKET 92940-001	21.00
		FUEL/CAP 145525-001	1.00
		BOLT 93300-001	42.00
		TEETH 92939-02	20.00
Parts Charge:	1,132.03	Labor Charge:	265.00

Workorder: 544115

Problem: CLUTCH WONT ENGUAGE

Meter Reading: 98	Labor	Parts	
In Date: 05/06/2005	Hours	Description	Quantity
- Pm Service	10.50	A/FILTER 220166005	1.00
- Pm Trailer Section Single Axle		HYD/FILTER 2683001	1.00
- Replace Guard Shock Absorber		FUEL/FILTER 53629013	1.00
- Service Upper And Lower Gear Boxes		SHOCK/ABSORBER 142445001	1.00
- Test Run To Confirm Complaint		SHOP SUPPLIES	1.00
- Shop Supplies		42385 SEAL	2.00
			1.00
		OIL/FILTER 140105001	1.00
		12345841 GEAR OIL SYNTHETIC 75W-90	3.00
		15/40 OIL	11.00
		G5/16 FUEL FILTER USE G2	1.00
Parts Charge:	270.23	Labor Charge:	525.00

1/3/2017  
4:36:05PM

Palm Beach County Fleet Management  
Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 550005

Problem: CONTAMINATED FUEL

Meter Reading: 105	Labor	Parts		
In Date: 07/12/2005	Hours	Description	Quantity	
- Siphon Fuel From Tank/Clean And Refill	2.50	SHOP SUPPLIES	1.00	
- Test Run				
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	125.00	

Workorder: 558837

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts		
In Date: 11/07/2005	Hours	Description	Quantity	
- Tiresoles Of Broward Inc				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 54.00

Workorder: 558842

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts		
In Date: 11/07/2005	Hours	Description	Quantity	
- Tiresoles Of Broward Inc				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 113.34

Workorder: 559232

Problem: CLUTCH STAYS ENGAUGED/STARTS W/CUTTER WHEEL RUNNINBROKEN CUTTER TEETH

Meter Reading: 136	Labor	Parts		
In Date: 12/07/2005	Hours	Description	Quantity	
- Actuator Control Stuck In Engauge Position Install Clutch Actuator Kit.	6.00	CLUTCH KIT IKO11113	1.00	
- Replaced Broken Cutter Teeth		SHOP SUPPLIES	1.00	
- Test Run				
- Shop Supplies				
Parts Charge:	799.93	Labor Charge:	300.00	

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

**Workorder:** 632736

**Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts
In Date: 01/03/2006	Hours	Description
Close Date: 01/12/2006		Quantity
- Tiresoles Of Broward Inc		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 60.00

**Workorder:** 633554

**Problem:** R/R LIGHT OUT

Meter Reading: 153	Labor	Parts
In Date: 01/31/2006	Hours	Description
Close Date: 01/31/2006		Quantity
- Repair Wire Harness R/R Light Assembly And Clean Male Plug Connections	1.50	SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 75.00	

**Workorder:** 634455

**Problem:** WHEEL VIBRATION & TOOTH MISSING

Meter Reading: 170	Labor	Parts
In Date: 02/14/2006	Hours	Description
Close Date: 02/24/2006		Quantity
- Clean Blade And Wheel Of Debris	14.50	THROW-OUT BEARING 180007117 1.00
- Replace All Teeth And Pockets W/Bolts		CLUTCH DISC 140343001 1.00
- R & R Clutch Housing And Replace Clutch Pressure Plate And Throw Out Bearing		PRESSURE/PLATE 1419001 1.00
- Test Run To Confirm Repair		SHOP SUPPLIES 1.00
- Shop Supplies		SCREW 93300001 42.00
		TOOTH 92939003 2.00
		85/140 GEAR OIL GEAR LUBE 15.00
		TOOTH 92939002 20.00
		TOOTH 92939001 20.00
		POCKET 92940001 21.00
		POCKET 92940003 21.00
		1.00
Parts Charge: 1,933.68	Labor Charge: 25.00	Commercial Charge: 92.70

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 638393		Problem: 001 DETAIL VEHICLE		04/19/06	
Meter Reading: 0		Labor		Parts	
In Date: 04/19/2006		Close Date: 05/03/2006		Hours	
		Description		Quantity	
- 001 Detail Vehicle		04/19/06			
Parts Charge:		0.00		Labor Charge: 0.00	
				Commercial Charge: 7.14	
Workorder: 638999		Problem: TIRESOLES OF BROWARD INC			
Meter Reading: 0		Labor		Parts	
In Date: 04/19/2006		Close Date: 05/10/2006		Hours	
		Description		Quantity	
- Tiresoles Of Broward Inc					
Parts Charge:		0.00		Labor Charge: 0.00	
				Commercial Charge: 125.66	
Workorder: 639010		Problem: TIRESOLES OF BROWARD INC			
Meter Reading: 0		Labor		Parts	
In Date: 04/19/2006		Close Date: 05/10/2006		Hours	
		Description		Quantity	
- Tiresoles Of Broward Inc					
Parts Charge:		0.00		Labor Charge: 0.00	
				Commercial Charge: 54.00	
Workorder: 639482		Problem: RIGHT TAIL LIGHT OUT			
Meter Reading: 208		Labor		Parts	
In Date: 05/18/2006		Close Date: 05/25/2006		Hours	
		Description		Quantity	
- Replace Light Repair Wiring		2.00		40202R TAIL LIGHT 4" RED (GROTE 52772)	
- Check Both Tires For Leaks Air Pressure All Ok				SHOP SUPPLIES	
- Shop Supplies					
Parts Charge:		7.61		Labor Charge: 25.00	

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 642174

Problem: P.M.

Meter Reading: 238		Labor		Parts	
In Date: 07/11/2006	Close Date: 07/24/2006	Hours	Description		Quantity
- Pm Eqpt		13.50	G5/16 FUEL FILTER USE G2		1.00
- Pm Trailer Single Axle			LITE M439		1.00
- Replace Battery			SEAL 42385		2.00
- Replace Teeth			F/FILTER 53629013		1.00
- Test Run			HP31E BATTERY GROUP 31 POST		1.00
- Shop Supplies			TEETH 10013096		20.00
			15/40 OIL		11.00
			BLD/BOLT 9330001		42.00
			POCKET 92940003		21.00
			SHOP SUPPLIES		1.00
			A/FILTER 220166005		1.00
			OIL/FILTER 140102001		1.00
			TEETH 92939001		20.00
			TEETH 10013095		2.00
			POCKET 92940001		21.00
Parts Charge:		1,216.61	Labor Charge:	25.00	

Workorder: 644651

Problem: TEETH MISSING/BRAKE WIRE PROBLEM

Meter Reading: 258		Labor		Parts	
In Date: 08/25/2006	Close Date: 08/31/2006	Hours	Description		Quantity
- Replace Missing Set Of Teeth & Sockets		3.50	SHOP SUPPLIES		1.00
- Replace Damaged Break Away Wire (Fabricate New Wire) And Bracket					
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	75.00	

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

**Workorder:** 735320

**Problem:** PM SERVICE. BOGS DOWN UNDER LOAD. HARD START WHEN COLD. NEW TEETH.

Meter Reading: 321		Labor		Parts	
In Date: 03/07/2007	Close Date: 03/19/2007	Hours	Description		Quantity
- R/R Teeth And Belts		8.00	53629013 FUEL FILTER		1.00
- R/R Filter System, Clean R/R Filters			92939002 TOOTH RIGHT		20.00
- Test Run Only Not Able To Duplicate Stump Grinding			92940001 PRO POCKETS		21.00
- Shop Supplies			93300001 CAP SCREW		42.00
			220166005 AIR FILTER		1.00
			3032 FUEL FILTER 5/16" FRM G2 WIX 33032		1.00
			SHOP SUPPLIES		1.00
			92940003 THREADED PO C		21.00
			92939001 TOOTH L/F		20.00
			92939003 TOOTH PRO ST		2.00
Parts Charge: 1,091.63		Labor Charge: 55.00			

**Workorder:** 743999

**Problem:** CLUTCH NOT ENGAGING, BOGGS DOWN, TEETH MISSING

Meter Reading: 356		Labor		Parts	
In Date: 09/12/2007	Close Date: 09/27/2007	Hours	Description		Quantity
- Pm Service		16.50	15/40 OIL		11.00
- R/R Clutch Assy Pilot Throwout Bearing Pressure Plate			OIL FILTER 140105001		1.00
- R/R 1 Tooth			FUEL FILTER 53629013		1.00
- Pm			AIR FILTER 220166005		1.00
- R/R Trl Plug And Ck Wiring			PRESSURE PLATE 1419001		1.00
- R/R Outer Bearing I Race Both Side					1.00
- Test Run			3032 FUEL FILTER 5/16" FRM G2 WIX 33032		1.00
- Shop Supplies			85/140 GEAR OIL GEAR LUBE		15.00
			CLUTCH DISK 140343001		1.00
			SHOP SUPPLIES		1.00
			RIGHT TOOTH 92939002		1.00
			67048 BEARING TIMKEN USE SET 6		2.00
			SLEEVE 180007117		1.00
			755-5046 MALE CONNECTOR		1.00
			BEARING 1730001		1.00
			LEFT TOOTH 92939001		1.00
Parts Charge: 1,122.23		Labor Charge: 27.50			

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 844926

Problem: PM SERVICE,BOGGS UNDER LOAD,REPLACE CUTTER TEETH

Meter Reading: 411		Labor		Parts	
In Date: 10/01/2008	Close Date: 10/07/2008	Hours	Description		Quantity
- Pm Service		17.50	15/40 OIL		11.00
- Pm Trailer			AIR FILTER		1.00
- Replaced R/Side Tire			OIL FILTER		1.00
- Repalce All Cutter Teeth And Bolts			FUEL FILTER		1.00
- Replaced Rear Brakes			3032 FUEL FILTER 5/16" FRM G2 WIX 33032		1.00
- Repair Broken Wiring To Tag Light			42385 SEAL		2.00
- Test Run			TIRE DISPOSAL FEE		1.00
- Shop Supplies			TIRE 875X16.5 E-10PL		1.00
			LEFT TOOTH		15.00
			HYD FILTER		1.00
			RIGHT TOOTH		8.00
			LH ELEC BRAKE ASSY		1.00
			RH ELEC BRAKE ASSY		1.00
			POCKET		21.00
			SCREW		24.00
			SHOP SUPPLIES		1.00
			POCKET		18.00
Parts Charge:		1,476.04	Labor Charge:	30.00	

Workorder: 934686

Problem: REPLACE WINDSHIELD, ORDER CUTTER TEETH

Meter Reading: 411		Labor		Parts	
In Date: 03/03/2009	Close Date: 03/19/2009	Hours	Description		Quantity
- Set Up Commercial Repair Charley'S Glass		7.50	LEFT TOOTH		20.00
- Replace Cutter Teeth			TOOTH - PRO S		2.00
- Repair Relay Block And Run New Harness To Clutch			RIGHT TOOTH		20.00
Activator			PRO POCKET		21.00
- Shop Supplies			BOLT		40.00
			SHOP SUPPLIES		1.00
			THREADED POCKET		21.00
			BOLT		12.00
			72241 RELAY 30/40A (IMPERIAL)		2.00
Parts Charge:		1,272.33	Labor Charge:	450.00	Commercial Charge: 240.00

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

**Workorder:** 935117

**Problem:** HYDRALIC LEAK

<b>Meter Reading: 411</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/13/2009	<b>Close Date:</b> 03/16/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- R/R Split Hyd Hose Check For Leaks		<b>3.50</b>	AW68 HYDRO FLUID HYDRAULIC OIL 68	4.00	
- Travel To Have Hose Made			SHOP SUPPLIES	1.00	
- Wash Spilled Hyd Oil Off					
- Shop Supplies					
<b>Parts Charge:</b>		12.33	<b>Labor Charge:</b>	210.00	<b>Commercial Charge:</b> 26.69

**Workorder:** 938514

**Problem:** BREAK AWAY CABLE BROKEN

<b>Meter Reading: 411</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/02/2009	<b>Close Date:</b> 06/03/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Replace Break Away Device		<b>1.00</b>	SHOP SUPPLIES	1.00	
- Shop Supplies			004098 BREAKAWAY SWITCH	1.00	
<b>Parts Charge:</b>		11.09	<b>Labor Charge:</b>	60.00	

**Workorder:** 940990

**Problem:** NEEDS TWO TIRES

<b>Meter Reading: 411</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/13/2009	<b>Close Date:</b> 07/20/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- John Prince Park Maint					
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 253.92

**Workorder:** 940998

**Problem:** SERVICE

<b>Meter Reading: 411</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/20/2009	<b>Close Date:</b> 07/20/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Jpp					
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 72.00

1/3/2017  
4:36:05PM

Palm Beach County Fleet Management  
Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 941316

Problem: CLUTCH NOT WORKING

Meter Reading: 411	Labor	Parts		
In Date: 07/28/2009	Hours	Description	Quantity	
- Repair Open Circuit In Pto Clutch Circuit	2.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	120.00	

Workorder: 944574

Problem: PM Service

Meter Reading: 411	Labor	Parts		
In Date: 10/15/2009	Hours	Description	Quantity	
- Pm Service	9.00	3032 FUEL FILTER 5/16" FRM G2 WIX 33032	1.00	
- Repalce Trailer Plug		755-5046 MALE CONNECTOR	1.00	
- Service Trailer 10/15		15/40 OIL	11.00	
- Fabricate New Cable For Breakaway Swich		AIR FILTER	1.00	
- Shop Supplies		Oil Filter	1.00	
		FUEL FILTER	1.00	
		SHOP SUPPLIES	1.00	
		42385 SEAL	2.00	
		HYD FILTER	1.00	
Parts Charge:	115.66	Labor Charge:	540.00	

Workorder: 1003843

Problem: FUEL PROBLEMS / ENGAGE CLUTCH PROBLEMS / NEEDS TEETH

Meter Reading: 411	Labor	Parts		
In Date: 04/14/2010	Hours	Description	Quantity	
- Replace Fuel Filter (Contaminted) Drain Fuel Tank And Clean	9.00	3032 FUEL FILTER 5/16" FRM G2 WIX 33032	1.00	
- Repair Open Circuit In Power Supply To Clutch Toggle Switch		STRAIGHT TOOTH	6.00	
- Replace Teeth On Cutting Wheel		BOLTS	48.00	
- Replace Damaged Fuel Gauge Cap		LEFT TOOTH	21.00	
- Shop Supplies		FUEL FILTER	1.00	
		SHOP SUPPLIES	1.00	
		THREADED POCKETS	12.00	
		FUEL GAUGE CAP	1.00	
		PRO POCKET	12.00	
		RIGHT TOOTH	21.00	
Parts Charge:	1,137.86	Labor Charge:	540.00	

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

**Workorder:** 1004607

**Problem:** dead battery

<b>Meter Reading: 468</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/04/2010	<b>Close Date:</b> 05/05/2010	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Replace Battery, Wont Hold A Charge	<b>1.00</b>	GROUP 31 POST BATTERY (ACD 31-901CT)		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 139.61		<b>Labor Charge:</b> 60.00			

**Workorder:** 1005478

**Problem:** fuel filter

<b>Meter Reading: 468</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/26/2010	<b>Close Date:</b> 06/29/2010	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Drain Fuel From Tank And Clean	<b>8.00</b>	SHOP SUPPLIES		1.00
-	Remove And Replace Panels To Gain Access To Engine		FREIGHT		1.00
-	Remvoe And Test Fuel Shut Down Solenoid		3032 FUEL FILTER 5/16" FRM G2 WIX 33032		1.00
-	Shop Supplies		GASKET		1.00
			FUEL SHUT OFF SOLENOID		1.00
			3031 FUEL FILTER 1/4" FRM G1 WIX 33031		1.00
<b>Parts Charge:</b> 412.73		<b>Labor Charge:</b> 480.00			

**Workorder:** 1014111

**Problem:** PM

<b>Meter Reading: 485</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/28/2010	<b>Close Date:</b> 01/31/2011	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Pm	<b>10.50</b>	FUEL FILTER		1.00
-	Trailer Pm		OIL FILTER		1.00
-	Replaced L&R Rear Grand Flaps		CA8737 AIR FILTER LBF LAF4544 WIX 46562		1.00
-	Replaced Inner And Outer Wheel Bearing R/Side		REAR DECK SIDE CURTAIN		2.00
-	Repair Wirign For L/Rear Brake		FREIGHT		1.00
-	Fabricate Cable For Breakaway Switch 12/30		25520 RACE		1.00
-	Shop Supplies		42385 SEAL		2.00
			3032 FUEL FILTER 5/16" FRM G2 WIX 33032		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			15/40 OIL		11.00
			SET 6 BEARING SET 67010 67048 (TIMKEN)		1.00
			SHOP SUPPLIES		1.00
			CA8737SY AIR FILTER WIX 46569		1.00
			25580 BEARING		1.00
<b>Parts Charge:</b> 278.42		<b>Labor Charge:</b> 630.00			

1/3/2017  
4:36:05PM

Palm Beach County Fleet Management  
Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 1105475

Problem: clutch stays engaged

Meter Reading: 496	Labor	Parts		
In Date: 05/24/2011	Hours	Description	Quantity	
- Repair Feed Wire To Clutch Actuator Relays	1.50	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	90.00	

Workorder: 1108732

Problem: wheel bearing

Meter Reading: 496	Labor	Parts		
In Date: 08/18/2011	Hours	Description	Quantity	
- Replace Left Side Wheel Bearings ,Seals ,Hub Drum	5.50	INNER BEARING	1.00	
Washer And Lock Nut		OUTER BEARING	1.00	
- Fm To Jpp		WASHER	1.00	
- Shop Supplies		LOCKNUT	1.00	
		HUB & DRUM ASSY	1.00	
		FREIGHT	1.00	
		SHOP SUPPLIES	1.00	
		WHEEL SEAL	1.00	
		45896 GREASE CAP	1.00	
Parts Charge:	290.02	Labor Charge:	330.00	

Workorder: 1109653

Problem: SAFETY PIN / BRAKE CABLE / TAG LIGHT

Meter Reading: 496	Labor	Parts		
In Date: 09/09/2011	Hours	Description	Quantity	
- Ck Replace Hitch Pintle Pin (Lost)	2.50	18410 PINTLE PIN	1.00	
- Replace Damaged Tag Light		TAG LIGHT	1.00	
- Repair Breakaway Cable		SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	13.82	Labor Charge:	150.00	

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

**Workorder:** 1110850

**Problem:** replace teeth / clutch won't disengage / see request

<b>Meter Reading: 511</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/12/2011	<b>Close Date:</b> 10/27/2011	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Replace All Teeth And Pockets	6.50	LEFT TOOTH		20.00
-	Repair Electrical Supply Circuit For Electric		RIGHT TOOTH		20.00
-	Repair Rt Side Tail Lite Wire Harness		PRO POCKET		21.00
-	Inspect And Adjust Brakes		BOLT		42.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			FREIGHT		1.00
			STRAIGHT TOOTH		2.00
			THREADED POCKET		21.00
<b>Parts Charge:</b> 1,316.55		<b>Labor Charge:</b> 390.00			

**Workorder:** 1111519

**Problem:** REPLACE BOTH TIRES

<b>Meter Reading: 511</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/26/2011	<b>Close Date:</b> 10/31/2011	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Se Shop				
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 44.70		

**Workorder:** 1200136

**Problem:** tires

<b>Meter Reading: 516</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 01/05/2012	<b>Close Date:</b> 01/05/2012	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Tire Service Vista		- Tires		
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 304.66		

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 1200997

Problem: pm service

Meter Reading: 519		Labor		Parts	
In Date: 01/31/2012	Close Date: 02/08/2012	Hours	Description		Quantity
- Pm Service		10.50	CA8737 AIR FILTER LBF LAF4544 WIX 46562		1.00
- Hyd Service			OIL FILTER		1.00
- Service Trailer			FUEL FILTER		1.00
- Replace Trailer Plug			42385 SEAL		2.00
- Replaced Breakaway Switch And Repair Wire			AW68 HYDRO FLUID HYDRAULIC OIL 68		2.00
- Shop Supplies			3032 FUEL FILTER 5/16" FRM G2 WIX 33032		1.00
			755-5046 MALE CONNECTOR		1.00
			004098 BREAKAWAY SWITCH		1.00
			SHOP SUPPLIES		1.00
			CA8737SY AIR FILTER WIX 46569		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			15/40 OIL		11.00
Parts Charge:		98.81	Labor Charge:	630.00	

Workorder: 1202575

Problem: clutch problem

Meter Reading: 519		Labor		Parts	
In Date: 03/15/2012	Close Date: 03/23/2012	Hours	Description		Quantity
- Ck Clutch Wirign Damaged Rewire Cutter From Pto		3.00	SHOP SUPPLIES		1.00
Switch And To Clutch Activator			06133 3M ELECTRIC TAPE STOCK #832260101		1.00
- Shop Supplies					
Parts Charge:		6.61	Labor Charge:	180.00	

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

**Workorder:** 1300457

**Problem:** Needs new muffler / protective screen needs replaced

Meter Reading: 537	Labor	Parts		
In Date: 01/14/2013	Hours	Description	Quantity	
- Replace Muffler And Tail Pipe Assy	20.00	NAPAGOLD FUEL FILTER	1.00	
- Ck Clean Unit R&R Engine Cabinet Panels		MUFFLER	1.00	
- Trouble Shoot To Find Fuel Leak At Injector Retorque		FUEL FILTER	1.00	
Injector Line Fitings To Stop Leak		TAIL SPOUT	1.00	
- Pm Service		NAPAGOLD OIL FILTER	1.00	
- Service Trailer		Freight Charge	1.00	
- Replace Missing Tooth Pocket Bolts		42385 SEAL	2.00	
- Repalce Battery Hold Down Bolts		2863 SHACKLE 3-8	2.00	
- Repkalce Console Warnbing Light Assy Missing Covers		BOLT	2.00	
And Bulbs		JACK ASSY	1.00	
- Replace Safety Cheair Hook\S		THREADED POCKET	1.00	
- R&R Breakaway Assy And Adjust		"PRO" POCKET	1.00	
- Replace Windshield		LH BRAKE ASSY	1.00	
- R/R Jack		MARKER LIGHT BULB	1.00	
- Shop Supplies		CA8737SY AIR FILTER W	1.00	
		RH BRAKE ASSY	1.00	
		3/8 CLEVIS SLIP HOOK	2.00	
		SHOP SUPPLIES	1.00	
		FUEL CAP W/ SENDER	1.00	
		LAMINATE PLEXI-GLASS	1.00	
		MARKER LIGHTS	2.00	
		CA8737 AIR FILTER LBF	1.00	
		U-BOLT	2.00	
		15-40 OIL	11.00	
<b>Parts Charge:</b> 1,129.07		<b>Labor Charge:</b> 1,200.00		

**Workorder:** 1307616

**Problem:** needs fuel cap

Meter Reading: 540	Labor	Parts		
In Date: 08/01/2013	Hours	Description	Quantity	
- Replace Fuel Cap		SHOP SUPPLIES	1.00	
- Shop Supplies		FUEL CAP W/ SENDER	1.00	
<b>Parts Charge:</b> 63.49		<b>Labor Charge:</b> 0.00		

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 1402361

Problem: pm/ throttle cable

Meter Reading: 552		Labor		Parts	
In Date: 03/11/2014	Close Date: 03/27/2014	Hours	Description		Quantity
- Pm		11.00	NAPAGOLD OIL FILTER		1.00
- Hyd Service			NAPAGOLD FUEL FILTER		1.00
- Trailer Service			AW68 HYDRO FLUID HYDR		2.00
- Repalce Trailer Plug			THROTTLE CABLE		1.00
- Replace Throttle Cable			NAPA HYDRAULIC FILTR		1.00
- Shop Supplies			THROTTLE CABLE		1.00
			SEAL 2.250X3.371X.375		2.00
			Freight Charge		1.00
			NAPAGOLD AIR FILTER		1.00
			Freight Charge		1.00
			TRAILER CONN PLUG		1.00
			SHOP SUPPLIES		1.00
			WHEEL BEARING CONE		1.00
			WHEEL BEARING CUP		1.00
			15-40 OIL		11.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge:		244.22	Labor Charge:	660.00	

Workorder: 1408852

Problem: blower belt/ oil switch leaks/ teeth/ fuel cap

Meter Reading: 560		Labor		Parts	
In Date: 09/03/2014	Close Date: 09/26/2014	Hours	Description		Quantity
- Diagnose Oil Leak-Replace Oil Pressure Switch. Fix		13.00	THREADED POCKET		21.00
Broken Throttle Cable Bracket-Drill Out Two Broken Bolts			"PRO" POCKET		21.00
Retap And Replace Hardwar			Freight Charge		1.00
- Replace All Teeth Bolts And Pockets			SHOP SUPPLIES		1.00
- Replace Fuel Cap Service Fuel Sys			PM-22-A ADDITIVE DIES		1.00
- Replace Blower Belt R&R Shields			OIL PRESSURE SWITCH		1.00
- Replace Two Ring			FUEL CAP W/ SENDER		1.00
- Shop Supplies			TOOTH-STRAIGHT		2.00
			BELT		1.00
			TOOTH-RIGHT		20.00
			HITCH RING		1.00
			BOLT		42.00
			TOOTH-LEFT		20.00
Parts Charge:		1,623.04	Labor Charge:	780.00	

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

**Workorder:** 1409879

**Problem:** leaking hydraulic hose

Meter Reading: 560		Labor		Parts	
In Date: 10/01/2014	Close Date: 10/07/2014	Hours	Description		Quantity
-	Replace Hyd Line From Hitch To Control Panel And Test Run	1.50	HYD HOSE ASM		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		109.28	Labor Charge:	90.00	

**Workorder:** 1506280

**Problem:** pm service

Meter Reading: 597		Labor		Parts	
In Date: 06/23/2015	Close Date: 06/29/2015	Hours	Description		Quantity
-	Pm	11.50	8.78-16.5 TIRE		2.00
-	Service Trailer		BEARING		2.00
-	Hyd Service		GREASE CAP		2.00
-	R/R 2 Tires (Dryrott)		BEARING CUP		2.00
-	R/R Bearings And Races Both Side		BEARING		1.00
-	Shop Supplies		RACE		1.00
			SHOP SUPPLIES		1.00
			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			NAPA HYDRAULIC FILTR		1.00
			15-40 OIL		11.00
			SEAL 2.250X3.371X.375		2.00
			NAPAGOLD AIR FILTER		1.00
			AW68 HYDRO FLUID HYDR		2.00
			NAPAGOLD AIR FILTER		1.00
			CONE		2.00
Parts Charge:		580.74	Labor Charge:	690.00	

**Workorder:** 1509944

**Problem:** flat tire, Boulevard has to order tire will come out Tuesday to repair.

Meter Reading: 599		Labor		Parts	
In Date: 09/04/2015	Close Date: 09/30/2015	Hours	Description		Quantity
-	Tire Service Jpp Nursery - Flat Tire, Boulevard Has To Order Tire Will Come Out Tuesday To Repair.				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 46.40

1/3/2017  
4:36:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156289 2004 VERMEER SC752 Stump Cutter Trailer Mntd

Workorder: 1509945

Problem: tire

Meter Reading: 599

Labor

Parts

In Date: 09/30/2015

Close Date: 09/30/2015

Hours

Description

Quantity

- Tire Service Jpp Nursery - Tire

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 139.14

Workorder: 1607171

Problem: Transition Prep Charge

Meter Reading: 617

Labor

Parts

In Date: 07/14/2016

Close Date: 07/14/2016

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: 17,919.67

Total Labor Charges: 9,982.50

Total Comm. Charges: 1,790.35