

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 745404

**Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	Quantity
In Date: 10/10/2007	Hours	Description	
- Pre-Delivery Inspection	2.00		
Parts Charge: 0.00	Labor Charge: 120.00		

**Workorder:** 746081

**Problem:** INSTALLED FUEL TANK AND GANG BOX.

Meter Reading: 362	Labor	Parts	Quantity
In Date: 10/23/2007	Hours	Description	
- Mount Aux Fuel Tank; Route Wire To Switch On Dashboard; Leak Test; Mount Toolbox; Make Label For Dashboard	11.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 30.00		

**Workorder:** 746538

**Problem:** INSTALL CUSTOMERS COMPUTOR STAND

Meter Reading: 362	Labor	Parts	Quantity
In Date: 10/31/2007	Hours	Description	
- Fabricate & Install Computer Stand. Install New Inline Fuse Holder & Wire In.	3.00	SHOP SUPPLIES 80865 FUSEHOLDER IMPERIAL 80865	1.00 1.00
- Shop Supplies			
Parts Charge: 8.09	Labor Charge: 180.00		

**Workorder:** 833434

**Problem:** P.M.SERVICE

Meter Reading: 5750	Labor	Parts	Quantity
In Date: 01/30/2008	Hours	Description	
- Pm Service	3.25	1066 WHITE LITHIUM (CRC 05037)	1.00
- Test Drive		10020 INJECTOR CLEANER DON'T REORDER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		10W30 MOTOR OIL	7.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge: 32.48	Labor Charge: 15.00		

3/2/2017  
10:09:30AM

Palm Beach County Fleet Management  
Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 835589

Problem: JUMP START.

Meter Reading: 8446	Labor	Parts	Quantity
In Date: 03/17/2008	Hours	Description	
- Jumpstart; Ck Charging Sys; Unable To Verify Cause Of Battery Dying	0.50		
Parts Charge: 0.00	Labor Charge: 30.00		

Workorder: 837779

Problem: P.M.SERVICE

Meter Reading: 11759	Labor	Parts	Quantity
In Date: 04/30/2008	Hours	Description	
- Pm Service	2.75	31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		5W20 ENGINE OIL	7.00
		1066 WHITE LITHIUM (CRC 05037)	1.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
Parts Charge: 69.67	Labor Charge: 165.00		

Workorder: 842854

Problem: P.M.SERVICE

Meter Reading: 17921	Labor	Parts	Quantity
In Date: 08/14/2008	Hours	Description	
- Pm Service	5.25	WASTE FEES	4.00
- R&R Tires And Balance		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Road Test		5W20 ENGINE OIL	7.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		TIRE DISPOSAL FEE	4.00
		SHOP SUPPLIES	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		TIRES 245/75R17	4.00
Parts Charge: 801.25	Labor Charge: 30.00		

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 844247

**Problem:** 001 WASH TICKET ISSUED OUT 09/16/08

Meter Reading: 0		Labor	Parts	
In Date: 09/16/2008	Close Date: 09/16/2008	Hours	Description	Quantity
- 001 Wash Ticket Issued Out 09/16/08				
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 7.20	

**Workorder:** 847029

**Problem:** CHECK TRAILER WIRING SYSTEM

Meter Reading: 21131		Labor	Parts	
In Date: 11/13/2008	Close Date: 11/18/2008	Hours	Description	Quantity
- C/S Trailer Brakes Lock Up Truck Hooked Up; Ck Trailer Fuse & Harness; Found Damaged Harness; R&R Harness & Trailer Plug		5.50	SHOP SUPPLIES	1.00
- Scan Trailer Brake Module For Dtc-Code U0137; Reset Module; Clear Code & Test Drive				
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	90.00	

**Workorder:** 933520

**Problem:** P.M.SERVICE/SEE NOTE

Meter Reading: 23169		Labor	Parts	
In Date: 02/03/2009	Close Date: 02/12/2009	Hours	Description	Quantity
-	Pm Service	5.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
-	Straighten Bent Tailpipe		1066 WHITE LITHIUM (CRC 05037)	1.00
-	Install No Smoking Decal; Install Spot Mirror		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
-	Remove & Disassemble Dispensing Gun; Clean Out Rust		7044D 3-3/4" SPOT MIRROR	1.00
	& Debris; Polish Pin		SHOP SUPPLIES	1.00
-	Shop Supplies		5W20 ENGINE OIL	7.00
	Parts Charge: 66.20	Labor Charge:	345.00	

3/2/2017  
10:09:30AM

Palm Beach County Fleet Management  
Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 940942

Problem: p.m.service

Meter Reading: 27893		Labor		Parts	
In Date: 07/20/2009	Close Date: 07/22/2009	Hours	Description		Quantity
-	P.M.Service.	5.00	1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Service Fuel Pump/Tank. R/R Fuel Filter.		SHOP SUPPLIES		1.00
-	Install New No Smoking Decals		1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
-	Repair Nail In R/Front Tire		31-20 WIPER BLADES 20" BLADE		2.00
-	Shop Supplies		5W20 ENGINE OIL		7.00
Parts Charge:		53.66	Labor Charge:	300.00	

Workorder: 1000832

Problem: P.M.SERVICE

Meter Reading: 33527		Labor		Parts	
In Date: 01/22/2010	Close Date: 02/09/2010	Hours	Description		Quantity
-	P. M.	5.25	1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Serviced Auxiliary Fuel Tank & R/R Filter.		5W20 ENGINE OIL		7.00
-	Disassembled Beacon Light, Repaired Ground.		CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
-	R/R Bulb For Running Light.		G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
Parts Charge:		102.46	Labor Charge:	315.00	

Workorder: 1002575

Problem: damage to rgt rear light, rear bumper & tail gate

Meter Reading: 34191		Labor		Parts	
In Date: 02/26/2010	Close Date: 03/12/2010	Hours	Description		Quantity
-	Damage To Rgt Rear Light, Rear Bumper & Tail Gate				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 475.40

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1006992

**Problem:** P. M., & nail in front driver's side tire

<b>Meter Reading: 37295</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/02/2010</b>	<b>Close Date: 07/08/2010</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	P. M. Service.	<b>5.75</b>	179636492 LT245/75R17 WRANGLER SR-A E		4.00
-	Service Auxiliary Fuel Pump, R/R Filter.		31-20 WIPER BLADES 20" BLADE		2.00
-	C/C: Nail In Tire. Verify. Vehicle Needs 4 Tires.		05023 BATTERY CLEANER		1.00
	Dismount, Mount, Balance, Add Nitrogen, Clear Low		5W20 ENGINE OIL		7.00
	Pressure Light.		05046 BATTERY PROTECTOR (CRC)		1.00
-	Shop Supplies		1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			TIRE DISPOSAL FEE		4.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		806.27	<b>Labor Charge:</b>	345.00	

**Workorder:** 1008959

**Problem:** Will not start, battery dead

<b>Meter Reading: 38576</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 08/19/2010</b>	<b>Close Date: 08/25/2010</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	C/S: Dead Battery, Verify. Check & Charge Battery, Ck Charging System, Ck For Drain & Found Computer Charger Plugged In & Draining Battery. Battery Is Ok.	<b>1.00</b>	SHOP SUPPLIES		1.00
-	Shop Supplies				
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>	60.00	

**Workorder:** 1013728

**Problem:** P. M. SERVICE

<b>Meter Reading: 40542</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 12/14/2010</b>	<b>Close Date: 12/22/2010</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	P. M. Service.	<b>3.75</b>	SHOP SUPPLIES		1.00
-	Service Aux Fuel Tank.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			5W20 ENGINE OIL		7.00
<b>Parts Charge:</b>		55.17	<b>Labor Charge:</b>	225.00	

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1107154

**Problem:** P. M. SERVICE

<b>Meter Reading: 45330</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/06/2011</b>	<b>Close Date: 07/14/2011</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Performed Service.	<b>11.00</b>	5W20 ENGINE OIL		7.00
-	R&R Filter Assy. Repaired Nozzle.		G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
-	R&R Pads & Cut Rotors. Bleed System.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Center Brake Out, R&R Bulb. Repaired Connection To		CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
-	Running Light.		1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
-	Batt Failed Load. Recharged Batt. & Retested, Passed.		31-20 WIPER BLADES 20" BLADE		2.00
-	Shop Supplies		FRONT BRAKE PAD		1.00
			09997 BRAKE CLEAN		1.00
			SHOP SUPPLIES		1.00
			1401 BRAKE FLUID BRAKE FLUID		2.00
<b>Parts Charge:</b>		149.11	<b>Labor Charge:</b>	660.00	

**Workorder:** 1108806

**Problem:** Makes odd noises (sounds like Diesel, but take regular fuel)

<b>Meter Reading: 46207</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 08/19/2011</b>	<b>Close Date: 08/31/2011</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Verified Driver'S Concer, Engine Sounds Like Diesel,	<b>2.50</b>	SHOP SUPPLIES		1.00
-	Found Bad Cat Converter.				
-	Dealer To Replace Bad Cat Converter.				
-	Transport & Pick Up Vehicle At Dealer (Defective Cat				
-	Converter).				
-	Shop Supplies				
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>	150.00	

**Workorder:** 1110856

**Problem:** Driver's side rear tire is flat

<b>Meter Reading: 47331</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 10/12/2011</b>	<b>Close Date: 10/17/2011</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Repair Left Rear Tire.	<b>1.00</b>	SHOP SUPPLIES		1.00
-	Shop Supplies				
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>	60.00	

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1201507

Problem: P. M. Service

Meter Reading: 49451	Labor	Parts	
In Date: 02/14/2012	Hours	Description	Quantity
- P. M. Service.	5.25	5W20 ENGINE OIL	7.00
- Service Auxiliary Fuel Tank. R&R Filter.		SHOP SUPPLIES	1.00
- Nail In Right Rear. Dismount, Patch, Mount, Balance, &		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Add N2.		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
- Shop Supplies			
Parts Charge:	33.97	Labor Charge:	315.00

Workorder: 1202250

Problem: ENGINE WILL NOT TURN OVER

Meter Reading: 49944	Labor	Parts	
In Date: 03/05/2012	Hours	Description	Quantity
- Ck And Replace Bad Battery Ck Charging Sys	0.75	GROUP 65 BATTERY (MTC BXT-65-850)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	130.75	Labor Charge:	45.00

Workorder: 1204774

Problem: SCREW IN R/REAR TIRE

Meter Reading: 52721	Labor	Parts	
In Date: 05/21/2012	Hours	Description	Quantity
- C/C: Nail In Tire. Dismount, Patch, Mount, Balance. Add N2.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1206167

**Problem:** pm, rear right tire almost flat

<b>Meter Reading:</b> 54292		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/02/2012	<b>Close Date:</b> 07/18/2012	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Pm	<b>7.00</b>	SHOP SUPPLIES		1.00
-	Ck Rr Tire Flat Dismount Patch Mount Balance Add N2		11B-0400 BLACK NOZZLE LEADED (OPW)		1.00
	Clear Tpms		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Ck Handle On Tank Broken Service Fuel Aux Tank		5W20 ENGINE OIL		7.00
	Replace Filter Replace Broken Handle And Test		31-20 WIPER BLADES 20" BLADE		2.00
-	Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			05023 BATTERY CLEANER		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
<b>Parts Charge:</b>		150.60	<b>Labor Charge:</b>	420.00	

**Workorder:** 1208486

**Problem:** right front tire flat

<b>Meter Reading:</b> 56065		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/07/2012	<b>Close Date:</b> 09/12/2012	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Fr Tire Flat Dismount Patch Mount Balance Add Ne	<b>1.00</b>	SHOP SUPPLIES		1.00
-	Shop Supplies				
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>	60.00	

**Workorder:** 1209992

**Problem:** SCREW IN L/REAR TIRE

<b>Meter Reading:</b> 57016		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/18/2012	<b>Close Date:</b> 10/22/2012	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Repair Left Rear Tire	<b>1.00</b>	SHOP SUPPLIES		1.00
-	Shop Supplies				
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>	60.00	



3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1301731

**Problem:** pm

**Meter Reading:** 59773

**In Date:** 02/20/2013

**Close Date:** 02/27/2013

**Labor**

**Hours**

**Description**

**Parts**

**Quantity**

- Pm	5.75	NAPA QUART 5W20	7.00
- Svc Inspect Aux Fuel Tank And Replace Filter		179636492 LT245-75R17	4.00
- Verify Needs 4 Tires, Mount Balance Add N2		TIRE DISPOSAL FEE	4.00
- Shop Supplies		CA10262 AIR FILTER MT	1.00
		HYDRAULIC FILTER P1653A	1.00
		SHOP SUPPLIES	1.00
		1372 OIL FILTER	1.00
<b>Parts Charge:</b>	1,024.53	<b>Labor Charge:</b>	345.00

**Workorder:** 1308540

**Problem:** pm

**Meter Reading:** 65216

**In Date:** 08/23/2013

**Close Date:** 08/29/2013

**Labor**

**Hours**

**Description**

**Parts**

**Quantity**

- Pm	3.75	USED FIRE X REFURBISHED	1.00
- Svc Aux Fuel Tank		NAPA TRANS FILTER	1.00
- Shop Supplies		NAPA QUART 5W20	7.00
		SHOP SUPPLIES	1.00
		NAPAGOLD FUEL FILTER	1.00
		NAPAGOLD OIL FILTER	1.00
		31-20 WIPER BLADES 20	2.00
<b>Parts Charge:</b>	68.93	<b>Labor Charge:</b>	225.00

**Workorder:** 1310379

**Problem:** Right rear directional turn signal not working.

**Meter Reading:** 66305

**In Date:** 10/15/2013

**Close Date:** 10/23/2013

**Labor**

**Hours**

**Description**

**Parts**

**Quantity**

- Ck Rr Tail Light Out Replace Tail Light Bulb Ck All Lights	0.25	BULB	1.00
<b>Parts Charge:</b>	0.99	<b>Labor Charge:</b>	15.00

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1312431

**Problem:** nail in passenger side rear tire

<b>Meter Reading:</b> 67698		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/13/2013	<b>Close Date:</b> 12/17/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Ck Nail In Tire Dismount Patch Mount Balance Add N2 Left Rear		<b>1.00</b>	SHOP SUPPLIES		1.00
- Shop Supplies					
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>	60.00	

**Workorder:** 1401745

**Problem:** pm, started to run ruff ck engine ligh came on needs oil

<b>Meter Reading:</b> 69219		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/24/2014	<b>Close Date:</b> 02/28/2014	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm		<b>17.25</b>	NAPA HYDRAULIC FILTR		1.00
- Svc Aux Fuel Tank			BRAKE CLEANER		1.00
- Remove Dirve Shaft Resurface Rotors Svc Calipers And Replace Pads			COIL ASSEMBLY		8.00
- Ck Engine Light On Scan And Found Code Po0300 Po316 Po301 Po304 Po36 Perform Pinpoint Test And Fouind Bad Coil Flush Upper Intake And Cyl Clean Throttle Plate Replace All Spark Plugs Coils			REAR PADS		1.00
- Clear Codes Test Drive After Repair			SPARK PLUG		8.00
- Shop Supplies			KA8A THROTTLE BODY- U		1.00
			SHOP SUPPLIES		1.00
			NAPAGOLD OIL FILTER		1.00
			WIPER BLADE		2.00
			NAPA QUART 5W20		7.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
<b>Parts Charge:</b>		927.15	<b>Labor Charge:</b>	1,035.00	

**Workorder:** 1402141

**Problem:** STARTED TO RUN ROUGH/CHECK ENGINE LIGHT CAME ON(RELATED TO W.O#1401745 WAS CLOSED )

<b>Meter Reading:</b> 69240		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/04/2014	<b>Close Date:</b> 03/11/2014	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Remove 3 Broken Spark Plugs From Cyl Head And Clean Carbon From Engine		<b>6.00</b>	SHOP SUPPLIES		1.00
- Shop Supplies					
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>	360.00	

3/2/2017  
10:09:30AM

Palm Beach County Fleet Management  
Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1407795

Problem: low tire pressure light cam on

Meter Reading: 73745	Labor	Parts		
In Date: 08/07/2014	Hours	Description	Quantity	
- Repair Left Front Tire	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	60.00	

Workorder: 1408736

Problem: pm, nail in left rear tire

Meter Reading: 74331	Labor	Parts		
In Date: 08/29/2014	Hours	Description	Quantity	
- Pm	3.75	NAPAGOLD OIL FILTER	1.00	
- Repair 4 Rear Tires Patch Mount Balance Add N2		NAPA QUART 5W20	8.00	
- Shop Supplies		SHOP SUPPLIES	1.00	
Parts Charge:	36.29	Labor Charge:	225.00	

Workorder: 1502706

Problem: pm, towed in flat tire right front

Meter Reading: 78488	Labor	Parts		
In Date: 03/16/2015	Hours	Description	Quantity	
- Pm	6.50	SHOP SUPPLIES	1.00	
- Svc Aux Fuel Tank And Replace Filter		WASHER FL	1.00	
- Replace All 4 Tires		NAPAGOLD AIR FILTER	1.00	
- Fill All Tires With Nitrogen Reprogram Tpm Sys		TIRE DISPOSAL FEE	4.00	
- Repair Pintle Pin		WIPER BLADE	2.00	
- Shop Supplies		179636492 LT245-75R17	4.00	
		NAPA HYDRAULIC FILTR	1.00	
		NAPAGOLD OIL FILTER	1.00	
		NAPA QUART 5W20	8.00	
		USED FIRE X REFURBISHED	1.00	
		NAPAGOLD FUEL FILTER	1.00	
Parts Charge:	1,136.92	Labor Charge:	390.00	

3/2/2017  
10:09:30AM

Palm Beach County Fleet Management  
Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1502799

Problem: r/f flat tire

Meter Reading: 78488

In Date: 03/16/2015

Close Date: 03/18/2015

Labor

Hours

Description

Parts

Quantity

- Tow From: 7411 Sedona Way Addison Reserve To: Sr Delray

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 104.15

Workorder: 1504253

Problem: battery warning light on all elec stopped working ac stopped working

Meter Reading: 79675

In Date: 04/24/2015

Close Date: 04/30/2015

Labor

Hours

Description

Parts

Quantity

- Ck Battery Light Test Battery Bad Ck Chargng Sys Verify 3.75 ALTERNATOR 1.00
- Bad Alternator Rr Alt FEMALE CONN SOCKET 1.00
- Ck Trailer Plug Bad Install New Plug ALTERNATOR 1.00
- Test Battery Bad Replace Battery BATTERY 1.00
- Shop Supplies SHOP SUPPLIES 1.00

Parts Charge: 400.10

Labor Charge: 225.00

Workorder: 1507435

Problem: ABS LIGHT COMES ON THEN GOES OFF

Meter Reading: 82318

In Date: 07/27/2015

Close Date: 07/31/2015

Labor

Hours

Description

Parts

Quantity

- Ck Abs Light Comes On And Off Verify Concern Scan 4.50 SENSOR ASY 2.00
- Found Code C1145 Perform Pinpoint Test Found Bad Abs SHOP SUPPLIES 1.00
- Wheel Speed Sensor Replace Both Front And Abs
- Sensor And Clear Codes
- Rest Drive Before And After Repair
- Shop Supplies

Parts Charge: 155.09

Labor Charge: 270.00

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1509103

**Problem:** pm, nail in left rear tire

<b>Meter Reading: 83521</b>		<b>Labor</b>		<b>Parts</b>	<b>Quantity</b>
<b>In Date:</b> 09/10/2015	<b>Close Date:</b> 09/18/2015	<b>Hours</b>	<b>Description</b>		
-	Pm	<b>5.00</b>	NAPAGOLD OIL FILTER		1.00
-	Ck Nail Lr Tire Repaire Lr Tire Add N2 Rotate To Front		NAPA QUART 5W20		8.00
-	Replace Rusty Hitch Pinand Damaged Clip		PIN W/CLIP 5/8 FOR HITCH		1.00
-	Svc Aux Fuel Tank		NAPA HYDRAULIC FILTR		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			75W140 FORD AXLE LUBE		3.00
<b>Parts Charge:</b> 126.20		<b>Labor Charge:</b> 300.00			

**Workorder:** 1511661

**Problem:** rr tailgate

<b>Meter Reading: 84803</b>		<b>Labor</b>		<b>Parts</b>	<b>Quantity</b>
<b>In Date:</b> 11/16/2015	<b>Close Date:</b> 11/30/2015	<b>Hours</b>	<b>Description</b>		
-	Ck Talil Light Bulb Rr Right Rear Tail Light Bulb	<b>0.25</b>	BULB		1.00
<b>Parts Charge:</b> 0.75		<b>Labor Charge:</b> 15.00			

**Workorder:** 1604591

**Problem:** Pm service.Pintle pin missing.

<b>Meter Reading: 88801</b>		<b>Labor</b>		<b>Parts</b>	<b>Quantity</b>
<b>In Date:</b> 05/02/2016	<b>Close Date:</b> 05/06/2016	<b>Hours</b>	<b>Description</b>		
-	P.M.Service	<b>7.00</b>	SHOP SUPPLIES		1.00
-	Service Aux. Fuel Tank. Replace Filter		PTEx ULTRA GREY 3OZ		1.00
-	Rear Differential Service		75W140 FORD AXLE LUBE		4.00
-	Replace Pintle Pin		NAPA TRANS FILTER		1.00
-	Repair F/Left Tire,Correct All N2 Level. Balance&Rotate All.		WASHER FLUID CONCENTR		1.00
-	Shop Supplies		FRICION MODIFIER		1.00
			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			NAPA QUART 5W20		8.00
			20" WIPER BLADE		2.00
			PINTLE PIN W/CHAIN		1.00
<b>Parts Charge:</b> 178.92		<b>Labor Charge:</b> 420.00			

3/2/2017  
10:09:30AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170972 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1610405

Problem: Will not start,bad battery.

Meter Reading: 92871	Labor	Parts		
In Date: 10/04/2016	Hours	Description	Quantity	
- Test Starting And Charging System.Battery Failed Load	0.75			
Test.Replace Defective Battery.				
Parts Charge:	0.00	Labor Charge:	45.00	

Workorder: 1611253

Problem: Dead battery will not crank.

Meter Reading: 93263	Labor	Parts		
In Date: 10/31/2016	Hours	Description	Quantity	
- Computer Plugged In For A Week,Killed Battery.Recharge	0.75			
Battery.Test Good.Check Alternator.Ok				
Parts Charge:	0.00	Labor Charge:	45.00	

Workorder: 1612721

Problem: Transition Prep Charge

Meter Reading: 93520	Labor	Parts		
In Date: 12/13/2016	Hours	Description	Quantity	
- Transition Prep Charge	2.00			
Parts Charge:	0.00	Labor Charge:	0.00	

Total Parts Charges:	6,537.55	Total Labor Charges:	8,115.00	Total Comm. Charges:	586.75
----------------------	----------	----------------------	----------	----------------------	--------