

5/31/2017  
9:43:49AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10189106 2012 TORO 3040 Ballfield Groomer

<b>Workorder:</b> 1208297		<b>Problem:</b> 1061 - Pre Delivery Inspection			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/04/2012	<b>Close Date:</b> 09/04/2012	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pre Delivery Inspection		<b>2.00</b>			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 120.00			

<b>Workorder:</b> 1308491		<b>Problem:</b> pm service			
<b>Meter Reading:</b> 163		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/22/2013	<b>Close Date:</b> 08/29/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm		<b>5.00</b>	NAPAGOLD AIR FILTER		1.00
- Remove Attachment And Clena Coupler Reattach			10W30 MOTOR OIL		2.00
- Shop Supplies			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 22.90		<b>Labor Charge:</b> 300.00			

<b>Workorder:</b> 1403222		<b>Problem:</b> HYDRAULIC LEAK			
<b>Meter Reading:</b> 291		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/02/2014	<b>Close Date:</b> 04/08/2014	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Ck For Leak Hector Turf Warranty Front Seal On Pump		<b>2.00</b>	SHOP SUPPLIES		1.00
- Wash Eqpt					
- Shop Supplies					
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 120.00			

<b>Workorder:</b> 1408365		<b>Problem:</b> pm service			
<b>Meter Reading:</b> 380		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/22/2014	<b>Close Date:</b> 08/28/2014	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm		<b>5.00</b>	10W30 MOTOR OIL		2.00
- Wash Eqpt			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			BRAKE CLEANER		1.00
<b>Parts Charge:</b> 26.40		<b>Labor Charge:</b> 300.00			

5/31/2017  
9:43:49AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10189106 2012 TORO 3040 Ballfield Groomer

**Workorder:** 1410249

**Problem:** rake handle sticks/align rack/see notes

<b>Meter Reading: 391</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 10/10/2014</b>	<b>Close Date: 10/29/2014</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Replace All 5 Rear Rakes Replace Hardware	<b>4.50</b>	ADAPTER		2.00
-	Replace Hydro Cylinder Pump Service Sys R&R Shields		REAR LEVER ASM		1.00
	And Hoses Replace All Hose Seals And O'Ring Fittings		Freight Charge		1.00
-	Shop Supplies		OFFSET LINK		1.00
			SHOP SUPPLIES		1.00
			WELDED PIVOT		1.00
			VALVE ASM		1.00
			O RING		4.00
			SPRING RAKE KIT		5.00
			WASHER		1.00
			O RING		4.00
			BRCKET-PIVOT		1.00
<b>Parts Charge:</b> 710.31		<b>Labor Charge:</b> 270.00			

**Workorder:** 1508329

**Problem:** pm service

<b>Meter Reading: 420</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 08/19/2015</b>	<b>Close Date: 08/25/2015</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Pm	<b>5.00</b>	BRAKE CLEANER		1.00
-	Wash		STARTRON 8OZ FUEL TRT		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			10W30 MOTOR OIL		2.00
			NAPAGOLD FUEL FILTER		1.00
<b>Parts Charge:</b> 35.72		<b>Labor Charge:</b> 300.00			

5/31/2017  
9:43:49AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10189106 2012 TORO 3040 Ballfield Groomer

Workorder: 1612265

Problem: pm service

Meter Reading: 458		Labor		Parts	
In Date: 11/30/2016	Close Date: 12/08/2016	Hours	Description		Quantity
- Pm		6.50	10W30 MOTOR OIL		2.00
- Load Test, Check Charging Sys, Replace Battery			NAPAGOLD OIL FILTER		1.00
- Hyd Service, Remove Hyd Hoses To Replace Filter And			NON-CHLOR BRAKE CLNR		1.00
Flush Sys			BATTERY		1.00
- Shop Supplies			NAPA TRANS FILTER		1.00
			AW68 HYDRO FLUID HYDR		18.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		109.48	Labor Charge:	390.00	

Workorder: 1704846

Problem: Transition Prep Charge

Meter Reading: 458		Labor		Parts	
In Date: 05/16/2017	Close Date: 05/16/2017	Hours	Description		Quantity
- Transition Prep Charge		2.00			
Parts Charge:		0.00	Labor Charge:	0.00	

Total Parts Charges:	906.81	Total Labor Charges:	1,800.00	Total Comm. Charges:	0.00
----------------------	--------	----------------------	----------	----------------------	------