

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 340128		Problem: WASH VEHICLE			
Meter Reading: 0		Labor		Parts	
In Date: 05/07/2003	Close Date: 05/07/2003	Hours	Description		Quantity
- Wash Vehicle		3.10			
- Pre-Delivery Inspection					
- Make Duplicate Keys For New Vehicle					
Parts Charge:		0.00	Labor Charge:	155.00	
Workorder: 340176		Problem: 001 WASH TICKET ISSUED OUT 05/07/03			
Meter Reading: 0		Labor		Parts	
In Date: 05/07/2003	Close Date: 05/08/2003	Hours	Description		Quantity
- 001 Wash Ticket Issued Out 05/07/03					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 7.14
Workorder: 432447		Problem: P.M.SERVICE			
Meter Reading: 2421		Labor		Parts	
In Date: 01/06/2004	Close Date: 01/08/2004	Hours	Description		Quantity
- Pm Service		2.75	L/F PH820 FRM PH2 WIX 51372 OIL FILTER		1.00
- Shop Supplies			5W20 ENGINE OIL		7.00
			SHOP SUPPLIES		1.00
Parts Charge:		23.55	Labor Charge:	137.50	
Workorder: 433745		Problem: 001 KEY ISSUED OUT 01/26/04			
Meter Reading: 0		Labor		Parts	
In Date: 01/26/2004	Close Date: 01/26/2004	Hours	Description		Quantity
- 001 Key Issued Out 01/26/04		0.20	DUPLICATE VEHICLE KEYS		1.00
Parts Charge:		3.00	Labor Charge:	10.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 441371

Problem: BOLT IN FR TIRE

Meter Reading: 3824		Labor		Parts	
In Date: 04/14/2004	Close Date: 04/16/2004	Hours	Description	Quantity	
- Tire Repair		1.00	SHOP SUPPLIES	1.00	
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	50.00	

Workorder: 449540

Problem: P.M.SERVICE

Meter Reading: 4621		Labor		Parts	
In Date: 06/30/2004	Close Date: 07/08/2004	Hours	Description	Quantity	
- Pm Service		3.75	5W20 ENGINE OIL	7.00	
- Fabricate & Install Half Moon Rear View Mirror.			SHOP SUPPLIES	1.00	
- Shop Supplies			1372 OIL FILTER FRM PH2 WIX 51372	1.00	
			50-805 HALFMOON REARVIEW MIRROR	1.00	
Parts Charge:		64.58	Labor Charge:	187.50	

Workorder: 461806

Problem: RECALL

Meter Reading: 7253		Labor		Parts	
In Date: 11/13/2004	Close Date: 11/16/2004	Hours	Description	Quantity	
- Transport & Pickup Vehicle At Dealer.(Recall #04S22/04S23)		1.00	SHOP SUPPLIES	1.00	
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	50.00	

Workorder: 532497

Problem: P.M.SERVICE

Meter Reading: 7680		Labor		Parts	
In Date: 01/05/2005	Close Date: 01/07/2005	Hours	Description	Quantity	
- P M Service		2.75	SHOP SUPPLIES	1.00	
- Shop Supplies			5W20 ENGINE OIL	7.00	
			1372 OIL FILTER FRM PH2 WIX 51372	1.00	
Parts Charge:		46.87	Labor Charge:	137.50	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 551900

Problem: P.M.SERVICE

Meter Reading: 10854		Labor		Parts	
In Date: 08/01/2005	Close Date: 08/03/2005	Hours	Description		Quantity
- Pm		3.25	5W20 ENGINE OIL		7.00
- Install Grease Fittings			1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Shop Supplies			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			G8018 FUEL FILTER LBF G6593 WIX 33595		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 38.93		Labor Charge:	162.50		

Workorder: 633452

Problem: P.M SERVICE.DEAD BATTERY.

Meter Reading: 13258		Labor		Parts	
In Date: 01/27/2006	Close Date: 02/03/2006	Hours	Description		Quantity
- Pm Service		3.75	SHOP SUPPLIES		1.00
- Transport And Pickup Vehicle At Dealer.(Battery)			5W20 ENGINE OIL		7.00
- Shop Supplies			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
Parts Charge: 64.01		Labor Charge:	50.00		

Workorder: 633868

Problem: SPEEDO. INOP.

Meter Reading: 13270		Labor		Parts	
In Date: 02/03/2006	Close Date: 02/23/2006	Hours	Description		Quantity
- Transport & Pickup Vehicle At Dealer.(Defective Instrument Assy)		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge:	50.00		

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 644218

Problem: P.M.SERVICE,SCREW ON L/FRONT TIRE

Meter Reading: 15788		Labor	Parts	
In Date: 08/17/2006	Close Date: 08/21/2006	Hours	Description	Quantity
- Pm Service		3.00	CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
- Remove Screw In L/Front Tire.Found No Leak.			5W20 ENGINE OIL	7.00
- Shop Supplies			WD40 SPRAY LUBE STOCK# 405540002	1.00
			31-22 WIPER BLADES 22" WIPER BLADE	2.00
			SHOP SUPPLIES	1.00
			G8018 FUEL FILTER LBF G6593 WIX 33595	1.00
			1372 OIL FILTER FRM PH2 WIX 51372	1.00
	Parts Charge: 61.65	Labor Charge: 12.50		

Workorder: 734153

Problem: P.M. SERVICE.

Meter Reading: 18753		Labor	Parts	
In Date: 02/12/2007	Close Date: 02/15/2007	Hours	Description	Quantity
- Performed Pm Service Complete.		8.50	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Replaced 4 Tires With New And Steel Valve			31-22 WIPER BLADES 22" WIPER BLADE	2.00
Stems.Balanced All4 Tires.			TIRE DISPOSAL FEE	4.00
- Performed Transmission Flush			744830900 225/75R16E WRANGLER HT E	4.00
- Perform Nitrogen Fill On All 4 Tires.			SYN/ATF TRANS FLUID SYNTHETIC	14.00
- Shop Supplies			SHOP SUPPLIES	1.00
			5W20 ENGINE OIL	7.00
			TR416 VALVE STEM	4.00
Parts Charge:	693.04	Labor Charge:	55.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 743572

Problem: P.M. SERVICE.SEE NOTE.

Meter Reading: 22621		Labor		Parts	
In Date: 09/04/2007	Close Date: 09/10/2007	Hours	Description		Quantity
-	Perform Pm Service	5.00	10020 INJECTOR CLEANER DON'T REORDER		1.00
-	Balance 4 Tires. Road Test.		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
			5W20 ENGINE OIL		7.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			G8018 FUEL FILTER LBF G6593 WIX 33595		1.00
Parts Charge:		70.96	Labor Charge:	55.00	

Workorder: 746092

Problem: CEI GROUP

Meter Reading: 0		Labor		Parts	
In Date: 09/06/2007	Close Date: 10/23/2007	Hours	Description		Quantity
-	Cei Group				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 572.40

Workorder: 835713

Problem: P.M SERVICE

Meter Reading: 25447		Labor		Parts	
In Date: 03/18/2008	Close Date: 03/25/2008	Hours	Description		Quantity
-	Pm Service	8.50	G8018 FUEL FILTER LBF G6593 WIX 33595		1.00
-	Pressure Test & Inspect Cooling System.Flush & Refill		1372 OIL FILTER FRM PH2 WIX 51372		1.00
	System		5W20 ENGINE OIL		7.00
-	Decarb Induction Service Cleaning Flush Fuel Injectors.		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Shop Supplies		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)		1.00
			L17301A ENGINE FOG KIT HARD CARBON (SMART BLEND)		1.00
			L17040 INJECT CLEANER ONE PART (SMART BLEND)		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		130.05	Labor Charge:	150.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 844748

Problem: P.M SERVICE

Meter Reading: 29607	Labor	Parts	
In Date: 09/25/2008	Hours	Description	Quantity
- Pm Service	10.00	CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
- Mount & Balance 2 New Front Tires.Nitro Fill.Balance All 4.		G8018 FUEL FILTER LBF G6593 WIX 33595	1.00
- Service Transmission,Flush.		749353434 245/75R16 WRANGLER RT/S E	2.00
- Complete Front End Alignment,Test Drive.		SYN/ATF TRANS FLUID SYNTHETIC	12.00
- Shop Supplies		TIRE DISPOSAL FEE	2.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		5W20 ENGINE OIL	7.00
		744830900 225/75R16E WRANGLER HT E	-2.00
		SHOP SUPPLIES	1.00
		744830900 225/75R16E WRANGLER HT E	2.00
Parts Charge:	401.62	Labor Charge:	150.00

Workorder: 935672

Problem: P.M SERVICE

Meter Reading: 33271	Labor	Parts	
In Date: 03/26/2009	Hours	Description	Quantity
- Pm Service	10.50	TIRE DISPOSAL FEE	2.00
- Mount And Nitrogen Fill 2 Front Tires.High Speed Balance All4		09997 BRAKE CLEAN	1.00
- Install New Frt Brk Pads Machine Frt Rotors Rr Pack		749353434 245/75R16 WRANGLER RT/S E	2.00
Bearingslube Frt & Rear Calipers Pins Nad Slide Bleed		SHOP SUPPLIES	1.00
Sys.Test Drive Ok.		1401 BRAKE FLUID BRAKE FLUID	1.00
- Shop Supplies		F132005 BRAKE LUBE	1.00
		MX655 BRAKE PADS RAY PGD655M	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		5W20 ENGINE OIL	7.00
		WD40 SPRAY LUBE STOCK# 405540002	1.00
		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
Parts Charge:	423.54	Labor Charge:	630.00

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 936600

Problem: RIGHT REAR TIRE FLAT.

Meter Reading: 33597		Labor		Parts	Quantity
In Date: 04/17/2009	Close Date: 04/20/2009	Hours	Description		
- Repair Right Rear Tire Nitrogen Fill And Balance Same.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	

Workorder: 943360

Problem: Nail in L/R tire

Meter Reading: 36557		Labor		Parts	Quantity
In Date: 09/17/2009	Close Date: 09/21/2009	Hours	Description		
- Repair L/R Tire.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	

Workorder: 944525

Problem: P.M service

Meter Reading: 37061		Labor		Parts	Quantity
In Date: 10/14/2009	Close Date: 10/30/2009	Hours	Description		
- P.M Service.		5.50	SHOP SUPPLIES		1.00
- Replace Cracked L/F Head Light.			5W20 ENGINE OIL		7.00
- Rotate & Balance All Four Tires.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Shop Supplies			G8018 FUEL FILTER LBF G6593 WIX 33595		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			H6054 SEALED BEAM		1.00
Parts Charge:		38.45	Labor Charge:	330.00	

Workorder: 1002591

Problem: left rear tire flat

Meter Reading: 39600		Labor		Parts	Quantity
In Date: 03/12/2010	Close Date: 03/15/2010	Hours	Description		
- Repair L/R Tire.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1003712

Problem: Pm service

Meter Reading: 40128		Labor		Parts	
In Date: 04/09/2010	Close Date: 04/20/2010	Hours	Description		Quantity
- P.M Service.		9.00	USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Test Starting & Charging System, Test & Replace Battery.			MKD802 PADS REAR		1.00
			5W20 ENGINE OIL		7.00
- Machine Both Rear Brake Rotors, Install New Pads,			SHOP SUPPLIES		1.00
Service Caliper Slides, Bleed System & Test Drive.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Shop Supplies			31-20 WIPER BLADES 20" BLADE		2.00
			GROUP 65 BATTERY (MTC BXT-65-850)		1.00
			1401 BRAKE FLUID BRAKE FLUID		1.00
			09997 BRAKE CLEAN		1.00
			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
Parts Charge: 236.39		Labor Charge: 540.00			

Workorder: 1004794

Problem: Nail in L/R tire.

Meter Reading: 40943		Labor		Parts	
In Date: 05/10/2010	Close Date: 05/10/2010	Hours	Description		Quantity
- Repair L/F Tire.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1005314

Problem: Nail in R/R tire.

Meter Reading: 41386		Labor		Parts	
In Date: 05/24/2010	Close Date: 05/24/2010	Hours	Description		Quantity
- Repair R/R Tire.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1009947

Problem: Air bag light on.

Meter Reading: 43659		Labor	Parts	
In Date: 09/10/2010	Close Date: 09/22/2010	Hours	Description	Quantity
- Computer Diagnose Air Bag Warning Light On.Remove Driver Seat And Replace Failed Seat Belt Pretensioner With New.		2.75	SHOP SUPPLIES	1.00
- Shop Supplies			SEAT BELT BUCKLE ASSY	1.00
Parts Charge: 122.62		Labor Charge:	165.00	

Workorder: 1011188

Problem: Pm service.

Meter Reading: 44030		Labor	Parts	
In Date: 10/12/2010	Close Date: 10/18/2010	Hours	Description	Quantity
- P.M. Service.		5.25	5W20 ENGINE OIL	7.00
- Replace Left Side A/C Vent.			SHOP SUPPLIES	1.00
- Rotate And Balance All Tires.			G8018 FUEL FILTER LBF G6593 WIX 33595	1.00
- Shop Supplies			31-20 WIPER BLADES 20" BLADE	2.00
			BIG G DEGREASER STOCK# 485180002	1.00
			FAR LEFT A/C VENT	1.00
			1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge: 62.86		Labor Charge:	315.00	

Workorder: 1100908

Problem: install side and rear locks

Meter Reading: 45582		Labor	Parts	
In Date: 01/24/2011	Close Date: 01/26/2011	Hours	Description	Quantity
- Fabricate And Install Locks On Side And Rear Doors		3.00	SHOP SUPPLIES	1.00
Customers Own Parts				
- Shop Supplies				
Parts Charge: 2.00		Labor Charge:	180.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1103725

Problem: Pm service,also see notes on hole in roof.

Meter Reading: 46693		Labor		Parts	
In Date: 04/05/2011	Close Date: 04/14/2011	Hours	Description		Quantity
-	Perform Pm Service.	5.00	5W20 ENGINE OIL		7.00
-	Rotate And Balance All Four Tires.		31-20 WIPER BLADES 20" BLADE		2.00
-	Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372		1.00
			L0152-063 GEAR SHIELD		1.00
			SHOP SUPPLIES		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
Parts Charge:		37.46	Labor Charge:	300.00	

Workorder: 1104600

Problem: repair rust on roof

Meter Reading: 46693		Labor		Parts	
In Date: 04/13/2011	Close Date: 04/29/2011	Hours	Description		Quantity
-	Repair Rust On Roof				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 601.90

Workorder: 1107696

Problem: Rear door handle inop.

Meter Reading: 47873		Labor		Parts	
In Date: 07/21/2011	Close Date: 07/26/2011	Hours	Description		Quantity
-	Remove Rear Door Trim.Inspect And Replace Failed Rear	1.75	REAR OUTER DOOR HANDLE ASSY		1.00
	Outer Handle And Latch Assembly With New.		SHOP SUPPLIES		1.00
-	Shop Supplies		CABLE LATCH ASSY		1.00
Parts Charge:		184.77	Labor Charge:	105.00	

Workorder: 1109060

Problem: check brake lights and turn signals.

Meter Reading: 48548		Labor		Parts	
In Date: 08/26/2011	Close Date: 08/29/2011	Hours	Description		Quantity
-	Test And Replace Failed Left Rear Brake And Turn Signal	0.50	3157 TAIL LIGHT BULBS		1.00
	Lamp Bulb With New.				
Parts Charge:		0.63	Labor Charge:	30.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1110447

Problem: Pm service

Meter Reading: 49094		Labor		Parts	
In Date: 09/30/2011	Close Date: 10/06/2011	Hours	Description		Quantity
-	Perform Pm Service.	5.00	5W20 ENGINE OIL		7.00
-	Rotate And Balance All Four Tires.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Shop Supplies		31-20 WIPER BLADES 20" BLADE		2.00
			G8018 FUEL FILTER LBF G6593 WIX 33595		1.00
			SHOP SUPPLIES		1.00
			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
Parts Charge:		41.97	Labor Charge:	300.00	

Workorder: 1202969

Problem: P.M. service.

Meter Reading: 51492		Labor		Parts	
In Date: 03/28/2012	Close Date: 04/09/2012	Hours	Description		Quantity
-	P.M. Service.	5.00	5W20 ENGINE OIL		7.00
-	Rotate Ande Balance All Tires.		31-20 WIPER BLADES 20" BLADE		2.00
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
Parts Charge:		46.12	Labor Charge:	300.00	

Workorder: 1209006

Problem: P.M. service.

Meter Reading: 54487		Labor		Parts	
In Date: 09/20/2012	Close Date: 09/28/2012	Hours	Description		Quantity
-	P.M. Service.	11.50	5W20 ENGINE OIL		7.00
-	Replace And Balance Four New Tires.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Complete Wheel Alignment.Test Drive.		31-20 WIPER BLADES 20" BLADE		2.00
-	Resurface Front Rotors For Pulsation.Service And Lube		179747492 LT245/75R16 WRANGLER SR-A E		4.00
-	Calipers.		TIRE DISPOSAL FEE		4.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			G8018 FUEL FILTER LBF G6593 WIX 33595		1.00
Parts Charge:		815.83	Labor Charge:	690.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1210148

Problem: repair rust on roof at front near windsheid

Meter Reading: 54487		Labor		Parts	
In Date: 10/02/2012	Close Date: 10/23/2012	Hours	Description	Quantity	
- Repair Rust On Roof At Front Near Windsheid					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 576.00

Workorder: 1300290

Problem: Side door lock inop. Cannot open.

Meter Reading: 55455		Labor	Parts	
In Date: 01/08/2013	Close Date: 01/17/2013	Hours	Description	Quantity
- Diagnose And Replace Failed Side Cargo Door Latch Assemble.		1.50	SHOP SUPPLIES	1.00
			REMOTE	1.00
- Shop Supplies			EMOTE CONTROL SYSTE	1.00
Parts Charge: 85.31		Labor Charge: 90.00		

Workorder: 1302821

Problem: Pm service.See notes on side door trimax lock missing.

Meter Reading: 56892		Labor	Parts	
In Date: 03/22/2013	Close Date: 03/29/2013	Hours	Description	Quantity
-	Perform Pm Service.	6.25	SHOP SUPPLIES	1.00
-	Diagnose For Windshield Washer Pump Inop.Test And		LOCK AND REKEY	1.00
	Replace Failed Washer Pump With New.Had To Remove		1372 OIL FILTER	1.00
	Battery To Acess.Install New Trimax Lock On Side Door		WASHER FL	1.00
	Asper Request.		5W20 ENGINE OIL	7.00
-	Rotate Nd Balance All Four Tires.		L0152-063 GEAR SHIELD	1.00
-	Shop Supplies		USED FIREX REFURBED F	1.00
			WASHER PUMP	1.00
	Parts Charge: 150.91	Labor Charge:	375.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1309756

Problem: P.M. service.

Meter Reading: 59498		Labor		Parts	
In Date: 09/26/2013	Close Date: 10/22/2013	Hours	Description	Quantity	
- P.M. Service.		6.00	SHOP SUPPLIES	1.00	
- Replace Leaking Front Shocks.			NAPAGOLD FUEL FILTER	1.00	
- Rotate And Balance All Tires.			Shock - Gas Grande Fleet - Front	2.00	
- Shop Supplies			5W20 ENGINE OIL	7.00	
			31-20 WIPER BLADES 20	2.00	
			NAPAGOLD OIL FILTER	1.00	
Parts Charge: 157.67		Labor Charge: 360.00			

Workorder: 1403662

Problem: Pm service.

Meter Reading: 61886		Labor		Parts	
In Date: 04/15/2014	Close Date: 04/24/2014	Hours	Description	Quantity	
- Perform Pm Service		6.00	5W20 ENGINE OIL	7.00	
- Test Starting And Charging System.Battery Failed Load			WIPER BLADE	2.00	
- Test After Recharge.Replace Failed Battery With New.			BATTERY	1.00	
- Rotate And Balance All Four Tires.			SHOP SUPPLIES	1.00	
- Shop Supplies			NAPAGOLD OIL FILTER	1.00	
			USED FIRE X REFURBISHED	1.00	
			NAPAGOLD FUEL FILTER	1.00	
			WASHER FL	1.00	
Parts Charge: 173.84		Labor Charge: 360.00			

Workorder: 1410845

Problem: Transition Prep Charge

Meter Reading: 64889		Labor		Parts	
In Date: 10/29/2014	Close Date: 10/29/2014	Hours	Description	Quantity	
- Transition Prep Charge		2.00			
Parts Charge: 0.00		Labor Charge: 0.00			

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1411774

Problem: P.M. Service.

Meter Reading: 64894		Labor		Parts	
In Date: 11/20/2014	Close Date: 11/26/2014	Hours	Description		Quantity
-	Pm Service.	6.50	5W20 ENGINE OIL		7.00
-	Inspect And Service Rear Differential.		NAPAGOLD OIL FILTER		1.00
-	Rotate And Balance All Four Tires.		NAPAGOLD AIR FILTER		1.00
-	Make Up And Replace Missing Front And Rear Asset Numbers.		NAPA GEAR 80W-90 QT		3.00
-	Shop Supplies		PTEX ULTRA GREY 3OZ		1.00
			SHOP SUPPLIES		1.00
			WIPER BLADE		2.00
			FRICITION MODIFIER		2.00
Parts Charge:		77.46	Labor Charge:	390.00	

Workorder: 1411926

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 64889		Labor		Parts	
In Date: 11/26/2014	Close Date: 11/26/2014	Hours	Description		Quantity
-	1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 97.92

Workorder: 1500094

Problem: 1 - Key(s) issued

Meter Reading: 65555		Labor		Parts	
In Date: 01/05/2015	Close Date: 01/05/2015	Hours	Description		Quantity
-	1 - Key(S) Issued	0.20	DUPLICATE VEHICLE KEYS		1.00
Parts Charge:		3.00	Labor Charge:	18.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1504805

Problem: Pm service and blower speed inop.

Meter Reading: 68464		Labor		Parts	
In Date: 05/12/2015	Close Date: 05/20/2015	Hours	Description		Quantity
- Pm Service.		9.50	5W20 ENGINE OIL		7.00
- Inspect Ac Blower Motor Speed Inop And Replace			WIPER BLADE		2.00
Defective Blower Motor Resistor.			NAPAGOLD FUEL FILTER		1.00
- Perform Transmission Service.Replace Filter.Flush And			TRANS FILTER		1.00
Replace Transmission Fluid.			WASHER FLUID CONCENTR		1.00
- Repair Right Front Tire.Rotate And Balance All Four.			BLOWER MOTOR RESISTOR		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			SYN-ATF TRANS FLUID S		16.00
			USED FIRE X REFURBISHED		1.00
			NAPAGOLD OIL FILTER		1.00
Parts Charge: 189.20		Labor Charge: 570.00			

Workorder: 1509107

Problem: Left brake light inop.

Meter Reading: 69287		Labor		Parts	
In Date: 09/11/2015	Close Date: 09/16/2015	Hours	Description		Quantity
- Test And Replace Defective Left Brake Lamp Bulb.		0.50	BULB		2.00
Parts Charge: 1.50		Labor Charge: 30.00			

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1510840

Problem: Pm service.Vibration when stopping.Clicking noise on slow turns.

Meter Reading: 69933		Labor		Parts	
In Date: 10/27/2015	Close Date: 11/16/2015	Hours	Description		Quantity
-	Pm Service.	18.75	SHAFT ASSY		1.00
-	Check Brake System.Replace Two Front Brake		LOADED CAL		1.00
	Rotors,Front And Rear Brake Pads And All Four		LOADED CAL		1.00
	Calipers.Resurface Rear Rotors. Flush And Bleed Brake		CASTER-CAMBER BUSHING		2.00
	System And Test Drive.		TR416 VALVE STEM		2.00
-	Diagnose Front End And Steering System.Replace		SHOP SUPPLIES		1.00
	Intermediate Steering Shaft.		WIPER BLADE		2.00
-	Replace Two Tires.Rotate And Balance All Four.		BRAKE CLEANER		1.00
-	Complete Front End Alignment.Replace Two Camber		NAPA OIL SEAL		2.00
	Bushings For Adjustment.		REAL BRAKE PAD		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		2.00
			NAPAGOLD OIL FILTER		1.00
			5W20 ENGINE OIL		7.00
			DISC BRAKE ROTOR HUB		2.00
			REMAN BRAKE CALIPER		1.00
			LT245 75R16		2.00
			REMAN BRAKE CALIPER		1.00
			B FLUID DOT 3-32OZ		2.00
Parts Charge: 1,641.10		Labor Charge:	1,125.00		

Workorder: 1602196

Problem: Rear door lock broken.Vibration when braking between 45 /50 MPH.Misfires when driving.

Meter Reading: 71741		Labor		Parts	
In Date: 03/02/2016	Close Date: 03/17/2016	Hours	Description		Quantity
-	Test And Replace Two Defective Back Door Latch	11.00	SHOP SUPPLIES		1.00
	Assemblies.		DOOR LATCH W/CABLE		1.00
-	Replace All Eight Sparkplugs.		DOOR HANDLE W/CABLE		1.00
-	Perform Fuel Injectors Clean And Decarb Top Engine		SPARK PLUG		8.00
	Induction Service.		INTAKE CLEANER KIT		1.00
-	Check And Resurface Both Front Brake Rotors.Clean And		INJECTOR CLEANER		1.00
	Lube Calipers And Test Drive.				
-	Shop Supplies				
Parts Charge: 260.20		Labor Charge:	660.00		

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1604933

Problem: P.M. service.

Meter Reading: 72091		Labor		Parts	
In Date: 05/12/2016	Close Date: 05/20/2016	Hours	Description		Quantity
- P.M. Service.		12.50	A C CONDENSER		1.00
- A/C Performance Test,Low On Freon.Replace Leaking			NAPAGOLD OIL FILTER		1.00
Condensor,Orifice And Accumulatorvacuum And Recharge			SERPENTINE BELT		1.00
System To Specs.			A/C Accumulator w/ Hose Assy		1.00
- Check And Replace Serpentine Belt.			20" WIPER BLADE		2.00
- Test Battery And Charging System.Replace Bad Battery.			BATTERY		1.00
- Replace Two Tires,Rotate And Balance All Four.			SHOP SUPPLIES		1.00
- Shop Supplies			NAPAGOLD AIR FILTER		1.00
			5W20 ENGINE OIL		7.00
			NAPAGOLD FUEL FILTER		1.00
			TR416 VALVE STEM		2.00
			CAP AND VALVE KIT		1.00
			LT245 75R16		2.00
			R134A LV SHOP 2		2.00
			BLOWER MOTOR RESISTOR		1.00
			TIRE DISPOSAL FEE		2.00
			A/C Orifice Tube		1.00
			USED FIRE X REFURBISHED		1.00
Parts Charge: 899.38		Labor Charge: 750.00			

Workorder: 1606387

Problem: A/C inop

Meter Reading: 72460		Labor		Parts	
In Date: 06/23/2016	Close Date: 07/06/2016	Hours	Description		Quantity
- Diagnose A/C Inop,Bad Compressor Coil.Replace		4.00	A/C COMPRESSOR		1.00
Compressor,Cycling Switch And High Pressure			SHOP SUPPLIES		1.00
Switch.Vacuum And Recharge System To Specs.			E8 A/C OIL UNIV W DYE		1.00
- Shop Supplies			A/C SWITCH		1.00
			O ring		2.00
			PRESSURE SWITCH		1.00
Parts Charge: 705.18		Labor Charge: 240.00			

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1608876

Problem: Side cargo door inop and vibration in steering wheel over 45 mph.

Meter Reading: 73550		Labor		Parts	
In Date: 08/25/2016	Close Date: 09/08/2016	Hours	Description		Quantity
-	Replace Side Door Latch And Handle Assemble.	3.50	latch		1.00
-	R&R All Fourv Tires And Reindex To Rims And Rebalance		SHOP SUPPLIES		1.00
	To Correct Vibration At High Speeds.		latch		1.00
-	Shop Supplies				
Parts Charge:		187.83	Labor Charge:	210.00	

Workorder: 1611327

Problem: P.M. service and oil light comes on and vibration at highway speeds.

Meter Reading: 74442		Labor		Parts	
In Date: 11/02/2016	Close Date: 11/22/2016	Hours	Description		Quantity
-	P.M. Service.	10.50	SHOP SUPPLIES		1.00
-	Pressure Test And Inspect Cooling System.Replace		NAPAGOLD OIL FILTER		1.00
	Leaking Radiator,Upper And Lower Hoses.Flush And Refill		CURVED RADIATOR HOSE		1.00
	System.		VALVE VASY		1.00
-	Replace One Tire,Road Force And Rotate And Balance All		WASHER FLUID CONCENTR		1.00
	Four.		20" WIPER BLADE		2.00
-	Shop Supplies		WD40 SPR		1.00
			PEAK GLOBAL ANTIFRZ		1.00
			CURVED HOSE		1.00
			RADIADOR ASSY		1.00
			5W20 ENGINE OIL		7.00
Parts Charge:		372.73	Labor Charge:	630.00	

Workorder: 1701468

Problem: damage to driver door

Meter Reading: 75141		Labor		Parts	
In Date: 01/25/2017	Close Date: 02/13/2017	Hours	Description		Quantity
-	Damage To Driver Door				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 988.80

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1704053

Problem: Runs rough and check engine light.

Meter Reading: 76246		Labor		Parts	Quantity
In Date: 04/24/2017	Close Date: 05/11/2017	Hours	Description		
-	Computer Diagnose ,Code P0305.Pinpoint Test Found	7.00	SHOP SUPPLIES		1.00
	Spark Pludgs At Cylinder # Five Inop.Replace Defective		20" WIPER BLADE		2.00
	Spark Plug And Road Test. Clear Codes.		5W20 ENGINE OIL		7.00
-	P.M. Service.		NAPAGOLD OIL FILTER		1.00
-	Balance And Rotate All Four Tires.		USED FIRE X REFURBISHED		1.00
-	Shop Supplies		INJECTOR CLEANER		1.00
			NAPAGOLD FUEL FILTER		1.00
			SPARK PLUG		1.00
			GREEN TIRE VALVE CAP		300.00
Parts Charge:		76.54	Labor Charge:	420.00	

Workorder: 1706020

Problem: Rough idle,poor acceleration.A/C not cold.

Meter Reading: 76871		Labor		Parts	Quantity
In Date: 06/19/2017	Close Date: 06/30/2017	Hours	Description		
-	Diagnose Rough Idle And No	5.00	FORD IGNITION COIL		2.00
	Power.P0301,P0302.Replace #1 & #2 Coil.Clear Codes.		A/C VALVE		1.00
-	Check A/C Performance, Intermittently Blows Out		VACUUM RESEVOIR		1.00
	Defrost.Replace Reservior And One Way Valve.		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		189.61	Labor Charge:	300.00	

Workorder: 1708049

Problem: 1 - Key(s) issued

Meter Reading: 77557		Labor		Parts	Quantity
In Date: 08/16/2017	Close Date: 08/16/2017	Hours	Description		
-	1 - Key(S) Issued	0.30	DUPLICATE VEHICLE KEYS		1.00
Parts Charge:		3.00	Labor Charge:	18.00	

3/1/2018
3:39:06PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139925 2003 FORD E350 Van, 1 Ton, Cargo, No Glass

Workorder: 1709559

Problem: P.M. service and check engine light, missing.

Meter Reading: 78284		Labor		Parts	Quantity
In Date: 10/02/2017	Close Date: 10/17/2017	Hours	Description		
-	P.M. Service.	10.00	SHOP SUPPLIES		1.00
-	Check ,Pinpoint Test ,Replace Defective Right Reverse Bulb.		LAMP		1.00
-	Computer Diagnose Check Engine Light .Code P0305		20" WIPER BLADE		2.00
-	And P0306.Pinpoint Test .Replace Defective Ignition Coils		DAMPER ASY		1.00
-	#5And #6 .Clear Light And Road Test.		F3TZ7L278A BUSHING SH		1.00
-	Check And Replace All Three Defective Shifter Bushings.		NAPAGOLD OIL FILTER		1.00
-	Balance And Rotate All Four Tires.		5W20 ENGINE OIL		8.00
-	Shop Supplies		FORD IGNITION COIL		2.00
Parts Charge:		195.13	Labor Charge:	600.00	

Workorder: 1801127

Problem: Transition Prep Charge

Meter Reading: 79090		Labor		Parts	Quantity
In Date: 01/30/2018	Close Date: 01/30/2018	Hours	Description		
-	Transition Prep Charge	2.00			
Parts Charge:		0.00	Labor Charge:	0.00	

Total Parts Charges:	8,996.49	Total Labor Charges:	12,743.50	Total Comm. Charges:	2,844.16
----------------------	-----------------	----------------------	------------------	----------------------	-----------------