

**Palm Beach County Fleet Management
Asset Maintenance History**

K11734 2006 DODGE 2500 Utility Body, 3/4 Ton, 4X4, W/Winch

Workorder: 641556 **Meter:** 0 **In Date:** 06/27/2006 **Closed:** 06/27/2006
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 100.00 Parts: 0.00 Total: 100.00
:

Workorder: 642452 **Meter:** 410 **In Date:** 07/17/2006 **Closed:** 07/18/2006
Problem: WINCH INOP.

- C/s Winch Inop. Verified Concern.reset Circuit Breaker.

Hours 0.50 Labor: 25.00 Parts: 0.00 Total: 25.00
:

Workorder: 647493 **Meter:** 2218 **In Date:** 10/19/2006 **Closed:** 10/20/2006
Problem: REPAIR WINCH CABLE.

- Cut Frayed Out,cable And Installed New Eyelet.reinstall Winch Cable.install Ground Cable From Battery To Motor.

Parts List	Qty
Shop Supplies	1.00
Wc2v Battery Cable 2 Gauge Black	3.00

- Shop Supplies

Hours 2.50 Labor: 137.50 Parts: 9.61 Total: 147.11
:

Workorder: 648457 **Meter:** 2510 **In Date:** 11/08/2006 **Closed:** 11/09/2006
Problem: REPAIR R/R TIRE.

- Repair And Balance Right Rear Tire.

Parts List	Qty
Shop Supplies	1.00

- Shop Supplies

Hours 1.00 Labor: 55.00 Parts: 2.00 Total: 57.00
:

Workorder: 733311 **Meter:** 0 **In Date:** 01/25/2007 **Closed:** 01/25/2007
Problem: MINOR WELD REPAIR OR MACHINING.

- Minor Weld Repair Or Machining.

Hours 2.00 Labor: 110.00 Parts: 0.00 Total: 110.00
:

Workorder: 735862 **Meter:** 5763 **In Date:** 03/20/2007 **Closed:** 03/23/2007
Problem: P.M SERVICE

- Pm Service

Parts List	Qty
Shop Supplies	1.00
Ph16 Oil Filter Lbf Ph253 Wix 51307	1.00
5w20 Engine Oil	7.00
10020 Injector Cleaner Don't Reorder	1.00

- Nitrogen Fill Tires

- Shop Supplies

Hours 3.75 Labor: 206.25 Parts: 39.28 Total: 245.53
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 745879 **Meter:** 11048 **In Date:** 10/18/2007 **Closed:** 10/24/2007
Problem: P.M SERVICE,INSTALL CUSTOMERS STROBE LIGHT

	Parts List	Qty
- Pm Service	Shop Supplies	1.00
- Install Customer Supplied Strobe Light;install Wiring & Switch.	Ph16 Oil Filter Lbf Ph253 Wix 51307	1.00
- Balance 4 Tires	5w20 Engine Oil	7.00
- Shop Supplies	10020 Injector Cleaner Don't Reorder	1.00
	31-24 Wiper Blades 24" Blade	2.00
	30055-20 Ckt Breaker 20 Amp	1.00
	84863 Lighted Switch	1.00
Hours 6.25	Labor: 375.00	Parts: 45.19
:		Total: 420.19

Workorder: 836698 **Meter:** 14615 **In Date:** 04/08/2008 **Closed:** 04/16/2008
Problem: P.M SERVICE,CHECK BLOWER MOTOR

	Parts List	Qty
- Pm Service	Shop Supplies	1.00
- R&r Pindle Hitch Safety Pin	Ca9401 Air Filter Lbf Af3590 Wix 42725	1.00
- Remove R/frt Heat Light Assembly To Repl Parking Light Bulb Repl Rad Reflector Right Front Of Bed.	Ph16 Oil Filter Lbf Ph253 Wix 51307	1.00
- Service Winch.test And Inspect Operation Of Winch And Cable.rewind & Lube Cable.	5w20 Engine Oil	7.00
- Diag Ac Broken Blend Door.send To Dealer For Repair	31-24 Wiper Blades 24" Blade	2.00
- Repair One Tire Mount On Right Rear.balance All 4 Tires. Nitro Fill Tires.	Used Firex Refurbed Fire Extingshers	1.00
- To/from Dealer For Ac Recirculation Door & Housing Replace't	Red Reflector	1.00
- Shop Supplies	18410 Pintle Pin	1.00
Hours 9.25	Labor: 555.00	Parts: 58.05
:		Total: 613.05

Workorder: 841310 **Meter:** 16426 **In Date:** 07/14/2008 **Closed:** 07/21/2008
Problem: REPLACE TIRES

	Parts List	Qty
- Replace All 4 Tires. Nitro Fill & Hgih Speed Balance All 4 Tires.	Shop Supplies	1.00
- Shop Supplies	Tire Disposal Fee	4.00
	748469189 245/70r17 Wrg Silent Armor E	4.00
Hours 2.00	Labor: 120.00	Parts: 755.80
:		Total: 875.80

Workorder: 846623 **Meter:** 18419 **In Date:** 11/03/2008 **Closed:** 11/14/2008
Problem: P.M SERVICE,CHECK D/S SEAT

	Parts List	Qty
- Pm Service	Shop Supplies	1.00
- Transmission Service Flush W/new Fluid.	Ca9401 Air Filter Lbf Af3590 Wix 42725	1.00
- Rotate And High Speed Balance All 4 Tires.	Ph16 Oil Filter Lbf Ph253 Wix 51307	1.00
- Service Winch.	5w20 Engine Oil	7.00
- To/from Dealer For Driver Seat Repair.0847028	Syn/atf Trans Fluid Synthetic	16.00
- Shop Supplies	31-24 Wiper Blades 24" Blade	2.00
Hours 8.25	Labor: 495.00	Parts: 119.94
:		Total: 614.94

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 935010	Meter: 21075	In Date: 03/11/2009	Closed: 03/16/2009
Problem: A/C INSPECTION			
- Ck A/c System. Condensor Fan Inop. Transport To Dealer For Warranty.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 937776	Meter: 22489	In Date: 05/14/2009	Closed: 05/18/2009
Problem: P.M SERVICE			
- Pm Service	Parts List		Qty
- Check Lights,diag R/r Marker Light Not Working.repair Wire To Correct Problem.	Shop Supplies		1.00
- Rotate And Hi Speed Balance 4 Tires.nitrofill Tires.	Ph16 Oil Filter Lbf Ph253 Wix 51307		1.00
- Service Winch.	5w20 Engine Oil		7.00
- Shop Supplies	L0135-063 Lubriplate Chain&cable Lube,03050crc		1.00
	31-24 Wiper Blades 24" Blade		2.00
	Used Firex Refurbed Fire Extingshers		1.00
Hours 5.05	Labor: 303.00	Parts: 53.64	Total: 356.64
:			
Workorder: 940646	Meter: 23898	In Date: 07/13/2009	Closed: 07/16/2009
Problem: RECALL #H46			
- To/from Dealer for reall # H46	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 942928	Meter: 25235	In Date: 09/03/2009	Closed: 09/10/2009
Problem: A/C inspection.			
- A/c inspection & performance test, evacuate, leak test & recharge system.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
	R134a Refrigerant		2.00
Hours 1.50	Labor: 90.00	Parts: 9.26	Total: 99.26
:			
Workorder: 943180	Meter: 25343	In Date: 09/14/2009	Closed: 09/15/2009
Problem: Check battery			
- Test starting & charging system, test & replace battery.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
	Group 65 Battery (mtc Bxt-65-850)		1.00
Hours 1.00	Labor: 60.00	Parts: 127.45	Total: 187.45
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 946031 **Meter:** 26997 **In Date:** 11/16/2009 **Closed:** 12/04/2009
Problem: P.M service, brakes making noise.

- P.m service.	Parts List	Qty
- Machine both front brake rotors, install new pads, service caliper slides, flush system & test drive.	Shop Supplies	1.00
- Replace broken pintal safety pin.	Ph16 Oil Filter Lbf Ph253 Wix 51307	1.00
- Inspect & service winch.	Mx965 Front Pads Dodge 2500/3500 P/u	1.00
- Repair L/r tire, rotate & balance all four tires.	5w20 Engine Oil	7.00
- Shop Supplies	31-24 Wiper Blades 24" Blade	2.00
	18410 Pintle Pin	1.00
Hours 9.55	Labor: 573.00	Parts: 77.69
:		Total: 650.69

Workorder: 947044 **Meter:** 27399 **In Date:** 12/15/2009 **Closed:** 12/16/2009
Problem: L/F Tire has nail

- Repair L/f tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Tr416 Valve Stem	1.00
Hours 1.00	Labor: 60.00	Parts: 3.19
:		Total: 63.19

Workorder: 1001401 **Meter:** 29165 **In Date:** 02/08/2010 **Closed:** 02/10/2010
Problem: Check turn signals.

- Test & replace L/f turn signal bulb.	Parts List	Qty
	3157na Amber Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 1.32
:		Total: 31.32

Workorder: 1004902 **Meter:** 31877 **In Date:** 05/12/2010 **Closed:** 05/19/2010
Problem: P.M service, R/R tire flat.

- P.m service.	Parts List	Qty
- Pressure test & inspect cooling system, flush & renew coolant.	Shop Supplies	1.00
- Service transfere case.	Fan Blade / 05104787aa	1.00
- Mount two new tires, rotate & balance all four tires.	Ac Fan Motor / 05103465aa	1.00
- Test & inspect A/c system, evacuate freon & replace condencer fan motor assembly, vacuum & recharge system & performance test.	Ph16 Oil Filter Lbf Ph253 Wix 51307	1.00
- Alignment.	Ca9401 Air Filter Lbf Af3590 Wix 42725	1.00
- Inspect & service winch.	Syn/atf Trans Fluid Synthetic	5.00
- Shop Supplies	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
	Antifreeze Ext/life All Makes (peak 407)	2.00
	179469492 Lt245/70r17 Wrangler Sr-a E	2.00
	Tr416 Valve Stem	2.00
	Tire Disposal Fee	2.00
Hours 14.25	Labor: 855.00	Parts: 565.55
:		Total: 1,420.55

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1008721 **Meter:** 34115 **In Date:** 08/13/2010 **Closed:** 08/20/2010

Problem: Ac blows warm air.Also engine stalls out.

<ul style="list-style-type: none"> - Ac performance and leak test. Vacume and recharge system to specs. with virgin freon,oil and ultra voilent dye. - Computer diagnose stalling concern.monitor pids. and perform trottle body service then relearn all engine controls and road test. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> L17026 Cleaner Throttle Plate (smrt Blind) Shop Supplies R134a Refrigerant 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 2.00 	
Hours 4.75	Labor: 285.00	Parts: 16.44	Total: 301.44
:			

Workorder: 1012670 **Meter:** 36088 **In Date:** 11/12/2010 **Closed:** 11/29/2010

Problem: Pm service also see notes on flat tire and brakes.

<ul style="list-style-type: none"> - Perform pm service. - Install three new tires.nitrogen fill and balance all four. - Perform hemi engine tune up.replace 16 spark plugs with new.clear codes with scan tool and road test. - Perform front differential service. - Perform rear differential service. - Ac performance test and leak test.remove dash board and heater housing.replace failed ac evaporator ,accumulator and expansion valve with new.vacume and recharge system to specs. - Rotate and balance all four tires. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Shop Supplies Ph16 Oil Filter Lbf Ph253 Wix 51307 09997 Brake Clean 12345841 Gear Oil Synthetic 75w-90 12345841 Gear Oil Synthetic 75w-90 C8az19b546a Additive Differential (mc XI-3) 5w20 Engine Oil 31-24 Wiper Blades 24" Blade Spark Plugs Evaporator Liquid Line A/c O-rings Accumulator 179469492 Lt245/70r17 Wrangler Sr-a E Tire Disposal Fee 179469492 Lt245/70r17 Wrangler Sr-a E Tire Disposal Fee Tr416 Valve Stem 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 1.00 3.00 3.00 2.00 7.00 2.00 16.00 1.00 1.00 3.00 1.00 1.00 2.00 2.00 2.00 	
Hours 20.75	Labor: 1,245.00	Parts: 1,105.29	Total: 2,350.29
:	0		

Workorder: 1013024 **Meter:** 36072 **In Date:** 11/22/2010 **Closed:** 11/23/2010

Problem: flat tire

- From: 5470 belvedere To: lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

:

Workorder: 1107858 **Meter:** 42352 **In Date:** 07/27/2011 **Closed:** 07/27/2011

Problem: Screw in left front tire.

<ul style="list-style-type: none"> - Repair flat left front tire.nitrogen fill and balance same. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1109149 **Meter:** 43244 **In Date:** 08/29/2011 **Closed:** 09/07/2011
Problem: P.M. Service.

- Perform pm service.	Parts List	Qty
- Test and replace failed right rear marker lamp assembly with new.	Shop Supplies	1.00
- Rotate and balance all four tires.	Ph16 Oil Filter Lbf Ph253 Wix 51307	1.00
- Inspect and service power winch.	5w20 Engine Oil	7.00
- Shop Supplies	31-24 Wiper Blades 24" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	93745 Adapter Plug Plug Led Marker Light	1.00
	35200r Marker Light Red Led	1.00
Hours 5.25	Labor: 315.00	Parts: 55.04
:		Total: 370.04

Workorder: 1110056 **Meter:** 43571 **In Date:** 09/20/2011 **Closed:** 09/29/2011
Problem: A/C blows warm air.

- Ac performance and leak test.recover freon and remove ac condenser to acess and replace failed condenser cooling fan motor with new.vacume and recharge system to specs.with freon and oil.	Parts List	Qty
- Front bumper pull down with winch prior.fabricate,repair and secure front bumper and adjust brackets to align. same.	Shop Supplies	1.00
- Shop Supplies	Seal	1.00
	Condensor Fan Motor	1.00
	Seal	1.00
	Seal	2.00
Hours 5.00	Labor: 300.00	Parts: 157.64
:		Total: 457.64

Workorder: 1112481 **Meter:** 44953 **In Date:** 11/28/2011 **Closed:** 12/15/2011
Problem: Towed in coolant leak and belt off.

- Pressure test and inspect cooling system.replace failed water pump ,thermostat and serpentine belt with new.reverse flush cooling system and renew coolant.	Parts List	Qty
- Remove damage driver seat and install after repaired.transport damage seat to and from Central auto trim shop for repairing cushion,padding and leather.	Shop Supplies	1.00
- Install two new tires.nitrogen fill and balance all.	Antifreeze Ext/life All Makes (peak 407)	2.00
- Shop Supplies	Water Pump	1.00
	Idler Pulley Tensioner	1.00
	Thermostat	1.00
	Serpentine Belt	1.00
	179469492 Lt245/70r17 Wrangler Sr-a E	2.00
	Tire Disposal Fee	2.00
Hours 9.30	Labor: 558.00	Parts: 624.43
:		Total: 1,182.43

Workorder: 1112506 **Meter:** 44706 **In Date:** 11/23/2011 **Closed:** 11/28/2011
Problem: BROKEN SERPENTINE BELT/ COOLANT LEAK

- From: Australian & Perimeter Rd To: Lv Shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1204324 **Meter:** 49372 **In Date:** 05/07/2012 **Closed:** 07/06/2012
Problem: P.M. Service. See notes

- P.m. Service.	Parts List	Qty
- Replace both front signal light bulbs.	Shop Supplies	1.00
- Replace two tires, rotate and balance all four.	Ph16 Oil Filter Lbf Ph253 Wix 51307	1.00
- Test battery and charging system. replace bad battery.	Ca9401 Air Filter Lbf Af3590 Wix 42725	1.00
- Test drive for transmission slipping complain. r&r pan, clutch and metal shavings in pan. r&r transmission assemble. top off fluid, clear codes and test drive.	09997 Brake Clean	1.00
- Inspect and service winch.	5w20 Engine Oil	7.00
- Shop Supplies	Syn/atf Trans Fluid Synthetic	6.00
	31-24 Wiper Blades 24" Blade	2.00
	3157 Tail Light Bulbs	2.00
	Group 65 Battery (mtc Bxt-65-850)	1.00
	179469492 Lt245/70r17 Wrangler Sr-a E	2.00
	Tire Disposal Fee	2.00
	Line Pressure Sensor	1.00
	Transmission Assy	1.00
	Transfer Shifter Bushings	2.00
Hours 14.75	Labor: 885.00	Parts: 4,187.54
:		Total: 5,072.54

Workorder: 1206701 **Meter:** 49758 **In Date:** 07/18/2012 **Closed:** 07/26/2012
Problem: Check engine light on.

- Computer diagnose for check engine light on. test and replace both failed up stream oxygen sensors with new. clear codes with scan tool and road test.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Oxygen Sensor	2.00
Hours 3.25	Labor: 195.00	Parts: 116.18
:		Total: 311.18

Workorder: 1212300 **Meter:** 52880 **In Date:** 12/21/2012 **Closed:** 01/08/2013
Problem: Pm service

- P.m. Service.	Parts List	Qty
- Replace missing pintle pins.	5w20 Engine Oil	7.00
- Replace left front signal light bulb.	Ph16 Oil Filter Lbf P	1.00
- Inspect and service winch.	Used Firex Refurbed F	1.00
- Rotate and balance all tires.	31-24 Wiper Blades 2	2.00
- Shop Supplies	18410 Pintle Pin	1.00
	Miniature Bulb	1.00
	Shop Supplies	1.00
Hours 5.25	Labor: 315.00	Parts: 62.09
:		Total: 377.09

Workorder: 1302777 **Meter:** 54233 **In Date:** 03/21/2013 **Closed:** 03/28/2013
Problem: Right rear tire flat.

- Repair flat right rear tire. nitrogen fill and balance same.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1303403 **Meter:** 54589 **In Date:** 04/08/2013 **Closed:** 04/18/2013

Problem: Brake warning light on and brake squeals.

- Replace failed brake master cylinder, front brake pads and two new front brake rotors with new service calipers and flush brake fluid. automated bleed hydraulic system with scan tool and road test.	Parts List	Qty
	Rotor	2.00
	Brake Pad	1.00
- Shop Supplies	1401 Brake Fluid Bra	1.00
	Ptex Anti-seize 16oz	1.00
	Master Cyl	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 285.00	Parts: 843.61
:		Total: 1,128.61

Workorder: 1305214 **Meter:** 55686 **In Date:** 05/28/2013 **Closed:** 06/11/2013

Problem: Check engine light on .

- Diagnose check engine light.p0456.perform evap system test.replace defective fuel cap.clear codes and test drive,	Parts List	Qty
	Gas Cap	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 11.80
:		Total: 101.80

Workorder: 1306755 **Meter:** 56511 **In Date:** 07/08/2013 **Closed:** 07/30/2013

Problem: P.M. service and power steering inop.

- P.m. Service.	Parts List	Qty
- Diagnose power steering system.replace power steering pump.flush and bleed system.	5w20 Engine Oil	7.00
	Ph16 Oil Filter Lbf P	1.00
- Replace two tires, rotate and balance all four.	31-24 Wiper Blades 2	2.00
- Replace hood props.	Power Steering Pum	1.00
- Inspect and service winch.	Syn-atf Trans Fluid S	5.00
- Complete wheel alignment.test drive.	179469492 Lt245-70r17	2.00
- Shop Supplies	Tr416 Valve Stem	2.00
	Hood Lift Support	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.25	Labor: 675.00	Parts: 618.39
:		Total: 1,293.39

Workorder: 1312750 **Meter:** 59612 **In Date:** 12/20/2013 **Closed:** 12/31/2013

Problem: Towed in for no start.

- Diagnose for no start.remove fuel tank and replace failed fuel pump assembly with new..drain fuel and clean fuel tank.clear codes with scan tool and roadtest.	Parts List	Qty
	Electric Fuel Pump	1.00
	179469492 Lt245-70r17	2.00
- Install two new tires to the rear wheels.nitrogen fill, rotate and balance all four.	Tr416 Valve Stem	2.00
- Shop Supplies	fuel pump assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 5.50	Labor: 330.00	Parts: 1,002.65
:		Total: 1,332.65

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1312753 **Meter:** 59541 **In Date:** 12/20/2013 **Closed:** 12/20/2013
Problem: No start

- Tow From: Park and Ride and Perimeter Rd To: Lv Shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1400722 **Meter:** 60036 **In Date:** 01/22/2014 **Closed:** 02/27/2014
Problem: P.M. service and colant leak and recall n62/13v-528 tie rod stud.

- P.m. Service.

Parts List **Qty**

- Test battery and charging system,replace bad battery. 5w20 Engine Oil 7.00

- Pressure test and inspect cooling system.replace defective radiator cap,flush and refill system. Napagold Oil Filter 1.00

- Inspect and service winch. 31-24 Wiper Blades 2 2.00

- Rotate and balance all tires. Used Fire X Refurbished 1.00

- Shop Supplies Battery 65 1.00

Peak Global 2.00

Radiator 1.00

Cap 1.00

Shop Supplies 1.00

Hours 7.75 Labor: 465.00 Parts: 628.70 Total: 1,093.70
:

Workorder: 1408074 **Meter:** 63497 **In Date:** 08/14/2014 **Closed:** 09/08/2014
Problem: Pm service.Wipers intermittent.Has to jiggle turnsignal switch to operate wipers

- Pm service.

Parts List **Qty**

- Flush and refill transmission fluid. 5w20 Engine Oil 7.00

- Transport vehicle to and from dealer for replacing wiper switch. Napagold Oil Filter 1.00

- Inspect and service power winch. Napagold Air Filter 1.00

- Rotate and balance all four tires. 31-24 Wiper Blades 2 2.00

- Shop Supplies Syn-atf Trans Fluid S 12.00

Shop Supplies 1.00

Hours 8.25 Labor: 495.00 Parts: 99.86 Total: 594.86
:

Workorder: 1409142 **Meter:** 63616 **In Date:** 09/11/2014 **Closed:** 09/15/2014
Problem: Left rear tire flat

- Repair flat and balance left rear tire.

Parts List **Qty**

- Shop Supplies Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1501298 **Meter:** 65975 **In Date:** 02/04/2015 **Closed:** 02/05/2015
Problem: Left brake lamp inop.

- Test and replace defective left Led brake lamp assembly.

Parts List **Qty**

- Shop Supplies 4 Led S T T Lamp 1.00

Shop Supplies 1.00

Hours 0.50 Labor: 30.00 Parts: 22.85 Total: 52.85
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1503063 **Meter:** 66519 **In Date:** 03/25/2015 **Closed:** 04/14/2015
Problem: Ac inop.Replace tires with more aggressive grip.

- Pm service.	Parts List	Qty
- Ac performance and leak test for ac not cooling.evacuate system and replace defective ac condenser cooling fan assembly.vacume and recharge system to specs.	5w20 Engine Oil	7.00
- Inspect and service winch and replace defective winch cable.	Napagold Oil Filter	1.00
- Replace and balance all four tires.	31-24 Wiper Blades 2	2.00
- Replace rear brake pads and two rear brake calipers.resurface both rear brake rotors.service front calipers.flush and bleed brake system.roadtest.	Washer Fluid Concentr	1.00
- Shop Supplies	245 70r17 At Adventure	4.00
	1401 Brake Fluid Bra	2.00
	Brake Cleaner	1.00
	Radiator Fan Motor	1.00
	Ac Condenser Assy	1.00
	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	Mkd702a Rear Pads Dod	1.00
	Crane Cable Fabrication	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 13.75	Labor: 825.00	Parts: 1,935.06
:		Total: 2,760.06

Workorder: 1504714 **Meter:** 67132 **In Date:** 05/08/2015 **Closed:** 05/13/2015
Problem: Check turnsignal lights operation

- Diagnose and replace defective turn signal/multifunction switch.	Parts List	Qty
- Shop Supplies	Switch Mul	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 118.33
:		Total: 178.33

Workorder: 1504929 **Meter:** 67266 **In Date:** 05/14/2015 **Closed:** 05/20/2015
Problem: Left front turnsignal lamp inop.

- Test and replace defective left front turnsignal lamp bulb and socket.	Parts List	Qty
	Bulb	1.00
	Left Front Socket	1.00
Hours 0.50	Labor: 30.00	Parts: 18.11
:		Total: 48.11

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1511518	Meter: 70683	In Date: 11/10/2015	Closed: 11/23/2015
Problem: Right rear tire flat.			
- Replace two tires.rotate and balance all four.		Parts List	Qty
- Pm service.		5w20 Engine Oil	7.00
- Test and replace defective tag lamp bulb.		Wiper Blade	2.00
- Complete front end alignment.		Used Fire X Refurbished	1.00
- Inspect and service winch.		Bulb	1.00
- Shop Supplies		Cap Wheel	1.00
		Napagold Oil Filter	1.00
		245 70r17 At Adventure	2.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 8.75	Labor: 525.00	Parts: 661.35	Total: 1,186.35
:			

Workorder: 1511975	Meter: 70892	In Date: 11/24/2015	Closed: 12/09/2015
Problem: Lost fuel cap.Broken right side grab handle.			
- Computer diagnose check engine light on.code P0457.replace missing fuel cap.perform evapt.test.clear codes .test drive.		Parts List	Qty
		Fuel Cap	1.00
- Replace broken right side A pillar grab handle and trim.		Panel A Pi	1.00
- Shop Supplies		Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 108.19	Total: 288.19
:			

Workorder: 1604936	Meter: 74100	In Date: 05/12/2016	Closed: 05/20/2016
Problem: P.M. service and recall R25 and P40			
- P.m. Service.		Parts List	Qty
- Replace two tires,rotate and balance all four.		5w20 Engine Oil	7.00
- Replace inop strobe light with costomer provided part.fabricate wiring.		Napagold Oil Filter	1.00
- Inspect and service winch.		Washer Fluid Concentr	1.00
- Transport vehicle to dealedr for recall #r25.		Wiper Blades 24"	2.00
- Shop Supplies		245 70r17 At Adventure	2.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 8.75	Labor: 525.00	Parts: 507.57	Total: 1,032.57
:			

Workorder: 1610324	Meter: 76234	In Date: 09/30/2016	Closed: 10/14/2016
Problem: Towed in left rear tire flat.			
- Replace one tire.repair left front and balance both.		Parts List	Qty
- Shop Supplies		245 70r17 At Adventure	1.00
		Tr416 Valve Stem	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	1.00
Hours 1.50	Labor: 90.00	Parts: 242.79	Total: 332.79
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1610398 **Meter:** 76234 **In Date:** 09/30/2016 **Closed:** 10/04/2016
Problem: Flat tire on Rear

- Tow From: Belverdere and 5th Street, To: Lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1700222 **Meter:** 77581 **In Date:** 01/09/2017 **Closed:** 01/31/2017
Problem: P.M. service and recall s 43

- P.m. Service.
- Test battery and charging system.replace bad battery.
- Replace leaking steering dampner.
- Inspect and service winch.
- Pressure test and inspect cooling system.replace leaking water pump,radiator hoses, thermostat and gasket.flush and refill cooling system..
- Replace beacon light switch.
- A/c not blowing out vents.diagnose system.r&r dash and replace defrost and blend door actuators.recalibrate actuators.
- Shop Supplies

Parts List	Qty
New Water Pump	1.00
Curved Radiator Hose	1.00
Curved Radiator Hose	1.00
Peak Global Antifrz	2.00
Belt - Serpentine	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Wiper Blades 24"	2.00
Battery	1.00
Steering Stabilizer	1.00
Macs Chain Cable Lube	1.00
Thermostat	1.00
Rocker Led Blk Ambe	1.00
Door Actuator A/c	1.00
Mode Door Repair Kit	1.00
Shop Supplies	1.00

Hours 18.25 Labor: 1,095.0 Parts: 605.92 Total: 1,700.92
:

Workorder: 1706029 **Meter:** 79352 **In Date:** 06/19/2017 **Closed:** 07/20/2017
Problem: 4x4 linkage broke.Front driver side.

- Replace transfer case shifter bushings and adjust linkage.
- Replace bad upper idler pully.bearing was coming apart.
- Fabricate door spring mount for drivers side front utility door.lubricate and adjust.
- P.m. service.
- Replace two tires.rotate and balance four tires.nitro service.
- Diagnose windshield washer operation.transport to and from dealer for Tipm module replacement.
- Complete front end alignment.
- Service and inspect winch and wire rope.
- Shop Supplies

Parts List	Qty
245 70r17 At Adventure	2.00
Grommet	2.00
Shield	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Wiper Blades 24"	2.00
Tipm Module	1.00
Used Fire X Refurbished	1.00
Module Tipm	1.00
Progran Module	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 12.25 Labor: 735.00 Parts: 2,819.27 Total: 3,554.27
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1709248 **Meter:** 80402 **In Date:** 09/25/2017 **Closed:** 09/27/2017
Problem: Right rear tire has screw.

- Remove and repair right rear tire flat. **Parts List** **Qty**
- Shop Supplies Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1710952 **Meter:** 80783 **In Date:** 11/03/2017 **Closed:** 11/09/2017
Problem: A/C blows hot, Dead battery - possible draw, Windshield wiper fluid doesnt work.

- Diagnose A/c not cooling .condenser fan not working.evacuate A/c system.remove condenser and fan assembly.replace fan assembly .vacuum and recharge A/c system.cools to 42 degrees. **Parts List** **Qty**
A/c Condenser Fan Assy 1.00
Washer Pump 1.00
Washer Fluid Concentr 1.00
Shop Supplies 1.00

- Diagnose washer pump malfunction.replace washer pump and top off fluid.
- Perform starting and charging system analysis.battery was low but passed .recharge battery ,check for draws.all systems good .remove debris from alternator regulator and retest charging system.
- Shop Supplies

Hours 5.60 Labor: 336.00 Parts: 136.33 Total: 472.33
:

Workorder: 1803100 **Meter:** 82513 **In Date:** 03/23/2018 **Closed:** 04/04/2018
Problem: P.m. service.Transmission problem.

- P.m. service. **Parts List** **Qty**
- Computer diagnose transmission ,code P0882 ,12 volt relay low .check circuits for resistance and shorts .clean connectors and road test.no faults at this time. 5w20 Engine Oil 7.00
Napagold Oil Filter 1.00
Wiper Blades 24" 2.00
Washer Fluid Concentr 1.00
Shop Supplies 1.00

- Inspect and service winch.
- Repair left rear tire .rotate and high speed balance all four wheels and nitro fill all.
- Shop Supplies

Hours 6.75 Labor: 405.00 Parts: 29.51 Total: 434.51
:

Workorder: 1806129 **Meter:** 83752 **In Date:** 06/15/2018 **Closed:** 06/20/2018
Problem: Repair driver front tire.

- Replace and balance both front tires. **Parts List** **Qty**
- Shop Supplies 179469492 Lt245-70r17 2.00
Shop Supplies 1.00
Tire Disposal Fee 2.00

Hours 1.00 Labor: 60.00 Parts: 408.60 Total: 468.60
: