

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 943925 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 1209	Labor	Parts			
In Date: 09/30/2009	Hours	Description	Quantity		
- 1 - Wash Ticket(S) Issued					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	7.14

Workorder: 944552 **Problem:** Wash Vehicle

Meter Reading: 234	Labor	Parts			
In Date: 10/14/2009	Hours	Description	Quantity		
- Pre Delivery Inspection					
- Wash Vehicle					
Labor Charge: 3.00					
Parts Charge:	0.00	Labor Charge:	180.00		

Workorder: 1000007 **Problem:** Tire light on.

Meter Reading: 1985	Labor	Parts			
In Date: 01/04/2010	Hours	Description	Quantity		
- Inspect Tires, Reset Air Pressure & Tire Light.					
Labor Charge: 0.50					
Parts Charge:	0.00	Labor Charge:	30.00		

Workorder: 1002487 **Problem:** P.M service.

Meter Reading: 5809	Labor	Parts			
In Date: 03/10/2010	Hours	Description	Quantity		
- P.M Service.					
- Repair R/F Tire, Perform Nitro Service On All Four Tires.					
- Shop Supplies					
Labor Charge: 4.00					
Parts Charge:	18.67	Labor Charge:	240.00	SHOP SUPPLIES	1.00
				10W30 MOTOR OIL	5.00
				PH9837 OIL FILTER WIX 51522	1.00

Workorder: 1003428 **Problem:** no start

Meter Reading: 5809	Labor	Parts			
In Date: 04/01/2010	Hours	Description	Quantity		
- From: 401 N Dixie Hwy(S.A. Parking Lot) To: Lv Shop					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	78.00

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1003453

Problem: Check no start, has to jump start all the time.

Meter Reading: 6690	Labor	Parts	
In Date: 04/02/2010	Hours	Description	Quantity
<hr/>			
- Test Starting & Charging System, Charge & Test Battery, Battery Not Holding On Load Test, Replace Battery.	1.00	GROUP 34 BATTERY (ACD 34PS) SHOP SUPPLIES	1.00 1.00
- Shop Supplies			
Parts Charge:	102.68	Labor Charge:	60.00

Workorder: 1005712

Problem: flat tire

Meter Reading: 6690	Labor	Parts	
In Date: 06/01/2010	Hours	Description	Quantity
<hr/>			
- From: Pike Rd Southbound Entrance To Turnpike			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	78.00

Workorder: 1005714

Problem: R/R tire flat.

Meter Reading: 8868	Labor	Parts	
In Date: 06/01/2010	Hours	Description	Quantity
<hr/>			
- Repair R/R Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1009174

Problem: Pm service

Meter Reading: 11692	Labor	Parts	
In Date: 08/25/2010	Hours	Description	Quantity
<hr/>			
- Perform Pm Service.	3.00	SHOP SUPPLIES	1.00
- Rotate And Balance All Four Tires.		10W30 MOTOR OIL	5.00
- Shop Supplies		PH9837 OIL FILTER WIX 51522	1.00
Parts Charge:	18.72	Labor Charge:	180.00

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1009212		Problem: reflash canceiver		
Meter Reading: 11692		Labor		
In Date: 08/25/2010	Close Date: 08/27/2010	Hours	Description	Parts
				Quantity
- Reflash Canceiver		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
Parts Charge:		2.00	Labor Charge:	60.00
Workorder: 1011873		Problem: Left rear tire flat.		
Meter Reading: 14357		Labor		
In Date: 10/22/2010	Close Date: 10/25/2010	Hours	Description	Parts
				Quantity
- Repair Both Rear Tire Flat,Nitrogen Fill And Balance Both.		1.50	SHOP SUPPLIES	1.00
- Shop Supplies				
Parts Charge:		2.00	Labor Charge:	90.00
Workorder: 1013743		Problem: Right rear tire flat.		
Meter Reading: 15548		Labor		
In Date: 12/14/2010	Close Date: 12/16/2010	Hours	Description	Parts
				Quantity
- Repair And Balance Right Rear Tire.		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
Parts Charge:		2.00	Labor Charge:	60.00
Workorder: 1101127		Problem: P.M. service and seatbelt anchor recall.		
Meter Reading: 17192		Labor		
In Date: 01/31/2011	Close Date: 02/03/2011	Hours	Description	Parts
				Quantity
- P.M. Service.		7.50	SHOP SUPPLIES	1.00
- Replace Worn Out Rotors And Front Brake Pads.Bleed System And Test Drive.			TIRE DISPOSAL FEE	2.00
			PH9837 OIL FILTER WIX 51522	1.00
- Replace Two Tires,Rotate And Balance All.			732354500 225/60R16 EAGLE RS-A 97V	2.00
- Shop Supplies			10W30 MOTOR OIL	5.00
			WIPER BLADES	2.00
			FRONT PADS	1.00
			09997 BRAKE CLEAN	1.00
			FRONT ROTORS	2.00
Parts Charge:		630.84	Labor Charge:	450.00

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1106239 **Problem:** P.M. service and seat belt recall and detail to clean paint off left side.

Meter Reading: 23378	Labor	Parts		
In Date: 06/14/2011	Hours	Description	Quantity	
- Perform Pm Service.	6.50	TIRE DISPOSAL FEE		2.00
- Install Two New Tires To The Front Wheels.Nitrogen Fill		PH9837 OIL FILTER WIX 51522		1.00
And Balance All Four.		10W30 MOTOR OIL		5.00
- Perform Wheel Alignment Complete.		732354500 225/60R16 EAGLE RS-A 97V		2.00
- Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:	240.90	Labor Charge:	390.00	

Workorder: 1106304 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 17192	Labor	Parts		
In Date: 06/15/2011	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 91.80

Workorder: 1110209 **Problem:** Pm service and request buff out scratches on rear bumper.See notes.

Meter Reading: 28726	Labor	Parts		
In Date: 09/26/2011	Hours	Description	Quantity	
- Perform Pm Service.	4.00	5W20 ENGINE OIL		5.00
- Repair Flat Left Rear Tire.Nitrogen Fill,Rotate And Balance		PH9837 OIL FILTER WIX 51522		1.00
All Four.		SHOP SUPPLIES		1.00
- Shop Supplies				
Parts Charge:	16.10	Labor Charge:	240.00	

Workorder: 1110926 **Problem:** rear bumper needs repainted because of deep scratches

Meter Reading: 28726	Labor	Parts		
In Date: 09/27/2011	Hours	Description	Quantity	
- Rear Bumper Needs Repainted Because Of Deep Scratches				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 198.60

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1111227	Problem: 3 - Wash ticket(s) issued				
Meter Reading: 28726		Labor		Parts	
In Date: 10/24/2011	Close Date: 10/24/2011	Hours	Description		Quantity
- 3 - Wash Ticket(S) Issued					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 25.52		

Workorder: 1113182	Problem: 3 - Wash ticket(s) issued				
Meter Reading: 28726		Labor		Parts	
In Date: 12/14/2011	Close Date: 12/14/2011	Hours	Description		Quantity
- 3 - Wash Ticket(S) Issued					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 25.52		

Workorder: 1202266	Problem: Pm service and see notes on repairing rear bumper				
Meter Reading: 34765		Labor		Parts	
In Date: 03/06/2012	Close Date: 03/19/2012	Hours	Description		Quantity
- P.M. Service.		5.00	SHOP SUPPLIES		1.00
- Replace Two Tires,Rotate And Balance All Four.			10W30 MOTOR OIL		5.00
- Test Battery And Charging System.Recharge And Retest			PH9837 OIL FILTER WIX 51522		1.00
Battery,Fail Load Test.Replace Defective Battery.			WIPER BLADE		1.00
- Shop Supplies			CA10014 AIR FILTER WIX 49115		1.00
			TIRE DISPOSAL FEE		2.00
			GROUP 34 BATTERY (ACD 34PS)		1.00
			1066 WHITE LITHIUM (CRC 05037)		1.00
			732354500 225/60R16 EAGLE RS-A 97V		2.00
			WIPER BLADE		1.00
	Parts Charge: 400.86	Labor Charge: 300.00			

Workorder: 1203863	Problem: Towed in, check engine light on and no power.				
Meter Reading: 36413		Labor		Parts	
In Date: 04/24/2012	Close Date: 05/07/2012	Hours	Description		Quantity
- Transport Vehicle To And From Dealer For Replacing		2.00	SHOP SUPPLIES		1.00
Failed Throttle Actuator Harness With New (Warranty.)					
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge: 120.00			

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1203884		Problem: running rough...appears to be not running on all cylinders.			
Meter Reading: 34765		Labor		Parts	
In Date: 04/24/2012	Close Date: 04/24/2012	Hours	Description		Quantity
- Tow From: Lw Turnpike Plaza (Nb) Just S Of The Shell Gas Stn To: Lv Shop					
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 104.15
Workorder: 1204360		Problem: 5 - Wash ticket(s) issued			
Meter Reading: 36413		Labor		Parts	
In Date: 05/08/2012	Close Date: 05/08/2012	Hours	Description		Quantity
- 5 - Wash Ticket(S) Issued					
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 42.54
Workorder: 1204404		Problem: Left turnsignal light inop.			
Meter Reading: 36545		Labor		Parts	
In Date: 05/09/2012	Close Date: 05/10/2012	Hours	Description		Quantity
- Replace Left Front Signal Light Bulb.					
	Parts Charge:	1.31	Labor Charge:	15.00	
			0.25	3157NA AMBER BULB	1.00
Workorder: 1204941		Problem: no start			
Meter Reading: 36545		Labor		Parts	
In Date: 05/29/2012	Close Date: 05/30/2012	Hours	Description		Quantity
- Tow From: 7653 Oakmont Dr., Lake Worth FI To: Lv Shop					
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 104.15
Workorder: 1204991		Problem: Towed in.Engine lost power.Will not go over 25 MPH.			
Meter Reading: 37348		Labor		Parts	
In Date: 05/30/2012	Close Date: 06/11/2012	Hours	Description		Quantity
- Transport Vehicle To And From Dealer For Replacing Failed Trottle Body Assembly With New Under Factory Warranty.					
- Shop Supplies					
	Parts Charge:	2.00	Labor Charge:	120.00	
			2.00	SHOP SUPPLIES	1.00

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1205628

Problem: 5 - Wash ticket(s) issued

Meter Reading: 37348	Labor	Parts	
In Date: 06/13/2012	Hours	Description	Quantity
<hr/>			
- 5 - Wash Ticket(S) Issued			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	42.54

Workorder: 1208771

Problem: Pm service.

Meter Reading: 41864	Labor	Parts	
In Date: 09/14/2012	Hours	Description	Quantity
<hr/>			
- P.M. Service.	3.00	PH9837 OIL FILTER WIX 51522	1.00
- Rotate And Balance All Tires.		SHOP SUPPLIES	1.00
- Shop Supplies		10W30 MOTOR OIL	5.00
Parts Charge:	16.20	Labor Charge:	180.00

Workorder: 1301079

Problem: Pm service and lower control arm recall

Meter Reading: 47217	Labor	Parts	
In Date: 01/30/2013	Hours	Description	Quantity
<hr/>			
- P.M. Service.	6.50	SHOP SUPPLIES	1.00
- Rotate And Balance All Tires.		31-22 WIPER BLADES 22	2.00
- Resurface Front Brake Caliper And Service And Lube Calipers To Correct Pulsation.		19187383 WIPER BLADE	1.00
- Transport Vehicle To Dealer For Recall #12104(Control Arms)		CA10014 AIR FILTER W FILTER	1.00
- Shop Supplies		19187382 WIPER BLADE	1.00
		10W30 MOTOR OIL	5.00
Parts Charge:	41.49	Labor Charge:	390.00

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1305430

Problem: P.M. service.

Meter Reading: 52726		Labor		Parts	
In Date: 06/03/2013	Close Date: 06/25/2013	Hours	Description		Quantity
-	P.M. Service.	8.50	TIRE DISPOSAL FEE		4.00
-	Replace And Balance Four New Tires.		10W30 MOTOR OIL		5.00
-	Complete Wheel Alignment.Test Drive.		SHOP SUPPLIES		1.00
-	Transport Vehicle To Dealer For Check Engine Light And		WIPER BLADE		2.00
-	No Power.P2135.(Repair T.B. Wiring).		732354500 225-60R16 E		4.00
-	Shop Supplies		NAPAGOLD OIL FILTER		1.00
Parts Charge: 583.51		Labor Charge:	510.00		

Workorder: 1305466

Problem: no start/PM

Meter Reading: 52520		Labor		Parts	
In Date: 06/03/2013	Close Date: 06/04/2013	Hours	Description		Quantity
-	Tow From: 17068 84Th Court, Loxahatchee Fl To: Fleet Lv Shop				
Parts Charge: 0.00		Labor Charge:	0.00	Commercial Charge:	104.15

Workorder: 1306205

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 52726		Labor		Parts	
In Date: 06/20/2013	Close Date: 06/20/2013	Hours	Description		Quantity
-	1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge:	0.00	Commercial Charge:	91.80

Workorder: 1308399

Problem: Both rea turn signal bulbs inop.

Meter Reading: 55976		Labor		Parts	
In Date: 08/20/2013	Close Date: 08/30/2013	Hours	Description		Quantity
-	Replace Both Rear Signal Light Bulbs.	0.50	3057 BULB		2.00
Parts Charge: 1.38		Labor Charge:	30.00		

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1309680

Problem: Towed in for check engine light on and no power.

Meter Reading: 57109 In Date: 09/24/2013	Close Date: 10/15/2013	Labor Hours	Description	Parts	Quantity
-		2.00	Transport Vehicle To And From Dealer For Replacing Failed Throttle Position Sensor Cover With New Asper Tsb# 12-06-040031 To Correct Failed Code P2135	SHOP SUPPLIES	1.00
			Parts Charge:	2.00	
			Labor Charge:	120.00	

Workorder: 1309691

Problem: Pull over warning light came on

Meter Reading: 56931 In Date: 09/24/2013	Close Date: 09/25/2013	Labor Hours	Description	Parts	Quantity
-			Tow From: Okeechobee And Church St. Behind "Rooms To Go" To: Lv Shop		
			Parts Charge:	0.00	
			Labor Charge:	0.00	
			Commercial Charge:	104.15	

Workorder: 1310365

Problem: 5 - Wash ticket(s) issued

Meter Reading: 56931 In Date: 10/15/2013	Close Date: 10/15/2013	Labor Hours	Description	Parts	Quantity
-			5 - Wash Ticket(S) Issued		
			Parts Charge:	0.00	
			Labor Charge:	0.00	
			Commercial Charge:	48.66	

Workorder: 1311298

Problem: 3 - Wash ticket(s) issued

Meter Reading: 58531 In Date: 11/06/2013	Close Date: 11/06/2013	Labor Hours	Description	Parts	Quantity
-			3 - Wash Ticket(S) Issued		
			Parts Charge:	0.00	
			Labor Charge:	0.00	
			Commercial Charge:	25.52	

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1311975

Problem: P.M. service.

Meter Reading: 59688		Labor		Parts	
In Date: 12/02/2013	Close Date: 12/10/2013	Hours	Description	Quantity	
-	P.M. Service.	7.00	SHOP SUPPLIES	1.00	
-	Replace Noisy Left Front Hub Assemble.		NAPAGOLD OIL FILTER	1.00	
-	Resurface Front Brake Rotors,Replace Front Brake Pads.Service And Lube Calipers.		10W30 MOTOR OIL	5.00	
-	Rotate And Balance All Tires.		HUB BEARING ASSEMBLY	1.00	
-	Shop Supplies		2232 BRAKE FLUID QUAR	1.00	
			CERAMIC BRAKE LUBE	1.00	
			PADS	1.00	
Parts Charge: 251.75		Labor Charge: 420.00			

Workorder: 1401644

Problem: 5 - Wash ticket(s) issued

Meter Reading: 63096		Labor		Parts	
In Date: 02/19/2014	Close Date: 02/19/2014	Hours	Description	Quantity	
-	5 - Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 42.54	

Workorder: 1403224

Problem: P.M. service.

Meter Reading: 65610		Labor		Parts	
In Date: 04/02/2014	Close Date: 04/03/2014	Hours	Description	Quantity	
-	Perform Pm Service.	3.00	WIPER BLADE	2.00	
-	Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00	
-	Shop Supplies		NAPAGOLD OIL FILTER	1.00	
			NAPAGOLD AIR FILTER	1.00	
			10W30 MOTOR OIL	5.00	
Parts Charge: 35.48		Labor Charge: 180.00			

Workorder: 1403433

Problem: 3 - Wash ticket(s) issued

Meter Reading: 65720		Labor		Parts	
In Date: 04/08/2014	Close Date: 04/08/2014	Hours	Description	Quantity	
-	3 - Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 25.52	

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1406309

Problem: Tow in, stall.

Meter Reading: 69384	Labor	Parts	
In Date: 06/26/2014	Hours	Description	Quantity
- Computer Diagnose For Check Engine Light On.Pin Point Test For Fail Code P2135.Perform Tsb And Replace Failed Throttle Position Sensor With New.Clear Code And Relearn Idle Controls With Tech 2.	2.50	SHOP SUPPLIES SENSOR	1.00 1.00
- Shop Supplies			
Parts Charge:	102.80	Labor Charge:	150.00

Workorder: 1406391

Problem: Died on Road

Meter Reading: 69122	Labor	Parts			
In Date: 06/26/2014	Hours	Description	Quantity		
- Tow From: 3Rd And Quadrille To: Lv Shop					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	104.15

Workorder: 1407361

Problem: 2 - Wash ticket(s) issued

Meter Reading: 70319	Labor	Parts			
In Date: 07/25/2014	Hours	Description	Quantity		
- 2 - Wash Ticket(S) Issued					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	17.02

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1407470

Problem: Pm service.AC door actuator ticking.

Meter Reading: 70559	Labor	Parts	
In Date: 07/30/2014	Hours	Description	
Close Date: 08/07/2014		Quantity	
- Perform Pm Service.	7.20	NAPAGOLD OIL FILTER	1.00
- Diagnose For Ticking Noise In Dash And Replace Failed		1401 BRAKE FLUID BRA	1.00
Hvac Recycle Door Actuator With New And Recalibrate Same.		10W30 MOTOR OIL	5.00
		WASHER FLUID CONCENTR	1.00
- Install New Rear Brake Pads And Resurface Both Rear		PAD KIT	1.00
Brake Rotors.Service Calipers,Flush Brake Fluid And		ACTUATOR	1.00
Bleed System.Test Drive.		SHOP SUPPLIES	1.00
- Rotate And Balance All Four Tires.			
- Shop Supplies			
Parts Charge:	170.68	Labor Charge:	432.00

Workorder: 1408259

Problem: Towed in.Stalls right after starts up.

Meter Reading: 71104	Labor	Parts	
In Date: 08/20/2014	Hours	Description	
Close Date: 09/08/2014		Quantity	
- Test Starting And Charging System.Recharge And Retest	2.50	Battery Cable - Negative	1.00
Battery,Fail Load Test.Bad Cell.Replace Bad Battery And		SHOP SUPPLIES	1.00
Broken Negative Battery Cable.		BATTERY	1.00
- Shop Supplies			
Parts Charge:	210.58	Labor Charge:	150.00

Workorder: 1408390

Problem: wont start

Meter Reading: 70852	Labor	Parts	
In Date: 08/19/2014	Hours	Description	
Close Date: 08/22/2014		Quantity	
- Tow From: 401 N. Dixie Hwy, Wpb (State Atty Parking Lot) To: Lv Shop			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	104.15

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1408612 **Problem:** 2 - Wash ticket(s) issued
Meter Reading: 70852 **Labor**
In Date: 08/27/2014 **Hours** **Description** **Parts** **Quantity**

- 2 - Wash Ticket(S) Issued

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 17.02

Workorder: 1410793 **Problem:** 25 - Wash ticket(s) issued
Meter Reading: 73469 **Labor**
In Date: 10/28/2014 **Hours** **Description** **Parts** **Quantity**

- 25 - Wash Ticket(S) Issued

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 212.70

Workorder: 1411030 **Problem:** Right front tire going flat.
Meter Reading: 73784 **Labor**
In Date: 11/04/2014 **Hours** **Description** **Parts** **Quantity**

- Repair And Balance Right Front Tire. **1.00** SHOP SUPPLIES 1.00

- Shop Supplies

Parts Charge: 2.00 **Labor Charge:** 60.00

Workorder: 1412074 **Problem:** 2 - Wash ticket(s) issued
Meter Reading: 74899 **Labor**
In Date: 12/02/2014 **Hours** **Description** **Parts** **Quantity**

- 2 - Wash Ticket(S) Issued

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 17.02

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1500338

Problem: Pm service.Safety recall #14299

Meter Reading: 76350	Labor	Parts		
In Date: 01/09/2015	Hours	Description	Quantity	
- P.M. Service.	9.50	NAPAGOLD OIL FILTER	1.00	
- Replace Worn Right Front Wheel Hub Assemble.		SHOP SUPPLIES	1.00	
- Resurface Front Brake Rotors To Correct Brake Pulsation.Srvce And Lube Calipers And Brake Pads.		LATCH	1.00	
- Repair Left Rear Tire,Rotate And Balance All Four.		HUB BEARING ASSEMBLY	1.00	
- Transport Vehicle To Dealer For Recall #14299.		WIPER BLADE	2.00	
- Shop Supplies		10W30 MOTOR OIL	5.00	
Parts Charge:		214.43		
Labor Charge:		570.00		

Workorder: 1504782

Problem: Pm service.

Meter Reading: 81677	Labor	Parts		
In Date: 05/11/2015	Hours	Description	Quantity	
- Pm Service.	10.00	WASHER FLUID CONCENTR	1.00	
- Replace And Balance All Four Tires.		REAL WINDOW REGULATOR	1.00	
- Inspect And Service Transmission.Replace Filter.Flush And Replace Transmission Fluid.		TIRE DISPOSAL FEE	4.00	
- Inspect And Replace Defective Left Rear Window Regulator Assembly.		WIPER BLADE	2.00	
- Perform Complete Front End Alignment.		SHOP SUPPLIES	1.00	
- Shop Supplies		732354500 225-60R16 E	4.00	
		10W30 MOTOR OIL	5.00	
		NAPAGOLD OIL FILTER	1.00	
		SYN-ATF TRANS FLUID S	14.00	
		TRANS FILTER	1.00	
Parts Charge:		960.87		
Labor Charge:		600.00		

Workorder: 1505711

Problem: 2 - Wash ticket(s) issued

Meter Reading: 82602	Labor	Parts		
In Date: 06/08/2015	Hours	Description	Quantity	
- 2 - Wash Ticket(S) Issued				
Parts Charge:		0.00		
Labor Charge:		0.00		
Commercial Charge:		16.68		

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1507364 **Problem:** 4 - Wash ticket(s) issued

Meter Reading: 83979	Labor	Parts
In Date: 07/23/2015	Hours	Description
Close Date: 07/23/2015		Quantity
- 4 - Wash Ticket(S) Issued		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 33.36

Workorder: 1507658 **Problem:** A/C not cold at idle.

Meter Reading: 84938	Labor	Parts
In Date: 07/31/2015	Hours	Description
Close Date: 08/07/2015		Quantity
- Diagnose A/C Not Cold At Idle.Inop Cooling Fan.Replace Cooling Fan Assemble.	2.00	SHOP SUPPLIES COOLING FAN MOTOR ASSY
- Shop Supplies		
Parts Charge: 168.21	Labor Charge: 120.00	

Workorder: 1510628 **Problem:** P.M. service.

Meter Reading: 88004	Labor	Parts
In Date: 10/21/2015	Hours	Description
Close Date: 10/28/2015		Quantity
- Pm Service.	3.00	WASHER FLUID CONCENTR
- Rotate And Balance All Four Wheels.		10W30 MOTOR OIL
- Shop Supplies		SHOP SUPPLIES
		NAPAGOLD OIL FILTER
		NAPAGOLD AIR FILTER
		WIPER BLADE
Parts Charge: 38.07	Labor Charge: 180.00	

10/17/2016
9:23:53AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179152 2009 CHEVROLET IMPALA Car, Standard,

Workorder: 1602759

Problem: Pm service.Wiper blades.

Meter Reading: 93719		Labor		Parts	
In Date: 03/16/2016	Close Date: 03/23/2016	Hours	Description	Quantity	
-	Pm Service.	6.75	NAPAGOLD OIL FILTER		1.00
-	Replace Both Left And Right Marker Lamp Bulbs.Had To R&R Headlamps To Access.		FRONT ROTOR		2.00
-	Replace Front Brake Pads And Brake Rotors.Service Calipers.		BRAKE CLEANER		1.00
-	Rotate And Balance All Four Tires.		BULB		2.00
-	Shop Supplies		PADS		1.00
			22" WIPER BLADE		2.00
			10W30 MOTOR OIL		5.00
			B FLUID DOT 3-32OZ		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		189.59	Labor Charge:	405.00	

Workorder: 1603944

Problem: 3 - Wash ticket(s) issued

Meter Reading: 94447		Labor		Parts	
In Date: 04/14/2016	Close Date: 04/14/2016	Hours	Description	Quantity	
-	3 - Wash Ticket(S) Issued				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 28.62

Workorder: 1606897

Problem: Left front window inop.

Meter Reading: 98221		Labor		Parts	
In Date: 07/08/2016	Close Date: 07/18/2016	Hours	Description	Quantity	
-	Diagnose And Replace Left Front Window Regulator.	1.25	WINDOR REGULATOR		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		190.29	Labor Charge:	75.00	

Workorder: 1607192

Problem: Transition Prep Charge

Meter Reading: 98199		Labor		Parts	
In Date: 07/15/2016	Close Date: 07/15/2016	Hours	Description	Quantity	
-	Transition Prep Charge	2.00			
Parts Charge:		0.00	Labor Charge:	0.00	

Total Parts Charges:	4,621.41	Total Labor Charges:	7,167.00	Total Comm. Charges:	1,791.02
----------------------	-----------------	----------------------	-----------------	----------------------	-----------------