

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 334286

Problem: WASH VEHICLE

Meter Reading: 0	Labor	Parts		
In Date: 02/06/2003	Hours	Description	Quantity	
- Wash Vehicle	3.10			
- Pre-Delivery Inspection				
- Make Duplicate Keys For New Vehicle				
Parts Charge:	0.00	Labor Charge:	155.00	

Workorder: 334580

Problem: 001 WASH TICKET ISSUED OUT 02/06/03

Meter Reading: 0	Labor	Parts		
In Date: 02/06/2003	Hours	Description	Quantity	
- 001 Wash Ticket Issued Out 02/06/03				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 7.14

Workorder: 334663

Problem: VEHICLE TAGS

Meter Reading: 16	Labor	Parts		
In Date: 02/13/2003	Hours	Description	Quantity	
- Vehicle Tag Charge		VEHICLE TAG	1.00	
Parts Charge:	51.85	Labor Charge:	0.00	

Workorder: 535762

Problem: P.M SERVICE.RECALL.

Meter Reading: 7479	Labor	Parts		
In Date: 02/09/2005	Hours	Description	Quantity	
- P M Service	3.75	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
- Transport & Pick Up Vehicle At Dealer (Recall # 04007-		3481 FUEL FILTER FRM G3727 WIX 33481	1.00	
Steering Noisy)		31-22 WIPER BLADES 22" WIPER BLADE	2.00	
- Shop Supplies		SHOP SUPPLIES	1.00	
		10W30 MOTOR OIL	5.00	
		AF1519 AIR FILTER USE LAF1520 FRM CA8755A	1.00	
Parts Charge:	37.95	Labor Charge:	187.50	

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 536158

Problem: CK FRT TIRES AND ALIGNMENT

Meter Reading: 7479		Labor		Parts	
In Date: 02/14/2005	Close Date: 02/18/2005	Hours	Description		Quantity
- 2 Tires		4.00	SHOP SUPPLIES		1.00
- Align			405845127 245/75R16 WRANGLER AP D		2.00
- Road Test			TR416 VALVE STEM		2.00
- Shop Supplies					
Parts Charge: 227.36		Labor Charge: 200.00			

Workorder: 636007

Problem: P.M.SERVICE

Meter Reading: 11784		Labor		Parts	
In Date: 03/20/2006	Close Date: 03/22/2006	Hours	Description		Quantity
- Pm Service		2.75	10W30 MOTOR OIL		5.00
- Shop Supplies			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			SHOP SUPPLIES		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
Parts Charge: 27.31		Labor Charge: 137.50			

Workorder: 645982

Problem: SISTERS TOWING & TRANSPORTATON TOW FROM EOC - TOW

Meter Reading: 0		Labor		Parts	
In Date: 09/20/2006	Close Date: 09/21/2006	Hours	Description		Quantity
- Sisters Towing & Transportaton Tow From Eoc - Tow To					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 78.00	

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 645989

Problem: TOW IN,NO START/P.M.SERVICE

Meter Reading: 14245	Labor	Parts		
In Date: 09/21/2006	Hours	Description	Quantity	
- Pm Service	5.50	10W30 MOTOR OIL	6.00	
- Check Starting System R&R Ignition Cylinder Lock.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
- Convert To Nitrogen System.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00	
- Shop Supplies		88937315 IGNITION CYLINDER	1.00	
		3481 FUEL FILTER FRM G3727 WIX 33481	1.00	
		SHOP SUPPLIES	1.00	
		15026222 BLANK KEY	2.00	
		22514722 O-RING SEAL FUEL FILTER (ACD 217-452)	2.00	
		31-22 WIPER BLADES 22" WIPER BLADE	2.00	
Parts Charge:	110.31	Labor Charge:	37.50	Commercial Charge: 48.00

Workorder: 738101

Problem: P.M SERVICE

Meter Reading: 16241	Labor	Parts		
In Date: 05/03/2007	Hours	Description	Quantity	
- Pm Service	4.25	10W30 MOTOR OIL	6.00	
- Transmission Service Flush		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
- Shop Supplies		10020 INJECTOR CLEANER DON'T REORDER	1.00	
		31-22 WIPER BLADES 22" WIPER BLADE	2.00	
		SYN/ATF TRANS FLUID SYNTHETIC	16.00	
		SHOP SUPPLIES	1.00	
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
Parts Charge:	178.40	Labor Charge:	82.50	

Workorder: 739252

Problem: 001 KEY ISSUED OUT 05/30/07

Meter Reading: 0	Labor	Parts		
In Date: 05/30/2007	Hours	Description	Quantity	
- 001 Key Issued Out	0.20	DUPLICATE VEHICLE KEYS	1.00	
Parts Charge:	3.00	Labor Charge:	0.00	

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 740582		Problem: 002 KEYS ISSUED OUT		06/26/07	
Meter Reading: 0			Labor	Parts	
In Date: 06/26/2007	Close Date: 06/26/2007		Hours	Description	Quantity
- 002 Keys Issued Out	06/26/07		0.40	DUPLICATE VEHICLE KEYS	2.00
	Parts Charge: 6.00		Labor Charge: 0.00		

Workorder: 743940		Problem: NAIL IN R/R TIRE			
Meter Reading: 20034			Labor	Parts	
In Date: 09/11/2007	Close Date: 09/13/2007		Hours	Description	Quantity
- R&R R/R Tire			1.00	TIRE DISPOSAL FEE	1.00
- Shop Supplies				SHOP SUPPLIES	1.00
				744395900 245/75R16 245/75R16 WRANGLER HT	1.00
	Parts Charge: 153.60		Labor Charge: 55.00		

Workorder: 745338		Problem: P.M SERVICE,SEE NOTE			
Meter Reading: 21646			Labor	Parts	
In Date: 10/09/2007	Close Date: 10/17/2007		Hours	Description	Quantity
- Pm Service And Replace Missing Left Front Center Cop			7.75	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Replace Tailgate Handle Trim Bezel				3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Replace 2 Tires Mount,Balance, Nitrofill And Mount On Front				10W30 MOTOR OIL	6.00
				15067579 CENTER WHEEL CAP	1.00
- Rear Brake Job.Replace Rear Pads,Resurface Rotors.Service Calipers.Test Drive.				749845060 245/75R16 WRANGLER RT/S D	2.00
- Shop Supplies				SHOP SUPPLIES	1.00
				19120859 TAILGATE HANDLE BEZEL	1.00
				10020 INJECTOR CLEANER DON'T REORDER	1.00
				31-22 WIPER BLADES 22" WIPER BLADE	2.00
				TIRE DISPOSAL FEE	2.00
				PD792B REAR BRAKE PAD SET	1.00
	Parts Charge: 491.88		Labor Charge: 180.00		

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 833962

Problem: P.M SERVICE

Meter Reading: 27343		Labor	Parts	
In Date: 02/11/2008	Close Date: 02/19/2008	Hours	Description	Quantity
- Pm Service		7.25	BP193 EXTENSION BOLT TERMIMAL EXTENSION	2.00
- Test Charging System & Battery.Replace Battery.			GROUP 78 BATTERY (ACD 78PS)	1.00
- R&R Steering Intermediate Shaft And Lubricate To Stop			SHOP SUPPLIES	1.00
Steering Column Noise.			6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Front End Alignment.			3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Shop Supplies			10W30 MOTOR OIL	6.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
			10020 INJECTOR CLEANER DON'T REORDER	1.00
			31-22 WIPER BLADES 22" WIPER BLADE	2.00
Parts Charge: 166.20		Labor Charge: 150.00		

Workorder: 842964

Problem: P.M. SERVICE.CHECK ENGINE LIGHT ON.

Meter Reading: 31987		Labor	Parts	
In Date: 08/18/2008	Close Date: 08/25/2008	Hours	Description	Quantity
- Pm Service		17.75	85/140 GEAR OIL GEAR LUBE	3.00
- Ck Eng Lampon Scan Test.P0449 Evap Solenoid Ctl.Diag			ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	2.00
Circuitpower & Ground Ok.Solenoid Stuck.Repl Vent,Rmv			WATER PUMP	1.00
& Instl Fuel Tank To Access Lin			THERMOSTAT	1.00
- Flush & Refill Front Differential.Water Contamination.			L17040 INJECT CLEANER ONE PART (SMART BLEND)	1.00
Realign Vent Hoses.			TIRE DISPOSAL FEE	2.00
- Replace 2 Tires.High Speed Balance 4 Tires.Fill			749845060 245/75R16 WRANGLER RT/S D	2.00
W/Nitrogen			EVAP VENT SOLENOID	1.00
- Perform Induction Cleaning Service.Flush Injectors.Test Dr			L17301A ENGINE FOG KIT HARD CARBON (SMART BLEND)	1.00
- Pressure Test & Inspect Cooling Sys.Repl Water			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
Pump,Leaking.Replace Thermostat,Replace Belt.Flush			K040378HD A/C BELT	1.00
And Refill Coolant.			10W30 MOTOR OIL	6.00
- Fabricate And Install New Asset Numbers Front And			3481 FUEL FILTER FRM G3727 WIX 33481	1.00
Rear.			31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies			SHOP SUPPLIES	1.00
			K060923HD SERP BELT	1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
Parts Charge: 885.39		Labor Charge: 60.00		

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 936375

Problem: PM SERVICE.

Meter Reading: 33944		Labor		Parts	
In Date: 04/10/2009	Close Date: 04/17/2009	Hours	Description	Quantity	
- Pm Service		7.75	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
- Inspect & Replace Front And Rear Shocks To Correct Tire Cupping.			31-22 WIPER BLADES 22" WIPER BLADE	2.00	
- Service Rear Differential. Drain,Reseal & Refill Rear Diff.			10W30 MOTOR OIL	6.00	
- Service Transfer Case.Drain & Refill.			CENTER WHEEL CAP	1.00	
- Rotate & High Speed Balance All 4 Tires. Nitro Fill Tires.			FRONT SHOCK ABSORBOR	2.00	
- Shop Supplies			82194 GRAY SILICONE (PERMATEX)	1.00	
			REAR SHOCK ABSORBOR	2.00	
			SYN/ATF TRANS FLUID SYNTHETIC	2.00	
			09997 BRAKE CLEAN	1.00	
			12345841 GEAR OIL SYNTHETIC 75W-90	3.00	
			SHOP SUPPLIES	1.00	
			1066 WHITE LITHIUM (CRC 05037)	1.00	
Parts Charge: 464.29		Labor Charge: 465.00			

Workorder: 946259

Problem: P.M. Service.See note.

Meter Reading: 36175		Labor		Parts	
In Date: 11/20/2009	Close Date: 12/09/2009	Hours	Description	Quantity	
- P.M Service.		4.75	3481 FUEL FILTER FRM G3727 WIX 33481	1.00	
- Test Starting & Charging System, Charge & Test Battery, Replace Battery.			10W30 MOTOR OIL	6.00	
- Rotate & Balance All Four Tires.			GROUP 78 BATTERY (ACD 78PS)	1.00	
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
			1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
			SHOP SUPPLIES	1.00	
Parts Charge: 148.51		Labor Charge: 570.00			

Workorder: 1005949

Problem: Pm service.

Meter Reading: 37070		Labor		Parts	
In Date: 06/07/2010	Close Date: 06/09/2010	Hours	Description	Quantity	
- P.M. Service.		2.75	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
- Shop Supplies			10W30 MOTOR OIL	6.00	
			SHOP SUPPLIES	1.00	
			31-22 WIPER BLADES 22" WIPER BLADE	2.00	
Parts Charge: 31.79		Labor Charge: 165.00			

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 1013396

Problem: Slow crack ,weak battery.

Meter Reading: 37688		Labor		Parts	
In Date: 12/06/2010	Close Date: 12/14/2010	Hours	Description		Quantity
-	Perform Pm Service.	4.75	10W30 MOTOR OIL		6.00
-	Rotate And Balance All Four Tires.		6678 AIR FILTER FRM CA8755A WIX 46678		1.00
-	Recharge And Load Test Battery.Test Starting And		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
	Charging System.Unplug Auxiliary Charger From Lighter		1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
	Receptacle To Correct Draw.		22514722 O-RING SEAL FUEL FILTER (ACD 217-452)		2.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
Parts Charge:		52.44	Labor Charge:	285.00	

Workorder: 1107094

Problem: Pm service

Meter Reading: 38480		Labor		Parts	
In Date: 07/05/2011	Close Date: 07/19/2011	Hours	Description		Quantity
-	Perform Pm Service.	6.50	10W30 MOTOR OIL		6.00
-	Diagnose Gear Shifter Goes Into Drive With Out Key In		31-22 WIPER BLADES 22" WIPER BLADE		2.00
	Ignition.Remove Steering Colum And Replace Failed		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
	Shifter Interlock Assembly With New.		LINEAR SHIFT ASSEMBLY		1.00
-	Rotate And Balance All Four Tires.		09997 BRAKE CLEAN		1.00
-	Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		274.33	Labor Charge:	390.00	

Workorder: 1113204

Problem: No start

Meter Reading: 38796		Labor		Parts	
In Date: 12/15/2011	Close Date: 12/15/2011	Hours	Description		Quantity
-	Tow From: 8100 Forest Hill Blvd To: Lv Shop				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 104.15

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 1113212

Problem: Towed in for no crank.

Meter Reading: 38894		Labor		Parts	
In Date: 12/15/2011	Close Date: 12/27/2011	Hours	Description		Quantity
- Test Starting And Charging System.Battery Failed Load		1.00	GROUP 78 BATTERY (ACD 78PS)		1.00
Test After Recharge.Replace Failed Battery With New.			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		109.52	Labor Charge:	60.00	

Workorder: 1201623

Problem: Pm service.

Meter Reading: 39248		Labor		Parts	
In Date: 02/17/2012	Close Date: 02/29/2012	Hours	Description		Quantity
- P.M. Service.		3.75	SHOP SUPPLIES		1.00
- Rotate And Balance All Tires.			10W30 MOTOR OIL		6.00
- Shop Supplies			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
Parts Charge:		25.47	Labor Charge:	225.00	

Workorder: 1207702

Problem: Pm service and speedometer inop.

Meter Reading: 39684		Labor		Parts	
In Date: 08/15/2012	Close Date: 09/20/2012	Hours	Description		Quantity
- P.M. Service.		10.75	1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
- Diagnose Inop Speedometer.Replace And Reprogram			31-22 WIPER BLADES 22" WIPER BLADE		2.00
Instrument Cluster.			10W30 MOTOR OIL		6.00
- Resurface Rear Brake Rotors,Replace Rear Calipers And			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
Brake Pads,Lube Caliper Slides,Flush And Bleed System			09997 BRAKE CLEAN		1.00
And Test Drive.			1401 BRAKE FLUID BRAKE FLUID		1.00
- Rotate And Balance All Tires.			INSTRUMENT CLUSTER		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			REAR BRAKE CALIPER		1.00
			REAR BRAKE PAD SET		1.00
			REAR BRAKE HOSE WASHER		4.00
			REAR BRAKE CALIPER		1.00
Parts Charge:		879.74	Labor Charge:	645.00	

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 1207803		Problem: 2 - Wash ticket(s) issued			
Meter Reading: 39534		Labor		Parts	
In Date: 08/16/2012	Close Date: 08/16/2012	Hours	Description	Quantity	
- 2 - Wash Ticket(S) Issued					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 19.46
Workorder: 1208642		Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
Meter Reading: 39534		Labor		Parts	
In Date: 09/11/2012	Close Date: 09/11/2012	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 97.92
Workorder: 1307698		Problem: Transition Prep Charge			
Meter Reading: 41115		Labor		Parts	
In Date: 08/01/2013	Close Date: 08/01/2013	Hours	Description	Quantity	
- Transition Prep Charge					
Parts Charge:		0.00	Labor Charge:	0.00	
Workorder: 1307789		Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
Meter Reading: 41115		Labor		Parts	
In Date: 08/05/2013	Close Date: 08/05/2013	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 97.92
Workorder: 1401364		Problem: Keys locked inside			
Meter Reading: 45460		Labor		Parts	
In Date: 02/10/2014	Close Date: 02/11/2014	Hours	Description	Quantity	
- Tow From: Gua Yard					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 60.00

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 1407731

Problem: PM SERVICE

Meter Reading: 49216		Labor		Parts	
In Date: 08/05/2014	Close Date: 08/18/2014	Hours	Description		Quantity
- Pm Service.		9.25	NAPA WHEEL BEARING		1.00
- Replace Leaking Axle Seals And Bearings. Refilll Rear Diff.			NAPA OIL SEAL		1.00
			PWR STEERING FL-QUART		2.00
- Power Steering Service.			NAPAGOLD OIL FILTER		1.00
- Test Drive.			USED FIRE X REFURBISHED		1.00
			5068 PENTRATING OIL		1.00
			NAPA 10W30 QT		6.00
			WASHER FLUID CONCENTR		1.00
			WIPER BLADE		2.00
			GEAR OIL DRUM PAHOKEE		8.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 175.46		Labor Charge:	555.00		

Workorder: 1409160

Problem: Driveline noise.

Meter Reading: 49354		Labor		Parts	
In Date: 09/11/2014	Close Date: 09/11/2014	Hours	Description		Quantity
- Tow From: Mosquito Control To: Pa Shop					
Parts Charge: 0.00		Labor Charge:	0.00	Commercial Charge:	90.00

Workorder: 1410471

Problem: Rear brakes making noise.

Meter Reading: 49376		Labor		Parts	
In Date: 10/21/2014	Close Date: 10/24/2014	Hours	Description		Quantity
- Replace Damaged Caliper Bolts.		1.00	Caliper Housing Bolt - Rear		2.00
			Caliper Housing Bolt - Rear		2.00
Parts Charge: 32.82		Labor Charge:	60.00		

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 1501670

Problem: Pm service.

Meter Reading: 52255		Labor		Parts	
In Date: 02/17/2015	Close Date: 02/19/2015	Hours	Description		Quantity
-	Test Drive.	3.75	NAPAGOLD OIL FILTER		1.00
-	Rotate And Balance Tires.		WIPER BLADE		2.00
			NAPA 10W30 QT		6.00
Parts Charge:		34.59	Labor Charge:	225.00	

Workorder: 1503355

Problem: Wash

Meter Reading: 52255		Labor		Parts	
In Date: 03/31/2015	Close Date: 04/13/2015	Hours	Description		Quantity
-	Wash Truck. Clean Cab.	2.00			
Parts Charge:		0.00	Labor Charge:	120.00	

Workorder: 1507836

Problem: Pm service

Meter Reading: 54428		Labor		Parts	
In Date: 08/05/2015	Close Date: 08/11/2015	Hours	Description		Quantity
-	P/M Service.	8.50	NAPAGOLD OIL FILTER		1.00
-	Replace All Tires. Nitro Fill And Balance.		NAPA 10W30 QT		6.00
-	Replace Worn Front Brake Pads And Rotors.		WIPER BLADE		2.00
-	Battery Failed Load Test. Replace Battery.		179636492 LT245-75R17		4.00
-	Test Drive 2X'S.		NAPAGOLD FUEL FILTER		1.00
			TIRE DISPOSAL FEE		4.00
			LT245 75R16		4.00
			BATTERY		1.00
			DISC BRAKE PADS		1.00
			BRAKE ROTOR ONLY		2.00
Parts Charge:		1,195.84	Labor Charge:	510.00	

Workorder: 1511771

Problem: Locked keys in vehicle.

Meter Reading: 58242		Labor		Parts	
In Date: 11/18/2015	Close Date: 11/18/2015	Hours	Description		Quantity
-	Tow From: Pa To: Pa				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 60.00

1/3/2017
12:15:48PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139788 2003 GMC 1500 Pickup, 1/2 Ton, 4X4, Strb Sys, T-Box

Workorder: 1602476

Problem: Pm service.

Meter Reading: 59480		Labor		Parts	
In Date: 03/08/2016	Close Date: 03/10/2016	Hours	Description		Quantity
-	Pm Service	4.25	WASHER FLUID CONCENTR		1.00
-	Rotate And Balance Tires		NAPAGOLD AIR FILTER		1.00
-	Test Drive		NAPAGOLD OIL FILTER		1.00
			22" WIPER BLADE		2.00
			USED FIRE X REFURBISHED		1.00
			NAPA 10W30 QT		6.00
Parts Charge: 60.38		Labor Charge:	255.00		

Workorder: 1609752

Problem: Shakes really bad

Meter Reading: 64956		Labor		Parts	
In Date: 09/09/2016	Close Date: 09/19/2016	Hours	Description		Quantity
-	Tow From: 12500 40Th Street North, Royal Palm Beach To: Pahokee Shop				
Parts Charge: 0.00		Labor Charge:	0.00	Commercial Charge:	96.00

Workorder: 1609841

Problem: Front wheel hub

Meter Reading: 64985		Labor		Parts	
In Date: 09/21/2016	Close Date: 10/03/2016	Hours	Description		Quantity
-	Replace Front Wheel Hub Assy'S.	4.50	HUB		2.00
-	Test Drive.				
Parts Charge: 759.24		Labor Charge:	270.00		

Workorder: 1610204

Problem: Transition Prep Charge

Meter Reading: 64966		Labor		Parts	
In Date: 09/29/2016	Close Date: 09/29/2016	Hours	Description		Quantity
-	Transition Prep Charge	2.00			
Parts Charge: 0.00		Labor Charge:	0.00		

Total Parts Charges:	6,583.67	Total Labor Charges:	6,045.00	Total Comm. Charges:	758.59
----------------------	-----------------	----------------------	-----------------	----------------------	---------------