

**Palm Beach County Fleet Management
Asset Maintenance History**

10181492 2010 FORD E250 Van, Cargo, 3/4 Ton

Workorder: 1009714 **Meter:** 0 **In Date:** 09/03/2010 **Closed:** 09/03/2010
Problem: Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1103338 **Meter:** 918 **In Date:** 03/28/2011 **Closed:** 03/31/2011
Problem: P.M. Service.

- Perform pm service.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
Used Firex Refurbed Fire Extingshers	1.00

Hours 4.00 Labor: 240.00 Parts: 32.57 Total: 272.57
:

Workorder: 1111019 **Meter:** 1480 **In Date:** 10/17/2011 **Closed:** 10/27/2011
Problem: Pm service.

- P.m. Service.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
Wd40 Spray Lube Stock# 405540002	1.00
5w20 Engine Oil	6.00

Hours 4.00 Labor: 240.00 Parts: 25.89 Total: 265.89
:

Workorder: 1203387 **Meter:** 2161 **In Date:** 04/10/2012 **Closed:** 04/19/2012
Problem: P.M. service and request spare keys.

- P.m. Service.
- Rotate and balance all tires.
- Cut spare key per request.

Parts List	Qty
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
Used Firex Refurbed Fire Extingshers	1.00

Hours 5.50 Labor: 330.00 Parts: 34.14 Total: 364.14
:

Workorder: 1210815 **Meter:** 2970 **In Date:** 11/05/2012 **Closed:** 11/26/2012
Problem: P.M. service.

- P.m. Service.
- Test battery and charging system.charge and retest battery,fail load test.replace defective battery.
- Diagnose tire monitor light.replace failed left front sensor.rotate and balance all four tires.
- Shop Supplies

Parts List	Qty
5w20 Engine Oil	7.00
Ph2 Oil Filter Lbf Ph	1.00
31-20 Wiper Blades 20	2.00
Battery 65	1.00
Tpms12 Sensor Tire Pr	1.00
Shop Supplies	1.00

Hours 7.00 Labor: 420.00 Parts: 266.21 Total: 686.21
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1211279 **Meter:** 2796 **In Date:** 11/20/2012 **Closed:** 11/20/2012
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 1304643 **Meter:** 3919 **In Date:** 05/09/2013 **Closed:** 05/22/2013
Problem: Pm service.

- P.m. Service.
 - Rotate and balance all tires.
 - Shop Supplies

Parts List
 5w20 Engine Oil Qty 7.00
 Napagold Oil Filter 1.00
 Used Firex Refurbed F 1.00
 Shop Supplies 1.00

Hours 5.00 Labor: 300.00 Parts: 42.22 Total: 342.22
 :

Workorder: 1312290 **Meter:** 4757 **In Date:** 12/10/2013 **Closed:** 12/18/2013
Problem: Pm service and request for detail vehicle.

- Perform pm service.
 - Rotate and balance all four tires
 - Shop Supplies

Parts List
 5w20 Engine Oil Qty 7.00
 Napagold Oil Filter 1.00
 Wiper Blade 2.00
 Shop Supplies 1.00

Hours 5.00 Labor: 300.00 Parts: 32.38 Total: 332.38
 :

Workorder: 1312408 **Meter:** 4540 **In Date:** 12/12/2013 **Closed:** 12/12/2013
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 1500160 **Meter:** 6040 **In Date:** 01/06/2015 **Closed:** 01/23/2015
Problem: Pm service.

- Pm service.
 - Rotate and balance all four tires.
 - Shop Supplies

Parts List
 5w20 Engine Oil Qty 7.00
 Napagold Oil Filter 1.00
 Washer Fluid Concentr 1.00
 Used Fire X Refurbished 1.00
 Wd40 16oz 1.00
 Napagold Air Filter 1.00
 Shop Supplies 1.00

Hours 5.00 Labor: 300.00 Parts: 60.98 Total: 360.98
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1509085 **Meter:** 6972 **In Date:** 09/10/2015 **Closed:** 09/28/2015
Problem: Pm service.Detail.

- Pm service.	Parts List	Qty
- Battery failed loadtest after recharge.alternator output at specs.no draw.replace defective battery.	5w20 Engine Oil	7.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Bat Term Protector	1.00
	Battery	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 180.71
:		Total: 540.71

Workorder: 1509587 **Meter:** 6972 **In Date:** 09/22/2015 **Closed:** 09/22/2015
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1603666 **Meter:** 7985 **In Date:** 04/07/2016 **Closed:** 04/19/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty	
- Flush and refill transmission.	5w20 Engine Oil	7.00	
- Rotate and balance all tires.	Napagold Oil Filter	1.00	
- Shop Supplies	20" Wiper Blade	2.00	
	Used Fire X Refurbished	1.00	
	Bulb	1.00	
	Syn-atf Trans Fluid S	14.00	
	Shop Supplies	1.00	
Hours 6.50	Labor: 390.00	Parts: 101.90	Total: 491.90
:			

Workorder: 1612052 **Meter:** 8518 **In Date:** 11/22/2016 **Closed:** 11/30/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty	
- Rotate and balance tires.	Napagold Oil Filter	1.00	
- Shop Supplies	5w20 Engine Oil	6.00	
	20" Wiper Blade	2.00	
	Shop Supplies	1.00	
Hours 5.00	Labor: 300.00	Parts: 24.88	Total: 324.88
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1705053 **Meter:** 8801 **In Date:** 05/22/2017 **Closed:** 05/31/2017
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Cooling system flush and fill.pressure test and road test.	Napagold Oil Filter	1.00
- Rotate and balance four tires.nitro service.	5w20 Engine Oil	7.00
- Shop Supplies	20" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Peak Global Antifrz	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 60.01
:		Total: 480.01

Workorder: 1706485 **Meter:** 8801 **In Date:** 06/06/2017 **Closed:** 06/30/2017
Problem: Damage to all of right side, front bumper, left front fender & hood

- Damage to all of right side, front bumper, left front fender & hood	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1800596 **Meter:** 9325 **In Date:** 01/18/2018 **Closed:** 01/30/2018
Problem: P.M. service and right side door lock inop with key.

- P.m. service.	Parts List	Qty
- Check and replace right side cargo door inop.r&i new door latch assembly and clip and adjust linkage.	door latch remote control	1.00
- Rotate and high speed balance all four wheels.nitrofill all.	5w20 Engine Oil	7.00
- Shop Supplies	Napagold Oil Filter	1.00
	20" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Door Clip	1.00
	Shop Supplies	1.00
Hours 6.25	Labor: 375.00	Parts: 132.83
:		Total: 507.83

Workorder: 1809272 **Meter:** 11004 **In Date:** 09/10/2018 **Closed:** 09/18/2018
Problem: P.M. Service.Rear door will not open.

- P.m. service.	Parts List	Qty
- Diagnose rear door inop . R&r defective latch and cable assembly on right rear cargo door.	Napagold Oil Filter	1.00
- Rotate and balance all four tires. Nitrogen fill tires.	5w20 Engine Oil	6.00
- Shop Supplies	20" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Door Remote	1.00
	Shop Supplies	1.00
Hours 6.25	Labor: 375.00	Parts: 99.85
:		Total: 474.85