



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 942354      **Meter:** 12439      **In Date:** 08/20/2009      **Closed:** 08/25/2009  
**Problem:** P.M service, tire light on.

- P.m service.	<b>Parts List</b>	<b>Qty</b>
- Repair L/f tire, rotate & balance all four tires, reset tire light.	Shop Supplies	1.00
- Inspect & service winch, overhaul planetary gears.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 6.75	Labor: 405.00	Parts: 65.38
:		Total: 470.38

**Workorder:** 1001219      **Meter:** 17295      **In Date:** 02/02/2010      **Closed:** 02/02/2010  
**Problem:** L/R tire flat

- Repair L/r tire.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Workorder:** 1003089      **Meter:** 19531      **In Date:** 03/26/2010      **Closed:** 04/07/2010  
**Problem:** PM service also see notes on trailer plug outlet

- P.m service.	<b>Parts List</b>	<b>Qty</b>
- Machine front & rear brake rotors, install new pads front & rear, service all four caliper, bleed system & test drive.	Shop Supplies	1.00
- Inspect & test trailer connector, replace connector, rewire trailer harness & replace blown trailer fuses.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- R&r front drive shaft, replace torn slip joint boot, clean & lube spline joints & repair damaged heat shield.	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
- Inspect & service winch.	Mx1083 Brake Pads	1.00
- Shop Supplies	Mkd1012 Brake Pads	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	5404 Female Connector	1.00
	Boot Clamps / F85z4k227aa	1.00
	Boot Clamp / F85z4k227ba	1.00
	Shaft Boot / F85z4421aa	1.00
Hours 15.75	Labor: 945.00	Parts: 189.60
:		Total: 1,134.60

**Workorder:** 1006837      **Meter:** 22327      **In Date:** 06/29/2010      **Closed:** 06/30/2010  
**Problem:** Check noise in four wheel drive.

- Diagnose noise concern.fabricate and repair bent heat shields and bracket due to damage from road hazzard.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

**Workorder:** 1006858      **Meter:** 22267      **In Date:** 06/30/2010      **Closed:** 07/07/2010  
**Problem:** FLASH CANCEIVER--SPOT #221

- Reflash Canceiver	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1007838      **Meter:** 22950      **In Date:** 07/23/2010      **Closed:** 07/30/2010  
**Problem:** Check engine wrench light on and see notes on four wheel drive performance.

- Vehicle driven through deep water.set engine controls in limp mode and four wheel drive default.scan for codes,reset and road test.	<b>Parts List</b>	<b>Qty</b>
	Shop Supplies	1.00
- Shop Supplies		
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

**Workorder:** 1010654      **Meter:** 25582      **In Date:** 09/28/2010      **Closed:** 10/13/2010  
**Problem:** P.M. Service..L/S mirror broke.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Install new left side view mirror lens.	Shop Supplies	1.00
- Inspect and service power wick.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate and balance all four tires.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Shop Supplies	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	5w20 Engine Oil	7.00
	Drivers Side Mirror Glass	1.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 5.50	Labor: 330.00	Parts: 66.98
:		Total: 396.98

**Workorder:** 1101936      **Meter:** 29297      **In Date:** 02/17/2011      **Closed:** 03/09/2011  
**Problem:** Low pressure warning light for tires on.

- Install four new tires as per request.nitrogen fill and balance all four.	<b>Parts List</b>	<b>Qty</b>
	Shop Supplies	1.00
- Perform pm service.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Install new rear brake pads and two new rear brake rotors.service calipers.lube slides and perform brake fluid flush.	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	Mkd1012 Brake Pads	1.00
- Inspect and replace failed left front wheel bearings assembly with new.	09997 Brake Clean	1.00
	Rear Brake Rotors	2.00
- Perform wheel alignment complete.	1401 Brake Fluid Brake Fluid	1.00
- Inspect and service power winch.	5w20 Engine Oil	7.00
- Shop Supplies	Wd40 Spray Lube Stock# 405540002	1.00
	D3tz2457b Brake Pedal Pad	1.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	Front Hub Assy	1.00
	Tire Disposal Fee	4.00
	Wrangle Mt/r Tire	4.00
Hours 13.75	Labor: 825.00	Parts: 1,766.10
:		Total: 2,591.10

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1104332      **Meter:** 31049      **In Date:** 04/21/2011      **Closed:** 04/27/2011  
**Problem:** Dead battery.Check a/c and ail filters.

- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.	<b>Parts List</b>	<b>Qty</b>
	Shop Supplies	1.00
- Check and replace dirty air filter.	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
- A/c performance test.clean dirt and trash from radiator and condensor.check system charge.	Group 65 Battery (mtc Bxt-65-850)	1.00
- Shop Supplies		
Hours 3.25	Labor: 195.00	Parts: 137.03
:		Total: 332.03

**Workorder:** 1107235      **Meter:** 33704      **In Date:** 07/08/2011      **Closed:** 07/21/2011  
**Problem:** Problem with four wheel drive and heat shield close to gas tank.

- Drain and remove fiel tank.straighten baffle and straps.align. tank and replace damage heat shield with new.	<b>Parts List</b>	<b>Qty</b>
	Shop Supplies	1.00
- Computer diagnose four wheel drive concern.test and replace failed l.w.e.solnoid with new.clear codes and road test.	I W E Solenoid	1.00
	Tank Heat Shield	1.00
- Shop Supplies	Shield Fastners	4.00
Hours 6.00	Labor: 360.00	Parts: 179.98
:		Total: 539.98

**Workorder:** 1108663      **Meter:** 34491      **In Date:** 08/16/2011      **Closed:** 08/29/2011  
**Problem:** P.M. Service.A/C no very cold.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service transmission.flush and renew transmission fluid.	Shop Supplies	1.00
	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Inspect and service power winch.	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
- Ac performance and leak test.vacuum and recharge system to specs with virgin freon and oil.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Rotate and balance all four tires.	Syn/atf Trans Fluid Synthetic	14.00
- Shop Supplies	L0135-063 Lubriplate Chain&cable	1.00
	Lube,03050crc	
	5w20 Engine Oil	7.00
	R134a Refrigerant	1.00
Hours 7.50	Labor: 450.00	Parts: 115.16
:		Total: 565.16

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1202047      **Meter:** 38648      **In Date:** 02/29/2012      **Closed:** 03/19/2012  
**Problem:** P.M. service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Replace front calipers and front rotors.service and lube caliper slides.flush and bleed system and test drive.	Shop Supplies	1.00
- Inspect winch.dis-assemble winch and clean and lube binding gears and lock.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate and balance all tires.	Front Pads	1.00
- Shop Supplies	Front Rotors	2.00
	Front Caliper	1.00
	Front Caliper	1.00
	Wd40 Spray Lube Stock# 405540002	1.00
	1401 Brake Fluid Brake Fluid	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 10.25	Labor: 615.00	Parts: 583.06
:		Total: 1,198.06

**Workorder:** 1204076      **Meter:** 39201      **In Date:** 04/16/2012      **Closed:** 05/01/2012  
**Problem:** damage to frt bumper

- damage to frt bumper	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1207791      **Meter:** 41768      **In Date:** 08/16/2012      **Closed:** 08/30/2012  
**Problem:** Pm service.Replace left headlamp and broken over head storage lid.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Replace broken overhead compartment.	Shop Supplies	1.00	
- Replace left front headlight bulb..	1372 Oil Filter Frm Ph2 Wix 51372	1.00	
- Rotate and balance all tires.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00	
- Inspect and service winch.	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00	
- Shop Supplies	5w20 Engine Oil	7.00	
	Overhead Console	1.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	31-20 Wiper Blades 20" Blade	2.00	
	9008 Bulb	1.00	
Hours 6.00	Labor: 360.00	Parts: 462.26	Total: 822.26
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1302594      **Meter:** 47106      **In Date:** 03/15/2013      **Closed:** 03/21/2013  
**Problem:** P.M. service.

	<b>Parts List</b>	<b>Qty</b>
- P.m. Service.		
- Resurface rear brake rotors,replace rear brake pads.service and lube calipers,flush and bleed system and test drive.	5w20 Engine Oil	7.00
	1372 Oil Filter	1.00
- R&r driveshaft and replace torn slip yoke boot.	Ca8039 Air Filter Lbf	1.00
- Inspect and service winch.	Used Firex Refurbed F	1.00
- Rotate and balance all tires.	31-20 Wiper Blades 20	2.00
- Shop Supplies	Brake Pads	1.00
	Brake Cleaner	1.00
	1401 Brake Fluid Bra	1.00
	Ford Transfer Case Flui	2.00
	Clamp	1.00
	Boot	1.00
	Clamp	1.00
	Shop Supplies	1.00
Hours 10.25	Labor: 615.00	Parts: 195.01
:		Total: 810.01

**Workorder:** 1308461      **Meter:** 52825      **In Date:** 08/21/2013      **Closed:** 09/12/2013  
**Problem:** P.M. service.

	<b>Parts List</b>	<b>Qty</b>
- Perform pm service.		
- Remove front driveshaft and replace failed slip joint boot with new.	5w20 Engine Oil	7.00
	Napagold Oil Filter	1.00
- Install four new tires to wheels.nitrogen fill and balance all four.	Napagold Air Filter	1.00
	31-20 Wiper Blades 20	2.00
- Inspect and replace failed parking brake cable with new and adjust.	Napagold Fuel Filter	1.00
- Perform wheel alignment complete.	Lt265/70r17	4.00
- Inspect and service power winch.	Boot	1.00
- Shop Supplies	Clamp	1.00
	Clamp	2.00
	Cable Asy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 11.50	Labor: 690.00	Parts: 1,355.56
:		Total: 2,045.56

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1402075      **Meter:** 56387      **In Date:** 03/04/2014      **Closed:** 03/18/2014  
**Problem:** Pm service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Replace belt tensioner and serpentine belt.	5w20 Engine Oil	7.00
- Resurface rear brake rotors,replace rear brake pads.service and lube rear calipers.flush and bleed system.	Napagold Oil Filter	1.00
- Rotate and balance all tires.	Wiper Blade	2.00
- Inspect and service winch.	Mac Wite Lithium Gres	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Serpentine Belt	1.00
	Dr Blt Tensioner Assy	1.00
	brake pad	1.00
	Brake Cleaner	1.00
	2232 Brake Fluid Quar	2.00
	Shop Supplies	1.00
Hours 10.50	Labor: 630.00	Parts: 207.58
:		Total: 837.58

**Workorder:** 1405634      **Meter:** 58290      **In Date:** 06/06/2014      **Closed:** 06/17/2014  
**Problem:** replace hitch lock

- Cut off hitch lock and replace with new	<b>Parts List</b>	<b>Qty</b>
	Hitch Pin Lock	1.00
Hours 0.50	Labor: 30.00	Parts: 13.56
:		Total: 43.56

**Workorder:** 1405646      **Meter:** 58307      **In Date:** 06/09/2014      **Closed:** 06/10/2014  
**Problem:** Right rear tire going flat.

- Repair and balance right rear tire	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1410886      **Meter:** 61529      **In Date:** 10/30/2014      **Closed:** 12/15/2014

**Problem:** Pm service Check engine light on.Pulls to the left. AC not cold.

	<b>Parts List</b>	<b>Qty</b>
- Pm service.		
- Check battery and charging system.battery failed loadtest after recharge.replace defective battery.	Orifice Tube	1.00
- Computer diagnose for check engine light on.code P0401.pinpoint test and replace defective Egr valve..clear codes with scan tool and test drive.	5w20 Engine Oil	7.00
	Napagold Oil Filter	1.00
	Wiper Blade	2.00
- Replace front and rear brake pads ,front and rear brake rotors,front and rear brake calipers.bleed the brake system.test drive.	Napagold Fuel Filter	1.00
	Battery	1.00
	Egr Valve	1.00
- Ac performance and leak test.replace defective engine fan clutch.evacuate system.replace orifice/expansion valve.vacume and recharge system to specs.	Brake Rotor	2.00
	Brake Rotor	2.00
- Inspect and service winch.	Caliper w/ Hardware - Right Rear (eclips	1.00
- Complete front end alignment and test drive.	Caliper w/ Hardware - Left Rear (eclipse	1.00
- Rotate and balance all four tires.	Reman Brake Caliper	1.00
- Shop Supplies	Reman Brake Caliper	1.00
	Disc Brake Pads	1.00
	Disc Brake Pads	1.00
	B Fluid Dot 3-32oz	1.00
	Napagold Air Filter	1.00
	Caliper Washer	4.00
	Fan Clutch	1.00
	Repair Kit	1.00
	Adhesive	1.00
	R134a Lv Shop 1	1.00
	Shop Supplies	1.00

Hours 22.75  
:

Labor: 1,365.0      Parts: 1,412.80  
0

Total: 2,777.80

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1506547      **Meter:** 65681      **In Date:** 06/30/2015      **Closed:** 07/21/2015  
**Problem:** P.M. service.

<ul style="list-style-type: none"> <li>- Pm service.</li> <li>- Computer diagnose Abs light on.multiple codes.c1155 and C1296.road test with sscan tool no data..replace defective left front hub and speed sensor.clear codes with scan tool and road test.</li> <li>- Inspect and replace both defective front sway bar links.</li> <li>- Inspect front drive shaft for clunking noise.replace both defective universal joints and boot.</li> <li>- Inspect and service front winch.</li> <li>- Rotate and balance all four wheels.</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left" colspan="2"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>5w20 Engine Oil</td><td></td><td align="right">7.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Washer Fluid Concentr</td><td></td><td align="right">1.00</td></tr> <tr><td>Battery Cleaner</td><td></td><td align="right">1.00</td></tr> <tr><td>Sway Bar Link</td><td></td><td align="right">2.00</td></tr> <tr><td>Napagold Air Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Front Wheel Bearing Hub</td><td></td><td align="right">1.00</td></tr> <tr><td>Front Speed Sensor</td><td></td><td align="right">1.00</td></tr> <tr><td>Joint</td><td></td><td align="right">2.00</td></tr> <tr><td>Clamp</td><td></td><td align="right">1.00</td></tr> <tr><td>Clamp</td><td></td><td align="right">1.00</td></tr> <tr><td>Boot</td><td></td><td align="right">1.00</td></tr> <tr><td>Stg Wheel Cov - Ford</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	<b>Parts List</b>		<b>Qty</b>	5w20 Engine Oil		7.00	Napagold Oil Filter		1.00	Wiper Blade		2.00	Washer Fluid Concentr		1.00	Battery Cleaner		1.00	Sway Bar Link		2.00	Napagold Air Filter		1.00	Front Wheel Bearing Hub		1.00	Front Speed Sensor		1.00	Joint		2.00	Clamp		1.00	Clamp		1.00	Boot		1.00	Stg Wheel Cov - Ford		1.00	Shop Supplies		1.00	<p align="right">Hours 10.75      Labor: 645.00      Parts: 902.17      Total: 1,547.17</p>
<b>Parts List</b>		<b>Qty</b>																																																
5w20 Engine Oil		7.00																																																
Napagold Oil Filter		1.00																																																
Wiper Blade		2.00																																																
Washer Fluid Concentr		1.00																																																
Battery Cleaner		1.00																																																
Sway Bar Link		2.00																																																
Napagold Air Filter		1.00																																																
Front Wheel Bearing Hub		1.00																																																
Front Speed Sensor		1.00																																																
Joint		2.00																																																
Clamp		1.00																																																
Clamp		1.00																																																
Boot		1.00																																																
Stg Wheel Cov - Ford		1.00																																																
Shop Supplies		1.00																																																

**Workorder:** 1509988      **Meter:** 66861      **In Date:** 10/01/2015      **Closed:** 10/13/2015  
**Problem:** Noise when engage 4X4

<ul style="list-style-type: none"> <li>- Computer diagnose for engine misfire.p0303,p0316 and P0308.replace #3 and #8 defective ignition coils and all eight spark plugs.clear codes with scan tool and retest.</li> <li>- Perform air intake system cleaning and decarb.clean throttle body and flush injectors.</li> <li>- Diagnose for noise when in four wheel drive.reposition exhaust heat shields away from exhaust pipe and front drive shaft.</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left" colspan="2"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Ford Ignition Coil</td><td></td><td align="right">2.00</td></tr> <tr><td>Intake Cleaner Kit</td><td></td><td align="right">1.00</td></tr> <tr><td>Injector Cleaner</td><td></td><td align="right">1.00</td></tr> <tr><td>spark plug</td><td></td><td align="right">8.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	<b>Parts List</b>		<b>Qty</b>	Ford Ignition Coil		2.00	Intake Cleaner Kit		1.00	Injector Cleaner		1.00	spark plug		8.00	Shop Supplies		1.00	<p align="right">Hours 8.50      Labor: 510.00      Parts: 219.86      Total: 729.86</p>
<b>Parts List</b>		<b>Qty</b>																		
Ford Ignition Coil		2.00																		
Intake Cleaner Kit		1.00																		
Injector Cleaner		1.00																		
spark plug		8.00																		
Shop Supplies		1.00																		

**Workorder:** 1512400      **Meter:** 68212      **In Date:** 12/08/2015      **Closed:** 01/26/2016  
**Problem:** Check over front end and steering wheel off set.

<ul style="list-style-type: none"> <li>- Inspect front end and confirm cross member damage.send vehicle to body shop.</li> </ul>	<p align="right">Hours 0.50      Labor: 30.00      Parts: 0.00      Total: 30.00</p>
--	--

**Workorder:** 1600423      **Meter:** 68212      **In Date:** 12/15/2015      **Closed:** 01/13/2016  
**Problem:** frame bent at rgt control arm

<ul style="list-style-type: none"> <li>- frame bent at rgt control arm</li> </ul>	<p align="right">Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00</p>
---	--

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1602282      **Meter:** 69244      **In Date:** 03/03/2016      **Closed:** 03/14/2016  
**Problem:** Pm service.

<ul style="list-style-type: none"> <li>- Pm service.</li> <li>- Perform engine coolant flush and refill.</li> <li>- Perform rear differential service.</li> <li>- Check and replace defective trailer plug socket and third brake lamp bulb.also replace defective windshield washer pump.</li> <li>- Check and replace two defective front sway bar links.</li> <li>- Inspect and service winch.</li> <li>- Rotate and balance all four tires.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>Used Fire X Refurbished</li> <li>Napagold Fuel Filter</li> <li>20" Wiper Blade</li> <li>Peak Global</li> <li>75w140 Ford Axle Lube</li> <li>Friction Modifier</li> <li>Ptex Ultra Grey 3oz</li> <li>5404 Female Connector</li> <li>Bulb</li> <li>Pump Motor</li> <li>Sway Bar Link</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>7.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>2.00</li> <li>3.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> </ul>	
Hours 11.25	Labor: 675.00	Parts: 323.68	Total: 998.68

**Workorder:** 1608904      **Meter:** 71744      **In Date:** 08/25/2016      **Closed:** 09/12/2016  
**Problem:** P.M. Service.Left rear tire flat.

<ul style="list-style-type: none"> <li>- P.m. Service.</li> <li>- Replace left headlight bulb.r&amp;r instrument cluster and replace blown bulbs.</li> <li>- Replace one tire,rotate and balance all four.</li> <li>- Inspect and service winch.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>20" Wiper Blade</li> <li>Napagold Air Filter</li> <li>Used Fire X Refurbished</li> <li>Mac Wite Lithium Gres</li> <li>Macs Chain Cable Lube</li> <li>Halogen Capsule</li> <li>Lt265/70r17</li> <li>Bulb</li> <li>Shop Supplies</li> <li>Tire Disposal Fee</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>7.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 7.25	Labor: 435.00	Parts: 379.11	Total: 814.11

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1702968      **Meter:** 73363      **In Date:** 03/23/2017      **Closed:** 04/10/2017  
**Problem:** P.M. service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Test charging system.replace bad alternator.replace noisy idler pulley.	Alternado Assy	1.00
- Test and replace bad battery.	Pulley	1.00
- Replace inner and outer tie rods on both sides.	Tie Rod End	2.00
- Complete wheel alignment.test drive.	Rod	2.00
- Rotate and balance tires.	1 2 Ss Hose Clamp	1.00
- Inspect and service winch.	5w20 Engine Oil	7.00
- Shop Supplies	Napagold Oil Filter	1.00
	Napagold Fuel Filter	1.00
	Used Fire X Refurbished	1.00
	20" Wiper Blade	2.00
	Battery	1.00
	Shop Supplies	1.00
Hours 12.25	Labor: 735.00	Parts: 802.36
:		Total: 1,537.36

**Workorder:** 1704685      **Meter:** 73384      **In Date:** 03/29/2017      **Closed:** 05/10/2017  
**Problem:** : Damage to right side of cab, right side of bed front & rear, rear bumper & tail gate.

- : Damage to right side of cab, right side of bed front & rear, rear bumper & tail gate.	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1704695      **Meter:** 73533      **In Date:** 05/10/2017      **Closed:** 05/22/2017  
**Problem:** Weatherstrip hanging from right rear door and Check mirrors.

- Replace broken driver side door mirror also reinstall weatherstrip for right rear door and new plastic sill plate.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Mirror Assy	1.00
	Door Plate	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 176.38
:		Total: 296.38

**Workorder:** 1705823      **Meter:** 74006      **In Date:** 06/12/2017      **Closed:** 06/12/2017  
**Problem:** 38 - Wash ticket(s) issued

- 38 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1707952      **Meter:** 75966      **In Date:** 08/14/2017      **Closed:** 08/24/2017  
**Problem:** Power steering inop.

- Found power steering inop.diagnose found rack and pinion stiff will not turn and steering shaft seized.replace rack and pinion and steering shaft.test drive.ok.	<b>Parts List</b>	<b>Qty</b>
- Complete four wheel alignment.	Rck/pin	1.00
- Shop Supplies	Syn-atf Trans Fluid S	4.00
	Non-chlor Brake Clnr	1.00
	Shaft Assym	1.00
	Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 1,034.45
:		Total: 1,424.45

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1709719      **Meter:** 76750      **In Date:** 10/04/2017      **Closed:** 10/19/2017  
**Problem:** P.M. service and right door handle broken.

<ul style="list-style-type: none"> <li>- P.m. service.</li> <li>- Check and replace trailer plug connector and fabricate wire as needed.</li> <li>- Check and resurface rear brake rotors,replace rear pads and service calipers.bleed brake system.</li> <li>- Check and replace both front sway bar links.</li> <li>- Check and replace broken right rear outside door handle and straighten door skin .</li> <li>- Check and replace defective rear pinion seal and top off gear lube.</li> <li>- Inspect and service winch.</li> <li>- Balance and rotate all four tires.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Handle Asy</li> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>Used Fire X Refurbished</li> <li>20" Wiper Blade</li> <li>trailer plug</li> <li>Brake Pad</li> <li>Sway Bar Link</li> <li>Seal Asy</li> <li>Kit Spac</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>7.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 15.50 :	Labor: 930.00	Parts: 332.44	Total: 1,262.44

**Workorder:** 1804604      **Meter:** 79345      **In Date:** 05/02/2018      **Closed:** 05/14/2018  
**Problem:** P.M. service.

<ul style="list-style-type: none"> <li>- P.m. service.</li> <li>- Check starting and charging system .battery failed load test .replace defective battery.</li> <li>- Resurface both front brake rotors. Replace front calipers and brake pads .flush and bleed brake system .road test.</li> <li>- Replace missing tailgate protector.</li> <li>- Inspect and service winch.</li> <li>- Rotate and high speed balance all four tires.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>20" Wiper Blade</li> <li>Used Fire X Refurbished</li> <li>Battery</li> <li>Caliper w/ Hardware - Right Front (eclip</li> <li>Caliper w/ Hardware - Left Front (eclips</li> <li>Caliper Washer</li> <li>B Fluid Dot 3-32oz</li> <li>Non-chlor Brake Clnr</li> <li>Hub Cap</li> <li>Front Pads</li> <li>Moulding</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>7.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>4.00</li> <li>1.00</li> <li>2.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 10.25 :	Labor: 615.00	Parts: 582.73	Total: 1,197.73

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1811178      **Meter:** 81558      **In Date:** 10/30/2018      **Closed:** 11/08/2018  
**Problem:** P.M. service.

<ul style="list-style-type: none"> <li>- P.m. service.</li> <li>- Inspect and service winch . Diagnose winch will not winch in .replace defective solinoid . Will no free spool. Remove gear set to clean and grease ,due to water contamination. Retest.</li> <li>- Diagnose noise in engine . R&amp;r defective idler pullies and tensioner . Replace belt and retest.</li> <li>- Inspect for power steering leak . Replace leaking power steering return line. Top off fluid and bleed system .</li> <li>- Replace both front swaybar links .</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Napagold Oil Filter</li> <li>Napa Quart 5w20</li> <li>20" Wiper Blade</li> <li>Washer Fluid Concentr</li> <li>Mac Wite Lithium Gres</li> <li>Napagold Fuel Filter</li> <li>Repl Solenoid Term Up</li> <li>Serpentine Belt</li> <li>Dr Blt Tensioner Assy</li> <li>Idler Pulley</li> <li>Psf Qt</li> <li>Sway Bar Link</li> <li>Ret/hose</li> <li>Link Kit</li> <li>Nut</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>7.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>2.00</li> <li>2.00</li> <li>1.00</li> </ul>
Hours 10.25 :	Labor: 686.75      Parts: 594.06	Total: 1,280.81

**Workorder:** 1813019      **Meter:** 82342      **In Date:** 12/26/2018      **Closed:** 12/26/2018  
**Problem:** Transition Prep Charge

<ul style="list-style-type: none"> <li>- Transition Prep Charge</li> </ul>	Labor: 134.00      Parts: 0.00	Total: 134.00
Hours 2.00 :		