

**Palm Beach County Fleet Management
Asset Maintenance History**

10169453 2008 FORD F350 Pickup, 1 Ton, Crewcab, Topper

Workorder: 744715 **Meter:** 0 **In Date:** 09/27/2007 **Closed:** 09/27/2007
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 110.00 Parts: 0.00 Total: 110.00
:

Workorder: 746505 **Meter:** 830 **In Date:** 10/31/2007 **Closed:** 11/07/2007
Problem: TRAILER WIRING FAULT

- Repair Broken Wires In Tailer Plug.

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 838429 **Meter:** 3312 **In Date:** 05/13/2008 **Closed:** 05/15/2008
Problem: P.M SERVICE

- Pm Service

Parts List **Qty**

- Rotate And Check High Speed Balance All 4 Tires.

Shop Supplies 1.00

- Service Winch

Ca10262 Air Filter Mtc Fa1883 Wix 49883 1.00

- Shop Supplies

1372 Oil Filter Frm Ph2 Wix 51372 1.00

G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00

5w20 Engine Oil 7.00

31-20 Wiper Blades 20" Blade 2.00

Used Firex Refurbed Fire Extingshers 1.00

Hours 6.00 Labor: 360.00 Parts: 76.16 Total: 436.16
:

Workorder: 847389 **Meter:** 5490 **In Date:** 11/21/2008 **Closed:** 12/10/2008
Problem: P.M. SERVICE.CHECK TRAILER PLUG.L/R LIGHT BROKE.

- Pm Service

Parts List **Qty**

- Replace Broken Left Rear Tail Light Lens And Bulbs.

05074 Silicone Spray 1.00

- Diag & Test Trailer Fault Replace Corroded Trailer Connectortest Drive.

Shop Supplies 1.00

- Service Winch.inspect Cable And Winch Operation,lube Cable And Rollers.

1372 Oil Filter Frm Ph2 Wix 51372 1.00

G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00

5w20 Engine Oil 7.00

- Rotate & Hi Speed Balance All 4 Tires.nitro Fill Tires.

31-20 Wiper Blades 20" Blade 2.00

- Shop Supplies

4114k Bulb (acd) 1.00

Left Tail Light Lens 1.00

5404 Female Connector 1.00

Hours 8.30 Labor: 498.00 Parts: 128.12 Total: 626.12
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 847745 **Meter:** 5475 **In Date:** 12/04/2008 **Closed:** 12/09/2008
Problem: REPAIR TRAILER PLEG WIRING

- Replace Trailer Plug	Parts List	Qty
- Trailer Disconnect Light On Rewire Truck Plug For Proper Wiring Set Up.	Shop Supplies	1.00
- Test Drive For Proper Controller Operations	755-5046 Male Connector	1.00
- Shop Supplies		
Hours 3.00	Labor: 180.00	Parts: 8.83
:		Total: 188.83

Workorder: 848527 **Meter:** 5779 **In Date:** 12/23/2008 **Closed:** 12/24/2008
Problem: CUSTOMER REQUESTS SPOT MIRRORS

- Mount 2 Spot Mirrors.	Parts List	Qty
	7039d Spot Mirror Velvac 723060	2.00
Hours 0.50	Labor: 30.00	Parts: 3.81
:		Total: 33.81

Workorder: 942246 **Meter:** 10556 **In Date:** 08/18/2009 **Closed:** 08/27/2009
Problem: P.M service.

- P.m service.	Parts List	Qty
- Test & replace R/f strobe bulb.	Shop Supplies	1.00
- Inspect & service winch.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate & balance all four tires.	5w20 Engine Oil	7.00
- Shop Supplies	31-20 Wiper Blades 20" Blade	2.00
	S30hacp Strobe Bulb For Kit S660cccc	1.00
Hours 6.50	Labor: 390.00	Parts: 68.85
:		Total: 458.85

Workorder: 1004189 **Meter:** 15114 **In Date:** 04/23/2010 **Closed:** 04/27/2010
Problem: P.M service, check back up alarm.

- P.m service.	Parts List	Qty
- Fabricate & install back up alarm.	Shop Supplies	1.00
- Inspect & service winch.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	9-2951 Backup Alarm Ecco 575 Grote 73120	1.00
Hours 6.50	Labor: 390.00	Parts: 99.98
:		Total: 489.98

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1100164 **Meter:** 20495 **In Date:** 01/05/2011 **Closed:** 01/20/2011

Problem: Pm service.Also see notes on winch cable broken.

- Perform pm service.	Parts List	Qty
- Remove damage cable from winch, then fabricate fastener and install new cable with hook.inspect and service power winch.	Shop Supplies	1.00
- Test and replace failed dome lamp bulb with new.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate and balance all four tires.	5w20 Engine Oil	7.00
- Shop Supplies	31-20 Wiper Blades 20" Blade	2.00
Hours 8.00	Labor: 480.00	Parts: 27.31
:	Total: 507.31	

Workorder: 1101020 **Meter:** 20495 **In Date:** 01/27/2011 **Closed:** 01/27/2011

Problem: replace tail light bulb

- r/r Right Brake light	Parts List	Qty
Hours 0.50	4114k Bulb (acd)	1.00
:	Labor: 30.00	Parts: 2.94
	Total: 32.94	

Workorder: 1101076 **Meter:** 20495 **In Date:** 01/18/2011 **Closed:** 01/28/2011

Problem: damage to rgt rear fender

- damage to rgt rear fender		
Hours 0.00	Labor: 0.00	Parts: 0.00
:	Total: 0.00	

Workorder: 1109898 **Meter:** 25296 **In Date:** 09/16/2011 **Closed:** 09/22/2011

Problem: Pm service and battery problem.See notes.

- P.m. Service.	Parts List	Qty
- Recharge battery and load test,fail load test.replace defective battery.	Shop Supplies	1.00
- Inspect and service winch.	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
- Rotate and and balance all tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	5w20 Engine Oil	7.00
	7090blk Frt Floor Mats (rubber Queen)	1.00
	Used Firex Refurbed Fire Extingshers	1.00
	Group 65 Battery (mtc Bxt-65-850)	1.00
Hours 7.00	Labor: 420.00	Parts: 214.68
:	Total: 634.68	

Workorder: 1204510 **Meter:** 29711 **In Date:** 05/11/2012 **Closed:** 05/17/2012

Problem: P.M. service and spare on truck .

- P.m. Service.	Parts List	Qty
- Repair right front tire,rotate and balance all four.secure spare tire.	Shop Supplies	1.00
- Replace center brake light bulb.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Inspect and service winch.	5w20 Engine Oil	7.00
- Shop Supplies	31-20 Wiper Blades 20" Blade	2.00
Hours 7.50	Labor: 450.00	Parts: 32.06
:	Total: 482.06	

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1207085 **Meter:** 30848 **In Date:** 02/03/2012 **Closed:** 07/30/2012
Problem: service call

- Tire Service service - service call

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1300292 **Meter:** 34297 **In Date:** 01/08/2013 **Closed:** 01/24/2013
Problem: Pm service.Flat tire.Trailer plug receptacle and tailgate cap.

- Perform pm service.

Parts List

Qty

- Test and replace failed left brake lamp bulb and socket with new.	5w20 Engine Oil	7.00
	1372 Oil Filter	1.00
- Install four new tires.nitrogen fill and balance all four.	31-20 Wiper Blades 20	2.00
- Inspect and replace failed tail gate trim cap with new.	Ford Fuel Filter	1.00
- Fabricate and replace failed trailer plug receptacle with new.secure and insulate .	Ls94 Bulb Socket Driv	1.00
	Miniature Bulb	1.00
- Perform wheel alignment complete.	179535492 Lt265-70r17	4.00
- Shop Supplies	Socket	1.00
	Used Firex Refurbed F	1.00
	Moulding	1.00
	5404 Female Connector	1.00
	Electrical Tape	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00

Hours 10.75 Labor: 645.00 Parts: 1,211.40 Total: 1,856.40
:

Workorder: 1308811 **Meter:** 38987 **In Date:** 08/30/2013 **Closed:** 09/17/2013
Problem: Pm service.

- P.m. Service.

Parts List

Qty

- Repair center brake light circuit.fabricate new ground.	5w20 Engine Oil	7.00
- R&r front calipers and lube and service slides.	Napagold Oil Filter	1.00
- Inspect and service winch.	31-20 Wiper Blades 20	2.00
- Rotate and balance all four tires.	Brake Cleaner	1.00
- Shop Supplies	Shop Supplies	1.00

Hours 8.00 Labor: 480.00 Parts: 39.41 Total: 519.41
:

Workorder: 1403532 **Meter:** 42886 **In Date:** 04/10/2014 **Closed:** 04/21/2014
Problem: Pm service.

- Perform pm service

Parts List

Qty

- Inspect and service transmission.flush and renew transmission fluid.	5w20 Engine Oil	7.00
	Napagold Oil Filter	1.00
- Inspect and service power winch.	Napagold Fuel Filter	1.00
- Rotate and balance all four tires.	Napagold Air Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Syn-atf Trans Fluid S	16.00
	Shop Supplies	1.00

Hours 7.50 Labor: 450.00 Parts: 135.14 Total: 585.14
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1410943 **Meter:** 46789 **In Date:** 10/31/2014 **Closed:** 11/25/2014
Problem: Pm service.Wiper blades.Check power steering and winch pendant.

	Parts List	Qty
- Pm service.		
- Test and replace defective right seal beam headlamp.	5w20 Engine Oil	7.00
- Replace defective power steering pump and bleed system.	Napagold Oil Filter	1.00
- Replace front brake pads and resurface both front brake rotors.sertvice calipers.flush and bleed brake system.test drive.	Napagold Air Filter	1.00
	Wiper Blade	2.00
	Halogen Lamp	1.00
- Replace broken right side running board and damage weather strip for right rear door.	Ps Pump	1.00
- Inspect and service power winch.replace damage pendant.	Pads	1.00
- Rotate and balance all four tires.	B Fluid Dot 3-32oz	1.00
- Shop Supplies	Brake Cleaner	1.00
	Running Board Assy	1.00
	Weatherstrip	1.00
	Winch Remote Control	1.00
	Syn-atf Trans Fluid S	3.00
	Shop Supplies	1.00
Hours 14.80	Labor: 888.00	Parts: 1,027.46
:		Total: 1,915.46

Workorder: 1412171 **Meter:** 46789 **In Date:** 11/17/2014 **Closed:** 12/04/2014
Problem: damage to rgt frt fender & door

- damage to rgt frt fender & door			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1506545 **Meter:** 51215 **In Date:** 06/30/2015 **Closed:** 07/15/2015
Problem: Pm service and wiper blades.

	Parts List	Qty
- Pm service.		
- Test battery and charging system.replace defective battery.	5w20 Engine Oil	7.00
- Pressure test and inspect cooling system.flush and replace antifreeze.	Napagold Oil Filter	1.00
	Napagold Fuel Filter	1.00
- Perform transfer case service.	Wiper Blade	2.00
- Replace both defective front body mounts.	Bigg Degreaser	1.00
- Replace left head lamp seal beam.test and replace defective left front strobe lamp bulb.	Used Fire X Refurbished	1.00
	Battery	1.00
- Rotate and balance all four tires.	Peak Global	2.00
- Inspect and service winch.	Ford Transfer Case Fluid	2.00
- Shop Supplies	Body Mount Kit	2.00
	Halogen Lamp	1.00
	Hide Away Strob	1.00
	Shop Supplies	1.00
Hours 13.00	Labor: 780.00	Parts: 443.20
:		Total: 1,223.20

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1602474 **Meter:** 55292 **In Date:** 03/08/2016 **Closed:** 03/23/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace both defective front and rear bump stops.	5w20 Engine Oil	7.00
- Front differential service.	Napagold Oil Filter	1.00
- Rear differential service.	Napagold Air Filter	1.00
- Rotate and balance all four tires.	Macs Battery Cleaner	1.00
- Inspect and service winch.	20" Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	75w140 Ford Axle Lube	3.00
	75w140 Ford Axle Lube	3.00
	Friction Modifier	2.00
	Ptex Ultra Grey 3oz	2.00
	Wd40 Spray Lube Stock	1.00
	bumper	2.00
	Bumper	2.00
	Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 345.32
:		Total: 885.32

Workorder: 1700740 **Meter:** 59975 **In Date:** 01/25/2017 **Closed:** 02/13/2017
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace and balance four new tires.	Napagold Air Filter	1.00
- Inspect and service winch.	5w20 Engine Oil	7.00
- Complete wheel alignment.test drive.	Napagold Oil Filter	1.00
- Shop Supplies	20" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Napagold Fuel Filter	1.00
	Tr416 Valve Stem	4.00
	179535492 Lt265-70r17	4.00
	Lt265/70r17 Gdy Silent Armor	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 9.50	Labor: 570.00	Parts: 2,279.55
:		Total: 2,849.55

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1710683 **Meter:** 64126 **In Date:** 10/30/2017 **Closed:** 11/16/2017
Problem: P.M. Service.Winch cable broke.Trailer plug inop.

- P.m. service.	Parts List	Qty
- Check battery and charging system.battery failed load test after fully charged.replace defective battery.	5w20 Engine Oil	7.00
- Check and replace defective trailer plug and fabricate wires as needed.	Napagold Oil Filter	1.00
- Check and replace all six camper door shocks.	Used Fire X Refurbished	1.00
- Check and replace both headlamps with sealed beams and left front strobe light bulb.	20" Wiper Blade	2.00
- Check and replace defective blower motor resistor.	Battery	1.00
- Balance and rotate all four tires.	trailer plug	1.00
- Shop Supplies	Lift-support	2.00
	Support	4.00
	Halogen Lamp	2.00
	Hide Away Strob	1.00
	Blower Resistor	1.00
	Lift Support Univ	4.00
	Shop Supplies	1.00
Hours 10.95	Labor: 657.00	Parts: 594.83
:		Total: 1,251.83

Workorder: 1807267 **Meter:** 67011 **In Date:** 07/17/2018 **Closed:** 07/25/2018
Problem: P.M. Service.Check noise in rear of vehicle.

- P.m. service.	Parts List	Qty
- Test and replace back up alarm and relocate due to water intrusion .	5w20 Engine Oil	7.00
- Resurface rear rotors . Replace rear calipers and pads .bleed and flush brake system .test drive.	Napagold Oil Filter	1.00
- Drive for noise . Replace both rear shocks . Retest.	Used Fire X Refurbished	1.00
- Rotate and balance all four tires . Nitrofill .	Washer Fluid Concentr	1.00
- Inspect and service winch .	20" Wiper Blade	2.00
- Shop Supplies	Napagold Air Filter	1.00
	Alarm	1.00
	Brake Pad	1.00
	B Fluid Dot 3-32oz	2.00
	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	Gas Grande Fleet Shoc	2.00
	Rear Shocks	2.00
	Shop Supplies	1.00
Hours 13.00	Labor: 780.00	Parts: 557.74
:		Total: 1,337.74

Workorder: 1812846 **Meter:** 69093 **In Date:** 12/18/2018 **Closed:** 12/18/2018
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 134.00	Parts: 0.00
:		Total: 134.00