

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 638629                      **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 05/04/2006	Hours	Description
Close Date: 05/04/2006		Quantity
- Pre-Delivery Inspection	<b>2.00</b>	
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 100.00	

**Workorder:** 638702                      **Problem:** 001 DETAIL VEHICLE      05/04/06

Meter Reading: 0	Labor	Parts
In Date: 05/04/2006	Hours	Description
Close Date: 05/09/2006		Quantity
- 001 Detail Vehicle      05/04/06		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 7.14

**Workorder:** 644019                      **Problem:** 003 WASH TICKETS ISSUED OUT      08/14/06

Meter Reading: 0	Labor	Parts
In Date: 08/14/2006	Hours	Description
Close Date: 08/14/2006		Quantity
- 003 Wash Tickets Issued Out      08/14/06		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 21.60

**Workorder:** 644709                      **Problem:** P.M SERVICE

Meter Reading: 5114	Labor	Parts
In Date: 08/28/2006	Hours	Description
Close Date: 09/06/2006		Quantity
- Pm Service	<b>2.00</b>	10W30 MOTOR OIL      6.00
- Shop Supplies		SHOP SUPPLIES      1.00
		PH3387A OIL FILTER LBF PH47 WIX 51040      1.00
		10020 INJECTOR CLEANER DON'T REORDER      1.00
		6678 AIR FILTER FRM CA8755A WIX 46678      1.00
<b>Parts Charge:</b> 34.83	<b>Labor Charge:</b> 100.00	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 648990                      **Problem:** ORDER BED LINER CAP FOR RIGHT SIDE RAIL OF BED

<b>Meter Reading:</b> 10821		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 11/21/2006	<b>Close Date:</b> 12/20/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Install Bed Liner Rails (Clean And Prep)	2.00	SHOP SUPPLIES		1.00
-	Shop Supplies		BED/RAILS 40151		1.00
<b>Parts Charge:</b> 105.50		<b>Labor Charge:</b> 110.00			

**Workorder:** 649765                      **Problem:** P.M. SERVICE.DETAIL.

<b>Meter Reading:</b> 10821		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/11/2006	<b>Close Date:</b> 12/15/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pm Service	3.00	6678 AIR FILTER FRM CA8755A WIX 46678		1.00
-	Nitrogen Fill All Tires.		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Shop Supplies		10W30 MOTOR OIL		5.00
			PH3387A OIL FILTER LBF PH47 WIX 51040		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 36.92		<b>Labor Charge:</b> 55.00			

**Workorder:** 650086                      **Problem:** 001 DETAIL VEHICLE                      12/18/06

<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/18/2006	<b>Close Date:</b> 12/18/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	001 Detail Vehicle                      12/18/06				
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00		<b>Commercial Charge:</b> 84.00	

**Workorder:** 734405                      **Problem:** 002 WASH TICKETS ISSUED OUT 02/16/07

<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/16/2007	<b>Close Date:</b> 02/16/2007	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	002 Wash Tickets Issued Out 02/16/07				
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00		<b>Commercial Charge:</b> 14.28	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 734600                      **Problem:** CHECK LIGHTS

**Meter Reading:** 15433                      **Labor**

**In Date:** 02/22/2007                      **Hours**                      **Parts**

In Date: 02/22/2007	Close Date: 02/23/2007	Hours	Description	Quantity
- Check All Lights & Replace L/R Brake Light Bulb.		0.50	3157 TAIL LIGHT BULBS	1.00
	<b>Parts Charge:</b> 0.79	<b>Labor Charge:</b>	27.50	

**Workorder:** 735018                      **Problem:** P.M SERVICE,DETAIL

**Meter Reading:** 16044                      **Labor**

**In Date:** 03/01/2007                      **Hours**                      **Parts**

In Date: 03/01/2007	Close Date: 03/07/2007	Hours	Description	Quantity
- Pm Service Complete		6.50	PH3387A OIL FILTER LBF PH47 WIX 51040	1.00
- Clean And Adjust Rear Brake Shoes & Lube All Adjusters.			SHOP SUPPLIES	1.00
			10W30 MOTOR OIL	6.00
- High Speed Balance All Tires To Correct Steering Wheel Vibration Over 45 Mph			6678 AIR FILTER FRM CA8755A WIX 46678	1.00
			09997 BRAKE CLEAN	1.00
- Wheel Alignment Complete To Correct Right Pulling Condition On Level Road Way And Center Steering Wheel.			31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies				
	<b>Parts Charge:</b> 47.53	<b>Labor Charge:</b>	137.50	

**Workorder:** 735330                      **Problem:** 001 DETAIL VEHICLE                      03/07/07

**Meter Reading:** 0                      **Labor**

**In Date:** 03/07/2007                      **Hours**                      **Parts**

In Date: 03/07/2007	Close Date: 03/07/2007	Hours	Description	Quantity
- 001 Detail Vehicle	03/07/07			
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 84.00

**Workorder:** 736285                      **Problem:** P.M SERVICE,PULLS RIGHT VOID VOID VOID

**Meter Reading:** 18300                      **Labor**

**In Date:** 03/27/2007                      **Hours**                      **Parts**

In Date: 03/27/2007	Close Date: 03/28/2007	Hours	Description	Quantity
-				
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b>	0.00	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 739165

**Problem:** P.M SERVICE,SEE NOTE,DETAIL

Meter Reading: 22080	Labor	Parts		
In Date: 05/29/2007	Hours	Description	Close Date: 05/31/2007	Quantity
- Pm Service	<b>9.60</b>	PH3387A OIL FILTER LBF PH47 WIX 51040		1.00
- Replace Serpentine Belt		L0152-063 GEAR SHIELD		1.00
- Mount,Balance And Nitrofill 4 New Tires		10020 INJECTOR CLEANER DON'T REORDER		1.00
- Transmission Flush		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Rear Brake Service		758508188 245/70R17 WRG SILENT ARMOR 108T		4.00
- Inspect Alignment And Correct After Tire Replacement		31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Shop Supplies		SYN/ATF TRANS FLUID SYNTHETIC		10.00
		SHOP SUPPLIES		1.00
		K060960 SERP BELT		1.00
		10W30 MOTOR OIL		5.00
		6678 AIR FILTER FRM CA8755A WIX 46678		1.00
		TIRE DISPOSAL FEE		4.00
	<b>Parts Charge:</b>	821.65	<b>Labor Charge:</b>	137.50

**Workorder:** 739360

**Problem:** 001 DETAIL VEHICLE 05/31/07

Meter Reading: 0	Labor	Parts		
In Date: 05/31/2007	Hours	Description	Close Date: 05/31/2007	Quantity
- 001 Detail Vehicle		05/31/07		
	<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
			<b>Commercial Charge:</b>	84.00

**Workorder:** 739872

**Problem:** L/R TIRE FLAT

Meter Reading: 22857	Labor	Parts		
In Date: 06/11/2007	Hours	Description	Close Date: 06/13/2007	Quantity
- Repair Lr Tire	<b>1.00</b>	SHOP SUPPLIES		1.00
- Shop Supplies				
	<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	55.00

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

<b>Workorder:</b> 741117		<b>Problem:</b> 002 WASH TICKETS ISSUED OUT 07/09/07			
<b>Meter Reading:</b> 0		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 07/09/2007	<b>Close Date:</b> 07/09/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- 002 Wash Tickets Issued Out 07/09/07					
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 16.68		
<b>Workorder:</b> 743589		<b>Problem:</b> P.M SERVICE			
<b>Meter Reading:</b> 28797		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 09/05/2007	<b>Close Date:</b> 09/10/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Performed Complete Pm Service.Also Replaced Wiper Blades,Fuel Additive, Rotated Tires.					
		<b>4.00</b>	10W30 MOTOR OIL		5.00
- Inspected Brakes & Performed Rear Brake Clean & Adjust.					
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Performed Hi Speed Balance On All 4 Tires.					
			SHOP SUPPLIES		1.00
- Shop Supplies					
			PH3387A OIL FILTER LBF PH47 WIX 51040		1.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
	<b>Parts Charge:</b> 32.56	<b>Labor Charge:</b> 55.00			
<b>Workorder:</b> 746127		<b>Problem:</b> INSTALL COMPUTER STAND.			
<b>Meter Reading:</b> 32227		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 10/24/2007	<b>Close Date:</b> 11/02/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Fabricate And Install Customer Computer Stand.					
		<b>1.50</b>	SHOP SUPPLIES		1.00
- Shop Supplies					
	<b>Parts Charge:</b> 2.00	<b>Labor Charge:</b> 90.00			
<b>Workorder:</b> 746683		<b>Problem:</b> 002 WASH TICKETS ISSUED OUT 11/01/07			
<b>Meter Reading:</b> 0		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 11/01/2007	<b>Close Date:</b> 11/02/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- 002 Wash Tickets Issued Out 11/01/07					
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 16.68		

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 747685

**Problem:** P.M SERVICE,SEE NOTE

Meter Reading: 34347	Labor	Parts	
In Date: 11/26/2007	Hours	Description	Quantity
- Pm Service	6.00	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Tire Repair.Repair Frt Passenger Side Tire.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Clen And Readjust Rear Shoes And Drums		PH3387A OIL FILTER LBF PH47 WIX 51040	1.00
- High Speed Balance All Four Tires		10W30 MOTOR OIL	6.00
- New Door Panel Reflector Mounted And Cleaned Door Panels.Fixed Loose Bed Rail On Both Right And Left Sides		SHOP SUPPLIES	1.00
- Shop Supplies		10020 INJECTOR CLEANER DON'T REORDER	1.00
<b>Parts Charge:</b> 43.69		<b>Labor Charge:</b> 60.00	

**Workorder:** 834941

**Problem:** P.M SERVICE,SEE NOTE

Meter Reading: 40929	Labor	Parts	
In Date: 03/04/2008	Hours	Description	Quantity
- Pm Service	6.50	09997 BRAKE CLEAN	1.00
- Pressure Test And Inspect Cooling Sys. Flush And Refill Sys.		SHOP SUPPLIES	1.00
- Service Rear Differential		10W30 MOTOR OIL	5.00
- Rotate And Hi Speed Balance All 4 Tires,Nitrofill Tires		PH3387A OIL FILTER LBF PH47 WIX 51040	1.00
- Ck Windshield Washer Sys.Flushed Out Clogged Washer Nozzles		10020 INJECTOR CLEANER DON'T REORDER	1.00
- Shop Supplies		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		PRF116 COOLANT FLUSH	1.00
		765-1589 BLACK SILICONE	1.00
		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	2.00
		12345841 GEAR OIL SYNTHETIC 75W-90	3.00
<b>Parts Charge:</b> 156.52		<b>Labor Charge:</b> 30.00	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 836930

**Problem:** REPAIR FLAT TIRE

Meter Reading: 43401	Labor	Parts	Quantity
In Date: 04/14/2008	Hours	Description	Quantity
- Repair Tire	1.50	SHOP SUPPLIES	1.00
- Balance Tire			
- Nitrogen Service			
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 30.00	

**Workorder:** 838702

**Problem:** P.M. SERVICE.

Meter Reading: 45847	Labor	Parts	Quantity
In Date: 05/19/2008	Hours	Description	Quantity
- Pm Service	12.50	SHOP SUPPLIES	1.00
- Repl Transmission Filter.Flush And Refill All Fluid.		10W30 MOTOR OIL	5.00
- Replace Distributor Cap And Rotor.Corroded.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Replace Both Inner Tie Rods.Loose		D328A DIST CAP (ACD)	1.00
- Perform Complete Wheel Alignment.Test Drive.		PH3387A OIL FILTER LBF PH47 WIX 51040	1.00
- Service Rear Brakes.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Rotate & High Speed Balance 4 Tires.Refill W/Nitrogen.		D465 IGNITION ROTOR (ACD)	1.00
- Shop Supplies		SYN/ATF TRANS FLUID SYNTHETIC	16.00
		FT1217 TRANS FILTER ATP B-165 WIX DON'T USE	1.00
		INNER TIE ROD END	2.00
<b>Parts Charge:</b> 259.08		<b>Labor Charge:</b> 60.00	

**Workorder:** 838950

**Problem:** REPAIR FLATIRE

Meter Reading: 46132	Labor	Parts	Quantity
In Date: 05/27/2008	Hours	Description	Quantity
- Repair Flat Tire On L/F Rebalance And Fill With Nitrogen	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 841117

**Problem:** INSTALL INVERTER.

Meter Reading: 48918	Labor	Parts		
In Date: 07/09/2008	Hours	Description	Quantity	
- Fabricate And Installed Power Inverter And Power Harness.	4.00	BP193 EXTENSION BOLT TERMIMAL EXTENSION	1.00	
		CS2L BLACK CABLE 2 GAUGE	3.00	
- Shop Supplies		CS2RV RED CABLE 2 GAUGE	15.00	
		CPI 1575 INVERTER 1500 WATT (COBRA)	1.00	
		82-2178 CIRCUIT BREAKER 100AMP	1.00	
		SHOP SUPPLIES	1.00	
		8-403 TERMINAL INVERTER 2 GAUGE	2.00	
<b>Parts Charge:</b>	298.89	<b>Labor Charge:</b>	240.00	

**Workorder:** 842133

**Problem:** 001 WASH TICKET ISSUED OUT 07/24/08

Meter Reading: 0	Labor	Parts		
In Date: 07/24/2008	Hours	Description	Quantity	
- 001 Wash Ticket Issued Out 07/24/08				
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 8.34

**Workorder:** 842978

**Problem:** FLATIRE R.R.

Meter Reading: 50938	Labor	Parts		
In Date: 08/19/2008	Hours	Description	Quantity	
- Inspectflat Tire /Cords Broken,Do Not Have This Size Tire Instock,Put Spare Tire On	0.70			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	42.00	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 843005

**Problem:** P.M SERVICE,FLAT TIRE

<b>Meter Reading: 50979</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/20/2008	<b>Close Date:</b> 08/25/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>5.00</b>	SHOP SUPPLIES		1.00
- Replace 1 Tire,Cord Damaged.High Speed Balance 4 Tires.Fill W/Nitrogen.Reinstall Spare.			PH3387A OIL FILTER LBF PH47 WIX 51040		1.00
			758508188 245/70R17 WRG SILENT ARMOR 108T		1.00
- Service Rear Brakes.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Shop Supplies			TIRE DISPOSAL FEE		1.00
			10W30 MOTOR OIL		5.00
<b>Parts Charge:</b> 205.44		<b>Labor Charge:</b> 60.00			

**Workorder:** 846698

**Problem:** PM SERVICE.

<b>Meter Reading: 56477</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 11/04/2008	<b>Close Date:</b> 11/07/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>5.00</b>	31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Noise In Steering When Turning.Diag/Locate Noise Coming Fr Steering Shaft.Inspect/Lubricate Middle Steering Shaft.Test Drive. Ok			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			PH3387A OIL FILTER LBF PH47 WIX 51040		1.00
- Service Rear Brakes.Clean,Inspect And Adjust.			SHOP SUPPLIES		1.00
- Rotate & High Speed Balance All Four Tires.Nitro Fill Tires To Spec.			10W30 MOTOR OIL		5.00
- Shop Supplies					
<b>Parts Charge:</b> 50.91		<b>Labor Charge:</b> 60.00			

**Workorder:** 847089

**Problem:** 002 WASH TICKETS ISSUED OUT 11/12/08

<b>Meter Reading: 0</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 11/12/2008	<b>Close Date:</b> 11/14/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- 002 Wash Tickets Issued Out 11/12/08					
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 16.68		

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 933900

**Problem:** P.M SERVICE

Meter Reading: 62515		Labor		Parts	
In Date: 02/11/2009	Close Date: 02/20/2009	Hours	Description		Quantity
- Pm Service		4.00	10W30 MOTOR OIL		5.00
- Service Rear Brkes.			SHOP SUPPLIES		1.00
- Rotate & Hi Speed Balance 4 Tires,Nitrofill Tires.			PH3387A OIL FILTER LBF PH47 WIX 51040		1.00
- Shop Supplies			09997 BRAKE CLEAN		1.00
<b>Parts Charge:</b>		21.47	<b>Labor Charge:</b>	240.00	

**Workorder:** 937933

**Problem:** P.M. SERVICE.

Meter Reading: 67778		Labor		Parts	
In Date: 05/19/2009	Close Date: 05/21/2009	Hours	Description		Quantity
- Pm Service		7.50	10W30 MOTOR OIL		5.00
- Ck Battery And Charging Sys. R&R Defective Battery.			GROUP 78 BATTERY (ACD 78PS)		1.00
- Service Trans, Flush And Refill			K060960 SERP BELT		1.00
- Replace Cracked Belt And Worn Tension.Pulley Assy.			PH3387A OIL FILTER LBF PH47 WIX 51040		1.00
- Mount & Balance 1 Tire Mount On Right Rear Due To Slice In Side Wall.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Service Rear Brakes. Clean,Inspect And Adjust Rear Brakes.			1066 WHITE LITHIUM (CRC 05037)		1.00
- Shop Supplies			49203 BELT TENSIONER (GOODYEAR)		1.00
			758508188 245/70R17 WRG SILENT ARMOR 108T		1.00
			SHOP SUPPLIES		1.00
			SYN/ATF TRANS FLUID SYNTHETIC		12.00
			TIRE DISPOSAL FEE		1.00
<b>Parts Charge:</b>		445.88	<b>Labor Charge:</b>	450.00	

**Workorder:** 941049

**Problem:** Repair flat left rear tire

Meter Reading: 71381		Labor		Parts	
In Date: 07/21/2009	Close Date: 07/21/2009	Hours	Description		Quantity
- Repair Tire		1.60	SHOP SUPPLIES		1.00
- Balance Tire					
- Nitrogen Fill Tire					
- Shop Supplies					
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>	96.00	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 941084

**Problem:** Flat tire, broken stud

<b>Meter Reading:</b> 71426		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/22/2009	<b>Close Date:</b> 07/27/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Mount, Balance & Nitro Fill One New Tire On R/R,	1.50	758508188 245/70R17 WRG SILENT ARMOR 108T		1.00
	Replace Broken Lug & Stud On R/R Hub.		TIRE DISPOSAL FEE		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		178.76	<b>Labor Charge:</b>		90.00

**Workorder:** 942339

**Problem:** P.M service,check engine light on

<b>Meter Reading:</b> 73203		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/20/2009	<b>Close Date:</b> 08/31/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P.M Service.	9.10	ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)		1.00
-	Perform Computer Diagnostics For Check Engine Light		WATER PUMP 252-711		1.00
	On, Perform Evap Test, Replace Gas Cap & Rerun Test,		GAS CAP GT289		1.00
	Clear Codes.		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Pressure Test & Inspect Cooling System. Replace		PH3387A OIL FILTER LBF PH47 WIX 51040		1.00
	Leaking Water Pump, Install New Thermostate, Flush &		131-151 THERMOSTAT (ACD)		1.00
	Renew Coolant.		SHOP SUPPLIES		1.00
-	Rotate & Balance All Four Tires.		10W30 MOTOR OIL		5.00
-	Service Rear Drum Brakes.				
-	Shop Supplies				
<b>Parts Charge:</b>		163.26	<b>Labor Charge:</b>		546.00

**Workorder:** 943876

**Problem:** Transition Prep Charge

<b>Meter Reading:</b> 74237		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/29/2009	<b>Close Date:</b> 09/29/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Transition Prep Charge	2.00			
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>		120.00

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 1006892

**Problem:** pm service .

<b>Meter Reading:</b> 74465		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/01/2010	<b>Close Date:</b> 07/08/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pm Service .	<b>4.50</b>	10W30 MOTOR OIL		5.00
-	Replace Rear Tires & Ballance .		1036 OIL FILTER FRM PH3980 WIX 51036		1.00
-	Test Drive .		AIR FRESHENER		1.00
-	Detail Inside Of Cab .		31-22 WIPER BLADES 22" WIPER BLADE		2.00
			TIRE DISPOSAL FEE		2.00
			183114470 P245/70R17 WRANGLER SR-A 108S		2.00
<b>Parts Charge:</b> 375.46		<b>Labor Charge:</b>	270.00		

**Workorder:** 1101451

**Problem:** PM Service

<b>Meter Reading:</b> 80477		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/07/2011	<b>Close Date:</b> 02/14/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pm Service	<b>3.50</b>	1036 OIL FILTER FRM PH3980 WIX 51036		1.00
-	Clean Rear Brakes And Adjust		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Road Tested		10W30 MOTOR OIL		5.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
<b>Parts Charge:</b> 43.71		<b>Labor Charge:</b>	210.00		

**Workorder:** 1103662

**Problem:** repair tire

<b>Meter Reading:</b> 80661		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/04/2011	<b>Close Date:</b> 04/05/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Check Tire For Leak	<b>0.50</b>			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b>	30.00		

**Workorder:** 1108176

**Problem:** disable asst#

<b>Meter Reading:</b> 83447		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/04/2011	<b>Close Date:</b> 08/04/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	From: Gua / Water Plant To: Fleet / Pahokee				
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	90.00

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 1108180      **Problem:** pm service

Meter Reading: 83447	Labor	Parts	
In Date: 08/04/2011	Hours	Description	
Close Date: 08/10/2011		Quantity	
- Pm Service	<b>2.30</b>	10W30 MOTOR OIL	5.00
- Test Drive		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
<b>Parts Charge:</b>	49.95	<b>Labor Charge:</b>	138.00

**Workorder:** 1201297      **Problem:** PM Service

Meter Reading: 85645	Labor	Parts	
In Date: 02/08/2012	Hours	Description	
Close Date: 02/14/2012		Quantity	
- Pm Service	<b>4.00</b>	5LB FIREX ABC STOCK# 340280001	1.00
- Clean Rear Brakes		10W30 MOTOR OIL	5.00
- Rotate & Balance Tires		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
<b>Parts Charge:</b>	35.18	<b>Labor Charge:</b>	240.00

**Workorder:** 1202927      **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 86702	Labor	Parts	
In Date: 03/27/2012	Hours	Description	
Close Date: 03/27/2012		Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	97.92

**Workorder:** 1205432      **Problem:** BRAKES MAKING NOISE

Meter Reading: 88502	Labor	Parts	
In Date: 06/11/2012	Hours	Description	
Close Date: 06/26/2012		Quantity	
- Replace Calipers , Rotors And Brake Pads	<b>4.00</b>	FRONT BRAKE ROTORS	2.00
- Performance Test		1401 BRAKE FLUID BRAKE FLUID	2.00
		1401 BRAKE FLUID BRAKE FLUID	2.00
		FRONT BRAKE CALIPERS	2.00
		09997 BRAKE CLEAN	2.00
		FRONT BRAKE PADS	1.00
<b>Parts Charge:</b>	514.95	<b>Labor Charge:</b>	240.00

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 1207389

**Problem:** PM SERVICE

Meter Reading: 89145		Labor		Parts	
In Date: 08/07/2012	Close Date: 08/13/2012	Hours	Description		Quantity
- Pm Service		4.00	6Y648 GRAPHITE LUBE (IMPERIAL 6590)		1.00
- Clean Rear Brakes Inspect And Adjust			05046 BATTERY PROTECTOR (CRC)		1.00
- Rotate And Road Force Balance Tires			10W30 MOTOR OIL		5.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			1036 OIL FILTER FRM PH3980 WIX 51036		1.00
<b>Parts Charge:</b>		48.16	<b>Labor Charge:</b>	240.00	

**Workorder:** 1302452

**Problem:** Pm service

Meter Reading: 92296		Labor		Parts	
In Date: 03/12/2013	Close Date: 03/18/2013	Hours	Description		Quantity
- Pm Service		4.50	USED FIREX REFURBED F		1.00
- Clean And Adjust Rear Brakes			NAPA 10W30 QT		5.00
- Rotate And Balance Tires			OIL FILTER PH3980		1.00
- Test Drive.			31-22 WIPER BLADES 22		2.00
<b>Parts Charge:</b>		47.98	<b>Labor Charge:</b>	270.00	

**Workorder:** 1307257

**Problem:** damage to lft side of bed

Meter Reading: 94985		Labor		Parts	
In Date: 07/08/2013	Close Date: 07/22/2013	Hours	Description		Quantity
- Damage To Lft Side Of Bed					
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 330.00

**Workorder:** 1308222

**Problem:** A/c not working

Meter Reading: 95610		Labor		Parts	
In Date: 08/15/2013	Close Date: 08/26/2013	Hours	Description		Quantity
- Replace Blower Control Module.		1.00	BLOWER MOTOR RESISTOR		1.00
			Blower Motor Resistor		1.00
<b>Parts Charge:</b>		52.50	<b>Labor Charge:</b>	60.00	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 1309290

**Problem:** Check a/c

<b>Meter Reading:</b> 95773	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 09/12/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
<hr/>			
- Diagnose Blower Not Working. Repair Blower Ground Circuit.	<b>1.50</b>		
- Test Drive.			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	90.00

**Workorder:** 1310489

**Problem:** Pm service.

<b>Meter Reading:</b> 95779	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 10/18/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
<hr/>			
- Pm Service.	<b>4.00</b>	NAPAGOLD OIL FILTER	1.00
- Tighten Lr Taillight Assy.		WASHER FLUID CONCENTR	1.00
- Rotate And Balance Tires.		WIPER BLADE	2.00
- Test Drive.		NAPA 10W30 QT	5.00
<b>Parts Charge:</b>	31.58	<b>Labor Charge:</b>	240.00

**Workorder:** 1311176

**Problem:** Transmission stolen

<b>Meter Reading:</b> 95780	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 10/29/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
<hr/>			
- Tow From: Parks Compound Sr. 715 To: Pa Shop			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	90.00

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 1311474

**Problem:** Install transmission.

Meter Reading: 95837 In Date: 11/14/2013	Close Date: 01/14/2014	Labor Hours	Description	Parts	Quantity
-	Replace Cut Fuel Lines And Brackets. Repair Cut Ect Sensor Wiring.	35.00	FUEL LINE		1.00
-	Reinstall Vandalized Transmission. Replace Input And Out Put Shaft Seals. Replace Vandalized Trans.Cooling Lines.		TRANSMISSION PARTS		1.00
-	Service Transmission.		CONNECTOR CLIPS		1.00
-	Replace Vandalized Battery Cables And Starter.		FT1217 TRANS FILTER A		1.00
-	Replace U-Joints And Missing Driveline Parts. Rephase And Install Drive Shaft.		HEADLAMP ASSY DR		1.00
-	R&R Exhaust System For Trans. Installation.		BOLT		8.00
-	Test Drive.		NUT		1.00
-	Replace Damaged Headlight Assy.		NEW STARTER		1.00
<b>Parts Charge:</b>		1,794.33	<b>Labor Charge:</b>		2,100.00

**Workorder:** 1401679

**Problem:** Shutting off.

Meter Reading: 96007 In Date: 02/20/2014	Close Date: 02/25/2014	Labor Hours	Description	Parts	Quantity
-	Check Dtc'S And Clear. Verify Correct Fuel Pressure. Replaced Damaged Ect Connector.	3.00	CONNECTOR		1.00
-	Test Drive.				
<b>Parts Charge:</b>		15.99	<b>Labor Charge:</b>		180.00

**Workorder:** 1404679

**Problem:** pm service.

Meter Reading: 97700 In Date: 05/13/2014	Close Date: 05/21/2014	Labor Hours	Description	Parts	Quantity
-	Pm Service.	5.00	WIPER BLADE		2.00
-	Rotate And Balance Tires.		WASHER FLUID CONCENTR		1.00
-	Clean And Adjust Rear Brakes.		NAPA 10W30 QT		5.00
-	Repair Bad Connection For Lr Turn Signal Light.		USED FIRE X REFURBISHED		1.00
-	Test Drive.		SYN ATF BULK PAHOKEE		1.00
			NAPAGOLD OIL FILTER		1.00
<b>Parts Charge:</b>		53.67	<b>Labor Charge:</b>		300.00

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 1405942

**Problem:** Vandalism damage

Meter Reading: 98218	Labor	Parts
In Date: 06/17/2014	Hours	Description
Close Date: 06/17/2014	Quantity	
- Tow From: Parks Compound To: Pa Shop		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 90.00

**Workorder:** 1407730

**Problem:** REPAIR VANDILISM TO DOOR LOCKS

Meter Reading: 98442	Labor	Parts
In Date: 08/05/2014	Hours	Description
Close Date: 08/26/2014	Quantity	
- Replace Damaged Door Handles Ands Locks.	3.00	RE-KEY LOCK 2.00 Door Handle - Exterior 1.00 Door Handle - Exterior 1.00 LOCK CYLINDER 2.00
<b>Parts Charge:</b> 450.33	<b>Labor Charge:</b> 180.00	

**Workorder:** 1412535

**Problem:** Pm service.

Meter Reading: 103727	Labor	Parts
In Date: 12/16/2014	Hours	Description
Close Date: 12/31/2014	Quantity	
- Pm Service.	8.50	NAPA 10W30 QT 5.00
- Replace Front Tires. Nitro Fill, Rotate And Balance.		WIPER BLADE 2.00
- Replace Worn Rear Brake Shoes,Drums.		183114470 P245-70R17 2.00 USED FIRE X REFURBISHED 1.00 BRAKE DRUM 2.00 NAPAGOLD OIL FILTER 1.00 BRAKE CLEANER 2.00 REMAN BRAKE SHOES 1.00 TIRE DISPOSAL FEE 2.00
<b>Parts Charge:</b> 707.62	<b>Labor Charge:</b> 510.00	

1/3/2017  
12:19:05PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 1503321                      **Problem:** Replace damaged taillights. Wash

Meter Reading: 105038	Labor	Parts	
In Date: 03/31/2015	Hours	Description	
Close Date: 04/14/2015		Quantity	
- Wash Vehicle. Clean Cab.	3.50	LAMP	1.00
- Replace Broken Taillight Assys.		LAMP	1.00
<b>Parts Charge:</b> 309.26	<b>Labor Charge:</b> 210.00		

**Workorder:** 1507613                      **Problem:** Pm service.

Meter Reading: 107167	Labor	Parts	
In Date: 07/30/2015	Hours	Description	
Close Date: 08/04/2015		Quantity	
- Pm Service.	5.00	TIRE DISPOSAL FEE	2.00
- Replace Front Tires.Nitro Fill And Balance.		NAPA 10W30 QT	5.00
- Rotate Tires.		NAPAGOLD OIL FILTER	1.00
- Battery Failed Load Test . Replace Battery.		WIPER BLADE	2.00
- Test Drive.		NAPAGOLD AIR FILTER	1.00
		BULB	2.00
		183114470 P245-70R17	2.00
		BATTERY	1.00
		WASHER FLUID CONCENTR	1.00
<b>Parts Charge:</b> 587.15	<b>Labor Charge:</b> 300.00		

**Workorder:** 1602552                      **Problem:** Pm service.

Meter Reading: 112076	Labor	Parts	
In Date: 03/10/2016	Hours	Description	
Close Date: 03/14/2016		Quantity	
- Pm Service.	4.50	NAPAGOLD OIL FILTER	1.00
- Rotate And Balance Tires.		WASHER FLUID CONCENTR	1.00
- Clean And Adjust Rear Brakes.		NAPA 10W30 QT	5.00
- Test Drive.		22" WIPER BLADE	2.00
<b>Parts Charge:</b> 29.15	<b>Labor Charge:</b> 270.00		

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162797 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

**Workorder:** 1607405                      **Problem:** damage to tail gate

Meter Reading: 117194	Labor	Parts			
In Date: 06/30/2016	Hours	Description	Quantity		
<hr/>					
- Damage To Tail Gate					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	872.64

**Workorder:** 1607933                      **Problem:** Pm service. Check a/c.

Meter Reading: 118280	Labor	Parts			
In Date: 08/02/2016	Hours	Description	Quantity		
<hr/>					
- Pm Service.	<b>7.00</b>	WASHER FLUID CONCENTR	1.00		
- Rotate And Balance Tires.		RESISTOR	1.00		
- A/C Blower Not Working. Replaced Shorted Blower		CONNECTOR	1.00		
Resistor And Resistor Wiring Connector.		22" WIPER BLADE	2.00		
- Test Drive Before And After Repairs		NAPA 10W30 QT	5.00		
- Replace Damagedtail Gate		NAPAGOLD OIL FILTER	1.00		
<b>Parts Charge:</b>	181.20	<b>Labor Charge:</b>	420.00		

**Workorder:** 1609946                      **Problem:** Transition Prep Charge

Meter Reading: 119784	Labor	Parts			
In Date: 09/23/2016	Hours	Description	Quantity		
<hr/>					
- Transition Prep Charge	<b>2.00</b>				
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00		

Total Parts Charges:	<b>8,241.85</b>	Total Labor Charges:	<b>9,549.50</b>	Total Comm. Charges:	<b>1,923.96</b>
----------------------	-----------------	----------------------	-----------------	----------------------	-----------------