

**Palm Beach County Fleet Management
Asset Maintenance History**

10189093 2013 FORD TRANSIT CONNECT Mini Van, Animal Care

Workorder: 1304972 **Meter:** 321 **In Date:** 05/20/2013 **Closed:** 05/20/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1308561 **Meter:** 4992 **In Date:** 08/26/2013 **Closed:** 09/04/2013
Problem: Pm service and floor mats.

- Perform pm service.	Parts List	Qty
- Perform rear drum brake service and adjust brake shoes.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	5w20 Engine Oil	5.00
- Shop Supplies	Floor Mat-2pc Rub Bk	1.00
	Mac Wite Lithium Gres	1.00
	Shop Supplies	1.00

Hours 4.75 Labor: 285.00 Parts: 51.83 Total: 336.83
:

Workorder: 1400354 **Meter:** 10692 **In Date:** 01/13/2014 **Closed:** 01/22/2014
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Service and adjust rear brakes.	Napagold Oil Filter	1.00
- Rotate and balance all tires.	5w20 Engine Oil	5.00
- Shop Supplies	Exact Fit Blade	1.00
	Wiper Blade	1.00
	Shop Supplies	1.00

Hours 4.75 Labor: 285.00 Parts: 35.32 Total: 320.32
:

Workorder: 1403827 **Meter:** 15270 **In Date:** 04/21/2014 **Closed:** 04/30/2014
Problem: P.M. service and rear A/C turns on and off at times.

- P.m. Service	Parts List	Qty
- Resurface front brake rotors,replace front brake pads.service and lube calipers.service and adjust rear brakes.flush and bleed system.	5w20 Engine Oil	5.00
	Napagold Oil Filter	1.00
	Exact Fit Blade	1.00
- Diagnose complain of aux. a/c system works intermittenly.repair loose wiring and secure.	Wiper Blade	1.00
- Rotate and balance all tires.	Brake Cleaner	1.00
- Shop Supplies	2232 Brake Fluid Quar	1.00
	kit brake lin	1.00
	Shop Supplies	1.00

Hours 9.25 Labor: 555.00 Parts: 111.91 Total: 666.91
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1407369 **Meter:** 20794 **In Date:** 07/28/2014 **Closed:** 08/11/2014
Problem: P.M. Service.Flat tire.Check a/c vents in cage.

- Perform pm service.	Parts List	Qty
- Install four new tires.nitrogen fill and balance all four tires.	5w20 Engine Oil	5.00
- Inspect and service rear drum brakes.	Napagold Oil Filter	1.00
- Perform wheel alignment complete.	Exact Fit Blade	1.00
- Check over for ac vents operation in rear of cage.remove inspection cover to inspect routing of vent ducts.found all operate ok as design.reseal and secure cover.	Wiper Blade	1.00
	P205/65r15 Assurance	4.00
- Shop Supplies	Hub Cap	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 9.25	Labor: 555.00	Parts: 627.94
:		Total: 1,182.94

Workorder: 1407868 **Meter:** 20794 **In Date:** 07/28/2014 **Closed:** 08/11/2014
Problem: flat tire/ after hour service

- Tire Service 14125 n road lox - flat tire/ after hour service	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1410652 **Meter:** 25335 **In Date:** 10/24/2014 **Closed:** 10/30/2014
Problem: Left brake lamp inop

- Test and replace left brake lamp bulb.	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 1.86
:		Total: 31.86

Workorder: 1500743 **Meter:** 28734 **In Date:** 01/21/2015 **Closed:** 02/09/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace front brake pads and resurface both front brake rotors.service calipers.inspect and service rear drum brakes.	Brake Pads	1.00
- Rotate and balance all four tires.	5w20 Engine Oil	5.00
- Shop Supplies	Napagold Oil Filter	1.00
	Exact Fit Blade	1.00
	Wiper Blade	1.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 7.75	Labor: 465.00	Parts: 103.19
:		Total: 568.19

Workorder: 1501344 **Meter:** 28615 **In Date:** 02/04/2015 **Closed:** 02/04/2015
Problem: 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1507903 **Meter:** 42159 **In Date:** 08/06/2015 **Closed:** 09/09/2015
Problem: P.M. service and stalls at idle and right rear tire going flat.

- Pm service.	Parts List	Qty
- Replace two tires.rotate and balance all four.	5w20 Engine Oil	5.00
- Induction system cleaning.flush injectors.clean trottle body.clear codes with scan tool.	Napagold Oil Filter	2.00
	Intake Cleaner Kit	1.00
- Tune up engine Replace all four spark plugs.	Spark Plug	4.00
- Shop Supplies	Injector Cleaner	1.00
	Exact Fit Blade	1.00
	Wiper Blade	1.00
	Wd40 16oz	1.00
	P205/65r15 Assurance	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.25	Labor: 495.00	Parts: 401.66
:		Total: 896.66

Workorder: 1510194 **Meter:** 44012 **In Date:** 10/07/2015 **Closed:** 10/20/2015
Problem: Runs rough and kennel not cooling.

- Computer diagnose engine running rough.test and replace defective Maf sensor and upstream oxygen sensor.retest and reset Kam.test drive.	Parts List	Qty
	Mass Air Flow Sensor	1.00
- Ac performance and leak test.evacuate and recharge system to factory specs.test for leaks.no leaks found at this time.	R134a Lv Shop 1	3.00
	Belt Tensioner	1.00
	V Belt	1.00
- Diagnose noise from belt area.replace defective tensioner pulley and belt.	V Belt	1.00
	Sensor	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 7.25	Labor: 435.00	Parts: 479.60
:		Total: 914.60

Workorder: 1511536 **Meter:** 46185 **In Date:** 11/10/2015 **Closed:** 11/13/2015
Problem: Left front turnsignal and one fuse inop.

- Test and replace defective left front turnsignal lamp bulbs.also replace #169 15 amps fuse for power outlet	Parts List	Qty
	Bulb	2.00
- Shop Supplies	Shop Supplies	1.00
Hours 0.75	Labor: 45.00	Parts: 8.48
:		Total: 53.48

Workorder: 1511744 **Meter:** 47279 **In Date:** 11/17/2015 **Closed:** 12/09/2015
Problem: Check battery .Has to jump start.

- Test battery and charging system.perform draw test..007 amp after 40 minuites.no draw found.let sit for 4 days and recheck.no problem found.	Parts List	Qty
	Shop Supplies	1.00
- Shop Supplies		
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1512353	Meter: 47288	In Date: 12/07/2015	Closed: 12/21/2015
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Recondition headlamps to reduce clouding.		5w20 Engine Oil	5.00
- Perform rear brake service.		Napagold Oil Filter	1.00
- Rotate and balance all four tires.		Wiper Bleade Anco	1.00
- Shop Supplies		18" wiper blades	1.00
		Washer Fluid Concentr	1.00
		Hub Cap	1.00
		Shop Supplies	1.00
Hours 6.25	Labor: 375.00	Parts: 95.51	Total: 470.51
:			
Workorder: 1600089	Meter: 48125	In Date: 01/05/2016	Closed: 02/11/2016
Problem: Check battery and stalling.			
- Diagnose voltage drop on negative battery cable.r&r defective battery cables assembly and retest.		Parts List	Qty
- Charge battery fully.test battery and charging system.perform draw test.replace defective battery.		Neg Battery Cable	1.00
- Shop Supplies		Bxt96r 59	2.00
		Neg Battery Cable	1.00
		Shop Supplies	1.00
		Freight Charge	1.00
Hours 2.50	Labor: 150.00	Parts: 740.09	Total: 890.09
:			
Workorder: 1601440	Meter: 48125	In Date: 02/10/2016	Closed: 02/10/2016
Problem: 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1602779	Meter: 50406	In Date: 03/16/2016	Closed: 03/23/2016
Problem: Low tire pressure warning light on.Left tail lamp inop.			
- Replace damage left tail lamp lens.fabricate to fit Led strobe lamp.		Parts List	Qty
- Repair and balance left rear tire.		Left Real Tail Lamp Assembly	1.00
- Shop Supplies		Clr Rtv Silcn Sealant	1.00
		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 224.87	Total: 344.87
:			
Workorder: 1603177	Meter: 50815	In Date: 03/25/2016	Closed: 04/15/2016
Problem: Towed in for no crank.Had to jump start.			
- P.m. Service.		Parts List	Qty
- Recharge battery.test ststarting and charging system,okay.check and rewire switch circuit for cage lamp.		5w20 Engine Oil	5.00
- Rotate and balance all tires.		Napagold Oil Filter	1.00
- Shop Supplies		Wiper Bleade Anco	1.00
		18" wiper blades	1.00
		Washer Fluid Concentr	1.00
		Shop Supplies	1.00
Hours 5.25	Labor: 315.00	Parts: 23.92	Total: 338.92
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1603197 **Meter:** 50589 **In Date:** 03/25/2016 **Closed:** 03/28/2016
Problem: no start

- Tow From: 5110 mobil air drive To: vista lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1606853 **Meter:** 54323 **In Date:** 07/07/2016 **Closed:** 07/25/2016
Problem: Right rear tire going flat.

- Replace and balance both rear tires.
- Shop Supplies

Parts List	Qty
P205/65r15 Assurance	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 1.00 Labor: 60.00 Parts: 235.44 Total: 295.44
:

Workorder: 1607289 **Meter:** 54323 **In Date:** 07/15/2016 **Closed:** 07/18/2016
Problem: Accident (rearended)

- Tow From: 2121 Pbl blvd (frt of City Furniture)

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1608640 **Meter:** 54465 **In Date:** 07/18/2016 **Closed:** 08/19/2016
Problem: Damage to rear bumper, rear doors & left rear fender

- Damage to rear bumper, rear doors & left rear fender

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1609701 **Meter:** 55560 **In Date:** 09/16/2016 **Closed:** 09/30/2016
Problem: P.M. service and cage A/C not cooling.

- P.m. Service.
- Replace two tires,rotate and balance all four.
- Diagnose rear a/c inop.replace fuse holder and repair ground.
- Cage lights inop.diagnose and replace burnt fuse hloder.
- Rotate and balance all tires.
- Complete wheel alignment.test drive.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	5.00
Wiper Bleade Anco	1.00
18" wiper blades	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
P205/65r15 Assurance	2.00
Fuse Holder	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 10.75 Labor: 645.00 Parts: 275.99 Total: 920.99
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1702924 **Meter:** 61859 **In Date:** 03/22/2017 **Closed:** 03/30/2017
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Resurface front brake rotors,replace pads.service and lube calipers.resurface rear brake drums,replace shoes and wheel cylinder.flush and bleed system.	5w20 Engine Oil	5.00
	Napagold Oil Filter	1.00
- Service transmission.flush and refill system.	Wiper Bleade Anco	1.00
- Rotate and balance tires.	18" wiper blades	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Hub Cap	1.00
	Brake Pads	1.00
	Brake Shoe	1.00
	Wheel Cyinders	2.00
	Brk Fluid Dot 4-12oz	1.00
	Non-chlor Brake Clnr	1.00
	Transmission Filter	1.00
	Syn-atf Trans Fluid S	12.00
	Shop Supplies	1.00
Hours 12.25	Labor: 735.00	Parts: 467.75
:		Total: 1,202.75

Workorder: 1705177 **Meter:** 65346 **In Date:** 05/25/2017 **Closed:** 05/31/2017
Problem: Towed in for left front tire flat.

- Replace one tire and balance .mount on left front .nitrogen fill tires Reset Tpms.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	P205/65r15 Tire	1.00
Hours 0.50	Labor: 30.00	Parts: 61.99
:		Total: 91.99

Workorder: 1705319 **Meter:** 65346 **In Date:** 05/25/2017 **Closed:** 05/30/2017
Problem: flat tire

- Tow From: acc 7100 belvedere To: 2601 vista	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

Workorder: 1705448 **Meter:** 65556 **In Date:** 06/01/2017 **Closed:** 06/02/2017
Problem: Towed in for belt came off.

- Check ,found frozen idler pulley.replace defective idler pulley and tensioner assembly and serpentine belt .road test.	Parts List	Qty
- Shop Supplies	Dr Blt Tensioner Assy	1.00
	Idler Pulley	1.00
	V Belt	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 117.37
:		Total: 237.37

Workorder: 1705580 **Meter:** 65556 **In Date:** 05/31/2017 **Closed:** 06/05/2017
Problem: overheated and shut off. on side of road near shelter entrance

- Tow From: 3615 St. Rd. 715 Pahokee To: Lv vista	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706860 **Meter:** 69426 **In Date:** 07/13/2017 **Closed:** 08/03/2017
Problem: P.M. Service.Check a/c in middle cage.Install inverter.

- P.m. service.	Parts List	Qty
- Replace broken left front inner door handle.	5w20 Engine Oil	5.00
- Check vibration from engine.replace worn right side engine mount.	Napagold Oil Filter	1.00
- Install power inverter,fabricate wiring as needed.	Wiper Bleade Anco	1.00
- Check rear A/c operation.one side is inlet air ,one side is outlet air.compared to similar vehicle.same.	18" wiper blades	1.00
- Perform rear brake service.	Stg Wheel Cov - Ford	1.00
- Rotate and balance four tires.nitrofill.	Engine Mount	1.00
- Test and replace right brake light bulb.retest.	1500 Watt Inverter	1.00
- Shop Supplies	Cb185-100 Cir Brkr	1.00
	Cabl/lug	6.00
	handle	1.00
	Bulk Battery Cable	13.00
	Bulk Battery Cable	3.00
	Fab Loom-split Poly	16.00
	Bulb	1.00
	Shop Supplies	1.00
Hours 11.55	Labor: 693.00	Parts: 710.72
:		Total: 1,403.72

Workorder: 1708010 **Meter:** 70482 **In Date:** 08/15/2017 **Closed:** 08/22/2017
Problem: Timex temp display inop and check cage air vents.

- Replace timex theremeter.a/c temps are good .vents are working properly.two vents are return not supply.normal operation.	Parts List	Qty
- Shop Supplies	In Car Temperture Guage	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 28.39
:		Total: 88.39

Workorder: 1708798 **Meter:** 71166 **In Date:** 09/07/2017 **Closed:** 09/07/2017
Problem: Towed in left front tire flat.

- Repair left front tire.nitro fill all.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1709064 **Meter:** 71983 **In Date:** 09/06/2017 **Closed:** 09/20/2017
Problem: Flat tire towed to Fleet

- Tow From: Animal Care		
Hours 0.00	Labor: 0.00	Parts: 0.00
:		Total: 0.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1709822 **Meter:** 72985 **In Date:** 10/06/2017 **Closed:** 10/16/2017
Problem: Brake light out, Tire light on.

- Replace right rear tire had multiple screws and previous repair.mount and balance one tire.	Parts List	Qty
	Sig Lamp	1.00
- Replace right rear tail light bulb.	P205/65r15 Assurance	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 1.00	Labor: 60.00	Parts: 128.64
:		Total: 188.64

Workorder: 1710448 **Meter:** 73670 **In Date:** 10/24/2017 **Closed:** 10/31/2017
Problem: Left rear tire going flat.

- Replace left rear tire due to screw in sidewall.	Parts List	Qty
- Perform advance battery analysis,battery tested bad .replace battery .retest starting and charging system,ok.no draws at this time.	P205/65r15 Assurance	1.00
	Battery	1.00
- Diagnose inverter not working .blown circuit breaker.load test inverter system.works as designed.check rear A/c system no indication of malfunctioning.	Shop Supplies	1.00
- Shop Supplies	Tire Disposal Fee	1.00
Hours 2.30	Labor: 138.00	Parts: 279.87
:		Total: 417.87

Workorder: 1712462 **Meter:** 75428 **In Date:** 12/19/2017 **Closed:** 12/28/2017
Problem: Replace left front signal bulb

- Replace left front turn signal bulb.	Parts List	Qty
- P.m. service.	5w20 Engine Oil	5.00
- Replace both front tires and rotate and balanced rear tires. Nitrogen filled all four tires.	Napagold Oil Filter	1.00
	Washer Fluid Concentr	1.00
- Coolant was low.pressure tested sysatem and found coolant overflow tank to be leaking.removed and replaced coolant overflow tank.flush coolant.	Wiper Bleade Anco	1.00
	18" wiper blades	1.00
- Clean and adjusted rear brakes.	Used Fire X Refurbished	1.00
- Perform four wheel alignment.	Fire Ext Mount Strap Style	1.00
- Shop Supplies	P205/65r15 Assurance	2.00
	Bulb	1.00
	Hub Cap	1.00
	Tank Assy Coolant	1.00
	Anti Freeze Motorcraft	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.75	Labor: 645.00	Parts: 474.21
:		Total: 1,119.21

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1801095	Meter: 76998	In Date: 01/30/2018	Closed: 01/31/2018
Problem: Cabin temperature display is inop.			
- Replace cabin temperature gauge and sensor .remove cage side panel to access temp sensor.	Parts List		Qty
	Indoor/outdoor Thermometer Digital		1.00
- Replace right rear tire ,screw in side wall .balance and nitro service.	P205/65r15 Assurance		1.00
	Shop Supplies		1.00
- Shop Supplies	Tire Disposal Fee		1.00
Hours 2.50	Labor: 150.00	Parts: 143.80	Total: 293.80
:			

Workorder: 1802100	Meter: 78654	In Date: 02/26/2018	Closed: 02/27/2018
Problem: Left head light inop and right high beam out.			
- Test and replace both headlight bulbs.retest.	Parts List		Qty
	Halogen Capsule		2.00
- Shop Supplies	Shop Supplies		1.00
Hours 0.50	Labor: 30.00	Parts: 24.17	Total: 54.17
:			

Workorder: 1802280	Meter: 78654	In Date: 02/22/2018	Closed: 02/28/2018
Problem: Flat tire on Rear Left			
- Tire Service End of sycamore Lane and Margo Way - Flat tire on Rear Left			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1803142	Meter: 80372	In Date: 03/26/2018	Closed: 04/04/2018
Problem: PM Service, TPMS light.			
- P.m. service. Replace missing hub cap.	Parts List		Qty
- Left side tag light inop .remove assembly to replace bulb and retest.	5w20 Engine Oil		5.00
	Napagold Oil Filter		1.00
- Rotate and high speed balance all four tires.	Wiper Bleade Anco		1.00
	18" wiper blades		1.00
- Shop Supplies	Washer Fluid Concentr		1.00
	Boxed Miniatures		1.00
	Hub Cap		2.00
	Shop Supplies		1.00
Hours 4.25	Labor: 255.00	Parts: 188.44	Total: 443.44
:			

Workorder: 1803715	Meter: 80792	In Date: 04/09/2018	Closed: 04/12/2018
Problem: A/C in cages turns on and off byself.			
- Diagnose intermittent A/c issue for cage .r&r defective relay for rear blower motor.	Parts List		Qty
	Relay		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 10.27	Total: 130.27
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1804375	Meter: 81528	In Date: 04/26/2018	Closed: 05/03/2018
Problem: Rear cage blower shuts after about an hour .			
- Diagnose and repair bad connection to A/c control switches .replace relay pigtail and fuse tap in fuse panel .retest system operation .		Parts List	Qty
		Connectr	1.00
		Mini Add-a-circuit	1.00
- Shop Supplies		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 30.97	Total: 150.97
:			
Workorder: 1806207	Meter: 84211	In Date: 02/20/2018	Closed: 06/18/2018
Problem: Emergency Service			
- Tire Service Sycamore & Margo Way - Emergency Service			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1806462	Meter: 84757	In Date: 06/25/2018	Closed: 06/28/2018
Problem: P.M. service and Left sliding door binding and left front locks and unlocks when tring to lock.			
- P.m. service.		Parts List	Qty
- Diagnose intermitten door locks .r&r defective left front door latch assembly and left sliding door latch . retest operation .		Napagold Oil Filter	1.00
		5w20 Engine Oil	5.00
- Perform head light restoration. Sand and polish headlights.		18" wiper blades	1.00
- Clean, inspect and adjust rear brakes .		Wiper Bleade Anco	1.00
- Rotate and balance all four tires. Nitrogen fill tires.		3m Tm Headlight Lens	1.00
- Shop Supplies		D/s Front Door Latch	1.00
		latch	1.00
		Shop Supplies	1.00
Hours 8.25	Labor: 495.00	Parts: 970.90	Total: 1,465.90
:			
Workorder: 1808510	Meter: 86953	In Date: 08/17/2018	Closed: 08/20/2018
Problem: Nail - back right tire.			
- Repair right rear tire and balance . Nitrogen fill tires.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1809740	Meter: 88762	In Date: 09/20/2018	Closed: 09/20/2018
Problem: Overheating			
- Tow From: 95 e of Glades in the Whole Food To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1809747	Meter: 88853	In Date: 09/20/2018	Closed: 09/28/2018
Problem: Towed in for overheating.			
- Pressure test cooling system . Replace leaking upper radiator hose and degas bottle vent tubing . Flush and refill colling system . Retest.		Parts List	Qty
		Anti Freeze Motorcraft	1.00
		Hose Asy	1.00
- Shop Supplies		Lower Hose	1.00
		Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 149.66	Total: 329.66
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810150	Meter: 89048	In Date: 10/01/2018	Closed: 10/02/2018
Problem: Towed in right front tire flat.			
- Replace both front tires and balance . Nitrogen fill all tires.	Parts List		Qty
- Shop Supplies	P205/65r15 Assurance		2.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 1.00	Labor: 67.00	Parts: 256.93	Total: 323.93
:			
Workorder: 1810172	Meter: 88933	In Date: 10/01/2018	Closed: 10/01/2018
Problem: flat tire			
- Tow From: 95 Nb n of 45th street			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1811374	Meter: 90875	In Date: 11/02/2018	Closed: 11/05/2018
Problem: Overheating/Due for PM			
Contact: Officer Weisberger-561-789-0729			
- Tow From: 21925 Mizner Way (frt of Leasing Bldg) To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1811375	Meter: 90926	In Date: 11/02/2018	Closed: 11/08/2018
Problem: PM Service, Overheating.			
- P.m. service.	Parts List		Qty
- Inspect for oil leak . Replace valve cover gasket and clean oil from engine. Retest .	Napa Quart 5w20		5.00
	Napagold Oil Filter		1.00
- Diagnose overheating concern . Test and replace defective cooling fan assmby and resistor and burnt connector .	Used Fire X Refurbished		1.00
	18" wiper blades		1.00
- Replace one tire . Rotate and balance all four tires. Nitrofill and reset Tpms.	Wiper Bleade Anco		1.00
	Valve Cover Gasket		1.00
- Shop Supplies	Fan Resistor Connector		1.00
	Bp Fmx-lp F Mx Fuse		1.00
	Bp Fmx-lp F Mx Fuse		1.00
	Cooling Fan Assembly		1.00
	Shop Supplies		1.00
	P205/65r15 Tire		1.00
	Tire Disposal Fee		1.00
Hours 7.85	Labor: 525.95	Parts: 615.95	Total: 1,141.90
:			
Workorder: 1811837	Meter: 91718	In Date: 11/19/2018	Closed: 11/29/2018
Problem: Cage A/C inop.			
- Diagnose auxillary fans inop. Replace blown fuse and retest operation of fans and rear A/c .test drive .	Parts List		Qty
	Shop Supplies		1.00
- Shop Supplies			
Hours 1.00	Labor: 67.00	Parts: 3.00	Total: 70.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1812781	Meter: 92722	In Date: 12/17/2018	Closed: 12/18/2018
Problem: Left front turn signal inop.			
- Test and replace left front turn signal bulb .		Parts List	Qty
		Bulb	1.00
Hours 0.30	Labor: 20.10	Parts: 1.49	Total: 21.59
:			
Workorder: 1900247	Meter: 93651	In Date: 01/07/2019	Closed: 01/10/2019
Problem: Cage A/C stoped blowing .			
- Diagnose rear cage A/c inop. Replace burnt inline fuse holder and retest circuit .		Parts List	Qty
		Fuse Holder	1.00
Hours 0.60	Labor: 40.20	Parts: 5.67	Total: 45.87
:			
Workorder: 1902045	Meter: 95408	In Date: 02/25/2019	Closed: 03/06/2019
Problem: Towed in for overheating .			
- Computer diagnose overheating .pressure test and inspect cooling system . R&r defective and corroded cylinder head temp sensor and connector . Clear codes and retest .		Parts List	Qty
		Wire Assy	1.00
		Sensor	1.00
- Shop Supplies		Shop Supplies	1.00
Hours 2.50	Labor: 167.50	Parts: 71.07	Total: 238.57
:			
Workorder: 1902089	Meter: 95301	In Date: 02/23/2019	Closed: 02/25/2019
Problem: Overheating			
- Tow From: 6390 W Indiantown rd To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1902681	Meter: 95958	In Date: 03/11/2019	Closed: 03/28/2019
Problem: P.M. service and overheating .			
- P.m. Service.		Parts List	Qty
- Pressure test and inspect cooling system.replaceleaking radiator and lower hose.flush and refill cooling system.test cooling fan operation.		Napagold Oil Filter	1.00
		5w20 Engine Oil	5.00
- Replace two tires,rotate and balance all four.		18" wiper blades	1.00
- Replace left headlight bulb.		Wiper Bleade Anco	1.00
- Shop Supplies		Thermostat	1.00
		Lower Hose	1.00
		Radiator Assy	1.00
		205/65/15 Tire Continental	2.00
		Boxed Capsules	1.00
		Hose Hea	1.00
		Anti Freeze Motorcraft	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 10.25	Labor: 686.75	Parts: 815.85	Total: 1,502.60
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1903739	Meter: 96521	In Date: 04/05/2019	Closed: 04/08/2019
Problem: Left rear tire has metal in it.			
- Repair left rear tire and balance . Nitrofill all tires .		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00	Total: 70.00
:			
Workorder: 1904016	Meter: 96656	In Date: 04/12/2019	Closed: 04/17/2019
Problem: No AC in cage, not blowing.			
- A/c performance test . Diagnose rear cage A/c inop .		Parts List	Qty
Replace blown fuse for cage A/c . Perform amp draw test ,		Shop Supplies	1.00
8.1 amps . Trace circuits . remove rear A/c cover and repair			
shorted blower fan power wire . Retest .			
- Shop Supplies			
Hours 2.00	Labor: 134.00	Parts: 3.00	Total: 137.00
:			
Workorder: 1904898	Meter: 97439	In Date: 05/06/2019	Closed: 05/16/2019
Problem: Whinning noise from engine .			
- Diagnose noise and inspect power steering for leaks .		Parts List	Qty
Replace power steering line seals at rack . Clean excess oil		Ptex Ultra Black 30z	1.00
and bleed and flush power steering fluid . Test drive.		Non-chlor Brake Clnr	1.00
- Pressure test and inspect cooling system . Replace leaking		oil auto	1.00
hose from thermostat to heater core . Refill and retest.		Seal	4.00
- Shop Supplies		Seal	4.00
		Anti Freeze Motorcraft	1.00
		Hose Hea	1.00
		Shop Supplies	1.00
Hours 3.50	Labor: 234.50	Parts: 154.11	Total: 388.61
:			
Workorder: 1906580	Meter: 99496	In Date: 06/24/2019	Closed: 07/03/2019
Problem: P.M. service and A/C blows warm .			
- P.m. service.		Parts List	Qty
- A/c performance test and leak test . Recover and evacuate		Napagold Oil Filter	1.00
system . Replace leaking condenser ,accumulator and orifice		5w20 Engine Oil	5.00
tube . Vacuum system and complete recharge to factory		18" wiper blades	1.00
spec. Retest .		Wiper Bleade Anco	1.00
- R&r broken left front seat adjusting handle .		Washer Fluid Concentr	1.00
- Service and inspect rear brakes .		Gasket Kit A/c	1.00
- Rotate and balance all four tires . Nitrofill all.		Freon Lv Shop 2	3.00
- Shop Supplies		E8 A/c Oil Univ W Dye	1.00
		Ofice Tube	1.00
		Accumulator	1.00
		A/c Condenserasy	1.00
		Handle	1.00
		Shop Supplies	1.00
Hours 10.85	Labor: 726.95	Parts: 547.16	Total: 1,274.11
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1908232 **Meter:** 101216 **In Date:** 08/08/2019 **Closed:** 08/15/2019

Problem: Left front turn signal out.

- Replace left front signal light bulb.

Parts List

Boxed Miniatures

Qty

1.00

Hours 0.50

Labor: 33.50

Parts: 1.49

Total: 34.99

:

Workorder: 1910477 **Meter:** 102540 **In Date:** 10/09/2019 **Closed:** 10/09/2019

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00

Labor: 146.00

Parts: 0.00

Total: 146.00

: