

**Palm Beach County Fleet Management
Asset Maintenance History**

10187817 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Workorder: 1207959	Meter: 163	In Date: 08/21/2012	Closed: 08/21/2012
Problem: 1061 - Pre Delivery Inspection			
- Pre Delivery Inspection			
Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			
Workorder: 1209214	Meter: 3159	In Date: 09/26/2012	Closed: 12/11/2012
Problem: Install topper			
- Transport vehicle to Rayside for topper installation.			
		Parts List	Qty
		topper	1.00
- Repair and balance right rear tire.			
		Shop Supplies	1.00
- Shop Supplies			
Hours 3.00	Labor: 180.00	Parts: 1,946.36	Total: 2,126.36
:			
Workorder: 1210652	Meter: 1716	In Date: 10/31/2012	Closed: 10/31/2012
Problem: put on spare rr			
- Tow From: lake lytle 3645 gun club			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1301027	Meter: 4806	In Date: 01/29/2013	Closed: 02/07/2013
Problem: Pm service.			
- P.m. Service.			
		Parts List	Qty
- Service and adjust rear brakes.			
		Dexos 5w30	5.00
- Make and install asset # for topper.			
		Napagold Oil Filter	1.00
- Rotate and balance all tires.			
		Shop Supplies	1.00
- Shop Supplies			
Hours 4.50	Labor: 270.00	Parts: 35.38	Total: 305.38
:			
Workorder: 1307605	Meter: 11185	In Date: 07/31/2013	Closed: 08/15/2013
Problem: Pm service. Topper window locking rod on right rear inop.			
- P.m. Service.			
		Parts List	Qty
- Fabricate and repair topper rear latch.			
		Dexos 5w30	5.00
- Service and adjust rear brakes.			
		Napagold Oil Filter	1.00
- rotate and balance all tires.			
		Wiper Blade	1.00
- Shop Supplies			
		Wiper Blade	1.00
		Shop Supplies	1.00
Hours 4.50	Labor: 270.00	Parts: 43.27	Total: 313.27
:			
Workorder: 1311455	Meter: 15696	In Date: 11/13/2013	Closed: 11/25/2013
Problem: Right front tire going flat.			
- Repair and balance right front tire.			
		Parts List	Qty
- Shop Supplies			
		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1400112 **Meter:** 17369 **In Date:** 01/06/2014 **Closed:** 01/31/2014
Problem: P.M. service and tire light on and 12319 hood latch recall.

- P.m. Service.	Parts List	Qty
- Repair left rear tire,rotate and balance all four.	Wiper Blade	1.00
- Transport vehicle to dealer for hood latch recall.	Napagold Air Filter	1.00
- Shop Supplies	Dexos 5w30 Oil	5.00
	Napagold Oil Filter	1.00
	Wiper Blade	2.00
	Washer FI	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 61.37
:		Total: 421.37

Workorder: 1405666 **Meter:** 23027 **In Date:** 06/09/2014 **Closed:** 06/18/2014
Problem: P.M. Service.

- Perform pm service.	Parts List	Qty
- Rotate and balance all four tires.	Dexos 5w30 Oil	5.00
- Inspect and service rear drum brakes.	Napagold Oil Filter	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 36.13
:		Total: 276.13

Workorder: 1406859 **Meter:** 24036 **In Date:** 07/11/2014 **Closed:** 07/14/2014
Problem: Left front tire flat.

- Repair flat left front tire.nitrogen fill and balance same.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1407230 **Meter:** 24550 **In Date:** 07/23/2014 **Closed:** 08/07/2014
Problem: A/C blower cuts out at times.

- Transport vehicle to and from dealer for repairing wiring harness to ac controller and replacing failed power steering rack.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1408818 **Meter:** 25406 **In Date:** 09/02/2014 **Closed:** 09/08/2014
Problem: Left rear tire flat.

- Mount and balance four tires.	Parts List	Qty
- Complete front end alignment and test drive.	215 70r16 All Season	4.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 4.50	Labor: 270.00	Parts: 552.88
:		Total: 822.88

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1412564 **Meter:** 29232 **In Date:** 12/16/2014 **Closed:** 01/06/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Inspect and replace defective possitive and negative battery cable assembly due to acid build up.	Dexos 5w30 Oil	5.00
- Inspect front suspension and replace leaking right front strut assembly.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	Wiper Blade	1.00
- Shop Supplies	Wiper Blade	1.00
	Washer Fluid Concentr	1.00
	Battery Cable	1.00
	Front Strut Rh	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 308.45
:		Total: 728.45

Workorder: 1500691 **Meter:** 29604 **In Date:** 01/20/2015 **Closed:** 02/19/2015
Problem: Battery light on and off.Cannot change cluster to english.

- Transport vehicle to and from dealer for instrument cluster intermittent and right door speaker.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1501944 **Meter:** 29697 **In Date:** 02/24/2015 **Closed:** 02/28/2015
Problem: Battery light on intermittent in cluster when running.

- Transport vehicle to and from dealer for replacing defective alternator and battery.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1505735 **Meter:** 33152 **In Date:** 06/08/2015 **Closed:** 06/16/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Inspect and service rear brakes.	Dexos 5w30 Oil	5.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Wiper Blade	1.00
	Wiper Blade	1.00
	Brake Cleaner	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 58.46
:		Total: 298.46

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1510217 **Meter:** 37725 **In Date:** 10/08/2015 **Closed:** 10/20/2015
Problem: Using brake fluid.

<ul style="list-style-type: none"> - Inspect and diagnose for low brake pedal.check for leaks at lines and wheel cylinder.master cylinder leaking into brake booster.replace new brake booster and master cylinder.perform automated brake bleeding.roadtest. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> B Fluid Dot 3-32oz Brake Cleaner Master Cylinder Brake Booster Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 1.00 1.00 1.00 	
Hours 4.50	Labor: 270.00	Parts: 276.62	Total: 546.62
:			

Workorder: 1510927 **Meter:** 38074 **In Date:** 10/28/2015 **Closed:** 11/12/2015
Problem: Pm service.

<ul style="list-style-type: none"> - Pm service. - Replace and balance all four tires. - Complete front end alignment and road test. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Dexos 5w30 Napagold Oil Filter 22" Wiper Blade Washer Fluid Concentr Wiper Blade 215 70r16 All Season Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 5.00 1.00 2.00 1.00 1.00 4.00 1.00 4.00 	
Hours 6.50	Labor: 390.00	Parts: 596.13	Total: 986.13
:			

Workorder: 1600965 **Meter:** 41786 **In Date:** 01/28/2016 **Closed:** 03/02/2016
Problem: Have to add engine oil.

<ul style="list-style-type: none"> - Check oil level and check for leaks.non found.top off oil level. 	Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
	:			

Workorder: 1603318 **Meter:** 43067 **In Date:** 03/30/2016 **Closed:** 04/18/2016
Problem: Pm service.

<ul style="list-style-type: none"> - P.m. Service. - Test battery and charging system.charge and retest battery,fail load test.replace defective battery. - Pressure test and inspect cooling system.flush and refill cooling system. - Service and adjust reat brakes. - Rotate and balance all tires. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Dexos 5w30 Napagold Oil Filter 22" Wiper Blade Wiper Blade Anco Washer Fluid Concentr Battery Peak Global Floor Mat Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 	
Hours 7.00	Labor: 420.00	Parts: 221.14	Total: 641.14
	:		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1608643 **Meter:** 48251 **In Date:** 08/19/2016 **Closed:** 08/31/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace tag lamp bulb.	Napagold Oil Filter	1.00
- Replace worn out right side topper window struts.	Napa Syn 5w30 Qt	5.00
- Service transmission.flush and refill system.	22" Wiper Blade	2.00
- Service and adjust rear brakes.	Bulb	2.00
- Repair right front tire,rotate and balance all four.	Support	2.00
- Shop Supplies	Syn-atf Trans Fluid S	16.00
	Filter Kit	1.00
	Wiper Blade Anco	1.00
	Support	2.00
	Shop Supplies	1.00
Hours 8.25	Labor: 495.00	Parts: 251.36
:		Total: 746.36

Workorder: 1612219 **Meter:** 52448 **In Date:** 11/30/2016 **Closed:** 12/15/2016
Problem: Right rear tire going flat.

- eplace and balance both rear tires.	Parts List	Qty
- Replace left brake lamp bulb.	215 70r16 All Season	2.00
- Shop Supplies	Bulb	1.00
	Ptex Superbond Sm	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.50	Labor: 90.00	Parts: 280.05
:		Total: 370.05

Workorder: 1700270 **Meter:** 53711 **In Date:** 01/10/2017 **Closed:** 01/23/2017
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace missing right side prop for topper.	Napa Syn 5w30 Qt	5.00
- Inspect and service rear differential.	Napagold Oil Filter	1.00
- Replace two tires,rotate and balance all four,	Napagold Air Filter	1.00
- Shop Supplies	22" Wiper Blade	1.00
	Support	1.00
	1qt Syngear Oil 75-90	2.00
	Non-chlor Brake Clnr	1.00
	Wiper Blade Anco	1.00
	215 70r16 All Season	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 5.25	Labor: 315.00	Parts: 383.67
:		Total: 698.67

Workorder: 1703233 **Meter:** 56372 **In Date:** 03/31/2017 **Closed:** 03/31/2017
Problem: repair tire, tire only

- Repair tire, tire only	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1703983 **Meter:** 57582 **In Date:** 04/20/2017 **Closed:** 04/28/2017
Problem: Right low beam headlight inop.

- Test and replace right side low beam headlight bulb .retest. **Parts List** **Qty**
- Shop Supplies Halogen Capsule 1.00
Shop Supplies 1.00

Hours 0.80 Labor: 48.00 Parts: 7.55 Total: 55.55
:

Workorder: 1706193 **Meter:** 60161 **In Date:** 06/22/2017 **Closed:** 06/30/2017
Problem: P.M. Service.

- P.m. Service. **Parts List** **Qty**
- Service and adjust rear brakes. Napa Syn 5w30 Qt 5.00
- Rotate and balance tires. Napagold Oil Filter 1.00
- Shop Supplies 22" Wiper Blade 1.00
Wiper Blade Anco 1.00
Shop Supplies 1.00

Hours 4.00 Labor: 240.00 Parts: 38.93 Total: 278.93
:

Workorder: 1709698 **Meter:** 64269 **In Date:** 10/04/2017 **Closed:** 10/05/2017
Problem: Left headlight inop and left rear tire going flat.

- Test and replace left low beam headlight bulb and retest. **Parts List** **Qty**
- repair left rear tire and balance .nitrogen fill tires. Halogen Capsule 1.00
- Shop Supplies Shop Supplies 1.00

Hours 1.50 Labor: 90.00 Parts: 7.55 Total: 97.55
:

Workorder: 1710570 **Meter:** 65267 **In Date:** 10/26/2017 **Closed:** 11/09/2017
Problem: P.M. service and service tire pressure light on.

- P.m. service. **Parts List** **Qty**
- Replace two front tires.balance and rotate all four Napa Syn 5w30 Qt 5.00
.computer diagnose tire light found no commucation with Napagold Oil Filter 1.00
sensors.replace and program all four sensors. 22" Wiper Blade 1.00
- Inspect and service rear brakes. Wiper Blade Anco 1.00
- Complete front end alignment and road test. Wd40 Spr 1.00
- Shop Supplies Radiator Cap 1.00
Sensor 4.00
215 70r16 All Season 2.00
Shop Supplies 1.00
Tire Disposal Fee 2.00

Hours 8.50 Labor: 510.00 Parts: 678.78 Total: 1,188.78
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1802508 **Meter:** 70389 **In Date:** 03/07/2018 **Closed:** 03/19/2018
Problem: P.M. service and left rear tire going flat.

<ul style="list-style-type: none"> - P.m. service. - Check and replace front brake rotors ,pads,calipers.replce rear brake shoes ,wheel cylinders and drums .bleed and flush brake system.road test. - Replace two front tires .balance and rotate all four tires. - Check and replace defective left side tail lamp lens assembly. - Check and replace defective left front door hinges ,upper and lower and adjust. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Caliper Washer 215 70r16 All Season Napa Syn 5w30 Qt Napagold Oil Filter Wiper Blade Anco 22" Wiper Blade B Fluid Dot 3-32oz Non-chlor Brake Clnr Front Rotor Brake Pad Brake Caliper Brake Caliper Brake Shoe A/c Delco Brake Cylinder Brake Drum Lamp Asy Hinge Hinge Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 4.00 2.00 5.00 1.00 1.00 1.00 1.00 1.00 2.00 1.00 1.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00 1.00 2.00 	
Hours 13.00 :	Labor: 780.00	Parts: 1,932.93	Total: 2,712.93

Workorder: 1804989 **Meter:** 72865 **In Date:** 05/14/2018 **Closed:** 05/24/2018
Problem: Check engine light on.Brakes feel low.

<ul style="list-style-type: none"> - Computer diagnosis check engine light . Perform pin point ,evap test . R&r defective purge valve .retest and clear codes. - Check brakes .measure excessive runout . Resurface both front rotors and rear drums .adjust rear brakes and test drive. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Evap Valve Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 	
Hours 5.50 :	Labor: 330.00	Parts: 34.45	Total: 364.45

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808453 **Meter:** 76353 **In Date:** 08/16/2018 **Closed:** 08/29/2018
Problem: P.M. service ,check lights , left camper top door prop, Left rear tire flat.

- P.m. service.	Parts List	Qty
- Replace two tires .rotate and high speed balance all four and nitrogen fill all.	Napagold Oil Filter	1.00
- Replace right tail light lens and brake light bulb.	Napa Syn 5w30 Qt	5.00
- Perform complete front end alignment and test drive.	22" Wiper Blade	1.00
- Reinstall left side camper door lock cylinder and retest.	Wiper Blade Anco	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Boxed Miniatures	2.00
	215 70r16 All Season	2.00
	Breake Light Socket Lamp Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.30	Labor: 498.00	Parts: 461.34
:		Total: 959.34

Workorder: 1811114 **Meter:** 79017 **In Date:** 10/29/2018 **Closed:** 11/06/2018
Problem: Check brake feel soft.

- Perform complete brake inspection .test drive . Adjust rear brakes . Flush and bleed system and power bleed with scan tool . Test drive.	Parts List	Qty
- Shop Supplies	Big G Degreaser 1 Gal	1.00
	B Fluid Dot 3-32oz	2.00
	Shop Supplies	1.00
Hours 2.20	Labor: 147.40	Parts: 23.67
:		Total: 171.07

Workorder: 1900481 **Meter:** 81948 **In Date:** 01/14/2019 **Closed:** 01/22/2019
Problem: P.M. service and brakes go to the floor at times .

- P.m. service.	Parts List	Qty
- Check all brakes and inspect . Replace defective master cylinder . Flush and bleed brake system . Service and inspect rear brakes . Road test.	Napagold Oil Filter	1.00
- Rotate and high speed balance all four wheels . Nitrfill all.	Napa Syn 5w30 Qt	5.00
- Shop Supplies	Wiper Blade Anco	1.00
	22" Wiper Blade	1.00
	Washer Fluid Concentr	1.00
	Non-chlor Brake Clnr	1.00
	B Fluid Dot 3-32oz	1.00
	Master Cylinder	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 402.00	Parts: 211.08
:		Total: 613.08

Workorder: 1901316 **Meter:** 82824 **In Date:** 02/04/2019 **Closed:** 02/22/2019
Problem: Brakes go to the floor and truck pulls left .

- Inspect all brakes . Perform scan tool automated power bleeding . Road test .	Parts List	Qty
- Shop Supplies	B Fluid Dot 3-32oz	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 9.56
:		Total: 76.56

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1904229 **Meter:** 85158 **In Date:** 04/18/2019 **Closed:** 04/22/2019

Problem: Repair tire .

- Repair one tire and balance . Nitrofill . Vehicle at parks shop.	Parts List	Qty
	Shop Supplies	1.00
- Shop Supplies		
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

Workorder: 1905928 **Meter:** 87209 **In Date:** 06/05/2019 **Closed:** 06/18/2019

Problem: P.M. service and left front window inop.

- P.m. service.	Parts List	Qty
- Perform battery charge and analyzing load test . Battery failed load test . R&r defective battery .	Napagold Oil Filter	1.00
- Diagnose and replace defective left front window regulator assembly . Retest .	Napa Syn 5w30 Qt	5.00
- Replace all four tires . Balance and nitrofill all.	22" Wiper Blade	1.00
- Inspect and service rear brakes .	Wiper Blade Anco	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Battery	1.00
	Window Regulator	1.00
	215/70/16 Tire Han	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 7.00	Labor: 469.00	Parts: 809.00
:		Total: 1,278.00

Workorder: 1912031 **Meter:** 93302 **In Date:** 11/20/2019 **Closed:** 11/20/2019

Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00