

**Palm Beach County Fleet Management
Asset Maintenance History**

10192552 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab

Workorder: 1304864 **Meter:** 325 **In Date:** 05/15/2013 **Closed:** 05/15/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1305902 **Meter:** 1207 **In Date:** 06/13/2013 **Closed:** 06/25/2013
Problem: Install tool box.

- Install new tool box.
- Shop Supplies

Parts List	Qty
117 Used Tool Box Wea	1.00
Tool Box	1.00
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 587.92 Total: 647.92
:

Workorder: 1309420 **Meter:** 6614 **In Date:** 09/17/2013 **Closed:** 09/30/2013
Problem: Install computer stand and Pm service.

- Fabricate,put together and install new customer supplied computer stand.
- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fl	1.00
Floor Mat-2pc Rub Bk	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours 5.00 Labor: 300.00 Parts: 66.98 Total: 366.98
:

Workorder: 1401825 **Meter:** 16213 **In Date:** 02/25/2014 **Closed:** 02/26/2014
Problem: Pm service.

- Pm service.
- Rotate and balance tires.
- Test drive.
- Shop Supplies

Parts List	Qty
Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours 3.50 Labor: 210.00 Parts: 47.59 Total: 257.59
:

Workorder: 1412525 **Meter:** 30579 **In Date:** 12/15/2014 **Closed:** 12/17/2014
Problem: Pm service.

- Pm service.
- Air bag light on. Check dtc's and clear. Lube lh seat belt latch.
- Rotate and balance tires.
- Test drive.
- Shop Supplies

Parts List	Qty
5w20 Oil Bulk	6.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours 5.00 Labor: 300.00 Parts: 32.09 Total: 332.09
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1505035 **Meter:** 39463 **In Date:** 05/18/2015 **Closed:** 05/26/2015
Problem: PM service screw in rear tire

- Pm service.	Parts List	Qty
- Replace all tires. Nitro fill and balance.	5w20 Oil Bulk	6.00
- Battery failed load test. Replace battery.	Napagold Oil Filter	1.00
- Test drive.	Napagold Air Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Battery 65	1.00
	235 75r17 Adventure	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 5.50	Labor: 330.00	Parts: 1,145.44
:		Total: 1,475.44

Workorder: 1511977 **Meter:** 50004 **In Date:** 11/24/2015 **Closed:** 12/02/2015
Problem: Pm service,list

- Pm service.	Parts List	Qty
- Rotate and balance tires.	Lamp Assembly	1.00
- Replace broken rr tallight assy.	Blower Motor	1.00
- Replace shorted a/c blower motor.	5w20 Oil Bulk	6.00
- Test drive.	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Air Filter	1.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 264.56
:		Total: 594.56

Workorder: 1602575 **Meter:** 54757 **In Date:** 03/10/2016 **Closed:** 03/15/2016
Problem: needs spare key

- Make and program one spare key	Parts List	Qty
- Shop Supplies	Ford Ignition Key Blank	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 28.61
:		Total: 88.61

Workorder: 1605190 **Meter:** 58759 **In Date:** 05/18/2016 **Closed:** 05/24/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Rotate and balance tires.	5w20 Oil Bulk	6.00
- Repair damaged trailer socket wiring.	Napagold Oil Filter	1.00
- Test drive.	22" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 47.39
:		Total: 287.39

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1612173 **Meter:** 68689 **In Date:** 11/29/2016 **Closed:** 12/15/2016
Problem: P.M. service and towed in for no start.

- P.m. Service.	Parts List	Qty
- Replace broken right tail lamp lens.	5w20 Engine Oil	6.00
- Replace front brake rotors,replace rear.replace front and rear pads.service and lube calipers.flush and bleed system.	Napagold Oil Filter	1.00
- Service transmission.flush and refill system.	Napagold Air Filter	1.00
- Rotate and balance tires.	22" Wiper Blade	2.00
- Shop Supplies	Tail Ligth Ass	1.00
	Front Rotor	2.00
	Brake Pad	1.00
	Pad Brak	1.00
	Syn-atf Trans Fluid S	16.00
	Screen Asy	1.00
	Shop Supplies	1.00
Hours 13.00	Labor: 780.00	Parts: 642.95
:		Total: 1,422.95

Workorder: 1612245 **Meter:** 68294 **In Date:** 11/29/2016 **Closed:** 11/30/2016
Problem: no start

- Tow From: 8100 forrst hill To: 2601 vista	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1700662 **Meter:** 69927 **In Date:** 01/23/2017 **Closed:** 02/06/2017
Problem: A/C not working.

- Check a/c system performnce. System pressures ok.blower motor speed intermittent.	Parts List	Qty
- Replace shorted blower motor,blower resistor and A/c control module. Reflash new module.	Blower Motor	1.00
- Shop Supplies	Blower Motor Resistor	1.00
	Module Control	1.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 398.18
:		Total: 698.18

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706239 **Meter:** 74172 **In Date:** 06/23/2017 **Closed:** 07/31/2017
Problem: P.M. Seervice.Check wiper operation.

<ul style="list-style-type: none"> - P.m. Service. - Pressure test and inspect cooling system.flush and refill system. - Replace broken right rear light lens. - Diagnose wiper intermitten operation.replace defective wiper switch.replace inop washer pump. - Replace two tires,rotate and balance all four. - Replace leaking pinnion seal.service and refill rear differential. - Complete wheel alignment.test drive. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>5w20 Engine Oil</td><td></td><td align="right">6.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>22" Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Used Fire X Refurbished</td><td></td><td align="right">1.00</td></tr> <tr><td>Anti Freeze Motorcraft</td><td></td><td align="right">2.00</td></tr> <tr><td>Tail Ligth Ass</td><td></td><td align="right">1.00</td></tr> <tr><td>Switch</td><td></td><td align="right">1.00</td></tr> <tr><td>235 75r17 Adventure</td><td></td><td align="right">2.00</td></tr> <tr><td>Pump Motor</td><td></td><td align="right">1.00</td></tr> <tr><td>Seal Asy</td><td></td><td align="right">1.00</td></tr> <tr><td>Kit Spac</td><td></td><td align="right">1.00</td></tr> <tr><td>75w140 Ford Axle Lube</td><td></td><td align="right">2.00</td></tr> <tr><td>Ptex Ultra Grey 3oz</td><td></td><td align="right">1.00</td></tr> <tr><td>Friction Modifier</td><td></td><td align="right">2.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">2.00</td></tr> </tbody> </table>	Parts List		Qty	5w20 Engine Oil		6.00	Napagold Oil Filter		1.00	22" Wiper Blade		2.00	Used Fire X Refurbished		1.00	Anti Freeze Motorcraft		2.00	Tail Ligth Ass		1.00	Switch		1.00	235 75r17 Adventure		2.00	Pump Motor		1.00	Seal Asy		1.00	Kit Spac		1.00	75w140 Ford Axle Lube		2.00	Ptex Ultra Grey 3oz		1.00	Friction Modifier		2.00	Shop Supplies		1.00	Tire Disposal Fee		2.00	
Parts List		Qty																																																			
5w20 Engine Oil		6.00																																																			
Napagold Oil Filter		1.00																																																			
22" Wiper Blade		2.00																																																			
Used Fire X Refurbished		1.00																																																			
Anti Freeze Motorcraft		2.00																																																			
Tail Ligth Ass		1.00																																																			
Switch		1.00																																																			
235 75r17 Adventure		2.00																																																			
Pump Motor		1.00																																																			
Seal Asy		1.00																																																			
Kit Spac		1.00																																																			
75w140 Ford Axle Lube		2.00																																																			
Ptex Ultra Grey 3oz		1.00																																																			
Friction Modifier		2.00																																																			
Shop Supplies		1.00																																																			
Tire Disposal Fee		2.00																																																			
Hours 14.50 :	Labor: 870.00	Parts: 863.13	Total: 1,733.13																																																		

Workorder: 1706692 **Meter:** 73997 **In Date:** 07/10/2017 **Closed:** 07/10/2017
Problem: 1 - Wash ticket(s) issued

<ul style="list-style-type: none"> - 1 - Wash ticket(s) issued 			
Hours 0.00 :	Labor: 0.00	Parts: 0.00	Total: 0.00

Workorder: 1801817 **Meter:** 77106 **In Date:** 02/15/2018 **Closed:** 02/27/2018
Problem: P.M. service and left taillight broken.

<ul style="list-style-type: none"> - P.m. service. - Replace two tires.nitrogen fill tires .rotate and high speed balance all four tires. - Replace right rear broken tail lamp lens assembly. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>5w20 Engine Oil</td><td></td><td align="right">6.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>22" Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Napagold Air Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Used Fire X Refurbished</td><td></td><td align="right">1.00</td></tr> <tr><td>235 75r17 Adventure</td><td></td><td align="right">2.00</td></tr> <tr><td>Lamp Assembly</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">2.00</td></tr> </tbody> </table>	Parts List		Qty	5w20 Engine Oil		6.00	Napagold Oil Filter		1.00	22" Wiper Blade		2.00	Napagold Air Filter		1.00	Used Fire X Refurbished		1.00	235 75r17 Adventure		2.00	Lamp Assembly		1.00	Shop Supplies		1.00	Tire Disposal Fee		2.00	
Parts List		Qty																														
5w20 Engine Oil		6.00																														
Napagold Oil Filter		1.00																														
22" Wiper Blade		2.00																														
Napagold Air Filter		1.00																														
Used Fire X Refurbished		1.00																														
235 75r17 Adventure		2.00																														
Lamp Assembly		1.00																														
Shop Supplies		1.00																														
Tire Disposal Fee		2.00																														
Hours 4.80 :	Labor: 288.00	Parts: 589.04	Total: 877.04																													

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808786 **Meter:** 80971 **In Date:** 08/24/2018 **Closed:** 09/04/2018
Problem: PM Service

<ul style="list-style-type: none"> - P.m. service. - Perform Tune up . Replace all six spark plugs .replace upper intake gasket . - Perform engine air intake decarb and flush injectors. - Test and replace broken right tail light lens assembly. - Check battery and charging system . After fully charging battery , battery failed load test . R&r defective battery. - Balance and rotate all four tires. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">6.00</td></tr> <tr><td>Used Fire X Refurbished</td><td></td><td align="right">1.00</td></tr> <tr><td>22" Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Intake Cleaner Kit</td><td></td><td align="right">1.00</td></tr> <tr><td>Gasket</td><td></td><td align="right">1.00</td></tr> <tr><td>Battery</td><td></td><td align="right">1.00</td></tr> <tr><td>Spark Plugs</td><td></td><td align="right">6.00</td></tr> <tr><td>Tail Ligth Ass</td><td></td><td align="right">1.00</td></tr> <tr><td>Injector Cleaner</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Napagold Oil Filter		1.00	5w20 Engine Oil		6.00	Used Fire X Refurbished		1.00	22" Wiper Blade		2.00	Intake Cleaner Kit		1.00	Gasket		1.00	Battery		1.00	Spark Plugs		6.00	Tail Ligth Ass		1.00	Injector Cleaner		1.00	Shop Supplies		1.00
Parts List		Qty																																			
Napagold Oil Filter		1.00																																			
5w20 Engine Oil		6.00																																			
Used Fire X Refurbished		1.00																																			
22" Wiper Blade		2.00																																			
Intake Cleaner Kit		1.00																																			
Gasket		1.00																																			
Battery		1.00																																			
Spark Plugs		6.00																																			
Tail Ligth Ass		1.00																																			
Injector Cleaner		1.00																																			
Shop Supplies		1.00																																			
Hours 9.50 :	Labor: 570.00 Parts: 433.93 Total: 1,003.93																																				

Workorder: 1812690 **Meter:** 82659 **In Date:** 12/03/2018 **Closed:** 12/13/2018
Problem: Locked keys in vehicle (Emergency Service)

<ul style="list-style-type: none"> - Tow From: 4219 Windchester Lane, Wpb 	Hours 0.00 :	Labor: 0.00 Parts: 0.00 Total: 0.00
--	-----------------	---

Workorder: 1902690 **Meter:** 84839 **In Date:** 03/11/2019 **Closed:** 03/22/2019
Problem: P.M. Service.A/C blower inop.

<ul style="list-style-type: none"> - P.m. Service. - Diagnose inop blower motor.replace defective blower motor and resistor. - Rotate and balance tires. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">6.00</td></tr> <tr><td>22" Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Blower Motor</td><td></td><td align="right">1.00</td></tr> <tr><td>Blower Resistor</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Napagold Oil Filter		1.00	5w20 Engine Oil		6.00	22" Wiper Blade		2.00	Blower Motor		1.00	Blower Resistor		1.00	Shop Supplies		1.00
Parts List		Qty																				
Napagold Oil Filter		1.00																				
5w20 Engine Oil		6.00																				
22" Wiper Blade		2.00																				
Blower Motor		1.00																				
Blower Resistor		1.00																				
Shop Supplies		1.00																				
Hours 5.00 :	Labor: 335.00 Parts: 268.79 Total: 603.79																					

Workorder: 1911810 **Meter:** 87920 **In Date:** 11/14/2019 **Closed:** 11/14/2019
Problem: Transition Prep Charge

<ul style="list-style-type: none"> - Transition Prep Charge 	Hours 2.00 :	Labor: 146.00 Parts: 0.00 Total: 146.00
--	-----------------	---