

**Palm Beach County Fleet Management
Asset Maintenance History**

10156435 2005 GMC 1500 Pickup, 1/2 Ton, W/Toolbox

Workorder: 538880 **Meter:** 0 **In Date:** 03/14/2005 **Closed:** 03/14/2005
Problem: TAG CHARGE

| | | | | |
|--------------|-------------|-------------------|--------------|------------|
| - Tag Charge | | Parts List | | Qty |
| | | Tag Charge | | 1.00 |
| Hours 0.00 | Labor: 0.00 | Parts: 51.85 | Total: 51.85 | |
| : | | | | |

Workorder: 542017 **Meter:** 0 **In Date:** 04/15/2005 **Closed:** 04/15/2005
Problem: WASH VEHICLE

| | | | | |
|---------------------------|---------------|-------------|---------------|--|
| - Wash Vehicle | | | | |
| - Pre-delivery Inspection | | | | |
| Hours 2.50 | Labor: 125.00 | Parts: 0.00 | Total: 125.00 | |
| : | | | | |

Workorder: 542341 **Meter:** 0 **In Date:** 04/15/2005 **Closed:** 04/19/2005
Problem: 001 WASH TICKET ISSUED OUT 04/15/05

| | | | | |
|---------------------------------------|-------------|-------------|-------------|--|
| - 001 Wash Ticket Issued Out 04/15/05 | | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 | |
| : | | | | |

Workorder: 555336 **Meter:** 1922 **In Date:** 09/19/2005 **Closed:** 09/21/2005
Problem: P.M.SERVICE

| | | | | |
|-----------------|---------------|-----------------------------|---------------|------------|
| - Pm Service | | Parts List | | Qty |
| - Shop Supplies | | Shop Supplies | | 1.00 |
| | | Ph3506 Oil Filter Wix 51042 | | 1.00 |
| | | 10w30 Motor Oil | | 5.00 |
| Hours 2.00 | Labor: 100.00 | Parts: 12.06 | Total: 112.06 | |
| : | | | | |

Workorder: 642296 **Meter:** 4714 **In Date:** 07/12/2006 **Closed:** 07/17/2006
Problem: P.M.SERVICE

| | | | | |
|-----------------------------------|---------------|---------------------------------------|---------------|------------|
| - Pm Service | | Parts List | | Qty |
| - Service Rear Brakes.test Drive. | | Shop Supplies | | 1.00 |
| - Glue Weather Strip On Tool Box. | | 6678 Air Filter Frm Ca8755a Wix 46678 | | 1.00 |
| - Shop Supplies | | Ph3506 Oil Filter Wix 51042 | | 1.00 |
| | | 09997 Brake Clean | | 1.00 |
| | | 10w30 Motor Oil | | 5.00 |
| | | 81731 Weatherstrip Yellow Adhesive | | 1.00 |
| Hours 3.25 | Labor: 162.50 | Parts: 34.07 | Total: 196.57 | |
| : | | | | |

Workorder: 737200 **Meter:** 7442 **In Date:** 04/16/2007 **Closed:** 04/17/2007
Problem: P.M. SERVICE.VOID VOID VOID

| | | | | |
|------------|-------------|-------------|-------------|--|
| - | | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 | |
| : | | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 737282 **Meter:** 7443 **In Date:** 04/17/2007 **Closed:** 04/23/2007
Problem: PM

| | Parts List | Qty |
|------------------------|------------------------------------|---------------|
| - Pm Service | Shop Supplies | 1.00 |
| - R/r Serpentine Belts | Alt/belt K060930 | 1.00 |
| - Nitro Tires | A/c Belt K040378 | 1.00 |
| - Road Test | Ph3506 Oil Filter Wix 51042 | 1.00 |
| - Shop Supplies | 10w30 Motor Oil | 5.00 |
| | Grease Nlgi 2 | 1.00 |
| | 85/140 Gear Oil Gear Lube | 1.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| Hours 4.00 | Labor: 220.00 | Parts: 108.10 |
| : | | Total: 328.10 |

Workorder: 746256 **Meter:** 8823 **In Date:** 10/25/2007 **Closed:** 10/30/2007
Problem: P.M SERVICE,CHECK ENGINE LIGHT ON

| | Parts List | Qty |
|--|--------------------------------------|---------------|
| - Pm Service | Shop Supplies | 1.00 |
| - Ck Engine Light On Code (p0455 Evap) Diagnosis & Clear Code And Test Run Gas Cap Loose | Ph9837 Oil Filter Wix 51522 | 1.00 |
| - Clean And Readjust Rear Shoes & Drums. | 10020 Injector Cleaner Don't Reorder | 1.00 |
| - High Speed Balance All 4 Tires.nitro Fill | 10w30 Motor Oil | 7.00 |
| - Shop Supplies | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| Hours 5.00 | Labor: 300.00 | Parts: 36.89 |
| : | | Total: 336.89 |

Workorder: 839299 **Meter:** 10934 **In Date:** 06/02/2008 **Closed:** 06/05/2008
Problem: P.M. SERVICE.

| | Parts List | Qty |
|---|--------------------------------------|---------------|
| - Pm Service | Shop Supplies | 1.00 |
| - Service Rear Brakes. | Ph9837 Oil Filter Wix 51522 | 1.00 |
| - Rotate & High Speed Balance Four Tires With Nitorgen Air. Test Drive. | 09997 Brake Clean | 1.00 |
| - Shop Supplies | 10w30 Motor Oil | 5.00 |
| | 10w30 Motor Oil | 1.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| Hours 4.00 | Labor: 240.00 | Parts: 44.27 |
| : | | Total: 284.27 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 932827 **Meter:** 14012 **In Date:** 01/15/2009 **Closed:** 01/27/2009
Problem: P.M SERVICE

| | Parts List | Qty |
|---|---|------------------------------------|
| - Pm Service | | |
| - Mount & Hi Speed Balance Nitrogen Fill 4 New Tires. | Shop Supplies | 1.00 |
| - Transmission Service & Flush W/new Fluid | 6678 Air Filter Frm Ca8755a Wix 46678 | 1.00 |
| - Complete Front End Alignment. | Ph9837 Oil Filter Wix 51522 | 1.00 |
| - Service Rear Brkes. | 10w30 Motor Oil | 10.00 |
| - Shop Supplies | Syn/atf Trans Fluid Synthetic | 14.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| | Tire Disposal Fee | 4.00 |
| | 758508188 245/70r17 Wrg Silent Armor 108t | 4.00 |
| Hours 9.00 | Labor: 540.00 | Parts: 844.05 Total: 1,384.05 |
| : | | |

Workorder: 940270 **Meter:** 14970 **In Date:** 07/06/2009 **Closed:** 07/13/2009
Problem: p.m service

| | Parts List | Qty |
|--|--|----------------------------------|
| - P.m service | | |
| - Test starting & charging system, test & replace battery. | Shop Supplies | 1.00 |
| - Pressure test & inspect cooling system, flush & renew coolant. | Ph9837 Oil Filter Wix 51522 | 1.00 |
| | 10w30 Motor Oil | 6.00 |
| - Service rear drum brakes. | Used Firex Refurbed Fire Extingshers | 1.00 |
| - Rotate & balance all four tires. | Group 78 Battery (acd 78ps) | 1.00 |
| - Shop Supplies | Antifreeze Ext/life All Makes (peak 407) | 2.00 |
| Hours 7.00 | Labor: 420.00 | Parts: 170.99 Total: 590.99 |
| : | | |

Workorder: 1000023 **Meter:** 16326 **In Date:** 01/04/2010 **Closed:** 01/07/2010
Problem: P.M. Service.

| | Parts List | Qty |
|------------------------------------|--------------------------------------|---------------------------------|
| - P.m service. | | |
| - Service rear drum brakes. | Shop Supplies | 1.00 |
| - Rotate & balance all four tires. | Ph9837 Oil Filter Wix 51522 | 1.00 |
| - Shop Supplies | 10w30 Motor Oil | 6.00 |
| | Wd40 Spray Lube Stock# 405540002 | 1.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| Hours 4.00 | Labor: 240.00 | Parts: 49.87 Total: 289.87 |
| : | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1006319 **Meter:** 17403 **In Date:** 06/15/2010 **Closed:** 06/25/2010
Problem: Pm service,also see notes on fuel gauge not accurate.

| | | |
|--|--|---------------|
| - Perform pm service. | Parts List | Qty |
| - Presure test cooling system.replace failed water pump and thermostat with new.flush and renew coolant. | Shop Supplies | 1.00 |
| - Diagnose instrument cluster concern.reprogram cluster asper tsb. to correct . | Ph3506 Oil Filter Wix 51042 | 1.00 |
| - Perform rear drum brakes service and adjust brake shoes. | 10w30 Motor Oil | 6.00 |
| - Shop Supplies | Used Firex Refurbed Fire Extingshers | 1.00 |
| | Antifreeze Ext/life All Makes (peak 407) | 2.00 |
| | Water Pump | 1.00 |
| | Thermostat | 1.00 |
| | Seal | 1.00 |
| Hours 9.50 | Labor: 570.00 | Parts: 234.54 |
| : | | Total: 804.54 |

Workorder: 1008635 **Meter:** 17713 **In Date:** 08/10/2010 **Closed:** 08/18/2010
Problem: Fuel gauge inop.Check wiper blades.

| | | |
|---|------------------------------------|---------------|
| - Diagnose fuel gauge inop.test and replace failed instrument cluster with new and reprogram with tech 2 scan tool. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| | Instrument Cluster | 1.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 297.09 |
| : | | Total: 417.09 |

Workorder: 1013670 **Meter:** 18387 **In Date:** 12/13/2010 **Closed:** 12/27/2010
Problem: Pm service.

| | | |
|---|--------------------------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Test and replace failed right reverse lamp bulb with new. | Shop Supplies | 1.00 |
| - Rotate and balance all four tires. | Ph3506 Oil Filter Wix 51042 | 1.00 |
| - Perform rear drum brakes service and adjust brake shoes. | 10w30 Motor Oil | 5.00 |
| - Shop Supplies | 10w30 Motor Oil | 1.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| | 3157 Tail Light Bulbs | 1.00 |
| Hours 4.50 | Labor: 270.00 | Parts: 37.32 |
| : | | Total: 307.32 |

Workorder: 1106078 **Meter:** 20008 **In Date:** 06/08/2011 **Closed:** 06/20/2011
Problem: Pm service.

| | | |
|--|---------------------------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Test starting and charging system.battery failed load test after recharge.replace failed battery with new. | Shop Supplies | 1.00 |
| - Rotate and balance all four tires. | Ph3506 Oil Filter Wix 51042 | 1.00 |
| - Perform rear drum brake service and adjust brake shoes. | 6678 Air Filter Frm Ca8755a Wix 46678 | 1.00 |
| - Shop Supplies | 10w30 Motor Oil | 6.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| | Group 78 Battery (acd 78ps) | 1.00 |
| Hours 5.00 | Labor: 300.00 | Parts: 151.66 |
| : | | Total: 451.66 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1200028 **Meter:** 21595 **In Date:** 01/03/2012 **Closed:** 01/09/2012
Problem: P.M. service.

| | | |
|---|--------------------------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Rotate and balance all four tires | Shop Supplies | 1.00 |
| - Perform rear drum brake service and adjust brake shoes. | Ph3506 Oil Filter Wix 51042 | 1.00 |
| - Shop Supplies | 10w30 Motor Oil | 6.00 |
| | 1066 White Lithium (crc 05037) | 1.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| Hours 4.00 | Labor: 240.00 | Parts: 35.72 |
| : | | Total: 275.72 |

Workorder: 1209001 **Meter:** 22757 **In Date:** 09/20/2012 **Closed:** 09/28/2012
Problem: P.M. service and detail.

| | | |
|-----------------------------------|--------------------------------------|---------------|
| - P.m. Service. | Parts List | Qty |
| - Rotate and balance all tires. | Shop Supplies | 1.00 |
| - Service and adjust rear brakes. | Ph3506 Oil Filter Wix 51042 | 1.00 |
| - Shop Supplies | 10w30 Motor Oil | 6.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| Hours 4.00 | Labor: 240.00 | Parts: 43.05 |
| : | | Total: 283.05 |

Workorder: 1209312 **Meter:** 22757 **In Date:** 09/28/2012 **Closed:** 09/28/2012
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

| | | | |
|--|-------------|-------------|-------------|
| - 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1303838 **Meter:** 23808 **In Date:** 04/18/2013 **Closed:** 04/24/2013
Problem: P.M. service.

| | | |
|---|-----------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Rotate and balance all four tires. | 10w30 Motor Oil | 5.00 |
| - Perform rear drum brake service and adjust brake shoes. | Napagold Oil Filter | 1.00 |
| - Shop Supplies | Used Firex Refurbed F | 1.00 |
| | 31-22 Wiper Blades 22 | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 4.00 | Labor: 240.00 | Parts: 44.84 |
| : | | Total: 284.84 |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|--|---------------------|----------------------------|---------------------------|
| Workorder: 1309635 | Meter: 24612 | In Date: 09/24/2013 | Closed: 10/08/2013 |
| Problem: Pm service .Belt noise and request for detail vehicle. | | | |
| - P.m. Service. | Parts List | Qty | |
| - Test battery and charging system.replace bad battery. | 10w30 Motor Oil | 5.00 | |
| - Replace both serpentine belts. | Napagold Oil Filter | 1.00 | |
| - Service and adjust rear brakes. | Wiper Blade | 2.00 | |
| - Rotae and balance all tires. | Bat Term Protector | 1.00 | |
| - Shop Supplies | Group 78 Battery | 1.00 | |
| | Serpentine Belt | 1.00 | |
| | Fleetranner Belt | 1.00 | |
| | Shop Supplies | 1.00 | |
| Hours 6.25 | Labor: 375.00 | Parts: 189.17 | Total: 564.17 |
| : | | | |

| | | | |
|--|---------------------|----------------------------|---------------------------|
| Workorder: 1310025 | Meter: 24595 | In Date: 10/03/2013 | Closed: 10/03/2013 |
| Problem: 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| - 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

| | | | |
|---|-------------------------|----------------------------|---------------------------|
| Workorder: 1405475 | Meter: 25717 | In Date: 06/04/2014 | Closed: 06/11/2014 |
| Problem: P.M. Service.Check engine light on. | | | |
| - P.m. Service. | Parts List | Qty | |
| - Diagnose check engine light.p0455.perform evap system bay test.replace defective fuel cap.clear codes and retest. | 10w30 Motor Oil | 6.00 | |
| - Rotate and balance all tires. | Napagold Oil Filter | 1.00 | |
| - Service and adjust rear brakes. | Used Fire X Refurbished | 1.00 | |
| - Shop Supplies | Wiper Blade | 2.00 | |
| | Washer FI | 1.00 | |
| | Gas Cap Non-locking | 1.00 | |
| | Shop Supplies | 1.00 | |
| Hours 6.00 | Labor: 360.00 | Parts: 59.86 | Total: 419.86 |
| : | | | |

| | | | |
|--|-----------------------|----------------------------|---------------------------|
| Workorder: 1412342 | Meter: 26895 | In Date: 12/10/2014 | Closed: 12/30/2014 |
| Problem: Pm service.Headliner falling.Detail. | | | |
| - Pm service. | Parts List | Qty | |
| - Inspect,secure and reglue falling headliner. | 10w30 Motor Oil | 6.00 | |
| - Inspect and service rear drum brakes. | Napagold Oil Filter | 1.00 | |
| - Rotate and balance all four tires. | Wiper Blade | 2.00 | |
| - Shop Supplies | Washer Fluid Concentr | 1.00 | |
| | Bigg Degreaser | 1.00 | |
| | Shop Supplies | 1.00 | |
| Hours 4.50 | Labor: 270.00 | Parts: 38.95 | Total: 308.95 |
| : | | | |

| | | | |
|--|---------------------|----------------------------|---------------------------|
| Workorder: 1412740 | Meter: 26773 | In Date: 12/19/2014 | Closed: 12/19/2014 |
| Problem: 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| - 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|---|---------------------|----------------------------|---------------------------|
| Workorder: 1506996 | Meter: 27500 | In Date: 07/14/2015 | Closed: 07/30/2015 |
| Problem: Pm service.Ac blows hot air.Right side turnsignal inop.Right rear damage.Detail. | | | |
| - P.m. Service. | | Parts List | Qty |
| - Replace right rear signal light bulb and back up light bulb. | | 10w30 Motor Oil | 6.00 |
| - Diagnose a/c,blows hot.b0408..perform pin point test.replace defective blend door actuator.recalibrate. | | Napagold Oil Filter | 1.00 |
| - Rotate and b alance all tires. | | Wiper Blade | 2.00 |
| - Service and adjust rear brakes. | | Used Fire X Refurbished | 1.00 |
| - Shop Supplies | | Bulb | 2.00 |
| | | Actuator | 1.00 |
| | | Shop Supplies | 1.00 |
| Hours 6.00 | Labor: 360.00 | Parts: 295.96 | Total: 655.96 |
| : | | | |
| Workorder: 1508422 | Meter: 27510 | In Date: 07/28/2015 | Closed: 08/21/2015 |
| Problem: damage to rear bumper, rgt rear fender & tail gate | | | |
| - damage to rear bumper, rgt rear fender & tail gate | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |
| Workorder: 1509515 | Meter: 4736 | In Date: 09/21/2015 | Closed: 09/21/2015 |
| Problem: 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| - 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |
| Workorder: 1509564 | Meter: 27510 | In Date: 09/22/2015 | Closed: 09/22/2015 |
| Problem: Transition Prep Charge | | | |
| - Transition Prep Charge | | | |
| Hours 2.00 | Labor: 120.00 | Parts: 0.00 | Total: 120.00 |
| : | | | |
| Workorder: 1600552 | Meter: 29054 | In Date: 01/19/2016 | Closed: 02/16/2016 |
| Problem: pm, flat tire | | | |
| - pm | | Parts List | Qty |
| - flat ire verify front tires worn and dry rot rr all 4 tires | | Napagold Oil Filter | 1.00 |
| - verify turn signals brake light and tail lights out replace multiple bulbs | | 10w30 Bulk Sr | 6.00 |
| - rear brake drum svc | | 22" Wiper Blade | 2.00 |
| - washer resivoir empty and leaking repair leaking hose | | 183114470 P245-70r17 | 4.00 |
| | | Bulb | 2.00 |
| | | Lamp | 1.00 |
| | | Bulb | 3.00 |
| | | Tire Disposal Fee | 4.00 |
| Hours 8.00 | Labor: 480.00 | Parts: 815.54 | Total: 1,295.54 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|---|---------------------|----------------------------|---------------------------|
| Workorder: 1610095 | Meter: 37134 | In Date: 09/27/2016 | Closed: 11/21/2016 |
| Problem: Pm service | | | |
| - Pm service. | | Parts List | Qty |
| - Rear drum service. | | Napagold Oil Filter | 1.00 |
| - Rotate and balance all tires. | | 10w30 Bulk Sr | 6.00 |
| | | Non-chlor Brake Clnr | 1.00 |
| Hours 3.75 | Labor: 225.00 | Parts: 25.59 | Total: 250.59 |
| : | | | |
| Workorder: 1704778 | Meter: 41751 | In Date: 05/12/2017 | Closed: 05/30/2017 |
| Problem: Pm service.Towed in.Flat tire. | | | |
| - Pm Service. | | Parts List | Qty |
| - Verify hood latch on interior broken.r/r cable and handle assm. | | Oil Sensor | 1.00 |
| - Verify airbag light on.scan found code for front left airbag sensor.r/r sensor and clear codes. | | Napagold Air Filter | 1.00 |
| - Verify front pads.turn front rotors.service calipers.replace pads.service rear brake drums>test drive. | | Napagold Oil Filter | 1.00 |
| - Repair left front tire.rotate and balance all four,add N2. | | 10w30 Bulk Sr | 6.00 |
| - Verify oil pressure gauge pinned.trouble shoot.verify bad sending unit.remove intake and repair threads.r/r unit,reassemble and test drive. | | 22" Wiper Blade | 2.00 |
| | | Washer Fluid Concentr | 1.00 |
| | | Used Fire X Refurbished | 1.00 |
| | | Hood release cable asm | 1.00 |
| | | Sensor | 1.00 |
| | | Disc Brake Pads | 1.00 |
| | | Oil Pressure Switch | 1.00 |
| Hours 18.50 | Labor: 1,110.00 | Parts: 583.04 | Total: 1,693.04 |
| : | 0 | | |
| Workorder: 1704889 | Meter: 41668 | In Date: 05/12/2017 | Closed: 05/17/2017 |
| Problem: Flat tire on D/F-PM Service | | | |
| - Tow From: 4976 Bocaire Blvd, Boca Raton To: Sr shop | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |
| Workorder: 1706328 | Meter: 42290 | In Date: 06/27/2017 | Closed: 06/30/2017 |
| Problem: Right front tire flat. | | | |
| - Mount and balance one tire on the right front. | | Parts List | Qty |
| | | 183114470 P245-70r17 | 1.00 |
| | | Tire Disposal Fee | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 205.70 | Total: 265.70 |
| : | | | |
| Workorder: 1706658 | Meter: 42396 | In Date: 07/07/2017 | Closed: 07/12/2017 |
| Problem: Blower motor smoke and stop working. | | | |
| - Diagnose for blower motor inop.found over heated blower resistor and wiring harness.replace blower motor assembly,blower resistor and pig tail harness. | | Parts List | Qty |
| | | Blower Motor | 1.00 |
| | | Resistor | 1.00 |
| | | Connector | 1.00 |
| Hours 2.50 | Labor: 150.00 | Parts: 465.86 | Total: 615.86 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|---|-------------------------|----------------------------|---------------------------|
| Workorder: 1709880 | Meter: 44394 | In Date: 10/10/2017 | Closed: 10/18/2017 |
| Problem: Bad battery.Has to jump start. | | | |
| - Test starting and charging system.replace bad battery. | Parts List | | Qty |
| | Group 78 Battery | | 1.00 |
| Hours 0.75 | Labor: 45.00 | Parts: 110.34 | Total: 155.34 |
| : | | | |
| Workorder: 1712070 | Meter: 44013 | In Date: 12/08/2017 | Closed: 12/28/2017 |
| Problem: PM Service | | | |
| - Pm Service. | Parts List | | Qty |
| - Replaced water pump,thermostet and gasket housing assy.coolant flush service. | Napagold Oil Filter | | 1.00 |
| - Rotate and balance 4 tires. | 10w30 Bulk Sr | | 6.00 |
| - Rear brake service.clean and adjust. | 22" Wiper Blade | | 2.00 |
| - Vacume debris from crawl and air intake. | Washer Fluid Concentr | | 1.00 |
| | New Water Pump | | 1.00 |
| | Thermostat | | 1.00 |
| | Peak Global Antifrz | | 2.00 |
| Hours 9.50 | Labor: 570.00 | Parts: 187.91 | Total: 757.91 |
| : | | | |
| Workorder: 1800488 | Meter: 44203 | In Date: 01/16/2018 | Closed: 01/31/2018 |
| Problem: Flat tire right rear. | | | |
| - Tete damage beyond repair.replace and balance two rear tires. | Parts List | | Qty |
| | 183114470 P245-70r17 | | 2.00 |
| | Tire Disposal Fee | | 2.00 |
| Hours 1.50 | Labor: 90.00 | Parts: 413.44 | Total: 503.44 |
| : | | | |
| Workorder: 1807646 | Meter: 46334 | In Date: 07/27/2018 | Closed: 07/31/2018 |
| Problem: PM Service. | | | |
| - Pm Service. | Parts List | | Qty |
| - Rotate and balance four tires | Used Fire X Refurbished | | 1.00 |
| - Clean and adjust rear brake service. | 10w30 Bulk Sr | | 6.00 |
| - Reglue falling headliner in front and sides. | Napagold Oil Filter | | 1.00 |
| - Vacume debris from engine compartment and air crowl. | Washer Fluid Concentr | | 1.00 |
| | 22" Wiper Blade | | 2.00 |
| Hours 5.50 | Labor: 330.00 | Parts: 44.48 | Total: 374.48 |
| : | | | |
| Workorder: 1810064 | Meter: 47932 | In Date: 09/28/2018 | Closed: 10/30/2018 |
| Problem: Power outlets inop. | | | |
| - Diagnose and replace with new auxiliary power outlet and install fuse holder.make up power and ground harness. | Parts List | | Qty |
| | Fuse Holder | | 1.00 |
| | 12v Power Socket | | 1.00 |
| Hours 2.00 | Labor: 134.00 | Parts: 18.86 | Total: 152.86 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1902065 **Meter:** 49538 **In Date:** 02/25/2019 **Closed:** 03/11/2019
Problem: PM Service.

| | | |
|---|-------------------------|-----------------|
| - Pm Service. | Parts List | Qty |
| - Replace two front tires.rotate and balance all . | Napagold Air Filter | 1.00 |
| - Replace two tag light bulbs and lenses.clean right reverse light socket. | 10w30 Bulk Sr | 6.00 |
| - Clean and adjust rear brake drums. | Napagold Oil Filter | 1.00 |
| - Verify makes noise on turns.disconnect steering shaft,lube and reinstall. | Used Fire X Refurbished | 1.00 |
| - Vacume dirt and debris from engine bay.clean interior and exterior. | Washer Fluid Concentr | 1.00 |
| | 183114470 P245-70r17 | 2.00 |
| | Tag Lamp | 2.00 |
| | Boxed Miniatures | 2.00 |
| | Non-chlor Brake Clnr | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 8.50 | Labor: 569.50 | Parts: 508.41 |
| : | | Total: 1,077.91 |

Workorder: 1903559 **Meter:** 50870 **In Date:** 04/02/2019 **Closed:** 04/15/2019
Problem: Left rear tire flat.

| | | | | |
|--------------------------------------|------------|--------------|-------------|--------------|
| - Repair and balance left rear tire. | Hours 1.00 | Labor: 67.00 | Parts: 0.00 | Total: 67.00 |
| | : | | | |

Workorder: 1908475 **Meter:** 51748 **In Date:** 08/13/2019 **Closed:** 09/30/2019
Problem: Radio inop.

| | | | | |
|---|------------|--------------|-------------|--------------|
| - Diagnose for Am/fm radio inop.verify radio internal failure.not cost effective to repair. | Hours 0.50 | Labor: 33.50 | Parts: 0.00 | Total: 33.50 |
| | : | | | |

Workorder: 1909855 **Meter:** 51748 **In Date:** 09/24/2019 **Closed:** 09/30/2019
Problem: PM Service

| | | | |
|---|-----------------------|--------------|---------------|
| - Pm Service. | Parts List | Qty | |
| - R/r washer pump and line assembly repaired. | Washer Fluid Concentr | 1.00 | |
| - Rear brake service. | 22" Wiper Blade | 1.00 | |
| - Rotate and balance four tires. | W S Wash | 1.00 | |
| - Reinstall radio and cluster bezel. | Napagold Oil Filter | 1.00 | |
| | 10w30 Bulk Sr | 6.00 | |
| Hours 6.75 | Labor: 452.25 | Parts: 45.02 | Total: 497.27 |
| : | | | |

Workorder: 1911073 **Meter:** 51748 **In Date:** 10/25/2019 **Closed:** 10/25/2019
Problem: Transition Prep Charge

| | | | | |
|--------------------------|------------|---------------|-------------|---------------|
| - Transition Prep Charge | Hours 2.00 | Labor: 146.00 | Parts: 0.00 | Total: 146.00 |
| | : | | | |