

**Palm Beach County Fleet Management
Asset Maintenance History**

10155209 2004 GMC 2500 HD Pickup, 3/4 Ton W/Strobe System

Workorder: 438109 **Meter:** 0 **In Date:** 03/16/2004 **Closed:** 03/16/2004
Problem: WASH VEHICLE

- Wash Vehicle
- Pre-delivery Inspection
- Make Duplicate Keys For New Vehicle

Hours 3.10 Labor: 155.00 Parts: 0.00 Total: 155.00
:

Workorder: 438358 **Meter:** 12 **In Date:** 03/17/2004 **Closed:** 03/17/2004
Problem: TAG CHARGE

- Vehicle Tag

Parts List
Vehicle Tag Charge Qty
1.00

Hours 0.00 Labor: 0.00 Parts: 51.85 Total: 51.85
:

Workorder: 547553 **Meter:** 4545 **In Date:** 06/14/2005 **Closed:** 06/20/2005
Problem: P.M.SERVICE/START PROBLEM

- Pm Service
- Check Charging Sys. Recharge Battery.
- Shop Supplies

Parts List
Shop Supplies Qty
1.00
Ph3506 Oil Filter Wix 51042 1.00
10w30 Motor Oil 7.00

Hours 3.25 Labor: 162.50 Parts: 13.46 Total: 175.96
:

Workorder: 550374 **Meter:** 4549 **In Date:** 07/15/2005 **Closed:** 07/18/2005
Problem: WONT START

- Recharge Battery.check Charging Sys. Found Bad Alternator.
- Transport & Pickup Vehicle At Dealer.(defective Alt.)
- Shop Supplies

Parts List
Shop Supplies Qty
1.00

Hours 1.50 Labor: 75.00 Parts: 2.00 Total: 77.00
:

Workorder: 732570 **Meter:** 9522 **In Date:** 01/09/2007 **Closed:** 01/17/2007
Problem: P.M SERVICE,L/S WINDOW HANDLE MISSING

- Pm Service
- Replace Missing Right Front Window Crank.
- Fill Tires With Nitrogen.
- Shop Supplies

Parts List
Shop Supplies Qty
1.00
6678 Air Filter Frm Ca8755a Wix 46678 1.00
Ph3506 Oil Filter Wix 51042 1.00
10w30 Motor Oil 7.00
31-22 Wiper Blades 22" Wiper Blade 2.00
Used Firex Refurbed Fire Extingshers 1.00
15705526 R/front Window Crank Handle 1.00

Hours 4.25 Labor: 233.75 Parts: 65.08 Total: 298.83
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 739164 **Meter:** 13266 **In Date:** 05/29/2007 **Closed:** 05/31/2007
Problem: P.M SERVICE,SEE NOTE

- Perform Pm Service	Parts List	Qty
- Ck Electrical Sys.starter Battery Alternator Found Bad Battery Replace Battery	Shop Supplies	1.00
- Balance All Tires.indext L Front Tire Nitrogen Service.	Ph3506 Oil Filter Wix 51042	1.00
- Stroke Steering Shaft As Per Bulliten E9446	10w30 Motor Oil	6.00
- Shop Supplies	31-22 Wiper Blades 22" Wiper Blade	2.00
	Group 78 Battery (acd 78ps)	1.00
Hours 6.75	Labor: 371.25	Parts: 123.63
:		Total: 494.88

Workorder: 743210 **Meter:** 15935 **In Date:** 08/27/2007 **Closed:** 08/28/2007
Problem: FLAT TIRE.

- Replace All Four Tires And High Speed Balance & Refill With Nitorgen Air,remount Spare.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	4.00
	Tr416 Valve Stem	4.00
	749353434 245/75r16 Wrangler Rt/s E	4.00
Hours 2.00	Labor: 110.00	Parts: 593.51
:		Total: 703.51

Workorder: 747262 **Meter:** 18119 **In Date:** 11/13/2007 **Closed:** 11/15/2007
Problem: P.M. SERVICE.

- Pm Service	Parts List	Qty
- Rotate And Balance All 4 Tires Nitrofill Tires.	Shop Supplies	1.00
- Complete Front End Alignment Test Drive.	A1518c Air Filter	1.00
- Shop Supplies	Ph3506 Oil Filter Wix 51042	1.00
	10020 Injector Cleaner Don't Reorder	1.00
	10w30 Motor Oil	6.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 6.25	Labor: 375.00	Parts: 75.03
:		Total: 450.03

Workorder: 747572 **Meter:** 0 **In Date:** 11/19/2007 **Closed:** 11/20/2007
Problem: 001 WASH TICKET ISSUED OUT 11/19/07

- 001 Wash Ticket Issued Out 11/19/07			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 838828 **Meter:** 22808 **In Date:** 05/21/2008 **Closed:** 05/27/2008
Problem: P.M SERVICE.

- Pm Service	Parts List	Qty
- Service Transmission.flush And Refill	Shop Supplies	1.00
- Complaint:steering Noise.r&r Steerng Intermediate Shaft And Lube To Stop Steering Column Noise.	Ph3506 Oil Filter Wix 51042	1.00
- Shop Supplies	10w30 Motor Oil	6.00
	Syn/atf Trans Fluid Synthetic	16.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 5.25	Labor: 315.00	Parts: 102.65
:		Total: 417.65

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 839556 **Meter:** 0 **In Date:** 06/04/2008 **Closed:** 06/05/2008
Problem: 001 WASH TICKET ISSUED OUT 06/04/08

- 001 Wash Ticket Issued Out 06/04/08

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 844957 **Meter:** 26157 **In Date:** 10/01/2008 **Closed:** 10/02/2008
Problem: R/R TIRE FLAT

- Repair R/r Tire.
 - Shop Supplies

Parts List
 Shop Supplies Qty
 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
 :

Workorder: 933479 **Meter:** 29024 **In Date:** 02/03/2009 **Closed:** 02/12/2009
Problem: P.M SERVICE

- Pm Service
 - R&r Worn Mid Steering Shaft.
 - Pressure Test & Inspect Coolant Sys. Flush And Refill Coolant Sys.
 - Rotate And Hi Speed Balance All 4 Tires.nitro Fill To Specs.
 - Shop Supplies

Parts List
 Shop Supplies Qty
 1.00
 Ph3506 Oil Filter Wix 51042 1.00
 10w30 Motor Oil 6.00
 Used Firex Refurbed Fire Extingshers 1.00
 Intermediate Steering Shaft 1.00
 Antifreeze Ext/life All Makes (peak 407) 2.00

Hours 7.25 Labor: 435.00 Parts: 161.44 Total: 596.44
 :

Workorder: 936432 **Meter:** 30650 **In Date:** 04/13/2009 **Closed:** 04/16/2009
Problem: R/R TIRE HAS NAIL.

- Replace 2 Rear Tires.worn.hi Speed Balance Fill/nitrogen.
 - Shop Supplies

Parts List
 Shop Supplies Qty
 1.00
 Tire Disposal Fee 2.00
 749353434 245/75r16 Wrangler Rt/s E 2.00

Hours 1.50 Labor: 90.00 Parts: 306.36 Total: 396.36
 :

Workorder: 945041 **Meter:** 35748 **In Date:** 10/26/2009 **Closed:** 11/13/2009
Problem: P.M. Service.See notes.

- P.m service.
 - Mount two new tires, rotate & balance all four tires.
 - Test starting & charging system. Battery failed load test,replace defective battery.
 - Test & replace L/r strobe bulb.
 - Alignment.
 - Shop Supplies

Parts List
 Shop Supplies Qty
 1.00
 Ph3506 Oil Filter Wix 51042 1.00
 6678 Air Filter Frm Ca8755a Wix 46678 1.00
 10w30 Motor Oil 6.00
 31-22 Wiper Blades 22" Wiper Blade 2.00
 S30hacp Strobe Bulb For Kit S660cccc 1.00
 Group 78 Battery (acd 78ps) 1.00
 179747492 Lt245/75r16 Wrangler Sr-a E 2.00
 Tr416 Valve Stem 2.00
 Tire Disposal Fee 2.00

Hours 8.75 Labor: 525.00 Parts: 516.32 Total: 1,041.32
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1003639 **Meter:** 39435 **In Date:** 04/08/2010 **Closed:** 04/20/2010
Problem: P.M service, check odometer inop & doors won't open.

	Parts List	Qty
- P.m service.		
- Diagnose speedometer not working, R&r instrument cluster & reprogram cluster.	Shop Supplies	1.00
- Service rear differential.	Ph3506 Oil Filter Wix 51042	1.00
- Remove both door panels I inspect lock & linkages,repair & adjust linlage on both door latches.	12345841 Gear Oil Synthetic 75w-90	3.00
- Test & replace L/r brake light bulb & third brake lamp bulb.	10w30 Motor Oil	6.00
- Shop Supplies	Dash Cluster / 15114649	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Hours 10.25 Labor: 615.00 Parts: 496.90 Total: 1,111.90	
:		

Workorder: 1012905 **Meter:** 43623 **In Date:** 11/18/2010 **Closed:** 11/30/2010
Problem: Pm service.Also see notes on flat tire.

	Parts List	Qty
- P.m. Service.		
- Replace serpentine beltand clean all pulleys.	Shop Supplies	1.00
- Replace both bump stoppers.	K060930hd Belt	1.00
- Repair L/f tire.rotate and balance all tires.	K040378hd A/c Belt	1.00
- Shop Supplies	Ph3506 Oil Filter Wix 51042	1.00
	6678 Air Filter Frm Ca8755a Wix 46678	1.00
	10w30 Motor Oil	6.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	Lower Control Arm Stop Bumper	2.00
	Hours 6.25 Labor: 375.00 Parts: 190.19 Total: 565.19	
:		

Workorder: 1013522 **Meter:** 43623 **In Date:** 12/08/2010 **Closed:** 01/19/2011
Problem: replace driver mirror

	Parts List	Qty
- replace drivers side mirror		
- Shop Supplies	Shop Supplies	1.00
	Drive Side Mirror Assy	1.00
	Hours 1.00 Labor: 60.00 Parts: 124.07 Total: 184.07	
:		

Workorder: 1013654 **Meter:** 43641 **In Date:** 11/29/2010 **Closed:** 12/13/2010
Problem: damage to frt grille

- damage to frt grille				
	Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00			
:				

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1105812 **Meter:** 46467 **In Date:** 06/01/2011 **Closed:** 06/20/2011
Problem: Pm service and ratching noise from under right side of dash.

- Perform pm service.	Parts List	Qty
- Inspect for oil leak.remove engine oil cooler line and replace failed flange gasket with new.	Shop Supplies	1.00
- Install two new tires to the front wheels.nitrogen fill and balance all four.	Ph3506 Oil Filter Wix 51042	1.00
- Diagnose for noise under dash.test and replace failed blend door actuator with new.	10w30 Motor Oil	6.00
- Perform wheel alignment complete.	31-22 Wiper Blades 22" Wiper Blade	2.00
- Shop Supplies	Used Firex Refurbed Fire Extingshers	1.00
	A/c Blend Door Motor	1.00
	Oil Line Gasket	1.00
	179747492 Lt245/75r16 Wrangler Sr-a E	2.00
	Tire Disposal Fee	2.00
	Tr416 Valve Stem	2.00
Hours 10.00	Labor: 600.00	Parts: 597.69
:		Total: 1,197.69

Workorder: 1112318 **Meter:** 49435 **In Date:** 11/17/2011 **Closed:** 11/29/2011
Problem: Pm service.Check tires,stroke lights and wipers see notes.

- Perform pm service.	Parts List	Qty
- Test and replace failed left rear strobe lamp bulb with new.replace broken tag lamp with new.	Shop Supplies	1.00
- Test starting and charging system.battery failed load test after recharge.replace failed battery with new.	Ph3506 Oil Filter Wix 51042	1.00
- Install two new tires to the front wheels.nitrogen fill and balance all four.	10w30 Motor Oil	6.00
- Shop Supplies	31-22 Wiper Blades 22" Wiper Blade	2.00
	S30hacp Strobe Bulb For Kit S660cccc	1.00
	15082619 Tag Light (gmc)	1.00
	Group 78 Battery (acd 78ps)	1.00
	179747492 Lt245/75r16 Wrangler Sr-a E	2.00
	Tire Disposal Fee	2.00
Hours 6.50	Labor: 390.00	Parts: 525.29
:		Total: 915.29

Workorder: 1202279 **Meter:** 51100 **In Date:** 03/06/2012 **Closed:** 03/13/2012
Problem: Left side reverse light out and brake lights flicker.

- Repair tail light wiring.replace back up light bulb.	Parts List	Qty
- Replace missing front asset numbers.	Shop Supplies	1.00
- Shop Supplies	3157 Tail Light Bulbs	2.00
Hours 1.50	Labor: 90.00	Parts: 3.22
:		Total: 93.22

Workorder: 1204582 **Meter:** 52378 **In Date:** 05/15/2012 **Closed:** 05/17/2012
Problem: Left rear strobe light inop.

- Replace left rear strobe light bulb.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	S30hacp Strobe Bulb For Kit S660cccc	1.00
Hours 0.50	Labor: 30.00	Parts: 46.97
:		Total: 76.97

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1208131 **Meter:** 54398 **In Date:** 08/29/2012 **Closed:** 09/17/2012
Problem: P.M. service and check engine light on.

- P.m. Service.	Parts List	Qty
- Diagnose check engine light.r&r intake manifold and replace both knock sensors.clear codes and test drive.	Shop Supplies	1.00
- Rotate and balance all tires.	Ph3506 Oil Filter Wix 51042	1.00
- Shop Supplies	6678 Air Filter Frm Ca8755a Wix 46678	1.00
	10w30 Motor Oil	6.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	Knock Sensor Harness	1.00
	Knock Sensor	2.00
Hours 8.75	Labor: 525.00	Parts: 200.88
:		Total: 725.88

Workorder: 1300543 **Meter:** 56342 **In Date:** 01/15/2013 **Closed:** 01/17/2013
Problem: Check engine light on.

- Diagnose check engine light.p0174,p0171.perform pin point test.repair Pcv Tube.clear codes,reset Kam and test drive.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 2.00
:		Total: 182.00

Workorder: 1307283 **Meter:** 57585 **In Date:** 07/22/2013 **Closed:** 08/21/2013
Problem: P.M. service and headliner falling and left front seat bottom hole in it.

- P.m. Service.	Parts List	Qty
- R&r driver seat for repair.secure headliner.	10w30 Motor Oil	6.00
- Diagnose and replace failed left door speaker.	Napagold Oil Filter	1.00
- Replace two tires,rotate and balance all four.	Wiper Blade	2.00
- Shop Supplies	Washer FI	1.00
	Used Fire X Refurbished	1.00
	08088 Adhesive Trim S	1.00
	Speaker	1.00
	179747492 Lt245-75r16	2.00
	Tr416 Valve Stem	2.00
	Seat R And R	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.75	Labor: 405.00	Parts: 887.69
:		Total: 1,292.69

Workorder: 1311308 **Meter:** 59669 **In Date:** 11/07/2013 **Closed:** 11/19/2013
Problem: Towed in for start.

- Test battery and charging system.replace bad battery.	Parts List	Qty
- Replace defective starter.	Group 78 Battery	1.00
- Shop Supplies	New Starter	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 285.74
:		Total: 405.74

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1311745 **Meter:** 59669 **In Date:** 11/06/2013 **Closed:** 11/21/2013
Problem: wont start, tried to jump and still not turning over

- Tow From: Croc-behind O&m building To: Vista

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1401058 **Meter:** 60280 **In Date:** 01/31/2014 **Closed:** 02/19/2014
Problem: Pm service and power outlets inop

- P.m. Service. **Parts List** **Qty**

- Test and replace power outlet.install etra outlet and fabricate and install wiring. 10w30 Motor Oil 6.00

- Rotate and balance all tires. Napagold Oil Filter 1.00

- Shop Supplies Wiper Blade 2.00

 Fuse Holder 1.00

 Cig Retainer Clip 1.00

 25774623 Receptacle P 1.00

 P Outlet 1.00

 Shop Supplies 1.00

Hours 5.75 Labor: 345.00 Parts: 49.93 Total: 394.93
:

Workorder: 1402658 **Meter:** 60709 **In Date:** 03/19/2014 **Closed:** 03/20/2014
Problem: Mount computer stand and fabericate braket for GPS antena.

- Assemble and install costomer supplied computer stand. **Parts List** **Qty**

- Shop Supplies Shop Supplies 1.00

Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00
:

Workorder: 1402751 **Meter:** 60709 **In Date:** 03/21/2014 **Closed:** 03/25/2014
Problem: Install GPS Holder

- Install Gps holder **Parts List** **Qty**

- Shop Supplies Shop Supplies 1.00

 2" Alum Pipe X 20' 5.00

Hours 3.00 Labor: 180.00 Parts: 15.29 Total: 195.29
:

Workorder: 1406293 **Meter:** 61822 **In Date:** 06/26/2014 **Closed:** 06/26/2014
Problem: Not running, also door hinge is broken

- Tow From: Croc, O&m building To: Vista

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1406367 **Meter:** 61952 **In Date:** 06/27/2014 **Closed:** 07/10/2014
Problem: Towed in for no stay running.and driver door stop

- Computer diagnose for stalling.fuel pressure test and remove fuel tank.replace failed fuel pump assembly with new.clean fuel tank and lines.roadtest. **Parts List** **Qty**

- Cut off failed driver door hinges.fabricate and install new upper and lower driver door hinges and door stop then adjust to open and close. Module 1.00

- Shop Supplies Pin Kit 2.00

 Pin Kit 1.00

 door ckeck 1.00

 Shop Supplies 1.00

Hours 7.50 Labor: 450.00 Parts: 831.55 Total: 1,281.55
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1408402 **Meter:** 62297 **In Date:** 08/12/2014 **Closed:** 08/22/2014
Problem: Winch out

- Tow From: 119 Urquhart St (lw Rd east of Mil)

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1412339 **Meter:** 64050 **In Date:** 12/10/2014 **Closed:** 12/29/2014
Problem: Pm service.Check tires,washer fluid and strobe lights inop.

- Pm service.	Parts List	Qty
- Replace defective left front and rear strobe lamp bulbs	10w30 Motor Oil	6.00
- Replace two tires.rotate and balance all four tires.	Napagold Oil Filter	1.00
- Replace defective hydraulic brake booster due to oil leak.	Wiper Blade	2.00
- Pressure test and inspect cooling system.replace leaking radiator.reverse flush and renew engine coolant.	Used Fire X Refurbished	1.00
- Complete front end alignment and roadtest.	Hide Away Strob	2.00
- Shop Supplies	Lt245 75r16 Mich Ltx Ms2	2.00
	Reman Brake Booster	1.00
	Pwr Steering Fl-quart	1.00
	Peak Global	2.00
	Radiator	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Hours 14.50 Labor: 870.00 Parts: 1,205.78 Total: 2,075.78
:

Workorder: 1500553 **Meter:** 64484 **In Date:** 01/15/2015 **Closed:** 01/22/2015
Problem: PIN FOR HITCH MISSING

- ck pin for hitch install pintle pin	Parts List	Qty
	Pintle Pin W/chain	1.00

Hours 0.25 Labor: 15.00 Parts: 2.61 Total: 17.61
:

Workorder: 1506929 **Meter:** 68628 **In Date:** 07/13/2015 **Closed:** 08/10/2015
Problem: Pm service.Strobe light inop.Stalls.

- P.m. Service.	Parts List	Qty
- Diagnose inop strobe lights.re[place and rewire defective cotroller unit.	10w30 Motor Oil	6.00
- Test battery and charging system.replace bad battery.	Napagold Oil Filter	1.00
- Replace two tires,rotate and balance all four.	Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Group 78 Battery	1.00
	Lt245 75r16	2.00
	Strobe Lamp Controller	1.00
	Ds317 Rocker Switch R	1.00
	Adapter Harness	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00

Hours 7.75 Labor: 465.00 Parts: 916.07 Total: 1,381.07
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1508225 **Meter:** 68850 **In Date:** 08/17/2015 **Closed:** 08/27/2015
Problem: Headliner falling.Strong glue odor.Check ac mode door functions.

- Computer diagnose Hvac doors.replace defective left temperature blend door actuator and recalibrate all door actuators.	Parts List	Qty
	Actuator	3.00
	Shop Supplies	1.00
- Locate smell.rusted punctured paint can behind driver seat.remove trim to clean up area.reg glue head liner.		
- Shop Supplies		
Hours 4.00	Labor: 240.00	Parts: 734.42
:		Total: 974.42

Workorder: 1509677 **Meter:** 69176 **In Date:** 09/24/2015 **Closed:** 09/29/2015
Problem: Right front tire flat,.DRL lights inop.

- Test and replace defective right side Drl lamp bulb.	Parts List	Qty
- Repair and balance right front tire.	Signal Stop Lamp	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 3.76
:		Total: 93.76

Workorder: 1510404 **Meter:** 69284 **In Date:** 10/14/2015 **Closed:** 10/14/2015
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 120.00	Parts: 0.00
:		Total: 120.00

Workorder: 1511976 **Meter:** 70461 **In Date:** 11/24/2015 **Closed:** 12/10/2015
Problem: Running hot.

- Replace leaking water pump and hoses.	Parts List	Qty
- Test drive.	New Water Pump	1.00
	Thermostat	1.00
	Curved Radiator Hose	1.00
	Curved Radiator Hose	1.00
	hose	1.00
	Clamp	1.00
	Connector	1.00
	Peak Global	2.00
Hours 4.50	Labor: 270.00	Parts: 376.59
:		Total: 646.59

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1606135 **Meter:** 77083 **In Date:** 06/15/2016 **Closed:** 06/16/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Rotate and balance tires.	Fleetranner Belt	1.00
- Replace broken fan belt,belt tensioner and idler pulley.	Dr Blt Tensioner Assy	1.00
- Test drive.	Idler Pulley	1.00
	Napa 10w30 Qt	6.00
	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
	Brake Cleaner	2.00
	Washer Fluid Concentr	1.00
Hours 6.25	Labor: 375.00	Parts: 159.15
:		Total: 534.15

Workorder: 1606295 **Meter:** 77536 **In Date:** 06/20/2016 **Closed:** 06/20/2016
Problem: Fan belt

- Tow From: Gua yard To: Pa shop	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1608122 **Meter:** 79345 **In Date:** 08/08/2016 **Closed:** 08/15/2016
Problem: Heater hose leaking

- Replace leaking heater hose. Top off coolant.	Parts List	Qty
- Test drive 2x's.	Peak Global Antifrz	2.00
- Check engine light on. Po300 present. Replace spark plugs and plug wires.	Spark Plug Asm	8.00
	Sensor	1.00
- Replace damaged coolant temp. sensor and temp. sensor connector.	Connector	1.00
	Premium Plug Wire Set	1.00
Hours 5.00	Labor: 300.00	Parts: 228.03
:		Total: 528.03

Workorder: 1612869 **Meter:** 80232 **In Date:** 12/15/2016 **Closed:** 12/29/2016
Problem: Pm service,a/c .

- Pm service.	Parts List	Qty
- A/c blowing warm Replace leaking Hs line from evap. to condensor. Evacuate and refill A/c system.	Tube	1.00
	Accumulat	1.00
- Won't start. Battery failed load test. Replace battery	Napa 10w30 Qt	6.00
- Rotate and balance tires.	Napagold Oil Filter	1.00
- Test drive.	22" Wiper Blade	2.00
	Battery	1.00
	Freon Pahokee Shop	2.00
Hours 7.75	Labor: 465.00	Parts: 282.50
:		Total: 747.50

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1703861 **Meter:** 83501 **In Date:** 04/17/2017 **Closed:** 04/24/2017
Problem: Repair front end damage

- Replace damaged front grill, headlight and turn signal assys.	Parts List	Qty
	Grill Front	1.00
- Battery failed load test. Replace battery	Headlamp Assy Dr	1.00
	Lamp	1.00
	Battery	1.00
	Lapm Ass	1.00
	Pass Side Headlamp Assy	1.00
Hours 5.00	Labor: 300.00	Parts: 1,388.40
:		Total: 1,688.40

Workorder: 1705925 **Meter:** 85777 **In Date:** 06/15/2017 **Closed:** 06/20/2017
Problem: Pm service.

- Pm service.	Parts List	Qty
	Used Fire X Refurbished	1.00
	Napagold Air Filter	1.00
	Pintle Pin W/clip	1.00
	Napa 10w30 Qt	6.00
	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
Hours 2.75	Labor: 165.00	Parts: 61.47
:		Total: 226.47

Workorder: 1707053 **Meter:** 85777 **In Date:** 07/19/2017 **Closed:** 07/24/2017
Problem: Won't start.

- Charge and load test battery. Battery passed load test.
Check charging system. Charging system working ok.

Hours 1.00	Labor: 60.00	Parts: 0.00	Total: 60.00
:			

Workorder: 1711212 **Meter:** 86860 **In Date:** 11/14/2017 **Closed:** 12/19/2017
Problem: Won't start.

- Diagnose battery draw. Check power circuits for draw with key off. Radio draining battery/ is faulty. Unplugged radio.

Hours 4.00	Labor: 240.00	Parts: 0.00	Total: 240.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1802773 **Meter:** 88939 **In Date:** 03/14/2018 **Closed:** 03/20/2018
Problem: Pm service, oil leak

- Pm service.	Parts List	Qty
- Replace worn front tires.	Pressure Hose	1.00
- Rotate and balance tires.	Napa 10w30 Qt	6.00
- Replace leaking power steering hose.	Napagold Oil Filter	1.00
- Test drive.	Napagold Air Filter	1.00
	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Lt245 75r16	2.00
Hours 5.75	Labor: 345.00	Parts: 494.61
:		Total: 839.61

Workorder: 1810740 **Meter:** 94625 **In Date:** 10/18/2018 **Closed:** 10/24/2018
Problem: Pm service, list.

- Pm service.	Parts List	Qty
- Repelace worn front tires.	Napagold Oil Filter	1.00
- Power steering cooler leaking. Replace power steering cooler.	Napa 10w30 Qt	6.00
- Shift lever not releasing properly. Replaced sticking shift lock actuator.	Napagold Air Filter	1.00
- Replace worn brake pads front and rear.	22" Wiper Blade	2.00
- Clean vehicle.	Lt245 75r16	2.00
- Test drive.	Non-chlor Brake Clnr	2.00
- Replaced shorted Lr taillight. Replaced shorted fuse for Obd connector.	Syn Atf Bulk Pahokee	4.00
	Steering Oil Cooler	1.00
	Interlock Solenoid	1.00
	Brake Pad Set	1.00
	Pads	1.00
	Tire Disposal Fee	2.00
Hours 12.75	Labor: 854.25	Parts: 851.68
:		Total: 1,705.93

Workorder: 1902146 **Meter:** 95725 **In Date:** 02/26/2019 **Closed:** 03/04/2019
Problem: Power steering leak.

- Replaced leaking power steering gearbox and hose.	Parts List	Qty
- Wash vehicle.	Syn Atf Bulk Pahokee	3.00
- Clear Abs and brake dtc's related to low hydrobooster fluid level.	Non-chlor Brake Clnr	2.00
- Test drive to check for leaks.	P/s Pressure Hose	1.00
	Gear Box A/c Delco	1.00
Hours 6.00	Labor: 402.00	Parts: 672.60
:		Total: 1,074.60

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1906515 **Meter:** 99137 **In Date:** 06/20/2019 **Closed:** 07/01/2019

Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace shorted washer pump.	Napagold Oil Filter	1.00
- Replace leaking oil pan gasket.	Napa 10w30 Qt	6.00
- R&r headliner for recovering. Replace worn steering wheel.	Washer Fluid Concentr	1.00
- Replace worn ds door hinge bushings and pins.	22" Wiper Blade	2.00
- Rotate and balance tires.	Used Fire X Refurbished	1.00
- Test drive.	W S Wash	1.00
	Oil Pan Gasket Set	1.00
	Steering Wheel	1.00
	Door Hinge Pin Kit	2.00
	Headliner Replace	1.00

Hours 10.75 Labor: 720.25 Parts: 785.64 Total: 1,505.89

:

Workorder: 1911792 **Meter:** 102351 **In Date:** 11/14/2019 **Closed:** 11/14/2019

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00

: