

**Palm Beach County Fleet Management
Asset Maintenance History**

10189092 2013 FORD TRANSIT CONNECT Mini Van, Animal Care

Workorder: 1304971 **Meter:** 331 **In Date:** 05/20/2013 **Closed:** 05/20/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1308027 **Meter:** 6145 **In Date:** 08/12/2013 **Closed:** 08/30/2013
Problem: Pm service.

- P.m. Service.

- Replace missing grill in front bumper

- Rotate and balance all tires.

- Shop Supplies

Parts List

	Qty
Grille	1.00
5w20 Engine Oil	5.00
Napagold Oil Filter	1.00
Plug	2.00
Screw Set	1.00
Shop Supplies	1.00

Hours 3.50 Labor: 210.00 Parts: 179.68 Total: 389.68
:

Workorder: 1309325 **Meter:** 6645 **In Date:** 09/13/2013 **Closed:** 09/19/2013
Problem: Both power outlet fuses open.

- Test for short circuit and replace both open 20 amp fuses with new.advise to try new charger.

Hours 0.50 Labor: 30.00 Parts: 0.00 Total: 30.00
:

Workorder: 1309537 **Meter:** 6673 **In Date:** 09/20/2013 **Closed:** 09/26/2013
Problem: Door ajar warning light on and signal indiactor flashing on dash.

- Diagnose with Ids for door ajar warning light on.test and replace failed right side sliding door pin switch with new and adjust to correct concern.

- Shop Supplies

Parts List

	Qty
Switch	1.00
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 31.78 Total: 91.78
:

Workorder: 1311403 **Meter:** 7159 **In Date:** 10/15/2013 **Closed:** 11/12/2013
Problem: damage to rear bumper, light & lft rear corner

- damage to rear bumper, light & lft rear corner

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1402458 **Meter:** 12798 **In Date:** 03/13/2014 **Closed:** 03/20/2014
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace right head light bulb.	Napagold Oil Filter	1.00
- Diagnose nise coming from engine area.replace defective belt tensioner.	5w20 Engine Oil	5.00
	Accufit Conventional	1.00
- Rotate and balance all tires.	Exact Fit Blade	1.00
- Service and adjust rear brakes.	bulb	1.00
- Shop Supplies	Belt Tensioner	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 151.03
:		Total: 511.03

Workorder: 1407464 **Meter:** 19757 **In Date:** 07/30/2014 **Closed:** 08/19/2014
Problem: Pm service.

- Pm service.	Parts List	Qty
- Inspect for winding noise in belt area and replace belt idler pulley due to noisy bearing.	Screw Set	4.00
	Grille	1.00
- Install front brake pads and two front brake rotors.service calipers and perform rear drum brake service.bleed hydraulic system and roadtest.	Bumper Asy	1.00
	Accufit Conventional	1.00
- Inspect and replace cracked front bumper cover.	5w20 Engine Oil	5.00
- Replace open left front park lamp bulb.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	Blade Asy	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Tensioner	1.00
	Brake Pads	1.00
	Bulb	1.00
	Shop Supplies	1.00
Hours 10.50	Labor: 630.00	Parts: 608.65
:		Total: 1,238.65

Workorder: 1408846 **Meter:** 20301 **In Date:** 09/02/2014 **Closed:** 09/03/2014
Problem: Flat tire on R/P

- Tire Service 7100 Belveder (animal Care) - Flat tire on R/p			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1408935 **Meter:** 20474 **In Date:** 09/04/2014 **Closed:** 09/15/2014
Problem: Right rear tire flat.Cannot find jack and handle after spare tire was put on by road service.

- Replace tire on spare wheel,mount spare tire on right rear wheel and balance both.replace missing jack and handle.mount under front seat.	Parts List	Qty
	Wrench Jack	1.00
- Shop Supplies	Jack	1.00
	P205/65r15 Assurance	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 1.50	Labor: 90.00	Parts: 377.02
:		Total: 467.02

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1410542 **Meter:** 21577 **In Date:** 10/20/2014 **Closed:** 10/22/2014
Problem: Flat tire on Front

- Tire Service Animal Care - Flat tire on Front

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1500702 **Meter:** 26513 **In Date:** 01/21/2015 **Closed:** 02/05/2015
Problem: Pm service

- P.m. Service.

- Repair one tire and replace one.rotate and balance all four.

- Service and adjust rear brakes.

- Shop Supplies

Parts List

	Qty
5w20 Engine Oil	5.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Accufit Conventional	1.00
Exact Fit Blade	1.00
P205/65r15 Assurance	1.00
Tpms12 Sensor Tire Pr	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours 5.75 Labor: 345.00 Parts: 256.12 Total: 601.12
:

Workorder: 1504010 **Meter:** 30957 **In Date:** 04/17/2015 **Closed:** 04/29/2015
Problem: Battery has to be jump started every time.

- Test battery and charging system.recharge and retest battery,fail load test.replace defectiver battery.

- Shop Supplies

Parts List

	Qty
Bxt96r 59	1.00
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 145.27 Total: 205.27
:

Workorder: 1505166 **Meter:** 32137 **In Date:** 05/21/2015 **Closed:** 05/29/2015
Problem: Pm service

- Pm service.

- Replace two tires.rotate and balance four.

- Inspect and service rear brakes.

- Complete front end alignment.

- Shop Supplies

Parts List

	Qty
5w20 Engine Oil	5.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
P205/65r15 Assurance	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 8.25 Labor: 495.00 Parts: 279.32 Total: 774.32
:

Workorder: 1505852 **Meter:** 33275 **In Date:** 06/11/2015 **Closed:** 06/25/2015
Problem: Tow in,no power.

- Computer diagnose for no power.code P2112 Perform pin point test and replace defective trottle body.clear code and retest.

- Shop Supplies

Parts List

	Qty
Throttle Body	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 375.35 Total: 555.35
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1505946	Meter: 33151	In Date: 06/11/2015	Closed: 06/15/2015
Problem: lack of power			
- Tow From: st davids way/ wellington trace			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1507555	Meter: 35015	In Date: 07/29/2015	Closed: 08/14/2015
Problem: A/c warm at idle.			
- Transport vehicle to and from dealer for a/c warranty.			
Parts List			
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1510504	Meter: 38730	In Date: 10/16/2015	Closed: 11/03/2015
Problem: Pm service.			
- Pm service.			
Parts List			
- Replace two tires.rotate and balance all four.	5w20 Engine Oil		5.00
- Inspect and service rear brakes.	Napagold Oil Filter		1.00
- Shop Supplies	Exact Fit Blade		1.00
	Accufit Conventional		1.00
	P205/65r15 Assurance		2.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 5.75	Labor: 345.00	Parts: 296.54	Total: 641.54
:			
Workorder: 1512006	Meter: 39830	In Date: 11/25/2015	Closed: 11/30/2015
Problem: Tire pressure light flashing.			
- Left rear tire pressure sensor failed.replace defective sensor and balance tire.			
Parts List			
- Shop Supplies	Tpms12 Sensor Tire Pr		1.00
	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 83.71	Total: 143.71
:			
Workorder: 1602800	Meter: 44196	In Date: 03/17/2016	Closed: 03/31/2016
Problem: Pm service.Check temperature gauge in side truck.			
- Pm service.			
Parts List			
- In car temperature gauge inop.trace wiring circuit.check resistance.r&i headliner and sun visor necessary to replace defective assembly and locate incar/ outside sensor probe.	5w20 Engine Oil		5.00
	Napagold Oil Filter		1.00
- Rotate and balance all four tires.	Exact Fit Blade		1.00
- Inspect and service rear brakes.	Accufit Conventional		1.00
- Shop Supplies	Washer Fluid Concentr		1.00
	Pawer Steering Fluid		1.00
	In Car Temperture Guage		1.00
	Shop Supplies		1.00
	Freight Charge		1.00
Hours 6.75	Labor: 405.00	Parts: 75.75	Total: 480.75
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1605232 **Meter:** 47780 **In Date:** 05/19/2016 **Closed:** 05/27/2016
Problem: TPMS light on.

- Diagnose and replace defective right rear Tpms sensor. **Parts List** **Qty**
- Shop Supplies Tpms12 Sensor Tire Pr 1.00
Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 83.71 Total: 143.71
:

Workorder: 1605811 **Meter:** 48892 **In Date:** 06/06/2016 **Closed:** 06/15/2016
Problem: Right rear tail light lens broken and bumper cover.

- R&r broken right tail light assemble.fabricate and install **Parts List** **Qty**
strobe light.replace bumper cap. Lamp Asy 1.00
- Shop Supplies Bumper Cover 1.00
Clip 1.00
Clr Rtv Silcn Sealant 1.00
Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 279.31 Total: 339.31
:

Workorder: 1606255 **Meter:** 50101 **In Date:** 06/20/2016 **Closed:** 07/08/2016
Problem: P.M. Service.Left rear tire flat.

- P.m. Service. **Parts List** **Qty**
- Replace front brake rotors,pads and clean and lube 5w20 Engine Oil 5.00
calipers.service and adjust rear brake.flush and bleed Napagold Oil Filter 1.00
system. Napagold Air Filter 1.00
- Replace and balance four new tires. Brake Cleaner 1.00
- Replace right front signal light bulb. Accufit Conventional 1.00
- Complete wheel alignment.test drive. Exact Fit Blade 1.00
- Shop Supplies Front Rotor 2.00
kit brake lin 1.00
P205/65r15 Assurance 4.00
Bulb 1.00
Shop Supplies 1.00
Tire Disposal Fee 4.00

Hours 11.75 Labor: 705.00 Parts: 740.35 Total: 1,445.35
:

Workorder: 1606290 **Meter:** 49126 **In Date:** 06/16/2016 **Closed:** 06/20/2016
Problem: FLAT TIRE ON D/R

- Tire Service 11449 W.palmetto Park Rd, Boca(walgreens) -
Flat Tire On D/r

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1607479 **Meter:** 50935 **In Date:** 07/22/2016 **Closed:** 07/28/2016
Problem: Right rear tire flat.

- Repair and balance right rear tire. **Parts List** **Qty**
- Shop Supplies Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1607520 **Meter:** 50655 **In Date:** 07/22/2016 **Closed:** 07/22/2016
Problem: Flat tire

- Tow From: 1150 Yamato Rd, Boca Raton

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1607928 **Meter:** 51569 **In Date:** 08/02/2016 **Closed:** 08/16/2016
Problem: A/C in cages not working.

- Remove panel in cage and replace defective blower motor.reseal panel.
- Check and replacew dome lamp bulbs.
- Shop Supplies

Parts List	Qty
Real Fan Motor	1.00
Bulb	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours 2.50 Labor: 150.00 Parts: 239.43 Total: 389.43
:

Workorder: 1610579 **Meter:** 55887 **In Date:** 10/13/2016 **Closed:** 11/21/2016
Problem: P.M. service and slider door inop and tire pressure light on.

- P.m. Service.
- Replace right cargo door latch assemble.
- Service and adjust rear brakes.
- Rotate and balance tires.
- Shop Supplies

Parts List	Qty
5w20 Engine Oil	5.00
Napagold Oil Filter	1.00
Exact Fit Blade	1.00
Accufit Conventional	1.00
Latch	1.00
Panel Fasteners	10.00
Knob	1.00
Shop Supplies	1.00

Hours 6.00 Labor: 360.00 Parts: 498.13 Total: 858.13
:

Workorder: 1611454 **Meter:** 55052 **In Date:** 11/04/2016 **Closed:** 11/04/2016
Problem: 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1703727 **Meter:** 60933 **In Date:** 04/12/2017 **Closed:** 04/18/2017
Problem: Right tire pressure sensor inop.

- Diagnose Tpms light.replace right front pressure sensor and reprogram.
- Shop Supplies

Parts List	Qty
Tpms12 Sensor Tire Pr	1.00
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 83.71 Total: 143.71
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1704270 **Meter:** 61651 **In Date:** 04/27/2017 **Closed:** 05/05/2017
Problem: P.M. service and low tire light on.

<ul style="list-style-type: none"> - P.m. service - Replace worn rear brake shoes.resurface drums,replace wheel cylinders.flush and bleed system .test drive. - Perform transmission service .replace filter and flush and refill fluid. - Replace broken left rear marker bulb and socket. - Inspect for noise from engine.replace failed idler pulley ,belt and tensioner. Retest. - Repair left rear tire .flat.rotate and balance four tires.nitro fill. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> 5w20 Engine Oil Napagold Oil Filter Exact Fit Blade Accufit Conventional Washer Fluid Concentr Big G Degreaser 1 Gal Brk Fluid Dot 4-12oz Non-chlor Brake Clnr Ptex Ultra Grey 3oz Syn-atf Trans Fluid S Bulb Hub Cap Real Brake Shoes Wheel Cyinders Transmission Filter Marker Lamp Socket Dr Blt Tensioner Assy Idler Pulley Serpentine Belt Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 12.00 2.00 1.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 	
Hours 13.05 :	Labor: 783.00	Parts: 606.04	Total: 1,389.04

Workorder: 1705022 **Meter:** 63009 **In Date:** 05/19/2017 **Closed:** 05/24/2017
Problem: Right front wiper blade came apart.

<ul style="list-style-type: none"> - Test and replaced defective right side wiper blade.retest operation. 	<p>Parts List</p> <ul style="list-style-type: none"> 18" wiper blades 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 	
Hours 0.20 :	Labor: 12.00	Parts: 3.39	Total: 15.39

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1708585 **Meter:** 66639 **In Date:** 08/30/2017 **Closed:** 09/07/2017
Problem: P.M. service and tire liggth on and loud in A/M .

- P.m. service.	Parts List	Qty
- Check battery, charging system, fully charge .retest battery. Failed load test.replace defective battery.	5w20 Engine Oil	5.00
- Check and replace all three defective engine mounts for noise when in drive.replace defective valve cover gasket for engine oil at spark plug boots.	Napagold Oil Filter	1.00
- Performed engine decarb and injector flush.	Exact Fit Blade	1.00
- Perform engine tune-up.replace defective ignition coil # 4 due to engine oil contamination. Replace all four spark plugs.	Accufit Conventional	1.00
- Replace and balance all four tires.	Battery	1.00
- Check and replace both rear shocks absorbers.	Intake Cleaner Kit	1.00
- Complete front end alignment and road test.	Injector Cleaner	1.00
- Inspect and service rear brakes.	Spark Plug	4.00
- Shop Supplies	P205/65r15 Assurance	4.00
	Throttle Body Cleaner	1.00
	Valve Cover Gasket	1.00
	Engine Moont	1.00
	Engine Mount	1.00
	Trans Mount	1.00
	Rear Shocks	2.00
	Ptex Ultra Black 30z	1.00
	Door Remote	1.00
	Ing Coil	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 17.75	Labor: 1,065.00	Parts: 1,365.39
:	0	Total: 2,430.39

Workorder: 1801023 **Meter:** 70550 **In Date:** 01/26/2018 **Closed:** 01/30/2018
Problem: Left front tire going flat.

- Repair left front tire and balance .nitrogen fill tires.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1803980 **Meter:** 72316 **In Date:** 04/17/2018 **Closed:** 04/25/2018
Problem: P.M. service and feels vibration on accel at times.

- P.m. service . Test drive for about 30 miles . Could not duplicate complaint at this time.	Parts List	Qty
- Rotate and balance all four tires .nitrogen filled tires.	5w20 Engine Oil	5.00
- Cleaned and inspected and adjust rear brakes.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Bleade Anco	1.00
	18" wiper blades	1.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 285.00	Parts: 24.49
:		Total: 309.49

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810804 **Meter:** 76385 **In Date:** 10/19/2018 **Closed:** 11/06/2018
Problem: PM Service, On acceleration 40-60mph shakes then shifts and smoothes out.

- P.m. service.	Parts List	Qty
- Pressure test cooling system . Replace leaking upper radiator hose . Flush and refill coolant . Retest.	Napagold Oil Filter	1.00
- Inspect and service rear brakes. Clean and adjust.	5w20 Engine Oil	5.00
- Diagnose cage lights inop . Repair bad connector at light switch . Retest.	18" wiper blades	1.00
- Diagnose shaking when shifting . Remove and replace transmission assmbly and transmission cooler . Top off fluid and test drive . Reset Kam .	Wiper Bleade Anco	1.00
- Rotate and balance all four tires. Nitrogen fill all tires .	Ford Triton Pvc Swc	1.00
- Shop Supplies	Lower Hose	1.00
	Anti Freeze Motorcraft	1.00
	oil auto	15.00
	Tramission Oil Cooler	1.00
	Tramission Assy	1.00
	Shop Supplies	1.00
Hours 19.05	Labor: 1,276.3	Parts: 3,257.73
:	5	Total: 4,534.08

Workorder: 1904683 **Meter:** 77227 **In Date:** 04/30/2019 **Closed:** 05/16/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Pressure test and inspect cooling system . Replace leaking thermostat and lower radiator hose . Flush and refill cooling system and retest .	Napagold Oil Filter	1.00
- Test and replace high mounted stop light . Time to remove cage panels to access lamp mounts .	5w20 Engine Oil	5.00
- Balance and rotate all four tires . Nitrofill all .	Washer Fluid Concentr	1.00
- Inspect and service rear brakes .	18" wiper blades	1.00
- Shop Supplies	Wiper Bleade Anco	1.00
	Lower Hose	1.00
	Anti Freeze Motorcraft	1.00
	Thermostat	1.00
	Lamp Asy	1.00
	Shop Supplies	1.00
Hours 11.75	Labor: 787.25	Parts: 322.35
:		Total: 1,109.60

Workorder: 1909142 **Meter:** 79008 **In Date:** 09/05/2019 **Closed:** 09/11/2019
Problem: Left rear tire goping flat .

- Repair left rear tire and balance . Nitrofill all.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

Workorder: 1910778 **Meter:** 79355 **In Date:** 10/21/2019 **Closed:** 10/21/2019
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00