

**Palm Beach County Fleet Management
Asset Maintenance History**

10178868 2009 FORD RANGER Pickup, Compact

Workorder: 935788 **Meter:** 0 **In Date:** 03/30/2009 **Closed:** 03/30/2009
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 936303 **Meter:** 311 **In Date:** 04/09/2009 **Closed:** 04/10/2009
Problem: DUPLICATE AND PROGRAM KEY

- Make Spare Key And Program

- Shop Supplies

Parts List	Qty
164-r0475 Ign Key 2010-earlier (don't Reorder)	1.00
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 23.45 Total: 83.45
:

Workorder: 942200 **Meter:** 3873 **In Date:** 08/17/2009 **Closed:** 08/17/2009
Problem: Service

- 8100 Forest Hill

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 944653 **Meter:** 5557 **In Date:** 10/16/2009 **Closed:** 10/23/2009
Problem: P.M service.

- P.m service.

- Service rear drum brakes.

- Repair R/r tire, rotate & balance all four tires.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
Ph9566 Oil Filter Use Fram Ph3614	1.00
5w20 Engine Oil	5.00

Hours 5.00 Labor: 300.00 Parts: 13.90 Total: 313.90
:

Workorder: 1005514 **Meter:** 10778 **In Date:** 05/27/2010 **Closed:** 06/01/2010
Problem: P.M sevice, check tires for nails.

- P.m service.

- Repair L/r tire.

- Service rear drum brakes.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
Ph9566 Oil Filter Use Fram Ph3614	1.00
Ca8243 Air Filter Lbf Af1658 Wix 46253	1.00
3424 Fuel Filter Frm 3424 Wix 33424	1.00
5w20 Engine Oil	5.00
Nb-18 Wiper Blades 18" Anco 31-18	2.00

Hours 4.00 Labor: 240.00 Parts: 37.31 Total: 277.31
:

Workorder: 1006846 **Meter:** 11448 **In Date:** 06/30/2010 **Closed:** 06/30/2010
Problem: Driver side front tire flat.

- Repair and balance right front tire.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1007931	Meter: 12247	In Date: 07/26/2010	Closed: 08/09/2010
Problem: Towed in,brakes smoking.Shift indicator inop.			
- Inspect.verify and replace failed left rear brake shoe return springs with new to correct dragging brake shoes.	Parts List		Qty
	Shop Supplies		1.00
- Inspect ,verify and replace failed gear shifter indicator in instrument cluster with new.	3l5z2296ca Spring Kit (ford)		1.00
- Shop Supplies	Gear Shift Indicator		1.00
Hours 2.00	Labor: 120.00	Parts: 37.88	Total: 157.88
:			
Workorder: 1009967	Meter: 12885	In Date: 07/26/2010	Closed: 09/10/2010
Problem: brakes hot/ smoking			
- From: mosquito control fuel site	To: lv shop		
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1013199	Meter: 14870	In Date: 11/30/2010	Closed: 12/14/2010
Problem: Pm service also see notes on Regular key to open door only.			
- Perform pm service.	Parts List		Qty
- Install new front brake pads and resurface front brake rotors.service calipers and lube slides.perform rear drum brakes service,adjust brake shoes and bleed hydraulic system.	Shop Supplies		1.00
	Ph9566 Oil Filter Use Fram Ph3614		1.00
- Install four new tires.nitrogen fill and balance all four.	Mkd833 Brake Pads Ranger Front		1.00
- Perform wheel alignment complete.	5w20 Engine Oil		5.00
- Cut and supply one regular key just to open door as per operator request.	Nb-18 Wiper Blades 18" Anco 31-18		2.00
	183482418 P225/70r15 Wrangler Sr-a 100s		4.00
- Shop Supplies	Tire Disposal Fee		4.00
Hours 11.00	Labor: 660.00	Parts: 535.23	Total: 1,195.23
:			
Workorder: 1013631	Meter: 14880	In Date: 12/10/2010	Closed: 12/15/2010
Problem: flash canceiver spot #182			
- Reflash Canceiver and reprogram	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1100466	Meter: 15541	In Date: 11/05/2010	Closed: 01/13/2011
Problem: LEFT REAR TIRE Flat			
- 8100 forst hill blvd s side of Bldg #1			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1104778	Meter: 18792	In Date: 05/04/2011	Closed: 05/05/2011
Problem: Right rear tire flat.			
- Repair and balance right rear tire.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1107828 **Meter:** 20414 **In Date:** 07/26/2011 **Closed:** 08/08/2011
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Repair right rear tire.rotate and balance all four.	Shop Supplies	1.00
- Service and adjust rear brake.	Ca8243 Air Filter Lbf Af1658 Wix 46253	1.00
- Shop Supplies	3424 Fuel Filter Frm 3424 Wix 33424	1.00
	1348 Oil Filter Frm Ph3614 Wix 51348	1.00
	5w20 Engine Oil	5.00
	Wd40 Spray Lube Stock# 405540002	1.00
	Nb-18 Wiper Blades 18" Anco 31-18	2.00
Hours 5.00	Labor: 300.00	Parts: 50.99
:		Total: 350.99

Workorder: 1202319 **Meter:** 22741 **In Date:** 03/07/2012 **Closed:** 03/15/2012
Problem: P.M. service and nail left front tire.

- P.m. Service.	Parts List	Qty
- Check battery and charging system.recharge battery and retest,failed load test.replace defective battery.	Shop Supplies	1.00
- Repair left front tire,rotate and balance all four.	1348 Oil Filter Frm Ph3614 Wix 51348	1.00
- Service and adjust rear brakes.	5w20 Engine Oil	5.00
- Shop Supplies	Group 59 Battery (mtc Bxt 59)	1.00
Hours 6.00	Labor: 360.00	Parts: 135.06
:		Total: 495.06

Workorder: 1208534 **Meter:** 26166 **In Date:** 09/10/2012 **Closed:** 09/13/2012
Problem: Left rear turn signal inop.

- Replace left rear signal light bulb.	Parts List	Qty
	3157 Tail Light Bulbs	2.00
Hours 0.25	Labor: 15.00	Parts: 1.20
:		Total: 16.20

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1211487 **Meter:** 27343 **In Date:** 11/29/2012 **Closed:** 12/11/2012
Problem: Pm service driver door wind noise and gear shift indicator.

	Parts List	Qty
- P.m. Service.		
- Replace broken shift indicator.	Filter	1.00
- Wind noise coming from left door.replace left door upper hinge and adjust door to correct problem.	5w20 Engine Oil	5.00
- Replace and balance four new tires.	G9343 Fuel Filter Mtc	1.00
- Resurface front brake rotors and replace rear drums.replace front pads.service and lube calipers,service and adjust rear brake.flush and bleed system and test drive.	31-18 Wiper Blades 18	2.00
- Complete wheel alignment.test drive.	Brake Drum	2.00
- Shop Supplies	Reman Brake Shoes	1.00
	Disc Brake Pads	1.00
	Napa Oil Seal	2.00
	05088 Brake Clean	1.00
	Wheel Cylinder	2.00
	Shift indicator	1.00
	Hinge Ass	1.00
	183482418 P225-70r15	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 16.00	Labor: 960.00	Parts: 946.69
:		Total: 1,906.69

Workorder: 1302373 **Meter:** 28444 **In Date:** 03/08/2013 **Closed:** 03/08/2013
Problem: LR FLAT

- Tow From: 8100 forest hill, croc To: lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1302407 **Meter:** 28467 **In Date:** 03/11/2013 **Closed:** 03/15/2013
Problem: Towed in for flat tire left rear.

	Parts List	Qty
- Replace defective wiper blade.		
- Repair and balance left rear tire.	Wiper Blade	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.25	Labor: 75.00	Parts: 6.25
:		Total: 81.25

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1310826 **Meter:** 32822 **In Date:** 10/29/2013 **Closed:** 11/21/2013
Problem: pm, add strobes, engine light on mis firing, ac turns on and off not working, nail in tire

- pm	Parts List	Qty
- ck ac turns on and off ok ck sys perssure and found low	Napagold Oil Filter	1.00
freon add uv dye ane ck for leaks found leaking shrader	Napa Quart 5w20	5.00
vlaves evac replace both shradder valves recharge and ck for leaks	Napagold Fuel Filter	1.00
- ck engine light is on scan code po037 and po316 perform	Wiper Blade	2.00
pinpoint test and found bad coil pack replace coil pack spark	Napagold Air Filter	1.00
plugs wires and clear codes	Mac Wite Lithium Gres	1.00
- clean and adj rear brakes	Washer FI	1.00
- install strobe light sys	Valve Core	1.00
- test drive vehicle 50 miles after repair	Ac Valve Core High	1.00
- replace 3rd brake light bulb	South Region R134a	2.00
- repair reight rear tire	E8 A-c Oil R134a A-c	1.00
- Shop Supplies	Coil Asy	1.00
	Spark Plug	4.00
	Wire Asy	1.00
	Brake Cleaner	1.00
	Vtx609c Led Strobe Cl	4.00
	Fuse Holder	1.00
	Universal Switch	1.00
	A/c Service Port	1.00
	Cable Tie	2.00
	Shop Supplies	1.00
Hours 24.25	Labor: 1,455.0	Parts: 832.94
:	0	Total: 2,287.94

Workorder: 1310827 **Meter:** 31981 **In Date:** 10/29/2013 **Closed:** 10/29/2013
Problem: misfiring

- Tow From: 9045 s jog road boynton beach To: sr delray

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1401917 **Meter:** 34240 **In Date:** 02/27/2014 **Closed:** 02/28/2014
Problem: need extra key

- Make and program 1 key	Parts List	Qty
- Shop Supplies	Ford Ignition Key Blank	1.00
	Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 28.61 Total: 88.61
:

Workorder: 1404119 **Meter:** 34573 **In Date:** 04/29/2014 **Closed:** 04/30/2014
Problem: needs 2 extra keys

- Make and program 2 extra keys	Parts List	Qty
- Shop Supplies	Ford Ignition Key Blank	2.00
	Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 55.22 Total: 115.22
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1405617 **Meter:** 35200 **In Date:** 06/06/2014 **Closed:** 06/12/2014
Problem: P.M.SERVICE

	Parts List	Qty
- pm		
- svc rear drum brakes	Napagold Oil Filter	1.00
- Shop Supplies	Napa Quart 5w20	5.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 24.35
:		Total: 204.35

Workorder: 1409158 **Meter:** 38110 **In Date:** 09/11/2014 **Closed:** 09/22/2014
Problem: indicator not working hazard light not working ck brake lights

	Parts List	Qty
- Ck Lights Not Working Replace Multi Funciton Hazard Switch	Headlight Dimmer Swit	1.00
- Repair Lr Tail Light	Bulb	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.75	Labor: 165.00	Parts: 99.74
:		Total: 264.74

Workorder: 1410430 **Meter:** 39003 **In Date:** 10/17/2014 **Closed:** 10/23/2014
Problem: NAIL IN R/Front TIRE

	Parts List	Qty
- ck nail fr tires verify need two front tires mount balance add n2	183482418 P225-70r15	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.50	Labor: 90.00	Parts: 318.72
:		Total: 408.72

Workorder: 1411399 **Meter:** 39630 **In Date:** 11/14/2014 **Closed:** 11/19/2014
Problem: p.m.service,brakes grinding

	Parts List	Qty
- pm		
- verify need two tire replace two rear tires rotate to front	Napagold Oil Filter	1.00
- ck brakes replace front brake pads rotors calipers and brackets reassemble bleed test drive new bearings race and seals	Napa Quart 5w20	5.00
	Napagold Fuel Filter	1.00
- rear brake ddrum svc	Wiper Blade	2.00
- Shop Supplies	Washer Fl	1.00
	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	Caliper Bracket	2.00
	Brake Rotor	2.00
	Tappered Bearing Set	2.00
	Tappered Bearing Set	2.00
	Napa Oil Seal	2.00
	183482418 P225-70r15	2.00
	1401 Brake Fluid Bra	1.00
	Brake Cleaner	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 9.50	Labor: 570.00	Parts: 954.14
:		Total: 1,524.14

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1504668 **Meter:** 43795 **In Date:** 05/07/2015 **Closed:** 05/19/2015
Problem: pm, heat not working window washer not working need alignment

	Parts List	Qty
- pm		
- replace worn out left rear brake self adjuster and clean and adj rear brakes	Adj/kit	1.00
	Napa Quart 5w20	5.00
- have no heat perform pinpoint test and found bad ac blend door acuator replace accuator	Napagold Oil Filter	1.00
	Wiper Blade	2.00
- replace both front lower ball joints and both stablizer bar link	Washer Fl	1.00
	Brake Cleaner	1.00
- ck wind shield washer not working ck washer and was unable to verify concern at this time	Blend Door Acuator	1.00
- Shop Supplies	Lower Ball Joint	2.00
	Sway Bar Repair Kit	1.00
	Shop Supplies	1.00
Hours 12.50	Labor: 750.00	Parts: 230.77
:		Total: 980.77

Workorder: 1505732 **Meter:** 44341 **In Date:** 06/08/2015 **Closed:** 06/16/2015
Problem: no start, towed in west wat

	Parts List	Qty
- wont start test battery bad replace battery ck charging sys	Battery	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 0.75	Labor: 45.00	Parts: 99.89
:		Total: 144.89

Workorder: 1505773 **Meter:** 44204 **In Date:** 06/08/2015 **Closed:** 06/09/2015
Problem: no start

- Tow From: 9045 jog road boynton To: sr delray			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1511495 **Meter:** 48054 **In Date:** 11/09/2015 **Closed:** 11/30/2015
Problem: PM, NAIL IN RF TIRE, CAB LIGHT OUT

	Parts List	Qty
- pm		
- clean and adj rear brakes	Napa Quart 5w20	5.00
- repair left tag light repair dome light circuit and replace door adjar switch	Napagold Oil Filter	1.00
	Wiper Blade	2.00
- repair right front tire	Washer Fluid Concentr	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Napagold Air Filter	1.00
	Brake Cleaner	1.00
	Bulb	2.00
	Bulb	2.00
	Swi8tch Assy	2.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 102.10
:		Total: 522.10

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1600813 **Meter:** 49361 **In Date:** 01/25/2016 **Closed:** 01/27/2016
Problem: rr tire low

- repaired rr tire		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
	Hours 1.00	Labor: 60.00	Parts: 2.00
	:		Total: 62.00

Workorder: 1605365 **Meter:** 52516 **In Date:** 05/24/2016 **Closed:** 06/14/2016
Problem: Pm service.Wind noise.Hazzard lights inop.Check ac.

- Pm service		Parts List	Qty
- Verify needs two tires.mount and balance.add N2.		Napagold Oil Filter	1.00
- C/c hazzard inop.replace bad flasher unit relay.		Napa Quart 5w20	5.00
- Turn front rotors.service calipers.replace brake pads.service rear drum brake.		183482418 P225-70r15	2.00
- C/c air not fresh.remove blower motor and glove box.clean debris from evap screen.reassemble.		Flasher	1.00
- Shop Supplies		Disc Brake Pads	1.00
		Brake Cleaner	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
	Hours 11.00	Labor: 660.00	Parts: 416.15
	:		Total: 1,076.15

Workorder: 1613135 **Meter:** 57439 **In Date:** 12/28/2016 **Closed:** 01/17/2017
Problem: PM Service

- Pm Service		Parts List	Qty
- Verify washer fluid leaking.r&r washer fluid pump wth grummet.		Napagold Fuel Filter	1.00
- Replace two tires.rotate and balance.add N2.		Napagold Oil Filter	1.00
- Rear brake drum service.		Napa Quart 5w20	5.00
- Replace left tag lamp bulb.		18" wiper blades	2.00
- Shop Supplies		Washer Fluid Concentr	1.00
		Washer Pump	1.00
		Washer Pump Grummet	1.00
		183482418 P225-70r15	2.00
		Non-chlor Brake Clnr	1.00
		Bulb	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
	Hours 6.75	Labor: 405.00	Parts: 364.52
	:		Total: 769.52

Workorder: 1701440 **Meter:** 58123 **In Date:** 02/10/2017 **Closed:** 02/13/2017
Problem: R/REAR TIRE SLOW LEAK

- Repair and balance right rear tire.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
	Hours 1.00	Labor: 60.00	Parts: 2.00
	:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1705129 **Meter:** 60566 **In Date:** 05/24/2017 **Closed:** 05/30/2017
Problem: FRONT LEFT TIRE SLOW LEAK

- Repair and balance left front tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1707266 **Meter:** 61991 **In Date:** 07/25/2017 **Closed:** 08/14/2017
Problem: PM Service.Left rear tire flat.Windshield washer pump inop.

- Pm Service.	Parts List	Qty
- Service rear brakes.resurface front rotors.service calipers.replace brake pads.	Napagold Oil Filter	1.00
- Replace both rear tires.balance all four.rotate new tires to the front.	Napa Quart 5w20	5.00
- Replace right front upper control arm.	18" wiper blades	2.00
- Replace washer pump.	Washer Fluid Concentr	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Non-chlor Brake Clnr	1.00
	Disc Brake Pads	1.00
	B Fluid Dot 3-32oz	1.00
	183482418 P225-70r15	2.00
	Control Arm Assembly	1.00
	Washer Pump	1.00
	Seal	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.75	Labor: 705.00	Parts: 469.53
:		Total: 1,174.53

Workorder: 1711632 **Meter:** 64614 **In Date:** 11/28/2017 **Closed:** 12/11/2017
Problem: PM Service.Driver door lock.Ac inop.Gear shifter indicator broken.

- Pm Service	Parts List	Qty
- Replace right reverse lamp/bulb.	Napagold Oil Filter	1.00
- Replace ac blower motor and blower resistor.	Napa Quart 5w20	5.00
- Replace gearshift indicatorin instrument cluster	18" wiper blades	2.00
- Clean and adjust rear brakes.	Washer Fluid Concentr	1.00
- R/r driver door lock cylinder to clean and lube to open and close properly.	Lamp	1.00
- Rotate and balance four tires.	Blw Mtr	1.00
- Shop Supplies	Blower Motor Resistor	1.00
	Non-chlor Brake Clnr	1.00
	Shift indicator	1.00
	Shop Supplies	1.00
Hours 12.25	Labor: 735.00	Parts: 158.47
:		Total: 893.47

Workorder: 1712761 **Meter:** 64908 **In Date:** 12/28/2017 **Closed:** 01/19/2018
Problem: Wont start Bad battery.

- Test starting and charging system Battery failed load test.replace bad battery.	Parts List	Qty
- Shop Supplies	Battery	1.00
	Shop Supplies	1.00
Hours 0.75	Labor: 45.00	Parts: 118.75
:		Total: 163.75

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1804370 **Meter:** 67651 **In Date:** 04/26/2018 **Closed:** 05/04/2018
Problem: P.M. service ,check for brake noise .

<ul style="list-style-type: none"> - P.m. service. - Replace front brake rotors ,pads ,wheel bearing and seals .repack wheel bearing .service rear brakes. Test drive . - Inspect and replace valve cover gasket and belt. - Service and inspect transmission .replace filter and pan gasket.replace tail shaft seal.refill transmission .inspect for leaks . Replace missing shift cap. - Replace two worn tires .rotate and balance all four tires. Replace Tpm sensor in leftr front tire .nitrogen fill tires and reset Tpms. - Perform front end alignment. Road test. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Tpms Sensor Napagold Oil Filter 5w20 Engine Oil Napagold Fuel Filter 18" wiper blades Brake Rotor Hub Tappered Bearing Set Tappered Bearing Set Napa Oil Seal Non-chlor Brake Clnr Syn-atf Trans Fluid S Int Manifold Gasket Fil Kit B Fluid Dot 3-32oz Cap Cap Grea Brake Pads Valve Cover Gasket Belt Rear Trans Seal 183482418 P225-70r15 wheel cover Belt Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 5.00 1.00 2.00 2.00 2.00 2.00 2.00 1.00 5.00 1.00 2.00 1.00 1.00 1.00 2.00
Hours 17.20 :	Labor: 1,032.00 0	Parts: 937.26 Total: 1,969.26

Workorder: 1806503 **Meter:** 69224 **In Date:** 06/26/2018 **Closed:** 06/28/2018
Problem: Recall 16S26.

<ul style="list-style-type: none"> - Transport to and from dealer for recall 16s26 . - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00
Hours 2.00 :	Labor: 120.00	Parts: 2.00 Total: 122.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1812628 **Meter:** 73446 **In Date:** 12/12/2018 **Closed:** 12/20/2018
Problem: P.M. service and left rear tire going flat.

<ul style="list-style-type: none"> - P.m. service. - Inspect all tires . Replace two worn tires . Rotate and high speed balance all four tires. Nitrofill all. - Test and replace left tail light bulb. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Napagold Oil Filter Napa Quart 5w20 Washer Fluid Concentr 18" wiper blades Mac Wite Lithium Gres Non-chlor Brake Clnr Pedal Pad P225/70r15 Bfg Boxed Miniatures Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 5.00 1.00 2.00 1.00 1.00 1.00 2.00 1.00 1.00 2.00 	
Hours 4.50 :	Labor: 301.50	Parts: 421.20	Total: 722.70

Workorder: 1904532 **Meter:** 77068 **In Date:** 04/26/2019 **Closed:** 05/07/2019
Problem: PM Service, Cabin light inop.

<ul style="list-style-type: none"> - P.m. service. - Test and replace dome light bulb . Test and replace high mounted brake light bulb . Test and replace tag light bulbs and sockets . - Resurface both brake rotors and service calipers . Replace brake pads . Inspect and service rear brakes . Flush and bleed brake system . Road test. - Replace leaking dip stick tube seal and refill transmission fluid . - Pressure test and inspect cooling system . Replace leaking heater control valve and heater hose . Flush and refill cooling system . - Rotate and balance all four tires. Nitrofill all tires and reset Tpms. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> 5w20 Engine Oil Napagold Oil Filter 18" wiper blades Mac Wite Lithium Gres Boxed Miniatures Boxed Miniatures Tag Lamp Non-chlor Brake Clnr B Fluid Dot 3-32oz Brake Pads dip stick seal Coolant Ford Gold Heater Hose heater controle valve Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 5.00 1.00 2.00 1.00 2.00 2.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 	
Hours 12.10 :	Labor: 810.70	Parts: 192.75	Total: 1,003.45

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1911027 **Meter:** 82003 **In Date:** 10/25/2019 **Closed:** 11/06/2019

Problem: P.M. service and right front tire going flat .

- P.m. service .	Parts List	Qty
- Diagnose A/c blower inop . Replace defective blower resistor and pigtail . Retest .	Napagold Oil Filter	1.00
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill all.	5w20 Engine Oil	5.00
- Shop Supplies	18" wiper blades	2.00
	Napagold Fuel Filter	1.00
	Wire Assy	1.00
	Blower Motor Resistor	1.00
	P225/70r15 Bfg	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.00	Labor: 438.00	Parts: 468.38
:		Total: 906.38

Workorder: 1913145 **Meter:** 83635 **In Date:** 12/30/2019 **Closed:** 12/30/2019

Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			