

**Palm Beach County Fleet Management
Asset Maintenance History**

10192559 2013 FORD F150 Pickup, 1/2 Ton

Workorder: 1305802 **Meter:** 32 **In Date:** 06/11/2013 **Closed:** 06/11/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1309004 **Meter:** 3841 **In Date:** 08/19/2013 **Closed:** 09/05/2013
Problem: damage to rear fenders, lft taillight & rear bumper

- damage to rear fenders, lft taillight & rear bumper

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1311601 **Meter:** 8495 **In Date:** 11/18/2013 **Closed:** 11/27/2013
Problem: Pm service.

- Perform pm service.

- Install two new tires to the front wheels.nitrogen fill and balance all four.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Floor Mat-2pc Rub Bk	1.00
Washer Fluid Concentr	1.00
235 75r17 Adventure	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 4.00 Labor: 240.00 Parts: 624.93 Total: 864.93
:

Workorder: 1312672 **Meter:** 10091 **In Date:** 12/19/2013 **Closed:** 12/30/2013
Problem: Right rear tire flat.

- Repair right rear tire flat.nitrogen fill and balance same.install spare tire back to rack and secure.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1312789 **Meter:** 9981 **In Date:** 12/17/2013 **Closed:** 12/26/2013
Problem: flat tire/put spare tire on

- Tow From: 12170 58th pl n

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1401569 **Meter:** 12625 **In Date:** 02/18/2014 **Closed:** 02/20/2014
Problem: Left rear tire flat,damage beyond repairs.

- Install two new tires to rear wheels.nitrogen fill and balance both.

- Shop Supplies

Parts List	Qty
235 75r17 Adventure	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 1.00 Labor: 60.00 Parts: 472.35 Total: 532.35
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1402612	Meter: 14272	In Date: 03/18/2014	Closed: 04/03/2014
Problem: P.M. service.			
- P.m. Service.	Parts List	Qty	
- Rotate and balance all tires.	5w20 Engine Oil	6.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	Napagold Air Filter	1.00	
	Used Fire X Refurbished	1.00	
	Wiper Blade	2.00	
	Shop Supplies	1.00	
Hours 3.00	Labor: 180.00	Parts: 53.84	Total: 233.84
:			

Workorder: 1406573	Meter: 19663	In Date: 07/02/2014	Closed: 07/18/2014
Problem: Pm service			
- Perform pm service.	Parts List	Qty	
- Rotate and balance all four tires.	5w20 Engine Oil	6.00	
- Transport vehicle to and from dealer for repairing left door wiring harness for air bag light on.	Napagold Oil Filter	1.00	
- Shop Supplies	Wiper Blade	2.00	
	Shop Supplies	1.00	
Hours 5.00	Labor: 300.00	Parts: 29.68	Total: 329.68
:			

Workorder: 1412810	Meter: 25418	In Date: 12/24/2014	Closed: 01/29/2015
Problem: Pm service.Driver door speaker inop.Blower motor growling.			
- P.m. Service.	Parts List	Qty	
- Replace two tires,rotate and balance all four.	5w20 Engine Oil	6.00	
- Complete wheel alignment.test drive.	Napagold Oil Filter	1.00	
- R&r blower and clean leaves from housing.	Wiper Blade	2.00	
- Transport vehicle to dealer for airbag light staying on and defective left speaker.	235 75r17 Adventure	2.00	
- Shop Supplies	Stg Wheel Cov - Ford	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 9.00	Labor: 540.00	Parts: 528.86	Total: 1,068.86
:			

Workorder: 1504495	Meter: 31076	In Date: 05/01/2015	Closed: 05/12/2015
Problem: Pm service.			
- Pm service.	Parts List	Qty	
- Replace three tires.rotate and balance all four.	5w20 Engine Oil	6.00	
- Replace front brake pads and resurface both front brake rotors.service and lube calipers.	Napagold Oil Filter	1.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Used Fire X Refurbished	1.00	
	235 75r17 Adventure	3.00	
	kit brak	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	3.00	
Hours 7.00	Labor: 420.00	Parts: 841.33	Total: 1,261.33
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1509221 **Meter:** 36766 **In Date:** 09/14/2015 **Closed:** 09/28/2015
Problem: P.M. service.

- Pm service.	Parts List	Qty
- Test starting and charging system.battery failed loadtest after recharge.replace defective battery.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Air Filter	1.00
	Wiper Blade	2.00
	Silicone Spray 10oz	1.00
	Battery 65	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 189.62
:		Total: 429.62

Workorder: 1510659 **Meter:** 37958 **In Date:** 10/21/2015 **Closed:** 10/21/2015
Problem: 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1513079 **Meter:** 41615 **In Date:** 12/30/2015 **Closed:** 01/20/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Test left rear turnsignal lamp inop.replace defective bulb.	5w20 Engine Oil	6.00
- Replace and balance all four tires.	Napagold Oil Filter	1.00
- Replace rear brake pads and resurface rear brake rotors.service calipers and test drive.	22" Wiper Blade	2.00
- Complete front end alignment.	Bulb	1.00
- Shop Supplies	235 75r17 Adventure	4.00
	Pad Brak	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 10.50	Labor: 630.00	Parts: 1,051.69
:		Total: 1,681.69

Workorder: 1604061 **Meter:** 45445 **In Date:** 04/18/2016 **Closed:** 04/22/2016
Problem: Left rear tire going flat.

- Repair and balance left rear tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1605266 **Meter:** 47183 **In Date:** 05/20/2016 **Closed:** 05/31/2016
Problem: P.M. Service.Install strobe light.Check inverters.

- P.m. Service.	Parts List	Qty
- R&r driveshaft and replace leaking pinnion seal.inspect and service rear differential.	Napagold Oil Filter	1.00
- Fabricate and install four crner strobe lights.install wiring and switch.	5w20 Engine Oil	6.00
- Resurface both front brake rotors to correct pulsation.service and lube calipers.	22" Wiper Blade	2.00
- Shop Supplies	Seal Asy	1.00
	Ptex Ultra Grey 3oz	1.00
	Vtx609a Led Strobe Am	2.00
	Vtx609c Led Strobe Cl	2.00
	Fab Loom-split Poly	10.00
	Fuse Holder	1.00
	Ds-364 Rocker Switch	1.00
	Napagold Air Filter	1.00
	Used Fire X Refurbished	1.00
	Friction Modifier	1.00
	75w140 Ford Axle Lube	3.00
	Shop Supplies	1.00
Hours 15.00	Labor: 900.00	Parts: 649.79
:		Total: 1,549.79

Workorder: 1607633 **Meter:** 50301 **In Date:** 07/26/2016 **Closed:** 08/04/2016
Problem: Won't start intermittently,just make clicking noise.

- Test battery and charging system.replace bad battery.	Parts List	Qty
- Shop Supplies	Battery 65	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 148.34
:		Total: 208.34

Workorder: 1608898 **Meter:** 51766 **In Date:** 08/25/2016 **Closed:** 09/08/2016
Problem: P.M. service and check engine light on

- P.m. Service.	Parts List	Qty
- Diagnose check engine light.p2196 & P2198.perform evap system bay test.replace defective purge solenoid.clear codes and retest	5w20 Engine Oil	6.00
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00
- Complete wheel alignment.test drive.	22" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Valva Asy	1.00
	235 75r17 Adventure	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 9.00	Labor: 540.00	Parts: 489.80
:		Total: 1,029.80

Workorder: 1610934 **Meter:** 54468 **In Date:** 10/24/2016 **Closed:** 10/24/2016
Problem: 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1612815 **Meter:** 57505 **In Date:** 12/14/2016 **Closed:** 01/03/2017
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Resurface front brake rotors,replace brake pads.service and lube calipers.flush and bleed system.	5w20 Engine Oil	6.00
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00
- R&r drive shaft and clean and lube splines to correct clunking noise at stop and take-off.	Washer Fluid Concentr	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Brake Pad	1.00
	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	1.00
	235 75r17 Adventure	2.00
	Repair Kit	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.75	Labor: 525.00	Parts: 545.07
:		Total: 1,070.07

Workorder: 1703092 **Meter:** 62390 **In Date:** 03/28/2017 **Closed:** 04/10/2017
Problem: Left rear tire going flat.

- Repair and balance left rear tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1703749 **Meter:** 62726 **In Date:** 04/12/2017 **Closed:** 04/12/2017
Problem: 2 - Wash ticket(s) issued

- 2 - Wash ticket(s) issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

Workorder: 1703819 **Meter:** 63012 **In Date:** 04/14/2017 **Closed:** 04/28/2017
Problem: P.M. service and runs rough and check engine light on.

- P.m. service.	Parts List	Qty	
- Perform transmission service and flush with new filter	5w20 Engine Oil	6.00	
- Computer diagnose engine light on.code P2195 bank 1 sensor 1stuck lean failed.check wiring .r&i both Ho2 sensors clear codes retest .road Test.	Napagold Oil Filter	1.00	
- Rotate and high speed balance all wheels .nitro fill all.	22" Wiper Blade	2.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Mac Wite Lithium Gres	1.00	
	Used Fire X Refurbished	1.00	
	Napagold Air Filter	1.00	
	Screen Asy	1.00	
	Syn-atf Trans Fluid S	14.00	
	Sensor	2.00	
	Shop Supplies	1.00	
Hours 8.00	Labor: 480.00	Parts: 478.63	Total: 958.63
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1705013 **Meter:** 63383 **In Date:** 05/19/2017 **Closed:** 05/24/2017
Problem: Had to jump start.

- Charge battery fully.test battery and charging system.r&r defective battery .	Parts List	Qty
	Battery	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 130.66
:		Total: 190.66

Workorder: 1708078 **Meter:** 67792 **In Date:** 08/16/2017 **Closed:** 08/24/2017
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replaced all four tires.high speed balance and nitrofilled.	5w20 Engine Oil	6.00
- Serviced rear differential.	Napagold Oil Filter	1.00
- Pressure tested cooling system.inspected, flushed and replaced coolant.	22" Wiper Blade	2.00
- Complete four wheel alignment.	Washer Fluid Concentr	1.00
- Shop Supplies	Stg Wheel Cov - Ford	1.00
	Napagold Air Filter	1.00
	235 75r17 Adventure	4.00
	Non-chlor Brake Clnr	1.00
	75w140 Ford Axle Lube	3.00
	Friction Modifier	1.00
	Anti Freeze Motorcraft	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 9.50	Labor: 570.00	Parts: 1,050.06
:		Total: 1,620.06

Workorder: 1708883 **Meter:** 68722 **In Date:** 09/15/2017 **Closed:** 09/19/2017
Problem: Flat tire.

- Replace left front valve stem and balance tires .	Parts List	Qty
- Shop Supplies	Tire Pressure Monitoring System Sensor (1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 4.91
:		Total: 64.91

Workorder: 1710886 **Meter:** 71517 **In Date:** 11/02/2017 **Closed:** 11/09/2017
Problem: Towed in for crank but no start.

- Computer diagnoise no start,code P0205.fabricate and install fuse 27 fuse relocation kit per Tsb 15-0137.clear codes, retest.	Parts List	Qty
- Shop Supplies	Fuse Relocate Kit	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 20.05
:		Total: 80.05

Workorder: 1710890 **Meter:** 71447 **In Date:** 11/02/2017 **Closed:** 11/03/2017
Problem: no start

- Tow From: 8364 Cloud Peak Dr, Boyton Bch (valencia Isles) To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1710935 **Meter:** 71447 **In Date:** 11/03/2017 **Closed:** 11/03/2017
Problem: 3 - Wash ticket(s) issued

- 3 - Wash ticket(s) issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1712326 **Meter:** 73301 **In Date:** 12/14/2017 **Closed:** 12/21/2017
Problem: P.M. service and detail.

- P.m. Service.

- Rotate and balance tires.

- Shop Supplies

Parts List

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 25.18 Total: 205.18
:

Workorder: 1712675 **Meter:** 73301 **In Date:** 12/27/2017 **Closed:** 12/27/2017
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1803120 **Meter:** 77231 **In Date:** 03/26/2018 **Closed:** 03/29/2018
Problem: Flat tire

- Repaire left rear tire .balance and nitrogen fill tires.

- Shop Supplies

Parts List

Shop Supplies	1.00
---------------	------

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1803963 **Meter:** 78451 **In Date:** 04/17/2018 **Closed:** 04/23/2018
Problem: P.M. service and left rear tire going flat.

- P.m. service.

- Perform air intake decarb and flush fuel injector service.

- Perform tune up .replace all six spark plugs.

- Repair left rear tire and rotate and balance all four tires.nitrofill all.

- Shop Supplies

Parts List

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Intake Cleaner Kit	1.00
Injector Cleaner	1.00
Spark Plugs	6.00
Intake Gasket	1.00
Shop Supplies	1.00

Hours 8.60 Labor: 516.00 Parts: 216.67 Total: 732.67
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808320 **Meter:** 83503 **In Date:** 08/14/2018 **Closed:** 08/28/2018
Problem: P.M. service , left rear tire flat ,inverters stop working and Detail.

- P.m. service.	Parts List	Qty
- Replace two tires and repair one tire . Balance and nitrofill all four tires . Reset Tpms.	5w20 Engine Oil	6.00
- Test and replace power inverter and rewire and fabricate new harness and circuit breaker . Test operation.	Napagold Oil Filter	1.00
- Pressure test cooling system ,inspect for leaks . Replace water pump ,thermostat and gasket and heater hose . Flush and refill cooling system .	Used Fire X Refurbished	1.00
- Perform complete front end alignment. Test drive.	235 75r17 Adventure	2.00
- Shop Supplies	Cpi 1575 Inverter 1500 W	1.00
	Inverter Cable End 4ga	2.00
	Cabl/lug	6.00
	Cb185-100 Cir Brkr	2.00
	Anti Freeze Motorcraft	2.00
	Hosing Thermostat	1.00
	Tmermostat Housing	1.00
	Bulk Battery Cable	4.00
	Bulk Battery Cable	12.00
	Gasket	1.00
	Heater Hose	1.00
	Water Pump	1.00
	Fab Loom-split Poly	5.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 14.50	Labor: 870.00	Parts: 1,160.19
:		Total: 2,030.19

Workorder: 1808733 **Meter:** 83286 **In Date:** 08/23/2018 **Closed:** 08/23/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1808734 **Meter:** 83286 **In Date:** 08/23/2018 **Closed:** 08/23/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1810319 **Meter:** 84989 **In Date:** 10/04/2018 **Closed:** 10/10/2018
Problem: Flat tire.

- Diagnose tire sensor fault light . Replace left front tire pressure sensor . Repair right rear tire . Balance both tires and nitorgen fill all.	Parts List	Qty
- Shop Supplies	Tpms12 Sensor Tire Pr	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 134.00	Parts: 81.17
:		Total: 215.17

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1811728 **Meter:** 86642 **In Date:** 11/15/2018 **Closed:** 11/19/2018
Problem: Right rear tire going flat.

- Repair right rear tire and balance . Nitrogen fill tires.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

Workorder: 1900168 **Meter:** 88384 **In Date:** 01/04/2019 **Closed:** 01/10/2019
Problem: P.M. service detail.

- P.m. service.	Parts List	Qty
- Replace two worn tires . Rotate and balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00
- Shop Supplies	Napa Quart 5w20	6.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Tire Pressure Monitoring System Sensor (2.00
	Hankook P235 75r17 Dp At	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 4.00	Labor: 268.00	Parts: 495.40
:		Total: 763.40

Workorder: 1900427 **Meter:** 88384 **In Date:** 01/10/2019 **Closed:** 01/10/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

Workorder: 1904647 **Meter:** 92731 **In Date:** 04/29/2019 **Closed:** 05/01/2019
Problem: Right rear tire going flat.

- Repair right rear tire and balance . Nitrofill all.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

Workorder: 1905889 **Meter:** 94655 **In Date:** 06/04/2019 **Closed:** 06/10/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Repair right front tire . Rotate and high speed balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	6.00
	Napagold Air Filter	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 268.00	Parts: 52.64
:		Total: 320.64

Workorder: 1906164 **Meter:** 94655 **In Date:** 04/26/2019 **Closed:** 06/11/2019
Problem: Flat tire change

- Tow From: Military and Lantana behind Wendys	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1906796 **Meter:** 95108 **In Date:** 06/28/2019 **Closed:** 07/02/2019

Problem: Flat right front tire.

- Repair right front tire and balance . Nitrofill all.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

Workorder: 1910920 **Meter:** 99779 **In Date:** 10/22/2019 **Closed:** 11/02/2019

Problem: P.M. service and 12 volt power outlet inop.

- P.m. service.	Parts List	Qty
- Road test , diagnose noise . R&r defective right front hub assembly .road test .	Napagold Oil Filter	1.00
- Test power outlet , replace blown fuse . Retest . Test and replace defective high mounted stop light bulb .	5w20 Engine Oil	6.00
- Rotate and high speed balance all four tires . Nitrofill all.	Ford Triton Pvc Swc	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Hub Assy	1.00
	Boxed Miniatures	1.00
	Fmx-20lp Fuse	1.00
	Shop Supplies	1.00
Hours 5.30	Labor: 386.90	Parts: 543.55
:		Total: 930.45

Workorder: 2000415 **Meter:** 101942 **In Date:** 01/14/2020 **Closed:** 01/14/2020

Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			