

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10178880    2009 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg**

**Workorder:** 938067    **Meter:** 0    **In Date:** 05/21/2009    **Closed:** 05/21/2009  
**Problem:** PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00    Labor: 120.00    Parts: 0.00    Total: 120.00  
:

**Workorder:** 938592    **Meter:** 325    **In Date:** 06/03/2009    **Closed:** 06/04/2009  
**Problem:** DUPLICATE AND PROGRAM KEY

- Program And Dupliate Two Keys  
- Shop Supplies

**Parts List**  
164-r0475 Ign Key 2010-earlier (don't Reorder)    1.00  
164-r0475 Ign Key 2010-earlier (don't Reorder)    1.00  
Shop Supplies    1.00

Hours 1.50    Labor: 90.00    Parts: 44.90    Total: 134.90  
:

**Workorder:** 946090    **Meter:** 1544    **In Date:** 11/17/2009    **Closed:** 11/23/2009  
**Problem:** P. M. MAINTENANCE

- P. M. Service  
- Retightened Racks  
- Shop Supplies

**Parts List**  
Shop Supplies    1.00  
1372 Oil Filter Frm Ph2 Wix 51372    1.00  
5w20 Engine Oil    8.00  
1066 White Lithium (crc 05037)    1.00

Hours 3.75    Labor: 225.00    Parts: 48.30    Total: 273.30  
:

**Workorder:** 1002195    **Meter:** 3350    **In Date:** 03/02/2010    **Closed:** 03/08/2010  
**Problem:** CHECK ENGINE LIGHT ON

- Transport & pick up vehicle at dealer. (check engine light stays on).  
- Shop Supplies

**Parts List**  
Shop Supplies    1.00

Hours 2.50    Labor: 150.00    Parts: 2.00    Total: 152.00  
:

**Workorder:** 1005333    **Meter:** 3653    **In Date:** 05/24/2010    **Closed:** 05/27/2010  
**Problem:** P. M. SERVICE

- P.m.  
- Service ladder rack, lubricate adjusters. Check all mounting bolts on rack & tool boxes.  
- Tire repair, remove nail, mount, balance, add nitrogen.  
- Shop Supplies

**Parts List**  
Shop Supplies    1.00  
1372 Oil Filter Frm Ph2 Wix 51372    1.00  
5w20 Engine Oil    8.00  
Used Firex Refurbed Fire Extingshers    1.00

Hours 4.75    Labor: 285.00    Parts: 56.87    Total: 341.87  
:

**Workorder:** 1010169    **Meter:** 3997    **In Date:** 09/16/2010    **Closed:** 09/29/2010  
**Problem:** Check battery, truck will not start

- Transport & pick up vehicle at dealer (defective battery).  
- Battery warranty by dealer.  
- Shop Supplies

**Parts List**  
Shop Supplies    1.00

Hours 2.00    Labor: 120.00    Parts: 2.00    Total: 122.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1102075      **Meter:** 4448      **In Date:** 02/23/2011      **Closed:** 03/14/2011  
**Problem:** P. M. SERVICE

- P. M. Service.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	5w20 Engine Oil	8.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 2.75	Labor: 165.00	Parts: 53.93
:		Total: 218.93

**Workorder:** 1102734      **Meter:** 4480      **In Date:** 03/11/2011      **Closed:** 03/14/2011  
**Problem:** reflash canceiver

- Reflash Canceiver and reprogram	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Workorder:** 1110591      **Meter:** 5499      **In Date:** 10/04/2011      **Closed:** 10/17/2011  
**Problem:** P.M.SERVICE

- P. M. Service.	<b>Parts List</b>	<b>Qty</b>
- Service ladder rack. Adjust.	Shop Supplies	1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	5w20 Engine Oil	8.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 3.75	Labor: 225.00	Parts: 57.57
:		Total: 282.57

**Workorder:** 1203812      **Meter:** 6608      **In Date:** 04/23/2012      **Closed:** 04/26/2012  
**Problem:** pm

- pm	<b>Parts List</b>	<b>Qty</b>
- service ladder rack and tool box	Shop Supplies	1.00
- verify nail in fl tire dismount patch mount balance swap spare as rotation	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- ck engine light on clear po607 50 mile test drive no light at this time	5w20 Engine Oil	8.00
- nitro fill all truck tires		
- Shop Supplies		
Hours 7.25	Labor: 435.00	Parts: 33.84
:		Total: 468.84

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1305256      **Meter:** 13673      **In Date:** 05/29/2013      **Closed:** 05/31/2013  
**Problem:** pm

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Verify, needs two front tires. Mount, balance, add N2.	Napagold Air Filter	1.00
- Service ladder rack, tighten fastening bolts.	Napagold Fuel Filter	1.00
- Shop Supplies	Napagold Oil Filter	1.00
	Napa Quart 5w20	8.00
	Wiper Blade	2.00
	Used Firex Refurbed F	1.00
	179636492 Lt245-75r17	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 5.25	Labor: 315.00	Parts: 568.95
:		Total: 883.95

**Workorder:** 1307107      **Meter:** 14291      **In Date:** 07/16/2013      **Closed:** 07/19/2013  
**Problem:** Towed in for no start.

- Recharge battery and test battery and charging system.battery fail load test.replace defective battery.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Battery	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 117.97
:		Total: 177.97

**Workorder:** 1307112      **Meter:** 14077      **In Date:** 07/16/2013      **Closed:** 07/16/2013  
**Problem:** No Start (Towed to WPB Fleet)

- Tow From: 2969 North Hampton St (century Village) To: Lv Shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Workorder:** 1403736      **Meter:** 21151      **In Date:** 04/16/2014      **Closed:** 04/25/2014  
**Problem:** pm, balance tires

- pm	<b>Parts List</b>	<b>Qty</b>
- ck balance tires verify two tires need replaced mount	Napagold Oil Filter	1.00
balance add n2 balance all 4 tires	Napa Quart 5w20	8.00
- Shop Supplies	179636492 Lt245-75r17	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 4.25	Labor: 255.00	Parts: 527.82
:		Total: 782.82

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1410826      **Meter:** 25695      **In Date:** 10/29/2014      **Closed:** 11/10/2014  
**Problem:** P.M.SERVICE

- pm	<b>Parts List</b>	<b>Qty</b>
- repair lr tire	Napagold Fuel Filter	1.00
- Shop Supplies	Napagold Oil Filter	1.00
	Napa Quart 5w20	8.00
	Wiper Blade	2.00
	Washer Fl	1.00
	Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 54.10
:		Total: 279.10

**Workorder:** 1504653      **Meter:** 31350      **In Date:** 05/07/2015      **Closed:** 05/12/2015  
**Problem:** P.M. service.

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all four tires.	5w20 Engine Oil	8.00
- Shop Supplies	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
	Wiper Blade	2.00
	Floor Mat-2pc Rub Bk	1.00
	Used Fire X Refurbished	1.00
	Stg Wheel Cov - Ford	1.00
	Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 106.85
:		Total: 331.85

**Workorder:** 1507192      **Meter:** 33228      **In Date:** 07/20/2015      **Closed:** 07/20/2015  
**Problem:** Trailer Connection Caught On Fire-Towed In

- Trailer Connection Caught On Fire-tow From: Century Village To: Lv Shop

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 1507193      **Meter:** 33247      **In Date:** 07/20/2015      **Closed:** 07/27/2015  
**Problem:** Tow in,trailer plug caught fire.

- R&i rear trailer plug connector and burnt wiring.replace connector and wiring.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Trailer Conn Socket	1.00
	5402 Socket Bracket	1.00
	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 12.68
:		Total: 102.68

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1601477      **Meter:** 38245      **In Date:** 02/11/2016      **Closed:** 02/24/2016  
**Problem:** Pm service. Rattle under truck.

<ul style="list-style-type: none"> <li>- Pm service.</li> <li>- Perform rear differential service due to water contamination.</li> <li>- Perform transmission flush service.</li> <li>- Inspect for noise under vehicle.replace six worn body mounts.</li> <li>- Rotate and balance all four tires.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>Napagold Fuel Filter</li> <li>22" Wiper Blade</li> <li>Used Fire X Refurbished</li> <li>Pedal Pad</li> <li>Rpl Bulb</li> <li>75w140 Ford Axle Lube</li> <li>Friction Modifier</li> <li>Brake Cleaner</li> <li>Ptex Ultra Grey 3oz</li> <li>Syn-atf Trans Fluid S</li> <li>Body Mount Kit</li> <li>Body Mount Kit</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>7.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>3.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>18.00</li> <li>2.00</li> <li>4.00</li> <li>1.00</li> </ul>
Hours 12.25 :	Labor: 735.00      Parts: 725.62	Total: 1,460.62

**Workorder:** 1607157      **Meter:** 42160      **In Date:** 07/14/2016      **Closed:** 07/25/2016  
**Problem:** Had jump start .lights left on.

<ul style="list-style-type: none"> <li>- Test battery and charging system.replace bad battery.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Battery</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>1.00</li> </ul>
Hours 1.00 :	Labor: 60.00      Parts: 120.41	Total: 180.41

**Workorder:** 1610265      **Meter:** 44716      **In Date:** 09/30/2016      **Closed:** 10/14/2016  
**Problem:** P.M. service.

<ul style="list-style-type: none"> <li>- P.m. Service.</li> <li>- Replace two tires,rotate and balance all four.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Napagold Oil Filter</li> <li>5w20 Engine Oil</li> <li>Napagold Air Filter</li> <li>22" Wiper Blade</li> <li>179636492 Lt245-75r17</li> <li>Shop Supplies</li> <li>Tire Disposal Fee</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>7.00</li> <li>1.00</li> <li>2.00</li> <li>2.00</li> <li>1.00</li> <li>2.00</li> </ul>
Hours 4.75 :	Labor: 285.00      Parts: 540.84	Total: 825.84

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1705163      **Meter:** 52155      **In Date:** 05/25/2017      **Closed:** 06/02/2017  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Replace two tires and rotate and balance four tires.nitro service.	Napagold Oil Filter	1.00
- Replace two front bump stops.	5w20 Engine Oil	7.00
- Cooling system flush and fill .pressure test and topoff.	22" Wiper Blade	2.00
- Replace passenger side visor holder to hold strobe lamps in place.	Used Fire X Refurbished	1.00
- Perform front end alignment.	Napagold Fuel Filter	1.00
- Shop Supplies	179636492 Lt245-75r17	2.00
	bumper	2.00
	Peak Global Antifrz	2.00
	Retainer	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.25	Labor: 615.00	Parts: 666.11
:		Total: 1,281.11

**Workorder:** 1711800      **Meter:** 54676      **In Date:** 12/01/2017      **Closed:** 12/18/2017  
**Problem:** P.M. service and brakes pull to the right when braking.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Check and replace two rear bump stops.	5w20 Engine Oil	7.00
- Check ,found frozen left front caliper piston.resurface both front rotors.replace pads and both front calipers and front brake hoses.bleed hydraulic brake system.road test.	Napagold Oil Filter	1.00
- Balance and rotate all four tires.	Used Fire X Refurbished	1.00
- Shop Supplies	20" Wiper Blade	2.00
	Bumper	2.00
	Caliper w/ Hardware - Left Front (eclips	1.00
	Caliper w/ Hardware - Right Front (eclip	1.00
	Rear Pads	1.00
	lube	1.00
	B Fluid Dot 3-32oz	1.00
	Brake Hose	1.00
	Brake Hose	1.00
	Shop Supplies	1.00
Hours 9.35	Labor: 561.00	Parts: 457.21
:		Total: 1,018.21

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1809318      **Meter:** 59844      **In Date:** 09/11/2018      **Closed:** 09/19/2018  
**Problem:** P.M. Service.Trailer brake message came up.

- P.m. service .	<b>Parts List</b>	<b>Qty</b>
- Computer diagnose trailer warning . Replace defective trailer plug connector and rewire as needed. No communicate with trailer brake control module . Test and replace trailer brake control module .	Brake Module	1.00
	Napagold Oil Filter	1.00
	5w20 Engine Oil	7.00
- Test and replace right rear turn signal bulb . Replace left rear tail lamp assembly due to water intrusion .	Napagold Fuel Filter	1.00
	Used Fire X Refurbished	1.00
- Rotate and balance all four tires. Nitrogen fill tires.	20" Wiper Blade	2.00
- Shop Supplies	trailer plug	1.00
	Boxed Miniatures	1.00
	Lamp Asy	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 577.42
:		Total: 997.42

**Workorder:** 1905036      **Meter:** 65906      **In Date:** 05/09/2019      **Closed:** 05/20/2019  
**Problem:** P.M. service ,visor lights falling down and windshield cracked.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Test and replace dome light bulb and high mounted stop light bulb .	Napagold Oil Filter	1.00
	5w20 Engine Oil	8.00
- Replace broken left side visor clip and reinstall visor strobe light .	20" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
- Rotate and balance all four tires . Nitrofill all.	Boxed Miniatures	3.00
- Shop Supplies	Boxed Miniatures	3.00
	Retainer	1.00
	Shop Supplies	1.00
Hours 4.60	Labor: 308.20	Parts: 76.44
:		Total: 384.64

**Workorder:** 1905363      **Meter:** 65906      **In Date:** 05/17/2019      **Closed:** 05/22/2019  
**Problem:** replace cracked windsheild

- pre delivery inspection	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

**Workorder:** 1910779      **Meter:** 68874      **In Date:** 10/21/2019      **Closed:** 10/21/2019  
**Problem:** Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00