

**Palm Beach County Fleet Management
Asset Maintenance History**

10171039 2007 TORO 7200 Mower, 62" Ztr, Riding

Workorder: 742249 **Meter:** 0 **In Date:** 07/31/2007 **Closed:** 07/31/2007
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 110.00 Parts: 0.00 Total: 110.00
:

Workorder: 841004 **Meter:** 118 **In Date:** 07/08/2008 **Closed:** 07/11/2008
Problem: P.M.SERVICE,F/FRONT TIRE FLAT

- Pm Service

Parts List

Qty

- C/s R/f Tire Flat; Verify Complaint; R&r Tire; Repack Wheel Bearings & Reinstall	Shop Supplies	1.00
- Clear Grass From All Belts & Pulleys; Clean Out Cooling Sys;remove All Grass & Dust From Radiator/oil Cooler	Hyd Filter	1.00
- Shop Supplies	33583 Fuel Filter Toro	1.00
	6438 Air Filterfrm Ca9550 Wix 46438	1.00
	Ph3593a Oil Filter Lbf Ph2808 Wix 51334	1.00
	3032 Fuel Filter 5/16" Frm G2 Wix 33032	1.00
	1066 White Lithium (crc 05037)	1.00
	15/40 Oil	4.00
	Tire 15.5x6	1.00
	Waste Fee	1.00

Hours 6.00 Labor: 360.00 Parts: 125.95 Total: 485.95
:

Workorder: 847926 **Meter:** 186 **In Date:** 12/08/2008 **Closed:** 01/21/2009
Problem: HYD.FLUID LEAK,L/REAR TIRE LOSES AIR

- Hyd Tank Empty; Add Fluid & Ck For Leak; Clean Off Problem Area; Leaking At L/r Drive Motor Seal

Parts List

Qty

- R&r Tires	Shop Supplies	1.00
- Set Up Hector Turf For Warranty Repair; Bad Left Hand Hyd Motor	Aw68 Hydro Fluid Hydraulic Oil 68	10.00
- Shop Supplies	Tire Disposal Fee	1.00
	511409 24-1200-12 Turfmaster 4ply	1.00

Hours 3.00 Labor: 180.00 Parts: 134.16 Total: 314.16
:

Workorder: 940014 **Meter:** 238 **In Date:** 07/01/2009 **Closed:** 07/06/2009
Problem: P.M.SERVICE/SEE NOTE

- P.m.service

Parts List

Qty

- c/s mower blades damage.verified concern.found bent blade guard.repair guard remove blades and sharpen,test drive	Shop Supplies	1.00
- Shop Supplies	Shop Supplies	1.00
	3032 Fuel Filter 5/16" Frm G2 Wix 33032	1.00
	Ph3593a Oil Filter Lbf Ph2808 Wix 51334	1.00
	33583 Fuel Filter Toro	1.00
	6438 Air Filterfrm Ca9550 Wix 46438	1.00
	15/40 Oil	4.00

Hours 7.00 Labor: 420.00 Parts: 54.79 Total: 474.79
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 940433 **Meter:** 240 **In Date:** 07/07/2009 **Closed:** 07/07/2009
Problem: P.M.SERVICE

- check p.m.service was done on july 6- 2009

Hours 0.25 Labor: 15.00 Parts: 0.00 Total: 15.00
:

Workorder: 1007337 **Meter:** 340 **In Date:** 07/13/2010 **Closed:** 07/19/2010
Problem: P. M. Service, sharpen blades, right chain dislodged from deck.

- P. M. Service.

- Service hydraulic system, R&r filter, correct fluid level.

- Wash equipment, clean debris from radiator & coolers.

- C/c: Sharpen blades. Raise equipment. Remove & sharpen all blads, reinstall.

- C/c: Chain dislodged from deck. Fabricate new chain mount, repair deck damage. Install grease fittings on front damage.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
6438 Air Filterfrm Ca9550 Wix 46438	1.00
3032 Fuel Filter 5/16" Frm G2 Wix 33032	1.00
33583 Fuel Filter Toro	1.00
Ph3593a Oil Filter Lbf Ph2808 Wix 51334	1.00
15/40 Oil	4.00
Aw68 Hydro Fluid Hydraulic Oil 68	6.00

Hours 11.50 Labor: 690.00 Parts: 67.80 Total: 757.80
:

Workorder: 1010088 **Meter:** 362 **In Date:** 09/14/2010 **Closed:** 09/24/2010
Problem: Left front tire flat

- C/c: Lf tire flat. Attempt to repair, unable to repair. R&r tire.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
Tire Disposal Fee	1.00
15x6.00x6 Carlisle Tire	1.00

Hours 1.00 Labor: 60.00 Parts: 51.36 Total: 111.36
:

Workorder: 1107574 **Meter:** 442 **In Date:** 07/19/2011 **Closed:** 07/28/2011
Problem: P. M., Needs new blades, Bolt missing deck passenger side rear

- P. M. Service.

- Service hydraulic system. Inspect all lines & hoses. Replace filter, correct hyd fluid level.

- Wash equipment for service & repair.

- C/c: Sharpen or replace blades. Verify, blades need replacement. Install 3 new blades.

- C/c: Bolt missing from deck. Fabricate bracket for adjuster. Install new bolt, etc. Test mow.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
Hyd. Filter	1.00
6438 Air Filterfrm Ca9550 Wix 46438	1.00
3032 Fuel Filter 5/16" Frm G2 Wix 33032	1.00
33583 Fuel Filter Toro	1.00
Ph3593a Oil Filter Lbf Ph2808 Wix 51334	1.00
15/40 Oil	4.00
Aw68 Hydro Fluid Hydraulic Oil 68	4.00
Blades	3.00

Hours 9.00 Labor: 540.00 Parts: 187.78 Total: 727.78
:

Workorder: 1108913 **Meter:** 454 **In Date:** 08/23/2011 **Closed:** 08/26/2011
Problem: Broken bolt on mower deck left rear side

- C/c: Broken bolt on mower deck. R&r bolt, readjust mower deck, & test mow.

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
Clevis Adjustment	1.00

Hours 2.00 Labor: 120.00 Parts: 19.25 Total: 139.25
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1205812	Meter: 526	In Date: 06/19/2012	Closed: 06/26/2012
Problem: broken chain on deck in back needs blades			
- ck chain on deck broken verify linkage broken replace clevis adj deck	Parts List		Qty
	Shop Supplies		1.00
- ck replace sharpen blades verity blades unable to sharpen replace 3 blades lube spindles	Clevis Adjustment		1.00
	Blades		3.00
- Shop Supplies			
Hours 3.50	Labor: 210.00	Parts: 106.01	Total: 316.01
:			

Workorder: 1210897	Meter: 572	In Date: 11/07/2012	Closed: 11/16/2012
Problem: pm			
- pm	Parts List		Qty
- service hyd sys inspect lines and hoses correct fluid level	Napagold Air Filter		1.00
- wash eq	Fuel Filter ``		1.00
- verify drags on starting test and recharge battery	Ph3593a Oil Filter Lb		1.00
- Shop Supplies	15-40 Oil		4.00
	Napagold Fuel Filter		1.00
	15w40 Bulk South Reg		4.00
	Shop Supplies		1.00
Hours 6.50	Labor: 390.00	Parts: 89.11	Total: 479.11
:			

Workorder: 1302331	Meter: 588	In Date: 03/07/2013	Closed: 03/22/2013
Problem: needs gas cap, new blades, wont start up			
- ck replace blades rr 3 blades lube spindles and test mow	Parts List		Qty
- ck gas cap install new gas cap	Atomic Blade 21.75		3.00
- ck wont start verify needs battery rr battery ck charging system	Fuel Cap		1.00
	Relay		1.00
- repair wiring replace damaged relay	Group 26 Acd		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 4.00	Labor: 240.00	Parts: 274.93	Total: 514.93
:			

Workorder: 1303523	Meter: 589	In Date: 04/10/2013	Closed: 04/18/2013
Problem: broken chain for deck rack right			
- ck deck linkage broken install new linkage components adj test mow	Parts List		Qty
	Clevis Adjust		2.00
- Shop Supplies	Nut		2.00
	Clevis Pin		2.00
	Rue Ring Pin		2.00
	Locknut		2.00
	Shop Supplies		1.00
Hours 1.50	Labor: 90.00	Parts: 73.22	Total: 163.22
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1312006 **Meter:** 653 **In Date:** 12/02/2013 **Closed:** 12/11/2013
Problem: P. M. Service, and flat front tire. (Contact person: Dwayne, 561-523-0947)

	Parts List	Qty
- pm		
- svc hyd sys inspect lines and hoses	Napagold Air Filter	1.00
- ck flat front tire replace two front tires hand mount grease	Napagold Fuel Filter	1.00
bearihgs add n2	Napagold Fuel Filter	1.00
- wash eq	Napagold Oil Filter	1.00
- Shop Supplies	15w40 Bulk South Reg	4.00
	Napa Hydraulic Filtr	1.00
	Aw68 Bulk Sr	2.00
	Tire	2.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 123.85
:		Total: 603.85

Workorder: 1405998 **Meter:** 675 **In Date:** 06/18/2014 **Closed:** 06/26/2014
Problem: BELT OFF FOR BLADES TO ENGAGE

	Parts List	Qty
- ck belt on deck verify bad bushngs on gear box replace	Flange Nut Ni	3.00
brackets bushings bolts belt et c	Washer	3.00
- Shop Supplies	Gearbox Bracket Lh	1.00
	Rubber Mount	3.00
	Bolt	3.00
	Gearbox Bracket Rh	1.00
	Belt	1.00
	Shop Supplies	1.00
Hours 3.50	Labor: 210.00	Parts: 256.18
:		Total: 466.18

Workorder: 1407496 **Meter:** 688 **In Date:** 07/30/2014 **Closed:** 08/12/2014
Problem: NEW BLADES/CUTS UNEVEN CHECK AFTER BLADES INSTALLED.

	Parts List	Qty
- ck needs blades replace blades adj deck greese spindles	Atomic Blade 21.75	3.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 121.39
:		Total: 241.39

Workorder: 1412967 **Meter:** 789 **In Date:** 12/31/2014 **Closed:** 01/09/2015
Problem: pm

	Parts List	Qty
- pm		
- svc hyd sys inspect lines hoses correct fluid level	Napagold Air Filter	1.00
- wash eq	Napagold Fuel Filter	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Napagold Oil Filter	1.00
	15w40 Bulk South Reg	4.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 41.95
:		Total: 401.95

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1505172 **Meter:** 789 **In Date:** 05/21/2015 **Closed:** 05/29/2015
Problem: broken chain left side rear deck

- ck broken chain repair deck on chain adj and test	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.25	Labor: 135.00	Parts: 2.00
:		Total: 137.00

Workorder: 1508109 **Meter:** 789 **In Date:** 08/12/2015 **Closed:** 08/25/2015
Problem: CHAIN BROKE ON DECK, NEEDS NEW BLADES, AIR FILTER COVER, CUTS UNEVEN

- ck deck chains blades etc replace adj chain linkage install	Parts List	Qty
new blades air filter cover	Blade	3.00
- Shop Supplies	Blade Bolt	3.00
	Clevis Adjust	2.00
	Nut	2.00
	Locknut	2.00
	Valve-actuator	1.00
	Air Cleaner Cover Assy	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 310.67
:		Total: 490.67

Workorder: 1603220 **Meter:** 792 **In Date:** 03/28/2016 **Closed:** 04/05/2016
Problem: pm, gas cap needed

- Pm service.	Parts List	Qty
- Service hydraulic system.inspect lines and hoses	Napagold Air Filter	1.00
etc.correct fluid level.	Napagold Fuel Filter	1.00
- C/c gas cap.replace two gas caps.	Napagold Fuel Filter	1.00
- Wash equipment.	Napagold Oil Filter	1.00
- Repair multiple tires.	15w40 Bulk South Reg	4.00
- Shop Supplies	Fuel Cap	2.00
	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 109.66
:		Total: 559.66

Workorder: 1606913 **Meter:** 824 **In Date:** 07/08/2016 **Closed:** 08/17/2016
Problem: SHUTS OFF/WONT SWITCH TANK ONLY WORKS ON ONE SIDE.

- C/c C/k Tires. Replace 4 Tires.mount Add N2.	Parts List	Qty
- Verify Belt Loose. Unscized Tensioners ,replace Gear Box	24-1200-12b Turf M Carl	2.00
Bushings	Tire	2.00
- Verify Air Filter Housing Bad.replace Air Filter Housing	Flange Nut Ni	3.00
Assy.	Rubber Mount	3.00
- C/c Shut Down. Only Runs On One Tank.remove Fuel	Bolt	3.00
Lines&clear Screen. Replace Fuel Filter.test Mow.	Napagold Fuel Filter	1.00
- Shop Supplies	Air Cleaner Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 7.00	Labor: 420.00	Parts: 692.43
:		Total: 1,112.43

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1610302 **Meter:** 828 **In Date:** 09/30/2016 **Closed:** 10/28/2016

Problem: Deck broke screw.Also stalls and loses power after use for a while.

- C/c Stalls A7 Loose Power. Remove Contaminated Fuel Tanks After Sample Bad Fuel. Clean Tanks,lines,screens. R/r Fuel Filter,test Mow Multiple Times.	Parts List	Qty
	Napagold Fuel Filter	1.00
- Repair Deck Linkage And Adjust.	Napagold Fuel Filter	1.00
- Shop Supplies	Clean-r-carb 20oz	1.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 18.23
:		Total: 318.23

Workorder: 1700774 **Meter:** 832 **In Date:** 01/25/2017 **Closed:** 01/31/2017

Problem: Wont start.Sputters.

- C/c sputters..wont run.verify complain.found primary fuel filter clogged.r/r filter.drain fuel seperator found no water or debris.bleed air from system.test run.	Parts List	Qty
	Battery	1.00
- Verify dead battery.loadtest and check charging system.failed battery test.r/r battery.	Napagold Fuel Filter	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.75	Labor: 165.00	Parts: 119.36
:		Total: 284.36

Workorder: 1703518 **Meter:** 832 **In Date:** 04/07/2017 **Closed:** 04/24/2017

Problem: PM Service.

- Pm Service.	Parts List	Qty
- Service and inspect hyd.system,hoses,lines,fittings etc..replace filter.correct fluid level.	Roller	1.00
- Replace front roller,shaft and gear box bushings and hardware.	Shaft,roller	1.00
- Wash equipment.	Washer	3.00
- Shop Supplies	Flange Nut Ni	3.00
	Rubber Mount	3.00
	Bolt	3.00
	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
	Napagold Fuel Filter	1.00
	Napagold Oil Filter	1.00
	15w40 Bulk South Reg	4.00
	Napa Hydraulic Filtr	1.00
	Aw68 Bulk Sr	2.00
	Shop Supplies	1.00
Hours 9.50	Labor: 570.00	Parts: 239.95
:		Total: 809.95

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1712519 **Meter:** 889 **In Date:** 12/19/2017 **Closed:** 01/29/2018
Problem: Water in hydraulic system.New blades and two gas caps

	Parts List	Qty
- Flush fuel system.replace filter and caps.	Fuel Cap	2.00
- Flush hydraulic system and replace filters.	Napagold Fuel Filter	1.00
- Replace three blades and danage grease fittings.	Napagold Fuel Filter	1.00
- Clean radiator,deck and engine compartment before repairs.	Napa Hydraulic Filtr	1.00
- Shop Supplies	Aw68 Bulk Sr	20.00
	Blade	3.00
	Wd40 Spr	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 251.80
:		Total: 731.80

Workorder: 1803751 **Meter:** 901 **In Date:** 04/10/2018 **Closed:** 04/23/2018
Problem: PM Service.Front tire flat.

	Parts List	Qty
- Pm Service.	Napagold Air Filter	1.00
- Service hyd, system Inspect lines hoses etc.	Napagold Fuel Filter	1.00
- Replace two front tires.mount and add N2	Napagold Fuel Filter	1.00
- Replace gearbox bushings.l/h wingnut.	Napagold Oil Filter	1.00
- Wash equipment.	15w40 Bulk South Reg	4.00
- Shop Supplies	15-600-6 Nhs Str Rib 04	2.00
	Knob	1.00
	Rubber Mount	3.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 9.25	Labor: 555.00	Parts: 223.98
:		Total: 778.98

Workorder: 1805549 **Meter:** 911 **In Date:** 05/31/2018 **Closed:** 07/12/2018
Problem: Tire.Also cuts off while mowing.

	Parts List	Qty
- C/c Tire.replace left rear tire.mount and add N2.	24-1200-12b Turf M Carl	1.00
- C/c Cuts off while mowing.replace two fuel filters.	Napagold Fuel Filter	1.00
- Verify under side of seat cracked not holding safety switch properly.replace seat base and switch.test Mow.	Napagold Fuel Filter	1.00
- Shop Supplies	Bail Switch	1.00
	Bottom Cushion Kit	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 5.00	Labor: 300.00	Parts: 533.82
:		Total: 833.82

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810747 **Meter:** 956 **In Date:** 10/18/2018 **Closed:** 11/19/2018
Problem: Deck chain broken.Need two fuel caps

- C/c Deck chain broken.replace multiple linkages and adjust all.	Parts List	Qty
	Locknut	1.00
- Replace fuel caps.	Rue Ring Pin	3.00
- Shop Supplies	Clevis Pin	3.00
	Nut	1.00
	Fuel Cap	2.00
	Clevis Adjust	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
	Freight Charge	1.00
Hours 2.00	Labor: 134.00	Parts: 152.92
:		Total: 286.92

Workorder: 1904470 **Meter:** 988 **In Date:** 04/24/2019 **Closed:** 05/13/2019
Problem: PM Service

- Pm Service.	Parts List	Qty
- Deck bushings and hardware.unseize both deck tensioners and lube.	Napagold Air Filter	1.00
- Service hyd.system.replace filter and correct fluid level.	Napagold Fuel Filter	1.00
- Wash equipment.	Napagold Fuel Filter	1.00
- Shop Supplies	15w40 Bulk South Reg	4.00
	Napagold Oil Filter	1.00
	Bolt	3.00
	Rubber Mount	3.00
	Napa Hydraulic Filtr	1.00
	Shop Supplies	1.00
Hours 9.00	Labor: 603.00	Parts: 128.60
:		Total: 731.60

Workorder: 1912807 **Meter:** 988 **In Date:** 12/16/2019 **Closed:** 12/16/2019
Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			