

**Palm Beach County Fleet Management
Asset Maintenance History**

10195262 2014 FORD ESCAPE Suv, Mid Size

Workorder: 1410577 **Meter:** 181 **In Date:** 10/22/2014 **Closed:** 10/22/2014
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1411251 **Meter:** 1309 **In Date:** 11/10/2014 **Closed:** 11/18/2014
Problem: Right rear tire roll flat,side wall damage.

- Replace and balance one tire.

Parts List **Qty**

- Shop Supplies

P235/55r17 Conti Pro Contact Tire 1.00

Shop Supplies 1.00

Tire Disposal Fee 1.00

Hours 0.50 Labor: 30.00 Parts: 224.31 Total: 254.31
 :

Workorder: 1411288 **Meter:** 773 **In Date:** 11/08/2014 **Closed:** 11/12/2014
Problem: Flat tire on Left Rear

- Tire Service 7301 Haverhill Rd, Wpb (dyer Park) - Flat tire on Left Rear

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 1411820 **Meter:** 2385 **In Date:** 11/21/2014 **Closed:** 12/04/2014
Problem: Left rear tire flat.

- Repair flat left rear tire and balance.

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
 :

Workorder: 1412492 **Meter:** 3310 **In Date:** 12/15/2014 **Closed:** 12/16/2014
Problem: Right rear tire flat.

- Repair flat and balance right rear tire.

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
 :

Workorder: 1501560 **Meter:** 7843 **In Date:** 02/11/2015 **Closed:** 02/19/2015
Problem: Pm service.

- Pm service.

Parts List **Qty**

- Rotate and balance all four tires.

5w20 Engine Oil 6.00

- Shop Supplies

Napagold Oil Filter 1.00

Washer Fluid Concentr 1.00

Shop Supplies 1.00

Hours 3.00 Labor: 180.00 Parts: 22.60 Total: 202.60
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1505048	Meter: 16185	In Date: 05/19/2015	Closed: 05/27/2015
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Repair flat left rear tire.rotate and balance all four.		Napagold Oil Filter	1.00
- Shop Supplies		5w20 Engine Oil	5.00
		Accufit Beam	2.00
		Blade	1.00
		Mac Wite Lithium Gres	1.00
		Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 73.37	Total: 313.37
:			

Workorder: 1508749	Meter: 25065	In Date: 09/01/2015	Closed: 09/16/2015
Problem: Pm service.Damage to front and rear bumpers and rear hatch.			
- Pm service.		Parts List	Qty
- Replace and balance all four tires.		Washer Fluid Concentr	1.00
- Complete front rear end alignment.		5068 Penetrating Oil	1.00
- Shop Supplies		235/55r17 Assurance	4.00
		Used Fire X Refurbished	1.00
		5w20 Engine Oil	5.00
		Napagold Oil Filter	1.00
		Accufit Beam	2.00
		Blade	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	4.00
Hours 6.50	Labor: 390.00	Parts: 688.59	Total: 1,078.59
:			

Workorder: 1510625	Meter: 26200	In Date: 09/09/2015	Closed: 10/21/2015
Problem: damage to bumpers & grille			
- damage to bumpers & grille			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1600479	Meter: 31879	In Date: 01/14/2016	Closed: 02/08/2016
Problem: Pm service.Pulls to right side.			
- Pm service.		Parts List	Qty
- Perform transmission flush service.		5w20 Engine Oil	6.00
- Rotate and balance all four tires.		Napagold Oil Filter	1.00
- Perform complete wheel alignment to correct right pull condition.test drive.		Accufit Beam	2.00
- Transport vehicle to and from dealer for repairing engine oil leak.		Washer Fluid Concentr	1.00
- Shop Supplies		Syn-atf Trans Fluid S	8.00
		Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 89.29	Total: 629.29
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1604058	Meter: 36074	In Date: 04/18/2016	Closed: 04/28/2016
Problem: Check battery and screw in right rear tire.			
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.	Parts List		Qty
	Bxt96r 59		1.00
- Replace and balance two tires.	235/55r17 Assurance		2.00
- Shop Supplies	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 2.00	Labor: 120.00	Parts: 438.27	Total: 558.27
:			

Workorder: 1604846	Meter: 37306	In Date: 05/09/2016	Closed: 06/17/2016
Problem: P.M. service.			
- P.m. Service.	Parts List		Qty
- Replace two tires,rotate and balance all four.	5w20 Engine Oil		6.00
- Transport vehicle to dealer for oil leak.(front cover)	Napagold Oil Filter		1.00
- Shop Supplies	Washer Fluid Concentr		2.00
	Accufit Beam		2.00
	235/55r17 Assurance		2.00
	Used Fire X Refurbished		1.00
	Blade		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 6.00	Labor: 360.00	Parts: 382.16	Total: 742.16
:			

Workorder: 1607576	Meter: 40767	In Date: 07/25/2016	Closed: 07/28/2016
Problem: Engine skid plate hanging down.			
- R&r damaged skid plate and repair.install sterering wheel cover.	Parts List		Qty
	Stg Wheel Cov - Ford		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 18.74	Total: 78.74
:			

Workorder: 1608405	Meter: 42498	In Date: 08/15/2016	Closed: 08/23/2016
Problem: P.M. service.			
- P.m. Service.	Parts List		Qty
- Replace two tires,rotate and balance all fpur.	5w20 Engine Oil		6.00
- Shop Supplies	Napagold Oil Filter		1.00
	Accufit Beam		2.00
	Wpr/blde		1.00
	235/55r17 Assurance		2.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 4.00	Labor: 240.00	Parts: 349.05	Total: 589.05
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1609447 **Meter:** 44595 **In Date:** 09/12/2016 **Closed:** 09/27/2016

Problem: Right brake light inop and water in lens.

- R&r right tail light assemble.seal strobe light and replace brake lamp bulb.	Parts List	Qty
	Right Real Lamp. Asy	1.00
- Shop Supplies	Bulb	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 226.28
:		Total: 286.28

Workorder: 1611247 **Meter:** 46834 **In Date:** 10/31/2016 **Closed:** 11/03/2016

Problem: No crank/no start.

- Recharge battery and test charging system.battery fail load test.replace defective battery.	Parts List	Qty
	Battery	1.00
- Replace left brake lamp bulb.	Bulb	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 161.12
:		Total: 251.12

Workorder: 1611495 **Meter:** 48347 **In Date:** 11/07/2016 **Closed:** 11/22/2016

Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Rotate and balance tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Oil Filter	1.00
	Accufit Beam	2.00
	Wpr/blde	1.00
	Used Fire X Refurbished	1.00
	Mac Wite Lithium Gres	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 81.61
:		Total: 261.61

Workorder: 1701205 **Meter:** 54316 **In Date:** 02/06/2017 **Closed:** 03/01/2017

Problem: P.M. service and recall 16S30.

- P.m. Service.	Parts List	Qty
- R&r seat for upholstery repairs.	5w20 Engine Oil	6.00
- Pressure test and inspect cooling system.flush and refill system.	Napagold Oil Filter	1.00
	Wiper Blade	1.00
- Replace and balance four new tires.	Wiper Blade	1.00
- Complete wheel alignment.test drive.	Anti Freeze Motorcraft	1.00
- Transport vehicle to dealer for recall #16s30.	P235 55r17 Fuel Max	4.00
- Shop Supplies	Seat R And R	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 11.50	Labor: 690.00	Parts: 1,014.72
:		Total: 1,704.72

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1704051 **Meter:** 55938 **In Date:** 04/04/2017 **Closed:** 04/24/2017
Problem: Description of repairs: Damage to left front fender, left front door, left front hub cap possible steering. Need separat
- Description of repairs: Damage to left front fender, left front door, left front hub cap possible steering. Need separat
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1706031 **Meter:** 59531 **In Date:** 06/19/2017 **Closed:** 06/29/2017
Problem: P.M. Service.
- P.m. Service.
- Diagnose and replace inop takedown lamps mounted in lightbar.
- Resurface front brake rotors,replace front pads.service and lube calipers.flush and bleed system.
- Rotate and balance tires.
- Shop Supplies
Parts List
5w20 Engine Oil Qty 6.00
Napagold Oil Filter Qty 1.00
Napa Air Filter Qty 1.00
Washer Fluid Concentr Qty 1.00
Bulb Qty 3.00
Brake Pad Qty 1.00
Brk Fluid Dot 4-12oz Qty 1.00
Non-chlor Brake Clnr Qty 1.00
Hi Int Led Takedown Justice Qty 2.00
Shop Supplies Qty 1.00
Freight Charge Qty 1.00
Hours 7.00 Labor: 420.00 Parts: 574.84 Total: 994.84
:

Workorder: 1706580 **Meter:** 60223 **In Date:** 07/05/2017 **Closed:** 07/10/2017
Problem: Replace fire extinguisher it was used.
- Replace spent fire extinguisher.
Parts List
Used Fire X Refurbished Qty 1.00
Hours 0.20 Labor: 12.00 Parts: 13.98 Total: 25.98
:

Workorder: 1708742 **Meter:** 63375 **In Date:** 09/05/2017 **Closed:** 09/07/2017
Problem: Left rear tire going flat.
- Repair left rear tire and balance .nitrogen fill tires.
- Shop Supplies
Parts List
Shop Supplies Qty 1.00
Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1708812 **Meter:** 64199 **In Date:** 09/07/2017 **Closed:** 09/21/2017
Problem: Left rear tire flat ,spare on vehicle.Right headlight inop.
- Replace left rear tire and balance .nitrogen fill tires.
- Test and replace right headlight bulb.retest.
- Shop Supplies
Parts List
P235 55r17 Fuel Max Qty 1.00
Halogen Bulb Qty 1.00
Shop Supplies Qty 1.00
Tire Disposal Fee Qty 1.00
Hours 1.00 Labor: 60.00 Parts: 186.15 Total: 246.15
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1709170 **Meter:** 64199 **In Date:** 09/21/2017 **Closed:** 09/21/2017
Problem: Emergency Service

- Tire Service okeeheelee park next to restroom - Emergency Service

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 1709253 **Meter:** 64551 **In Date:** 09/25/2017 **Closed:** 09/27/2017
Problem: P.M. Service.Left head light out.

- P.m. service.

- Test and replace failed left low beam bulb.

- Rotate and balance four tires.nitrofill.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Halogen Bulb	1.00
Shop Supplies	1.00

Hours 3.50 Labor: 210.00 Parts: 32.30 Total: 242.30
 :

Workorder: 1710807 **Meter:** 66806 **In Date:** 11/01/2017 **Closed:** 11/02/2017
Problem: Right brake light inop.

- Test and replace right brake light bulb.retest.

Parts List	Qty
Bulb	2.00

Hours 0.30 Labor: 18.00 Parts: 1.56 Total: 19.56
 :

Workorder: 1712108 **Meter:** 69542 **In Date:** 12/11/2017 **Closed:** 12/18/2017
Problem: P.M. service.

- P.m. service.

- Replace both front tires.rotated and balanced all four tires.nitrogen filled tires.

- Replaced both serpentine belts.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Blade	1.00
P235 55r17 Fuel Max	2.00
A/c V Belt	1.00
V Belt	1.00
Wheel Cover	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 5.60 Labor: 336.00 Parts: 548.79 Total: 884.79
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1802914 **Meter:** 74399 **In Date:** 03/19/2018 **Closed:** 03/29/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replace one tire and nitrogen fill.rotate and high speed balance all four tires.	5w20 Engine Oil	6.00
	Napagold Oil Filter	1.00
- Resurface rear rotors and service rear calipers.replace rear beake pads and flush and bleed brake system .road test.	Wiper Blade	1.00
	Wiper Blade	1.00
- Shop Supplies	Blade	1.00
	Used Fire X Refurbished	1.00
	Brake Pad Real	1.00
	Shop Supplies	1.00
	P235/55r17 Tire	1.00
Hours 7.50	Labor: 450.00	Parts: 274.45
:		Total: 724.45

Workorder: 1809035 **Meter:** 79084 **In Date:** 08/31/2018 **Closed:** 09/04/2018
Problem: Slow leak in front passenger side tire.

- Repair right front tire . Balance and nitrofill .	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1809091 **Meter:** 79205 **In Date:** 09/04/2018 **Closed:** 09/10/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replace two tires . Rotate and high speed balance all four tires. Nitrofill tires.	Napagold Oil Filter	1.00
	5w20 Engine Oil	6.00
- Complete four wheel alignment and road test.	Washer Fluid Concentr	1.00
- Shop Supplies	Blade	1.00
	Wiper Blade	1.00
	Wiper Blade	1.00
	235/55r17 Assurance	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.50	Labor: 390.00	Parts: 395.91
:		Total: 785.91

Workorder: 1811192 **Meter:** 81595 **In Date:** 10/30/2018 **Closed:** 10/31/2018
Problem: Left rear tire going flat.

- Repair left rear tire and balance . Nitrofill all tires.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1812805 **Meter:** 83808 **In Date:** 12/17/2018 **Closed:** 12/26/2018
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. service. - Replace two worn tires . Balance and rotate all four tires. Nitrofill all. - Diagnose noise on turns . R&r both front defective axle shafts . Retest . - Complete alignment and road test. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Napa Quart 5w20</td><td></td><td align="right">6.00</td></tr> <tr><td>2pc Hd Mat Set Blk</td><td></td><td align="right">1.00</td></tr> <tr><td>Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Used Fire X Refurbished</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire235/55/17 Mic</td><td></td><td align="right">2.00</td></tr> <tr><td>Axle Nut</td><td></td><td align="right">2.00</td></tr> <tr><td>Left Front Axle</td><td></td><td align="right">1.00</td></tr> <tr><td>Shaft Assy Motorcraft</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">2.00</td></tr> </tbody> </table>	Parts List		Qty	Napagold Oil Filter		1.00	Napa Quart 5w20		6.00	2pc Hd Mat Set Blk		1.00	Blade		1.00	Wiper Blade		1.00	Wiper Blade		1.00	Used Fire X Refurbished		1.00	Tire235/55/17 Mic		2.00	Axle Nut		2.00	Left Front Axle		1.00	Shaft Assy Motorcraft		1.00	Shop Supplies		1.00	Tire Disposal Fee		2.00	
Parts List		Qty																																										
Napagold Oil Filter		1.00																																										
Napa Quart 5w20		6.00																																										
2pc Hd Mat Set Blk		1.00																																										
Blade		1.00																																										
Wiper Blade		1.00																																										
Wiper Blade		1.00																																										
Used Fire X Refurbished		1.00																																										
Tire235/55/17 Mic		2.00																																										
Axle Nut		2.00																																										
Left Front Axle		1.00																																										
Shaft Assy Motorcraft		1.00																																										
Shop Supplies		1.00																																										
Tire Disposal Fee		2.00																																										
Hours 10.50	Labor: 703.50	Parts: 1,023.76	Total: 1,727.26																																									
:																																												

Workorder: 1903067 **Meter:** 88543 **In Date:** 03/20/2019 **Closed:** 03/28/2019
Problem: Driver side rear tail light out. P.M. service.

<ul style="list-style-type: none"> - Replace melted left rear lamp assembly . Drill strobe mount . - P.m. service. - Charge battery fully . Test battery and charging system . R&r failed battery . - Replace two front tires and balance all four tires . Nitrofill all. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Lamp Asy</td><td></td><td align="right">1.00</td></tr> <tr><td>Ford Triton Pvc Swc</td><td></td><td align="right">1.00</td></tr> <tr><td>Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Napa Air Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">6.00</td></tr> <tr><td>Battery</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire235/55/17 Mic</td><td></td><td align="right">2.00</td></tr> <tr><td>Arm Wiper Asy</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">2.00</td></tr> </tbody> </table>	Parts List		Qty	Lamp Asy		1.00	Ford Triton Pvc Swc		1.00	Blade		1.00	Wiper Blade		1.00	Wiper Blade		1.00	Napa Air Filter		1.00	Napagold Oil Filter		1.00	5w20 Engine Oil		6.00	Battery		1.00	Tire235/55/17 Mic		2.00	Arm Wiper Asy		1.00	Shop Supplies		1.00	Tire Disposal Fee		2.00	
Parts List		Qty																																										
Lamp Asy		1.00																																										
Ford Triton Pvc Swc		1.00																																										
Blade		1.00																																										
Wiper Blade		1.00																																										
Wiper Blade		1.00																																										
Napa Air Filter		1.00																																										
Napagold Oil Filter		1.00																																										
5w20 Engine Oil		6.00																																										
Battery		1.00																																										
Tire235/55/17 Mic		2.00																																										
Arm Wiper Asy		1.00																																										
Shop Supplies		1.00																																										
Tire Disposal Fee		2.00																																										
Hours 6.00	Labor: 402.00	Parts: 809.20	Total: 1,211.20																																									
:																																												

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1905249 **Meter:** 91258 **In Date:** 05/15/2019 **Closed:** 05/23/2019
Problem: Towed in for overheating .

<ul style="list-style-type: none"> - Perform cooling system pressure test and inspection . Replace leaking heater hoses ,upper radiator hose , bypass hose and thermostat .refill coolant and retest. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Anti Freeze Motorcraft Thermostat Hose Heater Hose Hea Tank Asy Hose Hose Heater Hose Hea Hose Hea Hose Hea Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 	
Hours 8.40 :	Labor: 562.80	Parts: 573.50	Total: 1,136.30

Workorder: 1905280 **Meter:** 91143 **In Date:** 05/15/2019 **Closed:** 05/15/2019
Problem: overheating

<ul style="list-style-type: none"> - Tow From: Park Ranger office 	Hours 0.00 :	Labor: 0.00	Parts: 0.00	Total: 0.00
--	-----------------	-------------	-------------	-------------

Workorder: 1906594 **Meter:** 93435 **In Date:** 06/24/2019 **Closed:** 07/02/2019
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. service. - Replace missing left front door handle trim . - Rotate and high speed balance all four tires . Nitro fill all - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Napagold Oil Filter 5w20 Engine Oil Wiper Blade Wiper Blade Blade Washer Fluid Concentr Interior Door Handle Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00 	
Hours 3.20 :	Labor: 214.40	Parts: 122.79	Total: 337.19

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1909485 **Meter:** 98385 **In Date:** 09/16/2019 **Closed:** 09/23/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Inspect all tires . Replace two tires and repair left rear tire . Rotate and balance all four tires . Nitrofill all .	Napagold Oil Filter	1.00
	5w20 Engine Oil	6.00
- Resurface both front brake rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test .	Wiper Blade	1.00
	Wiper Blade	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Blade	1.00
	Tire235/55/17 Mic	2.00
	Non-chlor Brake Clnr	1.00
	Brk Fluid Dot 4-12oz	1.00
	Brake Pad	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 7.50	Labor: 502.50	Parts: 545.20
:		Total: 1,047.70

Workorder: 1911941 **Meter:** 100778 **In Date:** 11/19/2019 **Closed:** 11/19/2019
Problem: remove decals for surplus

- remove decals for surplus	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 73.00	Parts: 4.00
:		Total: 77.00

Workorder: 1911966 **Meter:** 100778 **In Date:** 11/19/2019 **Closed:** 11/19/2019
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00