



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V13201

In Date: 02/12/2008
Close Date: 02/28/2008

Meter Reading: 118.00

Problem?

INSTALL NEW LIGHTS IN REAR OF TRUCK

Task performed:

1. Install work lights, installed battery charger and auto eject system

Parts	Quantity
091-20WP-120AUTO EJECT	1
0913912CHARGER 2000	1
KR-CCLCATHODE COMPARTMENT LIGHT	2

Workorder: V13714

In Date: 03/06/2008
Close Date: 03/07/2008

Meter Reading: 118.00

Problem?

ON CALL DC2 NO EMERGENCY LTS

Task performed:

1. Drive to St 28, check out wires and replace blown fuse for emergency lights on DC2

Parts	Quantity
NO PARTS USED	

Workorder: V13058

In Date: 02/05/2008
Close Date: 05/14/2008

Meter Reading: 118.00

Problem?

TINT FRONT WINDOWS DC-3

Task performed:

Tint front windows DC3 - 60 Minute Auto j

Parts	Quantity
NO PARTS USED	

10174222, 10174223, 10174225, 10174226

Vendor?: 60 MIN AUTO TINT

Workorder: V16083

In Date: 07/01/2008
Close Date: 07/21/2008

Meter Reading:

Problem?

drivers window will not go up dc3

Task performed:

1.check unit, no problem found at this time

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V16352

In Date: 07/14/2008
Close Date: 07/21/2008

Meter Reading: 6,017.00

Problem?

SET UP NEW VEHICLE, INSTALL COMMAND CABINET DC-3

Task performed:

1. Vac 7/2-7/3 & 7/11/08.
2. install wiring, box & mount; install hand lights & tig; install for warn wire up box; install radio cabling, etc.
3. Install wiring & cab in DC 3. j

Parts	Quantity
5025TERMINAL BOX	1
PD2343BACKUP RADAR	1

Workorder: V16521

In Date: 07/22/2008
Close Date: 07/28/2008

Meter Reading:

Problem?

Check engine light is on. (Just came back from shop for installation of "command center").bc3

Task performed:

1sent unit to roger dean chevrolet for warranty repair.

Parts	Quantity
NO PARTS USED	

Workorder: V17713

In Date: 09/15/2008
Close Date: 09/29/2008

Meter Reading: 9,679.00

Problem?

on call dc3 battery dead

Task performed:

DC 3 stated unit dead, found shore lone unplugged - unit was running when arrived, check charge system 13.9 volts. All system operating normal at time.

Parts	Quantity
NO PARTS USED	

Workorder: V18658

In Date: 10/28/2008
Close Date: 10/31/2008

Meter Reading: 11,566.00

Problem?

DEAD BATTERY DC3

Task performed:

Drive to stn; C/O truck; when I arrived, truck was running; chk charging/battery; both ok; was not plugged in at station. j

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V19515

In Date: 12/04/2008

Meter Reading:

Close Date: 01/02/2009

Problem?

Please order rubber floor mats and clothe seat covers for the 08 suburban.

Task performed:

Dropped off floor mats & seat covers. j

Parts

Quantity

31411FLOOR MATS

1

SSC-3SEAT COVERS

1

Workorder: V20220

In Date: 01/08/2009

Meter Reading: 212.00

Close Date: 01/27/2009

Problem?

Bolt in left rear tire. Screw in left front tire. Will be at HQ 0830-1000. dc3

Task performed:

Bolt in left rear tire; screw in left front tire; will be at HQ DC3 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLGHAN

Workorder: V20478

In Date: 01/20/2009

Meter Reading:

Close Date: 01/28/2009

Problem?

Batteries died on 1/19 after unit being off for 2 hrs without shoreline. On shoreline units starts properly. DC-3

Task performed:

1- found no problem with system and tested ok.

Parts

Quantity

NO PARTS USED

Workorder: V16687

In Date: 07/29/2008

Meter Reading: 7,075.00

Close Date: 03/02/2009

Problem?

lost power on control panel when activating rumbler D/C 3

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V17896

In Date: 09/23/2008

Meter Reading:

Close Date: 03/02/2009

Problem?

low buzz noise in the rear speaker when at idle.battery died after only several hours off of the shore line. low engine power when trying to accelerate.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V19510

In Date: 12/04/2008

Meter Reading:

Close Date: 03/02/2009

Problem?

install another battery to maintain starting power - truck's battery dies frequently. dc3

Task performed:

Parts

Quantity

Will do at B-Inspection j

NO PARTS USED

Workorder: V16880

In Date: 08/06/2008

Meter Reading: 7,364.00

Close Date: 03/04/2009

Problem?

DC-3 (HAUBERT) WENT TO ROGER DEAN TO HAVE SPARE KEY MADE FOR NEW VEHICLE

Task performed:

Parts

Quantity

DC3 (Haubert) went to Roger Dean to have spare key made for new vehicle - Delray Lincoln j

NO PARTS USED

Vendor?: DELRAY LINCOLN



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V21672

In Date: 03/10/2009
Close Date: 03/27/2009

Meter Reading: 17,788.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC3 CHECK CHARGER AND AUTO EJECT BATTERY SEEMS TO GO DEAD OFTEN.

Task performed:

1. Dead btry; jump start veh; charge btry.
2. B-Inspection.
3. Install 2nd btry, cables & hold down.
3. Meeting.
4. Fuel fork lift & unload truck.
5. Change spare with R-frnt; road test. j

Parts	Quantity
15888242F-CABLE	1
15W40BSYN OIL BULK QTS	6
24-60BATTERY GROUP 24	1
24F-60BATTERY	1
356668USE 14005061 BAT HOLD DOWN	1
42487USE CA8756 AIR FILTER	1
57060OIL FILTER	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

Workorder: V22083

In Date: 03/25/2009
Close Date: 03/30/2009

Meter Reading: 18,219.00

Problem?

INSTALL RUMBLER, DC-3

Task performed:

1. Install frnt grilleTIR6 LED lamp asys; wire in new fixtures.
2. Start install on rumbler.
3. Finish up rumbler install; wire up unit & timer unit; finish up; cln up shop. j

Parts	Quantity
50R03ZCRLIGHT LED RED TIR 6	2
54-871PLCIRCUIT BREAKER 100 AMP	1
5TSMACMOUNT 500 TIR SER CHROME	2
SWT54916V2D1000B-00000-000 SW ROCKER SPST NON-I	1
SWT5492744435 ACTUATOR-BLACK	1

Workorder: V21987

In Date: 03/21/2009
Close Date: 04/03/2009

Meter Reading:

Problem?

Shore-line battery charge indicator shows only battery #1 charging. Battery #2 shows 1 bar only. DC3

Task performed:

- Truck only has (1) btry in truck. j

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V22993

In Date: 05/03/2009

Meter Reading:

Close Date: 05/26/2009

Problem?

4/30 came to shop because the siren was not working on a call, then it worked. Today the lights were working responding to a call and then stopped. Now they work. Siren is OK today. DC3

Task performed:

Parts

Quantity

1. C/O siren; fnd no problem at this time.
2. Brakes not stopping; road tested; tested ok. j

NO PARTS USED

Workorder: V23882

In Date: 06/08/2009

Meter Reading:

Close Date: 07/06/2009

Problem?

Portable battery charger on DC3 not working. Light are on but no one is home.

Task performed:

Parts

Quantity

rep brkn wires on charger. j

NO PARTS USED

Workorder: V21986

In Date: 03/21/2009

Meter Reading:

Close Date: 08/25/2009

Problem?

Please remove rear bench seat and replace with aluminum diamond plate platform. Install protection cage. DC 3

Task performed:

Parts

Quantity

1. Fab floor plate & weld up; fab new floor plate.
2. Install divider in truck; install floor pan; finish welding; move radio & rewire. j

NO PARTS USED

Workorder: V25539

In Date: 08/15/2009

Meter Reading:

Close Date: 09/11/2009

Problem?

Left-rear pax door lock not working electronically. dc3

Task performed:

Parts

Quantity

1. C/O door & will send to dealer.
2. rep rear LED light that was out. j

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V25563

In Date: 08/16/2009
Close Date: 09/11/2009

Meter Reading: 25,380.00

Problem?

Door locks, driver's side front door and driver's side back door do not work electronically. Rear, right strobe does not work. DC3

Task performed:

- 1. Dome light out; rep switch.
- 2. Realigned headlights.

j

Parts

Quantity

NO PARTS USED

Workorder: V25906

In Date: 08/31/2009
Close Date: 09/14/2009

Meter Reading: 26,096.00

Problem?

repair flat dc 3 tiresoles

Task performed:

Repair flat DC3 - Tiresoles

j

Parts

Quantity

NO PARTS USED

Vendor?: TIRESOLES

Workorder: V25987

In Date: 09/03/2009
Close Date: 09/30/2009

Meter Reading:

Problem?

Right tail light strobe out. OK to repair during PM scheduled soon. DC3

Task performed:

replcd rear strobe light,.

j

Parts

Quantity

NO PARTS USED

Workorder: V27675

In Date: 11/16/2009
Close Date: 01/15/2010

Meter Reading:

Problem?

Reccurent low pressure warning left rear tire. "Whopping" noise from front tires at high speeds. Will take to Callaghan tire this AM to check rear tire pressure. Advise on front tire check please. 308-4113 (outside agency-callaghan tire)

Task performed:

DC3 took to Callaghan

j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V29255

In Date: 01/19/2010
Close Date: 01/19/2010

Meter Reading: 32,887.00

Problem?

B inspection and repairs D/C3 (performed by-al packer ford)

Task performed:

B inspection and repairs performed by al packer ford

Parts

NO PARTS USED

Quantity

Workorder: V28988

In Date: 01/11/2010
Close Date: 02/10/2010

Meter Reading: 32,554.00

Problem?

on call wont start dc3

Task performed:

Auto-eject acting up; replc auto-eject; shoreline charger worked intermittent; wne to shop to get new charger; when return to stn; fnd btry too hot; bad cell; replcd btry. j

Parts

091-20WP-120AUTO EJECT
24-60BATTERY GROUP 24
65-72BXT65750 BATTERY
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

Quantity

1
1
1
2

Workorder: V29324

In Date: 01/21/2010
Close Date: 02/10/2010

Meter Reading: 32,887.00

Problem?

repair battery wiring and rewire modem D/C3

Task performed:

Replc btry; rep wiring. j

Parts

24F-60BATTERY
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

Quantity

1
1

Workorder: V29184

In Date: 01/15/2010
Close Date: 02/25/2010

Meter Reading: 32,554.00

Problem?

B inspection and repairs D/C3 (outside agency-al packer ford)

Task performed:

B-Inspection/repair - Al Packer j

Parts

NO PARTS USED

Quantity

Vendor?: AL PACKER



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V31793

In Date: 04/26/2010 Meter Reading: 32,554.00
Close Date: 04/30/2010

Problem?

oil leak and runs rough (on call) dc3

Task performed:

Replc filter oil & clnd air filter. j

Parts

Quantity

NO PARTS USED

Workorder: V31778

In Date: 04/25/2010 Meter Reading: 37,363.00
Close Date: 05/25/2010

Problem?

DC3 Vehicle - Battery 2 shows low when plugged into smart charge. Will not charge.

Task performed:

Tested btry & tested all ok; unit is charging. j

Parts

Quantity

NO PARTS USED

Workorder: V33038

In Date: 06/21/2010 Meter Reading: 40,158.00
Close Date: 06/30/2010

Problem?

B inspection and repairs D/C3 (outside agency-al packer ford)

Task performed:

B-Inspection/repairs DC3 - Al Packer j

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER FORD

Workorder: V33070

In Date: 06/23/2010 Meter Reading: 40,179.00
Close Date: 07/01/2010

Problem?

replace 2 front tires D/C3 (outside agency-callaghan tire)

Task performed:

Replc (2) frnt tires DC3 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN TIRE



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V28984

In Date: 01/11/2010
Close Date: 07/08/2010

Meter Reading: 32,554.00

Problem?

replace batterys dc3

Task performed:

Parts	Quantity
48-60BATTERY	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

Workorder: V34583

In Date: 08/28/2010
Close Date: 09/29/2010

Meter Reading: 42,474.00

Problem?

Overhead light above command area in back of DC3 is loose and hanging down by it's wires. Dc3

Task performed:

Parts	Quantity
Rep lights that were falling off rear. j	NO PARTS USED

Workorder: V34975

In Date: 09/15/2010
Close Date: 10/06/2010

Meter Reading: 43,766.00

Problem?

tow from sta 31 to shumacher buick (outside agency-westway towing)

Task performed:

Parts	Quantity
Request cancelled per Mike Lehan j	NO PARTS USED

Workorder: V35001

In Date: 09/16/2010
Close Date: 10/18/2010

Meter Reading: 43,766.00

Problem?

vehicle won't start D/C3 (outside agency-schumacher buick)

Task performed:

Parts	Quantity
Veh wont start DC3 - Schumacher j	NO PARTS USED

Vendor?: SCHUMACHER



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V36593

In Date: 11/21/2010

Meter Reading: 46,544.00

Close Date: 12/15/2010

Problem?

Tail light strobes out.

Task performed:

Parts

Quantity

(1) TRAVELED TO STATION 91 TO REPAIR TAIL LIGHT STROBE LIGHTS ON DC3. CHECKED OUT AND FOUND REAR STROBES NOT WORKING. REPLACED STROBES. WORKING OK.

NO PARTS USED

(2) FOUND REAR BRAKE LIGHTS NOT WORKING ON DC3. BRAKE SWITCH HAD BAD CONNECTION. REPAIRED CONNECTION. TESTED BRAKE LIGHT, WORKING OK NOW.
J.W.

Workorder: V37328

In Date: 12/21/2010

Meter Reading: 4,779.00

Close Date: 12/21/2010

Problem?

repair howler

Task performed:

Parts

Quantity

parts only no labor

HOWLERSIREN

2

Workorder: V35260

In Date: 09/28/2010

Meter Reading: 44,006.00

Close Date: 12/22/2010

Problem?

TIC charging base possibly not functioning. DC3

Task performed:

Parts

Quantity

(1) TRAVELD TO BAT3 HQ TO FIX POSSIBLE TIC BASE IN DC3 VEHICLE.

NO PARTS USED

CHECKED UNIT AND FOUND BROKEN WIRES. REPAIRED THE WIRES AND TESTED OK.
J.W.



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V36626

In Date: 11/23/2010

Meter Reading: 46,666.00

Close Date: 12/22/2010

Problem?

Batt 110 charger inop batt 3

Task performed:

Parts

Quantity

(1) TRAVELED TO ST 23 TO REPAIR SHORELINE CHARGING SYSTEM FOR DC-3 VEHICLE. REPLACED A FUSE IN THE CHARGER. OK. J.W.

NO PARTS USED

Workorder: V37118

In Date: 12/13/2010

Meter Reading: 47,758.00

Close Date: 12/22/2010

Problem?

B inspection and repairs D/C3

Task performed:

Parts

Quantity

- B-Inspection
- 2. Isntall R/frnt marker lite & t-signal bulb.
- 3. Chk cruise cntrl; _____ . j

194BULB

1

3157NAAMBER BULB

1

Workorder: V37279

In Date: 12/20/2010

Meter Reading: 4,779.00

Close Date: 01/10/2011

Problem?

BATTERY CHARGER 10- 7 ON CALL

Task performed:

Parts

Quantity

Shore charge inop; cld not find problem w/power; suspect charger faulty; DC swapped into spare that was already at stn. j

NO PARTS USED

Workorder: V37278

In Date: 12/20/2010

Meter Reading: 4,779.00

Close Date: 01/11/2011

Problem?

BATTERY CHARGER 10- 7

Task performed:

Parts

Quantity

Replcd btrys & tested. j

0913912CHARGER 2000

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V37416

In Date: 12/27/2010
Close Date: 01/11/2011

Meter Reading: 48,051.00

Problem?

Please install larger screw in lower right corner of SCBA bottle retaining net. Glue in the track of the finishing strip may help also. S.H.D/C91

Task performed:

1. Rep rear netting for air bottles.
2. Rep 12 volt chargers that had no power. j

Parts

Quantity

NO PARTS USED

Workorder: V37415

In Date: 12/27/2010
Close Date: 02/08/2011

Meter Reading: 48,051.00

Problem?

Shore line not charging batteries. No bars showing on indicator. S.H. Sta 91 d/c

Task performed:

- Rep bad connection at 100 plug. j

Parts

Quantity

24-60BATTERY GROUP 24

1

24F-60BATTERY

1

65-72BXT65750 BATTERY

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

3

Workorder: V37905

In Date: 01/19/2011
Close Date: 02/25/2011

Meter Reading: 49,026.00

Problem?

Left brake light out. DC3

Task performed:

- Replcd left side bulb in brake light. j

Parts

Quantity

NO PARTS USED

Workorder: V38468

In Date: 02/13/2011
Close Date: 03/09/2011

Meter Reading: 50,513.00

Problem?

right break light out. dc3

Task performed:

- Replcd bulb in rear taillight. j

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V39313

In Date: 03/20/2011

Meter Reading: 52,248.00

Close Date: 04/06/2011

Problem?

T.I.C. base not charging the T.I.C. - will charge the spare battery. S.H. DC3

Task performed:

Parts

Quantity

Clnd contacts on TIC & tested. j

NO PARTS USED

Workorder: V39441

In Date: 03/25/2011

Meter Reading: 52,248.00

Close Date: 04/06/2011

Problem?

TIC wont charge in holder. sta. 91.

Task performed:

Parts

Quantity

Clnd contacts on TIC. j

NO PARTS USED

Workorder: V39809

In Date: 04/09/2011

Meter Reading: 53,290.00

Close Date: 04/14/2011

Problem?

Flat tire on DC3, right rear, this morning at 0700. Piece of metal in tread, looked like large nail. Mechanic called and scheduled vendor to come to 91. Vendor arrived and changed tire.

Task performed:

Parts

Quantity

Call stn; then call tire co - Boulevard Tire; tire Firestone
LT245/75R16

NO PARTS USED

Workorder: V39845

In Date: 04/11/2011

Meter Reading: 53,290.00

Close Date: 04/20/2011

Problem?

flat tire (outside agency-Boulevard tire) D/C3

Task performed:

Parts

Quantity

Flat tire DC3 - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V39607

In Date: 04/01/2011 Meter Reading: 52,825.00
Close Date: 05/16/2011

Problem?

parking brake cable disconnected. sta. 35.

Task performed:

Park brake cable release inop - cable brkn; rep cable & ordered new one. j

Parts	Quantity
15929213PARK BRAKE CABLE	1
83982976BRAKE PEDAL PAD	1

Workorder: V40631

In Date: 05/16/2011 Meter Reading: 55,182.00
Close Date: 05/18/2011

Problem?

Replace parking brake release cable when truck is at shop for PM. Thanks! Sta 91.

Task performed:

Will have done at Roger Dean. j

Parts	Quantity
NO PARTS USED	

Workorder: V40607

In Date: 05/13/2011 Meter Reading: 54,943.00
Close Date: 05/20/2011

Problem?

B Inspection

Task performed:

B-Inspection - Roger Dean j

Parts	Quantity
NO PARTS USED	

Vendor?: ROGER DEAN

Workorder: V40632

In Date: 05/16/2011 Meter Reading: 55,182.00
Close Date: 05/20/2011

Problem?

Please install hook where screw holds spot light on dash board. Please check 12v DC port in back command center. Sta 91.

Task performed:

1. R/F strobe inop; replc strobe bulb.
2. Install hook.
3. 12V power supply inop; cable unplugged; rem panel in fish out cable & rein stalled. j

Parts	Quantity
01046301700S30HACP STROBE CLEAR	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V41117

In Date: 06/05/2011

Meter Reading: 55,837.00

Close Date: 06/08/2011

Problem?

Check Engine Light on; Tech evaluated and said O2 sensor needs replaced Sta 35

Task performed:

Parts

Quantity

Chk eng light came on for about 30 minutes; fnd code P1133; needs O2 sensor. j

NO PARTS USED

On-call mech - parts ordered. j(6/28/11)

Workorder: V41825

In Date: 07/06/2011

Meter Reading: 57,330.00

Close Date: 07/11/2011

Problem?

Noise in front end D/c 9

Task performed:

Parts

Quantity

NOISE IN FRONT END - CV JOINTS GOING BAD 7-6
REPLACED BOTH CV JOINTS AND FRONT HUBS 7-7
7-8

01046301700S30HACP STROBE CLEAR

1

20835869AXEL HUB

2

ASSISTED WITH FRONT END REPARID 7-6

20875738CV AXEL SHAFT

2

A INSPECTION 7-8

L-R STROBE INOP BULB REPLACED BULB 7-8

STORAGE CABINET DOORS / HINDEGES FALLING

APART REPARID CABINET DOORS 7-7 AK

Workorder: V40686

In Date: 05/18/2011

Meter Reading: 55,182.00

Close Date: 08/04/2011

Problem?

replace passenger front tire, normal wear. Sta 35.

Task performed:

Parts

Quantity

work completed

NO PARTS USED

Vendor?: CALLAGHAN



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V42986

In Date: 08/23/2011

Meter Reading: 66,458.00

Close Date: 08/24/2011

Problem?

B inspection DC 9

Task performed:

BATTERY CABLE CONNECTED CLEANED CABLES AND REPLACED BATTERY

STROBES INOP FUSE BLOWN TO POWER SUPPLY AND RR BULB BURNT REPLACED FUSE AND REPLACED RR BULB

REPLACE WIPER BLADES DUE REPLACED BLADES AND TOP OFF FLUID

RUMBLER NOT LABELED MADE NEW LABEL FOR RUMBLER

AUT TIRE PRESSURES TIRE MONITOR INOP ADJ TIRE PRESSURES AND RE SET TIRE MONITOR

Parts

Quantity

15W40BSYN OIL BULK QTS	6
25820122WIPER BLADE NEW GM 14"	1
25877402WIPER BLADES NEW GM 22 IN	2
48-60BATTERY	1
57060OIL FILTER	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1
S30HACSTROBE BULB	1

Workorder: V43696

In Date: 09/15/2011

Meter Reading: 58,675.00

Close Date: 09/26/2011

Problem?

a/c inop dc3

Task performed:

1. A/C inop - intermittent; fan clutch needs to be replcd; fnd fan clutch causing high eng temp & head pressure; cln radiator/condensor; refilled coolant tank.

2. Coolant leak; connector at heater core bypassed heater coil; will replc at next svc. j

Parts

Quantity

15710101FAN CLUTCH	1
388863-1HTR HOSE SHUT VALVE NEW HORTONS	2

Workorder: V43577

In Date: 09/11/2011

Meter Reading: 58,675.00

Close Date: 10/03/2011

Problem?

latch on the drawer in the back of DC3 is broken. Sta 91 D/C 3

Task performed:

repaired broken latch

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V45004

In Date: 11/07/2011

Meter Reading: 62,781.00

Close Date: 11/09/2011

Problem?

No start.

Task performed:

Parts

Quantity

C/O btry charger; loose cable - bad wire on btry; rep;
chk charging - ok. j

NO PARTS USED

Workorder: V44983

In Date: 11/04/2011

Meter Reading:

Close Date: 12/02/2011

Problem?

DC3's commadd board has a metal piece that is broken. This part keeps the board from sliding off the supporting drawer. Sta 91

Task performed:

Parts

Quantity

repaired bracket in rear slide out

NO PARTS USED

Workorder: V45589

In Date: 12/02/2011

Meter Reading: 62,965.00

Close Date: 12/16/2011

Problem?

Engine light on d/c 3

Task performed:

Parts

Quantity

ROAD TESTED, FOUND NO PROBLEM WITH TRUCK.

NO PARTS USED

Workorder: V45930

In Date: 12/19/2011

Meter Reading: 64,171.00

Close Date: 01/04/2012

Problem?

Auxiliary battery overcharging- removed 12/18. S.H. Sta 35

Task performed:

Parts

Quantity

TRAVEL TO ST. 91 R&R BATT. ON TK.

24-60BATTERY GROUP 24

1

FOUND ONE BATTERY SHORTED OUT - REMOVED
SHORTED BATTERY.

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V46559

In Date: 01/13/2012
Close Date: 01/13/2012

Meter Reading: 65,197.00

Problem?

Dead battery.

Task performed:

DEAD BATTERIES - INSTALL NEW BATTERIES. HAD TO USE 2 CABLE TO START - DRIVE TO SHOP TO CHECK UNIT CHARGING AT 14.2-V INSERVICE.

Parts	Quantity
65-72BXT65750 BATTERY	1
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY	1

Workorder: V47166

In Date: 02/07/2012
Close Date: 02/10/2012

Meter Reading: 66,777.00

Problem?

headlight wig-wag slow on the right side. DC 3

Task performed:

REPAIRED BAD CONNECTION WITH WIG WAGS.

Parts	Quantity
NO PARTS USED	

Workorder: V47477

In Date: 02/22/2012
Close Date: 03/06/2012

Meter Reading: 67,396.00

Problem?

TIC charger not charging DC3

Task performed:

REPAIRED TIC CHARGER THAT WAS NOT WORKING

Parts	Quantity
NO PARTS USED	

Workorder: V47758

In Date: 03/05/2012
Close Date: 03/06/2012

Meter Reading: 67,396.00

Problem?

CHARGING SYSTEM 10-7 DC 3

Task performed:

DIAGNOSE CHARGING SYSTEM GO PICK UP PARTS INSTALL ALTERNATER AND SEPENTINE BELT.

Parts	Quantity
12626222BELT	1
2088133707-08 2 WIRE GM	1
9-2669 FLOOR MAT	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V47909

In Date: 03/12/2012

Meter Reading: 68,403.00

Close Date: 03/13/2012

Problem?

REPLACE TWO TIRES DC 3

Task performed:

Parts

Quantity

REPLACE TWO TIRES DC3

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V47932

In Date: 03/13/2012

Meter Reading: 68,403.00

Close Date: 03/14/2012

Problem?

Repair Flat

Task performed:

Parts

Quantity

REPAIR FLAT.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V47981

In Date: 03/14/2012

Meter Reading: 68,403.00

Close Date: 03/20/2012

Problem?

B inspection - Roger Dean

Task performed:

Parts

Quantity

B inspection
Oil and filter change
relearn tpm sensors
replace pinon seal and rear diff seal
replace brake light switch
replaced throttle body

NO PARTS USED

Vendor?: AL PACKER



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V48052

In Date: 03/19/2012

Meter Reading: 68,403.00

Close Date: 03/20/2012

Problem?

check eme lts and tires dc 3

Task performed:

- CHECK ALL TIRES FOR TREAD SET TIRE PRESSURES AS PER DOOR POST.
- CHECK ALL EMERGENCY LIGHTS. R/F STROBE OUT HAD TO R&R R/F HEAD LIGHT ASSY IN ORDER TO R&R STROBE TUBE.

Parts

Quantity

01046301700S30HACP STROBE CLEAR

1

Workorder: V47982

In Date: 03/15/2012

Meter Reading: 68,403.00

Close Date: 03/30/2012

Problem?

Wig-wag inop

Task performed:

REPAIRED GROUND WIRE AND TESTED.

Parts

Quantity

NO PARTS USED

Workorder: V50283

In Date: 06/21/2012

Meter Reading: 72,926.00

Close Date: 06/25/2012

Problem?

DC3 won't start

Task performed:

INSTALLED NEW BATTERY AND CHECKED CHARGING SYSTEM.

Parts

Quantity

65-72BXT65750 BATTERY

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

1

Workorder: V50187

In Date: 06/17/2012

Meter Reading: 72,926.00

Close Date: 07/13/2012

Problem?

When starting the vehicle: the MDC losses the wireless connection and the vehicle's clock reset itself back to 1200 hrs. The shoreline has been plug in. DC 3

Task performed:

NEW BATTERIES WERE INSTALLED.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V50950

In Date: 07/18/2012

Meter Reading: 74,298.00

Close Date: 07/24/2012

Problem?

R headlight out. R front turn signal strobe out. R wig wag not working. L reer turn signal strobe out. DC 3

Task performed:

- ORDER PART. ROAD TECH CAME INSTALL.
- CHANGES OUT RIGHT SIDE HEAD LIGHT, HIGH, CHANGES OUT RIGHT RUNNING LIGHT; CHECKOUT STROBE LIGHT IN RIGHT SIDE HAVE TO REMOVE BRUSH GARD TO GET HEAD LIGHTS OUT.
- REPLACE PRO NET IN REAR COMPARTMENT TO HOLD IN BOTTLE IN RACK, HAD TO REPAIR DOOR TO COMPARTMENT ALL SCREW OUT.
- CHECK OUT EMERGENCY LIGHT, FOUND WIG WAY CONTROLER BAD, ORDER ONE LIKE THE ONE IN TRUCK, BEHIND LEFT FRONT HEAD LIGHT.

Parts

Quantity

01046301700S30HACP STROBE CLEAR	1
3157TAIL LIGHT BULBS	1
90059005 HEADLIGHT BULB	1
UHF-2150AFLASHER-WHELEN HEADLIGHT HIGH BEAM	1

Workorder: V51961

In Date: 08/29/2012

Meter Reading:

Close Date: 09/12/2012

Problem?

Moderate pull to right when driving. Grinding noise when driving, especially when turning right. Left at shop on 8/28/12. DC 3 Also need to repair command cabinet: broken doors and slide drawer in back.

Task performed:

- CHANGED BOTH FRT WHEEL AND SUB BEARING ASSY DUE TO WATER DAMAGE CHANGED OIL AND FILTERS BOTH SETS OK FRT BRAKE PADS.

Parts

Quantity

19210706PADS 08 SUB	1
20980075HUB ASSBLY	2
57060OIL FILTER	1
CA875642487 FILTER AIR	1

Workorder: V52013

In Date: 08/30/2012

Meter Reading: 76,387.00

Close Date: 10/01/2012

Problem?

repalce 3 tires

Task performed:

- REPLACE 3 TIRES.

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN TIRE



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V53521

In Date: 11/04/2012

Meter Reading:

Close Date: 11/30/2012

Problem?

Right side scene light out in the light bar. Right wig-wag and headlight strobe out. DC 3

Task performed:

Parts

Quantity

REPAIRED LIGHTS OUT IN IGH T BAD.

NO PARTS USED

Workorder: V53705

In Date: 11/12/2012

Meter Reading:

Close Date: 11/30/2012

Problem?

Engine service light is on. All fluids are good. DC3

Task performed:

Parts

Quantity

UNIT WILL GO IN FOR SERVICE.

NO PARTS USED

Workorder: V54133

In Date: 12/02/2012

Meter Reading:

Close Date: 12/07/2012

Problem?

AC not cold DC 3

Task performed:

Parts

Quantity

CHECKED SYSTEM AND TESTED OK.

NO PARTS USED

Workorder: V54383

In Date: 12/11/2012

Meter Reading:

Close Date: 01/14/2013

Problem?

Dash light buttons pushed into dash. Unable use. DC 3

Task performed:

Parts

Quantity

REPLACED DAAASH PANEL HEADLIGHT SWITCH.
REPAIRED AUTO EJECT PLUG.

25810643PLATE

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V54551

In Date: 12/21/2012

Meter Reading:

Close Date: 01/14/2013

Problem?

Right wigwag out. Right side scene light out in light bar. Left rear turn signal stobe out. At next PM, please divert exhaust pipe out the side of the vehicle. It discharges under command area presently

Task performed:

Parts

Quantity

- 1.REPALCED ALL STROBE BULBS THAT WERE OUT.
2. REPAIRED COOLANT LEAK AT BOTTOM OF RADIATOR.

NO PARTS USED

Workorder: V55143

In Date: 01/18/2013

Meter Reading: 81,348.00

Close Date: 01/22/2013

Problem?

Starter intermittent DC-3

Task performed:

Parts

Quantity

1. FOUND STARTER BAD. REMOVED BELT. CABLES R&R STARTER CK OPERATION CHECK OK.
2. ALTERED TAIL PIPE TO EXIT SIDE OF TRUCK INSTEAD OF REAR OF TRUCK.

336-1932ASTARTER

1

35794MUFFLER CLAMP 3 IN

2

41892CONNECTOR

1

7441BULB BACKUP LIGHT GM

10

Workorder: V54859

In Date: 01/05/2013

Meter Reading: 80,904.00

Close Date: 02/12/2013

Problem?

Replace wiper blades - badly worn. Multiple lights out - see previous requests. DC3

Task performed:

Parts

Quantity

1. REPLACED BLADES.
2. REPLACED STROBE BULBS IN ALL LIGHTS THAT WERE OUT.
3. REPLACED AIR BOTTLE HOLDER.

01046301700S30HACP STROBE CLEAR

3

25877402WIPER BLADES NEW GM 22 IN

2

FHLP-6TANK CLIP

2

KD-UN-6-SFBRACKET

1

S30HACSTROBE BULB

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V55058

In Date: 01/15/2013

Meter Reading: 81,216.00

Close Date: 02/12/2013

Problem?

Command board face detached and slide needs help.

Task performed:

Parts

Quantity

REPAIRED COMMAND CENTER THAT WAS FALLING APART.

NO PARTS USED

Workorder: V55059

In Date: 01/15/2013

Meter Reading: 81,216.00

Close Date: 02/12/2013

Problem?

Rear speaker doing "low battery" groan

Task performed:

Parts

Quantity

REPAIRED GROUND WIRE, AND TESTED.

NO PARTS USED

Workorder: V55541

In Date: 02/05/2013

Meter Reading: 81,815.00

Close Date: 02/22/2013

Problem?

Right side scene light in light bar and right license tag light out. Please re-attach long door inside command center (hinge on left side of door). Thanks! e91

Task performed:

Parts

Quantity

1. REPAIRED ALLEY LIGHTS AND REWIRED.
2. REPAIRED COMMAND CENTER DOORS.

MR1135 WATT BULB

1

Q20MR16BULB 20 WATT

1

Workorder: V55945

In Date: 02/22/2013

Meter Reading: 82,788.00

Close Date: 03/15/2013

Problem?

B-inspection

Task performed:

Parts

Quantity

NEEDS TO COME IN FOR SERVICE.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V56526

In Date: 03/20/2013

Meter Reading: 82,931.00

Close Date: 03/21/2013

Problem?

A-inspection

Task performed:

A-INSPECTION AND REPAIRS.

Parts

Quantity

NO PARTS USED

Workorder: V56512

In Date: 03/19/2013

Meter Reading: 82,931.00

Close Date: 04/01/2013

Problem?

B-Inspection [AI Packer] And repairs

Task performed:

B-inspection

Replaced both batteries

Replaced both fuel pumps

Replaced front brake pads and rotors

Replaced rear brake pads and rotors

Vendor?: ROGER DEAN

Parts

Quantity

NO PARTS USED

Workorder: V47723

In Date: 03/02/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

Right front parking light strobe out and wig-w wag right side slow. DC3

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V51713

In Date: 08/20/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

When driving, steering has moderate pull to the right. DC 3

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V52081

In Date: 09/01/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

Right headlight, wig-wag and marker light out. DC 3

Task performed:

Parts

Quantity

91-20WIPER BLADE 20 IN

2

Workorder: V57098

In Date: 04/17/2013

Meter Reading: 84,015.00

Close Date: 04/19/2013

Problem?

Stalled out in intersection

Task performed:

Parts

Quantity

FUEL PUMP BAD; TOWED TO SHOP.

NO PARTS USED

Workorder: V57248

In Date: 04/24/2013

Meter Reading: 84,015.00

Close Date: 04/25/2013

Problem?

Quality check [Back from roger dean]

Task performed:

Parts

Quantity

1. Q & A VEHICLE.
2. REPLACED LICENSE PLATE LIGHT BULB.
3. REMOVE ACCREDIDATION DECALS AND GLUE FROM BODY.

NO PARTS USED

Workorder: V57255

In Date: 04/24/2013

Meter Reading: 84,022.00

Close Date: 04/25/2013

Problem?

Quit running stalled in intersection

Task performed:

Parts

Quantity

Replaced MAF sensor
 Replaced purge solenoid
Vendor?: ROGER DEAN

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V57827

In Date: 05/18/2013

Meter Reading:

Close Date: 05/29/2013

Problem?

during a rain storm, water leaked from the cab roof onto the MDT. MDT not working.

Task performed:

Parts

Quantity

TRAVEL TO HQ SEAL UP CAB OF TRUCK CONNECTIONS.

NO PARTS USED

Workorder: V58020

In Date: 05/29/2013

Meter Reading: 85,140.00

Close Date: 05/30/2013

Problem?

stalled out

Task performed:

Parts

Quantity

FUEL PUMP PROBLEM SWAPED OUT.

NO PARTS USED

Workorder: V58021

In Date: 05/29/2013

Meter Reading: 85,387.00

Close Date: 05/31/2013

Problem?

stalls out after fueling tank

Task performed:

Parts

Quantity

Replaced evap canister , valve and solenoid

NO PARTS USED

Vendor?: ROGER DEAN

Workorder: V58556

In Date: 06/19/2013

Meter Reading: 85,910.00

Close Date: 07/05/2013

Problem?

Right side headlight (white) strobe light is out DC 3

Task performed:

Parts

Quantity

TRAVEL TO ST 91 CHECK OUT STROBE LIGHT CHECK CONTROLL BOX AND TEST POWER PACK PULL HEAD LIGHT ASSY. R&R STROBE BULB AND RUNNING LIGHT BULB.

01046301700S30HACP STROBE CLEAR

1

90059005 HEADLIGHT BULB

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V59025

In Date: 07/11/2013 Meter Reading: 87,000.00

Close Date: 07/19/2013

Problem?

INSTALL DC 3 ON BOTH SIDES OF UNIT

Task performed:

Parts

Quantity

TRAVEL TO ST 91 INSTALL DC-3 ON SIDES OF TRUCK.

NO PARTS USED

Workorder: V59338

In Date: 07/25/2013 Meter Reading: 87,691.00

Close Date: 08/16/2013

Problem?

Right side wig wag headlight out. Similiar /same request entered a short time back. Unknown if not repaired yet or it went out again DC 3

Task performed:

Parts

Quantity

LET DC KNOW WILL REPAIR ON P.M. PUSH CAGE HAS TO COME OFF TO GET TO FLASHER.

NO PARTS USED

Workorder: V59533

In Date: 08/03/2013 Meter Reading: 87,865.00

Close Date: 08/16/2013

Problem?

right turn signal/brake light out. DC3

Task performed:

Parts

Quantity

1. TRAVEL TO ST 91 R&R TAIL LIGHT BULB.
2. TPS LT ON CHECK PRESSURES AND ADJUST RESET TPS SYSTEM OK.

NO PARTS USED

Workorder: V59810

In Date: 08/14/2013 Meter Reading: 88,375.00

Close Date: 09/06/2013

Problem?

Please check operation of portable (radio batteries) battery charger. Unsure if working/working correctly. It is mounted on top of command center. Front seat driver seat cover is worn. Please replace with new.

Task performed:

Parts

Quantity

1. REMOVE AND REPLACE FRONT SEAT COVERS AND HEAD RESTERS COVERS TOO.
2. THROTTLE BODY - REMOVE AND REPLACE THROTTLE BODY TEST FOR OPERATION REPAIR WIRE ????? AND ROUTING TO T.B. CARD INSATATE. HARNESS RUBBING ON P.S. LINES.

C1161-H8SEAT COVER

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V59809

In Date: 08/14/2013
Close Date: 09/11/2013

Meter Reading: 88,375.00

Problem?

The DC jack at the back (rear) does not work. Jack was used in the past for portable green /command post flashing light.

Task performed:

- CHECK FOR THROTTLE NOT RESPONDING WELL
- REMOVE THROTTLE BODY AND RELOCATE WIRE HORNES TO IT.
- INSTALL WIRE LOOM TO HARNESS FOR THROTTLE BODY AND SECURE WITH STRAPS. NICE.
- WORK ON THROTTLE BODY.

Parts

NO PARTS USED

Quantity

Workorder: V59811

In Date: 08/14/2013
Close Date: 09/11/2013

Meter Reading: 88,375.00

Problem?

Front end vibration at highway speeds (50-70 mph). Additionally, front end noise - a bang / thunk / rattle when driving, especially over bumpy or uneven terrain left rear tire TPM (tire pressure management) light continually flashes / displays as message on dash board counsel/guage

Task performed:

- TEST DRIVE CHECK FRONT END. FOUND NEEDS SHOCKS AND TIRE ROTATION ALSO FRONT AND DIFF NEEDS REBUILDING SOON HOOMING.
- ROTATE TIRES ADJUST FRONT. RIDE HIGH OL.S. INCH TEST AGAIN. NEEDS TWO NEW TIRES VIBRATION IS AT 73 MPH NOW ON REAR.
- REPLACE TIC CHARGER BASE TEST FOR OPERATION ALSO ROAD TEST AFTER TWO REAR TIRES WERE INSTALL. TRUCK RIDES NICE NOW.

Parts

12580760THROTTLE BODY
 12589235SEAL THROTTLE BODY
 75W90GEAR OIL SYN QT

Quantity

1
1
4

Workorder: V58815

In Date: 07/02/2013
Close Date: 09/12/2013

Meter Reading: 88,375.00

Problem?

nail in L rear tire. Chief Mulligan on-duty.

Task performed:

TECH TEMP PLUGGED TIRE.

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V59812

In Date: 08/14/2013

Meter Reading: 88,435.00

Close Date: 09/17/2013

Problem?

B inspection DC3, also rattle/thud noise from front end when going over rough terrain

Task performed:

Parts

Quantity

B-inspection

NO PARTS USED

Replaced shocks

Replaced bump stops

Vendor?: ROGER DEAN

Workorder: V60623

In Date: 09/19/2013

Meter Reading: 89,199.00

Close Date: 09/19/2013

Problem?

Check engine light on

Task performed:

Parts

Quantity

Reprogrammed ecm

NO PARTS USED

Vendor?: ROGER DEAN

Workorder: V60715

In Date: 09/23/2013

Meter Reading: 89,325.00

Close Date: 09/27/2013

Problem?

Left brake light out. Tommy leaving a bulb at #31.

Task performed:

Parts

Quantity

1. TRAVEL TO ST 91 CHECK OUT BRAKE LIGHTS R&R BULB ON DRIVER SIDE LIGHT.

NO PARTS USED

2. CHECK OUT HEADLIGHTS COMPLAINT BRIGHTS STAY ON WIG WAG STUCK ON PASS SIDE REMOVE FUSE AND BULB FOR NOW DRIVER SIDE OK NEEDS TO GO TO SHOP TO HAVE PUSH BAR REMOVED TO GO TO FLASHER.



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V60776

In Date: 09/25/2013

Meter Reading: 89,325.00

Close Date: 09/27/2013

Problem?

R/S headlight stays on hi beam

Task performed:

FOUND HEADLIGHT BULB MISSING - REPLACED RIGHT HIGH BEAM BULB - REMOVED CENTER CONSOLE MOUNTS - REMOVED FRONT BUSH HAR FENDER WELL AND LEFT HEAD LIGHT TROUBLESHOOT BAD WIG WAG FLASHER CONT: REPLACED AND WIRED FLASHER MODULE - CHECK OPERATION CHECK OK- REASSEMBLED ALL PARTS - R&R LEFT SIDE EMERGENCY LENSES.

Parts

Quantity

6819634283068-1963428-30 LENS CLR

4

90059005 HEADLIGHT BULB

1

UHF-2150AFLASHER-WHELEN HEADLIGHT HIGH BEAM

1

Workorder: V60733

In Date: 09/24/2013

Meter Reading: 89,325.00

Close Date: 09/30/2013

Problem?

High beams will not turn off. Fuses removed. Right side bulb removed to de-activate. Left brake light out. Steve contacted by phor last night.

Task performed:

REPAIRED ON W.O.

Parts

Quantity

NO PARTS USED

Workorder: V60992

In Date: 10/04/2013

Meter Reading: 89,873.00

Close Date: 10/10/2013

Problem?

Replace both rear tires, left rear to spare.

Task performed:

REPLACE BOTH REAR TIRES, LEFT REAR TO SPARE

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V61502

In Date: 10/24/2013

Meter Reading: 90,578.00

Close Date: 10/31/2013

Problem?

REPLACE FUEL PUMP ROGER DEAN

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: ROGER DEAN

Workorder: V62962

In Date: 12/26/2013

Meter Reading: 93,077.00

Close Date: 01/23/2014

Problem?

LEFT SCENE LIGHT AND RIGHT REAR WINDOW STROBE NOT WORKING. DC3

Task performed:

Parts

Quantity

TRAVEL TO ST 91 WAIT FOR TRUCK, GOT ANOTHER CALL WILL RETURN.

NO PARTS USED

Workorder: V63599

In Date: 01/22/2014

Meter Reading:

Close Date: 02/04/2014

Problem?

left scene light and some strobe out. dc3

Task performed:

Parts

Quantity

TRAVEL TO ST-91 R&R SCENE LIGHT IN LT BAR REPLACE REAR LIGHT AND REWIRE TEST OK.

AVN2RCAVENGER LED RED/CLEAR 1

MR1135 WATT BULB 1

Q20MR16BULB 20 WATT 1

Workorder: V64564

In Date: 02/26/2014

Meter Reading:

Close Date: 03/17/2014

Problem?

B inspection Roger Dean, needs tires

Task performed:

Parts

Quantity

B Inspection
Multi Point Inspection
Repair Tag Lights

NO PARTS USED

Vendor?: ROGER DEAN



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V65167

In Date: 03/24/2014

Meter Reading: 96,350.00

Close Date: 03/25/2014

Problem?

Left head light inop

Task performed:

CHECK HEADLIGHT PLUG BURNT UP, ORDER NEW PLUG AND MADE BAD PLUG WORK.

Parts

H11H11-55WLL BULB LOW BEAM 92095787

Quantity

1

Workorder: V65020

In Date: 03/18/2014

Meter Reading: 96,232.00

Close Date: 04/01/2014

Problem?

Auto eject inop Replace steering wheel Restore headlights and lightbar

Task performed:

1. REPLACED AUTO EJECT/ NOT CHARGING DIAGNOSED PROBLEM AND CLEAN LENS AND REPLACE BATTS.
2. STEERING WHEEL- REPLACE STEERING WHEEL.

Parts

091-20WP-120AUTO EJECT

22947808WHEEL STEERING SUBURBAN

24F-60BATTERY

39045HEADLITE KIT WITH SEALER

54-870PL558-60 CIRCUIT BREAKER 60 AMP

65-72BXT65750 BATTERY

Quantity

1

1

1

1

1

1

Workorder: V65113

In Date: 03/22/2014

Meter Reading:

Close Date: 05/22/2014

Problem?

Low beam head lamp (Dirver side) and high beam lamp (passeger side) out / not working DC3

Task performed:

TRAVEL TO ST-91 CHECK OUT LIGHTS OUT CHECK OUT LIGHTS LOSE CONNECTION ON HEADLIGHT ON DR/SIDE REPAIR PINS IN CONNECTOR NIGHT LIGHT WIG WAG BAD WILL ORDER NEW ONE.

Parts

NO PARTS USED

Quantity

Workorder: V66726

In Date: 05/24/2014

Meter Reading:

Close Date: 06/18/2014

Problem?

Left rear turn signal out. AT20 - Norris Rhodes replaced bulb at #91. Thanks!

Task performed:

left rear turn signal out replaced bulb ok .

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V67862

In Date: 07/12/2014

Meter Reading:

Close Date: 07/30/2014

Problem?

R.SIDE SCENE LIGHT NOT WORKING ON ROOF LIGHT BAR.

Task performed:

repairs complete on ticket v68218.

Parts

Quantity

NO PARTS USED

Workorder: V68218

In Date: 07/28/2014

Meter Reading:

Close Date: 07/30/2014

Problem?

RIGHT SCENE LIGHT NOT WORKING ON THE LIGHT BAR.

Task performed:

travel to sta,91 ck, out light bar repaired wiring and r&r bulb.

Parts

Quantity

MR1135 WATT BULB

1

Workorder: V68395

In Date: 08/04/2014

Meter Reading:

Close Date: 08/07/2014

Problem?

Batteries not charging on shore line.

Task performed:

TRAVEL TO STA,91 CK, OUT 110V BATTERY CHARGER INOP, FOUND FUSE MELTED AND BURNED TRIPPED ,REPLACED FUSE CONNECTOR AND FUSE RESET BREAKER TESTED OK.

Parts

Quantity

NO PARTS USED

Workorder: V67149

In Date: 06/11/2014

Meter Reading:

Close Date: 08/14/2014

Problem?

Right side scene light out in light bar.

Task performed:

WORK WAS COMPLETE ON W/O V67862.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V69014

In Date: 08/28/2014

Meter Reading: 103,390.00

Close Date: 08/28/2014

Problem?

B-inspection

Task performed:

Parts

Quantity

B-inspection
Replace 4WD mode switch
Replace headlight assemblies
Replace tail lamp assemblies
Replaced front and rear shocks

NO PARTS USED

Vendor?: AL PACKER

Workorder: V69984

In Date: 10/08/2014

Meter Reading: 105,233.00

Close Date: 10/29/2014

Problem?

Vehicle pulls to the left

Task performed:

Parts

Quantity

Checked truck pull ,Found truck had mild drift left.
Swapped front tires left to right and checked brakes.
Found no brake problems. Road tested truck for a second time , still drifts left. Truck will be scheduled for front alignment.

NO PARTS USED

Workorder: V70609

In Date: 10/31/2014

Meter Reading: 106,207.00

Close Date: 10/31/2014

Problem?

B-inspection

Task performed:

Parts

Quantity

B-inspection
Replaced radiator
Air filter
Wiper blades

NO PARTS USED

Vendor?: AL PACKER



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V69412

In Date: 09/15/2014

Meter Reading: 104,100.00

Close Date: 11/03/2014

Problem?

Pulley noise - unknown origin in engine compartment. DC3

Task performed:

Repaired at shop.

Parts

NO PARTS USED

Quantity

Workorder: V70693

In Date: 11/04/2014

Meter Reading: 106,336.00

Close Date: 11/06/2014

Problem?

battery charger inop

Task performed:

1. Travel to station 91. Check out battery charger inoperable. Found fuse holder melted. Repair fuse holder. Also, R & R bad charge gauge.

Parts

091-39-INDAUTO CHARGER INDICATOR

1

Quantity

Workorder: V70401

In Date: 10/23/2014

Meter Reading: 106,144.00

Close Date: 11/20/2014

Problem?

Engine runs hot

Task performed:

Repaired at AI packer

Parts

NO PARTS USED

Quantity

Workorder: V71307

In Date: 12/01/2014

Meter Reading: 107,777.00

Close Date: 12/05/2014

Problem?

Batteries

Task performed:

R/R 2 batteries-replace one amrine terminal-clean all connections had to R/R support bars to access batteries

Parts

24F-60BATTERY

1

65-72BXT65750 BATTERY

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174224

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V71316

In Date: 12/02/2014

Meter Reading:

Close Date: 12/10/2014

Problem?

2 new batteries installed yesterday. Shoreline charger is now indicating that it is not charging. ? blown fuse during battery install.

Task performed:

Parts

Quantity

Repaired at shop

NO PARTS USED

Workorder: V71569

In Date: 12/11/2014

Meter Reading:

Close Date: 12/17/2014

Problem?

Rumber (siren) cut out while using on an emergency call and now no longer works

Task performed:

Parts

Quantity

Travel to station 91-check out siren remount speaker on push bar, replace fuse test ok.

82831043-KCRADLE BRACKET

2

CV1C05RB-CVIC05 RUMBLER MOUNT KIT

1

Z82831062ABAND RUMBLER

1

Workorder: V74501

In Date: 04/08/2015

Meter Reading: 113,481.00

Close Date: 04/08/2015

Problem?

outside b service

Task performed:

Parts

Quantity

b inspection
replace mass air flow
replace wiper blades

NO PARTS USED

Vendor?: AL PACKER



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10174224) 2008 - CHEVROLET SUBURBAN LS Suv Chevy Suburban

10174224

CSHOP-2015-2826

Comments: LACK OF POWER REPLACED PURGE VALVE AND MASS AIR FLOW SENSOR

Date Opened: 9-10-2015 Date Finished 9-15-2015 Meter 1 Reading: 115,373

TASKS PERFORMED

NO PARTS USED

TOWING HITCH

VENDOR? AL PACKER

CSHOP-2015-3038

Comments: DEAD BATTERY QC CHECK TIRES GIVE ME SIZE PLEASE

Date Opened: 9-22-2015 Date Finished 9-24-2015 Meter 1 Reading: 115,373

TASKS PERFORMED

NO PARTS USED

BATTERY
TIRES & WHEELS

CSHOP-2015-3230

Comments: REPLACE TIRES

Date Opened: 10-5-2015 Date Finished 10-5-2015 Meter 1 Reading: 115,373

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2015-3690

Comments: BATTERIES POSSIBLY LOW, HAVING TROUBLE STARTING

Date Opened: 10-30-2015 Date Finished 10-30-2015 Meter 1 Reading: 115,720

TASKS PERFORMED

Q PARTS

CHARGING SYSTEM

2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
2 BATTERY; BATTERY

CSHOP-2015-4379

Comments: B INSPECTION ROTATE TIRES

Date Opened: 12-8-2015 Date Finished 12-8-2015 Meter 1 Reading: 117,954

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History 10174224

CSHOP-2015-4551

Comments: **ENGINE SURGES AT 70 MPH**

Date Opened: 12-18-2015 Date Finished 12-18-2015 Meter 1 Reading: 118,141

TASKS PERFORMED

NO PARTS USED

FUEL SYSTEM

VENDOR? AL PACKER

CSHOP-2016-1436

Comments: **STROBES INOP LOW TIRE WARNING**

Date Opened: 3-25-2016 Date Finished 3-28-2016 Meter 1 Reading: 118,741

TASKS PERFORMED

Q PARTS

TIRES & WHEELS
STROBE LIGHTS

2 9IP; S30HACP STROBE CLEAR
1 9IP; S30HACP STROBE CLEAR

CSHOP-2016-1728

Date Opened: 4-12-2016 Date Finished 4-12-2016 Meter 1 Reading: 119,238

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

04/12/2016 BODY / 12: BROKEN / REPAIR

CSHOP-2016-1730

Comments: **COMMAND BOX SLIDES**

Date Opened: 4-12-2016 Date Finished 4-13-2016 Meter 1 Reading: 119,550

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY - WORK COMPARTMENT EMER

CSHOP-2016-1810

Comments: **EMS28**

Date Opened: 4-18-2016 Date Finished 4-18-2016 Meter 1 Reading: 119,569

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY - WORK COMPARTMENT EMER

Service Requests:

04/15/2016 BODY / 10: BENT / INSPECT
BOTTOM DRAWER IN THE REAR COMMAND CENTER IS BROKEN. WILL NOT SLIDE IN OR OUT. WAS JUST REPAIRED
AND NOW IT IS BROKEN AGAIN.

Asset Work Order History 10174224

CSHOP-2016-1893

Comments: **SPARE EMS AT ST28**

Date Opened: 4-22-2016 Date Finished 4-25-2016 Meter 1 Reading: 119,569

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

1 CHARGER; CHARGER 2000
2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
2 BATTERY; BATTERY

Service Requests:

04/21/2016 STARTER / 38: SHORTED / EXCHANGE - NEW
BATTERY APPEARS TO BE DYING. NOT HOLDING A CHARGE.

CSHOP-2016-2223

Comments: **EMS 28**

Date Opened: 5-9-2016 Date Finished 5-13-2016 Meter 1 Reading: 121,195

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CONNECTOR
WIRING

Service Requests:

05/06/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
TIC CHARGER DOES NOT CHARGE THE TIC. CHARGER HAS POWER AND THE SPARE BATTERY CHARGES BUT THE TIC DOES NOT.

CSHOP-2016-2710

Comments: **ON-CALL EMS 28 NO START**

Date Opened: 6-7-2016 Date Finished 6-7-2016 Meter 1 Reading: 122,745

TASKS PERFORMED

NO PARTS USED

CRANKING SYSTEM

CSHOP-2016-2865

Comments: **OVEHEATING AT ST28**

Date Opened: 6-15-2016 Date Finished 6-21-2016 Meter 1 Reading: 123,049

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
THERMOSTAT
ANTIFREEZE
OVERFLOW TANK

2 FLUID; COOLANT ANTIFREEZE GAL

Asset Work Order History 10174224

CSHOP-2016-3360

Comments: **B INSPECTION REPAIRED COOLING SYSTEM**

Date Opened: 7-12-2016 Date Finished 7-12-2016 Meter 1 Reading: 123,321

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-4454

Date Opened: 9-13-2016 Date Finished 9-13-2016 Meter 1 Reading: 124,114

TASKS PERFORMED

NO PARTS USED

STEERING

VENDOR? AL PACKER

CSHOP-2016-5379

Comments: **DEAD BATTERY**

Date Opened: 11-17-2016 Date Finished 11-29-2016 Meter 1 Reading: 124,114

TASKS PERFORMED

Q PARTS

SIDE COMPARTMENT BODY

2 SLIDE; 3320-22 DOOR SLIDE

HEADLIGHTS LOW BEAM

1 LAMP; HEADLAMP HOUSING

BATTERY

2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

TIRES & WHEELS

2 BATTERY; BATTERY

INTERIOR TRIM-MOLDINGS-UPHOLS

3 CAP; HUB CAP

QUALITY CHECK-REPAIRS

1 MOTOR; 15W40 MOTOR OIL NON SYN

CSHOP-2017-1872

Date Opened: 3-28-2017 Date Finished 3-28-2017 Meter 1 Reading: 124,795

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-1882

Date Opened: 3-29-2017 Date Finished 3-29-2017 Meter 1 Reading: 124,856

TASKS PERFORMED

NO PARTS USED

A INSPECTION

Asset Work Order History 10174224

CSHOP-2017-2310

Date Opened: 4-19-2017 Date Finished 4-19-2017 Meter 1 Reading: 125,395

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2017-2899

Date Opened: 5-16-2017 Date Finished 6-16-2017 Meter 1 Reading: 126,217

TASKS PERFORMED

NO PARTS USED

SHORELINE CHARGER
BRAKES

Service Requests:

05/16/2017 BRAKES / 19: LOOSE / REPAIR
BRAKE ISSUES. BRAKES HAVE TO BE DEPRESSED ALL THE WAY DOWN TO THE FLOOR AND STILL DOES NOT STOP
VEHICLE COMPLETELY.

05/16/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST: SHORELINE ON VEHICLE SEEMS TO BE PUSHED IN FAR ENOUGH, NOT ALLOWING THE POWER
CARD TO BE PLUGGED IN. .

CSHOP-2017-3473

Comments: **PRE-TRIP**

Date Opened: 6-12-2017 Date Finished 6-16-2017 Meter 1 Reading: 126,217

TASKS PERFORMED

NO PARTS USED

PRE TRIP INSPECTION

CSHOP-2017-3879

Comments: **DEAD BATTERY**

Date Opened: 6-30-2017 Date Finished 7-5-2017 Meter 1 Reading: 12,617

TASKS PERFORMED

Q PARTS

FUEL FILL BODY
CRANKING SYSTEM 1 9IP; LIGHT STEP LED
SAFTEY-EMERGENCY EQUIPMENT

CSHOP-2017-4383

Date Opened: 7-28-2017 Date Finished 8-21-2017 Meter 1 Reading: 126,217

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS 2 1AD; BATTERY
BATTERY
AUTO-EJECT
DIAGNOSE ELECTRICAL

Asset Work Order History 10174224

CSHOP-2017-5555

Date Opened: 9-25-2017 Date Finished 11-7-2017 Meter 1 Reading: 126,217

TASKS PERFORMED

Q PARTS

MIRRORS

1 1GM; MIRROR

CSHOP-2017-7007

Date Opened: 12-7-2017 Date Finished 12-7-2017 Meter 1 Reading: 126,539

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2017-7223

Date Opened: 12-18-2017 Date Finished 12-18-2017 Meter 1 Reading: 126,625

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? AL PACKER

CSHOP-2017-7278

Date Opened: 12-20-2017 Date Finished 12-20-2017 Meter 1 Reading: 126,625

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? AL PACKER

CSHOP-2018-1167

Date Opened: 2-26-2018 Date Finished 2-27-2018 Meter 1 Reading: 126,758

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? AL PACKER

CSHOP-2018-1529

Date Opened: 3-15-2018 Date Finished 3-19-2018 Meter 1 Reading: 127,705

TASKS PERFORMED

Q PARTS

BATTERY

1 1AD; BATTERY 96
2 1AD; BATTERY

Service Requests:

03/14/2018 ENGINE / 27: OVERHEATED / REPAIR
ENGINE. CHECK ENGINE LIGHT ON

Asset Work Order History 10174224

CSHOP-2018-1714

Date Opened: 3-26-2018 Date Finished 3-26-2018 Meter 1 Reading: 127,904

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? AL PACKER

CSHOP-2018-2239

Date Opened: 4-23-2018 Date Finished 4-23-2018 Meter 1 Reading: 128,535

TASKS PERFORMED

NO PARTS USED

BRAKES

VENDOR? AL PACKER

CSHOP-2018-3804

Date Opened: 7-5-2018 Date Finished 7-17-2018 Meter 1 Reading: 128,679

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2018-4572

Date Opened: 8-15-2018 Date Finished 8-15-2018 Meter 1 Reading: 129,321

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2018-6701

Date Opened: 11-27-2018 Date Finished 12-26-2018 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

BATTERY

2 1AD; BATTERY, SEVERE DUTY

CSHOP-2019-4290

Date Opened: 8-15-2019 Date Finished 8-15-2019 Meter 1 Reading: 129,901

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History 10174224

CSHOP-2019-5192

Date Opened: 10-3-2019 Date Finished 10-4-2019 Meter 1 Reading: 130,200

TASKS PERFORMED

Q PARTS

BATTERY

2 1AD; BATTERY GROUP 48

Service Requests:

10/03/2019 STARTER / 12: BROKEN / REPLACED NEW
VEHICLE BATTERY NOT CHARGING OR ALTERNATOR IS BAD. I HAVE HAD TO JUMP START IT THE PAST COUPLE OF TIMES IF I WENT MORE THAN A DAY WITHOUT USING IT... I AM AT HQ ALL DAY TODAY AND TOMORROW IF YOU ARE COMING TO PICK IT UP. PLEASE BRING A SPARE VEHICLE, AS IT IS MY MODE OF TRANSPORTATION AND I NEED A WAY TO GET HOME. THANK YOU KINDLY. MB

CSHOP-2019-6367

Date Opened: 12-9-2019 Date Finished 3-6-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

TOWING HITCH
VENDOR TIRE REPAIR/CHANGE

1 BK; BK
1 BK; TRI BALL REC HITCH

CSHOP-2020-1172

Date Opened: 2-27-2020 Date Finished 3-4-2020 Meter 1 Reading: 136,167

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2020-4007

Date Opened: 8-4-2020 Date Finished 8-5-2020 Meter 1 Reading: 138,054

TASKS PERFORMED

Q PARTS

BATTERY

2 1AD; BATTERY GROUP 48

CSHOP-2020-5478

Date Opened: 10-16-2020 Date Finished 10-20-2020 Meter 1 Reading: 138,054

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
BATTERY
STROBE LIGHTS

2 1AD; BATTERY GROUP 48
1 1WL; LED STROBE LIGHT RED
3 NW; PROSOFTTOUCHSWITCH
