

**Palm Beach County Fleet Management
Asset Maintenance History**

10195260 2014 FORD ESCAPE Suv, Mid Size

Workorder: 1409385 **Meter:** 182 **In Date:** 09/18/2014 **Closed:** 09/18/2014
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1500674 **Meter:** 9479 **In Date:** 01/20/2015 **Closed:** 01/29/2015
Problem: Pm service.

- P.m. Service.
 - Rotate and balance tires.
 - Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 43.22 Total: 223.22
 :

Workorder: 1503536 **Meter:** 15529 **In Date:** 04/06/2015 **Closed:** 04/14/2015
Problem: Pm service.

- Pm service.
 - Rotate and balance all four tires.
 - Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	2.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 55.39 Total: 235.39
 :

Workorder: 1505927 **Meter:** 21182 **In Date:** 06/15/2015 **Closed:** 06/22/2015
Problem: P.M. Service.

- Pm service.
 - Rotate and balance all four tires.
 - Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 24.04 Total: 204.04
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1508878 **Meter:** 28137 **In Date:** 09/03/2015 **Closed:** 09/11/2015
Problem: P.M. service and right rear tire flat.

- Pm service.	Parts List	Qty
- Replace and balance all four tires.	5w20 Engine Oil	6.00
- Complete front end alignment.test drive.	Napagold Oil Filter	1.00
- Shop Supplies	Mac Wite Lithium Gres	1.00
	Accufit Beam	2.00
	P235 55r17 Fuel Max	4.00
	Lug Nut	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 6.50	Labor: 390.00	Parts: 899.68
:		Total: 1,289.68

Workorder: 1508908 **Meter:** 27493 **In Date:** 09/03/2015 **Closed:** 09/04/2015
Problem: FFlat tire on passenger rear

- Tire Service Congress and 10th Ave shopping plaza - Flat tire on passenger rear	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1512191 **Meter:** 34407 **In Date:** 12/02/2015 **Closed:** 12/16/2015
Problem: Pm service.Check front end noise gets louder as you speed up.

- Pm service.	Parts List	Qty	
- Test and replace defective right brake lamp bulb.	Napagold Oil Filter	1.00	
- Rotate and balance all four tires.	5w20 Engine Oil	6.00	
- Transport vehicle to and from dealer for replacing defective left front wheel bearings.	Element	1.00	
- Shop Supplies	Accufit Beam	2.00	
	Blade	2.00	
	Bulb	1.00	
	Left Front Axle	1.00	
	Retainer	1.00	
	Napagold Oil Filter	1.00	
	Washer Fluid Concentr	1.00	
	Shop Supplies	1.00	
Hours 5.50	Labor: 330.00	Parts: 290.41	Total: 620.41
:			

Workorder: 1601676 **Meter:** 38288 **In Date:** 02/17/2016 **Closed:** 02/18/2016
Problem: Left headlamp inop.

- Test and replace left low beam headlamp bulb.	Parts List	Qty	
	Halogen Bulb	1.00	
Hours 0.50	Labor: 30.00	Parts: 12.44	Total: 42.44
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1602492 **Meter:** 39988 **In Date:** 03/09/2016 **Closed:** 03/14/2016
Problem: P.M. Service.Mount extinguisher.

- Pm service.	Parts List	Qty
- Rotate and balance all four tires.	5w20 Engine Oil	6.00
- Mount fire extinguisher and bracket.	Napagold Oil Filter	1.00
- Shop Supplies	Accufit Beam	2.00
	Blade	1.00
	Used Fire X Refurbished	1.00
	Custom Bracket Fire Ex	1.00
	Shop Supplies	1.00
Hours 3.50	Labor: 210.00	Parts: 133.60
:		Total: 343.60

Workorder: 1603963 **Meter:** 42890 **In Date:** 04/14/2016 **Closed:** 04/26/2016
Problem: R/F tire slow leak

- Repair and balance right front tire.	Parts List	Qty
- Replace right headlamp bulb.	Halogen Bulb	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 14.44
:		Total: 104.44

Workorder: 1605620 **Meter:** 45692 **In Date:** 06/01/2016 **Closed:** 06/09/2016
Problem: P.M. service and check battery.

- P.m. Service.	Parts List	Qty
- Test battery and charging system.recharge and retest battery,fail load test.replace dfective battery.	5w20 Engine Oil	6.00
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00
- Replace missing left front door handle trim.replace tag lamp bulb.	Accufit Beam	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Mac Wite Lithium Gres	1.00
	Bxt96r 59	1.00
	P235 55r17 Fuel Max	2.00
	Bulb	1.00
	235/55r17 Assurance	2.00
	Interior Door Handle	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.00	Labor: 360.00	Parts: 886.49
:		Total: 1,246.49

Workorder: 1608134 **Meter:** 51711 **In Date:** 08/08/2016 **Closed:** 08/23/2016
Problem: P.M. service and tag light out.

- P.m. Service.	Parts List	Qty
- Replace tag lamp bulb.	Bulb	1.00
- Rotate and balance all tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Oil Filter	1.00
	Accufit Beam	2.00
	Blade	1.00
	Shop Supplies	1.00
Hours 3.25	Labor: 195.00	Parts: 71.59
:		Total: 266.59

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1610172 **Meter:** 55336 **In Date:** 09/28/2016 **Closed:** 10/14/2016
Problem: Left headlight reflector fell down.

- Remove bumper assemble to replace left head light.	Parts List	Qty
- Replace light bar fuse, left front strobe light and two switches.	Headlamp Assy	1.00
- Shop Supplies	Universal Switch	2.00
	Vtx609c Led Strobe Cl	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 465.88
:		Total: 705.88

Workorder: 1611235 **Meter:** 58352 **In Date:** 10/31/2016 **Closed:** 11/29/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace two tires, rotate and balance all four.	5w20 Engine Oil	6.00
- A/c not cooling properly. a/c performance check. evacuate system and replace defective expansion valve and seal. vacuum system and recharge to specs.	Napagold Oil Filter	1.00
- Complete wheel alignment. test drive.	Accufit Beam	2.00
- Transport vehicle to dealer for transmission leak and noisy front axle.	Wpr/blde	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	235/55r17 Assurance	2.00
	Lug Nut	2.00
	Valva Asy A/c	1.00
	O Ring Kit A/c	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.50	Labor: 690.00	Parts: 442.13
:		Total: 1,132.13

Workorder: 1613065 **Meter:** 59569 **In Date:** 12/27/2016 **Closed:** 12/29/2016
Problem: Mount tire

- Tire Service Congress Ave - Mount tire	Labor: 0.00	Parts: 0.00	Total: 0.00
Hours 0.00			
:			

Workorder: 1613080 **Meter:** 60562 **In Date:** 12/27/2016 **Closed:** 01/10/2017
Problem: Right front tire flat.

- Replace and baalnce right front tire.	Parts List	Qty
- Shop Supplies	235/55r17 Assurance	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 0.50	Labor: 30.00	Parts: 290.79
:		Total: 320.79

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701030	Meter: 62407	In Date: 02/01/2017	Closed: 02/13/2017
Problem: Towed in, right rear tire flat.			
- Replace and balance right rear tire.		Parts List	Qty
- Check anfd adjust headlights.		235/55r17 Assurance	1.00
- Shop Supplies		Lug Nut	5.00
		Shop Supplies	1.00
		Tire Disposal Fee	1.00
Hours 1.00	Labor: 60.00	Parts: 182.55	Total: 242.55
:			

Workorder: 1701145	Meter: 61746	In Date: 01/31/2017	Closed: 02/02/2017
Problem: tire blow out			
- Tow From: 95 so bound/ lantana/ linton To: 2601 vista			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1701806	Meter: 63156	In Date: 02/21/2017	Closed: 03/01/2017
Problem: P.M. Service.Sctrew in right front tire.			
- P.m. Service.		Parts List	Qty
- Replace one tire,rotate and balance all four.		Napagold Oil Filter	1.00
- Pressure test and inspect cooling system.flush and refill system.		Washer Fluid Concentr	1.00
		5w20 Engine Oil	6.00
- Flush and refill transmission.		Accufit Beam	2.00
- Shop Supplies		Wpr/blde	1.00
		Used Fire X Refurbished	1.00
		235/55r17 Assurance	1.00
		Anti Freeze Motorcraft	2.00
		Syn-atf Trans Fluid S	12.00
		Non-chlor Brake Clnr	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	1.00
Hours 7.00	Labor: 420.00	Parts: 330.34	Total: 750.34
:			

Workorder: 1704580	Meter: 67965	In Date: 05/08/2017	Closed: 05/11/2017
Problem: P.M. service.			
- P.m. service.		Parts List	Qty
- Remove and install driver`s seat for repair.fabric torn.		5w20 Engine Oil	6.00
- Replace worn front brake pads.resurface rotors.service calipers.test drive.		Napagold Oil Filter	1.00
		Accufit Beam	2.00
- Rotate and balance four tires.nitrofill tires.		Stg Wheel Cov - Ford	1.00
- Shop Supplies		Floor Mat-2pc Rub Bk	1.00
		Fron Brake Pad	1.00
		Non-chlor Brake Clnr	1.00
		Seat R And R	1.00
		Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 438.58	Total: 858.58
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1707695 **Meter:** 73212 **In Date:** 08/07/2017 **Closed:** 08/16/2017
Problem: P.M. service.

- P.m. service.
- Four new tires,mount and nitorgen fill and high speed balance all four.
- Shop Supplies

Parts List	Qty
Blade	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
235/55r17 Assurance	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours 4.00 Labor: 240.00 Parts: 727.69 Total: 967.69
 :

Workorder: 1708563 **Meter:** 73841 **In Date:** 08/30/2017 **Closed:** 08/31/2017
Problem: Hard to start and won't at times.

- Charge battery fully.test battery and charging system.battery failed load test .r&r defective battery.
- Shop Supplies

Parts List	Qty
Battery	1.00
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 122.11 Total: 182.11
 :

Workorder: 1711175 **Meter:** 78284 **In Date:** 11/13/2017 **Closed:** 11/16/2017
Problem: P.M. service.

- P.m. service.
- Check and resurface both rear rotors.replace pads and service calipers.bleed hydraulic brake system and road test.
- Balance and rotate all four tires.
- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napa Air Filter	1.00
Napa Cabin Air Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Blade	1.00
Brake Pad Real	1.00
Shop Supplies	1.00

Hours 6.00 Labor: 360.00 Parts: 158.50 Total: 518.50
 :

Workorder: 1800170 **Meter:** 81197 **In Date:** 01/04/2018 **Closed:** 01/08/2018
Problem: Right front tire going flat.

- Replace right front tire.two screws and sidewall damage .balance and nitro service.
- Shop Supplies

Parts List	Qty
235/55r17 Assurance	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours 0.50 Labor: 30.00 Parts: 161.89 Total: 191.89
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1800917 **Meter:** 82404 **In Date:** 01/25/2018 **Closed:** 01/29/2018
Problem: Right headlight inop.

- Test and replace right low beam headlight bulb.retest.	Parts List	Qty
	Halogen Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 11.88
:		Total: 41.88

Workorder: 1801651 **Meter:** 84208 **In Date:** 02/12/2018 **Closed:** 03/15/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replace two front tires .rotate and balance all four tires.nitrogen fill tires.	5w20 Engine Oil	6.00
- Diagnose light bar take down lights and alley light inop.remove and replace all three lights .retest .replace left rear tail light lens and fabricate strobe in lens.	Napagold Oil Filter	1.00
- Shop Supplies	235/55r17 Assurance	2.00
	Lug Nut	4.00
	Engine Oil Stop Leak	1.00
	Lamp Asy	1.00
	Aley Light For Justice Bar	1.00
	Justice Take Down Light	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
	Freight Charge	1.00
Hours 6.50	Labor: 390.00	Parts: 1,177.16
:		Total: 1,567.16

Workorder: 1807182 **Meter:** 88328 **In Date:** 07/16/2018 **Closed:** 07/26/2018
Problem: P.M. service and left rear door will not close.

- P.m. service.	Parts List	Qty
- Test and replace left rear door latch and retest. Replace left front door weatherstrip. Replace missing door handle trim and left front seat recline handle.	Used Fire X Refurbished	1.00
- Perform tune-up . Replace all four spark plugs .	Washer Fluid Concentr	1.00
- Perform air induction cleaning and service. Flush injectors .	Wiper Blade	1.00
- Rotate and balance all four tires. Nitrofill and reset Tpms.	Wiper Blade	1.00
- Shop Supplies	Whl/nut	2.00
	Spark Plug	4.00
	Injector Cleaner	1.00
	Intake Cleaner Kit	1.00
	Blade	1.00
	Napagold Oil Filter	1.00
	5w20 Engine Oil	6.00
	Latch Door	1.00
	Interior Door Handle	1.00
	Door Seal	1.00
	Door Weatherstr	1.00
	Adjuster Handle	1.00
	Shop Supplies	1.00
Hours 8.50	Labor: 510.00	Parts: 559.22
:		Total: 1,069.22

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1811850 **Meter:** 93636 **In Date:** 11/19/2018 **Closed:** 11/26/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Test and replace loose left inner tie rod end .	Napagold Oil Filter	1.00
- Replace all four tires . High speed balance and nitrogen fill all.	Napa Quart 5w20	6.00
	Blade	1.00
- Complete four wheel alignment. Road test.	Wiper Blade	1.00
- Shop Supplies	Wiper Blade	1.00
	Rod Asy	1.00
	Tire235/55/17 Mic	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.30	Labor: 556.10	Parts: 880.03
:		Total: 1,436.13

Workorder: 1902664 **Meter:** 98252 **In Date:** 03/11/2019 **Closed:** 03/13/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Diagnose clicking noise on turns . R&r both defective front axles . Test drive.	White Shepherd Stp Lk	1.00
	Napagold Oil Filter	1.00
- Rotate and balance all four tires . Nitrofill all tires .	5w20 Engine Oil	6.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Blade	1.00
	Wiper Blade	1.00
	Wiper Blade	1.00
	Left Front Axle	1.00
	Shaft Assy Motorcraft	1.00
	Axle Nut	2.00
	Shop Supplies	1.00
Hours 7.30	Labor: 489.10	Parts: 608.67
:		Total: 1,097.77

Workorder: 1905835 **Meter:** 102732 **In Date:** 06/03/2019 **Closed:** 06/05/2019

Problem: Left rear tire flat spare on vehicle .

- Replace left rear tire and five damaged lug nuts . Nitrofill and balance tire.	Parts List	Qty
	Tire235/55/17 Mic	1.00
- Shop Supplies	Lug Nut	5.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 0.50	Labor: 33.50	Parts: 219.41
:		Total: 252.91

Workorder: 1905958 **Meter:** 102732 **In Date:** 06/03/2019 **Closed:** 06/05/2019

Problem: FLAT TIRE

- Tire Service Jpp Ranger Office - Flat Tire

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1906077 **Meter:** 103489 **In Date:** 06/10/2019 **Closed:** 06/20/2019

Problem: P.M. service.

- P.m. service.
- Check and inspect and replace defective front and side motor mounts. Retest .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Used Fire X Refurbished	1.00
Blade	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Engine Mount	1.00
Housing	1.00
Shop Supplies	1.00

Hours 5.20 Labor: 348.40 Parts: 251.85 Total: 600.25
:

Workorder: 1906989 **Meter:** 104352 **In Date:** 07/05/2019 **Closed:** 07/05/2019

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1909157 **Meter:** 107597 **In Date:** 09/05/2019 **Closed:** 09/18/2019

Problem: P.M. service and right rear door inop recall 16S30 .

- P.m. service.
- Rotate and balance all four tires . Nitrofill all.
- Transport to and from dealer for recall 16s30 .
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Blade	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Brake Pedal Cover	1.00
Shop Supplies	1.00

Hours 5.00 Labor: 335.00 Parts: 98.37 Total: 433.37
:

Workorder: 1911832 **Meter:** 110239 **In Date:** 11/14/2019 **Closed:** 11/15/2019

Problem: remove decals for surplus

- remove extra decals for surplus
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.50 Labor: 109.50 Parts: 4.00 Total: 113.50
:

Workorder: 1911856 **Meter:** 110239 **In Date:** 11/15/2019 **Closed:** 11/15/2019

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00
: