

**Palm Beach County Fleet Management
Asset Maintenance History**

10185254 2011 GMC SAVANA 2500 Van, 3/4 Ton, Cargo

Workorder: 1103856 **Meter:** 0 **In Date:** 04/11/2011 **Closed:** 04/11/2011
Problem: Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1112517 **Meter:** 6076 **In Date:** 11/28/2011 **Closed:** 01/23/2012
Problem: PM Service

- pm service

Parts List

Qty

- rotate tires

Shop Supplies 1.00

- mount fire ext bracket

Ph10060 Oil Filter Acd Pf48 Wix 57060 1.00

- replace mirror

10w30 Motor Oil 6.00

- Shop Supplies

5lb Firex Abc Stock# 340280001 1.00

Custom5lb Bracket Firex Stock #340060300 1.00

Mirror / 19207169 1.00

Hours 6.00 Labor: 360.00 Parts: 95.74 Total: 455.74
:

Workorder: 1113202 **Meter:** 5829 **In Date:** 11/30/2011 **Closed:** 12/15/2011
Problem: damage to rear bumper

- damage to rear bumper

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1208571 **Meter:** 13081 **In Date:** 09/10/2012 **Closed:** 09/20/2012
Problem: DRIVERS HEAD LIGHT OUT

- Remove And Replace Headlight

Parts List

Qty

H6054 Sealed Beam 1.00

Hours 0.50 Labor: 30.00 Parts: 17.99 Total: 47.99
:

Workorder: 1212238 **Meter:** 16145 **In Date:** 12/19/2012 **Closed:** 12/26/2012
Problem: Pm service

- Pm service

Parts List

Qty

- Rotate and balance tires

Napa 10w30 Qt 6.00

- Test drive

Filter 1.00

- Shop Supplies

Napagold Air Filter 1.00

31-22 Wiper Blades 22 2.00

Shop Supplies 1.00

Hours 5.50 Labor: 330.00 Parts: 51.34 Total: 381.34
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1400588 **Meter:** 24376 **In Date:** 01/17/2014 **Closed:** 01/31/2014
Problem: P.M. service and left rear tire going flat and noise from A/C fan.

- P.m. Service.	Parts List	Qty
- R&r blower motot and clean leaves and debris from evaporator housing.	Dexos 5w30 Oil	6.00
- Rotate and balance all tires.	Napagold Oil Filter	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Wiper Blade	2.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 68.51
:		Total: 428.51

Workorder: 1402007 **Meter:** 25518 **In Date:** 02/28/2014 **Closed:** 03/11/2014
Problem: Left headlamp inop.

- Test and replace failed left headlamp sealbeam assembly with new.	Parts List	Qty
	Halogen Lamp	1.00
Hours 0.50	Labor: 30.00	Parts: 9.87
:		Total: 39.87

Workorder: 1407645 **Meter:** 30166 **In Date:** 08/04/2014 **Closed:** 08/19/2014
Problem: Pm service.left front tire flat.Safety recall,impact protection trim.

- Perform pm service.	Parts List	Qty
- Install four new tires.nitrogen fill and balance all four.	Napagold Oil Filter	1.00
- Perform wheel alignment.	10w30 Motor Oil	6.00
- Transport vehicle to and from dealer for performing restrain system safety recall #14082 Replacing trim panel and tray for passenger side restrain system.	Napagold Air Filter	1.00
	179747492 Lt245-75r16	4.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 10.50	Labor: 630.00	Parts: 918.93
:		Total: 1,548.93

Workorder: 1501417 **Meter:** 37482 **In Date:** 02/06/2015 **Closed:** 02/19/2015
Problem: Pm service.Check brakes.

- Pm service.	Parts List	Qty
- Rotate and balance all four tires.	Dexos 5w30 Oil	6.00
- Inspect and service all four calipers and lube slide pins.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 69.38
:		Total: 519.38

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1508332	Meter: 47563	In Date: 08/19/2015	Closed: 08/26/2015
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Rotate and balance tires.		Brake Cleaner	1.00
- Test drive.		Napa 10w30 Qt	6.00
- Shop Supplies		Napagold Oil Filter	1.00
		Wiper Blade	2.00
		Washer Fluid Concentr	1.00
		Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 41.53	Total: 371.53
:			

Workorder: 1512632	Meter: 49042	In Date: 12/15/2015	Closed: 12/17/2015
Problem: Slow crank,A/C blower not working.			
- Check a/c blower operation. Replace shorted blower module.		Parts List	Qty
- Load test battery. Battery failed load test. Replace battery.		Blower Motor Resistor	1.00
- Test drive.		Battery	1.00
- Shop Supplies		Blower Motor Resistor	1.00
		Shop Supplies	1.00
Hours 3.50	Labor: 210.00	Parts: 144.07	Total: 354.07
:			

Workorder: 1601960	Meter: 53198	In Date: 02/25/2016	Closed: 03/07/2016
Problem: Towed in right rear tire damage.PM service.			
- Pm service.		Parts List	Qty
- Replace and balance all four tires.		Lt245 75r16 Mich Ltx Ms2	4.00
- Pressure test and inspect cooling system.flush and replace coolant.		Dexos 5w30	6.00
- Transmission service.replace filter.flush and replace fluid.		Napagold Oil Filter	1.00
- Complete front end alignment.		22" Wiper Blade	2.00
- Shop Supplies		Used Fire X Refurbished	1.00
		Peak Global	2.00
		Syn-atf Trans Fluid S	16.00
		Filter Kit	1.00
		Fliter Tram Kit	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	4.00
Hours 13.00	Labor: 780.00	Parts: 1,198.96	Total: 1,978.96
:			

Workorder: 1602016	Meter: 53130	In Date: 02/25/2016	Closed: 02/26/2016
Problem: flat tire			
- Tow From: lantana and jog To: vista lv			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1604976 **Meter:** 58454 **In Date:** 05/13/2016 **Closed:** 05/20/2016
Problem: Left rear signal light inop

- Replace left rear signal light bulb.	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.78
:		Total: 30.78

Workorder: 1607156 **Meter:** 60495 **In Date:** 07/14/2016 **Closed:** 08/03/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Rotate and balance tires.	Actuator	1.00
- A/c blowing hot. A/c temp blend door actuator not working.	Actuator	1.00
Replace blend door actuator.	Napa 10w30 Qt	6.00
- Test drive.	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Actuator 52417462	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 167.33
:		Total: 647.33

Workorder: 1611288 **Meter:** 65558 **In Date:** 11/01/2016 **Closed:** 11/10/2016
Problem: Pm service and list

- Pm service.	Parts List	Qty
- Won't start. No fuel pressure. R&r fuel tank. Replace fuel pump assy.	Fuel Pump	1.00
	Insulator	2.00
- Replace temp. blend door actuator.	Actuator 52417462	1.00
- Replace worn sway bar mounting bushings.	Napa 10w30 Qt	6.00
- Rotate and balance tires.	Napagold Oil Filter	1.00
- Test drive.	Napagold Air Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Syn Atf Bulk Pahokee	1.00
	Shop Supplies	1.00
Hours 15.50	Labor: 930.00	Parts: 511.15
:		Total: 1,441.15

Workorder: 1611298 **Meter:** 65419 **In Date:** 11/01/2016 **Closed:** 11/01/2016
Problem: Won't run

- Tow From: Pa wastewater palnt To: Pa shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1702414 **Meter:** 72205 **In Date:** 03/09/2017 **Closed:** 03/23/2017
Problem: Pm service, check a/c.

- Pm service.	Parts List	Qty
- A/c not working. Temp control not working. No voltage to temp door actuator. Replace a/c control head.	Napa 10w30 Qt	6.00
- Rotate and balance tires.	Napagold Oil Filter	1.00
- Test drive.	22" Wiper Blade	2.00
- R&r dash assy. Reinstall temp. door actuator.	Washer Fluid Concentr	1.00
- Shop Supplies	Control	1.00
	Shop Supplies	1.00
Hours 12.00	Labor: 720.00	Parts: 281.80
:		Total: 1,001.80

Workorder: 1702942 **Meter:** 72519 **In Date:** 03/23/2017 **Closed:** 03/30/2017
Problem: Check charging system warning on dash .

- Recharge battery and test charging system.alternator not charging.replace bad alternator.	Parts List	Qty
- Replace serpentine belt.	Alternado A/c Delco	1.00
- Shop Supplies	Belt	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 409.85
:		Total: 589.85

Workorder: 1706270 **Meter:** 78350 **In Date:** 06/26/2017 **Closed:** 06/27/2017
Problem: Pm service.

- Pm service.	Parts List	Qty
- Rotate and balance tires.	Napa 10w30 Qt	6.00
- Check a/c blower. Repaired poor connection in a/c blower harness.	Napagold Oil Filter	1.00
- Test drive.	Napagold Air Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 59.53
:		Total: 449.53

Workorder: 1706363 **Meter:** 78350 **In Date:** 06/27/2017 **Closed:** 07/13/2017
Problem: Replace cracked windshield.

- Replaced cracked windshield.			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1707921 **Meter:** 80615 **In Date:** 08/14/2017 **Closed:** 08/16/2017
Problem: Left headlight inop.

- Test and replace left headlamp assembly.retest.	Parts List	Qty
	Halogen Lamp	1.00
Hours 0.50	Labor: 30.00	Parts: 13.01
:		Total: 43.01

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1711484 **Meter:** 87431 **In Date:** 11/20/2017 **Closed:** 12/04/2017
Problem: PM Service, Left front tire has plug in it, Check Tranny fluid.

- P.m. service.	Parts List	Qty
- Inspect and replace two worn tires on front with new.rotate and high speed balance four wheels.nitro fill all.	10w30 Motor Oil	6.00
- Perform complete front end alignment .road test .	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Lt245/75/16 Tire Mic	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.50	Labor: 510.00	Parts: 478.91
:		Total: 988.91

Workorder: 1803386 **Meter:** 95155 **In Date:** 03/30/2018 **Closed:** 04/06/2018
Problem: PM Service, Transmission intermittently hangs up when shifting from 3rd to 4th.

- P.m. service.	Parts List	Qty
- Replace two worn tire .rotate and balance all four tires .nitrogen fill all tires.	Napagold Oil Filter	1.00
- Computer diagnose transmission issue .no codes ,test drive .service transmission .replace Filter and flush transmission fluid .test drive.	22" Wiper Blade	2.00
- Fabricate and install new front asset number.	Used Fire X Refurbished	1.00
- Shop Supplies	Lt245/75/16 Tire Mic	2.00
	Atp Platinum Kit	1.00
	Syn-atf Trans Fluid S	16.00
	10w30 Motor Oil	6.00
	Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 593.95
:		Total: 1,133.95

Workorder: 1806065 **Meter:** 98704 **In Date:** 06/13/2018 **Closed:** 07/03/2018
Problem: Check engine light, hesitates and almost stalls. A/C intermittently stops blowing.

- Diagnose burned harness at blower motor .r&r defective resistor and pigtail and blower motor .	Parts List	Qty
- Computer diagnose check engine light and stalling .codes P0171 and P0174 .check for vacuum leaks replace mass air flow pigtail .check fuel pressure .remove fuel tank to replace fuel pump and pigtail.clear codes and test drive.	Blower Motor A/c	1.00
- Shop Supplies	A/c Connector Blower Resistor	1.00
	Blower Resistor	1.00
	Maf Sensor Connector	1.00
	Fuel Pump	1.00
	Fuel Harness Repair Kit	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 655.24
:		Total: 1,105.24

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808735 **Meter:** 101338 **In Date:** 08/23/2018 **Closed:** 08/30/2018

Problem: PM Service

- P.m. service.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
10w30 Motor Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours 5.00 Labor: 300.00 Parts: 35.78 Total: 335.78
:

Workorder: 1810737 **Meter:** 104000 **In Date:** 10/18/2018 **Closed:** 10/24/2018

Problem: replace left rear door glass

- set up repairs & check
- Shop Supplies

Parts List	Qty
Window Replacement 10185254	1.00
Shop Supplies	1.00

Hours 1.00 Labor: 67.00 Parts: 264.32 Total: 331.32
:

Workorder: 1812637 **Meter:** 107214 **In Date:** 12/12/2018 **Closed:** 12/20/2018

Problem: P.M. service.

- P.m. service.
- Check battery and charging system .after fully charging battery failed load test . R&R defective battery and battery terminal bolts .
- Balance and rotate all four tires. Nitrofill all .
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napa Syn 5w30 Qt	6.00
22" Wiper Blade	2.00
Chevy Gold Bow Swc	1.00
Battery Cable Bolt	1.00
Battery	1.00
2pc Hd Mat Set Blk	1.00
Shop Supplies	1.00

Hours 6.00 Labor: 402.00 Parts: 224.24 Total: 626.24
:

Workorder: 1902988 **Meter:** 111806 **In Date:** 03/18/2019 **Closed:** 03/28/2019

Problem: P.M. Service.Check battery.

- P.m. service . Test battery and charging system . Test starting system and electrical systems . No problem found could not duplicate at this time .
- Test and replace right headlight bulb .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napa Syn 5w30 Qt	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Halogen Sealed Beams	1.00
Shop Supplies	1.00

Hours 5.80 Labor: 388.60 Parts: 80.64 Total: 469.24
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1906332 **Meter:** 116901 **In Date:** 06/17/2019 **Closed:** 06/24/2019

Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Test and replace tag light bulb .	Napagold Oil Filter	1.00
- Rotate and high speed balance all four tires . Nitrofill all.	Napa Syn 5w30 Qt	6.00
- Shop Supplies	Bat Term Protector	1.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Boxed Miniatures	1.00
	Shop Supplies	1.00
Hours 5.50	Labor: 368.50	Parts: 55.64
:		Total: 424.14

Workorder: 1910657 **Meter:** 123737 **In Date:** 10/16/2019 **Closed:** 10/29/2019

Problem: P.M. service and A/C blower inop .

- P.m. service.	Parts List	Qty
- Test and replace defective blower resistor . Retest .	Napagold Oil Filter	1.00
- Replace broken left front window knob .	Napa Syn 5w30 Qt	6.00
- Rotate and high speed balance all four tires . Nitrofill all.	Washer Fluid Concentr	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Module Kit	1.00
	handle	1.00
	Shop Supplies	1.00
Hours 6.60	Labor: 481.80	Parts: 204.12
:		Total: 685.92

Workorder: 2002390 **Meter:** 128100 **In Date:** 03/09/2020 **Closed:** 03/11/2020

Problem: Right rear tire flat and spare on vehicle .

- Replace left rear tire and balance . Nitrofill all tires and remount spare under vehicle .	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Lt245/75r16 Tire	1.00
	Tire Disposal Fee	1.00
Hours 0.50	Labor: 36.50	Parts: 125.99
:		Total: 162.49

Workorder: 2003372 **Meter:** 128557 **In Date:** 04/02/2020 **Closed:** 04/02/2020

Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			