

**Palm Beach County Fleet Management
Asset Maintenance History**

K11490 2004 GMC 1500 Pickup, 1/2 Ton, W/8 Ft. Body

Workorder: 438351 **Meter:** 0 **In Date:** 03/17/2004 **Closed:** 03/17/2004
Problem: TAG CHARGE

- Vehicle Tag	Parts List	Qty
	Vehicle Tag Charge	1.00
Hours 0.00	Labor: 0.00	Parts: 34.35
:		Total: 34.35

Workorder: 438871 **Meter:** 0 **In Date:** 03/22/2004 **Closed:** 03/22/2004
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection	Hours 2.00	Labor: 100.00	Parts: 0.00	Total: 100.00
:				

Workorder: 439339 **Meter:** 13 **In Date:** 03/26/2004 **Closed:** 03/29/2004
Problem: INSTALL STROBE LIGHT.

- Fabricate & Install Strobe Light Assy.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Ds-167 Toggle Switch (standard)	1.00
	06133 3m Electric Tape Stock #832260101	1.00
	Ds366 Red Pilot Light	1.00
Hours 4.00	Labor: 200.00	Parts: 14.25
:		Total: 214.25

Workorder: 439911 **Meter:** 13 **In Date:** 04/01/2004 **Closed:** 04/13/2004
Problem: FAB LIGHT BRACKET

- Fab Light Bracket.	Parts List	Qty
- Welding Supplies	Shop Supplies	1.00
	1/2x6x12 Alum Flat Bar	1.00
	3/16x4x12 Alum Plate 5052	1.00
	1/4x2x4x20 Alum Angle 6063	1.00
	1/4x2x24 Sq. Alum Tube	3.00
Hours 4.00	Labor: 200.00	Parts: 36.59
:		Total: 236.59

Workorder: 442186 **Meter:** 215 **In Date:** 04/22/2004 **Closed:** 04/30/2004
Problem: FAB LADDER RACK

- Fab Ladder Rack	Parts List	Qty
- Welding Supplies	Blade 2ac18	3.00
	Shop Supplies	1.00
	1/4x3x20 Alum Flat Bar 6063	4.00
	1/4x8x12 Alum. Flat Bar	3.00
	3/16x4x10 Dia Plate Aluminum Non Bright	8.00
	2x2x1/4x20 Alum Angle Architectual	1.00
	1/4x2x24 Sq. Alum Tube	14.00
Hours 18.00	Labor: 900.00	Parts: 217.41
:		Total: 1,117.41

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 453462 **Meter:** 1683 **In Date:** 08/09/2004 **Closed:** 08/11/2004
Problem: RT.REAR TIRE FLAT

- Tire Repair	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 50.00	Parts: 2.00
:		Total: 52.00

Workorder: 540605 **Meter:** 4623 **In Date:** 03/31/2005 **Closed:** 04/04/2005
Problem: P.M.SERVICE/SEE NOTE

- Pm Service	Parts List	Qty
- Install Rear Wiring Kit For Rear Mounted Hitch.	Shop Supplies	1.00
- Shop Supplies	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
	10w30 Motor Oil	5.00
Hours 6.00	Labor: 300.00	Parts: 13.57
:		Total: 313.57

Workorder: 548642 **Meter:** 5640 **In Date:** 06/24/2005 **Closed:** 06/27/2005
Problem: SLOW LEAK R/F TIRE.

- R&r R/front Tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	773430430 235/75r16 Wrangler St SI	1.00
Hours 1.00	Labor: 50.00	Parts: 74.90
:		Total: 124.90

Workorder: 556740 **Meter:** 6770 **In Date:** 10/13/2005 **Closed:** 10/14/2005
Problem: P.M. SERVICE.

- Pm Service	Parts List	Qty
- Install F/extinguisher And Bracket.	Shop Supplies	1.00
- Shop Supplies	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
	3481 Fuel Filter Frm G3727 Wix 33481	1.00
	10w30 Motor Oil	6.00
Hours 2.25	Labor: 112.50	Parts: 20.14
:		Total: 132.64

Workorder: 637318 **Meter:** 8753 **In Date:** 04/13/2006 **Closed:** 04/14/2006
Problem: P.M.SERVICE

- Pm Service	Parts List	Qty
- R&r 3 Tires	Shop Supplies	1.00
- Remove Comber Kit To Complete Alignment.test Drive.	6678 Air Filter Frm Ca8755a Wix 46678	1.00
- Shop Supplies	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
	10w30 Motor Oil	5.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	88891787 Drain Plug Gmc/chevy	1.00
	Tire Disposal Fee	3.00
	773430430 235/75r16 Wrangler St SI	3.00
Hours 6.50	Labor: 325.00	Parts: 367.07
:		Total: 692.07

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 650414	Meter: 10547	In Date: 12/22/2006	Closed: 12/28/2006
Problem: PM SERVICE			
- Perform Pm Service		Parts List	Qty
- Nitrogen Fill All Tires.		Shop Supplies	1.00
- Shop Supplies		Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		10w30 Motor Oil	5.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 3.00	Labor: 165.00	Parts: 33.83	Total: 198.83
:			
Workorder: 734302	Meter: 10883	In Date: 02/14/2007	Closed: 02/16/2007
Problem: R/R TIRE GOING FLAT			
- Repair R/r Tire		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 55.00	Parts: 2.00	Total: 57.00
:			
Workorder: 741095	Meter: 12104	In Date: 07/09/2007	Closed: 07/10/2007
Problem: P.M. SERVICE.			
- Pm Service Complete.replace 2 Wiper Blades And Rotate Tires Added Fuel Additive		Parts List	Qty
- Hi Speed Balance On All 4 Tires.		Shop Supplies	1.00
- Shop Supplies		Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
		10020 Injector Cleaner Don't Reorder	1.00
		10w30 Motor Oil	5.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 3.00	Labor: 165.00	Parts: 32.18	Total: 197.18
:			
Workorder: 833834	Meter: 14111	In Date: 02/07/2008	Closed: 02/12/2008
Problem: P.M. SERVICE.RATTLE IN STEERING.			
- Pm Service		Parts List	Qty
- Rotate & Highspeed Balance 4 Tires.refill W/nitrogen		Shop Supplies	1.00
- Lube Intermediate Steering Shaft Noisy.		Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Shop Supplies		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		10020 Injector Cleaner Don't Reorder	1.00
		10w30 Motor Oil	5.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
		Used Firex Refurbed Fire Extingshers	1.00
Hours 4.00	Labor: 240.00	Parts: 48.45	Total: 288.45
:			
Workorder: 838102	Meter: 14834	In Date: 05/06/2008	Closed: 05/08/2008
Problem: R/F TIRE FLAT			
- R&r R/f Tire W/used Tire.mount Tire High Speed Balance Refill W/nitrogen Air.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 838584 **Meter:** 15115 **In Date:** 05/15/2008 **Closed:** 05/16/2008
Problem: L/F TIRE FLAT.

- Repair Left Front Tire And Remount Spare Tire Back Under Bed	Parts List	Qty
	Shop Supplies	1.00
- Shop Supplies		
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 844277 **Meter:** 16028 **In Date:** 09/16/2008 **Closed:** 09/24/2008
Problem: P.M. SERVICE.INSTALL BED CAPS.

- Pm Service	Parts List	Qty
- Service Trans,flush & Refill System.	Big G Degreaser Stock# 485180002	1.00
- Remove Strobe Light Bracket & Ladder Rack.fabricate & Install 2 Bed End Caps.	Shop Supplies	1.00
- Rotate & Hi Speed Balance 4 Tires,nitro Fill Tires.	6678 Air Filter Frm Ca8755a Wix 46678	1.00
- Shop Supplies	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
	3481 Fuel Filter Frm G3727 Wix 33481	1.00
	10w30 Motor Oil	5.00
	Syn/atf Trans Fluid Synthetic	14.00
	Side Bed Cap	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 7.50	Labor: 450.00	Parts: 216.25
:		Total: 666.25

Workorder: 845601 **Meter:** 16228 **In Date:** 10/14/2008 **Closed:** 10/15/2008
Problem: FLAT TIRE

- Repair Right Rear Tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 933965 **Meter:** 0 **In Date:** 10/30/2008 **Closed:** 02/12/2009
Problem: SISTERS TOWING & TRANSPORTATON TOW FROM LANTANA AI

- Sisters Towing & Transportaton Tow From Lantana Airport			
- Tow To			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 935467 **Meter:** 17290 **In Date:** 03/23/2009 **Closed:** 03/30/2009
Problem: P.M. SERVICE.

- Pm Service	Parts List	Qty
- Mount,balance & Nitro Fill 4 New Tires.	Shop Supplies	1.00
- Complete Front End Alignment	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Shop Supplies	10w30 Motor Oil	5.00
	Used Firex Refurbed Fire Extingshers	1.00
	Tire Disposal Fee	4.00
	773430430 235/75r16 Wrangler St SI	4.00
Hours 6.50	Labor: 390.00	Parts: 489.88
:		Total: 879.88

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 943622	Meter: 18337	In Date: 09/23/2009	Closed: 09/29/2009
Problem: P.M service.			
- P.m. Service.		Parts List	Qty
- Test battery and charging system.battery failed load test,replace battery.		Shop Supplies	1.00
- Rotate and balance all tires.		Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Shop Supplies		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		10w30 Motor Oil	5.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
		Group 78 Battery (acd 78ps)	1.00
Hours 4.00	Labor: 240.00	Parts: 142.22	Total: 382.22
:			
Workorder: 1000910	Meter: 19728	In Date: 01/25/2010	Closed: 01/26/2010
Problem: Nail in R/F tire.			
- Repair R/f tire.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1004230	Meter: 20363	In Date: 04/23/2010	Closed: 04/28/2010
Problem: P.M service, see note.			
- P.m service.		Parts List	Qty
- Pressure test & inspect cooling system, flush & renew coolant.		Shop Supplies	1.00
- Shop Supplies		Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
		10w30 Motor Oil	5.00
		Used Firex Refurbed Fire Extingshers	1.00
		Antifreeze Ext/life All Makes (peak 407)	2.00
Hours 4.00	Labor: 240.00	Parts: 60.21	Total: 300.21
:			
Workorder: 1005832	Meter: 20534	In Date: 06/03/2010	Closed: 06/03/2010
Problem: no start			
- From: 3700 belvdere rd n of bldg b To: lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1005860	Meter: 20544	In Date: 06/03/2010	Closed: 06/09/2010
Problem: Towed in no start.			
- Computer diagnose and fuel pressure test. Replace failed distributor cap and rotor with new.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		D465 Ignition Rotor (acd)	1.00
		D328a Dist Cap (acd)	1.00
Hours 2.00	Labor: 120.00	Parts: 49.26	Total: 169.26
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1012393 **Meter:** 21224 **In Date:** 11/04/2010 **Closed:** 11/15/2010
Problem: Pm service.

- Perform pm service.	Parts List	Qty
- Diagnose noise in steering.test and replace failed steering intermediate sector shaft with new.	Shop Supplies	1.00
- Rotate and balance all four tires.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Shop Supplies	3481 Fuel Filter Frm G3727 Wix 33481	1.00
	10w30 Motor Oil	5.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	19153614 Steer Shaft Intermediate (gmc)	1.00
Hours 4.50	Labor: 270.00	Parts: 120.72
:		Total: 390.72

Workorder: 1106251 **Meter:** 22108 **In Date:** 06/14/2011 **Closed:** 06/22/2011
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Repair headliner.	Shop Supplies	1.00
- Rotate and balance all tires.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Shop Supplies	10w30 Motor Oil	5.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 3.50	Labor: 210.00	Parts: 43.51
:		Total: 253.51

Workorder: 1201205 **Meter:** 23504 **In Date:** 02/06/2012 **Closed:** 02/29/2012
Problem: P.M. service and headliner falling down and install tool box.see notes.

- P.m. Service.	Parts List	Qty
- Replace rear bump stoppers on rear suspension.install and secure tool box in cargo bed.	Shop Supplies	1.00
- Transport vehicle to upholstery shop for headliner repair.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Replace two tires,rotate and balance all four.	3481 Fuel Filter Frm G3727 Wix 33481	1.00
- Complete wheel alignment.test drive.	1066 White Lithium (crc 05037)	1.00
- Shop Supplies	10w30 Motor Oil	5.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Rear Spring Bump Stop	1.00
	183680418 P235/75r16 Wrangler Sr-a 109s	2.00
	Tire Disposal Fee	2.00
	117 Used Tool Box Weather Guard Tool Box	1.00
Hours 10.00	Labor: 600.00	Parts: 450.55
:		Total: 1,050.55

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1301743 **Meter:** 26291 **In Date:** 02/20/2013 **Closed:** 03/11/2013
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Replace two tires,rotate and balance all four.	10w30 Motor Oil	5.00
- Test battery and charging system.replace bad battery.	Oil Filter	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	22514722 O-ring Seal	2.00
	31-22 Wiper Blades 22	2.00
	Used Firex Refurbed F	1.00
	183680418 P235-75r16	2.00
	Group 78 Acd	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 5.00	Labor: 300.00	Parts: 538.58
:		Total: 838.58

Workorder: 1302590 **Meter:** 26291 **In Date:** 03/05/2013 **Closed:** 03/15/2013
Problem: repair rust at third light

- repair rust at third light	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1309238 **Meter:** 28218 **In Date:** 09/11/2013 **Closed:** 10/08/2013
Problem: Pm service.

- P.m. Service.	Parts List	Qty	
- Test and replace a/c blower resistor.	Brake Hose	1.00	
- Replace both front brakes hoses.flush and bleed system.	Instrument Cluster	1.00	
- Diagnose inop tach-meter and temp gauge.replace and reprogram instrument cluster.	10w30 Motor Oil	5.00	
- Repair right rear tire,rotate and balance all four.	Napagold Oil Filter	1.00	
- Shop Supplies	Napagold Fuel Filter	1.00	
	Wiper Blade	2.00	
	Blower Motor Resistor	1.00	
	Brake Cleaner	1.00	
	Brake Hose	1.00	
	Brake Hose	1.00	
	Resistor	1.00	
	Brake Hose	1.00	
	Brake Hose	1.00	
	Shop Supplies	1.00	
Hours 9.00	Labor: 540.00	Parts: 735.28	Total: 1,275.28
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1405367 **Meter:** 30262 **In Date:** 06/02/2014 **Closed:** 06/10/2014
Problem: P.M. Service

- P.m.,. Service.	Parts List	Qty
- Rotate and balance all tires.	10w30 Motor Oil	5.00
- Shop Supplies	Napagold Oil Filter	1.00
	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 41.83
:		Total: 221.83

Workorder: 1502648 **Meter:** 31551 **In Date:** 03/13/2015 **Closed:** 03/20/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Diagnose for windshield washer pump inop.test and replace defective washer pump.	10w30 Motor Oil	5.00
- Diagnose for becon strobe lamp inop.test and replace defective becon strobe lamp assembly.fabricate pedestal necessary to mount lamp.	Napagold Oil Filter	1.00
- Replace two tires.rotate and balance all four.	Wiper Blade	2.00
- Perform complete front end alignment.	Napagold Fuel Filter	1.00
- Shop Supplies	183680418 P235-75r16	2.00
	Washer Fluid Concentr	1.00
	Wiper Fluid Reservoir	1.00
	W S Wash	1.00
	Strobe	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 9.00	Labor: 540.00	Parts: 597.72
:		Total: 1,137.72

Workorder: 1512049 **Meter:** 32372 **In Date:** 11/30/2015 **Closed:** 12/08/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Rotate and balance all four tires.	10w30 Motor Oil	5.00
- Shop Supplies	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 44.02
:		Total: 224.02

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1606053 **Meter:** 34120 **In Date:** 06/13/2016 **Closed:** 06/23/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Test battery and charging system.replace bad battery.	10w30 Motor Oil	5.00
- Replace missing tailgate handle bezel.	Napagold Oil Filter	1.00
- Rotate and balance all tires.	22" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Group 78 Battery	1.00
	Mac Wite Lithium Gres	1.00
	Tail Gate Handle Bezel	1.00
	Drain Plug	1.00
	Shop Supplies	1.00
Hours 4.50	Labor: 270.00	Parts: 166.58
:		Total: 436.58

Workorder: 1613242 **Meter:** 35166 **In Date:** 12/30/2016 **Closed:** 02/14/2017
Problem: P.M. Service.

- P.m. Service.	Parts List	Qty
- Replace two tires,rotate and balance all four.	10w30 Motor Oil	5.00
- Replace rear brake rotors and brake pads.service and lube calipers.flush and bleed system.	Napagold Oil Filter	1.00
- Replace right rear signal light bulb.	22" Wiper Blade	2.00
- Re-install rearview mirror.	Washer Fluid Concentr	1.00
- Complete wheel alignment.test drive.	Napagold Fuel Filter	1.00
- Shop Supplies	183680418 P235-75r16	2.00
	Disc Brake Pads	1.00
	Non-chlor Brake Clnr	1.00
	Brake Rotor	2.00
	Bulb	2.00
	Ptex Rview Mir Adh Cd	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.00	Labor: 660.00	Parts: 623.70
:		Total: 1,283.70

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1708370 **Meter:** 36182 **In Date:** 08/24/2017 **Closed:** 09/07/2017
Problem: PM Service, Drivers side tire has screw in it.

- P.m. service.	Parts List	Qty
- Check ,pinpoint test and replace left front turn signal bulb.	10w30 Motor Oil	5.00
- Check serpentine belt and pulleys for noise from engine area when running.replace defective belt and tensioner and idler pulley.	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
- Check and replace the upper and lower left front door hinge pins and bushings by cutting them out.	Used Fire X Refurbished	1.00
	Washer Fluid Concentr	1.00
- Check battery and charging system.fully charge battery and retest. Battery failed load test .replace battery and terminal bolts.	Bulb	1.00
	Engine Belt	1.00
	Tensioner	1.00
- Repair left rear tire and balance all four and rotate.	Pulley Idler	1.00
- Shop Supplies	Pin Kitfront Door Upper	2.00
	Group 78 Battery	1.00
	Battery Cable Bolt	1.00
	Shop Supplies	1.00
Hours 8.80	Labor: 528.00	Parts: 554.68
:		Total: 1,082.68

Workorder: 1803061 **Meter:** 37248 **In Date:** 03/22/2018 **Closed:** 03/29/2018
Problem: P.M. Service.

- P.m. service.	Parts List	Qty
- Repair right rear tire .rotate and balance all four tires.nitrogen fill tires.	10w30 Motor Oil	5.00
	Napagold Oil Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 28.60
:		Total: 268.60

Workorder: 1808237 **Meter:** 38320 **In Date:** 08/10/2018 **Closed:** 08/28/2018
Problem: Repair right front tire.

- Cancel P.m. service.	Parts List	Qty
- Repair right front tires and balance . Nitrofill all.	Shop Supplies	1.00
- Shop Supplies		
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1811059 **Meter:** 39257 **In Date:** 10/26/2018 **Closed:** 11/06/2018
Problem: PM Service

- P.m. service.	Parts List	Qty
- Test and replace right reverse light bulb .	Napagold Oil Filter	1.00
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill all.	10w30 Motor Oil	5.00
	Adhesive	1.00
- Replace both rear bump stops .	Mac Wite Lithium Gres	1.00
- Replace missing pintle hitch pin.	Wd40 Spr	1.00
- Reinstall rear view mirror to windshield .	22" Wiper Blade	2.00
- Complete front end alignment and road test.	Used Fire X Refurbished	1.00
- Shop Supplies	Boxed Miniatures	1.00
	183680418 P235-75r16	2.00
	Bump Stopers	2.00
	Pintle Pin W/clip	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.40	Labor: 562.80	Parts: 514.71
:		Total: 1,077.51

Workorder: 1905246 **Meter:** 41236 **In Date:** 05/15/2019 **Closed:** 05/29/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Charge battery fully . Test battery and charging system . R&r defective battery .	Napagold Oil Filter	1.00
- Test and replace leaking washer tank . Refill and retest .	10w30 Motor Oil	5.00
- Replace two tires . Rotate and balance all four tires . Nitrofill all.	Napagold Fuel Filter	1.00
- Test and replace right side reverse light bulb .	22" Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Battery	1.00
	Wiper Fluid Reservoir	1.00
	P235/75r16xl Hankook Dynapro	2.00
	Ptex Ultra Grey 3oz	1.00
	Boxed Miniatures	2.00
	Washer Container	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.80	Labor: 455.60	Parts: 658.18
:		Total: 1,113.78

Workorder: 1908892 **Meter:** 41980 **In Date:** 08/26/2019 **Closed:** 08/29/2019
Problem: Check for power steering leak .

- Diagnose power steering leak . Replace leaking power steering cooler and bleed power steering . Test drive.	Parts List	Qty
- Shop Supplies	Pawer Steering Fluid	1.00
	cooler	1.00
	Big G Degreaser 1 Gal	1.00
	Shop Supplies	1.00
Hours 1.50	Labor: 100.50	Parts: 113.19
:		Total: 213.69

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1912883 **Meter:** 42929 **In Date:** 12/17/2019 **Closed:** 01/03/2020
Problem: P.M. service.

- P.m. service.
- Replace front and rear brake rotors and pads . Service all calipers . Flush and bleed brake system . Road test .
- Test door ajar . Remove left front door panel to replace defective door latch assembly . Retest .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
10w30 Motor Oil	5.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
Brake Rotor Only	2.00
Brake Rotor	2.00
Brake Pads	1.00
Brake Pad Set	1.00
Door Lock	1.00
Shop Supplies	1.00

Hours 10.50 Labor: 766.50 Parts: 667.81 Total: 1,434.31
 :