

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10193012    2013 CET DIPFP20HPKHLRM Pump, 300 Gallon, Fire, Skid Mounted, Foam System**

**Workorder:** 1312777    **Meter:** 0    **In Date:** 12/26/2013    **Closed:** 12/26/2013  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00    Labor: 120.00    Parts: 0.00    Total: 120.00  
 :

**Workorder:** 1501799    **Meter:** 0    **In Date:** 02/19/2015    **Closed:** 02/19/2015  
**Problem:** wont start

- To ten-8 for pump warranty

Hours 0.00    Labor: 0.00    Parts: 0.00    Total: 0.00  
 :

**Workorder:** 1501800    **Meter:** 0    **In Date:** 02/19/2015    **Closed:** 02/26/2015  
**Problem:** pm service

	<b>Parts List</b>	<b>Qty</b>
- Pm		
- Ign Service	Oil Fil	1.00
- R/r carb to clean out and adjust	Napagold Fuel Filter	1.00
- Remount gauge on control panel	10w30 Motor Oil	2.00
- Shop Supplies	Spark Plug	2.00
	Shop Supplies	1.00

Hours 6.00    Labor: 360.00    Parts: 30.88    Total: 390.88  
 :

**Workorder:** 1507124    **Meter:** 0    **In Date:** 07/16/2015    **Closed:** 07/22/2015  
**Problem:** foam unit not working

	<b>Parts List</b>	<b>Qty</b>
- Fill tank and test ran x2 Foamer operating normally		
- Shop Supplies	Shop Supplies	1.00

Hours 1.00    Labor: 60.00    Parts: 2.00    Total: 62.00  
 :

**Workorder:** 1602798    **Meter:** 0    **In Date:** 03/17/2016    **Closed:** 04/22/2016  
**Problem:** pm service, foam amount knob broke

	<b>Parts List</b>	<b>Qty</b>
- Pm		
- Ign Service	Oil Fil	1.00
- Replace knob on foamer control	10w30 Motor Oil	2.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Air Filter	1.00
	Spark Plug	2.00
	Knob	2.00
	Shop Supplies	1.00
	Freight Charge	1.00

Hours 4.50    Labor: 270.00    Parts: 55.86    Total: 325.86  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1705437	<b>Meter:</b> 0	<b>In Date:</b> 05/31/2017	<b>Closed:</b> 06/07/2017
<b>Problem:</b> pm service			
- Pm		<b>Parts List</b>	<b>Qty</b>
- Ign Service		Oil Fil	1.00
- Shop Supplies		Napa 10w30 Qt	2.00
		Napagold Fuel Filter	1.00
		Air Filter	1.00
		Spark Plug	2.00
		Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 54.31	Total: 294.31
:			

---

<b>Workorder:</b> 1800830	<b>Meter:</b> 0	<b>In Date:</b> 01/23/2018	<b>Closed:</b> 02/21/2018
<b>Problem:</b> runs rough at high rpms and smoking			
- Test run pump unit 2x working normally		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

---

<b>Workorder:</b> 1803693	<b>Meter:</b> 0	<b>In Date:</b> 04/09/2018	<b>Closed:</b> 04/17/2018
<b>Problem:</b> pm service			
- pm service		<b>Parts List</b>	<b>Qty</b>
- ignition service		Oil Fil	1.00
- Shop Supplies		Napa 10w30 Qt	2.00
		Napagold Fuel Filter	1.00
		Spark Plug	2.00
		Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 35.02	Total: 275.02
:			

---

<b>Workorder:</b> 1906358	<b>Meter:</b> 0	<b>In Date:</b> 06/17/2019	<b>Closed:</b> 06/20/2019
<b>Problem:</b> pm service			
- Pm Service		<b>Parts List</b>	<b>Qty</b>
- Ignition service		Air Filter	1.00
- Shop Supplies		Oil Fil	1.00
		Napagold Fuel Filter	1.00
		Napa 10w30 Qt	2.00
		Spark Plug	2.00
		Shop Supplies	1.00
Hours 4.00	Labor: 268.00	Parts: 47.61	Total: 315.61
:			

---

<b>Workorder:</b> 2002905	<b>Meter:</b> 0	<b>In Date:</b> 03/23/2020	<b>Closed:</b> 03/23/2020
<b>Problem:</b> Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			