

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10198913    2015 FORD ESCAPE Suv, Mid Size, 4X4**

**Workorder:** 1511733    **Meter:** 346    **In Date:** 11/17/2015    **Closed:** 11/17/2015  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00                      Labor: 120.00              Parts: 0.00              Total: 120.00  
 :

**Workorder:** 1600684    **Meter:** 1848    **In Date:** 01/21/2016    **Closed:** 01/21/2016  
**Problem:** 12 - Wash ticket(s) issued

- 12 - Wash ticket(s) issued

Hours 0.00                      Labor: 0.00              Parts: 0.00              Total: 0.00  
 :

**Workorder:** 1603738    **Meter:** 6788    **In Date:** 04/08/2016    **Closed:** 04/20/2016  
**Problem:** P.M. service.

- P.m. Service.

- Rotate and balance all tires.

- Shop Supplies

| <b>Parts List</b>     | <b>Qty</b> |
|-----------------------|------------|
| 5w20 Engine Oil       | 5.00       |
| Napagold Oil Filter   | 1.00       |
| Washer Fluid Concentr | 1.00       |
| Accufit Beam          | 2.00       |
| Blade                 | 1.00       |
| Shop Supplies         | 1.00       |

Hours 3.75                      Labor: 225.00              Parts: 70.79              Total: 295.79  
 :

**Workorder:** 1605372    **Meter:** 8451    **In Date:** 05/24/2016    **Closed:** 05/24/2016  
**Problem:** 10 - Wash ticket(s) issued

- 10 - Wash ticket(s) issued

Hours 0.00                      Labor: 0.00              Parts: 0.00              Total: 0.00  
 :

**Workorder:** 1607272    **Meter:** 12837    **In Date:** 07/18/2016    **Closed:** 07/28/2016  
**Problem:** P.M. Seervice.

- P.m. Service.

- Rotate and balance all tires.

- Shop Supplies

| <b>Parts List</b>     | <b>Qty</b> |
|-----------------------|------------|
| Napagold Oil Filter   | 1.00       |
| 5w20 Engine Oil       | 5.00       |
| Accufit Beam          | 2.00       |
| Wpr/blde              | 1.00       |
| Washer Fluid Concentr | 1.00       |
| Shop Supplies         | 1.00       |

Hours 3.75                      Labor: 225.00              Parts: 59.69              Total: 284.69  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

|  |                       |                            |                           |
|--|-----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1610871  | <b>Meter:</b> 17757   | <b>In Date:</b> 10/21/2016 | <b>Closed:</b> 10/31/2016 |
| <b>Problem:</b> P.M. service.  |                       |                            |                           |
| - P.m. Service.  | <b>Parts List</b>     |                            | <b>Qty</b>                |
| - Rotate and balance all tires.  | 5w20 Engine Oil       |                            | 5.00                      |
| - Shop Supplies  | Napagold Oil Filter   |                            | 1.00                      |
|  | Accufit Beam          |                            | 2.00                      |
|  | Wpr/blde              |                            | 1.00                      |
|  | Washer Fluid Concentr |                            | 1.00                      |
|  | Shop Supplies         |                            | 1.00                      |
| Hours 3.75   | Labor: 225.00         | Parts: 59.96               | Total: 284.96             |
| :  |                       |                            |                           |
| <b>Workorder:</b> 1700930  | <b>Meter:</b> 23394   | <b>In Date:</b> 01/30/2017 | <b>Closed:</b> 02/13/2017 |
| <b>Problem:</b> P.M. service and recall 15C06  |                       |                            |                           |
| - P.m. Service.  | <b>Parts List</b>     |                            | <b>Qty</b>                |
| - Test battery and charging system.recharge and retest battery,fail load test.replace defective battery. | 5w20 Engine Oil       |                            | 5.00                      |
| - Rotate and balance tires.  | Napagold Oil Filter   |                            | 1.00                      |
| - Shop Supplies  | Blade                 |                            | 1.00                      |
|  | Wiper Blade           |                            | 1.00                      |
|  | Wiper Blade           |                            | 1.00                      |
|  | Battery               |                            | 1.00                      |
|  | Shop Supplies         |                            | 1.00                      |
| Hours 4.75   | Labor: 285.00         | Parts: 219.98              | Total: 504.98             |
| :  |                       |                            |                           |
| <b>Workorder:</b> 1703594  | <b>Meter:</b> 26358   | <b>In Date:</b> 04/10/2017 | <b>Closed:</b> 04/19/2017 |
| <b>Problem:</b> replace cracked windsheild   |                       |                            |                           |
| - Set up repairs, reasset  | <b>Parts List</b>     |                            | <b>Qty</b>                |
| - Shop Supplies  | Shop Supplies         |                            | 1.00                      |
| Hours 1.00   | Labor: 60.00          | Parts: 2.00                | Total: 62.00              |
| :  |                       |                            |                           |
| <b>Workorder:</b> 1703746  | <b>Meter:</b> 26358   | <b>In Date:</b> 04/12/2017 | <b>Closed:</b> 04/12/2017 |
| <b>Problem:</b> 6 - Wash ticket(s) issued  |                       |                            |                           |
| - 6 - Wash ticket(s) issued  |                       |                            |                           |
| Hours 0.00   | Labor: 0.00           | Parts: 0.00                | Total: 0.00               |
| :  |                       |                            |                           |
| <b>Workorder:</b> 1705141  | <b>Meter:</b> 29407   | <b>In Date:</b> 05/24/2017 | <b>Closed:</b> 05/31/2017 |
| <b>Problem:</b> P.M. service.  |                       |                            |                           |
| - P.m. service.  | <b>Parts List</b>     |                            | <b>Qty</b>                |
| - Balance and rotate all four tires.   | 5w20 Engine Oil       |                            | 5.00                      |
| - Shop Supplies  | Napagold Oil Filter   |                            | 1.00                      |
|  | Accufit Beam          |                            | 2.00                      |
|  | Wpr/blde              |                            | 1.00                      |
|  | White Lithium Grease  |                            | 1.00                      |
|  | Shop Supplies         |                            | 1.00                      |
| Hours 3.75   | Labor: 225.00         | Parts: 64.34               | Total: 289.34             |
| :  |                       |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1705817      **Meter:** 29812      **In Date:** 06/12/2017      **Closed:** 06/12/2017  
**Problem:** 3 - Wash ticket(s) issued

- 3 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
 :

**Workorder:** 1709270      **Meter:** 35502      **In Date:** 09/25/2017      **Closed:** 10/03/2017  
**Problem:** P.M. Service.Check wipers.Spot light does not rotate.

- P.m. Service.

- Replace two tires,rotate and balance all four.
- Replace left front signal light bulb and socket.
- Complete wheel alignment.test drive.
- Shop Supplies

**Parts List**

|                       | <b>Qty</b> |
|-----------------------|------------|
| 5w20 Engine Oil       | 5.00       |
| Napagold Oil Filter   | 1.00       |
| Washer Fluid Concentr | 1.00       |
| Wiper Blade           | 1.00       |
| Wiper Blade           | 1.00       |
| Blade                 | 1.00       |
| 235/55r17 Assurance   | 2.00       |
| Socket Asy            | 1.00       |
| Bulb                  | 1.00       |
| Lamp                  | 1.00       |
| Napa Cabin Air Filter | 1.00       |
| Shop Supplies         | 1.00       |
| Tire Disposal Fee     | 2.00       |

Hours 8.25      Labor: 495.00      Parts: 416.90      Total: 911.90  
 :

**Workorder:** 1801003      **Meter:** 41877      **In Date:** 01/26/2018      **Closed:** 01/26/2018  
**Problem:** 20 - Wash ticket(s) issued

- 20 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
 :

**Workorder:** 1804643      **Meter:** 45736      **In Date:** 05/03/2018      **Closed:** 05/09/2018  
**Problem:** P.M. service.

- P.m. service.

- Mount two new tires .rotate and balance all four tires.
- Shop Supplies

**Parts List**

|                     | <b>Qty</b> |
|---------------------|------------|
| Napagold Oil Filter | 1.00       |
| 5w20 Engine Oil     | 5.00       |
| Wiper Blade         | 1.00       |
| Wiper Blade         | 1.00       |
| Blade               | 1.00       |
| 235/55r17 Assurance | 2.00       |
| Shop Supplies       | 1.00       |
| Tire Disposal Fee   | 2.00       |

Hours 4.75      Labor: 285.00      Parts: 391.95      Total: 676.95  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1810713      **Meter:** 53285      **In Date:** 10/17/2018      **Closed:** 10/25/2018  
**Problem:** P.M. service.

|  |                        |               |
|--|------------------------|---------------|
| - P.m. service.  | <b>Parts List</b>      | <b>Qty</b>    |
| - Replace two tires . High speed balance and nitorgen fill all four tires. | Napagold Oil Filter    | 1.00          |
| - Replace both rear leaking rear shocks.                                   | 5w20 Engine Oil        | 5.00          |
| - Pressure test and inspect cooling system . Flush and refill coolant.     | Napa Air Filter        | 1.00          |
| - Complete front end alignment. Road test.                                 | Napa Cabin Air Filter  | 1.00          |
| - Shop Supplies  | Brk Fluid Dot 4-12oz   | 1.00          |
|  | Wiper Blade            | 1.00          |
|  | Blade                  | 1.00          |
|  | Wiper Blade            | 1.00          |
|  | Washer Fluid Concentr  | 1.00          |
|  | Tire235/55/17 Mic      | 2.00          |
|  | Shock Absober          | 2.00          |
|  | Anti Freeze Motorcraft | 1.00          |
|  | Shop Supplies          | 1.00          |
|  | Tire Disposal Fee      | 2.00          |
| Hours 10.35  | Labor: 693.45          | Parts: 712.45 |
| :  | Total: 1,405.90        |               |

**Workorder:** 1810959      **Meter:** 53126      **In Date:** 10/24/2018      **Closed:** 10/24/2018  
**Problem:** 10 - Wash ticket(s) issued

|                              |            |             |             |             |
|------------------------------|------------|-------------|-------------|-------------|
| - 10 - Wash ticket(s) issued | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
|                              | :          |             |             |             |

**Workorder:** 1812346      **Meter:** 55273      **In Date:** 12/04/2018      **Closed:** 12/05/2018  
**Problem:** Tire repair.

|  |                   |               |
|--|-------------------|---------------|
| - Replace left front tire and balance . Nitrogen fill all . Remount spare. | <b>Parts List</b> | <b>Qty</b>    |
| - Shop Supplies  | Tire235/55/17 Mic | 1.00          |
|  | Shop Supplies     | 1.00          |
|  | Tire Disposal Fee | 1.00          |
| Hours 0.50   | Labor: 33.50      | Parts: 193.46 |
| :  | Total: 226.96     |               |

**Workorder:** 1812398      **Meter:** 55273      **In Date:** 12/04/2018      **Closed:** 12/05/2018  
**Problem:** Tire Change

|  |            |             |             |             |
|--|------------|-------------|-------------|-------------|
| - Tire Service 3228 Gunclub Rd - Tire Change | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
|  | :          |             |             |             |

**Workorder:** 1900203      **Meter:** 56921      **In Date:** 01/04/2019      **Closed:** 01/07/2019  
**Problem:** TPMS on, screw in back passenger tire.

|   |                   |             |
|---|-------------------|-------------|
| - Repair right rear tire and balance . Nitrofill all. | <b>Parts List</b> | <b>Qty</b>  |
| - Shop Supplies                                       | Shop Supplies     | 1.00        |
| Hours 1.00  | Labor: 67.00      | Parts: 3.00 |
| :   | Total: 70.00      |             |

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

|  |                     |                            |                           |
|--|---------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1900840                                | <b>Meter:</b> 57902 | <b>In Date:</b> 01/23/2019 | <b>Closed:</b> 01/29/2019 |
| <b>Problem:</b> Key fob inop and need spare key .        |                     |                            |                           |
| - Order and program two spare remote key fobs . Retest . | <b>Parts List</b>   |                            | <b>Qty</b>                |
| - Shop Supplies  | Key Fab With Kiey   |                            | 2.00                      |
|  | Shop Supplies       |                            | 1.00                      |
| Hours 0.50   | Labor: 33.50        | Parts: 442.14              | Total: 475.64             |
| :  |                     |                            |                           |

---

|  |                       |                            |                           |
|--|-----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1901920  | <b>Meter:</b> 58766   | <b>In Date:</b> 02/20/2019 | <b>Closed:</b> 02/27/2019 |
| <b>Problem:</b> P.M. service and at times will not crank on first try .  |                       |                            |                           |
| - P.m. service.  | <b>Parts List</b>     |                            | <b>Qty</b>                |
| - Perform battery charge and load test . Battery failed load test . R&r defective battery .  | Napagold Oil Filter   |                            | 1.00                      |
|  | 5w20 Engine Oil       |                            | 5.00                      |
| - Inspect all brakes . Resurface rear brake rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test. | Wiper Blade           |                            | 1.00                      |
|  | Wiper Blade           |                            | 1.00                      |
| - Rotate and high speed balance all four wheels . Nitrofill all.   | Blade                 |                            | 1.00                      |
| - Shop Supplies  | Washer Fluid Concentr |                            | 1.00                      |
|  | Battery               |                            | 1.00                      |
|  | Brake Pad Real        |                            | 1.00                      |
|  | Non-chlor Brake Clnr  |                            | 1.00                      |
|  | Brk Fluid Dot 4-12oz  |                            | 1.00                      |
|  | Shop Supplies         |                            | 1.00                      |
| Hours 8.25   | Labor: 552.75         | Parts: 327.47              | Total: 880.22             |
| :  |                       |                            |                           |

---

|   |                       |                            |                           |
|---|-----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1904536   | <b>Meter:</b> 62277   | <b>In Date:</b> 04/26/2019 | <b>Closed:</b> 05/06/2019 |
| <b>Problem:</b> Water leak, Passenger side floor AC drain?  |                       |                            |                           |
| - Water leak test vehicle . Remove right front seat assembly to remove carpet to dry and replace damaged juke padding . Repair clogged evap drain . Retest . deodize floor board and replace cabin air filter . | <b>Parts List</b>     |                            | <b>Qty</b>                |
|   | Napa Cabin Air Filter |                            | 1.00                      |
|   | Frshner               |                            | 1.00                      |
| - Shop Supplies   | Shop Supplies         |                            | 1.00                      |
| Hours 3.50  | Labor: 234.50         | Parts: 18.53               | Total: 253.03             |
| :   |                       |                            |                           |

---

|  |                     |                            |                           |
|--|---------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1906593  | <b>Meter:</b> 65207 | <b>In Date:</b> 06/24/2019 | <b>Closed:</b> 07/02/2019 |
| <b>Problem:</b> P.M. service.  |                     |                            |                           |
| - P.m. service.  | <b>Parts List</b>   |                            | <b>Qty</b>                |
| - Replace two worn tires . Rotate and balance all four tires . Nitrofill all . | Napagold Oil Filter |                            | 1.00                      |
|  | 5w20 Engine Oil     |                            | 5.00                      |
| - Test and diagmose horns inop . R&r defective horn .                          | Blade               |                            | 1.00                      |
| - Shop Supplies  | Wiper Blade         |                            | 1.00                      |
|  | Wiper Blade         |                            | 1.00                      |
|  | Tire235/55/17 Mic   |                            | 2.00                      |
|  | Horn Assembly       |                            | 1.00                      |
|  | Shop Supplies       |                            | 1.00                      |
|  | Tire Disposal Fee   |                            | 2.00                      |
| Hours 5.75   | Labor: 385.25       | Parts: 468.57              | Total: 853.82             |
| :  |                     |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1906831      **Meter:** 65087      **In Date:** 06/28/2019      **Closed:** 06/28/2019  
**Problem:** 10 - Wash ticket(s) issued

- 10 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
 :

**Workorder:** 1910887      **Meter:** 71406      **In Date:** 10/22/2019      **Closed:** 10/29/2019  
**Problem:** P.M. service ,right rear tire going flat and power outlet inop .

- P.m. service.

**Parts List**

**Qty**

- Repair right rear tire . Rotate and balance all four tires . Nitrofill all..

Napagold Oil Filter

1.00

5w20 Engine Oil

5.00

- Diagnose power outlet inop . Repair damaged wires in center console . Retest .

Blade

1.00

Wiper Blade

1.00

- Shop Supplies

Wiper Blade

1.00

Shop Supplies

1.00

Hours 5.75      Labor: 419.75      Parts: 81.30      Total: 501.05  
 :

**Workorder:** 2001969      **Meter:** 79017      **In Date:** 02/26/2020      **Closed:** 02/27/2020  
**Problem:** P.M. service and light bar leaking water into headliner .

- P.m. service.

**Parts List**

**Qty**

- Water leak test roof . Remove light bar to reseal though wiring harness for light bar . Retest .

Napagold Oil Filter

1.00

5w20 Engine Oil

5.00

- Repair left rear tire . Rotate and balance all four tires . Nitrofill all.

Washer Fluid Concentr

1.00

Napa Cabin Air Filter

1.00

Wd40 Spr

1.00

Marine Adh Seal White

1.00

- Shop Supplies

Shop Supplies

1.00

Hours 5.75      Labor: 419.75      Parts: 57.40      Total: 477.15  
 :

**Workorder:** 2003145      **Meter:** 80231      **In Date:** 03/27/2020      **Closed:** 03/27/2020  
**Problem:** 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 2005950      **Meter:** 84974      **In Date:** 06/16/2020      **Closed:** 06/23/2020  
**Problem:** P.M. Service.TPMS light on.

|   |                       |               |
|---|-----------------------|---------------|
| - P.m. Service.   | <b>Parts List</b>     | <b>Qty</b>    |
| - Resurface front brake rotors.service and lube calipers,replace pads.flush and bleed system. | Napagold Oil Filter   | 1.00          |
| - Repair left rear tire,rotate and balance all four.  | 5w20 Engine Oil       | 5.00          |
| - Shop Supplies   | Blade                 | 1.00          |
|   | Wiper Blade           | 1.00          |
|   | Wiper Blade           | 1.00          |
|   | Washer Fluid Concentr | 1.00          |
|   | Non-chlor Brake Clnr  | 1.00          |
|   | Brk Fluid Dot 4-32oz  | 1.00          |
|   | Brake Pads            | 1.00          |
|   | Shop Supplies         | 1.00          |
| Hours 8.75  | Labor: 638.75         | Parts: 206.11 |
| :   |                       | Total: 844.86 |

**Workorder:** 2010489      **Meter:** 91544      **In Date:** 10/19/2020      **Closed:** 10/19/2020  
**Problem:** 1 - Wash ticket(s) issued

|                             |            |             |             |             |
|-----------------------------|------------|-------------|-------------|-------------|
| - 1 - Wash ticket(s) issued | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
|                             | :          |             |             |             |

**Workorder:** 2011122      **Meter:** 91695      **In Date:** 11/03/2020      **Closed:** 11/03/2020  
**Problem:** remove extra decals for surplus

|   |                   |               |
|---|-------------------|---------------|
| - Transition Charge/ Remove Medical Examiner Decals | <b>Parts List</b> | <b>Qty</b>    |
| - Shop Supplies                                     | Shop Supplies     | 1.00          |
| Hours 1.50  | Labor: 109.50     | Parts: 4.00   |
| :   |                   | Total: 113.50 |