

**Palm Beach County Fleet Management
Asset Maintenance History**

10192536 2013 FORD ESCAPE Suv, Mid Size, 4X4

Workorder: 1303716 **Meter:** 371 **In Date:** 04/16/2013 **Closed:** 04/16/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1304193 **Meter:** 376 **In Date:** 04/16/2013 **Closed:** 04/29/2013
Problem: damage to lft rear door

- damage to lft rear door

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1304777 **Meter:** 401 **In Date:** 05/13/2013 **Closed:** 05/23/2013
Problem: Install PA system to new vehicle

- Remove left headlamp assembly and bumper cover to access and install Pa system.fabricate mounting bracket and make up new wiring harness.

Parts List	Qty
Vinyl Electrical Tape	1.00
40 60 Ros Core Sld1	1.00
Shop Supplies	1.00

- Shop Supplies

Hours 3.50 Labor: 210.00 Parts: 36.82 Total: 246.82
:

Workorder: 1309600 **Meter:** 4030 **In Date:** 09/23/2013 **Closed:** 10/08/2013
Problem: Pm service.

- Perform pm service.

- Diagnose for oil leak under engine.inspect and replace failed/leaking engine oil cooler oring/gasket with new.degrease and clean oil resedue.

Parts List	Qty
5w20 Engine Oil	5.00
Napagold Oil Filter	1.00
Washer FI	1.00
Oil Cooler Gasket	1.00
Brake Cleaner	1.00
Shop Supplies	1.00

- Rotate and balance all four tires.

- Shop Supplies

Hours 4.75 Labor: 285.00 Parts: 30.47 Total: 315.47
:

Workorder: 1402551 **Meter:** 9186 **In Date:** 03/17/2014 **Closed:** 03/20/2014
Problem: Pm service.

- P.m. Service.

- Rotate and balance all tires.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	5.00
Napagold Oil Filter	1.00
Washer FI	1.00
Shop Supplies	1.00

Hours 3.75 Labor: 225.00 Parts: 20.50 Total: 245.50
:

Workorder: 1402926 **Meter:** 9186 **In Date:** 03/25/2014 **Closed:** 03/26/2014
Problem: Check Engine light on and "red" Oil pressure light flashing simultaneously...will have towed on am of 3/26/14

- Tow From: 800 Clematis Ave To: Lv Shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1402957	Meter: 10034	In Date: 03/26/2014	Closed: 04/30/2014
Problem: Check engine and oil light flashing.			
- Replace leaking oil filter and add oil.		Parts List	Qty
		Napagold Oil Filter	1.00
		5w20 Engine Oil	3.00
Hours 0.50	Labor: 30.00	Parts: 10.86	Total: 40.86
:			
Workorder: 1403419	Meter: 9186	In Date: 04/08/2014	Closed: 04/08/2014
Problem: 2 - Wash ticket(s) issued			
- 2 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1409428	Meter: 14198	In Date: 09/19/2014	Closed: 10/08/2014
Problem: Pm service.Safety recalls 13S12,14S03 and 14S04			
- Pm service.		Parts List	Qty
- Rotate and balance all four tires.		Napagold Oil Filter	1.00
- Transport vehicle to and from dealer for safety recalls#13s12,14s03,14s04 and 14s21.replace thermostat,dipstick,shield,reprogram restraints control module,inspect all outer door handle and adjust right rear.		5w20 Engine Oil	5.00
		Accufit Beam	2.00
		Mac Wite Lithium Gres	1.00
- Shop Supplies		Shop Supplies	1.00
Hours 5.75	Labor: 345.00	Parts: 54.82	Total: 399.82
:			
Workorder: 1503841	Meter: 18817	In Date: 04/14/2015	Closed: 04/28/2015
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Rotate and balance all four tires.		5w20 Engine Oil	5.00
- Shop Supplies		Napagold Oil Filter	1.00
		Accufit Beam	2.00
		Blade	1.00
		Napagold Air Filter	1.00
		Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 76.94	Total: 301.94
:			
Workorder: 1508051	Meter: 22687	In Date: 08/11/2015	Closed: 08/14/2015
Problem: Left rear damage.			
- Replace and balance left rear tire.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		P235/55r17 Tire	1.00
Hours 0.50	Labor: 30.00	Parts: 77.00	Total: 107.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1510769 **Meter:** 23704 **In Date:** 10/26/2015 **Closed:** 11/12/2015
Problem: Pm service.Remote inop.Recall.

- Pm service.	Parts List	Qty
- Computer diagnose remote inop.reprogram all remotes and retest.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	5w20 Engine Oil	5.00
- Transport vehicle to and from dealer for safety recall #14s21.	Accufit Beam	2.00
- Shop Supplies	Napa Cabin Air Filter	1.00
	Mac Wite Lithium Gres	1.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 7.25	Labor: 435.00	Parts: 69.37
:		Total: 504.37

Workorder: 1604867 **Meter:** 29133 **In Date:** 05/10/2016 **Closed:** 05/24/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Rotate and balance all tires.	Lug Nut	1.00
- Fabricate and replace front and rear asset#'s.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	5.00
	Air Filter	1.00
	Washer Fluid Concentr	1.00
	Accufit Beam	2.00
	Blade	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 285.00	Parts: 96.43
:		Total: 381.43

Workorder: 1605534 **Meter:** 29133 **In Date:** 05/27/2016 **Closed:** 05/27/2016
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1608475 **Meter:** 30671 **In Date:** 08/16/2016 **Closed:** 08/30/2016
Problem: ABS light on and traction light at times and left front seat collapsed and liftgate handle loose.

- Diagnose Abs/traction light.c0037.perform pin point test.replace defective rear speed sensor.clear codes.	Parts List	Qty
- Repair rear liftgate handle.check driver seat.unable to varify complain at this time.	Abs Sensor	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 18.71
:		Total: 198.71

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1613240 **Meter:** 34616 **In Date:** 12/30/2016 **Closed:** 01/12/2017
Problem: P.M. Service.

<ul style="list-style-type: none"> - P.m. Service. - Replace and balance four new tires. - Completre wheel alignment.test drive. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Napagold Oil Filter 5w20 Engine Oil Washer Fluid Concentr Accufit Beam Wpr/blde Napa Cabin Air Filter P235 55r17 Fuel Max Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 5.00 1.00 2.00 1.00 1.00 4.00 1.00 4.00 	
Hours 7.25 :	Labor: 435.00	Parts: 746.64	Total: 1,181.64

Workorder: 1708133 **Meter:** 39998 **In Date:** 08/17/2017 **Closed:** 08/30/2017
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. service. - Pressure test and inspect cooling system .flush with new anti-freeze. - Test battey and charging system,battery low charge.recharge battery fully and retest.fail load test.replace defective battery. - Rotate and high speed balance all four tires. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> 5w20 Engine Oil Napagold Oil Filter Wd40 Spr Washer Fluid Concentr Wiper Blade Wiper Blade Blade Anti Freeze Motorcraft Battery Battery Terminal Protectors Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 	
Hours 6.75 :	Labor: 405.00	Parts: 289.03	Total: 694.03

Workorder: 1710519 **Meter:** 41712 **In Date:** 10/25/2017 **Closed:** 10/31/2017
Problem: Abs light and traction control lights on.

<ul style="list-style-type: none"> - Computer diagnoise Abs light code C003a .perform pinpoint test.r&r defective right rear Abs wheel speed sensor.retest and clear code. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Sensor Asy Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 	
Hours 1.40 :	Labor: 84.00	Parts: 18.70	Total: 102.70

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1802493 **Meter:** 45259 **In Date:** 03/06/2018 **Closed:** 03/12/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Rotate and high speed balance all four tires.	5w20 Engine Oil	5.00
- Shop Supplies	Napagold Oil Filter	1.00
	Wiper Blade	1.00
	Wiper Blade	1.00
	Blade	1.00
	Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 72.13
:		Total: 297.13

Workorder: 1809603 **Meter:** 49407 **In Date:** 09/18/2018 **Closed:** 09/28/2018
Problem: PM Service

- P.m. service.	Parts List	Qty
- Rotate and high speed balance all four wheels . Nitrofill all.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	5.00
	Wiper Blade	1.00
	Wiper Blade	1.00
	Blade	1.00
	Mac Wite Lithium Gres	1.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 80.99
:		Total: 305.99

Workorder: 1904709 **Meter:** 53676 **In Date:** 04/30/2019 **Closed:** 05/09/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Resurface rear brake rotors and service calipers . Replace rear brake pads , flush and bleed brake system . Road test .	5w20 Engine Oil	5.00
- Rotate and balance all four tires . Nitrofill all and reset Tpms.	Napagold Oil Filter	1.00
- Shop Supplies	Blade	1.00
	Wiper Blade	1.00
	Wiper Blade	1.00
	Non-chlor Brake Clnr	1.00
	Brk Fluid Dot 4-12oz	1.00
	Rear Brake Pad	1.00
	Shop Supplies	1.00
Hours 7.25	Labor: 485.75	Parts: 149.12
:		Total: 634.87

Workorder: 1906339 **Meter:** 54394 **In Date:** 06/17/2019 **Closed:** 07/02/2019
Problem: Left rear door will not latch close Recall 16S30.

- Computer diagnose check engine light ,code P26b7 . Perform pinpoint test . R&r defective coolant bypass valve C . Flush cooling system and refill . Clear codes and retest .	Parts List	Qty
- Transport to and from dealer for recall 16s30 door latches .	Anti Freeze Motorcraft	1.00
- Shop Supplies	Valve Assy	1.00
	Shop Supplies	1.00
Hours 4.80	Labor: 321.60	Parts: 93.68
:		Total: 415.28

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1912251 **Meter:** 57640 **In Date:** 11/27/2019 **Closed:** 12/10/2019
Problem: PM Service, ABS light on and car hesitates for a few seconds before driving.

<ul style="list-style-type: none"> - P.m. service. - Replace cabin air filter and clean fresh air intake . - Computer diagnose Abs light , code C0037 . Perform pinpoint test . R&r defective left rear wheel speed sensor . Clear code and retest . - Diagnose oil leak . Remove intake and cowl panel to replace leaking valve cover gasket and rear cover . Replace fuel line . Hook up Ids to retrain wiper motor . Clean excess oil. Retest . - Rotate and balance all four tires . Nitrofill all. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">5.00</td></tr> <tr><td>Washer Fluid Concentr</td><td></td><td align="right">1.00</td></tr> <tr><td>Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">1.00</td></tr> <tr><td>Napa Cabin Air Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Non-chlor Brake Clnr</td><td></td><td align="right">2.00</td></tr> <tr><td>Sensor Asy</td><td></td><td align="right">1.00</td></tr> <tr><td>Tube Asy</td><td></td><td align="right">1.00</td></tr> <tr><td>Sealant</td><td></td><td align="right">1.00</td></tr> <tr><td>Kit O Ring</td><td></td><td align="right">1.00</td></tr> <tr><td>Valve Cover Gasket</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Napagold Oil Filter		1.00	5w20 Engine Oil		5.00	Washer Fluid Concentr		1.00	Blade		1.00	Wiper Blade		1.00	Wiper Blade		1.00	Napa Cabin Air Filter		1.00	Non-chlor Brake Clnr		2.00	Sensor Asy		1.00	Tube Asy		1.00	Sealant		1.00	Kit O Ring		1.00	Valve Cover Gasket		1.00	Shop Supplies		1.00	<p align="right">Hours 10.75 Labor: 784.75 Parts: 445.86 Total: 1,230.61</p>
Parts List		Qty																																													
Napagold Oil Filter		1.00																																													
5w20 Engine Oil		5.00																																													
Washer Fluid Concentr		1.00																																													
Blade		1.00																																													
Wiper Blade		1.00																																													
Wiper Blade		1.00																																													
Napa Cabin Air Filter		1.00																																													
Non-chlor Brake Clnr		2.00																																													
Sensor Asy		1.00																																													
Tube Asy		1.00																																													
Sealant		1.00																																													
Kit O Ring		1.00																																													
Valve Cover Gasket		1.00																																													
Shop Supplies		1.00																																													

Workorder: 2002498 **Meter:** 59444 **In Date:** 03/11/2020 **Closed:** 03/19/2020
Problem: Towed in for check engine light and oil light on .

<ul style="list-style-type: none"> - Computer diagnose check engine light , P0012. Inspect for oil leak . Replace defective oil filter and clean undercarrage . Refill oil and inspect for leaks . Clear codes and road test . - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>5w20 Engine Oil</td><td></td><td align="right">5.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Big G Degreaser 1 Gal</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	5w20 Engine Oil		5.00	Napagold Oil Filter		1.00	Big G Degreaser 1 Gal		1.00	Shop Supplies		1.00	<p align="right">Hours 2.00 Labor: 146.00 Parts: 28.11 Total: 174.11</p>
Parts List		Qty															
5w20 Engine Oil		5.00															
Napagold Oil Filter		1.00															
Big G Degreaser 1 Gal		1.00															
Shop Supplies		1.00															

Workorder: 2002574 **Meter:** 59355 **In Date:** 03/11/2020 **Closed:** 03/13/2020
Problem: Eng Light and Oil Light on

<ul style="list-style-type: none"> - Tow From: 6401 W.indiantown Rd To: Lv shop 	<p align="right">Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00</p>
--	--

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2008533 **Meter:** 62957 **In Date:** 08/26/2020 **Closed:** 09/09/2020
Problem: PM Service, Low tire light, Brake light bulb out. Recall 20S30

	Parts List	Qty
- P.m. service.		
- Perform tune up . Replace all four spark plugs .	5w20 Engine Oil	5.00
- Perform complete air intake decarb and cleaning . Flush injectors .	Napagold Oil Filter	1.00
	Washer Fluid Concentr	1.00
- Inspect and service transmission . Drain and refill transmission fluid .	Blade	1.00
	Wiper Blade	1.00
- Test and replace both rear brake light bulbs and retest .	Wiper Blade	1.00
- R&r peeling seperating shifter assmbly .	Sprak Plug	4.00
- Rotate and balance all four tires . Nitrofill all and reset Tpms .	Intake Cleaner Kit	1.00
	Motor Tune-up 16oz	1.00
- During vehicle inspection , Battery had low charge . Charge battery fully and retest .	oil auto	9.00
	Boxed Miniatures	2.00
- Computer diagnose Abs light , Code C003a . Perform pinpoint test . R&r right rear wheel speed sensor . Clear code and retest .	Gear Shift Lever	1.00
	Abs Wheel Sensor Rear	1.00
- Perform latch inpection per Recall 20s30 . Left front 240817 ,left rear 220817 , right front 250817 , right rear 210817 . Enter on ford site all ok .	Shop Supplies	1.00
- Shop Supplies		

Hours 14.85 Labor: 1,084.0 Parts: 498.16 Total: 1,582.21
: 5

Workorder: 2011901 **Meter:** 63538 **In Date:** 12/01/2020 **Closed:** 12/01/2020
Problem: Transition Prep Charge

- Transition Prep Charge		
	Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00	
	:	