

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10195237      2014 FORD E250 Van, 3/4 Ton, Cargo**

**Workorder:** 1407284      **Meter:** 325      **In Date:** 07/24/2014      **Closed:** 07/24/2014  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00  
:

**Workorder:** 1408205      **Meter:** 358      **In Date:** 08/19/2014      **Closed:** 08/28/2014  
**Problem:** Install inverter and hitch to new vehicle that was remove from asset #10161679

- Install inverter.100 amp circuit breaker.fabricate power and ground cables.install hitch.install new trailer socket and bracket.fabricate trailer harness wires to socket.

- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Cb185-100 Cir Brkr	1.00
Bat/cabl	9.00
Cs2l Black Cable 2 Ga	2.00
Battery Cable Lug	4.00
5402 Socket Bracket	1.00
Female Conn Socket	1.00
Vinyl Electrical Tape	1.00
Shop Supplies	1.00

Hours 6.00      Labor: 360.00      Parts: 113.54      Total: 473.54  
:

**Workorder:** 1411867      **Meter:** 4936      **In Date:** 11/24/2014      **Closed:** 12/10/2014  
**Problem:** Pm service.

- Pm service.

- Rotate and balance all four tires.

- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Floor Mat-2pc Rub Bk	1.00
Shop Supplies	1.00

Hours 5.00      Labor: 300.00      Parts: 51.47      Total: 351.47  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1503390      **Meter:** 10893      **In Date:** 04/01/2015      **Closed:** 05/07/2015  
**Problem:** P.M. Service.Inverter breaker turns off.

- Pm service.
- Test circuit breaker and inverter.repair short circuit and install protective loom from circuit breaker to inverter and secure cables.retest and also test trailer connector ok.
- Rotate and balance all four tires.
- Fabricate and install trailer 12 volts accessories and electrical brake harness and controller.test on trailer.
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Brake Control	1.00
Trailer Controler	1.00
Relay	1.00
Connectr	1.00
Fuse Holder	1.00
Fab Loom-split Poly	16.00
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Wiper Blade	2.00
Trailer Conn Socket	1.00
Fuse	1.00
Shop Supplies	1.00

Hours 11.00      Labor: 660.00      Parts: 215.12      Total: 875.12  
 :

**Workorder:** 1503964      **Meter:** 9492      **In Date:** 04/06/2015      **Closed:** 04/17/2015  
**Problem:** damage to rgt rear fender

- damage to rgt rear fender

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
 :

**Workorder:** 1507935      **Meter:** 15080      **In Date:** 08/07/2015      **Closed:** 08/25/2015  
**Problem:** P.M. Service.

- Pm service.
- Replace right front camber/caster sleeve.complete front end alignment.
- Rotate and balance all four tires.
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Caster-camber Bushing	1.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
5w20 Engine Oil	7.00
Shop Supplies	1.00

Hours 8.00      Labor: 480.00      Parts: 65.27      Total: 545.27  
 :

**Workorder:** 1509834      **Meter:** 16881      **In Date:** 09/29/2015      **Closed:** 09/30/2015  
**Problem:** Left rear tire flat.

- Repair and balance left rear tire.
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00

Hours 1.00      Labor: 60.00      Parts: 2.00      Total: 62.00  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1511258	<b>Meter:</b> 19568	<b>In Date:</b> 11/03/2015	<b>Closed:</b> 11/12/2015
<b>Problem:</b> Pm service			
- Pm service.		<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all four tires.		Napagold Oil Filter	1.00
- Shop Supplies		5w20 Engine Oil	7.00
		Washer Fluid Concentr	1.00
		Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 25.51	Total: 325.51
:			
<b>Workorder:</b> 1601252	<b>Meter:</b> 23562	<b>In Date:</b> 02/04/2016	<b>Closed:</b> 02/11/2016
<b>Problem:</b> Left front tire flat.			
- Repair and balance left front tire.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1601916	<b>Meter:</b> 25553	<b>In Date:</b> 02/24/2016	<b>Closed:</b> 03/24/2016
<b>Problem:</b> Pm service.			
- Pm service.		<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all four tires.		5w20 Engine Oil	7.00
- Transport vehicle to and from dealer for replacing noisy steering shaft		Napagold Oil Filter	1.00
- Shop Supplies		22" Wiper Blade	2.00
		Washer Fluid Concentr	1.00
		Used Fire X Refurbished	1.00
		Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 45.32	Total: 465.32
:			
<b>Workorder:</b> 1604064	<b>Meter:</b> 27328	<b>In Date:</b> 04/18/2016	<b>Closed:</b> 04/22/2016
<b>Problem:</b> Nail in right rear tire.			
- Repair and balance right rear tire.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1605799	<b>Meter:</b> 29928	<b>In Date:</b> 06/06/2016	<b>Closed:</b> 06/22/2016
<b>Problem:</b> P.M. service.			
- P.m. Service.		<b>Parts List</b>	<b>Qty</b>
- Rotate and balance tires.		Napagold Oil Filter	1.00
- Diagnose check engine light.p0304,p0316.perform pinpoint test.replace defectiv e #4 coil.clear codes and test drive.		5w20 Engine Oil	7.00
- Shop Supplies		22" Wiper Blade	2.00
		Washer Fluid Concentr	1.00
		Napagold Air Filter	1.00
		Ford Ignition Coil	1.00
		Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 106.88	Total: 586.88
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1609909      **Meter:** 34994      **In Date:** 09/22/2016      **Closed:** 09/28/2016  
**Problem:** P.M. service.

- P.m/. Service.	<b>Parts List</b>	<b>Qty</b>
- Replace and balance four new tires.	5w20 Engine Oil	7.00
- Complete wheel alignment.test drive.	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	744395900 245-75r16	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.50	Labor: 510.00	Parts: 835.59
:		Total: 1,345.59

**Workorder:** 1611866      **Meter:** 38686      **In Date:** 11/17/2016      **Closed:** 11/29/2016  
**Problem:** Tire pressure light on and rattle noise left front .

- Test drive for noise.replace missing brake pad rattle shim.	<b>Parts List</b>	<b>Qty</b>
- Replace defective left front Tpms and reprogram.	Clip	2.00
- Shop Supplies	Tire Pressure Monitoring System Sensor (	1.00
	Ceramic Brake Lube	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 58.31
:		Total: 178.31

**Workorder:** 1612743      **Meter:** 40729      **In Date:** 12/13/2016      **Closed:** 01/02/2017  
**Problem:** P.M. service and pulls to right at highway speeds.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all tires.	Napagold Oil Filter	1.00
- Complete wheel alignment.test drive.	5w20 Engine Oil	7.00
- Shop Supplies	20" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 28.87
:		Total: 478.87

**Workorder:** 1702585      **Meter:** 45042      **In Date:** 03/14/2017      **Closed:** 03/28/2017  
**Problem:** P.M. service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Pressure test and inspect cooling system.flush and refill system.	Napagold Oil Filter	1.00
	5w20 Engine Oil	6.00
- Rotate and tires.	22" Wiper Blade	2.00
- Shop Supplies	Coolant Ford Gold	2.00
	Drain Plug	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 69.38
:		Total: 489.38

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1703723      **Meter:** 46441      **In Date:** 04/12/2017      **Closed:** 04/18/2017  
**Problem:** Right side wiper blade came apart.

- Replace broken right wiper blade.	<b>Parts List</b>	<b>Qty</b>
	22" Wiper Blade	1.00
Hours 0.25	Labor: 15.00	Parts: 3.39
:		Total: 18.39

**Workorder:** 1706082      **Meter:** 50139      **In Date:** 06/20/2017      **Closed:** 06/30/2017  
**Problem:** P.M. Service.Check a/c operation.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Diagnose a/c system blowing through defrost at time.replace vacuum reservoir and check valve.replace broken dash outlet.	5w20 Engine Oil	6.00
- Resurface rear brake rotors,replace brake pads.service and lube calipers.flush and bleed system.	Napagold Oil Filter	1.00
- Flush and refill transmission.	Used Fire X Refurbished	1.00
- Rotate and balance tires.	Vacuum Reservoir	1.00
- Shop Supplies	A/c Valve	1.00
	Brf1439 Brake Pads	1.00
	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	1.00
	Syn-atf Trans Fluid S	14.00
	A/c Louvre Asy	1.00
	Shop Supplies	1.00
Hours 14.50	Labor: 870.00	Parts: 307.03
:		Total: 1,177.03

**Workorder:** 1709045      **Meter:** 54842      **In Date:** 09/20/2017      **Closed:** 09/27/2017  
**Problem:** P.M. service and brakes pull to the right.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Resurface front rotors and brake caliper assemblies and new pads.flush and bleed brake system.	5w20 Engine Oil	6.00
- Replace all four tires.nitrogen fill and high speed balance all four tires.	Napagold Oil Filter	1.00
- Check starting and charging system.battery failed load test.replace with new battery.	22" Wiper Blade	2.00
- Perform front end alignment.	Used Fire X Refurbished	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	2.00
	Lt245/75/16 Tire Mic	4.00
	Battery 65	1.00
	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	Front Brake Pad	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 14.00	Labor: 840.00	Parts: 1,356.82
:		Total: 2,196.82

**Workorder:** 1712796      **Meter:** 59497      **In Date:** 12/29/2017      **Closed:** 01/04/2018  
**Problem:** Right side wiper blade came apart.

- Replace right side wiper blade and retest.	<b>Parts List</b>	<b>Qty</b>
	22" Wiper Blade	1.00
Hours 0.20	Labor: 12.00	Parts: 3.39
:		Total: 15.39

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1800357      **Meter:** 59835      **In Date:** 01/10/2018      **Closed:** 01/19/2018  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service rear differential.	5w20 Engine Oil	6.00
- Rotate and high speed balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	1qt Syngear Oil 75-90	3.00
	Friction Modifier	2.00
	Napagold Air Filter	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 97.87
:		Total: 457.87

**Workorder:** 1801372      **Meter:** 60899      **In Date:** 02/05/2018      **Closed:** 02/21/2018  
**Problem:** Check transmission ,shifting and 45 mph in and out.

- Transport to and from dealer for transmission repair.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

**Workorder:** 1804830      **Meter:** 64885      **In Date:** 05/09/2018      **Closed:** 05/17/2018  
**Problem:** P.M. service and noise on turns when hot.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Road test for noise on turns when hot .add four ounces of friction modifier to rear end .test drive.	5w20 Engine Oil	6.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Friction Modifier	1.00
	Drain Plug	1.00
	Napa Quart 5w20	6.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 61.85
:		Total: 421.85

**Workorder:** 1808865      **Meter:** 69901      **In Date:** 08/28/2018      **Closed:** 09/06/2018  
**Problem:** P.M. Service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance all four tires. Nitrogen fill tires.	Napagold Oil Filter	1.00
- Repair left front tire and replace leaking valve stem .	5w20 Engine Oil	6.00
Balance and nitrofill .	Used Fire X Refurbished	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Tire Pressure Monitoring System Sensor (	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 42.56
:		Total: 402.56

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1812432      **Meter:** 74343      **In Date:** 12/06/2018      **Closed:** 12/13/2018  
**Problem:** P.M. service , cracked windshield and inverter inop.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Check and inspect inverter operation . Operated invert with load for 15 minutes . Could not duplicate at this time. Repair cut bck up alarm wire and retest operation.	Napa Quart 5w20	6.00
- Rotate and balance all four tires. Nitrofill all and reset Tpm.	Napagold Oil Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00
Hours 5.80	Labor: 388.60	Parts: 39.87
:		Total: 428.47

**Workorder:** 1812633      **Meter:** 74145      **In Date:** 12/12/2018      **Closed:** 12/18/2018  
**Problem:** repair chipped windsheild

- set up repairs & inspect	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

**Workorder:** 1903354      **Meter:** 79698      **In Date:** 03/27/2019      **Closed:** 04/10/2019  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Replace two tires . Rotate and balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00
- Inspect all brakes . Replace rear brake rotors, calipers, and brake pads . Flush and bleed brake system . Road test .	5w20 Engine Oil	6.00
- Perform tune up . Replace all eight spark plugs .	Napagold Air Filter	1.00
- Perform fresh air decarb cleaning and flush injectors .	Used Fire X Refurbished	1.00
- Perform complete front end alignment and road test .	22" Wiper Blade	2.00
- Shop Supplies	Lt245/75/16 Tire Mic	2.00
	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	1.00
	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	Brake Pads	1.00
	Brake Rotor	2.00
	spark plug	8.00
	Intake Cleaner Kit	1.00
	Injector Cleaner	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 17.60	Labor: 1,179.2	Parts: 1,211.89
:	0	Total: 2,391.09

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1906872	<b>Meter:</b> 84430	<b>In Date:</b> 07/01/2019	<b>Closed:</b> 07/16/2019
<b>Problem:</b> P.M. service and inverter inop at times .			
- P.m. service.		<b>Parts List</b>	<b>Qty</b>
- Test and inspect power inverter . Replace defective circuit breaker and retest .		Napagold Oil Filter	1.00
		5w20 Engine Oil	7.00
- Replace two tires . Rotate and balance all four tires . Nitrofill all		22" Wiper Blade	2.00
		Washer Fluid Concentr	1.00
- Shop Supplies		Cb187f Marine-fuse	1.00
		Lt245/75/16 Tire Mic	2.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 6.80	Labor: 455.60	Parts: 598.11	Total: 1,053.71
:			

---

<b>Workorder:</b> 1910648	<b>Meter:</b> 90222	<b>In Date:</b> 10/16/2019	<b>Closed:</b> 10/29/2019
<b>Problem:</b> P.M. service.			
- P.m. service.		<b>Parts List</b>	<b>Qty</b>
- Balance and rotate all four tires . Nitrofill all.		Napagold Oil Filter	1.00
- Shop Supplies		5w20 Engine Oil	6.00
		22" Wiper Blade	2.00
		Used Fire X Refurbished	1.00
		Shop Supplies	1.00
Hours 5.00	Labor: 365.00	Parts: 53.58	Total: 418.58
:			

---

<b>Workorder:</b> 1911274	<b>Meter:</b> 90417	<b>In Date:</b> 10/30/2019	<b>Closed:</b> 10/31/2019
<b>Problem:</b> Left brake light inop.			
- Test and replace left brake light bulb .		<b>Parts List</b>	<b>Qty</b>
		Boxed Miniatures	2.00
Hours 0.50	Labor: 36.50	Parts: 1.53	Total: 38.03
:			

---

<b>Workorder:</b> 2001604	<b>Meter:</b> 94637	<b>In Date:</b> 02/14/2020	<b>Closed:</b>
<b>Problem:</b> Remove inverter and install in 10201491.			
-			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 2001931	<b>Meter:</b> 94637	<b>In Date:</b> 02/25/2020	<b>Closed:</b> 02/25/2020
<b>Problem:</b> Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			