

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 638078                      **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 04/26/2006	Hours	Description	Quantity
- Pre-Delivery Inspection	<b>2.00</b>		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	100.00

**Workorder:** 640851                      **Problem:** DRIVERS DOOR MIRROR BROKEN

Meter Reading: 549	Labor	Parts	
In Date: 06/14/2006	Hours	Description	Quantity
- R&R Driver'S Door View Mirror.	<b>0.50</b>	88944454 DRIVER DOOR MIRROR GLASS	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	74.05	<b>Labor Charge:</b>	25.00

**Workorder:** 648975                      **Problem:** P.M. SERVICE.

Meter Reading: 2440	Labor	Parts	
In Date: 11/21/2006	Hours	Description	Quantity
- Pm Service	<b>5.00</b>	10W30 MOTOR OIL	7.00
- Nitrogen Fill All Tires.		PH3506 OIL FILTER WIX 51042	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	21.88	<b>Labor Charge:</b>	55.00

**Workorder:** 733803                      **Problem:** REAR INSIDE DOOR LATCH COME APART

Meter Reading: 3290	Labor	Parts	
In Date: 02/05/2007	Hours	Description	Quantity
- Install Missing Bolts To Rear Door Handle.	<b>0.30</b>		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	16.50

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 739078

**Problem:** P.M. SERVICE.

<b>Meter Reading:</b> 4767	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/24/2007	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm Service	<b>5.50</b>	PH3506 OIL FILTER WIX 51042	1.00
- Replace Broken Front Right Seat Tilt Lever.		10W30 MOTOR OIL	7.00
- R&R Wiper Arms & Cowling Remove Screws To Pivot Arm		10020 INJECTOR CLEANER DON'T REORDER	1.00
Apply Thread Locker And Reinstall.Complete Complaint		SHOP SUPPLIES	1.00
#06140		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies		88981429 R/FRONT SEAT TILT HANDLE	1.00
<b>Parts Charge:</b>	44.72	<b>Labor Charge:</b>	55.00

**Workorder:** 742549

**Problem:** NAIL IN REAR TIRE

<b>Meter Reading:</b> 5584	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/03/2007	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Repair Right Rear Tire.	<b>1.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	55.00

**Workorder:** 748861

**Problem:** P.M SERVICE

<b>Meter Reading:</b> 7940	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 12/19/2007	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm Service	<b>5.00</b>	10W30 MOTOR OIL	7.00
- Highspeed Balance 4 Tires		6573 AIR FILTER FRM CA9269 WIX 46573	1.00
- Shop Supplies		PH3506 OIL FILTER WIX 51042	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		10020 INJECTOR CLEANER DON'T REORDER	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	56.83	<b>Labor Charge:</b>	60.00

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 834635                      **Problem:** MOLDING ON D/S DOOR COME OFF

Meter Reading: 8867	Labor	Parts	
In Date: 02/26/2008	Hours	Description	
Close Date: 02/27/2008		Quantity	
- Replace Molding On D/S Door	0.50	SHOP SUPPLIES	1.00
- Shop Supplies		DRIVER SIDE WEATHER STRIP	1.00
<b>Parts Charge:</b> 25.33		<b>Labor Charge:</b> 30.00	

**Workorder:** 839285                      **Problem:** P.M. SERVICE.

Meter Reading: 10374	Labor	Parts	
In Date: 06/02/2008	Hours	Description	
Close Date: 06/06/2008		Quantity	
- Pm Service	5.50	DRIVER SIDE VISOR	1.00
- D/S Sunvisor Keeps Dropping Down.Replace Defective D/S Sunvisor.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		PH3506 OIL FILTER WIX 51042	1.00
- Rotate & Hi Speed Balance 4 Tires, Nitro Fill Tires.		10W30 MOTOR OIL	7.00
- Shop Supplies		6573 AIR FILTER FRM CA9269 WIX 46573	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b> 182.20		<b>Labor Charge:</b> 60.00	

**Workorder:** 845189                      **Problem:** RIGHT REAR TIRE FLAT,TOWED IN.

Meter Reading: 11945	Labor	Parts	
In Date: 10/06/2008	Hours	Description	
Close Date: 10/09/2008		Quantity	
- Repair Right Rear Tire,Nitrogen Fill & Highspeed Balance.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

**Workorder:** 845234                      **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	
In Date: 10/03/2008	Hours	Description	
Close Date: 10/06/2008		Quantity	
-			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 845268

**Problem:** SISTERS TOWING & TRANSPORTATON TOW FROM 505 5TH ST

Meter Reading: 0	Labor	Parts			
In Date: 10/03/2008	Hours	Description	Quantity		
- Sisters Towing & Transportaton Tow From 505 5Th Street					
- Tow To					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	78.00

**Workorder:** 847627

**Problem:** P.M. SERVICE.SEE NOTE.

Meter Reading: 12773	Labor	Parts	
In Date: 12/02/2008	Hours	Description	Quantity
- Pm Service			
	6.00	10W30 MOTOR OIL	6.00
- Batt Failed Load Test.Ck Elec Sys.Charg Rate At			
		31-20 WIPER BLADES 20" BLADE	2.00
Spec.No Excessive Draw.Replace Battery.			
		GROUP 78 BATTERY (ACD 78PS)	1.00
- Rotate And Hi Speed Balance 4 Tires. Fill W/Nitrogen			
		SHOP SUPPLIES	1.00
- Shop Supplies			
		PH3506 OIL FILTER WIX 51042	1.00
<b>Parts Charge:</b>	141.00	<b>Labor Charge:</b>	60.00

**Workorder:** 847950

**Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts			
In Date: 10/24/2008	Hours	Description	Quantity		
- Tiresoles Of Broward Inc					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	60.00

**Workorder:** 938505

**Problem:** REPAIR SIDE CARGO DOOR,WON'T OPEN.

Meter Reading: 15090	Labor	Parts	
In Date: 06/02/2009	Hours	Description	Quantity
- Replace Broken Latch Retainer Clip			
	0.50	CARGO DOOR LATCH CLIP	1.00
<b>Parts Charge:</b>	2.93	<b>Labor Charge:</b>	30.00

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 940544

**Problem:** P.M. Service.

<b>Meter Reading:</b> 15573		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/09/2009	<b>Close Date:</b> 07/16/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- P.M Service		<b>8.50</b>	10W30 MOTOR OIL		6.00
- Mount, Balance & Nitro Fill Four New Tires.			TIRE DISPOSAL FEE		4.00
- Alignment			SHOP SUPPLIES		1.00
- Shop Supplies			179747492 LT245/75R16 WRANGLER SR-A E		4.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			PH3506 OIL FILTER WIX 51042		1.00
			TR416 VALVE STEM		4.00
<b>Parts Charge:</b> 676.36		<b>Labor Charge:</b> 510.00			

**Workorder:** 1000476

**Problem:** P.M service

<b>Meter Reading:</b> 18398		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 01/12/2010	<b>Close Date:</b> 01/22/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- P.M Service.		<b>5.00</b>	SHOP SUPPLIES		1.00
- Rotate & Balance All Four Tires.			31-20 WIPER BLADES 20" BLADE		2.00
- Shop Supplies			PH3506 OIL FILTER WIX 51042		1.00
			10W30 MOTOR OIL		6.00
			6573 AIR FILTER FRM CA9269 WIX 46573		1.00
<b>Parts Charge:</b> 39.93		<b>Labor Charge:</b> 300.00			

**Workorder:** 1007569

**Problem:** P.M. Service.

<b>Meter Reading:</b> 21149		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/19/2010	<b>Close Date:</b> 07/29/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Perform Pm Service.		<b>6.50</b>	PH3506 OIL FILTER WIX 51042		1.00
- Replace Failed Driver Side Sun Visor And Clip With New.			10W30 MOTOR OIL		6.00
- Test And Replace Both Failed Third Brake Lamp Bulbs			09997 BRAKE CLEAN		1.00
With New.			SHOP SUPPLIES		1.00
- Rotate And Balance All Four Tires.			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Shop Supplies			VISOR CLIP		1.00
			DRIVER SIDE SUNVISOR		1.00
<b>Parts Charge:</b> 183.50		<b>Labor Charge:</b> 390.00			

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1011157

**Problem:** Oil warning light flashing on cluster.

Meter Reading: 22086		Labor		Parts	
In Date: 10/08/2010	Close Date: 10/15/2010	Hours	Description		Quantity
-	Computer Diagnose Engine Light On.Test Evapt.System	2.50	GT335 FUEL CAP (ACD)		1.00
	And Replace Failed Gas Cap With New.		SHOP SUPPLIES		1.00
-	Shop Supplies				
<b>Parts Charge:</b> 20.60		<b>Labor Charge:</b> 150.00			

**Workorder:** 1013948

**Problem:** right rear door glass broken

Meter Reading: 22603		Labor		Parts	
In Date: 12/20/2010	Close Date: 12/22/2010	Hours	Description		Quantity
-	Set Up Glass Repair With Vendor And Replace Rear	1.00	SHOP SUPPLIES		1.00
	Asset #				
-	Shop Supplies				
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00		<b>Commercial Charge:</b> 205.78	

**Workorder:** 1014042

**Problem:** install security screens / locks w/all keyed the same

Meter Reading: 22808		Labor		Parts	
In Date: 12/22/2010	Close Date: 01/19/2011	Hours	Description		Quantity
-	Fabricate And Install Security Screens And Locks	4.00	SIDE WINDOW SCREENS		1.00
			REAR WINDOW SCREENS		1.00
-	Shop Supplies		LOCK HASP		2.00
			SHOP SUPPLIES		1.00
			SECURITY LOCKS		2.00
<b>Parts Charge:</b> 409.25		<b>Labor Charge:</b> 240.00			

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1100818

**Problem:** P.M. Service

Meter Reading: 22878	Labor	Parts	
In Date: 01/20/2011	Hours	Description	Quantity
- P.M. Service.	7.50	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Test Battery And Charging System.Replace Bad Battery,.		1066 WHITE LITHIUM (CRC 05037)	1.00
- Flush And Refill Transmission System.		SYN/ATF TRANS FLUID SYNTHETIC	13.00
- Rotate And Balance All Tires.		GROUP 78 BATTERY (ACD 78PS)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		PH3506 OIL FILTER WIX 51042	1.00
		10W30 MOTOR OIL	6.00
<b>Parts Charge:</b>	209.24	<b>Labor Charge:</b>	450.00

**Workorder:** 1107806

**Problem:** Pm service

Meter Reading: 25530	Labor	Parts	
In Date: 07/26/2011	Hours	Description	Quantity
- P.M. Service.	8.50	USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Replace Leaking Hydrobooster.Flush And Bleed Power		SHOP SUPPLIES	1.00
- Steering System.		10W30 MOTOR OIL	6.00
- Rotate And Balance All Tires.		BRAKE HYDRO BOOSTER	1.00
- Shop Supplies		61A P/STEERING FLUID	1.00
		09997 BRAKE CLEAN	1.00
		PH3506 OIL FILTER WIX 51042	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
<b>Parts Charge:</b>	334.96	<b>Labor Charge:</b>	510.00

**Workorder:** 1109520

**Problem:** Check engine light on .

Meter Reading: 25997	Labor	Parts	
In Date: 09/06/2011	Hours	Description	Quantity
- Computer Diagnose For Check Engine Light On.Perform	2.00	SHOP SUPPLIES	1.00
- Evapt.Test And Replace Failed Gas Cap With New.Clear		FUEL CAP	1.00
- Codes With Scan Tool And Road Test.			
- Shop Supplies			
<b>Parts Charge:</b>	19.17	<b>Labor Charge:</b>	120.00

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1112543

**Problem:** Ignition key will not turn.

Meter Reading: 26965 In Date: 11/28/2011	Close Date: 12/12/2011	Labor Hours	Description	Parts	Quantity
- Diagnose Ignition Cylinder Inop.Remove Steering Wheel.Test And Replace Failed Ignition Cylinder With New And Cut New Keys.Recode Tumblers And Program Pass Lock To Start Engine.		3.50	SHOP SUPPLIES IGNITION CYLINDER WITH TUMBLER		1.00 1.00
- Shop Supplies					
<b>Parts Charge:</b>		63.81	<b>Labor Charge:</b>		210.00

**Workorder:** 1112941

**Problem:** No start

Meter Reading: 26954 In Date: 11/28/2011	Close Date: 12/07/2011	Labor Hours	Description	Parts	Quantity
- Tow From: Lake Lytal					
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>		0.00
			<b>Commercial Charge:</b>		104.15

**Workorder:** 1200614

**Problem:** P.M. service.

Meter Reading: 27619 In Date: 01/19/2012	Close Date: 01/30/2012	Labor Hours	Description	Parts	Quantity
- P.M. Service.		7.00	SHOP SUPPLIES		1.00
- Replace Two Tires,Rotate And Balance All Four.			6573 AIR FILTER FRM CA9269 WIX 46573		1.00
- Replace Front Sway Bar Bushings.			10W30 MOTOR OIL		6.00
- Shop Supplies			SWAY BAR BUSHINGS		2.00
			179747492 LT245/75R16 WRANGLER SR-A E		2.00
			TIRE DISPOSAL FEE		2.00
			PH3506 OIL FILTER WIX 51042		1.00
<b>Parts Charge:</b>		399.02	<b>Labor Charge:</b>		420.00

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1206492

**Problem:** P.M. service

<b>Meter Reading:</b> 29825		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/11/2012	<b>Close Date:</b> 07/23/2012	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Perform Pm Service.	<b>9.50</b>	TIRE DISPOSAL FEE	2.00
-	Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Four.		K040378HD A/C BELT	1.00
-	Inspect And Replace Failed Serpentine Belt With New.		PH3506 OIL FILTER WIX 51042	1.00
-	Perform Wheel Alignment Complete.		179747492 LT245/75R16 WRANGLER SR-A E	2.00
-	Shop Supplies		10W30 MOTOR OIL	6.00
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
			K060923HD SERP BELT	1.00
			SHOP SUPPLIES	1.00
			31-22 WIPER BLADES 22" WIPER BLADE	2.00
<b>Parts Charge:</b> 487.73		<b>Labor Charge:</b> 570.00		

**Workorder:** 1300182

**Problem:** Pm service

<b>Meter Reading:</b> 31929		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/04/2013	<b>Close Date:</b> 01/17/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	P.M. Service.	<b>5.50</b>	SHOP SUPPLIES	1.00
-	Replace Broken Headlamp Ring.		HL/RING	1.00
-	Rotate And Balance All Tires.		PH3506 OIL FILTER WIX	1.00
-	Shop Supplies		31-22 WIPER BLADES 22	2.00
			10W30 MOTOR OIL	6.00
			USED FIREX REFURBED F	1.00
<b>Parts Charge:</b> 67.31		<b>Labor Charge:</b> 330.00		

**Workorder:** 1300900

**Problem:** Side door will not open.

<b>Meter Reading:</b> 32050		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/25/2013	<b>Close Date:</b> 01/29/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Inspect And Replace Failed Rod Clip With New Then Adjust Linkage To Open And Close.	<b>0.50</b>	DOOR CLIP	1.00
<b>Parts Charge:</b> 4.25		<b>Labor Charge:</b> 30.00		

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1306678

**Problem:** Pm service

<b>Meter Reading:</b> 34397		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/03/2013	<b>Close Date:</b> 07/19/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- P.M Service.		<b>6.00</b>	10W30 MOTOR OIL		6.00
- Test Battery And Charging System.Replace Bad Battery.			WASHER FL		1.00
- Rotate And Balance All Tires.			WIPER BLADE		2.00
- Shop Supplies			GROUP 78 BATTERY		1.00
			SHOP SUPPLIES		1.00
			NAPAGOLD OIL FILTER		1.00
			MAC WITE LITHIUM GRES		1.00
<b>Parts Charge:</b> 132.01		<b>Labor Charge:</b> 360.00			

**Workorder:** 1400467

**Problem:** pm service.

<b>Meter Reading:</b> 36828		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 01/14/2014	<b>Close Date:</b> 01/29/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- P.M. Service.		<b>5.00</b>	NAPAGOLD OIL FILTER		1.00
- Rotate And Balance All Tires.			WIPER BLADE		2.00
- Shop Supplies			10W30 MOTOR OIL		6.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 29.65		<b>Labor Charge:</b> 300.00			

**Workorder:** 1403970

**Problem:** Right side power outlet inop.

<b>Meter Reading:</b> 38152		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/23/2014	<b>Close Date:</b> 04/29/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Diagnose Right Side Power Outlet Inop.Test And Replace		<b>1.00</b>	25774623 RECEPTACLE P		1.00
- Failed Right Power Outlet Receptacle With New.			SHOP SUPPLIES		1.00
- Shop Supplies					
<b>Parts Charge:</b> 6.70		<b>Labor Charge:</b> 60.00			

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1407344

**Problem:** P.M. service.

Meter Reading: 39063 In Date: 07/25/2014	Close Date: 08/07/2014	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		12.00	SHOP SUPPLIES		1.00
- Ac Performance And Leak Test.Replace Failed Low Pressure Switch.Blower Resistor And Pigtail Connector .Evacuate And Recharge System To Specs.			NAPAGOLD AIR FILTER		1.00
			PRESSURE SWITCH		1.00
			R134A LV SHOP 2		2.00
- Replace Worn Idle Arm.			USED FIRE X REFURBISHED		1.00
- Pressure Test And Inspect Cooling System.Reverse Flush And Renew Engine Coolant.			IDLER ARM ASSEMBLY		1.00
			PEAK GLOBAL		2.00
- Rotate And All Four Tires.			NAPAGOLD OIL FILTER		1.00
			10W30 MOTOR OIL		6.00
- Shop Supplies			ELECTRICAL CONNECTOR		1.00
			BLOWER MOTOR RESISTOR		1.00
	<b>Parts Charge:</b> 227.67	<b>Labor Charge:</b> 720.00			

**Workorder:** 1501332

**Problem:** P.M. Service.

Meter Reading: 41008 In Date: 02/04/2015	Close Date: 02/19/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		5.00	NAPAGOLD OIL FILTER		1.00
- Rotate And Balance All Four Tires.			SHOP SUPPLIES		1.00
- Shop Supplies			10W30 MOTOR OIL		6.00
			WIPER BLADE		2.00
	<b>Parts Charge:</b> 30.16	<b>Labor Charge:</b> 300.00			

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1507895

**Problem:** P.M. service.

<b>Meter Reading:</b> 42802		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/06/2015	<b>Close Date:</b> 08/19/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service.		<b>9.25</b>	WIPER BLADE		2.00
- Replace Two Tires.Rotate And Balance All Four.			USED FIRE X REFURBISHED		1.00
- Complete Front End Alignment And Roadtest.			WASHER FLUID CONCENTR		1.00
- Right Side Cargo Door Inner Latch Linkage Came Apart.Remove Inner Door Panel To Secure And Adjust Linkage.			SHOP SUPPLIES		1.00
- Shop Supplies			LT245 75R16		2.00
			NAPAGOLD OIL FILTER		1.00
			10W30 MOTOR OIL		6.00
			TIRE DISPOSAL FEE		2.00
<b>Parts Charge:</b> 520.06		<b>Labor Charge:</b> 555.00			

**Workorder:** 1508820

**Problem:** Towed in for no start.

<b>Meter Reading:</b> 43114		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/02/2015	<b>Close Date:</b> 09/11/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Test Battery And Charging System.Replace Defective Battery.		<b>1.00</b>	SHOP SUPPLIES		1.00
- Shop Supplies			BATTERY CABLE BOLT		1.00
			GROUP 78 BATTERY		1.00
<b>Parts Charge:</b> 100.08		<b>Labor Charge:</b> 60.00			

**Workorder:** 1508894

**Problem:** No Start

<b>Meter Reading:</b> 43058		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/02/2015	<b>Close Date:</b> 09/03/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Tow From: 4215 Cherry Rd To: Lv Shop					
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00		<b>Commercial Charge:</b> 104.15	

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1510047

**Problem:** Check ignition switch.Seat belt and washer fluid.

<b>Meter Reading:</b> 43347		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/02/2015	<b>Close Date:</b> 10/20/2015	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Diagnose Binding Ignition Switch.Replace Defective Ignition Lock Cylinder, Pass Lock And Housing.Rekey Cylinder And Relearn Theft Deterant.	<b>6.50</b>	SHOP SUPPLIES W S WASH IGNITION KEY & SWITCH ASSY		1.00 1.00 1.00
-	Remove Washer Tank To Replace Defective Washer Pump.R&R Defective Driver Seat Belt Buckle.		belt kit front seat WASHER FLUID CONCENTR		1.00 1.00
-	Shop Supplies		IGNITION CASE		1.00
<b>Parts Charge:</b> 410.48		<b>Labor Charge:</b>	390.00		

**Workorder:** 1512500

**Problem:** Right front turnsignal light inop.

<b>Meter Reading:</b> 44141		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/10/2015	<b>Close Date:</b> 12/16/2015	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Test And Replace Defective Right Front Turnsignal Lamp Bulb.	<b>0.50</b>	BULB		2.00
<b>Parts Charge:</b> 1.50		<b>Labor Charge:</b>	30.00		

**Workorder:** 1601715

**Problem:** Pm service.

<b>Meter Reading:</b> 45081		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/18/2016	<b>Close Date:</b> 02/29/2016	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Pm Service.	<b>6.00</b>	10W30 MOTOR OIL		6.00
-	Replace Two Tires.Rotate And Balance All Four.		WASHER FLUID CONCENTR		1.00
-	Shop Supplies		LT245 75R16 NAPAGOLD OIL FILTER SHOP SUPPLIES 22" WIPER BLADE TIRE DISPOSAL FEE		2.00 1.00 1.00 2.00 2.00
<b>Parts Charge:</b> 480.42		<b>Labor Charge:</b>	360.00		

2/6/2017  
2:43:58PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164720 2006 GMC SAVANA HD Van, 1 Ton, Cargo, W/Shelves

**Workorder:** 1602144                      **Problem:** Left rear turnsignal inop.

Meter Reading: 45143	Labor	Parts	Quantity
In Date: 03/01/2016	Hours	Description	
- Check And Replace Both Left Rear Turnsignal And Brake Lamp Bulbs.	0.50	BULB	2.00
<b>Parts Charge:</b> 1.56		<b>Labor Charge:</b> 30.00	

**Workorder:** 1608828                      **Problem:** P.M. service and left front lock cylinder binding and side door inop.

Meter Reading: 47606	Labor	Parts	Quantity
In Date: 08/24/2016	Hours	Description	
- P.M. Service.	6.75	10W30 MOTOR OIL	6.00
- Rotate And Balance All Tires.		USED FIRE X REFURBISHED	1.00
- Fabricate And Replace Front And Rear Asset #S.		NAPAGOLD OIL FILTER	1.00
- Replace And Cut New Ignition Key.		MAC WITE LITHIUM GRES	1.00
- Replace Rear Door Latch Retainer Clip.		SHOP SUPPLIES	1.00
- Shop Supplies		ROD CLIP	1.00
		WASHER FLUID CONCENTR	1.00
		KEY	1.00
<b>Parts Charge:</b> 54.69		<b>Labor Charge:</b> 405.00	

**Workorder:** 1612102                      **Problem:** lLeft front turn signal inop.

Meter Reading: 48860	Labor	Parts	Quantity
In Date: 11/28/2016	Hours	Description	
- Replace Left Front Signal Light Bulb.	0.50	BULB	1.00
<b>Parts Charge:</b> 0.78		<b>Labor Charge:</b> 30.00	

**Workorder:** 1700443                      **Problem:** Transition Prep Charge

Meter Reading: 49260	Labor	Parts	Quantity
In Date: 01/13/2017	Hours	Description	
- Transition Prep Charge	2.00		
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	

Total Parts Charges:	<b>5,465.83</b>	Total Labor Charges:	<b>8,496.50</b>		Total Comm. Charges:	<b>552.08</b>
----------------------	-----------------	----------------------	-----------------	--	----------------------	---------------