

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10189442    2012 HARPER INDUSTRIAL TV40 Lawn Vac, Harper Ind, Tv40 Re, Recrcg Turf Vac**

**Workorder:** 1208676    **Meter:** 0    **In Date:** 09/12/2012    **Closed:** 09/12/2012  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00    Labor: 120.00    Parts: 0.00    Total: 120.00  
 :

**Workorder:** 1311872    **Meter:** 73    **In Date:** 11/25/2013    **Closed:** 12/26/2013  
**Problem:** P.M.SERVICE

- pm	<b>Parts List</b>	<b>Qty</b>
- svc hyd sys inspect lines and hoses replace filter correct fluid level	Air Filter	1.00
- Verify Ignition Switch Inop Replace Ign Switch	Napagold Fuel Filter	2.00
- verify deadl battery test bad replace battery	Napagold Oil Filter	1.00
- wash eq	15w40 Bulk South Reg	3.00
- Shop Supplies	Napa Hydraulic Filtr	1.00
	Aw68 Bulk Sr	2.00
	Ignition Switch	1.00
	Battery	1.00
	Shop Supplies	1.00

Hours 8.25    Labor: 495.00    Parts: 106.91    Total: 601.91  
 :

**Workorder:** 1400601    **Meter:** 742    **In Date:** 01/17/2014    **Closed:** 01/29/2014  
**Problem:** broken jack

- roken jack heat frame bend jack plate back into place weld jack paint	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00

Hours 3.00    Labor: 180.00    Parts: 2.00    Total: 182.00  
 :

**Workorder:** 1404772    **Meter:** 742    **In Date:** 05/15/2014    **Closed:** 05/28/2014  
**Problem:** will not start

- diagnose no start test charging sys charge battery	<b>Parts List</b>	<b>Qty</b>
- Oil change-fuel in oil drain and recondition carb and rebuild	Starter	1.00
- Shop Supplies	Napa Heavy Duty 30qt	2.00
	Clean-r-carb 20oz	1.00
	Shop Supplies	1.00

Hours 4.00    Labor: 240.00    Parts: 180.64    Total: 420.64  
 :

**Workorder:** 1408421    **Meter:** 742    **In Date:** 08/09/2014    **Closed:** 08/22/2014  
**Problem:** Tow Heavy plus Stand By Tlme

- Tow From: 9255 Vista Del Lago, Boca Raton To: He Shop

Hours 0.00    Labor: 0.00    Parts: 0.00    Total: 0.00  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1500849      **Meter:** 113      **In Date:** 01/23/2015      **Closed:** 02/09/2015  
**Problem:** P.M.SERVICE

	<b>Parts List</b>	<b>Qty</b>
- pm		
- svc hyd sys inspect lines hoses correct fluid level rr filter	Air Filter	1.00
- wash eq	Napagold Fuel Filter	1.00
- Shop Supplies	Napagold Oil Filter	1.00
	15w40 Bulk South Reg	3.00
	Aw68 Bulk Sr	2.00
	Napa Hydraulic Filtr	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 36.92
:		Total: 396.92

**Workorder:** 1504320      **Meter:** 1173      **In Date:** 04/28/2015      **Closed:** 05/19/2015  
**Problem:** ck left tire keeps going flat, replace wheel bracket for brush roller

	<b>Parts List</b>	<b>Qty</b>
- ck wheel and bracket install new wheel and bracket		
- repair left tire add n2	Bolt	1.00
- verify dead battery and ignition sticking lubricate ignition	Nut	1.00
recharge battery test good ck charging sys	Nut	1.00
- Shop Supplies	Washer	2.00
	Caster Wheel	1.00
	Left Wheel Mount	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 227.47
:		Total: 407.47

**Workorder:** 1512606      **Meter:** 1173      **In Date:** 12/14/2015      **Closed:** 01/15/2016  
**Problem:** left tire keeps going flat, ck ingition switch, dead battery

	<b>Parts List</b>	<b>Qty</b>
- ck battery test battery ad replace ck charging sys		
- ck ignition sticking replace ignition and key	Battery	1.00
- ck left rire leaking repair both tires correct n2 level	Ignition Switch	1.00
- verify hyd sys overfilled correct fluid level test run	Shop Supplies	1.00
- Shop Supplies		
Hours 4.75	Labor: 285.00	Parts: 68.27
:		Total: 353.27

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1603367      **Meter:** 1173      **In Date:** 03/31/2016      **Closed:** 04/27/2016  
**Problem:** pm, right rear tire need to be replaced

	<b>Parts List</b>	<b>Qty</b>
- Pm service.		
- Service hydraulic system.inspect lines,hoses etc..replace filter and correct fluid level.	Air Filter	1.00
- C/c replace tire.verify left rear tire bad.replace left rear tire.	Napagold Fuel Filter	1.00
- Wash equipment.	Napagold Oil Filter	1.00
- Shop Supplies	15w40 Bulk South Reg	3.00
	Aw68 Bulk Sr	1.00
	Napa Hydraulic Filtr	1.00
	Caster Wheel	1.00
	Tire & Wheel Assy	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 7.50	Labor: 450.00	Parts: 423.44
:		Total: 873.44

**Workorder:** 1704865      **Meter:** 1173      **In Date:** 05/16/2017      **Closed:** 05/30/2017  
**Problem:** PM Service.Right side tire flat.Check battery.

	<b>Parts List</b>	<b>Qty</b>
- Pm Service		
- Service hyd.system.inspect lines,hoses,fittings etc..replace filter,correct fluid level.	Air Filter	1.00
- Wash equipment	Napagold Fuel Filter	1.00
- C/c right rear tire leaking.repair.	Napagold Oil Filter	1.00
- C/c check battery.r/r battery .test charging system.	15w40 Bulk South Reg	2.00
- Shop Supplies	Napa Hydraulic Filtr	1.00
	Aw68 Bulk Sr	3.00
	Battery	1.00
	Shop Supplies	1.00
Hours 8.25	Labor: 495.00	Parts: 96.43
:		Total: 591.43

**Workorder:** 1709412      **Meter:** 1173      **In Date:** 09/27/2017      **Closed:** 10/18/2017  
**Problem:** Key switch?Wont start.Hour meter inop.

	<b>Parts List</b>	<b>Qty</b>
- Replace ignition switch and key.		
- C/c Tach./hour meter.replace bracket.meter and rewire.replace fuse and fan Pto toggle switch.	Switch Key Assy	1.00
- Recharge and test battery.good.check charging system.	Bracket	1.00
- Shop Supplies	Tachometer/hourmeter	1.00
	Switch	1.00
	Boot	1.00
	Screw	4.00
	Ignition Switch	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 4.75	Labor: 285.00	Parts: 448.10
:		Total: 733.10

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1804351      **Meter:** 1173      **In Date:** 04/26/2018      **Closed:** 05/14/2018  
**Problem:** PM Service.Replace both tires.Replace pull cord.

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Replace two tires.mount and add N2	Napagold Fuel Filter	1.00
- Service hyd. system.found hyd. tank filled with water.drain,flush and refilled with 20 quarts Aw68.change filter.	Napagold Oil Filter	1.00
	15w40 Bulk South Reg	2.00
	Air Filter	1.00
- Empty lawn vacume.wash equipment.	Napa Hydraulic Filtr	1.00
- Shop Supplies	18.5x8.50-8 6ply Lr C	2.00
	Aw68 Hydro Fluid Hydr	20.00
	Aw68 Bulk Sr	20.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 9.25	Labor: 555.00	Parts: 208.20
:		Total: 763.20

**Workorder:** 1904901      **Meter:** 1173      **In Date:** 05/06/2019      **Closed:** 06/17/2019  
**Problem:** PM Service

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Test battery-bad.replace battery and check charging system.	Air Filter	1.00
- Replace spark plugs.	Napagold Fuel Filter	1.00
- Clean carb and fuel system.	10w30 Bulk Sr	2.00
- Service hyd.system.repair hole on top of hyd.tank.flush tank of contaminated fluid and replace filter.	Napagold Oil Filter	1.00
- Shop Supplies	Battery	1.00
	Cham Plt Pwr Spark PI	2.00
	Clean-r-carb 20oz	1.00
	Aw68 Bulk Sr	40.00
	Napa Hydraulic Filtr	2.00
	Jb Weld	1.00
	Shop Supplies	1.00
Hours 9.00	Labor: 603.00	Parts: 206.25
:		Total: 809.25

**Workorder:** 1912247      **Meter:** 2102      **In Date:** 11/27/2019      **Closed:** 12/11/2019  
**Problem:** hyd leak, wont start, can jump but dies when take cables off

- check no start. replace ignition switch	<b>Parts List</b>	<b>Qty</b>
- r/r belt gaurd. tighten clamp from tank to pump and test run	Ignition Switch	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 146.00	Parts: 38.94
:		Total: 184.94

**Workorder:** 2003405      **Meter:** 2102      **In Date:** 04/03/2020      **Closed:** 04/03/2020  
**Problem:** Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00