

**Palm Beach County Fleet Management
Asset Maintenance History**

10192681 2013 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Workorder: 1310109 **Meter:** 313 **In Date:** 10/07/2013 **Closed:** 10/07/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1311316 **Meter:** 826 **In Date:** 11/07/2013 **Closed:** 11/22/2013
Problem: Request installing toggle switch and wiring in cab for transfer pump.

- Install switch inside cab for aux. fuel pump per request.fabricate wiring.pump out contaminated fuel and clean tank.replace filter.

- Shop Supplies

Parts List	Qty
Fuse Holder	1.00
Toggle Switch	1.00
Floor Mat-2pc Rub Bk	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours 4.00 Labor: 240.00 Parts: 44.68 Total: 284.68
:

Workorder: 1403727 **Meter:** 4166 **In Date:** 04/16/2014 **Closed:** 04/24/2014
Problem: Pm service and bent tool box props.

- Perform pm service.

- Inspect and replace bent tool box prop on left side with new and repair hinge support bracket.

- Inspect and service auxiliary fuel tank.

- Rotate and balance all six tires.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Support	1.00
Support	1.00
Shop Supplies	1.00

Hours 7.25 Labor: 435.00 Parts: 89.09 Total: 524.09
:

Workorder: 1406108 **Meter:** 5900 **In Date:** 06/20/2014 **Closed:** 07/08/2014
Problem: need ignition and tool box key

- Make and program 1 truck key supply tool box keys

- Shop Supplies

Parts List	Qty
Ch502 Tool Box Key	4.00
Ford Ignition Key Blank	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours 1.00 Labor: 60.00 Parts: 56.74 Total: 116.74
:

Workorder: 1407756 **Meter:** 7095 **In Date:** 08/06/2014 **Closed:** 08/11/2014
Problem: Water in aux. fuel tank.

- Drain water from auxiliary fuel tank.service and replace fuel cap and filter.

- Shop Supplies

Parts List	Qty
Cap	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours 2.00 Labor: 120.00 Parts: 45.04 Total: 165.04
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1412711 **Meter:** 10080 **In Date:** 12/19/2014 **Closed:** 12/31/2014
Problem: P.M. service.

- Pm service.	Parts List	Qty
- Inspect and service auxiliary fuel tank.	5w20 Engine Oil	7.00
- Replace broken hitch pintle pin with chain.	Napagold Oil Filter	1.00
- Inspect ,fabricate and rerpair both broken tool box prop support brackets to lid.	Stg Wheel Cov - Ford	1.00
	Napagold Fuel Filter	1.00
- Rotate and balance all six tires.	Pintle Pin W/chain	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 49.84
:		Total: 529.84

Workorder: 1500385 **Meter:** 10426 **In Date:** 01/09/2015 **Closed:** 01/12/2015
Problem: Service

- Tire Service County Pines Rec Complex and Samuel Friedland Park - Service	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

Workorder: 1500386 **Meter:** 10426 **In Date:** 01/09/2015 **Closed:** 01/12/2015
Problem: Tire

- Tire Service County Pines Rec Complex and Samuel Friedland Park - Tire	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

Workorder: 1507038 **Meter:** 15721 **In Date:** 07/15/2015 **Closed:** 07/30/2015
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Inspect and service aux. fuel system.	5w20 Engine Oil	7.00
- Fabricate reinforcement plates for tool box lid and install new props.	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
- Rotate and balance all six tires.	Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Napagold Fuel Filter	1.00
	Support	2.00
	Shop Supplies	1.00
Hours 8.50	Labor: 510.00	Parts: 107.69
:		Total: 617.69

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1600461 **Meter:** 19797 **In Date:** 01/14/2016 **Closed:** 01/27/2016
Problem: Pm service.Check battery

- Pm service.	Parts List	Qty
- Service auxiliary fuel tank.replace fuel filter.	Napagold Oil Filter	1.00
- Test starting and charging system.battery failed loadtest after recharge.replace defective battery.	5w20 Engine Oil	7.00
- Replace one tire.rotate and balance all six.	Washer Fluid Concentr	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Battery 65	1.00
	Shop Supplies	1.00
	Lt245/75r17 Tire	1.00
Hours 8.00	Labor: 480.00	Parts: 325.21
:		Total: 805.21

Workorder: 1601220 **Meter:** 20809 **In Date:** 02/04/2016 **Closed:** 02/18/2016
Problem: Trailer plug inop

- Check inop trailer plug.replace corroded trailer plug and rewire. Replace blown fuses.	Parts List	Qty
- Shop Supplies	Female Conn Socket	1.00
	Vinyl Electrical Tape	1.00
	Fuse	1.00
	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 19.28
:		Total: 109.28

Workorder: 1603127 **Meter:** 21732 **In Date:** 03/24/2016 **Closed:** 03/24/2016
Problem: Emergency Service

- Tire Service Lake Lytal Baseball Field - Emergency Service			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1607295 **Meter:** 24721 **In Date:** 07/18/2016 **Closed:** 07/28/2016
Problem: P.M. service

- P.m. Service.	Parts List	Qty	
- Replace and balance six new tires.	Napagold Oil Filter	1.00	
- Inspect and service aux. fuel system.	5w20 Engine Oil	8.00	
- Replace right back up light bulb and socket.	20" Wiper Blade	2.00	
- Complete wheel alignment.test drive.	Washer Fluid Concentr	1.00	
- Shop Supplies	Napagold Air Filter	1.00	
	Used Fire X Refurbished	1.00	
	179636492 Lt245-75r17	6.00	
	Napagold Fuel Filter	1.00	
	Rpl Bulb	1.00	
	Napa Quart 5w20	8.00	
	Sockey Assy	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	6.00	
Hours 11.00	Labor: 660.00	Parts: 1,617.46	Total: 2,277.46
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1609688 **Meter:** 26496 **In Date:** 09/16/2016 **Closed:** 09/27/2016
Problem: Had to jump start.

- Recharge battery.test battery and charging system.battery failed load test,replace defective battery.	Parts List	Qty
	Shop Supplies	1.00
- Shop Supplies		
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1700756 **Meter:** 29632 **In Date:** 01/25/2017 **Closed:** 02/06/2017
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Resurface front brake rotors,replacefront pads.service and lube calipers.flush and bleed system.	5w20 Engine Oil	8.00
- Inspect and service aux. fuel system.	Napagold Oil Filter	1.00
- Replace and rewire corroded trailer plug.	22" Wiper Blade	2.00
- Replace worn out toolbox struts.	Front Brake Pad	1.00
- Rotate and balance all six titres.	lube	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	trailer plug	1.00
	Support	2.00
	Shop Supplies	1.00
Hours 13.25	Labor: 795.00	Parts: 214.39
:		Total: 1,009.39

Workorder: 1707042 **Meter:** 34806 **In Date:** 07/19/2017 **Closed:** 07/31/2017
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Inspect and service Aps auxiliary fuel system.	5w20 Engine Oil	7.00
- Rotate and high speed balance all six tires.nitro fill all.	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 57.08
:		Total: 447.08

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1800019 **Meter:** 39682 **In Date:** 01/02/2018 **Closed:** 01/09/2018
Problem: P.M. service and check vibration at 45 mph.

	Parts List	Qty
- P.m. Service.		
- Inspect and service aux. fuel system.	5w20 Engine Oil	7.00
- Resurface rear brake rotors,replace rear brake pads.service and lube calipers./flush and bleed system.	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
- Rotate and balance all six tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Real Brake Pad	1.00
	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	1.00
	Ford Triton Pvc Swc	1.00
	Shop Supplies	1.00
Hours 10.50	Labor: 630.00	Parts: 155.12 Total: 785.12
:		

Workorder: 1805343 **Meter:** 43902 **In Date:** 05/25/2018 **Closed:** 05/30/2018
Problem: Had to jump start in A.M.

	Parts List	Qty
- Charge battery fully .test battery and charging system .battery failed load test .r&r defective battery.	Battery 65	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 168.47 Total: 228.47
:		

Workorder: 1807199 **Meter:** 45350 **In Date:** 07/16/2018 **Closed:** 07/24/2018
Problem: P.M. service.

	Parts List	Qty
- P.m. service.		
- Inspect and service auxiliary fuel tank .	Napagold Oil Filter	1.00
- Check and replace leaking brake hydro-power booster . Bleed system and road test.	Napa Quart 5w30	8.00
	22" Wiper Blade	2.00
- Pressure test and inspect cooling system . Flush and refill coolant.	Napagold Fuel Filter	1.00
- Replace two front tires and rotate and balance all six tires. Nitrofill.	Brakr Booster	1.00
	Anti Freeze Motorcraft	2.00
- Complete front end alignment and road test.	Tr416 Valve Stem	2.00
- Shop Supplies	Tire	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 14.00	Labor: 840.00	Parts: 870.99 Total: 1,710.99
:		

Workorder: 1809862 **Meter:** 49903 **In Date:** 09/25/2018 **Closed:** 12/20/2018
Problem: Auxiliary fuel pump slow to pump .

	Parts List	Qty
- Replace defective flow meter and fuel filter on auxiliary fuel tank.	Napagold Fuel Filter	1.00
- Shop Supplies	Gallon Meter 3 4 In	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 310.13 Total: 377.13
:		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1809931 **Meter:** 47599 **In Date:** 09/26/2018 **Closed:** 10/03/2018
Problem: Clean fuel

- remove tank and pump. clean inside of tank and polish with filter cart	Parts List	Qty
	Pm-22-a Additive Dies	1.00
- Shop Supplies	Napagold Fuel Filter	2.00
	Motor Treatment Gal	1.00
	Shop Supplies	1.00
Hours 2.50	Labor: 167.50	Parts: 80.48
:		Total: 247.98

Workorder: 1900754 **Meter:** 50695 **In Date:** 01/18/2019 **Closed:** 01/31/2019
Problem: PM Service, Service fuel tank, Replace safe driver sticker.

- P.m. service.	Parts List	Qty
- Replace four tires . Rotate and high speed balance all six tires . Nitrofill all.	Napagold Oil Filter	1.00
	5w20 Engine Oil	7.00
- Inspect and service aux fuel tank . Replace broken toggle switch .	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Used Fire X Refurbished	1.00
	245/75/17/tire Nitiro	4.00
	Napagold Fuel Filter	1.00
	Toggle Switch	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.50	Labor: 569.50	Parts: 1,191.79
:		Total: 1,761.29

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1907914 **Meter:** 56131 **In Date:** 07/31/2019 **Closed:** 08/15/2019
Problem: P.M. Service.

- P.m. service.	Parts List	Qty
- Inspect all brake . Resurface both front brake rotors .	Napagold Oil Filter	1.00
Replace brake pads, calipers and brake hoses . Flush and bleed brake system . Road test.	5w20 Engine Oil	7.00
- Computer diagnose missfire . Perform tune up . Replace all sixteen spark plugs and wire set and #4 and #6 coils . Clear codes and retest .	Washer Fluid Concentr	1.00
- Perform complete air intake decarb and cleaning . Flush injectors .	22" Wiper Blade	2.00
- Inspect and service aux fuel tank .	Tire Crayon	1.00
- Rotate and high speed bal;ance all six tires . Nitrofill all.	Non-chlor Brake Clnr	1.00
- Shop Supplies	B Fluid Dot 3-32oz	1.00
	Brake Hose	1.00
	Brake Hose	1.00
	Front Brake Caliper	1.00
	Front Brake Caliper	1.00
	Front Brake Pad	1.00
	Espak Plug Wire	4.00
	Espak Plug Wire	4.00
	Spark Plug	16.00
	Caliper Washer	4.00
	Coil	1.00
	Coil	1.00
	Intake Cleaner Kit	1.00
	Injector Cleaner	1.00
	Throttle Body Cleaner	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 19.10	Labor: 1,279.7	Parts: 1,152.12
:	0	Total: 2,431.82

Workorder: 2001311 **Meter:** 61470 **In Date:** 02/06/2020 **Closed:** 02/12/2020
Problem: P.M. service and trailer warning on dash .

- P.m. service.	Parts List	Qty
- Inspect and service auxiliary fuel tank .	Napagold Oil Filter	1.00
- Test and replace defective trailer plug connector and rewire as needed and seal .	5w20 Engine Oil	8.00
- Rotate and balance all six tires . Nitrofill all.	22" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Napagold Fuel Filter	1.00
	trailer plug	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 547.50	Parts: 70.24
:		Total: 617.74

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2007443 **Meter:** 66578 **In Date:** 07/29/2020 **Closed:** 08/06/2020
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Remove and replace incorrect battery in truck .	Napagold Oil Filter	1.00
- Inspect and service auxiliary fuel tank .	5w20 Engine Oil	7.00
- Rotate and balance all six tires . Nitrofill all.	Washer Fluid Concentr	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Napagold Air Filter	1.00
	Battery	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 547.50	Parts: 195.91
:		Total: 743.41

Workorder: 2012322 **Meter:** 70885 **In Date:** 12/11/2020 **Closed:** 12/11/2020
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00