

**Palm Beach County Fleet Management
Asset Maintenance History**

10187815 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Workorder: 1208052 **Meter:** 164 **In Date:** 08/24/2012 **Closed:** 08/24/2012
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1301840 **Meter:** 3352 **In Date:** 02/22/2013 **Closed:** 02/27/2013
Problem: pm

	Parts List	Qty
- pm		
- rear brake drum service	Napagold Oil Filter	1.00
- vacuume tires add 35 psi of n2	Dexos 5w30	5.00
- transport and pickup vehicle at deler for recall 12319	Shop Supplies	1.00
- Shop Supplies		

Hours 5.50 Labor: 330.00 Parts: 35.45 Total: 365.45
:

Workorder: 1308586 **Meter:** 7158 **In Date:** 08/26/2013 **Closed:** 08/30/2013
Problem: pm, bad tire pass side rear

	Parts List	Qty
- pm		
- ck flat tire verify tire unable to repair swap w spare mount	Napagold Oil Filter	1.00
balance add n2 reinstall spare tire	Dexos 5w30	5.00
- rear brake drum svc	215 70r16	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	1.00

Hours 4.50 Labor: 270.00 Parts: 192.73 Total: 462.73
:

Workorder: 1311869 **Meter:** 9101 **In Date:** 11/25/2013 **Closed:** 12/04/2013
Problem: needs ignition key

	Parts List	Qty
- Make 1 spray key	Ignition Key	1.00

Hours 0.50 Labor: 30.00 Parts: 9.00 Total: 39.00
:

Workorder: 1402112 **Meter:** 12300 **In Date:** 03/04/2014 **Closed:** 03/18/2014
Problem: pm

	Parts List	Qty
- pm		
- svc rear brake drums	Napagold Oil Filter	1.00
- Shop Supplies	Dexos 5w30 Oil	5.00
	Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 36.13 Total: 216.13
:

Workorder: 1407128 **Meter:** 16905 **In Date:** 07/12/2014 **Closed:** 07/18/2014
Problem: Front Left falt tire

- Tire Service West Boynton Park - Front Left falt tire

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1407687	Meter: 17559	In Date: 08/05/2014	Closed: 08/12/2014
Problem: pm, rrepair tie flat ff, reset tire low gauge			
- pm		Parts List	Qty
- rear brake drum svc		Napagold Oil Filter	1.00
- repair rl tire mount patch balance add n2 reinstall spare tire		Dexos 5w30 Oil	5.00
- Shop Supplies		Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 36.13	Total: 276.13
:			
Workorder: 1411442	Meter: 20130	In Date: 11/17/2014	Closed: 11/20/2014
Problem: tail light bulbs			
- repair both brake left and right		Parts List	Qty
		Bulb	2.00
Hours 0.50	Labor: 30.00	Parts: 1.50	Total: 31.50
:			
Workorder: 1502640	Meter: 22481	In Date: 03/13/2015	Closed: 03/20/2015
Problem: P.M.SERVICE			
- pm		Parts List	Qty
- clean and adj rear brakes		Napagold Oil Filter	1.00
- Shop Supplies		Dexos 5w30 Oil	5.00
		Napagold Air Filter	1.00
		Wiper Blade	1.00
		Wiper Blade	1.00
		Washer Fl	1.00
		Brake Cleaner	1.00
		Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 60.68	Total: 240.68
:			
Workorder: 1509624	Meter: 25816	In Date: 09/23/2015	Closed: 09/30/2015
Problem: pm			
- pm		Parts List	Qty
- clean and adj rear brakes		Napagold Oil Filter	1.00
- replace all 4 tires		Dexos 5w30	5.00
- repair left front tirm signal		Washer Fluid Concentr	1.00
- fill tires with nitrogen		Brake Cleaner	1.00
- Shop Supplies		P215/70r16 Goodyear Wrangler Hp	4.00
		Shop Supplies	1.00
		Tire Disposal Fee	4.00
Hours 6.50	Labor: 390.00	Parts: 811.05	Total: 1,201.05
:			
Workorder: 1513003	Meter: 27525	In Date: 12/29/2015	Closed: 01/08/2016
Problem: make ing key			
- Order and cut one key		Parts List	Qty
		Ignition Key	1.00
Hours 0.50	Labor: 30.00	Parts: 9.00	Total: 39.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1602729	Meter: 28654	In Date: 03/15/2016	Closed: 03/29/2016
Problem: pm			
- pm		Parts List	Qty
- clean and adj rear brakes		Lamp	1.00
- replace damage right front fog light		Dexos 5w30	5.00
- installl hows my driving decal		Napagold Oil Filter	1.00
- Shop Supplies		Washer Fluid Concentr	1.00
		Mac Wite Lithium Gres	1.00
		Brake Cleaner	1.00
		Shop Supplies	1.00
Hours 4.25	Labor: 255.00	Parts: 140.86	Total: 395.86
:			
Workorder: 1605117	Meter: 29529	In Date: 05/17/2016	Closed: 05/24/2016
Problem: needs spare key			
- Secure key for Dept		Parts List	Qty
		Ignition Key	1.00
Hours 0.00	Labor: 0.00	Parts: 9.00	Total: 9.00
:			
Workorder: 1609539	Meter: 32680	In Date: 09/13/2016	Closed: 09/29/2016
Problem: P.M.SERVICE			
- Pm service.		Parts List	Qty
- Clean and adjust rear brakes.		Napa Syn 5w30 Qt	5.00
- Repair right front tire.		Napagold Oil Filter	1.00
- Shop Supplies		Washer Fluid Concentr	1.00
		18" wiper blades	1.00
		22" Wiper Blade	1.00
		Napagold Air Filter	1.00
		Non-chlor Brake Clnr	1.00
		Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 53.56	Total: 278.56
:			
Workorder: 1703081	Meter: 36813	In Date: 03/28/2017	Closed: 03/31/2017
Problem: P.M.SERVICE			
- Pm Service.		Parts List	Qty
- Rear brake service		Napa Syn 5w30 Qt	5.00
- Rotate and balance 4 wheels.correct N2		Napagold Oil Filter	1.00
- Shop Supplies		Non-chlor Brake Clnr	1.00
		Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 34.97	Total: 259.97
:			
Workorder: 1706589	Meter: 39077	In Date: 07/05/2017	Closed: 07/12/2017
Problem: Bad Battery			
- C/c dead battery.test and replace bad battery.check charging system ok.		Parts List	Qty
- Shop Supplies		Battery	1.00
		Shop Supplies	1.00
Hours 0.75	Labor: 45.00	Parts: 140.42	Total: 185.42
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1709845	Meter: 40568	In Date: 10/06/2017	Closed: 10/06/2017
Problem: 1 - Key(s) issued			
- 1 - Key(s) issued		Parts List	Qty
		Duplicate Vehicle Keys	1.00
Hours 0.30	Labor: 18.00	Parts: 3.00	Total: 21.00
:			

Workorder: 1709906	Meter: 40759	In Date: 10/11/2017	Closed: 10/30/2017
Problem: PM Service.Right rear tire flat			
- Pm Service		Parts List	Qty
- Mount and balance four tires.replace right front Tpms sensor.		Napa Syn 5w30 Qt	5.00
- Clean and adjust rear brakes.		Napagold Oil Filter	1.00
- Clean and vacume leave and debris from air intake cowl.		18" wiper blades	1.00
- Shop Supplies		22" Wiper Blade	1.00
		Washer Fluid Concentr	1.00
		215 70r16 All Season	4.00
		Non-chlor Brake Clnr	1.00
		Sensor	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	4.00
Hours 5.50	Labor: 330.00	Parts: 718.95	Total: 1,048.95
:			

Workorder: 1800216	Meter: 42240	In Date: 01/05/2018	Closed: 02/12/2018
Problem: Ac and heater inop.			
- Diagnose for ac blower inop..over heated wiring in dash.replace bad blower motor and resistor.r/r dash panel and replace overheated wiring for switch ground.		Parts List	Qty
- Shop Supplies		Blower Motor	1.00
		Blower Resistor	1.00
		Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 131.23	Total: 521.23
:			

Workorder: 1802516	Meter: 42426	In Date: 03/07/2018	Closed: 03/12/2018
Problem: Tire pressure warning light stay on.			
- Diagnose and replace defective left rear tire pressure sensor and retrain.balance tire and nitrogen fill all.		Parts List	Qty
- Shop Supplies		Sensor	1.00
		Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 83.77	Total: 173.77
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1804778 **Meter:** 43912 **In Date:** 05/08/2018 **Closed:** 05/14/2018
Problem: PM Service.Tailgate wont open.

	Parts List	Qty
- Pm Service.		
- Service rear brakes.	Napa Syn 5w30 Qt	5.00
- Repair tailgate.	Napagold Oil Filter	1.00
- Repair both front marker lights.	18" wiper blades	3.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Non-chlor Brake Clnr	1.00
	22" Wiper Blade	1.00
	Shop Supplies	1.00
Hours 5.25	Labor: 315.00	Parts: 51.59
:		Total: 366.59

Workorder: 1812504 **Meter:** 48772 **In Date:** 12/10/2018 **Closed:** 12/31/2018
Problem: PM Service.Driver window handle.TPMS warning light on.

	Parts List	Qty
- Pm Service.		
- Service rear brakes.	Napagold Oil Filter	1.00
- Replace driver window regulator and service window track.	Napa Syn 5w30 Qt	5.00
	Washer Fluid Concentr	1.00
- Replace four tire pressure sensors and program all.	22" Wiper Blade	1.00
- Test drive to check and reset Tpms system.	18" wiper blades	1.00
- Shop Supplies	Non-chlor Brake Clnr	1.00
	Window Regulator	1.00
	Sensor	4.00
	Shop Supplies	1.00
Hours 8.50	Labor: 569.50	Parts: 390.29
:		Total: 959.79

Workorder: 1906906 **Meter:** 52269 **In Date:** 07/02/2019 **Closed:** 07/31/2019
Problem: PM Service.Tire light on.

	Parts List	Qty
- Pm Service.		
- Service rear brakes.	Napa Syn 5w30 Qt	6.00
- Repair right front marker light.	Napagold Oil Filter	6.00
- Shop Supplies	Washer Fluid Concentr	1.00
	18" wiper blades	1.00
	22" Wiper Blade	1.00
	Non-chlor Brake Clnr	1.00
	Boxed Miniatures	1.00
	Shop Supplies	1.00
Hours 3.50	Labor: 234.50	Parts: 72.78
:		Total: 307.28

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1910162	Meter: 53781	In Date: 10/01/2019	Closed: 10/07/2019
Problem: Towed in for overheating .			
- Pressure test and inspect cooling system . R&r leaking water pump , thermostat, radiator cap and main drive belt . Flush and refill cooling system .		Parts List	Qty
- Shop Supplies		Radiator Cap	1.00
		Dex Coolant Engine	2.00
		Belt	1.00
		Thermostat Assy	1.00
		Water Pump	1.00
		Shop Supplies	1.00
Hours 6.00	Labor: 438.00	Parts: 398.70	Total: 836.70
:			

Workorder: 1910218	Meter: 53603	In Date: 10/01/2019	Closed: 10/02/2019
Problem: Water pump went out, asset overheated			
- Tow From: Ocean Inlet 6990 N Ocean Blvd Boynton To: vista			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 2000626	Meter: 56009	In Date: 01/17/2020	Closed: 02/04/2020
Problem: PM Service.			
- P.m. service.		Parts List	Qty
- Replace all four tires and balance . Nitrofill all.		Napagold Oil Filter	1.00
- Resurface both front brake rotors and service calipers .		Napa Syn 5w30 Qt	5.00
Replace front pads . Flush and bleed brake system . Inspect and service and adjust rear brakes . Road test .		18" wiper blades	1.00
- Diagnose no start . Test starter circuit test . R&r defective starter relay . Retest .		22" Wiper Blade	1.00
- Test and replace both tool box struts and adjust strikers .		Washer Fluid Concentr	1.00
- Remove left front seat assembly to be repaired . Reinstall seat assembly .		215/70/16tire Han	4.00
- Perform complete front end alignment and road test .		Brk Fluid Dot 4-12oz	1.00
- Shop Supplies		Non-chlor Brake Clnr	1.00
		Brake Pad	1.00
		Starter Relay	1.00
		Support	2.00
		Seat R And R	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	4.00
Hours 13.80	Labor: 1,007.4	Parts: 1,494.71	Total: 2,502.11
:	0		

Workorder: 2002564	Meter: 56619	In Date: 03/12/2020	Closed: 03/23/2020
Problem: Left rear tire flat.Remount spare tire.			
- Repair right rear tire clear codes with scanner.		Parts List	Qty
- Test drive after repairs to reset Tpms.		Shop Supplies	1.00
- Shop Supplies			
Hours 2.00	Labor: 146.00	Parts: 4.00	Total: 150.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2005028 **Meter:** 58031 **In Date:** 05/19/2020 **Closed:** 05/26/2020
Problem: Left side mirror broke.TPMS light blinking.

- Replace broken left outside mirror glass .		Parts List	Qty
- Nitrogen fill all tires and retrain all Tpms sensors . Clear codes and road test.		Mirror	1.00
- Shop Supplies		Shop Supplies	1.00
	Hours 1.00	Labor: 73.00	Parts: 133.38
	:		Total: 206.38

Workorder: 2005084 **Meter:** 57939 **In Date:** 05/20/2020 **Closed:** 05/20/2020
Problem: Mirror Fell off

- Tow From: Jpp To: Lv shop			
	Hours 0.00	Labor: 0.00	Parts: 0.00
	:		Total: 0.00

Workorder: 2008031 **Meter:** 61199 **In Date:** 08/12/2020 **Closed:** 08/25/2020
Problem: PM Service.

- Pm Service.		Parts List	Qty
- Install steering wheel cover.		Napa Syn 5w30 Qt	5.00
- Rear brake Service.		Napagold Oil Filter	1.00
- Rotate and balance four tires.		22" Wiper Blade	1.00
- Service tool box and adjust latches.		18" wiper blades	1.00
- Shop Supplies		Napagold Air Filter	1.00
		Chevy Gold Bow Swc	1.00
		Shop Supplies	1.00
	Hours 4.75	Labor: 346.75	Parts: 78.09
	:		Total: 424.84

Workorder: 2012689 **Meter:** 65233 **In Date:** 12/21/2020 **Closed:** 12/21/2020
Problem: Transition Prep Charge

- Transition Prep Charge			
	Hours 2.00	Labor: 146.00	Parts: 0.00
	:		Total: 146.00