

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10175018    2009 INTERNATIONAL 4300 Flatbed Dump Truck, 14 Ft., Highside, Aluminum**

**Workorder:** 843711      **Meter:** 1198      **In Date:** 09/03/2008      **Closed:** 09/04/2008  
**Problem:** REPLACE WINDSHEILD

- Set Up Replacement Clean-up	<b>Parts List</b>	<b>Qty</b>
- Asset Numbers	Shop Supplies	1.00
- Shop Supplies		
Hours 1.50	Labor: 90.00	Parts: 2.00
:		Total: 92.00

**Workorder:** 843856      **Meter:** 0      **In Date:** 09/08/2008      **Closed:** 09/08/2008  
**Problem:** PRE-DELIVERY INSPECTION

- Pre-delivery Inspection			
Hours 6.00	Labor: 360.00	Parts: 0.00	Total: 360.00
:			

**Workorder:** 844024      **Meter:** 1207      **In Date:** 09/10/2008      **Closed:** 09/15/2008  
**Problem:** INSTALL CANCEIVER

- Install Canceiver And Program	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	Ant-200 Antenna (ej Ward)	1.00
	Cbl-cvr-xts Cable Connector (ej Ward)	1.00
	J1708-9 Canceiver (ej Ward)	1.00
	Cbl-j1939-9p-in Cable International Don't Reorder	1.00
Hours 3.00	Labor: 180.00	Parts: 467.96
:		Total: 647.96

**Workorder:** 845109      **Meter:** 1207      **In Date:** 10/02/2008      **Closed:** 10/10/2008  
**Problem:** BODY UP LIGHT IS ON

- Pickup Truck At International	<b>Parts List</b>	<b>Qty</b>
- Check Body Up Light,replace Switch And Adjust.	Shop Supplies	1.00
- Road Test For Body Uplight.	B90 Switch Body Up Switch	1.00
- Shop Supplies		
Hours 4.00	Labor: 240.00	Parts: 42.28
:		Total: 282.28

**Workorder:** 847234      **Meter:** 1659      **In Date:** 11/19/2008      **Closed:** 11/20/2008  
**Problem:** WATER TANK PUMP

- Trouble Shoot Water Tank Pressure Pump Remv Pump/disassemblerepair Pressure Switch.reinstall Pump And Test.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 2.00
:		Total: 242.00

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 935154      **Meter:** 3548      **In Date:** 03/16/2009      **Closed:** 03/20/2009  
**Problem:** PM SERVICE

	<b>Parts List</b>	<b>Qty</b>
- Pm Service	Shop Supplies	1.00
- Install Nitrogen	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00
- Shop Supplies	3994 Fuel Filter Int 1878042c92	1.00
	15/40 Oil	30.00
Hours 7.50	Labor: 450.00	Parts: 167.38
:		Total: 617.38

**Workorder:** 935702      **Meter:** 0      **In Date:** 03/26/2009      **Closed:** 03/26/2009  
**Problem:** SISTERS TOWING & TRANSPORTATON TOW FROM 2601 VISTA

- Sisters Towing & Transportaton Tow From 2601 Vista Pkwy
- Tow To 3700 Belvedere Rd

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 942724      **Meter:** 8001      **In Date:** 08/31/2009      **Closed:** 09/04/2009  
**Problem:** P.M.

	<b>Parts List</b>	<b>Qty</b>
- pm service	Shop Supplies	1.00
- replace bed up switch	3994 Fuel Filter Int 1878042c92	1.00
- nitro all tires	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00
- test run	15/40 Oil	30.00
- Shop Supplies	Used Firex Refurbed Fire Extingshers	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Custom5lb Bracket Firex Stock #340060300	1.00
	B90 Switch Body Up Switch	1.00
Hours 10.00	Labor: 600.00	Parts: 235.40
:		Total: 835.40

**Workorder:** 1004336      **Meter:** 13351      **In Date:** 04/27/2010      **Closed:** 05/20/2010  
**Problem:** P.M.

	<b>Parts List</b>	<b>Qty</b>
- pm service	Shop Supplies	1.00
- replace leaking relay valve	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00
- move tag to rear and repair tag light	3994 Fuel Filter Int 1878042c92	1.00
- add nitrogen to all tires	Ca9346 Air Filter Lbf Laf9099 Wix 46870	1.00
- replac and adjust body up swtich	Relay Valve For Rear Brakes	1.00
- test drive	15/40 Oil	30.00
- chek for oil leak	31-22 Wiper Blades 22" Wiper Blade	2.00
- fm to int. warranty oil leak	Ds366 Red Pilot Light	1.00
- Shop Supplies	B90 Switch Body Up Switch	1.00
Hours 17.00	Labor: 1,020.00	Parts: 350.77
:	0	Total: 1,370.77

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1008174      **Meter:** 15426      **In Date:** 08/02/2010      **Closed:** 08/25/2010  
**Problem:** A/C

- replace evap. ,expansion valve ,drier, thermisters cab filter and evac and recharge	<b>Parts List</b>	<b>Qty</b>
- test run	Shop Supplies	1.00
- Shop Supplies	2506656c1 A/c Filter	1.00
	09997 Brake Clean	2.00
	R134a Refrigerant	4.00
	E8 A/c Oil R134a A/c Oil (tsi)	1.00
	Ring	1.00
	Ring	1.00
	A/c Drier	1.00
	Ring	1.00
	Evaporator	1.00
	Expansion Valve	1.00
	Thermistors	2.00
	Kit	1.00
Hours 8.00	Labor: 480.00	Parts: 1,101.63
:		Total: 1,581.63

**Workorder:** 1100355      **Meter:** 18967      **In Date:** 01/10/2011      **Closed:** 01/14/2011  
**Problem:** P.M.

- pm service	<b>Parts List</b>	<b>Qty</b>
- check for oil leak repaired under warranty rechtien	Shop Supplies	1.00
- test drive	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00
- fm to rechtien	3994 Fuel Filter Int 1878042c92	1.00
- Shop Supplies	2506656c1 A/c Filter	1.00
	Ca9346 Air Filter Lbf Laf9099 Wix 46870	1.00
	15/40 Oil	30.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 11.00	Labor: 660.00	Parts: 208.06
:		Total: 868.06

**Workorder:** 1109198      **Meter:** 24319      **In Date:** 08/30/2011      **Closed:** 09/23/2011  
**Problem:** pm service and exhaust light is on

- pm service	<b>Parts List</b>	<b>Qty</b>
- scan for codes clear codes low coolant sensor	Shop Supplies	1.00
- replace coolant reservoir and sensor	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00
- fm to int.	3994 Fuel Filter Int 1878042c92	1.00
- replace air compressor by int.	2506656c1 A/c Filter	1.00
- replace body up switch ,tag and body up indicator lights	15/40 Oil	30.00
- test drive	31-22 Wiper Blades 22" Wiper Blade	2.00
- Shop Supplies	B90 Switch Body Up Switch	1.00
	Ds366 Red Pilot Light	1.00
	Coolant Reservoir	1.00
	Coolant Level Sensor	1.00
	Coolant Cap	1.00
	H/duty A/freeze Ext/life (cat 238-8648)	3.00
Hours 14.50	Labor: 870.00	Parts: 573.94
:		Total: 1,443.94

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1202658      **Meter:** 28362      **In Date:** 03/19/2012      **Closed:** 03/29/2012  
**Problem:** pm service

	<b>Parts List</b>	<b>Qty</b>
- P.m.	Shop Supplies	1.00
- Service Trans.	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00
- Rewire and replace body switch	3994 Fuel Filter Int 1878042c92	1.00
- Replace Two rear tires	29526898 Trans Filter Frm C9031 Wix 57740xe	1.00
- Shop Supplies	2506656c1 A/c Filter	1.00
	09997 Brake Clean	1.00
	15/40 Oil	30.00
	Syn/atf Trans Fluid Synthetic	19.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	B90 Switch Body Up Switch	1.00
	Washdown Pump	1.00
Hours 9.50	Labor: 570.00	Parts: 642.18
:		Total: 1,212.18

**Workorder:** 1203832      **Meter:** 28960      **In Date:** 04/23/2012      **Closed:** 06/08/2012  
**Problem:** engine oil leak

	<b>Parts List</b>	<b>Qty</b>
- replace high pressure oil line clean area	Shop Supplies	1.00
- replace batteries	09997 Brake Clean	1.00
- road test	09997 Brake Clean	4.00
- Shop Supplies	15/40 Oil	4.00
	15/40 Oil	3.00
	15/40 Oil	12.00
	15/40 Oil	8.00
	Group 31 Stud Battery (acd 31-900ct)	2.00
	O Ring	1.00
	Oil Line Kit	1.00
	O Ring	2.00
	Fuel Line Seal Kit	2.00
	O Ring	1.00
Hours 5.00	Labor: 300.00	Parts: 605.39
:		Total: 905.39

**Workorder:** 1207933      **Meter:** 30962      **In Date:** 08/21/2012      **Closed:** 08/31/2012  
**Problem:** belt and recall

	<b>Parts List</b>	<b>Qty</b>
- replace belt	Shop Supplies	1.00
- replace water pump flush cooling system	Serp Belt	1.00
- test run	H/duty A/freeze Ext/life (cat 238-8648)	6.00
- fm to int.	Water Pump	1.00
- recall reflash ecm		
- Shop Supplies		
Hours 11.50	Labor: 690.00	Parts: 383.66
:		Total: 1,073.66

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1211577      **Meter:** 32695      **In Date:** 12/03/2012      **Closed:** 12/07/2012  
**Problem:** pm service

- P.m.	<b>Parts List</b>	<b>Qty</b>
- Repair tarp	15-40 Oil	30.00
- Test drive	1842639c91 Oil Filter	1.00
- Shop Supplies	1878042c92 Fuel Filte	1.00
	Cabin Air Filter	1.00
	31-22 Wiper Blades 22	2.00
	Bushing	4.00
	Napagold Air Filter	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 324.04
:		Total: 774.04

**Workorder:** 1211625      **Meter:** 32556      **In Date:** 12/03/2012      **Closed:** 12/06/2012  
**Problem:** replace rr traction tread tires boulevard

- replace right rear traction tires boulevard	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	158863 11r22.5 R260f Tire Lrh	1.00
Hours 0.00	Labor: 0.00	Parts: 420.32
:		Total: 420.32

**Workorder:** 1211913      **Meter:** 32695      **In Date:** 12/10/2012      **Closed:** 12/11/2012  
**Problem:** replace two rear tires

- boulevard replace two tires	<b>Parts List</b>	<b>Qty</b>
	158863 11r22.5 R260f Tire Lrh	2.00
Hours 0.00	Labor: 0.00	Parts: 836.64
:		Total: 836.64

**Workorder:** 1307254      **Meter:** 35498      **In Date:** 07/22/2013      **Closed:** 07/31/2013  
**Problem:** P.M.

- P.m.	<b>Parts List</b>	<b>Qty</b>
- Replace body up switch	15-40 Oil	30.00
- Test Drove	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Wiper Blade	2.00
	B90 Switch Body Up Sw	1.00
	Washer FI	1.00
	Napa Cabin Air Filter	1.00
	Used Fire X Refurbished	1.00
	L0135-063 Lubriplate	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 240.35
:		Total: 690.35

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1307327	<b>Meter:</b> 35448	<b>In Date:</b> 07/22/2013	<b>Closed:</b> 07/23/2013
<b>Problem:</b> LF Tire			
- replace lf tire		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
		Tire Disposal Fee	1.00
		158863 11r22.5 R260f Tire Lrh	1.00
Hours 0.00	Labor: 0.00	Parts: 422.32	Total: 422.32
:			

---

<b>Workorder:</b> 1401111	<b>Meter:</b> 39140	<b>In Date:</b> 02/03/2014	<b>Closed:</b> 02/12/2014
<b>Problem:</b> pm service and see list			
- P.m.		<b>Parts List</b>	<b>Qty</b>
- Replace Tarp Crank		Water System Pump	1.00
- Replace leaking electric water pump		Napagold Oil Filter	1.00
- Replace body light switch		15-40 Oil	30.00
- Replace 3 broken red reflectors		Napagold Fuel Filter	1.00
- Road test		Wiper Blade	2.00
- Shop Supplies		Washer Fl	1.00
		Crank Box	1.00
		Body Up Switch	1.00
		Reflectr	2.00
		Shop Supplies	1.00
Hours 12.50	Labor: 750.00	Parts: 909.64	Total: 1,659.64
:			

---

<b>Workorder:</b> 1405485	<b>Meter:</b> 41660	<b>In Date:</b> 06/04/2014	<b>Closed:</b>
<b>Problem:</b> P.M.			
-			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1412199	<b>Meter:</b> 45103	<b>In Date:</b> 12/05/2014	<b>Closed:</b> 12/05/2014
<b>Problem:</b> Jump Start			
- jump start		<b>Parts List</b>	<b>Qty</b>
- test run		Shop Supplies	1.00
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1501589	<b>Meter:</b> 46068	<b>In Date:</b> 02/12/2015	<b>Closed:</b> 03/03/2015
<b>Problem:</b> PM			
- Pm		<b>Parts List</b>	<b>Qty</b>
- Replace Ac refrigerant		15-40 Oil	30.00
- R&r tarp and bushings		Napagold Oil Filter	1.00
- Service air dryer		Fuel Fil	1.00
- Test Drive		Wiper Blade	2.00
- Shop Supplies		Washer Fl	1.00
		Used Fire X Refurbished	1.00
		Tarp 7.5 X 18 In	1.00
		Napagold Air Filter	1.00
		Napa Cabin Air Filter	1.00
		E8 A/c Oil Univ W Dye	1.00
		Bushing	1.00
		Cartridge Ad9	1.00
		Shop Supplies	1.00
Hours 13.50	Labor: 810.00	Parts: 395.15	Total: 1,205.15
:			
<b>Workorder:</b> 1503205	<b>Meter:</b> 46068	<b>In Date:</b> 03/02/2015	<b>Closed:</b> 03/27/2015
<b>Problem:</b> damage to left door			
- damage to left door			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1504588	<b>Meter:</b> 47198	<b>In Date:</b> 05/05/2015	<b>Closed:</b> 05/07/2015
<b>Problem:</b> replace headlight			
- headlight bulb			
		<b>Parts List</b>	<b>Qty</b>
		Halogen Capsule	1.00
Hours 0.50	Labor: 30.00	Parts: 5.01	Total: 35.01
:			
<b>Workorder:</b> 1505612	<b>Meter:</b> 47951	<b>In Date:</b> 06/03/2015	<b>Closed:</b> 06/16/2015
<b>Problem:</b> Head Light Switch			
- replace headlight switch			
- Shop Supplies			
		<b>Parts List</b>	<b>Qty</b>
		Light Switch Housing	1.00
		Light Switch Rocker	1.00
		Light Switch Housing	1.00
		Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 613.16	Total: 703.16
:			
<b>Workorder:</b> 1507163	<b>Meter:</b> 48994	<b>In Date:</b> 07/17/2015	<b>Closed:</b> 07/21/2015
<b>Problem:</b> Power Point			
- repair power point			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1507624      **Meter:** 49144      **In Date:** 07/30/2015      **Closed:** 07/31/2015  
**Problem:** Steering fluid

- Ps Fluid		<b>Parts List</b>	<b>Qty</b>
		Pwr Steering Fl-quart	1.00
Hours 0.50	Labor: 30.00	Parts: 6.06	Total: 36.06
:			

**Workorder:** 1509742      **Meter:** 50415      **In Date:** 09/25/2015      **Closed:** 10/08/2015  
**Problem:** PM / AC

- pm		<b>Parts List</b>	<b>Qty</b>
- replace 2 batteries and R&r step to access		Blower Motor	1.00
- replace Ac blower motor and resistor		Blower Resistor	1.00
- replace 3 round Led lights		Led M C Lamp	3.00
- replace body up switch and stopper bolt		Led M C Adapter Plug	3.00
- install new clevis pin on hood cable		Body Up Switch	1.00
- straighten right rear mudflap bracket		15-40 Oil	30.00
- road test		Napagold Oil Filter	1.00
- Shop Supplies		Napagold Air Filter	1.00
		Fuel Fil	1.00
		Wiper Blade	2.00
		Washer Fl	1.00
		Napa Cabin Air Filter	1.00
		Cabin Air Filter	1.00
		Brake Cleaner	3.00
		Group 31 Stud Delco	2.00
		Shop Supplies	1.00
Hours 15.00	Labor: 900.00	Parts: 1,079.98	Total: 1,979.98
:			

**Workorder:** 1510690      **Meter:** 50616      **In Date:** 10/22/2015      **Closed:** 11/05/2015  
**Problem:** AC

- R&r blend door. Replace thermistors and evac and charge system		<b>Parts List</b>	<b>Qty</b>
		3542606c1 Acuator Doo	1.00
- Shop Supplies		Mei	2.00
		Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 255.85	Total: 495.85
:			

**Workorder:** 1512722      **Meter:** 51530      **In Date:** 12/17/2015      **Closed:** 12/18/2015  
**Problem:** Power Steering

- Add power steering fluid		<b>Parts List</b>	<b>Qty</b>
		Psf Qt	1.00
Hours 0.50	Labor: 30.00	Parts: 6.06	Total: 36.06
:			

**Workorder:** 1602482      **Meter:** 53143      **In Date:** 03/09/2016      **Closed:** 03/11/2016  
**Problem:** Steering Fluid

- Add Ps fluid		<b>Parts List</b>	<b>Qty</b>
		Psf Qt	1.00
Hours 0.50	Labor: 30.00	Parts: 6.06	Total: 36.06
:			



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1602614      **Meter:** 53266      **In Date:** 03/11/2016      **Closed:** 03/30/2016  
**Problem:** PM / Steering box

	<b>Parts List</b>	<b>Qty</b>
- pm		
- replace air dryer	15-40 Oil	30.00
- replace steering gear box and power steering service	Napagold Oil Filter	1.00
- replace body up switch and tarp crank box and handle	Fuel Fil	1.00
- road test before and after	Napagold Air Filter	1.00
- replace radiator, hoses, fan clutch, and thermostat	22" Wiper Blade	2.00
- replace stripped intercooler clamp	Napa Cabin Air Filter	1.00
- Shop Supplies	Cartridge Ad9	1.00
	Steering Gear Box	1.00
	Psf Qt	2.00
	Power Steering Filter	1.00
	Body Up Switch	1.00
	Control Crank Kit	1.00
	Handle	1.00
	Bigg Degreaser	1.00
	Coolant Hose	1.00
	Coolant Hose Lower	1.00
	Fan Clutch	1.00
	Thermostat	1.00
	Cap	1.00
	H Duty Anti-freeze	6.00
	Cabin Air Filter	1.00
	radiator	1.00
	coolent hose	1.00
	hose clap	1.00
	Hose Clamp	1.00
	Radiator Hose Lower	1.00
	hose clap	2.00
	Lined Hose	3.00
	Shop Supplies	1.00

Hours 43.00      Labor: 2,580.0      Parts: 3,983.99      Total: 6,563.99  
:

**Workorder:** 1606067      **Meter:** 54880      **In Date:** 06/14/2016      **Closed:** 06/15/2016  
**Problem:** Tag bolts

- Install Tag		
	Hours 0.50	Labor: 30.00      Parts: 0.00      Total: 30.00
	:	

**Workorder:** 1606916      **Meter:** 55334      **In Date:** 07/08/2016      **Closed:** 07/15/2016  
**Problem:** Over heats at an idle

	<b>Parts List</b>	<b>Qty</b>
- Pulled codes and cleared one prev. active code		
- Tested cooling system Ok	Shop Supplies	1.00
- Many test drives		
- Shop Supplies		

Hours 3.00      Labor: 180.00      Parts: 2.00      Total: 182.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1611382      **Meter:** 57829      **In Date:** 11/02/2016      **Closed:** 11/21/2016  
**Problem:** PM / AC / Hinge

	<b>Parts List</b>	<b>Qty</b>
- Pm		
- Replace blower motor resistor and clean evaporator	Group 31 Stud Delco	2.00
- Repair tarp and body switch	15-40 Oil	30.00
- Service Trans.	Napagold Oil Filter	1.00
- Remove metal from tire and ck for leaks	Fuel Fil	1.00
- Weld repair tail gate	Napagold Air Filter	1.00
- Replace batteries	22" Wiper Blade	2.00
- Test Run	Napa Cabin Air Filter	1.00
- Shop Supplies	Cabin Air Filter	1.00
	Used Fire X Refurbished	1.00
	Bushing	5.00
	Napa Cabin Air Filter	1.00
	Napa Trans Filter	1.00
	Syn-atf Trans Fluid S	19.00
	Blower Motor	1.00
	Blower Resistor	1.00
	Body Up Switch	1.00
	Non-chlor Brake Clnr	2.00
	Shop Supplies	1.00
Hours 17.50	Labor: 1,050.00	Parts: 1,226.71
:	0	Total: 2,276.71

**Workorder:** 1700961      **Meter:** 59094      **In Date:** 01/31/2017      **Closed:** 02/06/2017  
**Problem:** Coolent

	<b>Parts List</b>	<b>Qty</b>
- add coolant		
	disf rotella	1.00
Hours 0.50	Labor: 30.00	Parts: 15.68
:		Total: 45.68

**Workorder:** 1702759      **Meter:** 59720      **In Date:** 03/17/2017      **Closed:** 04/25/2017  
**Problem:** Air Hose

	<b>Parts List</b>	<b>Qty</b>
- install air line adaptor and air tool kit		
- Shop Supplies	Coupler	2.00
	Adapter	1.00
	Air Hose	1.00
	13pc Set	1.00
	Ft Chuck	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 143.17
:		Total: 263.17



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1712371      **Meter:** 65607      **In Date:** 12/15/2017      **Closed:** 01/12/2018  
**Problem:** PM

		<b>Parts List</b>	<b>Qty</b>
- Pm			
- Service Ac		60" Under Bed Tool Box	1.00
- Test run		Visor Clip	1.00
- Install tool box		Sun Visor Clip	1.00
- Repair bed tarp		truck align	1.00
- Replace batteries		Trp NI M C 7-6 X 18	1.00
- Repair broken sun viser		Battery	2.00
- Alignment at Total Truck		Safety Sprng Hook	2.00
- Shop Supplies		15-40 Oil	30.00
		Napagold Oil Filter	1.00
		Filter	1.00
		Napagold Air Filter	1.00
		Wiper Blade	2.00
		Washer Fluid Concentr	1.00
		Cabin Air Filter	1.00
		Evap Odor Elinitator	1.00
		Napa Cabin Air Filter	1.00
		Shop Supplies	1.00
	Hours 18.00	Labor: 1,080.00	Parts: 2,048.86
	:	0	Total: 3,128.86

**Workorder:** 1712700      **Meter:** 65445      **In Date:** 12/27/2017      **Closed:** 01/24/2018  
**Problem:** LF rear tires

- Lf and rear tires			
	Hours 0.00	Labor: 0.00	Parts: 0.00
	:		Total: 0.00

**Workorder:** 1803946      **Meter:** 67226      **In Date:** 03/29/2018      **Closed:** 04/17/2018  
**Problem:** damage to rgt frt fender

- damage to rgt frt fender			
	Hours 0.00	Labor: 0.00	Parts: 0.00
	:		Total: 0.00

**Workorder:** 1805381      **Meter:** 68161      **In Date:** 05/29/2018      **Closed:** 06/05/2018  
**Problem:** Coolant

		<b>Parts List</b>	<b>Qty</b>
- Add Coolant			
		Rotell Elc Antifeerze	1.00
	Hours 0.50	Labor: 30.00	Parts: 15.33
	:		Total: 45.33



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1808836      **Meter:** 68765      **In Date:** 07/06/2018      **Closed:** 08/27/2018  
**Problem:** WINCH OUT-ON CANAL BANK

- Tow From: Old Boynton Rd-e4 Canal E Of Congress Nw  
 Crnr

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
 :

**Workorder:** 1812118      **Meter:** 70504      **In Date:** 11/28/2018      **Closed:** 12/07/2018  
**Problem:** Transmission leak

- Ck for leaks and replaced upper radiator hose
- Test run
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Rotell Elc Antifeerze	6.00
Coolant Hose	1.00
hose clap	2.00
Shop Supplies	1.00

Hours 3.50      Labor: 234.50      Parts: 208.85      Total: 443.35  
 :

**Workorder:** 1812720      **Meter:** 70991      **In Date:** 12/14/2018      **Closed:** 12/27/2018  
**Problem:** Low coolant

- Replaced bad coolant hose and changed coolant
- Repair marker lights
- Test drive
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
coolent hose	1.00
Rotell Elc Antifeerze	7.00
Hose Clamp	2.00
Lamp	2.00
Led M C Lamp	3.00
Led M C Adaper Plug	4.00
Shop Supplies	1.00

Hours 6.25      Labor: 418.75      Parts: 246.99      Total: 665.74  
 :

**Workorder:** 1900169      **Meter:** 71023      **In Date:** 01/04/2019      **Closed:** 01/10/2019  
**Problem:** No Start

- Pressure test and repair cooling system
- Test run
- To R&b
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Distilled Water 1gal	1.00
Shop Supplies	1.00

Hours 3.00      Labor: 201.00      Parts: 4.55      Total: 205.55  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1900969      **Meter:** 71284      **In Date:** 01/25/2019      **Closed:** 02/01/2019  
**Problem:** PM

	<b>Parts List</b>	<b>Qty</b>
- Pm		
- Service Ac	1cart Palladium 2 Grs	1.00
- Service front hubs	Non-chlor Brake Clnr	3.00
- Manual Regen	15-40 Oil	30.00
- Test run	Washer Fluid Concentr	1.00
- Shop Supplies	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
	Filter	1.00
	Cabin Air Filter	1.00
	Napa Cabin Air Filter	1.00
	Hub Cap	2.00
	1qt Syngear Oil 75-90	3.00
	Shop Supplies	1.00
Hours 11.00	Labor: 737.00	Parts: 431.73
:		Total: 1,168.73

**Workorder:** 1908003      **Meter:** 74678      **In Date:** 08/02/2019      **Closed:** 08/14/2019  
**Problem:** PM

	<b>Parts List</b>	<b>Qty</b>
- pm		
- service ac	15-40 Oil	30.00
- change cargo tool box	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Filter	1.00
	Wiper Blade	4.00
	Evap Odor Elinitator	1.00
	Napa Cabin Air Filter	1.00
	Cabin Air Filter	1.00
	60" Under Bed Tool Box	1.00
	Shop Supplies	1.00
Hours 11.00	Labor: 737.00	Parts: 1,422.81
:		Total: 2,159.81

**Workorder:** 1909521      **Meter:** 75137      **In Date:** 09/17/2019      **Closed:** 09/24/2019  
**Problem:** Tag Light

	<b>Parts List</b>	<b>Qty</b>
- tag light		
- add coolant	Boxed Miniatures	1.00
- Shop Supplies	Rotell Elc Antifeerze	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 18.93
:		Total: 85.93

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1910393	<b>Meter:</b> 75800	<b>In Date:</b> 10/08/2019	<b>Closed:</b> 10/16/2019
<b>Problem:</b> Coolant			
- Coolant		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Rotell Elc Antifeerze	3.00
		Shop Supplies	1.00
Hours 0.50	Labor: 36.50	Parts: 49.99	Total: 86.49
:			
<b>Workorder:</b> 1911314	<b>Meter:</b> 76192	<b>In Date:</b> 10/31/2019	<b>Closed:</b> 11/01/2019
<b>Problem:</b> Tail Gate Pin			
- Repair tailgate		<b>Parts List</b>	<b>Qty</b>
- Top off coolant		Shop Supplies	1.00
- Shop Supplies			
Hours 2.00	Labor: 146.00	Parts: 4.00	Total: 150.00
:			
<b>Workorder:</b> 1911834	<b>Meter:</b> 76418	<b>In Date:</b> 11/15/2019	<b>Closed:</b> 11/21/2019
<b>Problem:</b> Coolant			
- Top off coolant test for leaks		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Rotell Elc Antifeerze	1.00
		Shop Supplies	1.00
Hours 1.00	Labor: 73.00	Parts: 19.33	Total: 92.33
:			
<b>Workorder:</b> 1912404	<b>Meter:</b> 76631	<b>In Date:</b> 12/03/2019	<b>Closed:</b> 12/18/2019
<b>Problem:</b> Water leak			
- diagnose water leak. pressure test cooling system. replace hose and add coolant		<b>Parts List</b>	<b>Qty</b>
- long test drive		Hose Clamp	2.00
- Shop Supplies		Rotell Elc Antifeerze	4.00
		Hose Clamp	2.00
		Coolant Hose	1.00
		16.5 Oz Aero Kroil	1.00
		Shop Supplies	1.00
Hours 6.00	Labor: 438.00	Parts: 213.73	Total: 651.73
:			
<b>Workorder:</b> 1913099	<b>Meter:</b> 78815	<b>In Date:</b> 12/27/2019	<b>Closed:</b> 01/10/2020
<b>Problem:</b> Belt Squeal			
- Replace belts idlers and pullies		<b>Parts List</b>	<b>Qty</b>
- Multiple test runs		Dust Cover	1.00
- Shop Supplies		Bushing	1.00
		Bolt	1.00
		Tensioner	1.00
		Idler Pulley	1.00
		Drive Belt	1.00
		Shop Supplies	1.00
Hours 7.00	Labor: 511.00	Parts: 838.96	Total: 1,349.96
:			



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 2000353      **Meter:** 78815      **In Date:** 01/10/2020      **Closed:** 01/31/2020  
**Problem:** Drver door sprung

- Inspect driver door and sent to body shop	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 73.00      Parts: 4.00	Total: 77.00
:		

**Workorder:** 2001288      **Meter:** 78815      **In Date:** 01/13/2020      **Closed:** 02/06/2020  
**Problem:** : Wind blew drivers door open, now not closing properly, possible hinges.

- : Wind blew drivers door open, now not closing properly, possible hinges.

Hours 0.00	Labor: 0.00      Parts: 0.00	Total: 0.00
:		

**Workorder:** 2001377      **Meter:** 77553      **In Date:** 02/07/2020      **Closed:** 02/14/2020  
**Problem:** PM

- Pm	<b>Parts List</b>	<b>Qty</b>
- Service Ac	Napagold Oil Filter	1.00
- Repair engine oil leak	Napagold Air Filter	1.00
- Test drive	Filter	1.00
- Shop Supplies	Washer Fluid Concentr	3.00
	Wiper Blade	2.00
	Non-chlor Brake Clnr	3.00
	Cabin Air Filter	1.00
	Napa Cabin Air Filter	1.00
	15-40 Oil	30.00
	Shop Supplies	1.00
Hours 10.50	Labor: 766.50      Parts: 319.86	Total: 1,086.36
:		

**Workorder:** 2002342      **Meter:** 78376      **In Date:** 03/06/2020      **Closed:** 03/12/2020  
**Problem:** Head Light

- replace headlight	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Boxed Capsules	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 73.00      Parts: 14.16	Total: 87.16
:		

**Workorder:** 2003101      **Meter:** 78815      **In Date:** 03/27/2020      **Closed:** 04/20/2020  
**Problem:** Water tank leaking

- replace water hose and add new ends. replace nozzle	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Nozzle	1.00
	Hose Clamp	2.00
	Cable Tie	1.00
	Hd Heater Hose	10.00
	Connector	1.00
	Connector	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 219.00      Parts: 48.03	Total: 267.03
:		

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 2004955	<b>Meter:</b> 80320	<b>In Date:</b> 05/15/2020	<b>Closed:</b> 05/22/2020
<b>Problem:</b> Tag Housing			
- Replace water cooler		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		License Bracket W/light	1.00
		Shop Supplies	1.00
Hours 1.50	Labor: 109.50	Parts: 10.29	Total: 119.79
:			

---

<b>Workorder:</b> 2005576	<b>Meter:</b> 80668	<b>In Date:</b> 06/04/2020	<b>Closed:</b> 06/05/2020
<b>Problem:</b> Head light			
- headlight		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Boxed Capsules	1.00
		Shop Supplies	1.00
Hours 1.00	Labor: 73.00	Parts: 14.16	Total: 87.16
:			

---

<b>Workorder:</b> 2005649	<b>Meter:</b> 80668	<b>In Date:</b> 06/05/2020	<b>Closed:</b> 06/30/2020
<b>Problem:</b> AC			
- replace evap, dryer, expansion valve. evac and charge system		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Thermistor Kit	1.00
		Expansion Alve	1.00
		A/c Seal Kit	1.00
		A/c Accumulator	1.00
		evp	1.00
		Freon He Shop	10.00
		Shop Supplies	1.00
Hours 6.00	Labor: 438.00	Parts: 1,978.54	Total: 2,416.54
:			

---

<b>Workorder:</b> 2008761	<b>Meter:</b> 82700	<b>In Date:</b> 09/01/2020	<b>Closed:</b> 09/21/2020
<b>Problem:</b> PM/ Tailgate			
- pm		<b>Parts List</b>	<b>Qty</b>
- road test		15-40 Oil	30.00
- install batteries		Napagold Oil Filter	1.00
- service ac		Filter	1.00
- replace marker lights		Napagold Air Filter	1.00
- tarp arm bushings		Wiper Blade	2.00
- repair tool bin		Napa Cabin Air Filter	1.00
- Shop Supplies		Cabin Air Filter	1.00
		Used Fire X Refurbished	1.00
		Group 31 Stud Delco	2.00
		Led M C Lamp	2.00
		Bushing	2.00
		Shop Supplies	1.00
Hours 17.50	Labor: 1,277.50	Parts: 655.87	Total: 1,933.37
:	0		

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 2012305      **Meter:** 84961      **In Date:** 12/10/2020      **Closed:** 12/15/2020  
**Problem:** remove canceiver

- test and remove canceiver				<b>Parts List</b>	<b>Qty</b>
- Shop Supplies				Shop Supplies	1.00
	Hours 1.00	Labor: 73.00	Parts: 4.00	Total: 77.00	
	:				

---

**Workorder:** 2102146      **Meter:** 86099      **In Date:** 02/24/2021      **Closed:** 02/24/2021  
**Problem:** Transition Prep Charge

- Transition Prep Charge					
	Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00	
	:				